Color AND OPTION PRICING FOR All 3500 Models. M3CA44 - M3CAEL

Exterior Paint Overview

| Code | Description | Price | Paint | Code | Description | Price | Paint |
|------|--------------------------------------|---------|-------|------|-------------------------|---------|-------|
| 1243 | Calcite yellow | \$675 | 10=0 | 7701 | Pebble grey | \$0 | |
| 3432 | Sunset red | \$675 | 0_0_ | 7224 | Graphite grey | \$675 | |
| 3583 | Velvet red | \$0 | 0_0_ | 7708 | Silver grey | \$675 | 0 |
| 3589 | Jupiter red | \$0 | 0_0_ | 7709 | Blue grey | \$0 | 0=0- |
| 5362 | Brilliant blue | \$675 | 0-0 | 7755 | Tenorite grey metallic | \$1,070 | 0 0 |
| 5389 | Steel blue | \$0 | 0_0_ | 7992 | Selenite grey metallic | \$1,070 | |
| 5524 | Black blue | \$1,070 | 0-0- | 9040 | Jet black | \$1,070 | 0_0_ |
| 5890 | Cavansite blue metallic | \$1,070 | 0_0_ | 9136 | Grey white | \$675 | 0=0 |
| 5957 | Vanda blue | \$675 | 0_0_ | 9147 | Arctic white | \$0 | 0=0 |
| 6830 | Aqua green | \$0 | 0_0_ | 9197 | Obsidian black metallic | \$1,070 | 0_0_ |
| 7160 | Stone grey | \$675 | | 9775 | Iridiumsilver | \$1,070 | |
| | etStar for latest paint availabilite | | | | | | |


Please see NetStar for latest paint availability information.

Upholstery

Standard

VF7 Fabric

Maturin Black Upholstery




Optional

VF4

Fabric

Caluma Black Upholstery

| Upcharge | | | | | |
|---------------|----|-----|--|--|--|
| Cargo | \$ | 60 | | | |
| Cab Chassis | \$ | 60 | | | |
| Crew Van | \$ | 205 | | | |
| Passenger Van | \$ | 430 | | | |



Optional

VF6

Leatherette

Black


| Upcharge | | | | | |
|---------------|----|-----|--|--|--|
| Cargo | \$ | 60 | | | |
| Cab Chassis | \$ | 60 | | | |
| Crew Van | \$ | 205 | | | |
| Passenger Van | \$ | 430 | | | |




Seat restrictions

| | | | Fabrics | | |
|---------|----------------------|-----|---------|-----|--|
| Code | Seat | VF7 | VF4 | VF6 | |
| | Standard Seats Front | S | 0 | 0 | |
| | Standard Seats Rear | S | n/a | 0 | |
| SF1/SF2 | Power Seats | n/a | 0 | 0 | |
| | Comfort Seats Front | S | 0 | 0 | |
| | Comfort Seats Rear | n/a | 0 | 0 | |

Front and rear fabric always have to match.





Suspension Matrix

| | | Cargo Van | / Crew Va | n | | |
|-------------|--|-----------|--|-----|-----------|--|
| Standard | 1500 | 2500 | 3500 3500XD | | 4500 | |
| | Base Sus | pension | | CB8 | CB8 + A50 | |
| La July | | - | \50 | | | |
| | CB1 (add to st | tandard) | | | | |
| Ontinue | CB7 (moved to | option) | <u>-</u> | | | |
| Options | CB8 (replacing standard) | | S | | | |
| | - | CB4 (F | lecommended for RV) - only 6cyl Diesel | | | |
| | CT | 1 | • | | | |
| Specialized | CE8 (not with 4x4 models) | | | | | |
| Options | B01 (not with 3500/3500XD/4500 144"WB) | | | | | |
| Options | X2R (not with 3500/3500XD/4500 144"WB) | | | | | |

| | | Passenger | |
|----------|-------------|---------------------|-----------------------------------|
| | 1500 | 250 | 0 |
| Standard | 144" WB | 144 ⁸ WB | 170" WB |
| | Base Suspen | sion + CB1 + CT1 | Base Suspension + CB1 + CT1 + A50 |

| | Cab Chassis | WENT THE RESERVE OF THE PARTY O | | | |
|---------------------|-----------------------------------|--|--|--|--|
| Standard | 3500XD | 4500 | | | |
| Stantialu | CB8 | CB8 + A50 | | | |
| Options | CB4 | | | | |
| Options | A50 | | | | |
| 77 77 70 | CE8 (not on | 144"WB models) | | | |
| Specialized Options | BO1 (not with 3500XD/4500 144"WB) | | | | |
| | X2R (not with 3500XD/4. | 500 144"WB) | | | |

Suspension Details

| | | | Standard Suspensions and Options | | |
|----------------------------|--|--|--|--|--|
| Code | Title | | Details | | |
| A50 | Front axle reinforced | Includes an increased load capacity of the front axle, where heavier bodies and equipment can be fitted. The higher capacity from axle caters to heavier cabs and heavier special equipment (e.g. for fire-fighting vehicles and ambulances). | | | |
| | | Description | Ride comfort due to reduced roll stabilization. | | |
| No Factory Code | Base Standard Factory Suspension | Benefit | The Base Standard Factory suspension, has an adapted front suspension for a lower and more comfortable entry. With the removal of the rear stabilization bar it allows for an overall comfortable ride with reduced roll. | | |
| | | Description | Roll Stabilization with height body damping | | |
| CB7 | CB7 Stabilization Level I | | CB7 compensates for rolling behavior due to higher center of gravity of loads or bodies. Torsion bars with an increased diameter are added to the front and rear axels. Furthermore, shock absorbers with an adapted characteristic are installed. | | |
| | | Description | Enhanced roll stabilization with higher body damping compared to CB7 | | |
| CB8 Stabilization Level II | Benefit | Additional roll stabilization and body damping compared to CB7. Increases torsion bar diameters at the front and rear axles and provides an adapted shock absorber characteristic. Furthermore, rear axle springs with increased rigidity are installed. | | | |
| CB4 | Stabilization Level III | Description | Designed for vans with a intense rolling behavior due to a much heavier load and higher center of gravity. (i.e. recreational vehicles) | | |
| CB4 3 | Stabilization Level III | Benefit | CB4 comes with larger diameter stabilizers, shock absorbers and with charateristics that are adapted for an increased rebound and compression curve. Furthermore, the leaf springs are increased in rigidity. | | |
| CB1 | Suspension for comfort and load protection | Enhanced comfort due to adapted damper characteristics and the use of progressive spring characteristics. | | | |
| CT1 | Rear spring vibration absorbers | Includes vibration absorbers fitted on the left and right rear spring and lowers the resonant vibrations of the rear springs, thus hindering noise development. | | | |

| Specialized Suspension Options | | | | | | | | |
|--------------------------------|---|---------------|--|--|--|--|--|--|
| Code | Title | Explanation | | | | | | |
| CE8 | Raised rear body mounts | Raised body o | Raised body on rear axle (35mm/1.4") | | | | | |
| | B01 ESP for increased Center of Gravity | Description | Adjusted braking and handling characteristics for vehicles with increased center of gravity. | | | | | |
| B01 | | Benefit | With code B01, the ESP® is optimized to reduce the vehicles tilt tendency with a total center of gravity of more than 1000 mm [39,4 inches]. It is essential to ensure that the vehicle is equipped with the right suspension and tires. With B01 it is required to also add CB8 or CB4. | | | | | |
| X2R | Conversion to RV requirement | MBUX Timed S | Switch-off extended to 6 hours and B01 is automatically added to this code. | | | | | |

Rear view camera/head unit plausibility

| CA/PV/CV | | | | | | |
|-------------------|------------------------------|-----------------|-------------------|---------------------------------|---------------------------------|--|
| | Standard | Option A | Option A + JB7 | Option A + JB6 | Option A + JB8 | |
| Radio/HU | E10 | E3M/E4M | E3M/E4M | E3M/E4M | E3M/E4M | |
| Camera | FR3 | FR8 | integrated camera | integrated 360 degree camera | integrated 360 degree camera | |
| Pre-wiring Camera | n/a | n/a | n/a | n/a | n/a | |
| Camera Display | Interior rear view mirror | 7/10.25" Screen | 7/10.25" Screen | 7/10.25" Screen | 7/10.25" Screen | |

Options shown above lead to an upcharge.

| cc | | | | | |
|--------------------|----------|-----------------------|-------------------------------------|--|--|
| | Standard | Option A | Option B | | |
| Radio/HU | E10 | E10 | E3M/E4M | | |
| After-Sales Camera | - | Any analog* Camera | Mercedes-Benz Camera** (digital) | | |
| Pre-wiring | | FV1 | FR7 | | |
| Rear-View Display | | Interior rear view | | | |
| | - | mirror | 7/10.25" Screen | | |

Options shown above lead to an upcharge.

Cargo Van Floor Variations

| Standard | V93 | Without factory installed flooring |
|----------|-----|------------------------------------|
| | V43 | Wood floor with 6 D-rings |
| Options | VK8 | Floor covering, plastic |

Note: see restrictions in combination with metallic paint

Special Rule for cargo vans with metallic paint

| Paint Code | 5890/7755/7992/9197/9775 | | |
|------------------|---------------------------|--|--|
| | Wood floor with 6 D-rings | | |
| | VK8 | Floor covering, plastic | |
| Must have one of | ZZ9 | No floor covering; requires customer floor installation Package contains: V93 - No factory installed flooring VL4 - Metallic painted floor | |

Note: Fleet only

Additional comments ZZ9 Package

While applying the required clear coat layer to the metallic painted cargo floor, imperfections could occur. Therefore, we strongly recommend to install flooring in the cargo area for vehicles with a metallic paint.

Please be aware that potential paint appearance, contamination or imperfections of the uncovered cargo floor are not considered a defect and are therefore not reimbursable for repairs.

^{*}only cameras with analog signal works

^{**}only the Mercedes-Benz rear view camera works (digital signal)

Tire & Wheel Overview

| | | 1500/250 | 0 Models |
|-----|-------------------------|----------------------|---------------|
| | | Standard Tire | RH8 |
| | | Standard Wheel | RS3 |
| | | Optional Wheel | RL5 |
| | | Brand C | Options |
| | | RMO All-season tires | RM1 M+S tires |
| RD9 | Tire brand, unspecified | S | 0 |
| RF8 | Michelin | 0 | n/a |
| RF1 | Continental | n/a | 0 |
| RH0 | Kumho | 0 | n/a |

To order any of the tire brands above code RM9 has to be added to order.

| | | | 3500/3500XD M | odels | |
|-----|-------------------------|----------------------|---------------|----------------------|---------------|
| | | Standard: Dua | Rear Wheel | Optional: Sup | er Single |
| | | Standard Tire | RH7 | Standard Tire | R9A |
| | | Standard Wheel | RS6 | Standard Wheel | RS5 |
| | | Brand O | ptions | Brand Op | tions |
| | | RM0 All-season tires | RM1 M+S tires | RM0 All-season tires | RM1 M+S tires |
| RD9 | Tire brand, unspecified | 0 | 0 | S | n/a |
| RF8 | Michelin | 0 | n/a | n/a | n/a |
| RF1 | Continental | 0 | 0 | 0 | n/a |
| RHO | Kumho | n/a | n/a | n/a | n/a |

Single tire Steel Alloy

Dual Rear Wheel

Steel

To order any of the tire brands above code RM9 has to be added to order.

Standard is DRW, Option is Super Single

| | | 4500 M | lodels |
|-----|-------------------------|----------------------|---------------|
| | | Standard Tire | RH7 |
| | | Standard Wheel | RS6 |
| | | Brand O | ptions |
| | | RM0 All-season tires | RM1 M+S tires |
| RD9 | Tire brand, unspecified | S | 0 |
| RF8 | Michelin | 0 | n/a |
| RF1 | Continental | 0 | 0 |
| RH0 | Kumho | n/a | n/a |

To order any of the tire brands above code RM9 has to be added to order.

3500 CARGO VAN - 4cyl Diesel Standard Equipment

| 144" 4C | 170" 4C | 170" E 4C |
|---------|---------|-----------|
| M3CA44 | M3CA74 | M3CAE4 |
| 907.653 | 907.655 | 907.657 |

| | | 907.653 | 907.655 | 907.657 |
|---------------|---|---------|---------|---------|
| Engine | | | | |
| 4-Cyl E | ngine/7-Speed Trans. | S | S | 5 |
| ED4 | AGM battery 12V 92 AH 850 A | S | S | S |
| 342 | Automatic transmission, 7G-tronic | S | S | S |
| | Alternator 14 V / 200 A | S | S | S |
| MG3 | 2.0L 4-cylinder diesel engine | S | S | S |
| $\overline{}$ | SULEV emissions | S | S | S |
| | choose while ordering | | 9 | 0 |
| | Dual Rear Wheel | \$0 | \$0 | \$0 |
| | Tires LT 215/85 R16 | S | S | S |
| $\overline{}$ | 5.5 J x 16 steel wheels | S | S | S |
| _ | Unspecified tire brand | S | S | S |
| _ | Super Single Tire | \$385 | \$385 | |
| | 285/65 R 16 C super single tires | 7363 | | \$385 |
| $\overline{}$ | Steel wheels: 8.5Jx16 Rr; 6.5Jx16 Pr | | 0 | 0 |
| \rightarrow | | 0 | 0 | 0 |
| _ | Unspecified tire brand | 0 | 0 | 0 |
| | Tire pressure monitoring sensors | 0 | 0 | 0 |
| quipn | | | | |
| | Axle ratio 4.182 | S | S | S |
| _ | Active Brake Assist | S | \$ | S |
| | Hold Function | S | S | 5 |
| | Multifunction steering wheel | S | S | S |
| | Stabilization Level II | S | S | S |
| L1 / | Adjustable steering wheel (angle) | S | S | S |
| 03 H | High roof | 0 | S | S |
| 93 (| Omission bulkhead | S | S | 5 |
| 07 I | HIII Start Assist | S | 5 | 5 |
| 10 | Standard radio | S | S | S |
| 1U U | JSB-C socket, 5 V | S | S | S |
| 30 5 | Starter battery disconnect | S | S | S |
| 3J F | Pre-installation for switch panel | S | S | S |
| 40 1 | railer hitch prep. wiring | S | S | S |
| D8 F | Preinstallation PSM | S | S | S |
| E5 1 | Ultracapacitor discharge module | S | S | S |
| | Body Builder Connector | S | S | S |
| \rightarrow | ump start terminal | S | S | S |
| | Pre-installation for Mercedes me Remote Services | S | S | S |
| _ | mergency Call System | S | S | |
| _ | Breakdown management | S | | S |
| | Heated & electrically adjustable exterior mirrors | | S | \$ |
| | helf above windshield | S | S | 5 |
| | | S | S | S |
| | Cupholder front | S | S | S |
| | Remote key (315 mhz) w/central locking | S | S | S |
| | torage compartment underneath cockpit | S | S | S |
| | lear view camera (rear-view mirror display) | S | S | 5 |
| _ | Vindshield with filter band | S | S | S |
| _ | leater, auxiliary electric hot air | S | S | S |
| _ | ir Condition, Front | S | S | S |
| _ | lead Unit, North America | S | S | S |
| _ | peedometer, miles and km/h | S | S | \$ |
| | eat belt warning for co-driver seat | S | S | \$ |
| | eat belt reminder driver | S | S | S |
| 55 C | Outside temperature gauge | S | S | S |
| /8 C | crosswind Assist | S | S | \$ |
| -13 C | communication module (LTE) for dig. services | S | S | S |
| 9 S | ervice interval 20.000 miles | S | S | S |
| 56 R | ed diesel filler cap | S | S | S |
| _ | xhaust straight to rear | S | S | S |

3500 CARGO VAN - 4cyl Diesel Standard Equipment

| | | 144" 4C | 170" 4C | 170" E 4C |
|-----|--|---------|---------|-----------|
| | | M3CA44 | M3CA74 | M3CAE4 |
| | | 907.653 | 907.655 | 907.657 |
| KB7 | 24.5 gallon fuel tank | S | S | S |
| KL1 | Aux fuel sending unit w/ fuel tap | S | S | S |
| KL5 | Fuel filter with water separator | S | S | S |
| KP6 | 3rd generation SCR emission control system | S | S | S |
| L65 | Interior lights, cargo compartment | S | 5 | S |
| L94 | Parking lights deletion | S | S | S |
| .A2 | Headlight assistant | S | S | S |
| LB5 | 3rd brake light | S | S | S |
| MS1 | Cruise control | S | S | S |
| P47 | Front mudflaps | S | S | S |
| 248 | Rear mudflaps | S | 5 | S |
| Q11 | Longitudinal member reinforcement | S | S | S |
| R65 | Spare tire bracket below frame | S | S | S |
| ₹87 | Spare tire | S | S | S |
| RM0 | All-season tires | S | S | S |
| 502 | Standard driver seat | S | S | S |
| 504 | Standard front passenger seat | S | S | S |
| 22 | Armrest for driver's seat | S | S | S |
| 25 | Armrest for front passenger seat | S | S | S |
| A5 | Front airbag, driver | S | S | S |
| A6 | Front airbag, passenger | S | S | S |
| H1 | Thorax-pelvis sidebag, driver | S | S | S |
| H2 | Thorax-pelvis sidebag, co-driver | S | S | S |
| Н9 | Airbag, driver/passenger window | S | S | S |
| K2 | Seat occupancy sensor, driver's seat | S | S | S |
| 16 | Sliding door, passenger side | S | S | S |
| /93 | Without factory installed flooring | S | S | S |
| /94 | Cable duct - side wall | S | S | S |
| /95 | Cable duct - rear portal | S | S | S |
| V54 | Rear doors, opening to side wall | 0 | 0 | S |
| | GVWR 9,990 lbs. / 4,531 kg | S | S | S |
| 43 | Jack, hydraulic | S | S | S |

| | | 144" 4C | 170" 4C | 170" E 40 M3CAE4 |
|---------------|--|---------------|---|---------------------|
| | | M3CA44 | M3CA74 | |
| | | 907.653 | 907.655 | 907.657 |
| 450 | Front axle reinforced | \$346 | \$346 | \$346 |
| AP2 | Addtl. bar for driveshaft & exhaust extension | \$69 | \$69 | \$540 |
| AR2 | Axle ratio 3.923 | \$0 | \$0 | \$0 |
| | not with AR3 | 30 | 30 | 30 |
| 301 | ESP for increased Center of Gravity above 39.4" | | \$0 | \$0 |
| | must have CB4/CB8/X30; not with RHO/CB7 | | 70 | 30 |
| 3E2 | Handbrake lever, folding | \$55 | \$55 | \$55 |
| | not with B25; X69 choose B25/BE2 | 755 | 233 | 202 |
| 72 | Bumpers front/rear primed | \$268 | \$268 | \$268 |
| | must have CN2 (part of X67), not with CM0 | 7.00 | \$200 | 7200 |
| :72 | Bumpers front/rear primed | \$268 | \$268 | \$268 |
| | must have CN2 (part of X67), not with CM0 | 7200 | 9200 | 7200 |
| E8 | Raised rear body mounts | \$252 | \$252 | \$252 |
| L3 | Leather steering wheel | \$187 | \$187 | \$187 |
| | must have (C02/E3M)/C03 + (ET4/MS1) | 7107 | 7107 | 7101 |
| M0 | Painted metallic front & rear bumper | \$587 | \$587 | \$587 |
| | must have (CN2/X67) + (JA7/C01) + (JB6/JB7) + (7755/9197/9775) | \$50 , | 4507 | 4201 |
| :M9 | Primed side moldings | \$364 | \$364 | \$364 |
| 003 | High roof | \$2,900 | S | \$304 |
| 13 | Mounting rails for roof rack | \$300 | \$300 | \$300 |
| 22 | Fixed sunroof (rear roof section) | \$336 | \$336 | \$336 |
| | not with H08/HK4/H72/V36/ZK4 | 7550 | 9330 | 7550 |
| 50 | Cargo partition | \$288 | \$288 | \$288 |
| | not with D51/D93/H08/HK4/T74/V36; must have one of T93/T77 | V200 | Ÿ200 | 7200 |
| 51 | Cargo partition with 1 window | \$335 | \$335 | \$335 |
| | not with D50/D93/H08/HK4/T74/V37/D17; must have one of T93/T7 | | 2555 | 7555 |
| 1B | Tray for smartphones inci. wireless charging | \$156 | \$156 | \$156 |
| | must have CO2/E3M + H1I | 7130 | \$130 | 2130 |
| 1E | Navigation | \$728 | \$728 | \$728 |
| | must have CO2/E3M, not with CO3 | 7,25 | Ţ. 2 0 | 97.50 |
| 15 | Sirius XM, satellite radio | \$255 | \$255 | \$255 |
| | must have CO2/E3M/CO3 | | 7 | 7427 |
| 1R | Additional Fuses (40/80/150/100 Ampere) | \$50 | \$50 | \$50 |
| | SoP and Plausibility TBD | 7.00 | V 30 | 750 |
| 1Y | Additional Fuses (40/80/80/100 Ampere) | \$50 | \$50 | \$50 |
| | SoP and Plausibility TBD | | 700 | γου |
| 1X | MBUX multimedia 6-hour runtime | - 1 | \$0 | \$0 |
| | must have X2R + (C02+E1E/E1S)/C03/(E3M+E1E/E1S) | | | 7.7 |
| 2A | Access point for BB special signals in cockpit | \$29 | \$29 | \$29 |
| 21 | Additional battery, co-driver seat base | \$248 | \$248 | \$248 |
| | must have E36/C06; not with E2M/F09; CHS production only | 1 | | 7110 |
| 2M | Additional battery, engine compartment | \$248 | \$248 | \$248 |
| | must have X01+ (E36/C06); not with E2I/X69/F09 | 1 | | 7.10 |
| _ | MBUX Multimedia System with 7" touchscreen | \$474 | \$474 | \$474 |
| | not with CO2/CO3; must have JK5+(JB7/JB6/JB8/FR8) | | ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,, | Ψ,,, |
| | Cutoff relay for additional battery | \$110 | \$110 | \$110 |
| | standard with E2I/E2M | | | 7 -1-0 |
| | 12 V power outlet, driver seat base | \$92 | \$92 | \$92 |
| M | Extension of PSM standard contact | \$58 | \$58 | \$58 |
|)5 | Parametric special module (PSM) | \$317 | \$317 | \$317 |
| | not with ED8 | | | ,,,,,, |
| 3 | 115 V socket | \$125 | \$125 | \$125 |
| 7 | Basic electric fitting for rear loudspeakers | \$68 | \$68 | \$68 |
| $\overline{}$ | 12 V power outlet, rear compartment | \$92 | \$92 | \$92 |
| $\overline{}$ | Charging package, dashboard | \$82 | \$82 | \$82 |
| $\overline{}$ | Active Distance Assist DISTRONIC | \$263 | \$263 | \$263 |
| | must have CO2/CO3/E3M; not with ZH4 | | 7-50 | 7-00 |

| | | 144" 4C | 170" 4C | 170" E 4C M3CAE4 |
|-----|---|---------|---------|---------------------|
| | | МЗСА44 | M3CA74 | |
| | | 907.653 | 907.655 | 907.657 |
| F1K | Coat hooks in driver cabin | \$14 | \$14 | \$14 |
| | must have D50/D51 | | 111 | |
| F49 | Electrically heated windshield | \$218 | \$218 | \$218 |
| | no restriction | | | |
| 61 | Interior rear view mirror | \$36 | \$36 | \$36 |
| | not with D50; must have C02/E3M/C03 | | | |
| E9 | Additional DIN-slot | \$81 | \$81 | \$81 |
| F8 | Overhead storage slot, front center | \$105 | \$105 | \$105 |
| J1 | Hinged lid for storage compartment | \$93 | \$93 | \$93 |
| R8 | Rear view camera (head unit display) | \$336 | \$336 | \$336 |
| | must have CO2/E3M; not with FR3/JB7/JB6/JB8 | | | |
| Y1_ | Security alarm w. interior motion sensor | \$584 | \$584 | \$584 |
| | must have LC4/C00 | | | |
| Y7 | Optional 3-button keys | \$36 | \$36 | \$36 |
| Z9 | Keys, two additional masters | \$121 | \$121 | \$121 |
| 100 | Warm/cool air duct to rear compartment | \$59 | \$59 | \$59 |
| | not with D50/D51/Y2A | | | |
| 101 | Heat insulation, rear compartment | \$156 | \$156 | \$156 |
| | must have V21/V25/VA3/VA1/C07/X66 | | | |
| 104 | Heat insulation, front compartment | \$187 | \$187 | \$187 |
| | if + D50/D51 must have V07 | | | |
| 108 | Air conditioning rear, roof-mounted | \$2,872 | \$2,872 | \$2,872 |
| | must have D93 +V36; not with HK4/C06/X66/C07 | | | |
| 112 | Fuel-fired pre-heater/booster (17K BTU) | \$1,116 | \$1,116 | \$1,116 |
| | not with HZ9 | | | |
| 113 | Rear cabin heater and vents | \$786 | \$786 | \$786 |
| | must have H12/HZ9 | | | |
| 115 | Heated front passenger seat | \$284 | \$284 | \$284 |
| | must have H16; not with X68 | | | |
| 116 | Heated driver's seat | \$284 | \$284 | \$284 |
| | must have H15; not with X68 | | | |
| 122 | Rear window defroster | \$253 | \$253 | \$253 |
| | must have W61/W78; standard for W61+W70 | | | |
| 172 | Roof fan, electric | \$400 | \$400 | \$400 |
| | not with D22/V36 | | | |
| 88 | Rear heater prep | \$405 | \$405 | \$405 |
| | must have H12/HZ9; not with H13/T19 | | | |
| 11 | Front-to-rear outlet in instrument panel | \$0 | \$0 | \$0 |
| | must have FJ1/C01 | | | |
| IH4 | Thermotronic automatic climate control | \$337 | \$337 | \$337 |
| | must have JF1; if +H13 must have H08/HK4 | | | |
| IK4 | Rear air conditioner, heavyduty | \$3,940 | \$3,940 | \$3,940 |
| | must have D03+V36+D93; not with H08/ZB6/ZE6/N62/N63 | | | |
| Z9 | Fuel-fired heater booster (18,000 BTU) | \$676 | \$676 | \$676 |
| | not with H12 | | | |
| 51 | Fuel gauge, optimized for aux. fuel tap | \$72 | \$72 | \$72 |
| | not with HZ9/H12 | | | |
| _ | Engine oil level display at cold start | \$0 | \$0 | \$0 |
| \7 | Blind Spot Assist | \$450 | \$450 | \$450 |
| | must have F64; not with C01 | | | |
| _ | Active Lane Keeping Assist | \$288 | \$288 | \$288 |
| | standard with CO2/CA2 | | | |
| 36 | Parking Package with 360 degree camera | \$775 | \$775 | \$775 |
| | must have CO2/CO3/E3M; not with W75/W76/JB7 | | | |
| - | | | | |
| - | Parking Package | \$615 | \$615 | \$615 |
| 37 | Parking Package must have CO2/CO3/E3M; not with W75/W76/JB6 360 Degree Camera | \$615 | \$615 | \$615 |

| | | 144" 4C M3CA44 | 170" 4C M3CA74 | 170" E 4C M3CAE4 |
|---------------|---|-------------------|-------------------|---------------------|
| | | 907.653 | 907.655 | 907.657 |
| JF1 | Rain sensor | \$106 | \$106 | \$106 |
| | Instrument cluster with color display | \$144 | \$144 | \$144 |
| | standard with CO2/CA2 | V+11 | V±++ | ATTI |
| JWO | Backup alarm | \$99 | \$99 | \$99 |
| _ | Deactivation lamp monitoring failure | \$27 | \$27 | \$27 |
| | Attention Assist | \$49 | \$49 | \$49 |
| _ | Misfueling prevention for Diesel | \$49 | \$49 | \$49 |
| | DEF fluid filler cap - lockable | \$27 | \$27 | \$27 |
| | Fog lamp with cornering light function | \$199 | | |
| | Light/motion sensor in rear compartment | | \$199 | \$199 |
| | not with V36 | \$54 | \$54 | \$54 |
| _ | Illuminated front exits | 0454 | 4 | 4 |
| | | \$151 | \$151 | \$151 |
| _ | LED light strip in load compartment | \$263 | \$263 | \$263 |
| _ | not with H08/HK4/V36/C06 | | | |
| $\overline{}$ | Comfort overhead control panel | \$93 | \$93 | \$93 |
| $\overline{}$ | Speed limitation 65 mph | \$60 | \$60 | \$60 |
| _ | not with MD3 | | | |
| $\overline{}$ | Top speed limitation 75 mph | \$60 | \$60 | \$60 |
| \rightarrow | not with M20 | | | |
| N62 | Front engine bracket for additional alternator | \$467 | \$467 | \$467 |
| | not with HK4/N63 | | | |
| N63 | Front engine bracket for auxiliary A/C compressor | \$467 | \$467 | \$467 |
| | not with HK4/N62 | | | |
| 93 | Omission of D-rings | -\$15 | -S15 | -\$15 |
| | not with D93/V43/VK8 | | | |
| _ | Trailer cross member 7,500 lbs capacity | \$186 | \$186 | 100 |
| $\overline{}$ | not with W73/W75/W76/Q24/Q67 | 1 1 1 1 | 7200 | |
| _ | Half-sided step rear (for trailer hitch) | \$101 | \$101 | \$101 |
| \rightarrow | must have Q24/QA2; not with W73/W75/W76 | 7201 | 9101 | 9101 |
| _ | Frailer hitch, 5,000 lbs | | | \$147 |
| _ | not with W73/W75/W76 | | | 2147 |
| $\overline{}$ | Spare tire deletion | -\$110 | -\$110 | -\$110 |
| - | must have R92; not with R87 | -3110 | -2110 | -\$110 |
| | Spare tire carrier deletion | \$0 | \$0 | ćo. |
| _ | must have R91; not with R65 | \$0 | 50 | \$0 |
| | Rims painted jet black | T dou T | | 40- |
| _ | | \$81 | \$81 | \$81 |
| | not with RL5/RM2 | 1 | 24:00 | 200 |
| | Fire brand Continental | \$0 | \$0 | \$0 |
| _ | must have RM1 + RM9 | | | |
| | Fire brand Michelin | \$0 | \$0 | \$0 |
| | nust have RM9; not with RM1 | | | |
| | Fire brand Kumho | \$0 | \$0 | \$0 |
| _ | nust have RM9; not with RM1 | | | |
| - | vi+S winter tires | \$169 | \$169 | \$169 |
| _ | nust have RF1/RD9; not with RF8/RH0/X31 | | | |
| M2 F | Rims painted arctic white | \$81 | \$81 | \$81 |
| r | not with R98/RL5 | | | |
| M9 S | pecially requested tires | \$101 | \$101 | \$101 |
| r | nust have RF1/RF8/RH0; not with RD9 | | | |
| 23 1 | win front passenger seat | \$400 | \$400 | \$400 |
| r | not with C00/X68/X01 | | | |
| | Armrest, driver and passenger door | \$51 | \$51 | \$51 |
| - | leat belts orange, driver and front passenger | \$32 | \$32 | \$32 |
| | not with 523 | 732 | J32 | 734 |
| | Oriver's seat plus | ¢220 | ¢220 T | cana |
| - | nust have VF7; not with C00/X68/X69 | \$238 | \$238 | \$238 |
| | | , tr. | ec. I | 20. |
| | torage net, driver's seat backrest | \$64 | \$64 | \$64 |
| Z8 S | torage net, passenger seat backrest | \$64 | \$64 | \$64 |

| | | 144" 4C | 170" 4C M3CA74 | 170" E 4C M3CAE4 |
|------|---|----------|-------------------|---------------------|
| | | M3CA44 | | |
| | | 907.653 | 907.655 | 907.657 |
| 12 | Sliding door two stage opening | \$82 | \$82 | \$82 |
| | not with T55 | | | |
| 19 | Sliding door, driver's side | \$935 | \$935 | \$935 |
| | not with H13/H88/VC5/ZE6/F43/W16/F02; if +V36 must have D03 | | | |
| Γ50 | Electric closing assist right sliding door | \$335 | \$335 | \$335 |
| | must have D03; not with T55/T93 | | | |
| 751 | Electric closing assist left sliding door | \$335 | \$335 | \$335 |
| | must have T19 + D03 | | | |
| Г55 | Electric sliding door right | \$831 | \$831 | \$831 |
| | must have D03 + (FY7+T16); not with T12/T50 | | | |
| r57 | Electric sliding step | \$1,071 | \$1,071 | \$1,071 |
| | must have ED5; not with T93 | | | |
| T60 | Opening limiter electrically operated sliding door | \$120 | \$120 | \$120 |
| | must have T55 | | | |
| Г74 | Assist handle, B-pillar | \$32 | \$32 | \$32 |
| | must have D93; not with T77 | T | | |
| Γ75 | Door-mounted assist handles, driver & passenger | \$59 | \$59 | \$59 |
| T77 | Assist handle w/ partition | \$32 | \$32 | \$32 |
| 100 | must have D50/D51/D64 | , | | |
| T85 | Assist handle, left rear door | \$32 | \$32 | \$32 |
| T86 | Assist handles, right rear door | \$32 | \$32 | \$32 |
| Г93 | Sliding door right side deletion | \$0 | \$0 | \$0 |
| 1-2 | not with T16/T50/T57/VK8/VC5 | | | |
| /07 | Cab rear wall liner | \$360 | \$360 | \$360 |
| | must have (D50/D51)+F1K; standard with H04 | | | |
| /21 | Luxury interior Trim | \$661 | \$661 | \$661 |
| | must have VA5/VA7; not with V52/VA1/VA3 | , | | |
| /24 | Pallet support in sliding door step | \$96 | \$96 | \$96 |
| | must have (V43/X66)+(D50/D51); not with VK8/V93/C07 | | | |
| /25 | Half height load compartment trim | \$201 | \$201 | \$201 |
| | not with VA1/VA3/VA5/V52/X66 | - | | |
| /31 | Window pillar trim | \$513 | \$513 | \$513 |
| /2.5 | must have V36 + (V21/VA1) + (F02/F03/F07); not with V42 | | | |
| /35 | Wheel house covering | \$105 | \$105 | \$105 |
| 12.5 | if +V43 must have V25/VA1/VA3; not with V52 | , | | |
| /36 | Roof trim | \$876 | \$876 | \$876 |
| | must have D93; not with D17/D22/H72/L65/L71/LC2/VA3/V42/ZE6/(| | | |
| /42 | Lashing rails, waist level | \$277 | \$277 | \$277 |
| 112 | not with V36/ZE6 | T 4:55 T | A I | 4100 |
| /43 | Wood floor with 6 D-rings | \$422 | \$422 | \$422 |
| 140 | not with P93/V93/VL4/VK8/C07; standard with D93/H13/V24/V52/V | | 200 1 | |
| /48 | Floor cover behind seat box | \$27 | \$27 | 527 |
| /4A | must have D93; not with D50/D51/D56/D62/D64/V43/VK5 | 1 4400 1 | ÷400 | 4400 |
| 4A | Full paneling, right sliding door | \$109 | \$109 | \$109 |
| /85 | not with P93/V93/VL4/VK8/C07; standard with D93/H13/V24/V52/V | | 420 | ÁDO |
| A1 | Cigarette lighter & ash cup, front | \$39 | \$39 | \$39 |
| W.T. | Side wall paneling waist height PVC must have VA5/VA7; not with V52 | \$319 | \$319 | \$319 |
| (A2 | | C444 | 4444 | **** |
| A3 | Side wall paneling full hardboard | \$444 | \$444 | \$444 |
| ٨Ε | not with V36/F02; if T93 must have (D50/D51) | t20 I | 630 | *** |
| A5 | Full paneling, hinged rear doors | \$38 | \$38 | \$38 |
| // 7 | must have D03+VA7+(W61/W78); not with V25 | 645- | 6107 | 44.00 |
| 'A7 | Storage compart. w/ net in rear doors | \$127 | \$127 | \$127 |
| C4 | must have W61/W78; not with V52 | A | A | 4 |
| C4 | Cargo lashing rails, head height | \$415 | \$415 | \$415 |
| CE | must have V42/C07/X66; not with ZE6 | A 1 | ėn. | *** |
| C5 | Door sill - protective edge | \$71 | \$71 | \$71 |

| | | 144" 4C | 170" 4C | 170" E 4C |
|------|--|------------|-------------------|---|
| | | M3CA44 | M3CA74 907.655 | M3CAE4 |
| | | 907.653 | | 907.657 |
| /K8 | Floor covering, plastic | \$370 | \$370 | \$370 |
| | not with V43/P93/T19/T93/V52/VC5/X66 | 70.0 | \$370 | 4370 |
| VV2 | Lashing rails, floor level (plus 4 anchors) | \$270 | \$345 | \$377 |
| | must have V43; not with V93/VC5/ZE6 | 72.0 | 70-0 | 75/1 |
| W16 | 2nd row, fixed window, driver side | \$145 | \$145 | \$145 |
| | if D93 must have F43+W70; if D93 & standard roof CHS produ | | 4410 | 92.15 |
| W17 | 2nd row, fixed window, passenger side | \$145 | \$145 | \$145 |
| | if D93 must have F43+W70; if D93 & standard roof CHS produ | | 44 10 | 42.10 |
| V33 | FMVSS 217 emergency exit | \$379 | \$379 | \$379 |
| | must have V31; not with D50/T19/W16 | | 45.5 | φ373 |
| N54 | Rear doors, opening to side wall | \$360 | \$360 | S |
| N5F | 90 Degree fixation point- Rear Doors | \$80 | \$80 | \$80 |
| _ | SoP and Plausibility TBD | 400 | 700 | 700 |
| V61 | Windows in rear doors | \$93 | \$93 | \$93 |
| | must have VA7/ if D51 must have F61; not with W78/(W70+- | | 755 | 200 |
| V70 | Black tinting (90%) for rear windows | \$138 | \$138 | \$138 |
| | not with W94; must have W16/W17/F02/((W61/W78)+H22); | | | (9436) |
| V73 | Bumper step, rear, grey | \$187 | \$187 | \$187 |
| | not with Q24/W75/W76 | | 710, | 710 7 |
| V75 | Step, wide, at rear end | \$308 | \$308 | \$308 |
| | not with JB6/JB7/Q24/QA9; must have R91+R92 | | , | |
| V76 | Bumper step, rear, spring-loaded | | \$601 | \$601 |
| | must have R91+R92; not with JB6/JB7/X30/Q24 | | | |
| V78 | Heated rear window(s) w/ washers/wipers | \$335 | \$335 | \$335 |
| | Must have H22+VA7 / if D51 must have F61; not with W61 | | | ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,, |
| 90 | Deletion of Sprinter badge, left rear door | \$0 | \$0 | \$0 |
| 93 - | Deletion of model badge, right rear door | \$0 | \$0 | \$0 |
| 2R | Conversion to RV requirement | | \$0 | \$0 |
| | must have B01+D93+E1X | | | |
| M4 | Acoustic package | \$87 | \$87 | 587 |
| | standard with CO2/CO3 | | | 1,000 |
| 10 | First-aid kit | \$27 | \$27 | \$27 |
| 26 | Wheel chocks | \$38 | \$38 | \$38 |
| 45 | Emergency flashlight | \$27 | \$27 | \$27 |
| 68 | Paint preservative | \$187 | \$212 | \$225 |
| 69 | Surface protection for stock vehicles | \$315 | \$315 | \$315 |
| К3 | Cargo straps, D-rings | \$81 | \$81 | \$81 |
| K4 | Cargo straps, lashing rails | \$104 | \$104 | \$104 |
| | must have V42/VV2; not with ZE6 | | | |
| E6 | Shelving prep | \$640 | \$640 | \$640 |
| | not with T93/H13/T19/V36/V42/VC4/VK8/VV2/YK4 | 7010 | 40 10 | 9010 |

| 144" 4C | 170" 4C | 170" E 4C |
|---------|----------------------------------|---|
| M3CA44 | M3CA44 M3CA74 907.653 907.655 | M3CAE4 |
| 907.653 | | 907.657 |
| \$300 | \$300 | \$300 |
| X | X | X |
| X | X | X |
| X | X | X |
| X | X | X |
| X | X | X |
| X | X | X |
| | M3CA44 907.653 \$300 X X X X X | M3CA44 M3CA74 907.653 907.655 \$300 \$300 X X X X X X X X X X X X X X |

| | \$381 | \$381 |
|---|-------|-------|
| X | X | X |
| X | X | X |
| | Χ | X X |

| X68 | Comfort Plus Package | \$1,923 | \$1,923 | \$1,923 |
|-----|--|---------|---------|---------|
| H15 | Heated front passenger seat | Х | X | X |
| H16 | Heated driver's seat | Х | X | X |
| SF1 | Driver's seat electrically adjustable | Х | X | X |
| SF2 | Co-driver's seat electrically adjustable | X | X | Х |

| C01 | Driver Convenience Package | \$760 | \$760 | \$760 |
|-----|--|-------|-------|-------|
| E46 | 12 V power outlet, driver seat base | X | X | Х |
| F64 | Electrically folding exterior mirrors | X | X | Х |
| FJ1 | Hinged lid for storage compartment | X | X | X |
| FJ5 | Hinged Lid for Storage Compartments left and right | X | X | Х |
| FZ9 | Keys, two additional masters | X | X | Х |
| JA7 | Blind Spot Assist | Х | X | Х |
| JW8 | Attention Assist | Х | Х | Х |

| C02 | Premium Package | \$983 | \$983 | \$983 |
|-----|--|-------|-------|-------|
| CL3 | Leather steering wheel | X | X | Х |
| | MBUX Multimedia System with 7" touchscreen | X | X | X |
| FM3 | Wet Wiper System | X | X | Х |
| JB4 | Active Lane Keeping Assist | X | X | X |
| JK5 | Instrument cluster with color display | X | X | X |

Ordering availability restricted, see NetStar for availability and restrictions|must have JF1 + XM4; must choose FR8/JB7/JB6

| CA2 | C02 in combination with C03 | \$604 | \$604 | \$604 |
|-----|---------------------------------------|-------|-------|-------|
| CL3 | Leather steering wheel | Х | X | Х |
| FM3 | Wet Wiper System | X | X | Х |
| JB4 | Active Lane Keeping Assist | X | X | Х |
| JK5 | Instrument cluster with color display | X | X | Х |

Packages

| 144" 4C | 170" 4C | 170" E 4C |
|---------|---------|-----------|
| M3CA44 | М3СА74 | M3CAE4 |
| 907.653 | 907.655 | 907.657 |

| Premium Plus Package | \$1,793 | \$1,793 | \$1,793 |
|--|---|--|--|
| Tray for smartphones incl. wireless charging | X | X | X |
| Navigation | X | Х | Х |
| | X | X | Х |
| MBUX Multimedia System with 10.25" touchscreen | X | X | Х |
| Free map data updates for 3 years | Х | X | Х |
| Front-to-rear outlet in instrument panel | Х | X | Х |
| Traffic Sign Assist | X | X | Х |
| Acoustic package | X | X | X |
| | Tray for smartphones incl. wireless charging Navigation Intelligent navigation MBUX Multimedia System with 10.25" touchscreen Free map data updates for 3 years | Tray for smartphones incl. wireless charging X Navigation X Intelligent navigation X MBUX Multimedia System with 10.25" touchscreen X Free map data updates for 3 years X Front-to-rear outlet in instrument panel X Traffic Sign Assist X | Tray for smartphones incl. wireless charging X X X Navigation X X Intelligent navigation X X MBUX Multimedia System with 10.25" touchscreen X X Free map data updates for 3 years X X Front-to-rear outlet in instrument panel X X Traffic Sign Assist X X |

| \$290 | \$290 | \$290 |
|-------|--------|-----------|
| X | X | Х |
| X | X | Х |
| | X X | X X X X X |

| X13 | Exterior Lighting Package | \$1,608 | \$1,608 | \$1,608 |
|--------|--|---------|---------|---------|
| | Fog lamp with cornering light function | X | X | X |
| L22 | Partial LED tail lights | X | X | Х |
| | High beam assist | X | X | Х |
| LG7 | LED high performance headlamps | X | X | Х |
| no res | strictions | | | |

| C06 | Cargo Convenience Package | \$658 | \$658 | \$658 |
|------|-------------------------------------|-------|-------|-------|
| E36 | Cutoff relay for additional battery | X | X | Х |
| ES2 | 12 V power outlet, rear compartment | X | X | Х |
| LC2 | LED light strip in load compartment | X | X | Х |
| T12 | Sliding door two stage opening | X | X | Х |
| T85 | Assist handle, left rear door | Х | X | Х |
| T86 | Assist handles, right rear door | Х | X | Х |
| W54 | Rear doors, opening to side wall | X | Х | S |
| must | have T74 OR (T77+D50) OR (T77+D51) | | , | |

| C07 | Cargo Protection Package | \$1,117 | \$1,117 | \$1,117 |
|-------|-----------------------------------|---------|---------|---------|
| V25 I | Half height load compartment trim | X | X | X |
| V42 | Lashing rails, waist level | X | X | Х |
| | Cargo lashing rails, head height | X | X | X |
| VK8 | Floor covering, plastic | X | X | Х |
| YK3 | Cargo straps, D-rings | X | Х | X |

3500 CARGO VAN - 4cyl Diesel Packages

| 144" 4C | 170" 4C | 170" E 4C |
|---------|---------|-----------|
| М3СА44 | M3CA74 | M3CAE4 |
| 907.653 | 907.655 | 907.657 |

| X66 | Heavy-Duty-Cargo Protection Package | \$2,043 | \$2,043 | \$2,043 |
|-------|---|---------|---------|---------|
| V43 | Wood floor with 6 D-rings | X | X | Х |
| V42 | Lashing rails, waist level | Х | X | Х |
| VA3 | Side wall paneling full hardboard | Х | X | Х |
| VC4 | Cargo lashing rails, head height | Х | X | Х |
| VV2 | Lashing rails, floor level (plus 4 anchors) | Х | X | Х |
| YK3 | Cargo straps, D-rings | X | X | Х |
| YK4 | Cargo straps, lashing rails | X | X | Х |
| not u | rith CO7 | | | |

| X69 | Swivel Seat Package | \$532 | \$532 | \$532 |
|------|--------------------------------------|-------|-------|-------|
| SR8 | Swivel base for driver's seat | × | X | Х |
| SR9 | Swivel base for front passenger seat | Х | X | Х |
| 587 | Driver's seat frame, low | X | X | Х |
| \$88 | Passenger seat frame, low | X | X | Х |

| X01 | Suspension Seating Package | \$940 | \$940 | \$940 |
|--------------|--|-------|-------|-------|
| SB3 | Driver suspension seat, comfort version | X | X | Х |
| | Passenger suspension seat, comfort version | X | X | X |
| | Driver's seat frame, low | Х | X | Х |
| S88 not v | Passenger seat frame, low | X | X | Х |

| 144" 6C | 170" 6C | 170" E 6C |
|---------|---------|-----------|
| M3CA46 | M3CA76 | M3CAE6 |
| 907.653 | 907.655 | 907.657 |

| | | 907.653 | 907.655 | 907.657 |
|---------------|---|---------|---------|----------|
| Engin | e | | | |
| | Engine/7-Speed Trans. | S | S | 5 |
| ED4 | AGM battery 12V 92 AH 850 A | S | S | S |
| G42 | Automatic transmission, 7G-tronic | S | S | S |
| MIO | ULEV emission | S | S | S |
| | 3.0L V6 turbo diesel engine | S | S | S |
| | Alternator 14 V/220 A | S | S | S |
| | choose while ordering | | | 7 |
| | Dual Rear Wheel | \$0 | \$0 | \$0 |
| RH7 | Tires LT 215/85 R16 | S | S | S |
| | 5.5 J x 16 steel wheels | S | S | S |
| | Unspecified tire brand | S | S | S |
| | Super Single Tire | \$385 | \$385 | \$385 |
| | 285/65 R 16 C super single tires | 0 | 0 | 0 |
| | Steel wheels: 8.5Jx16 Rr; 6.5Jx16 Pr | 0 | 0 | 0 |
| | Unspecified tire brand | 0 | 0 | 0 |
| _ | Tire pressure monitoring sensors | 0 | 0 | 0 |
| _ | ment | | U | U |
| • | Axle ratio 4.182 | S | S | S |
| 3A3 | Active Brake Assist | S S | S | <u> </u> |
| | Hold Function | S | S | S |
| | Multifunction steering wheel | S | S | S |
| - | Stabilization Level II | S | 5 | S |
| _ | Adjustable steering wheel (angle) | S | S | |
| | High roof | 0 | S | S |
| | Omission bulkhead | S | S | S |
| _ | Hill Start Assist | S S | 5 | S |
| _ | Standard radio | S | | S |
| _ | USB-C socket, 5 V | 5 | S | S |
| | Starter battery disconnect | 5 | S | S |
| _ | Pre-installation for switch panel | 5 | S S | S |
| - | Trailer hitch prep. wiring | S S | | S |
| | Preinstallation PSM | | S | \$ |
| _ | Ultracapacitor discharge module | 5 | S | S |
| _ | Body Builder Connector | S | S | S |
| | Jump start terminal | S | S | S |
| | Pre-installation for Mercedes me Remote Services | S | S | \$ |
| $\overline{}$ | Emergency Call System | S | 5 | S |
| _ | Breakdown management | S | S | \$ |
| $\overline{}$ | Shelf above windshield | S | S | S |
| _ | Heated & electrically adjustable exterior mirrors | S | S | S |
| G8 | Cupholder front | S | S | 5 |
| 11 | Cupholder front Remote key (315 mhz) w/central locking | S | S | 5 |
| | Storage compartment underneath cockpit | S | \$ | S |
| _ | | S | S | 5 |
| - | Rear view camera (rear-view mirror display) | \$ | S | S |
| _ | Windshield with filter band | S | S | S |
| - | Heater, auxiliary electric hot air | S | S | S |
| - | Air Condition, Front | S | S | S |
| - | Head Unit, North America | S | S | S |
| _ | Speedometer, miles and km/h | S | S | S |
| | Seat belt warning for co-driver seat | S | S | - 5 |
| $\overline{}$ | Seat belt reminder driver | S | S | S |
| $\overline{}$ | Outside temperature gauge | S | S | S |
| | Crosswind Assist | S | S | S |
| _ | Communication module (LTE) for dig. services | S | S | S |
| | Service interval 20.000 miles | S | S | \$ |
| | Red diesel filler cap | S | \$ | \$ |
| 60 | Exhaust straight to rear | S | 5 | S |

3500 CARGO VAN - 6cyl Diesel Standard Equipment

| | | 144" 6C | 170" 6C | 170" E 6C |
|------|--|---------|---------|-----------|
| | | M3CA46 | M3CA76 | M3CAE6 |
| | | 907.653 | 907.655 | 907.657 |
| KB7 | 24.5 gallon fuel tank | S | S | S |
| KL1 | Aux fuel sending unit w/ fuel tap | S | S | S |
| KL5 | Fuel filter with water separator | \$ | S | S |
| KP6 | 3rd generation SCR emission control system | S | S | S |
| L65 | Interior lights, cargo compartment | S | S | S |
| L94 | Parking lights deletion | S | S | S |
| LA2 | Headlight assistant | S | S | S |
| LB5 | 3rd brake light | S | S | S |
| MS1 | Cruise control | S | S | S |
| P47 | Front mudflaps | S | S | S |
| P48 | Rear mudflaps | S | S | S |
| Q11 | Longitudinal member reinforcement | S | S | S |
| R65 | Spare tire bracket below frame | S | S | S |
| R87 | Spare tire | S | S | S |
| RM0 | All-season tires | S | S | S |
| 502 | Standard driver seat | S | S | S |
| 504 | Standard front passenger seat | S | 5 | S |
| 522 | Armrest for driver's seat | S | S | \$ |
| \$25 | Armrest for front passenger seat | S | S | S |
| SA5 | Front airbag, driver | S | S | S |
| SA6 | Front airbag, passenger | S | S | \$ |
| 5H1 | Thorax-pelvis sidebag, driver | S | S | S |
| SH2 | Thorax-pelvis sidebag, co-driver | S | S | S |
| SH9 | Airbag, driver/passenger window | S | S | S |
| SK2 | Seat occupancy sensor, driver's seat | S | S | S |
| Г16 | Sliding door, passenger side | S | S | S |
| /93 | Without factory installed flooring | S | \$ | S |
| /94 | Cable duct - side wall | S | S | S |
| /95 | Cable duct - rear portal | S | S | S |
| N54 | Rear doors, opening to side wall | 0 | 0 | S |
| (B3 | GVWR 9,990 lbs. / 4,531 kg | S | S | S |
| /43 | Jack, hydraulic | S | S | S |
| | | | | |

| | | 144" 6C | 170" 6C | 170" Ext.60 |
|------|--|---------|--------------|-------------|
| | | M3CA46 | M3CA76 | М3САЕ6 |
| | | 907.653 | 907.655 | 907.657 |
| 150 | Front axle reinforced | \$346 | \$346 | \$346 |
| AP2 | Addtl. bar for driveshaft & exhaust extension | \$69 | \$69 | 93.10 |
| R2 | Axle ratio 3.923 | \$0 | \$0 | SO |
| | not with AR3 | | | 1000 |
| 301 | ESP for increased Center of Gravity above 39.4" | - | \$0 | 50 |
| | must have CB4/CB8/X30; not with RH0/CB7 | | F | 1.5 |
| 3E2 | Handbrake lever, folding | \$55 | \$55 | \$55 |
| | not with B25; X69 choose B25/BE2 | 1 700 | 700 | 100 |
| 72 | Bumpers front/rear primed | \$268 | \$268 | \$268 |
| | must have CN2 (part of X67), not with CM0 | 7-1-1 | 7-0-0 | 7 |
| .B4 | Stabilization Level III | \$187 | \$187 | \$187 |
| | not with CB1/CB7/CB8/X30 | V-3. | V 207 | y a o ! |
| E8 | Raised rear body mounts | \$252 | \$252 | \$252 |
| L3 | Leather steering wheel | \$187 | \$187 | \$187 |
| | must have (C02/E3M)/C03 + (ET4/MS1) | 9107 | 7107 | 7101 |
| OM2 | Painted metallic front & rear bumper | \$587 | \$587 | \$587 |
| 1410 | must have (CN2/X67) + (JA7/C01) + (JB6/JB7) + (7755/9197/9775) | 100/ | 1001 | 730/ |
| M9 | Primed side moldings | \$364 | \$364 | \$364 |
| 203 | High roof | \$2,900 | \$304 S | \$354 S |
| 13 | | | | |
| - | Mounting rails for roof rack | \$300 | \$300 | \$300 |
|)22 | Fixed sunroof (rear roof section) | \$336 | \$336 | \$336 |
| .50 | not with H08/HK4/H72/V36/ZK4 | 4000 | Anno | Anna |
| 050 | Cargo partition | \$288 | \$288 | \$288 |
| | not with D51/D93/H08/HK4/T74/V36; must have one of T93/T77 | 4224 | 4 | 3000 |
|)51 | Cargo partition with 1 window | \$335 | \$335 | \$335 |
| | not with D50/D93/H08/HK4/T74/V37/D17; must have one of T93/T7; | | | |
| 1B | Tray for smartphones incl. wireless charging | \$156 | \$156 | \$156 |
| | must have CO2/E3M + H1I | | | |
| 1E | Navigation | \$728 | \$728 | \$728 |
| | must have CO2/E3M, not with CO3 | 4 | | 4 |
| 15 | Sirius XM, satellite radio | \$255 | \$255 | \$255 |
| | must have CO2/E3M/CO3 | | | |
| 1X | MBUX multimedia 6-hour runtime | - | \$0 | \$0 |
| | must have X2R + (CO2+E1E/E1S)/CO3/(E3M+E1E/E1S) | | 022.20 | 100000 |
| 1R | Additional Fuses (40/80/150/100 Ampere) | \$50 | \$50 | \$50 |
| | SoP and Plausibility TBD | | | |
| 1Y | Additional Fuses (40/80/80/100 Ampere) | \$50 | \$50 | \$50 |
| | SoP and Plausibility TBD | | | |
| 2A | Access point for BB special signals in cockpit | \$29 | \$29 | \$29 |
| 21 | Additional battery, co-driver seat base | \$248 | \$248 | \$248 |
| | must have E36/C06; not with E2M/F09; CHS production only | | | |
| 2M | Additional battery, engine compartment | \$248 | \$248 | \$248 |
| | must have X01+ (E36/C06); not with E2I/X69/F09 | | | |
| 3M | MBUX Multimedia System with 7" touchscreen | \$474 | \$474 | \$474 |
| | not with CO2/CO3; must have JK5+(JB7/JB6/JB8/FR8) | | | |
| 36 | Cutoff relay for additional battery | \$110 | \$110 | \$110 |
| | standard with E2I/E2M | | | |
| 46 | 12 V power outlet, driver seat base | \$92 | \$92 | \$92 |
| 5M | Extension of PSM standard contact | \$58 | \$58 | \$58 |
| D5 | Parametric special module (PSM) | \$317 | \$317 | \$317 |
| | not with ED8 | | | |
| E3 | 115 V socket | \$125 | \$125 | \$125 |
| P7 | Basic electric fitting for rear loudspeakers | \$68 | \$68 | \$68 |
| S2 | 12 V power outlet, rear compartment | \$92 | \$92 | \$92 |
| 55 | Charging package, dashboard | \$82 | \$82 | \$82 |
| T4 | Active Distance Assist DISTRONIC | \$263 | \$263 | \$263 |
| * 1 | | 7207 | 7200 | 7200 |

| | | 144" 6C | 170" 6C | 170" Ext.60 |
|--------------------------------------|---------------------------------------|---------|---------|---------------------------------------|
| | | M3CA46 | M3CA76 | M3CAE6 |
| | | 907.653 | 907.655 | 907.657 |
| 1K Coat hooks in di | river cabin | \$14 | \$14 | \$14 |
| must have D50/ | | 72. | 72. | , , , , , , , , , , , , , , , , , , , |
| 49 Electrically heat | | \$218 | \$218 | \$218 |
| no restriction | | | | |
| 61 Interior rear vie | w mirror | \$36 | \$36 | \$36 |
| not with D50; m | ust have CO2/E3M/CO3 | | | |
| E9 Additional DIN-s | slot | \$81 | \$81 | \$81 |
| F8 Overhead storage | ge slot, front center | \$105 | \$105 | \$105 |
| J1 Hinged lid for st | orage compartment | \$93 | \$93 | \$93 |
| R8 Rear view came | ra (head unit display) | \$336 | \$336 | \$336 |
| must have CO2/ | E3M; not with FR3/JB7/JB6/JB8 | | | |
| Y1 Security alarm v | v. interior motion sensor | \$584 | \$584 | \$584 |
| must have LC4/0 | 200 | | | |
| Y7 Optional 3-butte | on keys | \$36 | \$36 | \$36 |
| Z9 Keys, two additi | onal masters | \$121 | \$121 | \$121 |
| | duct to rear compartment | \$59 | \$59 | \$59 |
| not with D50/D5 | | | | |
| | rear compartment | \$156 | \$156 | \$156 |
| | V25/VA3/VA1/C07/X66 | | - | |
| Heat insulation, | | \$187 | \$187 | \$187 |
| if + D50/D51 mu | | | | |
| 108 Air conditioning | | \$2,872 | \$2,872 | \$2,872 |
| | +V36; not with HK4/C06/X66/C07 | | - | |
| | eater/booster (17K BTU) | \$1,116 | \$1,116 | \$1,116 |
| not with HZ9 | | | | 1 4 |
| 113 Rear cabin heat | | \$786 | \$786 | \$786 |
| must have H12/ | | 4004 | 4001 | éna. |
| Heated front pa | | \$284 | \$284 | \$284 |
| must have H16; | | ¢204 | čana. | ¢204 |
| Heated driver's | | \$284 | \$284 | \$284 |
| must have H15; 122 Rear window de | | \$253 | \$253 | \$253 |
| | /W78; standard for W61+W70 | 3233 | \$233 | 7233 |
| 172 Roof fan, electri | | \$400 | \$400 | \$400 |
| not with D22/V3 | | 2400 | 3400° | 9400 |
| 188 Rear heater pre | | \$405 | \$405 | \$405 |
| | HZ9; not with H13/T19 | Ş-03 | 2400 | Q-103 |
| | itlet in instrument panel | \$0 | \$0 | \$0 |
| must have FJ1/C | | 40 | 70 | |
| | utomatic climate control | \$337 | \$337 | \$337 |
| | f +H13 must have H08/HK4 | | | |
| K4 Rear air condition | | \$3,940 | \$3,940 | \$3,940 |
| | V36+D93; not with H08/ZB6/ZE6/N62/N63 | | 1500000 | |
| | r booster (18,000 BTU) | \$676 | \$676 | \$676 |
| not with H12 | | | | |
| 51 Fuel gauge, opti | mized for aux. fuel tap | \$72 | \$72 | \$72 |
| not with HZ9/H3 | 12 . | | | |
| 52 Engine oil level | display at cold start | \$0 | \$0 | \$0 |
| A7 Blind Spot Assist | t · | \$450 | \$450 | \$450 |
| must have F64; | not with CO1 | | | |
| B4 Active Lane Kee | ping Assist | \$288 | \$288 | \$288 |
| standard with C | 02/CA2 | | | |
| B6 Parking Package | with 360 degree camera | \$775 | \$775 | \$775 |
| must have CO2/ | C03/E3M; not with W75/W76/JB7 | | | |
| B7 Parking Package | | \$615 | \$615 | \$615 |
| must have CO2/ | C03/E3M; not with W75/W76/JB6 | | | |
| B8 360 Degree Cam | iera | \$685 | \$685 | \$685 |
| | ility TBD | | | |

| | | 144" 6C | 170" 6C | 170" Ext.60 M3CAE6 |
|------|---|---------|---------------|-----------------------|
| | | M3CA46 | M3CA76 | |
| | | 907.653 | 907.655 | 907.657 |
| IF1 | Rain sensor | \$106 | \$106 | \$106 |
| K5 | Instrument cluster with color display | \$144 | \$144 | \$144 |
| | standard with CO2/CA2 | | | |
| | Backup alarm | \$99 | \$99 | \$99 |
| W2 | Deactivation lamp monitoring failure | \$27 | \$27 | \$27 |
| IW8 | Attention Assist | \$49 | \$49 | \$49 |
| (51 | Misfueling prevention for Diesel | \$49 | \$49 | \$49 |
| ⟨52 | DEF fluid filler cap - lockable | \$27 | \$27 | \$27 |
| .13 | Fog lamp with cornering light function | \$199 | \$199 | \$199 |
| 71 | Light/motion sensor in rear compartment | \$54 | \$54 | \$54 |
| | not with V36 | | • | 7- |
| B9 | Illuminated front exits | \$151 | \$151 | \$151 |
| .C2 | LED light strip in load compartment | \$263 | \$263 | \$263 |
| | not with H08/HK4/V36/C06 | | , | 7 |
| .C4 | Comfort overhead control panel | \$93 | \$93 | \$93 |
| V120 | Speed limitation 65 mph | \$60 | \$60 | \$60 |
| | not with MD3 | | | 700 |
| MD3 | Top speed limitation 75 mph | \$60 | \$60 | \$60 |
| | not with M20 | | | |
| V62 | Front engine bracket for additional alternator | \$467 | \$467 | \$467 |
| | not with HK4/N63 | | 7 | Ţ.U, |
| V63 | Front engine bracket for auxiliary A/C compressor | \$467 | \$467 | \$467 |
| | not with HK4/N62 | | , , , | Ψ101 |
| 93 | Omission of D-rings | -\$15 | -\$15 | -\$15 |
| | not with D93/V43/VK8 | | | 720 |
| QA2 | Trailer cross member 7,500 lbs capacity | \$186 | \$186 | |
| | not with W73/W75/W76/Q24/Q67 | | | |
| QA9 | Half-sided step rear (for trailer hitch) | \$101 | \$101 | \$101 |
| | must have Q24/QA2; not with W73/W75/W76 | | | |
| 24 | Trailer hitch, 5,000 lbs | | | \$147 |
| | not with W73/W75/W76 | | | |
| 191 | Spare tire deletion | -\$110 | -\$110 | -\$110 |
| | must have R92; not with R87 | | | 7 |
| 92 | Spare tire carrier deletion | \$0 | 50 | \$0 |
| | must have R91; not with R65 | | | |
| 98 | Rims painted jet black | \$81 | \$81 | \$81 |
| | not with RL5/RM2 | | 1,000 | 7.00 |
| F.1 | Tire brand Continental | \$0 | \$0 | \$0 |
| | must have RM1 + RM9 | | To the second | -,4.0 |
| F8 | Tire brand Michelin | \$0 | SO I | \$0 |
| | must have RM9; not with RM1 | | | ** |
| НО | Tire brand Kumho | \$0 | \$0 | \$0 |
| | must have RM9; not with RM1 | 70 | 75 | 49 |
| M1 | M+S winter tires | \$169 | \$169 | \$169 |
| | must have RF1/RD9; not with RF8/RH0/X31 | \$105 | 7103 | 2100 |
| M2 | Rims painted arctic white | \$81 | \$81 | \$81 |
| | not with R98/RL5 | 701 | 201 | 201 |
| M9 | Specially requested tires | \$101 | \$101 | \$101 |
| | must have RF1/RF8/RH0; not with RD9 | 2101 | 9101 | J101 |
| 23 | Twin front passenger seat | \$400 | \$400 | \$400 |
| _ | not with C00/X68/X01 | →+00 | γ -100 | 2400 |
| | Armrest, driver and passenger door | \$51 | \$51 | ČE1 |
| _ | Seat belts orange, driver and front passenger | \$32 | \$32 | \$51 \$32 |
| _ | not with S23 | 334 | 232 | \$32 |
| - | Driver's seat plus | \$238 | ¢220 | casa |
| | must have VF7; not with COO/X68/X69 | \$238 | \$238 | \$238 |
| | Storage net, driver's seat backrest | cc4 | CCA T | ėc. |
| _ | Storage net, driver a seat backrest Storage net, passenger seat backrest | \$64 | \$64 | \$64 |
| | and a many basseringer acat packingst | \$64 | \$64 | \$64 |

| | | 144" 6C | 170" 6C | 170" Ext.60 |
|-----|--|----------------|---------|-------------|
| | | M3CA46 | M3CA76 | M3CAE6 |
| | | 907.653 | 907.655 | 907.657 |
| T12 | Sliding door two stage opening | \$82 | \$82 | 582 |
| | not with T55 | | 1000 | |
| 19 | Sliding door, driver's side | \$935 | \$935 | \$935 |
| | not with H13/H88/VC5/ZE6/F43/W16/F02; if +V36 must have D03 | | | |
| Γ50 | Electric closing assist right sliding door | \$335 | \$335 | \$335 |
| | must have D03; not with T55/T93 | | | |
| 51 | Electric closing assist left sliding door | \$335 | \$335 | \$335 |
| | must have T19 + D03 | | | |
| 55 | Electric sliding door right | \$831 | \$831 | \$831 |
| | must have D03 + (FY7+T16); not with T12/T50 | | | |
| 57 | Electric sliding step | \$1,071 | \$1,071 | \$1,071 |
| | must have ED5; not with T93 | | | |
| 60 | Opening limiter electrically operated sliding door | \$120 | \$120 | \$120 |
| | must have T55 | | | |
| 74 | Assist handle, B-pillar | \$32 | \$32 | \$32 |
| | must have D93; not with T77 | | | |
| | Door-mounted assist handles, driver & passenger | \$59 | \$59 | \$59 |
| 77 | Assist handle w/ partition | \$32 | \$32 | \$32 |
| | must have D50/D51/D64 | | | |
| 85 | Assist handle, left rear door | \$32 | \$32 | \$32 |
| 86 | Assist handles, right rear door | \$32 | \$32 | \$32 |
| 93 | Sliding door right side deletion | \$0 | \$0 | \$0 |
| | not with T16/T50/T57/VK8/VC5 | | | |
| 07 | Cab rear wall liner | \$360 | \$360 | \$360 |
| | must have (D50/D51)+F1K; standard with H04 | | | |
| 21 | Luxury interior Trim | \$661 | \$661 | \$661 |
| 0.4 | must have VA5/VA7; not with V52/VA1/VA3 | | | |
| | Pallet support in sliding door step | \$96 | \$96 | \$96 |
| | must have (V43/X66)+(D50/D51); not with VK8/V93/C07 | | | |
| | Half height load compartment trim | \$201 | \$201 | \$201 |
| | not with VA1/VA3/VA5/V52/X66 | | | |
| - | Window pillar trim | \$513 | \$513 | \$513 |
| | must have V36 + (V21/VA1) + (F02/F03/F07); not with V42 | | | |
| - | Wheel house covering | \$105 | \$105 | \$105 |
| | if +V43 must have V25/VA1/VA3; not with V52 | | | |
| | Roof trim | \$876 | \$876 | \$876 |
| | must have D93; not with D17/D22/H72/L65/L71/LC2/VA3/V42/ZE6/(1 | 93+-D03)/X66/C | 06/C07 | |
| | Lashing rails, waist level | \$277 | \$277 | \$277 |
| | not with V36/ZE6 | | | |
| | Wood floor with 6 D-rings | \$422 | \$422 | \$422 |
| | not with P93/V93/VL4/VK8/C07; standard with D93/H13/V24/V52/VC | | | |
| - | Floor cover behind seat box | \$27 | \$27 | \$27 |
| | must have D93; not with D50/D51/D56/D62/D64/V43/VK5 | | | |
| | Full paneling, right sliding door | \$109 | \$109 | \$109 |
| | not with P93/V93/VL4/VK8/C07; standard with D93/H13/V24/V52/VC | | | |
| _ | Cigarette lighter & ash cup, front | \$39 | \$39 | \$39 |
| | Side wall paneling waist height PVC | \$319 | \$319 | \$319 |
| | must have VA5/VA7; not with V52 | | | |
| | Side wall paneling full hardboard | \$444 | \$444 | \$444 |
| _ | not with V36/F02; if T93 must have (D50/D51) | | | |
| - | Full paneling, hinged rear doors | \$38 | \$38 | \$38 |
| _ | must have D03+VA7+(W61/W78); not with V25 | | | |
| _ | Storage compart. w/ net in rear doors | \$127 | \$127 | \$127 |
| | must have W61/W78; not with V52 | | | |
| | Cargo lashing rails, head height | \$415 | \$415 | \$415 |
| | must have V42/C07/X66; not with ZE6 | | | |
| | Door sill - protective edge | \$71 | \$71 | \$71 |

| | | 144" 6C | 170" 6C | 170" Ext.6C |
|-----|--|---------|--------------|--------------|
| | | M3CA46 | МЗСА76 | M3CAE6 |
| | | 907.653 | 907.655 | 907.657 |
| VK8 | Floor covering, plastic | \$370 | \$370 | \$370 |
| | not with V43/P93/T19/T93/V52/VC5/X66 | | | |
| VV2 | Lashing rails, floor level (plus 4 anchors) | \$270 | \$345 | \$377 |
| | must have V43; not with V93/VC5/ZE6 | | 7 | 4-11 |
| W16 | 2nd row, fixed window, driver side | \$145 | \$145 | \$145 |
| | if D93 must have F43+W70; if D93 & standard roof CHS | | 7-0- | 7=10 |
| W17 | 2nd row, fixed window, passenger side | \$145 | \$145 | \$145 |
| | if D93 must have F43+W70; if D93 & standard roof CHS | | 7 | 72.10 |
| W33 | FMVSS 217 emergency exit | \$379 | \$379 | \$379 |
| | must have V31; not with D50/T19/W16 | 73.5 | 42.5 | 4373 |
| W54 | Rear doors, opening to side wall | \$360 | \$360 | S |
| | 90 Degree fixation point- Rear Doors | \$80 | \$80 | \$80 |
| | SoP and Plausibility TBD | 700 | 200 | 900 |
| W61 | Windows in rear doors | \$93 | \$93 | \$93 |
| | must have VA7/ if D51 must have F61; not with W78/(W | | 433 | \$33 |
| W70 | Black tinting (90%) for rear windows | \$138 | \$138 | \$138 |
| | not with W94; must have W16/W17/F02/((W61/W78)+F | | | 9100 |
| W73 | Bumper step, rear, grey | \$187 | \$187 | \$187 |
| | not with Q24/W75/W76 | 720. | V10 , | 7107 |
| N75 | Step, wide, at rear end | \$308 | \$308 | \$308 |
| | not with JB6/JB7/Q24/QA9; must have R91+R92 | 7000 | 7300 | \$350 |
| N76 | Bumper step, rear, spring-loaded | | \$601 | \$601 |
| | must have R91+R92; not with JB6/JB7/X30/Q24 | | 7001 | 7001 |
| W78 | Heated rear window(s) w/ washers/wipers | \$335 | \$335 | \$335 |
| | Must have H22+VA7 / if D51 must have F61; not with W | | 4333 | 7555 |
| (90 | Deletion of Sprinter badge, left rear door | \$0 | \$0 | \$0 |
| | Deletion of model badge, right rear door | \$0 | \$0 | \$0 |
| | Conversion to RV requirement | - | \$0 | \$0 |
| | must have B01+D93+E1X | | 40 | 40 |
| (M4 | Acoustic package | \$87 | \$87 | \$87 |
| | standard with C02/C03 | | ,,,, | 781 |
| 10 | First-aid kit | \$27 | \$27 | \$27 |
| ′26 | Wheel chocks | \$38 | \$38 | \$38 |
| 45 | Emergency flashlight | \$27 | \$27 | \$27 |
| | Paint preservative | \$187 | \$212 | \$225 |
| | Surface protection for stock vehicles | \$315 | \$315 | \$315 |
| 'K3 | Cargo straps, D-rings | \$81 | \$81 | \$81 |
| | Cargo straps, lashing rails | \$104 | \$104 | \$104 |
| | must have V42/VV2; not with ZE6 | 7.77 | 7.0, | 7.01 |
| E6 | Shelving prep | \$640 | \$640 | \$640 |
| | not with T93/H13/T19/V36/V42/VC4/VK8/VV2/YK4 | 1 \$5.0 | 20-10 | 7070 |

| | | 144" 6C | 170" 6C | 170" E 6C |
|-------|-----------------------------------|---------|----------------------------------|-------------------|
| | | M3CA46 | M3CA46 M3CA76 907.653 907.655 | M3CAE6 907.657 |
| | | 907.653 | | |
| C00 C | Comfort Package | \$300 | \$300 | \$300 |
| LC4 C | Comfort overhead control panel | X | X | X |
| SE4 L | umbar support, co-driver's seat | X | X | X |
| SE5 L | umbar support, driver's seat | X | X | Х |
| SKO C | Comfort head restraint, driver | X | Х | X |
| SK1 C | Comfort head restraint, co-driver | X | X | X |
| 528 A | rmrest, driver and passenger door | X | X | X |

| | | \$381 |
|---|---|-------|
| X | X | X |
| X | X | X |
| | X | X X X |

| | Comfort Plus Package | \$1,923 | \$1,923 | \$1,923 |
|-----|--|---------|---------|---------|
| H15 | Heated front passenger seat | X | X | X |
| H16 | Heated driver's seat | X | X | X |
| SF1 | Driver's seat electrically adjustable | X | X | X |
| SF2 | Co-driver's seat electrically adjustable | X | Х | X |

| C01 | Driver Convenience Package | \$760 | \$760 | \$760 |
|-----|--|-------|-------|-------|
| E46 | 12 V power outlet, driver seat base | X | X | Х |
| F64 | Electrically folding exterior mirrors | X | Х | X |
| FJ1 | Hinged lid for storage compartment | X | Х | X |
| FJ5 | Hinged Lid for Storage Compartments left and right | Х | X | X |
| FZ9 | Keys, two additional masters | X | X | X |
| JA7 | Blind Spot Assist | Х | X | X |
| JW8 | Attention Assist | X | X | X |

| \$983 | \$983 | \$983 |
|-------|-------|-------|
| Х | X | X |
| X | X | Х |
| X | X | Х |
| X | X | Х |
| X | X | X |
| | \$983 | X X |

Ordering availability restricted, see NetStar for availability and restrictions|must have JF1 + XM4; must choose FR8/JB7/JB6

| CA2 | C02 in combination with C03 | \$604 | \$604 | \$604 |
|-----|---------------------------------------|-------|-------|-------|
| CL3 | Leather steering wheel | Х | Х | Х |
| FM3 | Wet Wiper System | X | X | Х |
| JB4 | Active Lane Keeping Assist | X | X | X |
| JK5 | Instrument cluster with color display | X | Х | X |

| 144" 6C | 170" 6C | 170" E 6C |
|---------|---------|-----------|
| M3CA46 | M3CA76 | M3CAE6 |
| 907.653 | 907.655 | 907.657 |

| C03 | Premium Plus Package | \$1,793 | \$1,793 | \$1,793 |
|-----|--|---------|------------------|---------|
| E1B | Tray for smartphones incl. wireless charging | X | X X X X | X |
| | Navigation | X | X | Х |
| EY2 | Intelligent navigation | X | X | Х |
| E4M | MBUX Multimedia System with 10.25" touchscreen | X | X | Х |
| EX9 | Free map data updates for 3 years | X | Х | Х |
| H1I | Front-to-rear outlet in instrument panel | X | Х | X |
| A9 | Traffic Sign Assist | X | X | X |
| XM4 | Acoustic package | X | X | X |

| | \$290 | \$290 |
|---|-------|-------|
| X | X | X |
| X | X | Х |
| | X | X X X |

| \$1,608 | \$1,608 | \$1,608 |
|---------|-----------------------------|---------------------------------------|
| X | X | X |
| X | X | X |
| X | X | Х |
| X | Х | Х |
| | \$1,608 X X X X | X X X X X X X X X X X X X X X X X X X |

| \$658 | \$658 | \$658 |
|-------|----------------------------|---------------------------------------|
| X | X | Х |
| X | Х | X |
| Х | Х | Х |
| X | Х | Х |
| X | Х | Х |
| X | Х | X |
| X | Х | Х |
| | X X X X X X | X X X X X X X X X X X X X X X X X X X |

| V | \$1,117 | \$1,117 |
|-----|-------------|---------------------------------------|
| 1 X | X | X |
| X | Х | X |
| Х | X | X |
| X | X | X |
| X | X | X |
| | X X X | X X X X X X X X X X X X X X X X X X X |

3500 CARGO VAN - 6cyl Diesel Packages

| 144" 6C | 170" 6C | 170" E 6C |
|---------|---------|-----------|
| M3CA46 | M3CA76 | M3CAE6 |
| 907.653 | 907.655 | 907.657 |

| X66 | Heavy-Duty-Cargo Protection Package | \$2,043 | \$2,043 | \$2,043 |
|------|---|---------|---------|---------|
| V43 | Wood floor with 6 D-rings | X | Х | X |
| V42 | Lashing rails, waist level | X | Х | X |
| V52 | Loadable wheel arch | X | X | X |
| VA3 | Side wall paneling full hardboard | X | X | X |
| VC4 | Cargo lashing rails, head height | X | Х | X |
| /V2 | Lashing rails, floor level (plus 4 anchors) | X | X | X |
| /K3 | Cargo straps, D-rings | X | Х | X |
| /K4 | Cargo straps, lashing rails | X | X | X |
| ot v | vith CO7 | | | |

| X69 | Swivel Seat Package | \$532 | \$532 | \$532 |
|-----|--------------------------------------|-------|-------|-------|
| SR8 | Swivel base for driver's seat | х | Х | X |
| SR9 | Swivel base for front passenger seat | X | X | X |
| S87 | Driver's seat frame, low | × | X | Х |
| S88 | Passenger seat frame, low | X | Х | X |

| \$940 | \$940 | \$940 |
|-------|---------------------------|-------|
| X | × | X |
| Х | X | Х |
| Х | X | Х |
| X | X | Х |
| | \$940 X X X X | X X X |