

Hyundai 2.5 to 4.5 CY Wheel Loaders Options Page:

	<u>HL930A/XT/TM</u>	<u>HL940A/XT/TM</u>	<u>HL955A/HD/HDXT/XT/TM</u>	<u>HL960A/HD/HDXT/XT</u>
2.5 CY Bucket	\$4,650	\$4,877	\$0	\$0
3/3.25 CY Bucket	\$0	\$5,361	\$0	\$0
3.75 CY Bucket	\$0	\$0	\$6,883	\$0
4.3 CY Bucket	\$0	\$0	\$0	\$10,021
Hyun Quick Coupler:	\$6,145	\$6,465	\$7,179	\$8,158
Belly Pan Guard:	\$630	\$662	\$753	\$815
Rear View Camera:	Standard	Standard	Standard	Standard
AAVM 360 Degree Camera:	\$3,310	\$3,310	\$3,950	\$4,050
2nd Monitor and Rear Detect:	\$2,208	\$2,208	\$2,208	\$2,208
Full LED Light Package:	\$6,144	\$6,144	\$6,144	\$6,228
Auto Lube System:	\$8,643	\$8,952	\$9,343	\$9,919

ADD OPTIONS ABOVE and many other attachments through various vendors