

Hyundai 2.5 to 4.5 CY Wheel Loaders Options Page:

	<u>HL930A/TM</u>	<u>HL940A/XT/TM</u>	<u>HL955A/HD/HDXT/XT/TM</u>	<u>HL960A/HD/HDXT/XT</u>
2.5 CY Bucket	\$7,480	\$0	\$0	\$0
3/3.25 CY Bucket	\$0	\$8,240	\$0	\$0
3.7 CY Bucket	\$0	\$0	\$10,390	\$0
4.3 CY Bucket	\$0	\$0	\$0	\$15,080
Hyun Quick Coupler:	\$9,360	\$9,740	\$10,840	\$12,020
Belly Pan Guard:	\$690	\$690	\$810	\$815
Rear View Camera:	Standard	Standard	Standard	Standard
AAVM 360 Degree Camera:	\$3,470	\$3,590	\$3,950	\$4,090
2nd Monitor and Rear Detect:	\$2,420	\$2,420	\$2,320	\$2,380
Full LED Light Package:	\$7,870	\$7,980	\$7,870	\$7,830
Auto Lube System:	\$11,920	\$12,500	\$12,960	\$13,290
XT Package:	\$2,973	\$3,268	\$3,356	\$5,120

ADD OPTIONS ABOVE and many other attachments through various vendors