Version 2

MY24



Dealer Ordering Guide



Publish date: 8/30/2023

MY24 eSprinter - Changes & Model Overview

| | MY24 eSprinter |
|----------------------|---|
| Model Designation | Model designation is "The all-new eSprinter". Due to readibility the term eSprinter is used in this DOG. For Model nomenclature 1st digit is changing due to electric powertrain launch. eSprinter is reflected with a "E". Internal combustion engine (ICE) Sprinter is reflected with "M": - eSprinter 2500 Cargo 170" WB Standard Output is E2CA7S - ICE Sprinter 2500 Cargo 170" WB Standard Output is M2CA7S. |
| Models | eSprinter 2500 Cargo 170" Wheelbase models are new addition to the Sprinter line. |
| Motor | M1E - New Electric Motor M5E - New Electric Motor Output 100 kw M9E - New Electric Motor Output 150 kw |
| Battery | E9V - High-Voltage battery (113kwh) |
| Charging | E95 - Typ 1 Vehicle Socket for electric vehicle E8A - AC Charging 9.6 kw E5J - DC Charging 50 kw E6J - DC Charging 110 kw (Optional) |
| Now Standard | JE1 - Integrated Service Package B25 - Electric parking brake J2A - Acoustic Presence Indicator H1K - Pre-Entry Climate Control ED1 - AGM battery 12V 70AH EW5 - Pre-Installation: Remote and Charging Services Premium EW8 - Pre-installation: Remote and navigation services H16 - Heated driver's seat JK5 - Instrument cluster with color display MD3 - Top speed limitation 75 mph W73 - Bumper step, rear, grey Until further notice eSprinter orders require customers to select a partition wall and a floor option during the new model launch phase. |
| Packages | New Comfort Steering Plus Package CS1 replaces X68. New Premium Plus Package MB1 replaces C02 and C03. New Navigation Charging Package NC1. New Rear Door Convenience Package CR1. New Upfit Prep and Load Restraining Package UL1. CA2, X01, X67 Package discontinued. |
| Optional Features | E7M - MBUX Multimedia System (new Generation) ED4 - AGM battery 12V 92 AH 850 A CK8 - Heated Steering Wheel E7B - Pre-Installation: Navigation E2O - Settings Charging Program Limited E1Q - Deactivitation of Recuperation stage selection Parking packages, Distronic, Active Lane Keeping Assist, Traffic Sign Assist (JB4, ET4, JA9, JB6, JB7, JB8, JB9) not available in MY24 eSprinter. |

MY24 eSprinter MSRP Overview

| Model | GVWR | Wheelbase | Engine | Roof | MB Model | MSRP* |
|------------------------|-----------|-----------|--------------|--------|----------|----------|
| Cargo 9.370 lbs | 170" WB | EV - SO | SO HR E2CA75 | E2CA7S | \$71,886 | |
| Cargo | 3,370 103 | 170 WB | EV - HO | HR | E2CA7H | \$75,316 |

SO: Standard Output engine 100 kw HO: High Output engine 150 kw

Until further notice eSprinter orders require customers to select a partition wall and a floor option during the new model launch phase. The displayed base price does not include this equipment. Please select a partition wall and a floor option during the build process. The available partition walls and floor options are displayed in the option section of this DOG.

^{*}MSRP excludes destination and delivery \$2,295.

MY24 Exterior Paint Overview

| Code | Description | Price | Paint | Code | Description | Price | Paint |
|------|----------------------------|---------|-------|------|----------------------------|---------|-------|
| 1243 | Calcite yellow | \$755 | | 7701 | Pebble grey | \$0 | |
| 3432 | Sunset red | \$755 | | 7224 | Graphite grey | \$755 | |
| 3583 | Velvet red | \$0 | | 7708 | Silver grey | \$755 | |
| 3589 | Jupiter red | \$0 | 0 0 | 7709 | Blue grey | \$0 | 0 0 |
| 5362 | Brilliant blue | \$755 | | 7755 | Tenorite grey metallic | \$1,198 | 6 6 |
| 5389 | Steel blue | \$0 | | 7992 | Selenite grey metallic | \$1,198 | |
| 5524 | Black blue | \$1,198 | | 9040 | Jet black | \$1,198 | 6 6 |
| 5890 | Cavansite blue metallic | \$1,198 | | 9136 | Grey white | \$755 | |
| 5957 | Vanda blue | \$755 | | 9147 | Arctic white | \$0 | |
| 6830 | Aqua green | \$0 | | 9197 | Obsidian black metallic | \$1,198 | |
| 7160 | Stone grey | \$755 | | 9775 | Iridiumsilver | \$1,198 | |

 $\label{please see NetStar for latest paint availability information.} \\$

MY24 Upholstery

Standard

VF7 Fabric Maturin Black Upholstery



Optional

VF4 Fabric Caluma Black Upholstery

| Į | Jpcharge | |
|-------|----------|----|
| Cargo | \$ | 67 |



Optional

VF6 Leatherette Black

| | Jpcharge | |
|-------|----------|----|
| Cargo | \$ | 67 |



Seat restrictions

| | | | Fabrics | |
|---------|---------------------|-----|---------|-----|
| Code | Seat | VF7 | VF4 | VF6 |
| | Standard Seats | | | |
| | Front | S | 0 | 0 |
| SF1/SF2 | Power Seats | n/a | 0 | 0 |
| | | | | |
| SB1/SB2 | Comfort Seats Front | S | 0 | 0 |





MY24 eSprinter Rear view camera/head unit plausibility

| eSprinter Cargo | | | | |
|-------------------|---------------------------|----------------|--|--|
| Standard Option A | | | | |
| Radio/HU | E10 | E7M (new code) | | |
| Camera | FR3 | FR8 | | |
| Camera Display | Interior rear view mirror | 10.25" Screen | | |

Options shown above lead to an upcharge.

Cargo Van Floor Variations

| Standard | V93 | Without factory installed flooring |
|----------|-----|------------------------------------|
| Ontions | V43 | Wood floor with 6 D-rings |
| Options | VK8 | Floor covering, plastic |

Note: see restrictions in

Special Rule for cargo vans with metallic paint

| Paint Code | | 5890/7755/7992/9197/9775 | |
|------------------|-----|--|--|
| | V43 | Wood floor with 6 D-rings | |
| | VK8 | Floor covering, plastic | |
| | | No floor covering; requires customer floor | |
| Must have one of | | installation | |
| | ZZ9 | Package contains: | |
| | | V93 - No factory installed flooring | |
| | | VL4 - Metallic painted floor | |
| | | · | |

Note: Fleet only

Additional comments ZZ9 Package

While applying the required clear coat layer to the metallic painted cargo floor, imperfections could occur. Therefore, we strongly recommend to install flooring in the cargo area for vehicles with a metallic paint.

Please be aware that potential paint appearance, contamination or imperfections of the uncovered cargo floor are not considered a defect and are therefore not reimbursable for repairs.

MY24 eSprinter Tire & Wheel Overview

| | | eSprinte | er 2500 | | |
|-----|-------------------------|-----------------------------|---------------|--|--|
| | | Standard Tire (Single tire) | RH8 | | |
| | | Standard Wheel (Steel) | RS3 | | |
| | | Optional Wheel (Alloy) | RL5 | | |
| | | Brand Options | | | |
| | | RM0 All-season tires | RM1 M+S tires | | |
| RD9 | Tire brand, unspecified | 0 | 0 | | |
| RF8 | Michelin | S | n/a | | |
| RF1 | Continental | n/a | 0 | | |
| RH0 | Kumho | 0 | n/a | | |

To order any of the tire brands above code RM9 has to be added to order.

| | | 170" EV | 170" EV |
|------------|--|---------|---------|
| | | E2CA7S | E2CA7H |
| | | 907.645 | 907.645 |
| Electri | ic powertrain | s | s |
| M1E | Electric Motor | S | S |
| M5E | Motor Output 100 kw | S | - |
| M9E | Motor Output 150 kw | - | S |
| E9V | high-voltage battery (113 kwh) | S | S |
| E95 | Type 1 Vehicle socket vor electric vehicle | S | S |
| E5J | DC Charging 50 kw | S | S |
| E8A | AC Charging 9.6 kw | S | S |
| ED1 | AGM battery 12V 70AH | S | S |
| Equip | , | 3 | 3 |
| B25 | Electric parking brake | S | S |
| BA3 | Active Brake Assist | S | S |
| BH1 | Hold Function | S | S |
| | | S | S |
| C6L | Multifunction steering wheel | | _ |
| CL1 | Adjustable steering wheel (angle) | S | S |
| D03 | High roof | S | S |
| D93 | Omission bulkhead | S | S |
| E07 | Hill Start Assist | S | S |
| E10 | Standard radio | S | S |
| E1U | USB-C socket, 5 V | S | S |
| E30 | Starter battery disconnect | S | S |
| E3J | Pre-installation for switch panel | S | S |
| E40 | Trailer hitch prep. wiring | S | S |
| ED8 | Preinstallation PSM | S | S |
| EE5 | Ultracapacitor discharge module | S | S |
| EK1 | Body Builder Connector | S | S |
| ES0 | Jump start terminal | S | S |
| EW5 | Pre-Installation: Remote and Charging Services Premium | S | S |
| EW8 | Pre-installation: Remote and navigation services | S | S |
| EY5 | Emergency Call System | S | S |
| EY6 | Breakdown management | S | S |
| F68 | Heated & electrically adjustable exterior mirrors | S | S |
| FF5 | Shelf above windshield | S | S |
| FG8 | Cupholder front | S | S |
| FI1 | Remote key (315 mhz) w/central locking | S | S |
| FJ4 | Storage compartment underneath cockpit | S | S |
| FR3 | Rear view camera (rear-view mirror display) | S | S |
| H16 | Heated driver's seat | S | S |
| H1K | Pre-Entry climate control | S | S |
| H21 | Windshield with filter band | S | S |
| HH2 | Heater, auxiliary electric hot air | S | S |
| HH9 | Air Condition, Front | S | S |
| J11 | Speedometer, miles and km/h | S | S |
| J1W | Service Interval 1 year | S | S |
| J2A | Acoustic presence indicator | S | S |
| J55 | Seat belt warning for co-driver seat | S | S |
| J58 | Seat belt reminder driver | S | S |
| J65 | Outside temperature gauge | S | S |
| JA8 | Crosswind Assist | S | S |
| JA8 JE1 | Integrated Service Package | S S | S |
| | | | |
| JH3 | Communication module (LTE) for dig. services | S | S |
| JK5 | Instrument cluster with color display | S | S |
| JZ2 | Service Intervall 25,000 miles | S | S |
| L65 | Interior lights, cargo compartment | S | S |

XI3

XY4

Y43

ZU8

ZZ4

Change Year G3-I

USA country version

Brand content Mercedes-Benz North America

Model Year 4

Jack, hydraulic

| | | 170" EV | 170" EV |
|-----|--------------------------------------|---------|---------|
| | | E2CA7S | E2CA7H |
| | | 907.645 | 907.645 |
| L94 | Parking lights deletion | S | S |
| LA2 | Headlight assistant | S | S |
| LB5 | 3rd brake light | S | S |
| MD3 | Top speed limitation 75 mph | S | S |
| MS1 | Cruise control | S | S |
| P47 | Front mudflaps | S | S |
| P48 | Rear mudflaps | S | S |
| Q11 | Longitudinal member reinforcement | S | S |
| R65 | Spare tire bracket below frame | S | S |
| R87 | Spare tire | S | S |
| RH8 | Tires LT 245/75 R16 | S | S |
| RM0 | All-season tires | S | S |
| RF8 | Tire brand Michelin | S | S |
| RS3 | 6.5 J x 16 steel wheels | S | S |
| RY2 | Tire pressure monitoring sensors | S | S |
| S02 | Standard driver seat | S | S |
| S04 | Standard front passenger seat | S | S |
| S22 | Armrest for driver's seat | S | S |
| S25 | Armrest for front passenger seat | S | S |
| SA5 | Front airbag, driver | S | S |
| SA6 | Front airbag, passenger | S | S |
| SH1 | Thorax-pelvis sidebag, driver | S | S |
| SH2 | Thorax-pelvis sidebag, co-driver | S | S |
| SH9 | Airbag, driver/passenger window | S | S |
| SK2 | Seat occupancy sensor, driver's seat | S | S |
| T16 | Sliding door, passenger side | S | S |
| V93 | Without factory installed flooring | S | S |
| V94 | Cable duct - side wall | S | S |
| V95 | Cable duct - rear portal | S | S |
| W73 | Bumper step, rear, grey | S | S |
| X64 | Plates/booklets in English (US) | S | S |
| X99 | Manufacturer Mercedes-Benz AG | S | S |
| XC8 | VIN visible from outside | S | S |
| XG5 | Weight variant 9,370 lbs / 4,250 kg | S | S |
| VIO | CL V C2 L | - | |

S

S

S S

S

S

S

S

Options not listed in this section are package only. Options listed as a \$0 are available as standalone options.

| 170" EV | 170" EV |
|---------|---------|
| E2CA7S | E2CA7H |
| 907.645 | 907.645 |

Until further notice eSprinter orders require customers to select a partition wall and a floor option during the new model launch phase. Please select a partition wall and a floor option during the build process.

| | new model launch phase. Please select a partition wall and a floor op | tion during the bu | ia process. |
|-------|---|--------------------|--------------|
| A50 | Front axle reinforced | \$387 | \$387 |
| CB8 | Stabilization Level II | \$810 | \$810 |
| CM9 | Primed side moldings | \$408 | \$408 |
| D13 | Mounting rails for roof rack | \$336 | \$336 |
| D22 | Fixed sunroof (rear roof section) | \$377 | \$377 |
| | not with H72 | | |
| D50 | Cargo partition | \$322 | \$322 |
| | not with D51/D93/T74; must have one of T77 | | |
| D51 | Cargo partition with 1 window | \$376 | \$376 |
| | not with D50/D93/T74/V37/D17; must have one of T77 | , | |
| E1B | Tray for smartphones incl. wireless charging | \$175 | \$175 |
| | must have MB1 + HH4 | , | |
| E1S | Sirius XM, satellite radio | \$285 | \$285 |
| | must have MB1 | , | , |
| E1P | Comfort Drive Program deactivated | \$0 | \$0 |
| E1Q | Deactivation of recuperation stage selection | \$0 | \$0 |
| E2A | Access point for BB special signals in cockpit | \$32 | \$32 |
| E2I | Additional battery, co-driver seat base | \$277 | \$277 |
| | must have E36; not with E2M | Ψ2., | Ψ2 |
| E2M | Additional battery, engine compartment | \$277 | \$277 |
| LZIVI | must have E36; not with E2I | <i>7211</i> | 3211 |
| E20 | | ćn | ¢0 |
| E20 | Settings charging program limited Cutoff relay for additional battery | \$0 \$124 | \$0 \$124 |
| E36 | , | \$124 | \$124 |
| F46 | standard with E2I/E2M | \$103 | ¢102 |
| E46 | 12 V power outlet, driver seat base | | \$103 |
| E5M | Extension of PSM standard contact | \$65 | \$65 |
| E6J | DC Charging 110 kw | \$593 | \$593 |
| ED5 | Parametric special module (PSM) | \$354 | \$354 |
| | not with ED8 | 4 | 4 |
| EE3 | 115 V socket | \$140 | \$140 |
| ED4 | AGM battery 12V 92 AH 850 A | \$126 | \$126 |
| ES2 | 12 V power outlet, rear compartment | \$103 | \$103 |
| ES5 | Charging package, dashboard | \$92 | \$92 |
| F1K | Coat hooks in driver cabin | \$15 | \$15 |
| | must have D50/D51 | | |
| F49 | Electrically heated windshield | \$244 | \$244 |
| | must have ED4 | | |
| F61 | Interior rear view mirror | \$41 | \$41 |
| | not with D50; must have PP1 | | |
| F84 | Digital Rearview Mirror | \$736 | \$736 |
| | Not with F61. | | |
| F64 | Electrically folding exterior mirrors | \$55 | \$55 |
| FE9 | Additional DIN-slot | \$91 | \$91 |
| FF8 | Overhead storage slot, front center | \$117 | \$117 |
| FJ1 | Hinged lid for storage compartment | \$105 | \$105 |
| FY1 | Security alarm w. interior motion sensor | \$654 | \$654 |
| | must have LC4/C00 | | |
| FY7 | Optional 3-button keys | \$41 | \$41 |
| FZ9 | Keys, two additional masters | \$136 | \$136 |
| H01 | Heat insulation, rear compartment | \$175 | \$175 |
| | must have V21/V25/VA3/VA1/C07/X66 | | |
| H04 | Heat insulation, front compartment | \$209 | \$209 |
| | if + D50/D51 must have V07 | | |
| H22 | Rear window defroster | \$283 | \$283 |
| | | | |
| | must have W61/W78; standard for W61+W70 | | |
| H2K | | \$0 | \$0 |
| H2K | Energy-saving mode, climate control | \$0 \$448 | |
| | | | \$0 \$448 |
| H2K | Energy-saving mode, climate control Roof fan, electric | | |

Options not listed in this section are package only. Options listed as a \$0 are available as standalone options.

| 170" EV | 170" EV | |
|---------|----------|--|
| E2CA7S | S E2CA7H | |
| 907.645 | 907.645 | |

| | vailable as standalone options. | 907.645 | 907.645 |
|---|---|---|---|
| JA7 | Blind Spot Assist | \$504 | \$504 |
| JAI | must have F64 | 9 504 | - |
| JF1 | Rain sensor | \$118 | \$118 |
| | Deactivation lamp monitoring failure | \$30 | \$30 |
| | Attention Assist | \$55 | \$55 |
| L13 | Fog lamp with cornering light function | \$223 | \$223 |
| L71 | Light/motion sensor in rear compartment | \$61 | \$61 |
| LB9 | Illuminated front exits | \$170 | \$170 |
| LC2 | LED light strip in load compartment | \$294 | \$294 |
| LC4 | Comfort overhead control panel | \$105 | \$105 |
| M20 | Top speed limitation 65 mph | \$67 | \$67 |
| | not with MD3/MK5 | - | ! |
| MK5 | Top speed limitation 50 mph | \$166 | \$166 |
| | not with M20/MD3 | • | • |
| P93 | Omission of D-rings | -\$15 | -\$15 |
| | not with D93/V43/VK8 | * | |
| Q24 | Trailer Hitch | tbd | tbd |
| | not with W73/W75/W76 | | |
| QA9 | Half-sided step rear (for trailer hitch) | \$113 | \$113 |
| | must have Q24/QA2; not with W73/W75/W76 | | |
| R91 | Spare tire deletion | -\$110 | -\$110 |
| | must have R92; not with R87 | , , | |
| R92 | Spare tire carrier deletion | \$0 | \$0 |
| | must have R91; not with R65 | Ψ° | , |
| R98 | Rims painted jet black | \$91 | \$91 |
| | not with RL5/RM2 | 7 | |
| RF1 | Tire brand Continental | \$0 | \$0 |
| | must have RM1 + RM9 | 7.0 | |
| RD9 | Unspecified tire brand | \$0 | \$0 |
| | not with RF1/RF8/RH0 | | |
| RH0 | Tire brand Kumho | \$0 | \$0 |
| | must have RM9; not with RM1 | 7.0 | |
| RL5 | Light-alloy wheels 6.5 J x 16 | \$1,015 | \$1,015 |
| | not with RS3/RM2/R98 | \$1,013 | Ψ1/013 |
| RM1 | M+S winter tires | \$190 | \$190 |
| | must have RF1/RD9; not with RF8/RH0/X31 | , | |
| RM2 | Rims painted arctic white | \$91 | \$91 |
| | not with R98/RL5 | 7 | 70- |
| D 1 40 | Specially requested tires | \$113 | 6442 |
| KIVI9 | | | 5113 |
| KIVIY | must have RF1/RHO: not with RD9 | \$113 | \$113 |
| | must have RF1/RH0; not with RD9 Twin front passenger seat | | |
| S23 | Twin front passenger seat | \$448 | \$113 |
| S23 | Twin front passenger seat not with COO/CS1 | \$448 | \$448 |
| S23 S28 | Twin front passenger seat not with COO/CS1 Armrest, driver and passenger door | \$448 | \$448 |
| S23 | Twin front passenger seat not with COO/CS1 Armrest, driver and passenger door Seat belts orange, driver and front passenger | \$448 | \$448 |
| S23 S28 S62 | Twin front passenger seat not with COO/CS1 Armrest, driver and passenger door Seat belts orange, driver and front passenger not with S23 | \$448 \$58 \$36 | \$448 \$58 \$36 |
| S23 S28 S62 | Twin front passenger seat not with COO/CS1 Armrest, driver and passenger door Seat belts orange, driver and front passenger not with S23 Driver's seat plus | \$448 | \$448 |
| S23 S28 S62 SB9 | Twin front passenger seat not with COO/CS1 Armrest, driver and passenger door Seat belts orange, driver and front passenger not with S23 Driver's seat plus must have VF7; not with COO/CS1/X69 | \$448 \$58 \$36 \$267 | \$448 \$58 \$36 \$267 |
| S23 S28 S62 SB9 | Twin front passenger seat not with COO/CS1 Armrest, driver and passenger door Seat belts orange, driver and front passenger not with S23 Driver's seat plus must have VF7; not with COO/CS1/X69 Storage net, driver's seat backrest | \$448 \$58 \$36 \$267 | \$448 \$58 \$36 \$267 |
| \$23 \$28 \$62 \$89 \$27 \$Z7 | Twin front passenger seat not with COO/CS1 Armrest, driver and passenger door Seat belts orange, driver and front passenger not with S23 Driver's seat plus must have VF7; not with COO/CS1/X69 Storage net, driver's seat backrest Storage net, passenger seat backrest | \$448 \$58 \$36 \$267 \$71 \$71 | \$448 \$58 \$36 \$267 \$71 \$71 |
| \$23 \$28 \$62 \$B9 | Twin front passenger seat not with COO/CS1 Armrest, driver and passenger door Seat belts orange, driver and front passenger not with S23 Driver's seat plus must have VF7; not with COO/CS1/X69 Storage net, driver's seat backrest Storage net, passenger seat backrest Sliding door two stage opening | \$448 \$58 \$36 \$267 | \$448 \$58 \$36 \$267 |
| S23 S28 S62 S89 S27 S28 T12 | Twin front passenger seat not with COO/CS1 Armrest, driver and passenger door Seat belts orange, driver and front passenger not with S23 Driver's seat plus must have VF7; not with COO/CS1/X69 Storage net, driver's seat backrest Storage net, passenger seat backrest Sliding door two stage opening not with T55 | \$448 \$58 \$36 \$267 \$71 \$71 \$92 | \$448 \$58 \$36 \$267 \$71 \$71 \$92 |
| S23 S28 S62 S89 S27 S28 T12 | Twin front passenger seat not with COO/CS1 Armrest, driver and passenger door Seat belts orange, driver and front passenger not with S23 Driver's seat plus must have VF7; not with COO/CS1/X69 Storage net, driver's seat backrest Storage net, passenger seat backrest Sliding door two stage opening not with T55 Electric closing assist right sliding door | \$448 \$58 \$36 \$267 \$71 \$71 | \$448 \$58 \$36 \$267 \$71 \$71 |
| S23 S28 S62 S89 SZ7 SZ8 T12 T50 | Twin front passenger seat not with COO/CS1 Armrest, driver and passenger door Seat belts orange, driver and front passenger not with S23 Driver's seat plus must have VF7; not with COO/CS1/X69 Storage net, driver's seat backrest Storage net, passenger seat backrest Sliding door two stage opening not with T55 Electric closing assist right sliding door must have D03; not with T55 | \$448 \$58 \$36 \$267 \$71 \$71 \$92 | \$448 \$58 \$36 \$267 \$71 \$71 \$92 \$376 |
| S23 S28 S62 S89 SZ7 SZ8 T12 T50 | Twin front passenger seat not with COO/CS1 Armrest, driver and passenger door Seat belts orange, driver and front passenger not with S23 Driver's seat plus must have VF7; not with COO/CS1/X69 Storage net, driver's seat backrest Storage net, passenger seat backrest Sliding door two stage opening not with T55 Electric closing assist right sliding door must have D03; not with T55 Electric sliding door right | \$448 \$58 \$36 \$267 \$71 \$71 \$92 | \$448 \$58 \$36 \$267 \$71 \$71 \$92 |
| S23 S28 S62 S89 S27 S28 T12 T50 | Twin front passenger seat not with COO/CS1 Armrest, driver and passenger door Seat belts orange, driver and front passenger not with S23 Driver's seat plus must have VF7; not with COO/CS1/X69 Storage net, driver's seat backrest Storage net, passenger seat backrest Sliding door two stage opening not with T55 Electric closing assist right sliding door must have D03; not with T55 Electric sliding door right must have D03 + (FY7+T16) + T74; not with T12/T50; | \$448 \$58 \$36 \$267 \$71 \$71 \$92 \$376 | \$448 \$58 \$36 \$267 \$71 \$71 \$92 \$376 |
| S23 S28 S62 S89 S27 S28 T12 T50 | Twin front passenger seat not with COO/CS1 Armrest, driver and passenger door Seat belts orange, driver and front passenger not with S23 Driver's seat plus must have VF7; not with COO/CS1/X69 Storage net, driver's seat backrest Storage net, passenger seat backrest Sliding door two stage opening not with T55 Electric closing assist right sliding door must have D03; not with T55 Electric sliding door right must have D03 + (FY7+T16) + T74; not with T12/T50; Opening limiter electrically operated sliding door | \$448 \$58 \$36 \$267 \$71 \$71 \$92 | \$448 \$58 \$36 \$267 \$71 \$71 \$92 \$376 |
| S28 S62 S89 S27 S28 T12 T50 | Twin front passenger seat not with COO/CS1 Armrest, driver and passenger door Seat belts orange, driver and front passenger not with S23 Driver's seat plus must have VF7; not with COO/CS1/X69 Storage net, driver's seat backrest Storage net, passenger seat backrest Sliding door two stage opening not with T55 Electric closing assist right sliding door must have D03; not with T55 Electric sliding door right must have D03 + (FY7+T16) + T74; not with T12/T50; Opening limiter electrically operated sliding door must have T55 | \$448 \$58 \$36 \$267 \$71 \$71 \$92 \$376 \$930 | \$448 \$58 \$36 \$267 \$71 \$71 \$92 \$376 \$930 |
| S28 S62 S89 S27 S28 T12 T50 | Twin front passenger seat not with COO/CS1 Armrest, driver and passenger door Seat belts orange, driver and front passenger not with S23 Driver's seat plus must have VF7; not with COO/CS1/X69 Storage net, driver's seat backrest Storage net, passenger seat backrest Sliding door two stage opening not with T55 Electric closing assist right sliding door must have D03; not with T55 Electric sliding door right must have D03 + (FY7+T16) + T74; not with T12/T50; Opening limiter electrically operated sliding door must have T55 Assist handle, B-pillar | \$448 \$58 \$36 \$267 \$71 \$71 \$92 \$376 | \$448 \$58 \$36 \$267 \$71 \$71 \$92 \$376 |
| S23 S28 S62 S89 S27 S28 T12 T50 T55 T60 | Twin front passenger seat not with COO/CS1 Armrest, driver and passenger door Seat belts orange, driver and front passenger not with S23 Driver's seat plus must have VF7; not with COO/CS1/X69 Storage net, driver's seat backrest Storage net, passenger seat backrest Sliding door two stage opening not with T55 Electric closing assist right sliding door must have D03; not with T55 Electric sliding door right must have D03 + (FY7+T16) + T74; not with T12/T50; Opening limiter electrically operated sliding door must have T55 Assist handle, B-pillar must have D93; not with T77; Standard with T55 + D93 | \$448 \$58 \$36 \$267 \$71 \$71 \$92 \$376 \$930 \$134 | \$448 \$58 \$36 \$267 \$71 \$71 \$92 \$376 \$930 \$134 |
| \$23 \$28 \$62 \$89 \$27 \$28 \$112 \$150 \$155 \$160 \$174 | Twin front passenger seat not with COO/CS1 Armrest, driver and passenger door Seat belts orange, driver and front passenger not with S23 Driver's seat plus must have VF7; not with COO/CS1/X69 Storage net, driver's seat backrest Storage net, passenger seat backrest Sliding door two stage opening not with T55 Electric closing assist right sliding door must have D03; not with T55 Electric sliding door right must have D03 + (FY7+T16) + T74; not with T12/T50; Opening limiter electrically operated sliding door must have T55 Assist handle, B-pillar must have D93; not with T77; Standard with T55 + D93 Door-mounted assist handles, driver & passenger | \$448 \$58 \$36 \$267 \$71 \$71 \$92 \$376 \$930 \$134 | \$448 \$58 \$36 \$267 \$71 \$71 \$92 \$376 \$930 \$134 |
| \$23 \$28 \$62 \$89 \$27 \$28 \$112 \$150 \$155 \$160 \$174 | Twin front passenger seat not with COO/CS1 Armrest, driver and passenger door Seat belts orange, driver and front passenger not with S23 Driver's seat plus must have VF7; not with COO/CS1/X69 Storage net, driver's seat backrest Storage net, passenger seat backrest Sliding door two stage opening not with T55 Electric closing assist right sliding door must have D03; not with T55 Electric sliding door right must have D03 + (FY7+T16) + T74; not with T12/T50; Opening limiter electrically operated sliding door must have T55 Assist handle, B-pillar must have D93; not with T77; Standard with T55 + D93 Door-mounted assist handles, driver & passenger Assist handle w/ partition | \$448 \$58 \$36 \$267 \$71 \$71 \$92 \$376 \$930 \$134 | \$448 \$58 \$36 \$267 \$71 \$71 \$92 \$376 \$930 \$134 |
| \$28 \$62 \$89 \$27 \$28 \$112 \$750 \$750 \$760 | Twin front passenger seat not with COO/CS1 Armrest, driver and passenger door Seat belts orange, driver and front passenger not with S23 Driver's seat plus must have VF7; not with COO/CS1/X69 Storage net, driver's seat backrest Storage net, passenger seat backrest Sliding door two stage opening not with T55 Electric closing assist right sliding door must have D03; not with T55 Electric sliding door right must have D03 + (FY7+T16) + T74; not with T12/T50; Opening limiter electrically operated sliding door must have T55 Assist handle, B-pillar must have D93; not with T77; Standard with T55 + D93 Door-mounted assist handles, driver & passenger | \$448 \$58 \$36 \$267 \$71 \$71 \$92 \$376 \$930 \$134 | \$448 \$58 \$36 \$267 \$71 \$71 \$92 \$376 \$930 \$134 |

| | 170" EV | 170" EV |
|--|-------------|---------------|
| Options not listed in this section are package only. Options listed as a \$ | E2CA7S | E2CA7H |
| are available as standalone options. | 907.645 | 907.645 |
| Control of the contro | 4 | 4 |
| V24 Pallet support in sliding door step | \$108 | \$108 |
| must have (V43/X66)+(D50/D51); not with VK8/V93/C07 | 4005 | 4005 |
| V25 Half height load compartment trim | \$225 | \$225 |
| not with VA1/VA3/VA5/V52/X66 | A | 444= |
| V35 Wheel house covering | \$117 | \$117 |
| if +V43 must have V25/VA1/VA3; not with V52 | 6240 | ¢210 |
| V42 Lashing rails, waist level not with ZE6 | \$310 | \$310 |
| | \$473 | \$473 |
| V43 Wood floor with 6 D-rings not with P93/V93/VL4/VK8/C07; standard with D93/H13/V24/V5 | | \$473 |
| V48 Floor cover behind seat box | \$30 | \$30 |
| must have D93; not with D50/D51/D56/D62/D64/V43/VK8 | \$30 | 330 |
| V52 Loadable wheel arch | \$419 | \$419 |
| must have V43/X66; not with EL9/V21/V25/V35/VA1/C07 | 2413 | Ş41 <i>3</i> |
| V85 Cigarette lighter & ash cup, front | \$44 | \$44 |
| VA1 Side wall paneling waist height PVC | \$356 | \$356 |
| must have VA5/VA7; not with V52 | 7330 | 7330 |
| VA3 Side wall paneling full hardboard | \$497 | \$497 |
| not with F02 | Ų 137 | Ų.57 |
| VA5 Full paneling, hinged rear doors | \$43 | \$43 |
| must have D03+VA7+(W61/W78); not with V25 | 7 | 7.0 |
| VA7 Storage compart. w/ net in rear doors | \$142 | \$142 |
| must have W61/W78; not with V52 | , | , |
| VC4 Cargo lashing rails, head height | \$465 | \$465 |
| must have V42/C07/X66; not with ZE6 | | |
| VC5 Door sill - protective edge | \$79 | \$79 |
| must have V43/X66; not with VK8/VV2/V93/C07 | | • |
| VK8 Floor covering, plastic | \$414 | \$414 |
| not with V43/P93/V52/VC5/X66/UL1 | • | • |
| VV2 Lashing rails, floor level (plus 4 anchors) | \$386 | \$386 |
| must have V43; not with V93/VC5/ZE6 | | |
| VV4 Additional Ground Weld Studs | \$50 | \$50 |
| W16 2nd row, fixed window, driver side | \$162 | \$162 |
| if D93 must have F43+W70; if D93 & standard roof CHS production | | |
| W17 2nd row, fixed window, passenger side | \$162 | \$162 |
| if D93 must have F43+W70; if D93 & standard roof CHS production | | |
| W61 Windows in rear doors | \$105 | \$105 |
| must have VA7/ if D51 must have F61; not with W78/(W70+-(H2 | | 1 |
| W70 Black tinting (90%) for rear windows | \$155 | \$155 |
| not with W94; must have W16/W17/F02/((W61/W78)+H22); sta | | |
| W76 Bumper step, rear, spring-loaded | \$673 | \$673 |
| must have R91+R92; not with X55/Q24 | 40=0 | 4275 |
| W78 Heated rear window(s) w/ washers/wipers | \$376 | \$376 |
| Must have H22+VA7 / if D51 must have F61; not with W61 | 607 | 607 |
| XM4 Acoustic package | \$97 | \$97 |
| standard with MB1 | 620 | 630 |
| Y10 First-aid kit | \$30 | \$30 |
| Y26 Wheel chocks | \$43 | \$43 \$20 |
| Y45 Emergency flashlight | \$30 | \$30 |
| Y68 Paint preservative | \$238 | \$238 |
| Y69 Surface protection for stock vehicles | \$352 | \$352 |
| YK4 Cargo straps, Jashing rails | \$91 | \$91 \$116 |
| YK4 Cargo straps, lashing rails | \$116 | \$116 |
| must have V42/VV2; not with ZE6 | ¢717 | \$717 |
| ZE6 Shelving prep | \$717 | \$717 |
| not with H13/V42/VC4/VK8/VV2/YK4 | | |

| | | 170" EV | 170" EV |
|--------|-----------------------------------|---------|---------|
| | | E2CA7S | E2CA7H |
| | | 907.645 | 907.645 |
| C00 | Comfort Package | \$307 | \$307 |
| LC4 | Comfort overhead control panel | Х | Х |
| SE4 | Lumbar support, co-driver's seat | X | Х |
| SE5 | Lumbar support, driver's seat | X | X |
| SK0 | Comfort head restraint, driver | Х | X |
| SK1 | Comfort head restraint, co-driver | X | Х |
| must l | nave COS OR CS1, not with S23 | | |

| COS | Comfort Package (Seat addition) | \$426 | \$426 |
|------|---------------------------------|-------|-------|
| SB1 | Comfort driver's seat | Х | Х |
| SB2 | Comfort passenger seat | Х | Х |
| must | must have COO | | |

| CS1 | Comfort Steering Package | \$1,643 | \$1,643 |
|--------|--|---------|---------|
| H15 | Heated front passenger seat | X | X |
| SF1 | Driver's seat electrically adjustable (includes comfort seat) | Х | X |
| SF2 | Co-driver's seat electrically adjustable (includes comfort seat) | Х | Х |
| must h | nust have COO and VF4 OR VF6, not with S23 | | |

| C01 | Driver Convenience Package | \$449 | \$449 |
|-----|--|-------|-------|
| E46 | 12 V power outlet, driver seat base | Х | X |
| F64 | Electrically folding exterior mirrors | Х | X |
| FJ1 | Hinged lid for storage compartment | Х | Χ |
| FJ5 | Hinged Lid for Storage Compartments left and right | Х | Х |
| FZ9 | Keys, two additional masters | X | X |
| JW8 | Attention Assist | Х | Χ |

| MB1 | Premium MBUX Package | \$2,390 | \$2,390 |
|-----|--|---------|---------|
| CL3 | Leather steering wheel | Х | Х |
| CK8 | Heated steering wheel | Х | Х |
| E7M | MBUX Multimedia System with 10.25" touchscreen | Х | Х |
| FM3 | Wet Wiper System | Х | Х |
| E7B | Pre-Installation: Navigation | Х | Х |
| E4S | Smartphone Integration Package | Х | Х |
| H1I | Front-to-rear outlet in instrument panel | Х | Х |
| XM4 | Acoustic package | X | Х |
| FJ1 | Hinged lid for storage compartment | X | Х |
| FR8 | Rear view camera (head unit display) | X | Х |
| XO5 | Digital owner's manual | Х | Х |
| JF1 | Rain sensor | Х | Х |

| 170" EV | 170" EV |
|---------|---------|
| E2CA7S | E2CA7H |
| 907.645 | 907.645 |

| NC1 | Navigation Charging Package | \$1,429 | \$1,429 |
|--------|------------------------------------|---------|---------|
| E6J | DC Charging 110 kw | X | X |
| E1E | Navigation | X | X |
| EY2 | Intelligent navigation | Х | Х |
| EX9 | Pre-Installation: Map Data Updates | Х | Х |
| must l | must have MB1 | | |

| X13 | Exterior Lighting Package | \$1,801 | \$1,801 | | | | | | | |
|--------|--|---------|---------|--|--|--|--|--|--|--|
| L13 | Fog lamp with cornering light function X | | | | | | | | | |
| L22 | Partial LED tail lights | X | | | | | | | | |
| LA1 | High beam assist | Х | Х | | | | | | | |
| LG7 | LED high performance headlamps | Х | | | | | | | | |
| no res | no restrictions . | | | | | | | | | |

| CR1 | Rear Door Convenience Package | \$508 | \$508 | | | | | |
|--------|--------------------------------------|-------|-------|--|--|--|--|--|
| W54 | Rear doors, opening to side wall | X | | | | | | |
| W5F | 90 Degree fixation point- Rear Doors | Х | Х | | | | | |
| T85 | Assist handle, left rear door | Х | Х | | | | | |
| T86 | Assist handles, right rear door | Х | | | | | | |
| not wi | not with VA1 | | | | | | | |

| C07 | Cargo Protection Package | \$1,250 | \$1,250 | | | | | |
|-------|-----------------------------------|---------|---------|--|--|--|--|--|
| V25 | Half height load compartment trim | Х | Х | | | | | |
| V42 | Lashing rails, waist level | Х | Х | | | | | |
| VC4 | Cargo lashing rails, head height | Х | Х | | | | | |
| VK8 | Floor covering, plastic | Х | Х | | | | | |
| YK3 | Cargo straps, D-rings | X | Х | | | | | |
| not w | not with X66 | | | | | | | |

| 170" EV | 170" EV |
|---------|---------|
| E2CA7S | E2CA7H |
| 907.645 | 907.645 |

| X66 | Heavy-Duty-Cargo Protection Package | \$2,287 | \$2,287 | | | | | | |
|-------|---|---------|---------|--|--|--|--|--|--|
| V43 | Wood floor with 6 D-rings | Х | X | | | | | | |
| V42 | Lashing rails, waist level | Х | X | | | | | | |
| V52 | Loadable wheel arch | X | X | | | | | | |
| VA3 | Side wall paneling full hardboard | Х | Х | | | | | | |
| VC4 | Cargo lashing rails, head height | Х | Х | | | | | | |
| VV2 | Lashing rails, floor level (plus 4 anchors) | Х | Х | | | | | | |
| YK3 | Cargo straps, D-rings | Х | Х | | | | | | |
| YK4 | Cargo straps, lashing rails | Х | Х | | | | | | |
| not w | not with CO7/UL1 | | | | | | | | |

| UL1 | Upfit Prep and Load Restraining Package | \$1,768 | \$1,768 | | | | | | |
|-------|---|---------|---------|--|--|--|--|--|--|
| V43 | Wood floor with 6 D-rings | X | X | | | | | | |
| V42 | Lashing rails, waist level | X | Х | | | | | | |
| VC4 | Cargo lashing rails, head height | X | X | | | | | | |
| VV2 | Lashing rails, floor level (plus 4 anchors) | X | X | | | | | | |
| VA3 | Side wall paneling full hardboard X X | | | | | | | | |
| not w | not with CO7/X66 | | | | | | | | |

| X69 | Swivel Seat Package | \$595 | \$595 | | | | | | |
|--------|--------------------------------------|-------|-------|--|--|--|--|--|--|
| SR8 | Swivel base for driver's seat | X | X | | | | | | |
| SR9 | Swivel base for front passenger seat | X | X | | | | | | |
| S87 | Driver's seat frame, low | Х | Х | | | | | | |
| S88 | Passenger seat frame, low X X | | | | | | | | |
| must i | must have (C00+C0S) OR (C00+CS1) | | | | | | | | |

Retail Orders

| | ExpertSolutions™ Ship-Thru Partners | | | | | | | | | | | | |
|-------|-------------------------------------|---------------|------------------------|----|----------|---------|-----|-----------------|-------------------------------|----------------|--|--|--|
| Price | Upfitter | U-Code | Descripton of U- | N | lodels / | Accepte | ed | Shipping | Shipping Email Address | Shipping phone | Shipping address | | |
| 11166 | Ophitici | O-Couc | Code | CA | CC | CV | PV | Contact | Shipping Linan Address | number | Simpping dudiess | | |
| \$100 | Driverge | US1 | Driverge Ship- Thru | Х | - | - | - | Stephen Fink | stephen.fink@driverge.com | 330 247 5246 | 9004 Sightline Drive, Suite 5, Ladson, SC 29456 | | |
| | | | Knapneiue van | | | | | THIK | | | Edd3011, 3C 23430 | | |
| \$100 | | | Equipment Ship- | Χ | - | - | - | | | | | | |
| 6400 | V n a m h a i d a | | Shaur mermoki | V | | | | Karl Braun | | 054 530 4033 | 2486 US Highway 52, | | |
| \$100 | Knapheide | UK2 | ng by Knapheide | Х | - | - | _ | Naii bi auii | expertsolutions@knapheide.com | 854 529 4923 | Moncks Corner, SC 29461 | | |
| \$100 | | UK3 | Knapheide | _ | x | _ | _ | | | | | | |
| \$100 | | UKS | Bodies Ship-Thru | • | ^ | - | • | | | | | | |
| \$100 | | UA1 | Holman Ship- | Х | | Х | | | | | | | |
| \$100 | Holman | UAI | Thru | ^ | _ | ^ | - | Tana | Tana.Keuck@holman.com | 866 428 8267 | 211 Farmington RD, | | |
| Ć400 | HOIMIAN | 1142 | Camina Van Chin | V | | · · | · · | Drake | Tana.Neuck@noiman.com | 000 428 8207 | Summerville, SC 29483 | | |
| \$100 | | UA2 Service \ | Service Van Ship- | Х | - X X | | | | | , | | | |

^{*}US1, UK1, UK2, UK3, UA1, UA2 are to be used when ordering the corresponding ExpertSOLUTIONS™ upfits as shown on upfitterportal.com or mbvans.com

| | Other Charleston, SC Ship-Thru Partners | | | | | | | | | | | | |
|-------|---|--------|---|----|----------|---------|----|-----------------|-----------------------------|----------------|---|--|--|
| Price | Facility | U-Code | Description of U- | M | lodels A | Accepte | ed | Shipping | Shipping Email Address | Shipping phone | Shipping address | | |
| FIICE | racinty | O-Coue | Code | CA | CC | CV | PV | Contact | Shipping Linan Address | number | Shipping address | | |
| \$100 | IVS | UI1 | Innovative Vehicle Solutions Ship-Thru | X | х | X | х | Sam Kuhn | sam.k@innovativevehicle.com | 843 376 3822 | 3241 Benchmark Drive, Ladson, SC 29456 | | |
| \$100 | Midway | UM1 | Midway Specialty Vehicles Ship- Thru | х | х | х | Х | Russ Gilpin | rgilpin@mymidway.com | 574-320-4188 | 3285 Benchmark Drive, Ladson, SC 29456 | | |
| \$100 | Thermo King | l 1J52 | Thermo King of Charleston | Χ | Х | - | - | Trevor Floyd | TFloyd@fleetsourcesc.com | 843 744 5040 | 180 Strathmore RD, Summerville, SC 29486 | | |

Small/Medium Fleet Upfitter Orders

| | All Charleston, SC Ship-Thru Partners | | | | | | | | | | | | |
|-------|---------------------------------------|--------|---------------------------------------|----|-----------------|----|----------|------------------------|--------------------------------------|------------------|--------------------------------|--|--|
| Price | Facility | U-Code | Descripton of U- | М | Models Accepted | | Shipping | Shipping Email Address | Shipping phone | Shipping address | | | |
| | | | Code | CA | CC | CV | PV | Contact | 5ppga | number | Suith Find and and | | |
| \$100 | Driverge | US5 | Driverge Fleet | Х | | | _ | Stephen | stephen.fink@driverge.com | 330 247 5246 | 9004 Sightline Drive, Suite 5, | | |
| \$100 | Driverge | 033 | Ship-Thru | ^ | | | | Fink | stephen.mk@driverge.com | 330 247 3240 | Ladson, SC 29456 | | |
| \$100 | Knapheide | UK5 | Knapheide | < | x x | Х | Х | Karl Daar | expertsolutions@knapheide.com | 854 529 4923 | 2486 US Highway 52, | | |
| \$100 | | UKS | Fleet Ship-Thru | Χ | | Х | X | Karl Braun | | | Moncks Corner, SC 29461 | | |
| \$100 | Holman | UA5 | Holman Fleet | Х | | > | х х | Tana | Tana.Keuck@holman.com | 866 428 8267 | 211 Farmington RD, | | |
| \$100 | | | Ship-Thru | ^ | • | ^ | | Drake | Talla.Reuck@floillan.com | | Summerville, SC 29483 | | |
| \$100 | Vehicle | UIS | Vahiala Calutiana V | х | x | Х | | Sam Kuhn | sam.k@innovativevehicle.com | 843 376 3822 | 3241 Benchmark Drive, | | |
| \$100 | Venicie | | Vehicle Solutions | ^ | ^ | ^ | - | Salli Kullii | <u>sam.k@iiiiovativeveilicie.com</u> | 043 370 3022 | Ladson, SC 29456 | | |
| \$100 | Midway | | , , , , , , , , , , , , , , , , , , , | Х | Х | Х | _ | Russ | railnin@mumidusu.com | 574-320-4188 | 3285 Benchmark Drive, | | |
| \$100 | Midway | UM1 | Specialty | ^ | ^ | ^ | • | Gilpin | rgilpin@mymidway.com | 5/4-320-4188 | Ladson, SC 29456 | | |
| ¢100 | Thorma Vina | LIES | Thermo King of | V | V | | | Trevor | TFloyd@fleetsourcesc.com | 942 744 5040 | 180 Strathmore RD, | | |
| \$100 | Thermo King | U52 | Charleston | Х | Х | - | - | Floyd | Trioyu@neetsourcesc.com | 843 744 5040 | Summerville, SC 29486 | | |

Ordering Information

U-Codes can be added to the Purchase Order via the VII screen in NetStar OR by emailing the request to MBUSA Van Distribution (vandistribution@mbusa.com)

Don't forget to place your upfit order with the upfitter after you add the U-Code
U-Codes can be added/changed through D40 status. No changes permitted after D41 status
U-Codes will carry over for dealer traded vehicles

Any requests to remove a U-Code must be approved by the Van Distribution & Upfitter Management Departments

For more information on U-codes, please reach out to the Upfitter Management team: upfitterinfo@mbusa.com

All information contained in this Reference Guide is based on the latest product information available at the time of publication. Mercedes-Benz USA, LLC reserve the right to make changes at any time, without notice, in colors, materials, equipment, specifications and models.

Prices are manufacturer suggested retail prices and are subject to change.