#### Version 1.0

# **MY24**

## SPRINTER

# Dealer Ordering Guide



Publish date: 4/14/2023



## **MY24 Sprinter - Changes & Model Overview**

	MY24 Sprinter Changes
	Diesel only engine Portfolio.
Portfolio	Cargo Van and Cab Chassis: 3500XD & 4500 models only available as Diesel High Output. Standard Output cancelled for 3500XD & 4500 models.
	Crew Van: Only available as 2500 model. Crew Van 3500, 3500XD, 4500 are phased out .
Standard	JK5 Instrument Cluster with color display new standard. H16 Heated driver's seat new standard. K56 (Red Diesel Filler Cap) replaced by Black Diesel Filler Cap (no code). AR5 (Axle ratio I = 4.727) is replaced by AR2 (Axle ratio I = 3,923) on 3500, 3500XD, 4500 Models. MD3 (top speed limitation 75 mph) as a standard on the 144" WB on the 3500, 3500XD, 4500 Models is removed and offered as an option.
Packages	CR1 - New Rear Door Convenience Package added. UL1 - Upfit Prep and Load Restraining Package added. X01 - Suspension Seating Package phased out. C06 - Cargo Convenience Package phased out.
Options	CB2 Cab Chassis Air Suspension added. J1V Cab Chassis Blind Spot Pre-Installation added KA3 Cab Chassis Lateral exhaust pipe in front of rear axle, left added. LA3 Light sensor for vehicles with alcove phased out. SB3, SB4 - Suspension Seats phased out. T19 Sliding door driver side phased out. T51 Electric closing assist left sliding door phased out.

## MY24 Model Portfolio (Changes compared to MY23)

Model	GVWR	Wheelbase	Engine	Roof	MB Model	Availability
	1500 (8,550 GVW)	144" WB	Gas	SR	M1CA4G	n/a
		144'' WB	Gas	SR	M2CA4G	n/a
			4 Cyl D- SO	SR	M2CA4S	available
			4 Cyl D- HO	SR	M2CA4H	available
			AWD	SR	M2CA4A	available
	2500		Gas	HR	M2CA7G	n/a
	2500 (9,050 GVW)	170'' WB	4 Cyl D- SO	HR	M2CA7S	available
	(3,030 GVVV)	170 WB	4 Cyl D- HO	HR	M2CA7H	available
			AWD	HR	M2CA7A	available
			4 Cyl D- SO	HR	M2CAES	available
		170EXT WB	4 Cyl D- HO	HR	M2CAEH	available
			AWD	HR	M2CAEA	available
	3500 (9,990 GVW)	144" WB	4 Cyl D- SO	SR	M3CA4S	available
			4 Cyl D- HO	SR	М3СА4Н	available
Cargo Vans		170" WB	4 Cyl D- SO	HR	M3CA7S	available
			4 Cyl D- HO	HR	М3СА7Н	available
		170EXT WB	4 Cyl D- SO	HR	M3CAES	available
			4 Cyl D- HO	HR	МЗСАЕН	available
	3500XD (11,030 GVW)		4 Cyl D- SO	SR	MXCA4S	n/a
		144" WB	4 Cyl D- HO	SR	MXCA4H	available
			AWD	SR	MXCA4A	available
			4 Cyl D- SO	HR	MXCA7S	n/a
		170" WB	4 Cyl D- HO	HR	MXCA7H	available
	(11,000 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0		AWD	HR	MXCA7A	available
			4 Cyl D- SO	HR	MXCAES	n/a
		170EXT WB	4 Cyl D- HO	HR	MXCAEH	available
			AWD	HR	MXCAEA	available
		144" WB	4 Cyl D- SO	SR	M4CA4S	n/a
		144 VVD	4 Cyl D- HO	SR	M4CA4H	available
	4500	170" WB	4 Cyl D- SO	HR	M4CA7S	n/a
	(12,125)	1/U WD	4 Cyl D- HO	HR	M4CA7H	available
		170EXT WB	4 Cyl D- SO	HR	M4CAES	n/a
		1/ULXI WB	4 Cyl D- HO	HR	M4CAEH	available

<sup>\*</sup>MSRP excludes destination and delivery \$2,295.

AWD MSRP shown above include upcharge of X55 package

SO: Standard Output engine 168hp HO: High Output engine 208hp

Model	GVWR	Wheelbase	Engine	Roof	MB Model	MSRP*
			Gas	SR	M2CV4G	n/a
Crew Vans		144'' WB	4 Cyl D- SO	SR	M2CV4S	available
		T44 AAD	4 Cyl D- HO	SR	M2CV4H	available
	2500		AWD	SR	M2CV4A	available
	(9,050 GVW)		Gas	HR	M2CV7G	n/a
		170'' WB	4 Cyl D- SO	HR	M2CV7S	available
		170 WB	4 Cyl D- HO	HR	M2CV7H	available
			AWD	HR	M2CV7A	available
		144" WB	4 Cyl D- SO	SR	M3CV4S	n/a
	3500	144 VVD	4 Cyl D- HO	SR	M3CV4H	n/a
	(9,990 GVW)	170" WB	4 Cyl D- SO	HR	M3CV7S	n/a
		170 WB	4 Cyl D- HO	HR	M3CV7H	n/a
			4 Cyl D- SO	SR	MXCV4S	n/a
		144" WB	4 Cyl D- HO	SR	MXCV4H	n/a
	3500XD		AWD	SR	MXCV4A	n/a
	(11,030 GVW)	170" WB	4 Cyl D- SO	HR	MXCV7S	n/a
			4 Cyl D- HO	HR	MXCV7H	n/a
			AWD	HR	MXCV7A	n/a
	4500 (12,125)	144" WB 170" WB	4 Cyl D- SO	SR	M4CV4S	n/a
			4 Cyl D- HO	SR	M4CV4H	n/a
			4 Cyl D- SO	HR	M4CV7S	n/a
			4 Cyl D- HO	HR	M4CV7H	n/a
	1500 (8,550 GVW)	144" WB	Gas	SR	M1PV4G	n/a
ļ.			Gas	SR	M2PV4G	n/a
		144'' WB 12-seater	4 Cyl D- SO	SR	M2PV4S	available
Passenger Vans	2500		4 Cyl D- HO	SR	M2PV4H	available
-	(9,050/9,480)		AWD	SR	M2PV4A	available
		170'' WB	4 Cyl D- SO	HR	M2PV7S	available
		15-seater	4 Cyl D- HO	HR	M2PV7H	available
			4 Cyl D- SO	n/a	MXCC4S	n/a
		144" WB	4 Cyl D- HO	n/a	MXCC4H	available
	3500XD		AWD	n/a	MXCC4A	available
	(11,030 GVW)		4 Cyl D- SO	n/a	MXCC7S	n/a
	•	170" WB	4 Cyl D- HO	n/a	МХСС7Н	available
Cab Chassis			AWD	n/a	MXCC7A	available
ŀ			4 Cyl D- SO	n/a	M4CC4S	n/a
	4500	144" WB	4 Cyl D- HO	n/a	M4CC4H	available
	(12,125 GVW)		4 Cyl D- SO	n/a	M4CC7S	n/a
	(11)113 3 1 1 1 1	170" WB	4 Cyl D- HO	n/a	М4СС7Н	available

<sup>\*</sup>MSRP excludes destination and delivery \$2,295.

AWD MSRP shown above include upcharge of X55 package

SO: Standard Output engine 168hp

HO: High Output engine 208hp

## **MY24 MSRP Overview**

Model	GVWR	Wheelbase	Engine	Roof	MB Model	MSRP*
			4 Cyl D- SO	SR	M2CA4S	\$49,900
Cargo		144" WB	4 Cyl D- HO	SR	M2CA4H	\$52,700
			AWD	SR	M2CA4A	\$59,400
			4 Cyl D- SO	HR	M2CA7S	\$56,500
	2500	144" WB	4 Cyl D- HO	HR	M2CA7H	\$59,300
	(9,050 GVW)		AWD	HR	M2CA7A	\$66,000
			4 Cyl D- SO	HR	M2CAES	\$58,900
		170EXT WB	4 Cyl D- HO	HR	M2CAEH	\$61,700
			AWD	HR	M2CAEA	\$68,400
		4.4411.445	4 Cyl D- SO	SR	M3CA4S	\$52,800
		144" WB	4 Cyl D- HO	SR	М3СА4Н	\$55,600
	3500	47011111	4 Cyl D- SO	HR	M3CA7S	\$59,400
	(9,990 GVW)	170" WB	4 Cyl D- HO	HR	М3СА7Н	\$62,200
			4 Cyl D- SO	HR	M3CAES	\$61,800
		170EXT WB	4 Cyl D- HO	HR	МЗСАЕН	\$64,600
	3500XD (11,030 GVW)	144" WB	4 Cyl D- HO	SR	MXCA4H	\$58,500
			AWD	SR	MXCA4A	\$65,200
		170" WB	4 Cyl D- HO	HR	MXCA7H	\$65,100
			AWD	HR	MXCA7A	\$71,700
		170EXT WB	4 Cyl D- HO	HR	MXCAEH	\$67,500
			AWD	HR	MXCAEA	\$74,200
	4500 (12,125)	144" WB	4 Cyl D- HO	SR	M4CA4H	\$61,000
		170" WB	4 Cyl D- HO	HR	M4CA7H	\$67,600
		170EXT WB	4 Cyl D- HO	HR	M4CAEH	\$70,000
		144" WB	4 Cyl D- SO	SR	M2CV4S	\$52,120
			4 Cyl D- HO	SR	M2CV4H	\$54,920
Cuann	2500		AWD	SR	M2CV4A	\$61,620
Crew	(9,050 GVW)		4 Cyl D- SO	HR	M2CV7S	\$59,420
		170" WB	4 Cyl D- HO	HR	M2CV7H	\$62,220
			AWD	HR	M2CV7A	\$68,920
			4 Cyl D- SO	SR	M2PV4S	\$55,800
	2500	144" WB	4 Cyl D- HO	SR	M2PV4H	\$58,600
Passenger	2500 (9,050/9,480)		AWD	SR	M2PV4A	\$65,300
	(9,030/9,400)	170" WB	4 Cyl D- SO	HR	M2PV7S	\$65,200
		170 008	4 Cyl D- HO	HR	M2PV7H	\$68,000
		144" WB	4 Cyl D- HO	n/a	MXCC4H	\$53,000
	3500XD	144 VVD	AWD	n/a	MXCC4A	\$59,700
Cab Chassis	(11,030 GVW)	170" WB	4 Cyl D- HO	n/a	МХСС7Н	\$53,900
Can Chassis		170 008	AWD	n/a	MXCC7A	\$60,600
ľ	4500	144" WB	4 Cyl D- HO	n/a	M4CC4H	\$55,500
	(12,125 GVW)	170" WB	4 Cyl D- HO	n/a	M4CC7H	\$56,400

<sup>\*</sup>MSRP excludes destination and delivery \$2,295.

AWD MSRP shown above include upcharge of X55 package

SO: Standard Output engine 168hp HO: High Output engine 208hp

### **Exterior Paint Overview**

Code	Description	Price	Paint	Code	Description	Price	Paint
1243	Calcite yellow	\$755		7701	Pebble grey	\$0	
3432	Sunset red	\$755		7224	Graphite grey	\$755	
3583	Velvet red	\$0		7708	Silver grey	\$755	
3589	Jupiter red	\$0		7709	Blue grey	\$0	
5362	Brilliant blue	\$755		7755	Tenorite grey metallic	\$1,198	
5389	Steel blue	\$0		7992	Selenite grey metallic	\$1,198	
5524	Black blue	\$1,198		9040	Jet black	\$1,198	
5890	Cavansite blue metallic	\$1,198		9136	Grey white	\$755	
5957	Vanda blue	\$755		9147	Arctic white	\$0	
6830	Aqua green	\$0		9197	Obsidian black metallic	\$1,198	
7160	Stone grey	\$755		9775	Iridiumsilver	\$1,198	

Please see NetStar for latest paint availability information. \\

## **Upholstery**

#### Standard

VF7

Fabric

Maturin Black Upholstery



#### **Optional**

VF4

Fabric

Caluma Black Upholstery

Upcharge				
Cargo	\$	67		
Cab Chassis	\$	67		
Crew Van	\$	229		
Passenger Van	\$	481		



#### **Optional**

VF6

Leatherette Black

Upcharge				
Cargo	\$	67		
Cab Chassis	\$	67		
Crew Van	\$	229		
Passenger Van	\$	481		



#### **Seat restrictions**

			Fabrics	
Code	Seat	VF7	VF4	VF6
	Standard Seats Front	S	0	0
	Standard Seats Rear	S	n/a	0
SF1/SF	Power Seats	n/a	0	0
SB1/SB	Comfort Seats Front	S	0	0
	Comfort Seats Rear	n/a	0	0

Front and rear fabric always have to match.





## Rear view camera/head unit plausibility

	CA/PV/CV						
	Standard	Option A	Option A + JB7	Option A + JB6	Option A + JB8		
Radio/HU	E10	E3M/E4M	E3M/E4M	E3M/E4M	E3M/E4M		
Camera	FR3	FR8	integrated camera	integrated 360 degree camera	integrated 360 degree camera		
Pre-wiring Camera	n/a	n/a	n/a	n/a	n/a		
Camera Display	Interior rear view mirror	7/10.25" Screen	7/10.25" Screen	7/10.25" Screen	7/10.25" Screen		

Options shown above lead to an upcharge.

	CC						
	Standard	Option A	Option B	Option B + JB1/JB2/JB3			
Radio/HU	E10	E10	E3M/E4M	E3M/E4M			
After-Sales Camera	-	Any analog* Camera	Mercedes-Benz Camera** (digital)	n/a			
Pre-wiring	•	FV1	FR7	JB1 / JB2 / JB3			
Camera Display	-	Interior rear view mirror	7/10.25" Screen	7/10.25" Screen			

Options shown above lead to an upcharge.

## **Cargo Van Floor Variations**

Standard	V93	Without factory installed flooring
Ontions	V43	Wood floor with 6 D-rings
Options	VK8	Floor covering, plastic

Note: see restrictions in combination with metallic

#### Special Rule for cargo vans with metallic paint

			_
Paint Code	5890/7755/7992/9197/9775		
	V43	Wood floor with 6 D-rings	1
	VK8	Floor covering, plastic	
		No floor covering; requires customer	
Must have one of		floor installation	
Widst Have one of	779	Package contains:	
	223	V93 - No factory installed flooring	
		VL4 - Metallic painted floor	
		· · ·	

Note: Fleet only

#### Additional comments ZZ9 Package

While applying the required clear coat layer to the metallic painted cargo floor, imperfections could occur. Therefore, we strongly recommend to install flooring in the cargo area for vehicles with a metallic paint.

Please be aware that potential paint appearance, contamination or imperfections of the uncovered cargo floor are not considered a defect and are therefore not reimbursable for repairs.

 $<sup>\</sup>boldsymbol{*}$  only cameras with analog signal works

<sup>\*\*</sup>only the Mercedes-Benz rear view camera works (digital signal)

## **Tire & Wheel Overview**

		1500/250	0 Models
		Standard Tire (Single tire)	RH8
		Standard Wheel (Steel)	RS3
		Optional Wheel (Alloy)	RL5
		Brand (	Options
		RM0 All-season tires	RM1 M+S tires
RD9	Tire brand, unspecified	S	0
RF8	Michelin	0	n/a
RF1	Continental	n/a	0
RH0	Kumho	0	n/a

To order any of the tire brands above code RM9 has to be added to order.

		3500/3500XD Models				
		Standard: Dua	al Rear Wheel	Optional: Sup	oer Single	
		Standard Tire	RH7	Standard Tire	R9A	
		Standard Wheel	RS6	Standard Wheel	RS5	
		Brand Options		Brand Options		
		RM0 All-season tires	RM1 M+S tires	RM0 All-season tires	RM1 M+S tires	
RD9	Tire brand, unspecified	0	0	S	n/a	
RF8	Michelin	0	n/a	n/a	n/a	
RF1	Continental	0	0	0	n/a	
RH0	Kumho	n/a	n/a	n/a	n/a	

To order any of the tire brands above code RM9 has to be added to order.

Standard is DRW, Option is Super Single

		4500 Models- D	ual Rear Wheel
		Standard Tire	RH7
		Standard Wheel	RS6
		Brand (	Options
		RM0 All-season tires	RM1 M+S tires
RD9	Tire brand, unspecified	S	0
RF8	Michelin	0	n/a
RF1	Continental	0	0
RH0	Kumho	n/a	n/a

To order any of the tire brands above code RM9 has to be added to order.

#### **Hermes Module for Government contracts**

Note: municipal and county business is still

Please note that all Sprinter vehicles with the code **JH3** (communications module LTE – standard equipment for all Sprinter) are no longer eligible for tenders, sales, and lease or rental contracts with U.S. federal institutions, such as U.S. governmental bodies, U.S. authorities, U.S. embassies and diplomatic missions as well as U.S. armed forces worldwide.

The background is a new U.S. provision that prohibits the U.S. federal government from entering into, extending, or renewing contracts with any entity that uses any equipment, system, or service that uses telecommunication equipment incorporating certain Chinese technology (Interim rule to Section 889(a)(1)(B) of the John S. McCain National Defense Authorization Act for Fiscal Year 2019, published in the U.S. Federal Register on July 14, 2020).

Since Mercedes-Benz Vans vehicles currently do incorporate such covered technology (code JH3), business with U.S. federal contractor is no longer possible. The new rule applies to contracts entered into after **August 13, 2020** or contracts entered into before **August 13, 2020** of which the supply of vehicles takes place after that date.

#### **Ordering**

If you are planning to supply a customer out of the above listed groups with Sprinter vans, please be aware that JH3 is standard for all Sprinter models. Therefore, a special ordering process is required. For details, please reach out to your responsible RSM.

#### Removal of JH3 from stock vehicles

The Hermes Module can be removed from vehicles. Please contact Service & Parts for details.

144" 4D Std	170" 4D Std	170" E 4D Std
M2CA4S	M2CA7S	M2CAES
907.643	907.645	907.647

Engin	e			
	Standard Output Engine/9-Speed Trans.	S	S	5
ED4	AGM battery 12V 92 AH 850 A	S	S	S
G43	Automatic transmission, 9G-tronic	S	S	S
	Alternator 14 V / 250 A	S	S	S
	Approval Bio-Diesel B20	S	S	S
	2.0L 4-cylinder diesel engine (168hp output)	S	S	S
	SULEV emissions	S	S	S
Equip		3	3	<u> </u>
AR2	Axle ratio 3.923	S	S	S
BA3	Active Brake Assist	S	S	S
BH1	Hold Function	S	S	S
C6L	Multifunction steering wheel	S	S	S
		S		
CL1	Adjustable steering wheel (angle)		S	S
D03	High roof	0	S	S
D93	Omission bulkhead	S	S	S
E07	Hill Start Assist	S	S	S
E10	Standard radio	S	S	S
E1U	USB-C socket, 5 V	S	S	S
E30	Starter battery disconnect	S	S	S
E3J	Pre-installation for switch panel	S	S	S
E40	Trailer hitch prep. wiring	S	S	S
ED8	Preinstallation PSM	S	S	S
EE5	Ultracapacitor discharge module	S	S	S
EK1	Body Builder Connector	S	S	S
ES0	Jump start terminal	S	S	S
EW6	Pre-installation for Mercedes me Remote Services	S	S	S
EY5	Emergency Call System	S	S	S
EY6	Breakdown management	S	S	S
F68	Heated & electrically adjustable exterior mirrors	S	S	S
FF5	Shelf above windshield	S	S	S
FG8	Cupholder front	S	S	S
FI1	Remote key (315 mhz) w/central locking	S	S	S
FJ4	Storage compartment underneath cockpit	S	S	S
FR3	Rear view camera (rear-view mirror display)	S	S	S
H16	Heated driver's seat	S	S	S
H21	Windshield with filter band	S	S	S
HH2	Heater, auxiliary electric hot air	S	S	S
нн9	Air Condition, Front	S	S	S
IH7	Headunit	S	S	S
J11	Speedometer, miles and km/h	S	S	S
J55	Seat belt warning for co-driver seat	S	S	S
J58	Seat belt reminder driver	S	S	S
J65	Outside temperature gauge	S	S	S
JA8	Crosswind Assist	S	S	S
JH3	Communication module (LTE) for dig. services	S	S	S
JI9	Service interval 20.000 miles	S	S	S
JK5		S	S	S
3//2	Instrument cluster with color display	S	S	S
V60	Black diesel filler cap  Exhaust straight to rear	S	S	S S
K60	Exhaust straight to rear			
KB7	24.5 gallon fuel tank	S	S	S
KL1	Aux fuel sending unit w/ fuel tap	S	S	S
M15	Fuel/water seprarator & lubrication package	S	S	S
KP7	4rd generation SCR emission control system	S	S	S
L65	Interior lights, cargo compartment	S	S	S
L94	Parking lights deletion	S	S	S
LA2	Headlight assistant	S	S	S

		144" 4D Std	170" 4D Std	170" E 4D Std
		M2CA4S	M2CA7S	M2CAES
		907.643	907.645	907.647
LB5	3rd brake light	S	S	S
MS1	Cruise control	S	S	S
P47	Front mudflaps	S	S	S
P48	Rear mudflaps	S	S	S
Q11	Longitudinal member reinforcement	S	S	S
R65	Spare tire bracket below frame	S	S	S
R87	Spare tire	S	S	S
RH8	Tires LT 245/75 R16	S	S	S
RM0	All-season tires	S	S	S
RD9	Unspecified tire brand	S	S	S
RS3	6.5 J x 16 steel wheels	S	S	S
RY2	Tire pressure monitoring sensors	S	S	S
S02	Standard driver seat	S	S	S
S04	Standard front passenger seat	S	S	S
S22	Armrest for driver's seat	S	S	S
S25	Armrest for front passenger seat	S	S	S
SA5	Front airbag, driver	S	S	S
SA6	Front airbag, passenger	S	S	S
SH1	Thorax-pelvis sidebag, driver	S	S	S
SH2	Thorax-pelvis sidebag, co-driver	S	S	S
SH9	Airbag, driver/passenger window	S	S	S
SK2	Seat occupancy sensor, driver's seat	S	S	S
T16	Sliding door, passenger side	S	S	S
V93	Without factory installed flooring	S	S	S
V94	Cable duct - side wall	S	S	S
V95	Cable duct - rear portal	S	S	S
W54	Rear doors, opening to side wall	0	0	S
XL2	GVWR 9,050 lbs. / 4.100 Kg	S	S	S
X64	Plates/booklets in English (US)	S	S	S
X99	Manufacturer Mercedes-Benz AG	S	S	S
XC8	VIN visible from outside	S	S	S
XJ3	Change Year G3-I	S	S	S
XY4	Model Year 2024	S	S	S
Y43	Jack, hydraulic	S	S	S
ZU8	USA country version	S	S	S
ZZ4	Brand content Mercedes-Benz North America	S	S	S

		144" 4D Std	170" 4D Std	170" E 4D Std
		M2CA4S	M2CA7S	M2CAES
		907.643	907.645	907.647
A50	Front axle reinforced	\$387	\$387	\$387
AP2	Addtl. bar for driveshaft & exhaust extension	\$77	\$77	-
B01	ESP for increased Center of Gravity above 39.4"	\$0	\$0	\$0
	must have CB4/CB8/X55; not with RH0/CB7			·
B25	Electric parking brake	\$313	\$313	\$313
	not with BE2; X69 choose B25/BE2	<b>4010</b>	Ψ020	Ψ020
BE2	Handbrake lever, folding	\$62	\$62	\$62
	not with B25; X69 choose B25/BE2		, ,	, ,
C72	Bumpers front/rear primed	\$300	\$300	\$300
	must have CN2 (part of X67), not with CM0		·	
CB1	Suspension for comfort and load protection	\$270	\$270	\$270
CB7	Stabilization Level I	\$344	\$344	\$344
	not with CB4/CB8/X55		·	
CB8	Stabilization Level II	\$810	\$810	\$810
	not with CB1/CB4/CB7/X55		·	
CE8	Raised rear body mounts	\$282	\$282	\$282
CM0	Painted metallic front & rear bumper	\$657	\$657	\$657
	must have (CN2/X67) + (JA7/C01) + (JB6/JB7) + (7755/9197/9775)		·	
CM9	Primed side moldings	\$408	\$408	\$408
CT1	Rear spring vibration absorbers	\$155	\$155	\$155
	High roof	\$3,500	S	S
	Mounting rails for roof rack	\$336	\$336	\$336
D22	Fixed sunroof (rear roof section)	\$377	\$377	\$377
	not with H08/HK4/H72/V36/ZK4	Ţ\$??	ţo.,	ψ3
D50	Cargo partition	\$322	\$322	\$322
	not with D51/D93/H08/HK4/T74/V36; must have one of T93/T77	7	70	7522
D51	Cargo partition with 1 window	\$376	\$376	\$376
	not with D50/D93/H08/HK4/T74/V37/D17; must have one of T93/T77	•	·	
E1B	Tray for smartphones incl. wireless charging	\$175	\$175	\$175
	must have CO2/E3M + H1I			
E1E	Navigation	\$815	\$815	\$815
	must have CO2/E3M, not with CO3			
E1S	Sirius XM, satellite radio	\$285	\$285	\$285
	must have CO2/E3M/CO3	•		
E1R	Additional Fuses (40/80/150/100 Ampere)	\$57	\$57	\$57
	must have X2R/ not with E1Y	•		
E1Y	Additional Fuses (40/80/80/100 Ampere)	\$57	\$57	\$57
	must have X2R / not with E1R	•		
E1X	MBUX multimedia 6-hour runtime	\$0	\$0	\$0
	must have X2R + (C02+E1E/E1S)/C03/(E3M+E1E/E1S)	•		
E2A	Access point for BB special signals in cockpit	\$32	\$32	\$32
E2I	Additional battery, co-driver seat base	\$277	\$277	\$277
	must have E36/C06; not with E2M/F09; CHS production only	•		
E2M	Additional battery, engine compartment	\$277	\$277	\$277
	must have X01+ (E36/C06); not with E2I/X69/F09	•		
E3M	MBUX Multimedia System with 7" touchscreen	\$531	\$531	\$531
	not with CO2/CO3; must have JK5+(JB7/JB6/JB8/FR8)			
E36	Cutoff relay for additional battery	\$124	\$124	\$124
	standard with E2I/E2M			
E46	12 V power outlet, driver seat base	\$103	\$103	\$103
E5M	Extension of PSM standard contact	\$65	\$65	\$65
ED5	Parametric special module (PSM)	\$354	\$354	\$354
	, , ,			

		144" 4D Std	170" 4D Std	170" E 4D Std
		M2CA4S	M2CA7S	M2CAES
		907.643	907.645	907.647
EE3	115 V socket	\$140	\$140	\$140
EP7	Basic electric fitting for rear loudspeakers	\$76	\$76	\$76
ES2	12 V power outlet, rear compartment	\$103	\$103	\$103
ES5	Charging package, dashboard	\$92	\$92	\$92
ET4	Active Distance Assist DISTRONIC	\$294	\$294	\$294
	must have CO3	•		
F1K	Coat hooks in driver cabin	\$15	\$15	\$15
	must have D50/D51			
F49	Electrically heated windshield	\$244	\$244	\$244
	no restriction			
F61	Interior rear view mirror	\$41	\$41	\$41
	not with D50; must have C02/E3M/C03			
F64	Electrically folding exterior mirrors	\$55	\$55	\$55
F84	Digital Rearview Mirror	\$736	\$736	\$736
	must have LA2- Not with F61			
FE9	Additional DIN-slot	\$91	\$91	\$91
FF8	Overhead storage slot, front center	\$117	\$117	\$117
FJ1	Hinged lid for storage compartment	\$105	\$105	\$105
FR8	Rear view camera (head unit display)	\$377	\$377	\$377
	must have CO2/E3M; not with FR3/JB7/JB6/JB8			
FY1	Security alarm w. interior motion sensor	\$654	\$654	\$654
	must have LC4/C00			
FY7	Optional 3-button keys	\$41	\$41	\$41
FZ9	Keys, two additional masters	\$136	\$136	\$136
H00	Warm/cool air duct to rear compartment	\$66	\$66	\$66
	not with D50/D51/Y2A			
H01	Heat insulation, rear compartment	\$175	\$175	\$175
	must have V21/V25/VA3/VA1/C07/X66			
H04	Heat insulation, front compartment	\$209	\$209	\$209
	if + D50/D51 must have V07			
H08	Air conditioning rear, roof-mounted	\$3,216	\$3,216	\$3,216
	must have D93 +V36+M61; not with HK4/C06/X66/C07			
H12	Fuel-fired pre-heater/booster (17K BTU)	\$1,249	\$1,249	\$1,249
	not with HZ9			
H13	Rear cabin heater and vents	\$880	\$880	\$880
	must have H12/HZ9			
H15	Heated front passenger seat	\$318	\$318	\$318
	must have H16; not with X68	1 .	1	
H22	Rear window defroster	\$283	\$283	\$283
	must have W61/W78; standard for W61+W70	1 .	1	
H72	Roof fan, electric	\$448	\$448	\$448
	not with D22/V36			
H88	Rear heater prep	\$453	\$453	\$453
	must have H12/HZ9; not with H13/T19			
H1I	Front-to-rear outlet in instrument panel	\$0	\$0	\$0
<u></u>	must have FJ1/C01			
HH4	Thermotronic automatic climate control	\$378	\$378	\$378
	must have JF1; if +H13 must have H08/HK4		1	1
HK4	Rear air conditioner, heavyduty	\$4,411	\$4,411	\$4,411
L	must have D03+V36+D93; not with H08/ZB6/ZE6/N62/N63			/
HZ9	Fuel-fired heater booster (18,000 BTU)	\$756	\$756	\$756
	not with H12			

		144" 4D Std	170" 4D Std	170" E 4D Std
		M2CA4S	M2CA7S	M2CAES
		907.643	907.645	907.647
J51	Fuel gauge, optimized for aux. fuel tap	\$80	\$80	\$80
	not with HZ9/H12	, , , ,	,	,
J52	Engine oil level display at cold start	\$0	\$0	\$0
JA7	Blind Spot Assist	\$504	\$504	\$504
37 (7	must have F64	750-	<del>7</del> 50-1	7504
JB4	Active Lane Keeping Assist	\$322	\$322	\$322
704	standard with CO2/CA2	7322	7322	7322
JB6	Parking Package with 360 degree camera	\$867	\$867	\$867
100	must have CO2/CO3/E3M; not with W75/W76/JB7	Ş607	3007	3007
JB7	Parking Package	\$688	\$688	\$600
JD/		\$888	\$088	\$688
100	must have CO2/CO3/E3M; not with W75/W76/JB6	¢7.00	¢7.00	¢7.00
JB8	360 Degree Camera	\$766	\$766	\$766
	must have CO2/CO3/E3M, not with JB6/JB7	4440	4440	4440
JF1	Rain sensor	\$118	\$118	\$118
	Standard with CO2/CA2/X11	****	4	4
JW0	Backup alarm	\$111	\$111	\$111
JW2	Deactivation lamp monitoring failure	\$30	\$30	\$30
JW8	Attention Assist	\$55	\$55	\$55
K51	Misfueling prevention for Diesel	\$55	\$55	\$55
K52	DEF fluid filler cap - lockable	\$30	\$30	\$30
L13	Fog lamp with cornering light function	\$223	\$223	\$223
L71	Light/motion sensor in rear compartment	\$61	\$61	\$61
	not with V36			
LB9	Illuminated front exits	\$170	\$170	\$170
LC4	Comfort overhead control panel	\$105	\$105	\$105
LC2	LED light strip in load compartment	\$294	\$294	\$294
	not with H08/HK4/V36/C06			
M20	Speed limitation 65 mph	\$67	\$67	\$67
	not with MD3	•		
M61	Alternator 14 V / 280 A	\$188	\$188	\$188
MD3	Top speed limitation 75 mph	\$71	\$71	\$71
	not with M20			
N62	Front engine bracket for additional alternator	\$523	\$523	\$523
	not with HK4/N63	75-5	7525	7525
N63	Front engine bracket for auxiliary A/C compressor	\$523	\$523	\$523
	not with HK4/N62	¥020	<b>4020</b>	<b>4323</b>
P93	Omission of D-rings	-\$15	-\$15	-\$15
1 33	not with D93/V43/VK8	713	713	713
Q24	Trailer hitch, 5,000 lbs	\$164	\$164	\$164
QZ4	not with W73/W75/W76	7104	7104	7104
QA9	Half-sided step rear (for trailer hitch)	\$113	\$113	\$113
QAS	must have Q24/QA2; not with W73/W75/W76	\$112	\$115	\$112
DO1		¢110	-\$110	¢110
R91	Spare tire deletion	-\$110	-\$110	-\$110
DOS	must have R92; not with R87	ćo	ćo	ćo
R92	Spare tire carrier deletion	\$0	\$0	\$0
200	must have R91; not with R65	404	do.	401
R98	Rims painted jet black	\$91	\$91	\$91
	not with RL5/RM2	T		
RF1	Tire brand Continental	\$0	\$0	\$0
	must have RM1 + RM9			
RF8	Tire brand Michelin	\$0	\$0	\$0
	must have RM9; not with RM1			

		144" 4D Std	170" 4D Std	170" E 4D Std M2CAES
		M2CA4S	M2CA7S	
		907.643	907.645	907.647
RH0	Tire brand Kumho	\$0	\$0	\$0
KHU		ŞU	ŞU	ŞÜ
RL5	must have RM9; not with RM1 Light-alloy wheels 6.5 J x 16	\$1,015	¢1.01E	¢1.01E
KLS		\$1,015	\$1,015	\$1,015
DN 41	not with RS3/RM2/R98	¢400	¢400	¢400
RM1	M+S winter tires	\$190	\$190	\$190
DN 42	must have RF1/RD9; not with RF8/RH0/X31	604	604	604
RM2	Rims painted arctic white	\$91	\$91	\$91
DN 40	not with R98/RL5	6112	6443	6442
RM9	Specially requested tires	\$113	\$113	\$113
622	must have RF1/RF8/RH0; not with RD9	4440	4	4440
S23	Twin front passenger seat	\$448	\$448	\$448
	not with C00/X68/X01	4	4	4
S28	Armrest, driver and passenger door	\$58	\$58	\$58
S62	Seat belts orange, driver and front passenger	\$36	\$36	\$36
	not with S23	<u> </u>		
SB9	Driver's seat plus	\$267	\$267	\$267
	must have VF7; not with C00/X68/X69			
SZ7	Storage net, driver's seat backrest	\$71	\$71	\$71
SZ8	Storage net, passenger seat backrest	\$71	\$71	\$71
T12	Sliding door two stage opening	\$92	\$92	\$92
	not with T55			
T50	Electric closing assist right sliding door	\$376	\$376	\$376
	must have D03; not with T55/T93			-
T55	Electric sliding door right	\$930	\$930	\$930
	must have D03 + (FY7+T16); not with T12/T50			
T57	Electric sliding step	\$1,199	\$1,199	\$1,199
	must have ED5; not with T93			
T60	Opening limiter electrically operated sliding door	\$134	\$134	\$134
	must have T55			
T74	Assist handle, B-pillar	\$36	\$36	\$36
	must have D93; not with T77			
T75	Door-mounted assist handles, driver & passenger	\$66	\$66	\$66
T77	Assist handle w/ partition	\$36	\$36	\$36
	must have D50/D51/D64			
T85	Assist handle, left rear door	\$36	\$36	\$36
T86	Assist handles, right rear door	\$36	\$36	\$36
T93	Sliding door right side deletion	\$0	\$0	\$0
	not with T16/T50/T57/VK8/VC5			
V07	Cab rear wall liner	\$403	\$403	\$403
	must have (D50/D51)+F1K; standard with H04			
V21	Luxury interior Trim	\$740	\$740	\$740
	must have VA5/VA7; not with V52/VA1/VA3	-		
V24	Pallet support in sliding door step	\$108	\$108	\$108
	must have (V43/X66)+(D50/D51); not with VK8/V93/C07			
V25	Half height load compartment trim	\$225	\$225	\$225
	not with VA1/VA3/VA5/V52/X66	•		-
V31	Window pillar trim	\$574	\$574	\$574
	must have V36 + (V21/VA1) + (F02/F03/F07); not with V42			
V35	Wheel house covering	\$117	\$117	\$117
	if +V43 must have V25/VA1/VA3; not with V52			

		144" 4D Std	170" 4D Std	170" E 4D Std
		M2CA4S	M2CA7S	M2CAES
		907.643	907.645	907.647
V36	Roof trim	\$982	\$982	\$982
	must have D93; not with D17/D22/H72/L65/L71/LC2/VA3/V42/ZE6/(1			
V42	Lashing rails, waist level	\$310	\$310	\$310
	not with V36/ZE6			
V43	Wood floor with 6 D-rings	\$473	\$473	\$473
	not with P93/V93/VL4/VK8/C07; standard with D93/H13/V24/V52/VC		4	4
V48	Floor cover behind seat box	\$30	\$30	\$30
	must have D93; not with D50/D51/D56/D62/D64/V43/VK8	4	4	4
V4A	Full paneling, right sliding door	\$123	\$123	\$123
	must have D03+T16+V21+VA5+W17; not with T19	4	4	4
V52	Loadable wheel arch	\$419	\$419	\$419
	must have V43/X66; not with EL9/V21/V25/V35/VA1/C07	4	4	
V85	Cigarette lighter & ash cup, front	\$44	\$44	\$44
VA1	Side wall paneling waist height PVC	\$356	\$356	\$356
	must have VA5/VA7; not with V52	4407	4407	4407
VA3	Side wall paneling full hardboard	\$497	\$497	\$497
	not with V36/F02; if T93 must have (D50/D51)	642	ć 42	642
VA5	Full paneling, hinged rear doors	\$43	\$43	\$43
	must have D03+VA7+(W61/W78); not with V25	64.42	64.42	61.12
VA7	Storage compart. w/ net in rear doors	\$142	\$142	\$142
V/C4	must have W61/W78; not with V52	Ć4CE	Ć4CE	Ć 4CF
VC4	Cargo lashing rails, head height	\$465	\$465	\$465
VCE	must have V42/C07/X66; not with ZE6	670	ć70	670
VC5	Door sill - protective edge	\$79	\$79	\$79
VIVO	must have V43/X66; not with T19/T93/VK8/VV2/V93/C07	6414	¢111	¢414
VK8	Floor covering, plastic	\$414	\$414	\$414
VV2	not with V43/P93/T19/T93/V52/VC5/X66 Lashing rails, floor level (plus 4 anchors)	\$302	\$386	\$421
VVZ	must have V43; not with V93/VC5/ZE6	<del>3</del> 302	<del>3</del> 360	3421
VV4	Additional Ground Weld Studs	\$50	\$50	\$50
V V 4	no restriction	\$50	<b>\$</b> 50	\$50
\M16	2nd row, fixed window, driver side	\$162	\$162	\$162
VV 10	if D93 must have F43+W70; if D93 & standard roof CHS production red	•	\$102	\$102
\\/17	2nd row, fixed window, passenger side	\$162	\$162	\$162
VV 17	if D93 must have F43+W70; if D93 & standard roof CHS production red		\$102	\$102
W33	FMVSS 217 emergency exit	\$424	\$424	\$424
VV 33	must have V31; not with D50/T19/W16	<b>7424</b>	<b>7424</b>	7424
\\/5 <i>/</i> I	Rear doors, opening to side wall	\$403	\$403	S
W5F	90 Degree fixation point- Rear Doors	\$90	\$90	\$90
VVJI	must habe W54 / not with V21/V36/VA1/VA7	390	Ş90	Ş <del>3</del> 0
W61	Windows in rear doors	\$105	\$105	\$105
****	must have VA7/ if D51 must have F61; not with W78/(W70+-(H22/F02		7103	7103
W70	Black tinting (90%) for rear windows	\$155	\$155	\$155
VV / O	not with W94; must have W16/W17/F02/((W61/W78)+H22); standard	·	•	7133
W73	Bumper step, rear, grey	\$209	\$209	\$209
,5	not with Q24/W75/W76	7203	7203	7203
W75	Step, wide, at rear end	\$345	\$345	\$345
44/3	not with JB6/JB7/Q24/QA9; must have R91+R92	7040	7040	
W76	Bumper step, rear, spring-loaded	\$673	\$673	\$673
VV / U	must have R91+R92; not with JB6/JB7/X55/Q24	7073	7073	7013
W78	Heated rear window(s) w/ washers/wipers	\$376	\$376	\$376
VV / O	Must have H22+VA7 / if D51 must have F61; not with W61	<i>3310</i>	<i>3310</i>	3370
	mast have 1122 van / 11 Dot must have 1 of, not with wor			

		144" 4D Std	170" 4D Std	170" E 4D Std
		M2CA4S	M2CA7S	M2CAES
		907.643	907.645	907.647
X90	Deletion of Sprinter badge, left rear door	\$0	\$0	\$0
X93	Deletion of model badge, right rear door	\$0	\$0	\$0
X2R	Conversion to RV requirement	\$0	\$0	\$0
	must have B01+D93+E1X			
XM4	Acoustic package	\$97	\$97	\$97
	standard with CO2/CO3			
Y10	First-aid kit	\$30	\$30	\$30
Y26	Wheel chocks	\$43	\$43	\$43
Y45	Emergency flashlight	\$30	\$30	\$30
Y68	Paint preservative	\$209	\$238	\$252
Y69	Surface protection for stock vehicles	\$352	\$352	\$352
YK3	Cargo straps, D-rings	\$91	\$91	\$91
YK4	Cargo straps, lashing rails	\$116	\$116	\$116
	must have V42/VV2; not with ZE6			
ZE6	Shelving prep	\$717	\$717	\$717
	not with T93/H13/T19/V36/V42/VC4/VK8/VV2/YK4	•		

		144" 4D Std	170" 4D Std	170" E 4D Std
		M2CA4S	M2CA7S	M2CAES
		907.643	907.645	907.647
C00	Comfort Package	\$307	\$307	\$307
LC4	Comfort overhead control panel	Х	Х	Х
SE4	Lumbar support, co-driver's seat	Х	Х	Х
SE5	Lumbar support, driver's seat	Х	Х	Х
SK0	Comfort head restraint, driver	Х	Х	Х
SK1	Comfort head restraint, co-driver	Х	Х	Х
must	have COS OR X68; CA/CC only: not with S23			

COS	Comfort Package (Seat addition)	\$426	\$426	\$426	
SB1	Comfort driver's seat	Х	Х	Х	
SB2	Comfort passenger seat	Х	Х	Х	
must	nust have COO				

X68	Comfort Plus Package	\$1,898	\$1,898	\$1,898
H15	Heated front passenger seat	X	X	X
SF1	Driver's seat electrically adjustable	X	X	X
SF2	Co-driver's seat electrically adjustable	X	X	X
must	nust have COO and VF4 OR VF6, CA/CC only: not with S23			

C01	Driver Convenience Package	\$449	\$449	\$449
E46	12 V power outlet, driver seat base	X	X	Х
F64	Electrically folding exterior mirrors	Х	Х	Х
FJ1	Hinged lid for storage compartment	Х	Х	X
FJ5	Hinged Lid for Storage Compartments left and right	X	Х	X
FZ9	Keys, two additional masters	X	Х	X
JW8	Attention Assist	X	Х	X

C02	Premium Package	\$805	\$805	\$805	
E3M	MBUX Multimedia System with 7" touchscreen	Х	X	X	
FM3	Wet Wiper System	Х	X	X	
JB4	Active Lane Keeping Assist	Х	Х	Х	
must	must have JF1 + XM4; must choose FR8/JB7/JB6				

CA2	C02 in combination with C03	\$547	\$547	\$547
CL3	Leather steering wheel	X	X	X
FM3	Wet Wiper System	X	X	X
JB4	Active Lane Keeping Assist	X	X	X
must	have CO3 + JF1	_		

144" 4D Std	170" 4D Std	170" E 4D Std
M2CA4S	M2CA7S	M2CAES
907.643	907.645	907.647

C03	Premium Plus Package	\$2,008	\$2,008	\$2,008
E1B	Tray for smartphones incl. wireless charging	Х	Х	Х
	Navigation	Х	Х	Х
EY2	Intelligent navigation	X	Х	Х
E4M	MBUX Multimedia System with 10.25" touchscreen	X	Х	Х
EX9	Pre-Installation Map Data Updates	X	Х	Х
H1I	Front-to-rear outlet in instrument panel	X	Х	Х
JA9	Traffic Sign Assist	X	Х	Х
XM4	Acoustic package	X	Х	Х
must	have (CA2+(JB7/JB6/JB8)); not with FR8 and CO2		_	_

X67	Chrome Grille Package	\$325	\$325	\$325	
CN2	Radiator grille frame in vehicle color	Х	X	X	
FK3	Chrome plated radiator grille (MB only)	Х	X	X	
no re	no restrictions				

X13	Exterior Lighting Package	\$1,801	\$1,801	\$1,801
L13	Fog lamp with cornering light function	X	X	X
L22	Partial LED tail lights	Х	Х	X
LA1	High beam assist	Х	Х	X
LG7	LED high performance headlamps	Х	Х	X
no re	no restrictions			

C07	Cargo Protection Package	\$1,250	\$1,250	\$1,250
V25	Half height load compartment trim	X	X	X
V42	Lashing rails, waist level	X	X	X
VC4	Cargo lashing rails, head height	X	X	X
VK8	Floor covering, plastic	X	X	X
YK3	Cargo straps, D-rings	Х	Х	X
not w	not with X66			

CR1	Rear Door Convenience Package	\$508	\$508	\$508
T85	Assist handle, left rear door	X	Х	Х
T86	Assist handles, right rear door	Х	Х	Х
W54	Rear doors, opening to side wall	Х	Х	Х
W5F	90 Degree fixation point- Rear Doors	Х	Х	Х

UL1	Upfit Prep and Load Restraining Package	\$1,768	\$1,768	\$1,768
V43	Wood floor with 6 D-rings	X	Х	Х
V42	Lashing rails, waist level	Х	Х	Х
VC4	Cargo lashing rails, head height	X	Х	Х
VA3	Side wall paneling full hardboard	X	Х	Х
VV2	Lashing rails, floor level (plus 4 anchors)	X	X	X

144" 4D Std	170" 4D Std	170" E 4D Std
M2CA4S	M2CA7S	M2CAES
907.643	907.645	907.647

X66	Heavy-Duty-Cargo Protection Package	\$2,287	\$2,287	\$2,287					
V43	Wood floor with 6 D-rings	Х	X	Х					
V42	Lashing rails, waist level	Х	Х	Х					
V52	Loadable wheel arch	Х	Х	Х					
VA3	Side wall paneling full hardboard	Х	Х	Х					
VC4	Cargo lashing rails, head height	Х	Х	Х					
VV2	Lashing rails, floor level (plus 4 anchors)	Х	Х	Х					
YK3	Cargo straps, D-rings	Х	Х	Х					
YK4	Cargo straps, lashing rails	Х	Х	Х					
not v	not with CO7								

X69	Swivel Seat Package	\$595	\$595	\$595			
SR8	Swivel base for driver's seat	Х	Х	Х			
SR9	Swivel base for front passenger seat	Х	Х	Х			
S87	Driver's seat frame, low	Х	Х	Х			
S88	Passenger seat frame, low	Х	Х	Х			
must	nust have (COO+COS) OR (COO+X68), choose BE2 or B25 (1500/2500 only)						

144" 4D High	144" AWD	170" 4D High	170" AWD	170" E 4D High	170" E AWD
M2CA4H	M2CA4A	М2СА7Н	M2CA7A	M2CAEH	M2CAEA
907.643	907.643	907.645	907.645	907.647	907.647

Engir	ne						
4-Cyl	High Output Engine/9-Speed Trans.	S	S	S	S	S	5
ED4	AGM battery 12V 92 AH 850 A	S	S	S	S	S	S
G43	Automatic transmission, 9G-tronic	S	S	S	S	S	S
	SULEV emissions	S	S	S	S	S	S
	2.0L 4-cylinder diesel engine (208hp output)	S	S	S	S	S	S
	Alternator 14 V / 250 A	S	S	S	S	S	S
	Approval Bio-Diesel B20	S	S	S	S	S	S
	All Wheel Drive Package	-	\$6,700	-	\$6,700	-	\$6,700
T75	Door-mounted assist handles, driver & passenger	-	\$ <b>0,700</b>	-	\$ <b>0,700</b>		<b>\$0,700</b>
		-	S	-	S	-	S
	All Wheel Drive with torque on demand	-	3	-	3	-	3
	oment			C	C	C	C
AR2	Axle ratio 3.923	S	S	S	S	S	S
BA3	Active Brake Assist	S	S	S	S	S	S
BH1	Hold Function	S	S	S	S	S	S
	Multifunction steering wheel	S	S	S	S	S	S
CL1	Adjustable steering wheel (angle)	S	S	S	S	S	S
D03	High roof	0	0	S	S	S	S
D93	Omission bulkhead	S	S	S	S	S	S
E07	Hill Start Assist	S	S	S	S	S	S
E10	Standard radio	S	S	S	S	S	S
E1U	USB-C socket, 5 V	S	S	S	S	S	S
E30	Starter battery disconnect	S	S	S	S	S	S
E3J	Pre-installation for switch panel	S	S	S	S	S	S
E40	Trailer hitch prep. wiring	S	S	S	S	S	S
ED8	Preinstallation PSM	S	S	S	S	S	S
EE5	Ultracapacitor discharge module	S	S	S	S	S	S
EK1	Body Builder Connector	S	S	S	S	S	S
ES0	Jump start terminal	S	S	S	S	S	S
EW6	Pre-installation for Mercedes me Remote Services	S	S	S	S	S	S
EY5	Emergency Call System	S	S	S	S	S	S
EY6	Breakdown management	S	S	S	S	S	S
FF5	Shelf above windshield	S	S	S	S	S	S
FG8	Cupholder front	S	S	S	S	S	S
	·	S	S	S	S	S	S
F68	Heated & electrically adjustable exterior mirrors	_	_	_			
FI1	Remote key (315 mhz) w/central locking	S	S	S	S	S	S
FJ4	Storage compartment underneath cockpit	S	S	S	S	S	S
FR3	Rear view camera (rear-view mirror display)	S	S	S	S	S	S
H16	Heated driver's seat	S	S	S	S	S	S
H21	Windshield with filter band	S	S	S	S	S	S
HH2	Heater, auxiliary electric hot air	S	S	S	S	S	S
	Air Condition, Front	S	S	S	S	S	S
IH7	Headunit	S	S	S	S	S	S
J11	Speedometer, miles and km/h	S	S	S	S	S	S
J55	Seat belt warning for co-driver seat	S	S	S	S	S	S
J58	Seat belt reminder driver	S	S	S	S	S	S
J65	Outside temperature gauge	S	S	S	S	S	S
JA8	Crosswind Assist	S	S	S	S	S	S
JH3	Communication module (LTE) for dig. services	S	S	S	S	S	S
JI9	Service interval 20.000 miles	S	S	S	S	S	S
Jk5	Instrument cluster with color display	S	S	S	S	S	S
	Black diesel filler cap	S	S	S	S	S	S
K60	Exhaust straight to rear	S	S	S	S	S	S
KB7	24.5 gallon fuel tank	S	S	S	S	S	S
KL1	Aux fuel sending unit w/ fuel tap	S	S	S	S	S	S
M15	Fuel/water seprarator & lubrication package	S	S	S	S	S	S
KP7	4rd generation SCR emission control system	S	S	S	S	S	S
Kr/	Hun Remenation och ennission control system	3	3	3	3	3	3

		144" 4D High	144" AWD	170" 4D High	170" AWD	170" E 4D High	170" E AWD
		М2СА4Н	M2CA4A	М2СА7Н	M2CA7A	M2CAEH	M2CAEA
		907.643	907.643	907.645	907.645	907.647	907.647
L65	Interior lights, cargo compartment	S	S	S	S	S	S
L94	Parking lights deletion	S	S	S	S	S	S
LA2	Headlight assistant	S	S	S	S	S	S
LB5	3rd brake light	S	S	S	S	S	S
MS1	Cruise control	S	S	S	S	S	S
P47	Front mudflaps	S	S	S	S	S	S
P48	Rear mudflaps	S	S	S	S	S	S
Q11	Longitudinal member reinforcement	S	S	S	S	S	S
R65	Spare tire bracket below frame	S	S	S	S	S	S
R87	Spare tire	S	S	S	S	S	S
RH8	Tires LT 245/75 R16	S	S	S	S	S	S
RM0	All-season tires	S	S	S	S	S	S
RD9	Unspecified tire brand	S	S	S	S	S	S
RS3	6.5 J x 16 steel wheels	S	S	S	S	S	S
RY2	Tire pressure monitoring sensors	S	S	S	S	S	S
S02	Standard driver seat	S	S	S	S	S	S
S04	Standard front passenger seat	S	S	S	S	S	S
S22	Armrest for driver's seat	S	S	S	S	S	S
S25	Armrest for front passenger seat	S	S	S	S	S	S
SA5	Front airbag, driver	S	S	S	S	S	S
SA6	Front airbag, passenger	S	S	S	S	S	S
SH1	Thorax-pelvis sidebag, driver	S	S	S	S	S	S
SH2	Thorax-pelvis sidebag, co-driver	S	S	S	S	S	S
SH9	Airbag, driver/passenger window	S	S	S	S	S	S
SK2	Seat occupancy sensor, driver's seat	S	S	S	S	S	S
T16	Sliding door, passenger side	S	S	S	S	S	S
V93	Without factory installed flooring	S	S	S	S	S	S
V94	Cable duct - side wall	S	S	S	S	S	S
V95	Cable duct - rear portal	S	S	S	S	S	S
W54	Rear doors, opening to side wall	0	0	0	0	S	S
XL2	GVWR 9,050 lbs. / 4.100 Kg	S	S	S	S	S	S
X64	Plates/booklets in English (US)	S	S	S	S	S	S
X99	Manufacturer Mercedes-Benz AG	S	S	S	S	S	S
XC8	VIN visible from outside	S	S	S	S	S	S
XI2	Change Year G2-I	S	S	S	S	S	S
XY4	Model Year 2024	S	S	S	S	S	S
Y43	Jack, hydraulic	S	S	S	S	S	S
ZU8	USA country version	S	S	S	S	S	S
ZZ4	Brand content Mercedes-Benz North America	S	S	S	S	S	S

		144" 4D High	144" AWD	170" 4D High	170" AWD	170" E 4D High	170" E AWD
		M2CA4H	M2CA4A	M2CA7H	M2CA7A	M2CAEH	M2CAEA
		907.643	907.643	907.645	907.645	907.647	907.647
A50	Front axle reinforced	\$387	_	\$387	_	\$387	_
	Addtl. bar for driveshaft & exhaust extension	\$77	\$77	\$77	\$77	-	\$77
B01	ESP for increased Center of Gravity above 39.4"	\$0	\$0	\$0	\$0	\$0	\$0
501	must have CB4/CB8/X55; not with RHO/CB7	70	70	ΨO	70	ΨO	ÇÜ
B25	Electric parking brake	\$313	\$313	\$313	\$313	\$313	\$313
	not with BE2; X69 choose B25/BE2	ψ020	ψ020	ψ525	ψ010	ψ010	<b>4010</b>
BE2	Handbrake lever, folding	\$62	\$62	\$62	\$62	\$62	\$62
	not with B25; X69 choose B25/BE2	,	· ·	,	•	,	
C72	Bumpers front/rear primed	\$300	\$300	\$300	\$300	\$300	\$300
	must have CN2 (part of X67), not with CM0	,	·	,	•	,	· ·
CB1	Suspension for comfort and load protection	\$270	-	\$270	-	\$270	-
CB4	Stabilization Level III	\$1,031	-	\$1,031	-	\$1,031	-
	not with CB1/CB7/CB8/X55						
CB7	Stabilization Level I	\$344	-	\$344	-	\$344	-
	not with CB4/CB8/X55	•					
CB8	Stabilization Level II	\$810	-	\$810	-	\$810	-
	not with CB1/CB4/CB7/X55						
CE8	Raised rear body mounts	\$282	-	\$282	-	\$282	-
CM0	Painted metallic front & rear bumper	\$657	\$657	\$657	\$657	\$657	\$657
	must have (CN2/X67) + (JA7/C01) + (JB6/JB7) + (7755/9197/9775)	•		-		•	
CM9	Primed side moldings	\$408	\$408	\$408	\$408	\$408	\$408
CT1	Rear spring vibration absorbers	\$155	\$155	\$155	\$155	\$155	\$155
D03	High roof	\$3,500	\$3,500	S	S	S	S
D13	Mounting rails for roof rack	\$336	\$336	\$336	\$336	\$336	\$336
D22	Fixed sunroof (rear roof section)	\$377	\$377	\$377	\$377	\$377	\$377
	not with H08/HK4/H72/V36/ZK4						
D50	Cargo partition	\$322	\$322	\$322	\$322	\$322	\$322
	not with D51/D93/H08/HK4/T74/V36; must have one of T93/T77						
D51	Cargo partition with 1 window	\$376	\$376	\$376	\$376	\$376	\$376
	not with D50/D93/H08/HK4/T74/V37/D17; must have one of T93/T7	7					
E1B	Tray for smartphones incl. wireless charging	\$175	\$175	\$175	\$175	\$175	\$175
	must have CO2/E3M + H1I						
E1E	Navigation	\$815	\$815	\$815	\$815	\$815	\$815
	must have CO2/E3M, not with CO3						
E1S	Sirius XM, satellite radio	\$285	\$285	\$285	\$285	\$285	\$285
	must have CO2/E3M/CO3						
E1R	Additional Fuses (40/80/150/100 Ampere)	\$57	\$57	\$57	\$57	\$57	\$57
	must have X2R/ not with E1Y	1					
E1Y	Additional Fuses (40/80/80/100 Ampere)	\$57	\$57	\$57	\$57	\$57	\$57
	must have X2R / not with E1R	1 4-	4-	4-		4-	4 -
E1X	MBUX multimedia 6-hour runtime	\$0	\$0	\$0	\$0	\$0	\$0
F2.4	must have X2R + (C02+E1E/E1S)/C03/(E3M+E1E/E1S)	422	422	422	422	422	422
E2A	Access point for BB special signals in cockpit	\$32	\$32	\$32	\$32	\$32	\$32
E2I	Additional battery, co-driver seat base	\$277	\$277	\$277	\$277	\$277	\$277
<b></b>	must have E36/C06; not with E2M/F09; CHS production only	42	42	42	42	A2==	42
E2M	,	\$277	\$277	\$277	\$277	\$277	\$277
	must have X01+ (E36/C06); not with E2I/X69/F09		4=	4	Aw - :	A	4=
E3M	MBUX Multimedia System with 7" touchscreen	\$531	\$531	\$531	\$531	\$531	\$531
	not with CO2/CO3; must have JK5+(JB7/JB6/JB8/FR8)	1 4.	4.		1.		4.
E36	Cutoff relay for additional battery	\$124	\$124	\$124	\$124	\$124	\$124
	standard with E2I/E2M	1 4.	4.		1.		4.
	12 V power outlet, driver seat base	\$103	\$103	\$103	\$103	\$103	\$103
E5M	Extension of PSM standard contact	\$65	\$65	\$65	\$65	\$65	\$65

		144" 4D High	144" AMD	170" 4D High	170" AWD	170" F 4D High	170" F AWD
		144" 4D High M2CA4H	144" AWD M2CA4A	170" 4D High M2CA7H	M2CA7A	170" E 4D High M2CAEH	170" E AWD M2CAEA
		907.643	907.643	907.645	907.645	907.647	907.647
		907.043	307.043	907.043	307.043	907.647	307.047
ED5	Parametric special module (PSM)	\$354	\$354	\$354	\$354	\$354	\$354
	not with ED8	1 .					
EE3	115 V socket	\$140	\$140	\$140	\$140	\$140	\$140
EP7	Basic electric fitting for rear loudspeakers	\$76	\$76	\$76	\$76	\$76	\$76
ES2	12 V power outlet, rear compartment	\$103	\$103	\$103	\$103	\$103	\$103
ES5	Charging package, dashboard	\$92	\$92	\$92	\$92	\$92	\$92
ET4	Active Distance Assist DISTRONIC	\$294	\$294	\$294	\$294	\$294	\$294
	must have CO3						
F1K	Coat hooks in driver cabin	\$15	\$15	\$15	\$15	\$15	\$15
	must have D50/D51	4		4	4	4	
F49	Electrically heated windshield	\$244	\$244	\$244	\$244	\$244	\$244
	no restriction		4	4	4	4	4
F61	Interior rear view mirror	\$41	\$41	\$41	\$41	\$41	\$41
	not with D50; must have C02/E3M/C03	4		4	4	4	
F64	Electrically folding exterior mirrors	\$55	\$55	\$55	\$55	\$55	\$55
504	no restriction	4=0.0	4===	4=0.0	4=0.0	4=0.0	4=0.0
F84	Digital Rearview Mirror	\$736	\$736	\$736	\$736	\$736	\$736
	must have LA2- Not with F61	401	40.	404	40.	404	40.
FE9	Additional DIN-slot	\$91	\$91	\$91	\$91	\$91	\$91
FF8	Overhead storage slot, front center	\$117	\$117	\$117	\$117	\$117	\$117
FJ1	Hinged lid for storage compartment	\$105	\$105	\$105	\$105	\$105	\$105
FR8	Rear view camera (head unit display)	\$377	\$377	\$377	\$377	\$377	\$377
F) (4	must have CO2/E3M; not with FR3/JB7/JB6/JB8	400.0	4	40=4	40	40=4	40=4
FY1	Security alarm w. interior motion sensor	\$654	\$654	\$654	\$654	\$654	\$654
F) (7	must have LC4/C00	444	<b>A</b> 4 4	644	A44	Ġ44	A 4.4
FY7	Optional 3-button keys	\$41	\$41	\$41	\$41	\$41	\$41
FZ9	Keys, two additional masters	\$136	\$136	\$136	\$136	\$136	\$136
H00	Warm/cool air duct to rear compartment	\$66	\$66	\$66	\$66	\$66	\$66
1101	not with D50/D51/Y2A	6475	6475	6475	Ć4.7E	6475	6475
H01	Heat insulation, rear compartment	\$175	\$175	\$175	\$175	\$175	\$175
1104	must have V21/V25/VA3/VA1/C07/X66	¢200	¢200	¢200	6200	¢200	¢200
H04	Heat insulation, front compartment	\$209	\$209	\$209	\$209	\$209	\$209
1100	if + D50/D51 must have V07	62.246	ć2 24 <i>C</i>	62.246	¢2.246	62.246	¢2.246
H08	Air conditioning rear, roof-mounted	\$3,216	\$3,216	\$3,216	\$3,216	\$3,216	\$3,216
1112	must have D93 +V36+M61; not with HK4/C06/X66/C07	64.240	Ć4 240	¢4.240	ć1 210	Ć4 240	Ć4 240
H12	Fuel-fired pre-heater/booster (17K BTU)	\$1,249	\$1,249	\$1,249	\$1,249	\$1,249	\$1,249
U12	not with HZ9  Pear cabin heater and yents	¢000	¢000	coon	6000	¢000	¢000
H13	Rear cabin heater and vents must have H12/HZ9	\$880	\$880	\$880	\$880	\$880	\$880
H15	Heated front passenger seat	\$318	\$318	\$318	\$318	\$318	\$318
н12		\$318	\$318	\$318	\$318	\$318	\$318
H22	must have H16; not with X68 Rear window defroster	ćaga	ćana	ຕ່ວດວ	ຕ່າຄາ	ຕ່າຄາ	ćaga
HZZ		\$283	\$283	\$283	\$283	\$283	\$283
H72	must have W61/W78; standard for W61+W70  Roof fan, electric	\$448	¢110	\$448	\$448	¢449	¢449
H72		\$ <del>44</del> 6	\$448	\$ <del>44</del> 6	3 <del>44</del> 6	\$448	\$448
цоо	not with D22/V36	¢4E2	¢4E2	¢4E2	¢4E2	¢4E2	¢4E2
H88	Rear heater prep	\$453	\$453	\$453	\$453	\$453	\$453
<b>⊔</b> 11	must have H12/HZ9; not with H13/T19	ćo	ćo	ćo	ćo	¢0	ćo.
H1I	Front-to-rear outlet in instrument panel	\$0	\$0	\$0	\$0	\$0	\$0
11114	must have FJ1/C01	6370	¢270	6270	¢270	6270	ć270
HH4	Thermotronic automatic climate control	\$378	\$378	\$378	\$378	\$378	\$378
111/4	must have JF1; if +H13 must have H08/HK4	64.444	Ć4 444	64.444	¢4.444	Ć4.444	Ć4 444
HK4	Rear air conditioner, heavyduty	\$4,411	\$4,411	\$4,411	\$4,411	\$4,411	\$4,411
1170	must have D03+V36+D93; not with H08/ZB6/ZE6/N62/N63	6756	6756	6756	6756	6756	6756
HZ9	Fuel-fired heater booster (18,000 BTU)	\$756	\$756	\$756	\$756	\$756	\$756
	not with H12						

		144" 4D High	144" AWD	170" 4D High	170" AWD	170" E 4D High	170" E AWD
		M2CA4H	M2CA4A	M2CA7H	M2CA7A	M2CAEH	M2CAEA
		907.643	907.643	907.645	907.645	907.647	907.647
154	First annual authorized for any first ton	ćoo		ćao		ćoo	
J51	Fuel gauge, optimized for aux. fuel tap	\$80	\$80	\$80	\$80	\$80	\$80
15.2	not with HZ9/H12	ćo	ćo	ćo	ćo	ćo	ćo
J52	Engine oil level display at cold start	\$0	\$0	\$0	\$0	\$0	\$0
JA7	Blind Spot Assist	\$504	\$504	\$504	\$504	\$504	\$504
ID4	must have F64	ćana	ćana	ćana	ćaaa	ćana	ćana
JB4	Active Lane Keeping Assist	\$322	\$322	\$322	\$322	\$322	\$322
IDC	standard with CO2/CA2	¢0C7	¢0C7	¢9.67	¢0C7	¢0C7	¢oc7
JB6	Parking Package with 360 degree camera  must have CO2/CO3/E3M; not with W75/W76/JB7	\$867	\$867	\$867	\$867	\$867	\$867
10.7		¢coo	¢coo	¢coo	¢coo	¢coo	¢coo.
JB7	Parking Package	\$688	\$688	\$688	\$688	\$688	\$688
JB8	must have CO2/CO3/E3M; not with W75/W76/JB6	¢7CC	¢7.CC	¢zcc	¢7CC	ĊZCC	¢7CC
JDO	360 Degree Camera must have CO2/CO3/E3M, not with JB6/JB7	\$766	\$766	\$766	\$766	\$766	\$766
JF1	Rain sensor	\$118	\$118	\$118	\$118	\$118	\$118
11.1	Standard with C02/CA2/X11	\$110	\$110	\$110	\$110	\$110	\$110
IVA/O	, ,	Ć111	¢111	¢111	¢111	¢111	¢111
JW0 JW2	Backup alarm  Deactivation lamp monitoring failure	\$111 \$30	\$111 \$30	\$111 \$30	\$111 \$30	\$111 \$30	\$111 \$30
JW8	Attention Assist	\$55	\$55	\$55	\$55	\$55	\$55
K51	Misfueling prevention for Diesel	\$55	\$55 \$55	\$55 \$55	\$55 \$55	\$55 \$55	\$55 \$55
K52	DEF fluid filler cap - lockable	\$30	\$30	\$30	\$30	\$30	\$30
L13	Fog lamp with cornering light function	\$223	\$223	\$223	\$223	\$223	\$223
L71	Light/motion sensor in rear compartment	\$61	\$61	\$61	\$61	\$61	\$61
L/1	not with V36	\$61	201	301	\$61	201	201
LB9	Illuminated front exits	\$170	\$170	\$170	\$170	¢170	\$170
LC4		\$170	\$170	\$170	\$170	\$170 \$105	\$170
LC2	Comfort overhead control panel	\$294	\$294	\$294	\$294	\$294	\$294
LCZ	LED light strip in load compartment not with H08/HK4/V36/C06	Ş254	<b>3234</b>	3234	Ş254	Ş254	<b>3234</b>
M20	Speed limitation 65 mph	\$67	\$67	\$67	\$67	\$67	\$67
IVIZU	not with MD3	<i>3</i> 07	<b>307</b>	Ş07	<b>307</b>	Ş07	Ş07
M61	Alternator 14 V / 280 A	\$188	\$188	\$188	\$188	\$188	\$188
	Top speed limitation 75 mph	\$71	\$71	\$71	\$71	\$71	\$71
IVIDS	not with M20	7/1	7/1	7/1	7/1	7/1	7/1
N62	Front engine bracket for additional alternator	\$523	\$523	\$523	\$523	\$523	\$523
1102	not with HK4/N63	3323	<del>3</del> 323	<del>3</del> 323	<del>3</del> 323	<i>\$32</i> 3	, 3323 
N63	Front engine bracket for auxiliary A/C compressor	\$523	\$523	\$523	\$523	\$523	\$523
1103	not with HK4/N62	3323	<del>3</del> 323	<del>3</del> 323	<del>3</del> 323	<i>\$32</i> 3	, 3323 
P93	Omission of D-rings	-\$15	-\$15	-\$15	-\$15	-\$15	-\$15
133	not with D93/V43/VK8	-313	-513	-512	-512	-513	-513
024	Trailer hitch, 5,000 lbs	\$164	\$164	\$164	\$164	\$164	\$164
Q24	not with W73/W75/W76	7104	7104	Ş10 <del>4</del>	<b>7104</b>	Ş10 <del>4</del>	7104
QA9	Half-sided step rear (for trailer hitch)	\$113	\$113	\$113	\$113	\$113	\$113
QAS	must have Q24/QA2; not with W73/W75/W76	7113	7113	7113	7115	Ş113	7115
R91	Spare tire deletion	-\$110	-\$110	-\$110	-\$110	-\$110	-\$110
NO1	must have R92; not with R87	-3110	-5110	-3110	-3110	-3110	-\$110
R92	Spare tire carrier deletion	\$0	\$0	\$0	\$0	\$0	\$0
NJZ	must have R91; not with R65	Ų	γo	70	Ų	Ų	, Ç0
R98	Rims painted jet black	\$91	\$91	\$91	\$91	\$91	\$91
11.50	not with RL5/RM2	791	791	791	791	791	791
RF1	Tire brand Continental	\$0	\$0	\$0	\$0	\$0	\$0
141 1	must have RM1 + RM9	ŞU	ŞU	ŞU	Ų	Ų	γU
RF8	Tire brand Michelin	\$0	\$0	\$0	\$0	\$0	\$0
111 0	must have RM9; not with RM1	ųυ	υÇ	Ψ	Ų	γU	- JU
RH0	Tire brand Kumho	\$0	\$0	\$0	\$0	\$0	\$0
	must have RM9; not with RM1	70	γo	70	ŢŪ	ΨU	, JU
Ь							

		144" 4D High	144" AWD	170" 4D High	170" AWD	170" E 4D High	170" E AWD
		M2CA4H	M2CA4A	M2CA7H	M2CA7A	M2CAEH	M2CAEA
		907.643	907.643	907.645	907.645	907.647	907.647
		307.043	907.043	307.043	907.043	307.047	307.047
RL5	Light-alloy wheels 6.5 J x 16	\$1,015	\$1,015	\$1,015	\$1,015	\$1,015	\$1,015
	not with RS3/RM2/R98						
RM1	M+S winter tires	\$190	\$190	\$190	\$190	\$190	\$190
	must have RF1/RD9; not with RF8/RH0/X31						
RM2	Rims painted arctic white	\$91	\$91	\$91	\$91	\$91	\$91
	not with R98/RL5						
RM9	Specially requested tires	\$113	\$113	\$113	\$113	\$113	\$113
	must have RF1/RF8/RH0; not with RD9						
S23	Twin front passenger seat	\$448	\$448	\$448	\$448	\$448	\$448
	not with C00/X68/X01						
S28	Armrest, driver and passenger door	\$58	\$58	\$58	\$58	\$58	\$58
S62	Seat belts orange, driver and front passenger	\$36	\$36	\$36	\$36	\$36	\$36
	not with S23						
SB9	Driver's seat plus	\$267	\$267	\$267	\$267	\$267	\$267
	must have VF7; not with C00/X68/X69						
SZ7	Storage net, driver's seat backrest	\$71	\$71	\$71	\$71	\$71	\$71
SZ8	Storage net, passenger seat backrest	\$71	\$71	\$71	\$71	\$71	\$71
T12	Sliding door two stage opening	\$92	\$92	\$92	\$92	\$92	\$92
	not with T55						
T50	Electric closing assist right sliding door	\$376	\$376	\$376	\$376	\$376	\$376
	must have D03; not with T55/T93						
T55	Electric sliding door right	\$930	\$930	\$930	\$930	\$930	\$930
	must have D03 + (FY7+T16); not with T12/T50						
T57	Electric sliding step	\$1,199	\$1,199	\$1,199	\$1,199	\$1,199	\$1,199
	must have ED5; not with T93						
T60	Opening limiter electrically operated sliding door	\$134	\$134	\$134	\$134	\$134	\$134
	must have T55						
T74	Assist handle, B-pillar	\$36	\$36	\$36	\$36	\$36	\$36
	must have D93; not with T77						
T75	Door-mounted assist handles, driver & passenger	\$66	S	\$66	S	\$66	S
T77	Assist handle w/ partition	\$36	\$36	\$36	\$36	\$36	\$36
	must have D50/D51/D64						
T85	Assist handle, left rear door	\$36	\$36	\$36	\$36	\$36	\$36
T86	Assist handles, right rear door	\$36	\$36	\$36	\$36	\$36	\$36
T93	Sliding door right side deletion	\$0	\$0	\$0	\$0	\$0	\$0
	not with T16/T50/T57/VK8/VC5						
V07	Cab rear wall liner	\$403	\$403	\$403	\$403	\$403	\$403
	must have (D50/D51)+F1K; standard with H04						
V21	Luxury interior Trim	\$740	\$740	\$740	\$740	\$740	\$740
	must have VA5/VA7; not with V52/VA1/VA3						
V24	Pallet support in sliding door step	\$108	\$108	\$108	\$108	\$108	\$108
	must have (V43/X66)+(D50/D51); not with VK8/V93/C07						
V25	Half height load compartment trim	\$225	\$225	\$225	\$225	\$225	\$225
	not with VA1/VA3/VA5/V52/X66						

NaccaHa			144" 4D High	144" AWD	170" 4D High	170" AWD	170" E 4D High	170" E AWD
Vision   Vindow pillar trim								M2CAEA
must have V36 + V12/1/A1] + (F02/F03/F07); not with V42							907.647	907.647
must have V36 + V12/1/A1] + (F02/F03/F07); not with V42	V/31	Window pillar trim	\$574	\$574	\$574	\$574	\$574	\$574
Wheel house covering	V31		7374	<del>-</del>	<del>7</del> 574	7374	<i>\$374</i>	Ş37 <del>4</del>
February   September   Septe	V35		\$117	\$117	\$117	\$117	\$117	\$117
March   Marc			Ų-1-7	<b>Ÿ</b> ==7	<b>411</b>	Ų,	Ÿ22,	¥227
must howe D93; not with D17/D22/H72/L65/L71/LC2/N3/N42/Z66/(T93+-D03)/K66/C06/C07   V42	V36		\$982	\$982	\$982	\$982	\$982	\$982
Not with V35/ZE6   V43   V40		must have D93; not with D17/D22/H72/L65/L71/LC2/VA3/V42/ZE6/	(T93+-D03)/X66	/C06/C07		,	·	
1943   Mood floor with 6 D-rings   5473   5473   5473   5473   5473   5473   5473   5473   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474   5474	V42	Lashing rails, waist level	\$310	\$310	\$310	\$310	\$310	\$310
Not with P93/N93/N4/VK8/C07; standard with D93/H13/V24/V52/VC5/VV2/ZE6		not with V36/ZE6						
Note	V43	Wood floor with 6 D-rings	\$473	\$473	\$473	\$473	\$473	\$473
must have D93; not with D50/D51/D56/D62/D64/V43/W8         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$123         \$124         <		not with P93/V93/VL4/VK8/C07; standard with D93/H13/V24/V52/V	/C5/VV2/ZE6					
VAA   Full paneling, right sliding door	V48	Floor cover behind seat box	\$30	\$30	\$30	\$30	\$30	\$30
must have D03+T16+V21+VA5+W17; not with T19         \$419         \$419         \$419         \$419         \$419         \$419         \$419         \$419         \$419         \$419         \$419         \$419         \$419         \$419         \$419         \$419         \$419         \$419         \$419         \$419         \$419         \$419         \$419         \$419         \$419         \$419         \$419         \$419         \$419         \$419         \$419         \$419         \$419         \$419         \$419         \$419         \$419         \$419         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$447         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497		must have D93; not with D50/D51/D56/D62/D64/V43/VK8						
VS2   Loadable wheel arch   S419	V4A	Full paneling, right sliding door	\$123	\$123	\$123	\$123	\$123	\$123
must have V43/X66; not with EL9/V21/V25/V35/VA1/C07         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$47         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497<								
\text{V85} Cigarette lighter & ash cup, front	V52		\$419	\$419	\$419	\$419	\$419	\$419
VA1   Side wall paneling waist height PVC   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356   \$356					4		4	4
must hove VA5/VA7; not with V52         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$497         \$492         \$492         \$424								\$44
VA3   Side wall paneling full hardboard   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497   \$497	VA1		\$356	\$356	\$356	\$356	\$356	\$356
Not with V36/F02; if T93 must have (DS0/DS1)	\/A2		Ć407	¢407	¢407	¢407	¢407	¢407
VAS   Full paneling, hinged rear doors	VA3		\$497	\$497	\$497	\$497	\$497	\$497
must have D03+VA7+{W61/W78}; not with V25           VA7         Storage compart. w/ net in rear doors         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$142         \$145         \$142         \$142 <th< td=""><td>\/</td><td></td><td>\$42</td><td>\$42</td><td>\$42</td><td>\$42</td><td>¢42</td><td>\$43</td></th<>	\/		\$42	\$42	\$42	\$42	¢42	\$43
\text{VA7} Storage compart. w/ net in rear doors \text{\$142} \text{\$143} \text{\$143} \text{\$144} \text{\$145} \text{\$144} \text{\$144} \text{\$144} \text{\$144} \text{\$144} \text{\$414} \text	VAS	5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	<b>ఫ</b> 45	<b>Ş45</b>	<b>345</b>	<b>Ş45</b>	<b>Ş45</b>	<b>ఫ4</b> 5
must have W61/W78; not with V52	VΔ7		\$142	\$142	\$142	\$142	\$142	\$142
VC4         Cargo lashing rails, head height         \$465         \$465         \$465         \$465         \$465         \$465         \$465         \$465         \$465         \$465         \$465         \$465         \$465         \$465         \$465         \$465         \$465         \$465         \$465         \$465         \$465         \$465         \$465         \$465         \$465         \$465         \$465         \$465         \$465         \$405         \$405         \$405         \$405         \$405         \$405         \$405         \$405         \$405         \$405         \$405         \$405         \$405         \$405         \$405         \$405         \$405         \$405         \$405         \$405         \$405         \$405         \$405         \$405         \$405         \$405         \$405         \$405         \$405         \$405         \$405         \$405         \$405         \$405         \$405         \$405         \$405         \$405         \$405         \$405         \$405         \$405         \$405         \$405         \$405         \$405         \$405         \$405         \$405         \$405         \$405         \$405         \$405         \$405         \$405         \$405         \$405         \$405         \$405         \$405	V/A/		7142	7142	<b>Ş142</b>	7142	<b>γ142</b>	7142
must have V42/C07/X66; not with ZE6         \$79         \$79         \$79         \$79           VC5         Door sill – protective edge         \$79         \$79         \$79         \$79           must have V43/X66; not with T19/T93/V58/VV2/V93/C07         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$	VC4		\$465	\$465	\$465	\$465	\$465	\$465
VC5         Door sill - protective edge         \$79         \$79         \$79         \$79           must have V43/X66; not with T19/T93/VK8/VV2/V93/C07         VK8         Floor covering, plastic         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$424         \$421 <td></td> <td></td> <td>7 .00</td> <td>7.00</td> <td>7 .55</td> <td>¥ .55</td> <td>7.00</td> <td>7 .55</td>			7 .00	7.00	7 .55	¥ .55	7.00	7 .55
must have V43/X66; not with T19/T93/VK8/VV2/V93/C07           VK8         Floor covering, plastic         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$414         \$421         \$42	VC5		\$79	\$79	\$79	\$79	\$79	\$79
not with V43/P93/T19/T93/V52/VC5/X66           VV2 Lashing rails, floor level (plus 4 anchors)         \$302         \$302         \$386         \$386         \$421         \$386           wust have V43; not with V93/VC5/ZE6         W14         Additional Ground Weld Studs         \$50         \$50         \$50         \$50           wust form or estriction         W16         2nd row, fixed window, driver side         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162		must have V43/X66; not with T19/T93/VK8/VV2/V93/C07		•	•			
VV2         Lashing rails, floor level (plus 4 anchors)         \$302         \$386         \$386         \$421         \$	VK8	Floor covering, plastic	\$414	\$414	\$414	\$414	\$414	\$414
must have V43; not with V93/VC5/ZE6           VV4 Additional Ground Weld Studs         \$50         \$50         \$50           W16 2nd row, fixed window, driver side         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$16		not with V43/P93/T19/T93/V52/VC5/X66						
VV4         Additional Ground Weld Studs         \$50         \$50         \$50         \$50           no restriction         W16         2nd row, fixed window, driver side         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162	VV2	Lashing rails, floor level (plus 4 anchors)	\$302	\$302	\$386	\$386	\$421	\$421
No restriction   No restriction   Side   S		must have V43; not with V93/VC5/ZE6						
W16         2nd row, fixed window, driver side         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162         \$162	VV4	Additional Ground Weld Studs	\$50	\$50	\$50	\$50	\$50	\$50
if D93 must have F43+W70; if D93 & standard roof CHS production required  W17 2nd row, fixed window, passenger side \$162 \$162 \$162 \$162 \$162 \$162 \$162 \$162		no restriction						
W17       2nd row, fixed window, passenger side       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$162       \$124       \$124       \$124       \$124       \$124       \$124       \$124       \$124       \$124       \$124       \$124       \$124       \$124       \$124       \$124       \$124       \$124       \$124       \$12	W16			\$162	\$162	\$162	\$162	\$162
if D93 must have F43+W70; if D93 & standard roof CHS production required  W33 FMVSS 217 emergency exit \$424 \$424 \$424 \$424 \$424 \$424 \$424 \$42								
W33   FMVSS 217 emergency exit   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$424   \$4	W17			\$162	\$162	\$162	\$162	\$162
must have V31; not with D50/T19/W16         W54 Rear doors, opening to side wall       \$403       \$403       \$403       \$403       \$         W5F 90 Degree fixation point- Rear Doors       \$90       \$90       \$90       \$90       \$90         must habe W54 / not with V21/V36/VA1/VA7       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105 <td< td=""><td></td><td>, , , ,</td><td>,</td><td></td><td>4</td><td></td><td></td><td>4</td></td<>		, , , ,	,		4			4
W54       Rear doors, opening to side wall       \$403       \$403       \$403       \$403       \$         W5F       90       \$90       \$90       \$90       \$90       \$90       \$90         must habe W54 / not with V21/V36/VA1/VA7         W61       Windows in rear doors       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105 <td< td=""><td>W33</td><td>,</td><td>\$424</td><td>\$424</td><td>\$424</td><td>\$424</td><td>\$424</td><td>\$424</td></td<>	W33	,	\$424	\$424	\$424	\$424	\$424	\$424
W5F         90 Degree fixation point- Rear Doors         \$90         \$90         \$90         \$90           must habe W54 / not with V21/V36/VA1/VA7         windows in rear doors         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105	\A/E 4		¢402	Ć 402	¢402	Ć402	C	C
must habe W54 / not with V21/V36/VA1/VA7         W61       Windows in rear doors       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105       \$105				-				S
W61         Windows in rear doors         \$105         \$105         \$105         \$           must have VA7/ if D51 must have F61; not with W78/(W70+-(H22/F02))         W70         Black tinting (90%) for rear windows         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155         \$155 </td <td>WSF</td> <td></td> <td>\$90</td> <td>\$90</td> <td>\$90</td> <td>\$90</td> <td>\$90</td> <td>\$90</td>	WSF		\$90	\$90	\$90	\$90	\$90	\$90
must have VA7/ if D51 must have F61; not with W78/(W70+-(H22/F02))         W70 Black tinting (90%) for rear windows       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155 <t< td=""><td>\\/61</td><td></td><td>¢10E</td><td>\$105</td><td>\$10E</td><td>\$105</td><td>\$10E</td><td>\$105</td></t<>	\\/61		¢10E	\$105	\$10E	\$105	\$10E	\$105
W70       Black tinting (90%) for rear windows       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155       \$155	4401			7103	2103	7103	7103	7103
not with W94; must have W16/W17/F02/((W61/W78)+H22); standard with F43/W33/F07         W73       Bumper step, rear, grey       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209       \$209	\M/70			\$155	\$155	\$155	\$155	\$155
W73 Bumper step, rear, grey \$209 \$209 \$209 \$209 \$  not with Q24/W75/W76	**/0				7133	7133	7133	7133
not with Q24/W75/W76	W73				\$209	\$209	\$209	\$209
			<b>¥203</b>	Ψ203	<b>\$203</b>	Ų203	Ψ203	<b>\$203</b>
[vv/5   545   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   5345   53	W75	Step, wide, at rear end	\$345	\$345	\$345	\$345	\$345	\$345
not with JB6/JB7/Q24/QA9; must have R91+R92								
W76 Bumper step, rear, spring-loaded \$663 - \$663 - \$663	W76		\$663	-	\$663	-	\$663	-
must have R91+R92; not with JB6/JB7/X55/Q24								
	W78		\$376	\$376	\$376	\$376	\$376	\$376
Must have H22+VA7 / if D51 must have F61; not with W61		Must have H22+VA7 / if D51 must have F61; not with W61						
X2R Conversion to RV requirement \$0 \$0 \$0 \$0	X2R	Conversion to RV requirement	\$0	\$0	\$0	\$0	\$0	\$0
	1	must have B01+D93+E1X						

		144" 4D High	144" AWD	170" 4D High	170" AWD	170" E 4D High	170" E AWD
		M2CA4H	M2CA4A	M2CA7H	M2CA7A	M2CAEH	M2CAEA
		907.643	907.643	907.645	907.645	907.647	907.647
X90	Deletion of Sprinter badge, left rear door	\$0	\$0	\$0	\$0	\$0	\$0
X93	Deletion of model badge, right rear door	\$0	\$0	\$0	\$0	\$0	\$0
XM4	Acoustic package	\$97	\$97	\$97	\$97	\$97	\$97
	standard with C02/C03						
Y10	First-aid kit	\$30	\$30	\$30	\$30	\$30	\$30
Y26	Wheel chocks	\$43	\$43	\$43	\$43	\$43	\$43
Y45	Emergency flashlight	\$30	\$30	\$30	\$30	\$30	\$30
Y68	Paint preservative	\$209	\$209	\$238	\$238	\$252	\$252
Y69	Surface protection for stock vehicles	\$352	\$352	\$352	\$352	\$352	\$352
YK3	Cargo straps, D-rings	\$91	\$91	\$91	\$91	\$91	\$91
YK4	Cargo straps, lashing rails	\$116	\$116	\$116	\$116	\$116	\$116
	must have V42/VV2; not with ZE6						
ZE6	Shelving prep	\$717	\$717	\$717	\$717	\$717	\$717
	not with T93/H13/T19/V36/V42/VC4/VK8/VV2/YK4						
ZH4	Downhill speed regulation for AWD	-	\$61	-	\$61	-	\$61
	must have ED5						

		144" 4D High	144" AWD	170" 4D High	170" AWD	170" E 4D High	170" E AWD
		M2CA4H	M2CA4A	М2СА7Н	M2CA7A	M2CAEH	M2CAEA
		907.643	907.643	907.645	907.645	907.647	907.647
C00	Comfort Package	\$307	\$307	\$307	\$307	\$307	\$307
LC4	Comfort overhead control panel	Х	Х	Х	Х	X	Х
SE4	Lumbar support, co-driver's seat	X	Χ	X	Х	X	Χ
SE5	Lumbar support, driver's seat	X	Χ	X	Х	X	Χ
SK0	Comfort head restraint, driver	Х	X	Х	Х	Х	Х
SK1	Comfort head restraint, co-driver	Х	Х	Х	Х	Х	Х
must	have COS OR X68; CA/CC only: not with S23	•		•			·

COS	Comfort Package (Seat addition)	\$426	\$426	\$426	\$426	\$426	\$426
SB1	Comfort driver's seat	Х	Х	Х	Х	Х	Х
SB2	Comfort passenger seat	Х	Х	Х	Х	Х	Х
must	have COO	•	•	•		•	

X68	Comfort Plus Package	\$1,898	\$1,898	\$1,898	\$1,898	\$1,898	\$1,898
H15	Heated front passenger seat	Х	Х	Х	Х	Х	Х
SF1	Driver's seat electrically adjustable	Х	Х	Х	Х	Х	Х
SF2	Co-driver's seat electrically adjustable	Х	Х	Х	Х	Х	Х
must	ust have COO and VF4 OR VF6, CA/CC only: not with S23						

C01	Driver Convenience Package	\$449	\$449	\$449	\$449	\$449	\$449
E46	12 V power outlet, driver seat base	Х	Х	Х	Х	Х	Х
F64	Electrically folding exterior mirrors	Х	Х	Х	Х	Х	Х
FJ1	Hinged lid for storage compartment	Х	Х	Х	Х	Х	Х
FJ5	Hinged Lid for Storage Compartments left and right	Х	Х	Х	Х	Х	Х
FZ9	Keys, two additional masters	X	Х	Х	X	Х	Х
JW8	Attention Assist	Х	Х	Х	Χ	Х	Х

C02	Premium Package	\$805	\$805	\$805	\$805	\$805	\$805		
E3M	MBUX Multimedia System with 7" touchscreen	Х	Х	Х	Х	Х	Х		
FM3	Wet Wiper System	Х	Х	Х	Х	Х	Х		
JB4	Active Lane Keeping Assist	Х	Х	Х	Х	Х	Х		
must	must have JF1 + XM4; must choose FR8/JB7/JB6								

CA2	C02 in combination with C03	\$547	\$547	\$547	\$547	\$547	\$547	
CL3	Leather steering wheel	Х	X	X	Х	Х	Х	
FM3	Wet Wiper System	Х	X	X	X	Х	X	
JB4	Active Lane Keeping Assist	X	X	X	X	Х	X	
must	nust have CO3 + JF1							

144" 4D High	144" AWD	170" 4D High	170" AWD	170" E 4D High	170" E AWD
M2CA4H	M2CA4A	М2СА7Н	M2CA7A	M2CAEH	M2CAEA
907.643	907.643	907.645	907.645	907.647	907.647

C03	Premium Plus Package	\$2,008	\$2,008	\$2,008	\$2,008	\$2,008	\$2,008
E1B	Tray for smartphones incl. wireless charging	Х	Х	Х	Х	Х	Х
	Navigation	Х	Х	Х	Х	Х	Х
EY2	Intelligent navigation	Х	X	Х	Х	Х	X
E4M	MBUX Multimedia System with 10.25" touchscreen	Х	Х	Х	Х	Х	Х
EX9	Pre-Installation Map Data Updates	Х	Х	Х	Х	Х	Х
H1I	Front-to-rear outlet in instrument panel	Х	Х	Х	Х	Х	Х
JA9	Traffic Sign Assist	Х	Х	Х	Х	Х	Х
XM4	Acoustic package	Х	Х	Х	Х	Х	Х
must	have (CA2+(JB7/JB6/JB8)); not with FR8 and CO2						

X67	Chrome Grille Package	\$325	\$325	\$325	\$325	\$325	\$325
CN2	Radiator grille frame in vehicle color	Х	Х	Х	Х	Х	Х
FK3	Chrome plated radiator grille (MB only)	Х	Х	Х	Х	Х	Х
no re	o restrictions						

X13	Exterior Lighting Package	\$1,801	\$1,801	\$1,801	\$1,801	\$1,801	\$1,801		
L13	Fog lamp with cornering light function	Х	Х	Х	Х	Х	X		
L22	Partial LED tail lights	Х	Х	Х	Х	Х	Х		
LA1	High beam assist	Х	Х	Х	Х	Х	Х		
LG7	LED high performance headlamps	Х	Х	Х	Х	Х	Х		
no re	o restrictions								

C07	Cargo Protection Package	\$1,250	\$1,250	\$1,250	\$1,250	\$1,250	\$1,250			
V25	Half height load compartment trim	Х	Х	Х	Х	Х	Х			
V42	Lashing rails, waist level	Х	Х	Х	Х	Х	Х			
VC4	Cargo lashing rails, head height	Х	Х	Х	Х	Х	Х			
VK8	Floor covering, plastic	Х	Х	Х	Х	Х	Х			
YK3	Cargo straps, D-rings	Х	Х	Х	Х	Х	Х			
not v	ot with X66									

CR1	Rear Door Convenience Package	\$508	\$508	\$508	\$508	\$508	\$508
T85	Assist handle, left rear door	X	X	X	X	X	X
T86	Assist handles, right rear door	Х	Х	Х	Х	Х	X
W54	Rear doors, opening to side wall	Х	Х	Х	Х	Х	X
W5F	90 Degree fixation point- Rear Doors	Х	X	Х	Х	Х	X

UL1	Upfit Prep and Load Restraining Package	\$1,768	\$1,768	\$1,768	\$1,768	\$1,768	\$1,768
V43	Wood floor with 6 D-rings	Х	Х	Х	Х	Х	Х
V42	Lashing rails, waist level	Х	Х	Х	Х	Х	Х
VC4	Cargo lashing rails, head height	Х	Х	Х	Х	Х	Х
VA3	Side wall paneling full hardboard	Х	Х	Х	Х	Х	Х
VV2	Lashing rails, floor level (plus 4 anchors)	Х	Х	Х	Х	Х	Х

144" 4D High	144" AWD	170" 4D High	170" AWD	170" E 4D High	170" E AWD
M2CA4H	M2CA4A	М2СА7Н	M2CA7A	M2CAEH	M2CAEA
907.643	907.643	907.645	907.645	907.647	907.647

X66	Heavy-Duty-Cargo Protection Package	\$2,287	\$2,287	\$2,287	\$2,287	\$2,287	\$2,287
V43	Wood floor with 6 D-rings	Х	Х	Х	Х	Х	Х
V42	Lashing rails, waist level	Х	Х	Х	Х	Х	Х
V52	Loadable wheel arch	Х	Х	Х	Х	Х	Х
VA3	Side wall paneling full hardboard	Х	Х	Х	Х	Х	Х
VC4	Cargo lashing rails, head height	Х	Х	Х	Х	Х	Х
VV2	Lashing rails, floor level (plus 4 anchors)	Х	Х	Х	Х	Х	Х
YK3	Cargo straps, D-rings	Х	Х	Х	Х	Х	Х
YK4	Cargo straps, lashing rails	Х	Х	Х	Х	Х	Х
not v	vith CO7	·		•	•	•	

X69	Swivel Seat Package	\$595	\$595	\$595	\$595	\$595	\$595
SR8	Swivel base for driver's seat	Х	Х	Х	Х	Х	Х
SR9	Swivel base for front passenger seat	Х	Х	Х	Х	Х	Х
S87	Driver's seat frame, low	Х	Х	Х	Х	Х	Х
S88	Passenger seat frame, low	Х	Х	Х	Х	Х	Х
must	must have (C00+C0S) OR (C00+X68), choose BE2 or B25 (1500/2500 only)						

144" 4D Std	170" 4D Std	170" E 4D Std
M3CA4S	M3CA7S	M3CAES
907.653	907.655	907.657

Engin		_	_	-
	Standard Output Engine/9-Speed Trans.	5	S	S
	AGM battery 12V 92 AH 850 A	S	S	S
	Automatic transmission, 9G-tronic	S	S	S
	Alternator 14 V / 250 A	S	S	S
M71	Approval Bio-Diesel B20	S	S	S
MU5	2.0L 4-cylinder diesel engine (168hp output)	S	S	S
MH8	SULEV emissions	S	S	S
Tires -	choose while ordering			
X34	Dual Rear Wheel	<i>\$0</i>	\$0	\$0
RH7	Tires LT 215/85 R16- DRW	S	S	S
RS6	5.5 J x 16 steel wheels	S	S	S
RD9	Unspecified tire brand	S	S	S
X31	Super Single Tire	\$431	\$431	\$431
R9A	285/65 R 16 C super single tires	0	0	0
RS5	Steel wheels: 8.5Jx16 Rr; 6.5Jx16 Fr	0	0	0
RD9	Unspecified tire brand	0	0	0
RY2	Tire pressure monitoring sensors	0	0	0
Equip	ment	•		
AR2	Axle ratio 3.923	S	S	S
BA3	Active Brake Assist	S	S	S
BH1	Hold Function	S	S	S
C6L	Multifunction steering wheel	S	S	S
	Stabilization Level II	S	S	S
	Adjustable steering wheel (angle)	S	S	S
	High roof	0	S	S
D93	Omission bulkhead	S	S	S
	Hill Start Assist	S	S	S
E10	Standard radio	S	S	S
	USB-C socket, 5 V	S	S	S
	Starter battery disconnect	S	S	S
E3J	Pre-installation for switch panel	S	S	S
E40	·	S	S	S
	Trailer hitch prep. wiring	S	S	S
	Preinstallation PSM			
EE5	Ultracapacitor discharge module	S	S	S
	Body Builder Connector	S	S	S
	Jump start terminal	S	S	S
	Pre-installation for Mercedes me Remote Services	S	S	S
	Emergency Call System	S	S	S
	Breakdown management	S	S	S
F68	Heated & electrically adjustable exterior mirrors	S	S	S
FF5	Shelf above windshield	S	S	S
FG8	Cupholder front	S	S	S
FI1	Remote key (315 mhz) w/central locking	S	S	S
FJ4	Storage compartment underneath cockpit	S	S	S
FR3	Rear view camera (rear-view mirror display)	S	S	S
H16	Heated driver's seat	S	S	S
H21	Windshield with filter band	S	S	S
HH2	Heater, auxiliary electric hot air	S	S	S
HH9	Air Condition, Front	S	S	S
IH7	Headunit	S	S	S
J11	Speedometer, miles and km/h	S	S	S
ILL	Seat belt warning for co-driver seat	S	S	S
J55	Seat beit warning for co-driver seat	3		
J58	Seat belt warning for co-driver seat	S	S	S
	-			S S

Service interval 20.000 miles   S   S   S   S   S   S   S   S   S			N43C14C	N42C47C	1420150
H3   Communication module (LTE) for dig. services   S   S   S     JIS   Service interval 20.000 miles   S   S   S     JIKS   Instrument cluster with color display   S   S   S     Black dieself filler cap   S   S   S     Black dieself filler cap   S   S   S   S     K6D   Exhaust straight to rear   S   S   S   S     K87   24.5 gallon fuel tank   S   S   S   S     K87   24.5 gallon fuel tank   S   S   S   S     K81   Aux fuel sending unit w/ fuel tap   S   S   S   S     K81   Aux fuel sending unit w/ fuel tap   S   S   S   S     M15   Fuel/water seprarator & lubrication package   S   S   S   S     M15   Fuel/water seprarator & lubrication package   S   S   S   S     M15   Tuel/water seprarator & lubrication package   S   S   S   S     M15   Tuel/water seprarator & lubrication package   S   S   S   S     M15   Tuel/water seprarator & lubrication package   S   S   S   S     M15   Tuel/water seprarator & lubrication package   S   S   S   S     M15   Tuel/water seprarator & lubrication package   S   S   S   S     M15   Tuel/water seprarator & lubrication package   S   S   S   S   S     M15   Tuel/water seprarator & lubrication package   S   S   S   S     M15   Tuel/water separator & lubrication package   S   S   S   S     M15   Tuel/water separator & lubrication package   S   S   S   S     L65   Interior lights, cargo compartment   S   S   S   S   S   S     L65   Interior lights, cargo compartment   S   S   S   S   S   S     M15   Tuel/water separator & S   S   S   S   S   S     M15   Tuel/water separator & S   S   S   S   S     M15   Tuel/water separator & S   S   S   S   S   S     M15   Tuel/water separator & S   S   S   S   S     M15   Tuel/water separator & S   S   S   S   S     M16   Tuel/water separator & S   S   S   S   S     M16   Tuel/water separator & S   S   S   S   S     M17   Tuel/water separator & S   S   S   S     M18   Tuel/water separator & S   S   S   S     M19   Tuel/water separator & S   S   S   S     M10   Tuel/water separator & S   S   S   S     M10   Tuel/water separator & S   S   S   S     M1					M3CAES
JIS   Service interval 20.000 miles   S   S   S   S   S   S   S   S   S			907.653	907.655	907.657
INST   Instrument cluster with color display   S   S   S   S   Black diesel filler cap   S   S   S   S   S   S   S   S   S	JH3	Communication module (LTE) for dig. services	S	S	S
Black diesel filler cap	JI9	Service interval 20.000 miles	S	S	S
K60         Exhaust straight to rear         S         S           K87         24.5 gallon fuel tank         S         S           K1.1         Aux fuel sending unit w/ fuel tap         S         S           M15         Fuel/water seprarator & lubrication package         S         S         S           M15         Fuel/water seprarator & lubrication package         S         S         S         S           M15         Top speed limitation 75 mph         S         O         O         O           KP7         4rd generation SCR emission control system         S         S         S         S           L65         Interior lights, cargo compartment         S         S         S         S           L65         Interior lights, cargo compartment         S         S         S         S           L64         Parking lights deletion         S         S         S         S         S           L84         Parking lights deletion         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S	JK5	Instrument cluster with color display	S	S	S
KB7         24.5 gallon fuel tank         S         S           KL1         Aux fuel sending unit w/ fuel tap         S         S           M15         Fuel/water seprarator & lubrication package         S         S           MD3         Top speed limitation 75 mph         S         O           MD3         Top speed limitation 75 mph         S         O           KP7         4rd generation SCR emission control system         S         S           L65         Interior lights, cargo compartment         S         S           L94         Parking lights deletion         S         S           L94         Parking lights deletion         S         S           LA2         Headlight assistant         S         S           L85         3rd brake light         S         S           M51         Cruise control         S         S         S           M52         Tont mudflaps         S         S         S           P47         Front mudflaps         S         S         S           P48         Rear mudflaps         S         S         S           Q11         Longitudinal member reinforcement         S         S         S <t< td=""><td></td><td>Black diesel filler cap</td><td>S</td><td>S</td><td>S</td></t<>		Black diesel filler cap	S	S	S
KL1         Aux fuel sending unit w/ fuel tap         S         S           M15         Fuel/water seprarator & lubrication package         S         S           M15         Fuel/water seprarator & lubrication package         S         S           M15         Top speed limitation 75 mph         S         O           KP7         4rd generation SCR emission control system         S         S           L65         Interior lights, cargo compartment         S         S           L65         Interior lights, cargo compartment         S         S           L94         Parking lights deletion         S         S           L24         Headlight assistant         S         S           L85         3rd brake light         S         S           M51         Cruise control         S         S           L85         3rd brake light         S         S           M51         Cruise control         S         S           L87         Font mudflaps         S         S           L87         Font mudflaps         S         S           L88         S pare tire bracket below frame         S         S           R87         Spare tire bracket below frame         S <td>K60</td> <td>Exhaust straight to rear</td> <td>S</td> <td>S</td> <td>S</td>	K60	Exhaust straight to rear	S	S	S
M15         Fuel/water seprarator & lubrication package         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$ </td <td>KB7</td> <td>24.5 gallon fuel tank</td> <td>S</td> <td>S</td> <td>S</td>	KB7	24.5 gallon fuel tank	S	S	S
MD3         Top speed limitation 75 mph         S         O         O           KP7         4rd generation SCR emission control system         S         S         S           L65         Interior lights, cargo compartment         S         S         S         S           L94         Parking lights deletion         S         S         S         S         S         L           LA2         Headlight assistant         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S	KL1	Aux fuel sending unit w/ fuel tap	S	S	S
KP7       4rd generation SCR emission control system       S       S       S         L65       Interior lights, cargo compartment       S       S       S         L94       Parking lights deletion       S       S       S         LA2       Headlight assistant       S       S       S         LB5       3rd brake light       S       S       S         MS1       Cruise control       S       S       S         MS1       Cruise control       S       S       S         P47       Front mudflaps       S       S       S         P48       Rear mudflaps       S       S       S         Q11       Longitudinal member reinforcement       S       S       S         R65       Spare tire bracket below frame       S       S       S         R65       Spare tire       S       S       S         R7       Spare tire       S       S       S         R87       Spare tire       S       S       S         R87       Spare tire       S       S       S         R87       Spare tire       S       S       S       S         R87 <td< td=""><td>M15</td><td>Fuel/water seprarator &amp; lubrication package</td><td>S</td><td>S</td><td>S</td></td<>	M15	Fuel/water seprarator & lubrication package	S	S	S
L65         Interior lights, cargo compartment         S         S         S           L94         Parking lights deletion         S         S         S           LA2         Headlight assistant         S         S         S           LB5         3rd brake light         S         S         S           MS1         Cruise control         S         S         S           MS1         Cruise control         S         S         S           P47         Front mudflaps         S         S         S           P48         Rear mudflaps         S         S         S           Q11         Longitudinal member reinforcement         S         S         S           R65         Spare tire bracket below frame         S         S         S           R65         Spare tire bracket below frame         S         S         S           R87         Spare tire         S         S         S           R87 <t< td=""><td>MD3</td><td>Top speed limitation 75 mph</td><td>S</td><td>0</td><td>0</td></t<>	MD3	Top speed limitation 75 mph	S	0	0
L94         Parking lights deletion         S         S         S           LA2         Headlight assistant         S         S         S           LB5         3rd brake light         S         S         S           MS1         Cruise control         S         S         S           MS1         Cruise control         S         S         S           P47         Front mudflaps         S         S         S           P48         Rear mudflaps         S         S         S           C11         Longitudinal member reinforcement         S         S         S           R65         Spare tire bracket below frame         S         S         S           R65         Spare tire         S         S         S           R87         Spare tire         S         S         S           S02         Standard driver seat         S <td>KP7</td> <td>4rd generation SCR emission control system</td> <td>S</td> <td>S</td> <td>S</td>	KP7	4rd generation SCR emission control system	S	S	S
LA2         Headlight assistant         S         S         S           LB5         3rd brake light         S         S         S           MS1         Cruise control         S         S         S           P47         Front mudflaps         S         S         S           P48         Rear mudflaps         S         S         S           P48         Rear mudflaps         S         S         S           Q11         Longitudinal member reinforcement         S         S         S           R65         Spare tire bracket below frame         S         S         S           R65         Spare tire bracket below frame         S         S         S           R7         Spare tire bracket below frame         S         S         S           R87         Spare tire         S         S         S           S02         Standard driver seat         S         S         S           S02         Standar	L65	Interior lights, cargo compartment	S	S	S
LB5         3rd brake light         S         S         S           MS1         Cruise control         S         S         S           P47         Front mudflaps         S         S         S           P48         Rear mudflaps         S         S         S           Q11         Longitudinal member reinforcement         S         S         S           R65         Spare tire bracket below frame         S         S         S           R87         Spare tire         S         S         S           R87         Spare tire         S         S         S           R87         Spare tire bracket below frame         S         S         S           R87         Spare tire bracket below frame         S         S         S           R87         Spare tire bracket below frame         S         S         S           R87         Spare tire bracket below frame         S         S         S           R87         Spare tire bracket below frame         S         S         S           R87         Spare tire bracket below frame         S         S         S           R87         Spare tire bracket below frame         S         S	L94	Parking lights deletion	S	S	S
MS1         Cruise control         S         S         S           P47         Front mudflaps         S         S         S           P48         Rear mudflaps         S         S         S           Q11         Longitudinal member reinforcement         S         S         S           R65         Spare tire bracket below frame         S         S         S           R87         Spare tire         S         S         S           R87         Spare tire         S         S         S           R87         Spare tire bracket below frame         S         S         S           R87         Spare tire bracket below frame         S         S         S           R87         Spare tire bracket below frame         S         S         S           R87         Spare tire bracket below frame         S         S         S           R87         Spare tire bracket below frame         S         S         S           R87         Spare tire bracket below frame         S         S         S         S           R87         Spare tire bracket below frame         S         S         S         S         S         S         S         S </td <td>LA2</td> <td>Headlight assistant</td> <td>S</td> <td>S</td> <td>S</td>	LA2	Headlight assistant	S	S	S
P47         Front mudflaps         S         S           P48         Rear mudflaps         S         S           Q11         Longitudinal member reinforcement         S         S           R65         Spare tire bracket below frame         S         S           R87         Spare tire         S         S           R80         All-season tires         S         S           S02         Standard driver seat         S         S           S02         Standard front passenger seat         S         S           S04         Standard front passenger seat         S         S           S22         Armrest for driver's seat         S         S           S25         Armrest for front passenger seat         S         S           S45         Front airbag, driver         S         S           SA6         Front airbag, passenger         S         S           SH1         Thorax-pelvis sidebag, driver         S         S           SH2         Thorax-pelvis sidebag, co-driver         S         S           SH2         Thorax-pelvis sidebag, co-driver         S         S           SH2         Satisfied for the company of the company of the company of the company of the c	LB5	3rd brake light	S	S	S
P48         Rear mudflaps         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$         \$	MS1	Cruise control	S	S	S
Q11Longitudinal member reinforcementSSR65Spare tire bracket below frameSSR87Spare tireSSRMOAll-season tiresSSS02Standard driver seatSSS04Standard front passenger seatSSS22Armrest for driver's seatSSS25Armrest for front passenger seatSSSA5Front airbag, driverSSSA6Front airbag, passengerSSSH1Thorax-pelvis sidebag, driverSSSH2Thorax-pelvis sidebag, co-driverSSSH9Airbag, driver/passenger windowSSSSK2Seat occupancy sensor, driver's seatSSST16Sliding door, passenger sideSSSV93Without factory installed flooringSSSV95Cable duct - side wallSSSV95Cable duct - rear portalSSS	P47	Front mudflaps	S	S	S
R65 Spare tire bracket below frame  R87 Spare tire  R87 Spare tire  R88 Spare tire  R88 Spare tire  R89 Spare tire  R89 Spare tire  R89 Spare tire  R80 All-season tires  Spare tire  Spar	P48	Rear mudflaps	S	S	S
R87         Spare tire         S         S           RMO         All-season tires         S         S           SO2         Standard driver seat         S         S           SO4         Standard front passenger seat         S         S           SO4         Standard front passenger seat         S         S           SO2         Armrest for driver's seat         S         S           SO3         S         S         S           SO4         Front airbag, driver         S         S           SA5         Front airbag, driver         S         S           SA6         Front airbag, passenger         S         S           SA6         Front airbag, passenger         S         S           SH1         Thorax-pelvis sidebag, driver         S         S           SH2         Thorax-pelvis sidebag, co-driver         S         S           SH3         Airbag, driver/passenger window         S         S           SK2         Seat occupancy sensor, driver's seat         S         S           SK2         Seat occupancy sensor, driver's seat         S         S           SK3         S         S         S           SK4	Q11	Longitudinal member reinforcement	S	S	S
RMO All-season tires  SS S S S S S S S S S S S S S S S S S	R65	Spare tire bracket below frame	S	S	S
SO2Standard driver seatSSSO4Standard front passenger seatSSS22Armrest for driver's seatSSS25Armrest for front passenger seatSSSA5Front airbag, driverSSSA6Front airbag, passengerSSSH1Thorax-pelvis sidebag, driverSSSH2Thorax-pelvis sidebag, co-driverSSSH9Airbag, driver/passenger windowSSSK2Seat occupancy sensor, driver's seatSST16Sliding door, passenger sideSSV93Without factory installed flooringSSV94Cable duct - side wallSSV95Cable duct - rear portalSS	R87	Spare tire	S	S	S
504Standard front passenger seatSS522Armrest for driver's seatSS525Armrest for front passenger seatSS525Armrest for front passenger seatSS525SSS526Front airbag, driverSSS526Front airbag, passengerSSS527SSSS527SSSS527SSSS527SSSS527SSSS527SSSS527SSSS527SSSS537SSSS547Cable duct - side wallSSS548Cable duct - rear portalSSS	RM0	All-season tires	S	S	S
S22         Armrest for driver's seat         S         S           S25         Armrest for front passenger seat         S         S           SA5         Front airbag, driver         S         S           SA6         Front airbag, passenger         S         S           SH1         Thorax-pelvis sidebag, driver         S         S           SH2         Thorax-pelvis sidebag, co-driver         S         S           SH9         Airbag, driver/passenger window         S         S           SK2         Seat occupancy sensor, driver's seat         S         S           T16         Sliding door, passenger side         S         S           V93         Without factory installed flooring         S         S           V94         Cable duct - side wall         S         S           V95         Cable duct - rear portal         S         S	S02	Standard driver seat	S	S	S
S25         Armrest for front passenger seat         S         S           SA5         Front airbag, driver         S         S           SA6         Front airbag, passenger         S         S           SA6         Front airbag, passenger         S         S           SH1         Thorax-pelvis sidebag, driver         S         S           SH2         Thorax-pelvis sidebag, co-driver         S         S           SH9         Airbag, driver/passenger window         S         S           SK2         Seat occupancy sensor, driver's seat         S         S           SK2         Seat occupancy sensor, driver's seat         S         S           T16         Sliding door, passenger side         S         S           V93         Without factory installed flooring         S         S           V94         Cable duct - side wall         S         S           V95         Cable duct - rear portal         S         S	S04	Standard front passenger seat	S	S	S
SA5         Front airbag, driver         S         S           SA6         Front airbag, passenger         S         S           SH1         Thorax-pelvis sidebag, driver         S         S           SH2         Thorax-pelvis sidebag, co-driver         S         S           SH9         Airbag, driver/passenger window         S         S           SK2         Seat occupancy sensor, driver's seat         S         S           T16         Sliding door, passenger side         S         S           V93         Without factory installed flooring         S         S           V94         Cable duct - side wall         S         S           V95         Cable duct - rear portal         S         S	S22	Armrest for driver's seat	S	S	S
SA6         Front airbag, passenger         S         S           SH1         Thorax-pelvis sidebag, driver         S         S           SH2         Thorax-pelvis sidebag, co-driver         S         S           SH9         Airbag, driver/passenger window         S         S           SK2         Seat occupancy sensor, driver's seat         S         S           T16         Sliding door, passenger side         S         S           V93         Without factory installed flooring         S         S           V94         Cable duct - side wall         S         S           V95         Cable duct - rear portal         S         S	S25	Armrest for front passenger seat	S	S	S
SH1       Thorax-pelvis sidebag, driver       S       S         SH2       Thorax-pelvis sidebag, co-driver       S       S         SH9       Airbag, driver/passenger window       S       S         SK2       Seat occupancy sensor, driver's seat       S       S         T16       Sliding door, passenger side       S       S         V93       Without factory installed flooring       S       S         V94       Cable duct - side wall       S       S         V95       Cable duct - rear portal       S       S	SA5	Front airbag, driver	S	S	S
SH2         Thorax-pelvis sidebag, co-driver         S         S           SH9         Airbag, driver/passenger window         S         S           SK2         Seat occupancy sensor, driver's seat         S         S           T16         Sliding door, passenger side         S         S           V93         Without factory installed flooring         S         S           V94         Cable duct - side wall         S         S           V95         Cable duct - rear portal         S         S	SA6	Front airbag, passenger	S	S	S
SH9 Airbag, driver/passenger window SS SS SS SK2 Seat occupancy sensor, driver's seat SS SS SS T16 Sliding door, passenger side SS SS SS V93 Without factory installed flooring SS SS SS V94 Cable duct - side wall SS	SH1	Thorax-pelvis sidebag, driver	S	S	S
SK2         Seat occupancy sensor, driver's seat         S         S           T16         Sliding door, passenger side         S         S           V93         Without factory installed flooring         S         S           V94         Cable duct - side wall         S         S           V95         Cable duct - rear portal         S         S	SH2	Thorax-pelvis sidebag, co-driver	S	S	S
T16       Sliding door, passenger side       S       S         V93       Without factory installed flooring       S       S         V94       Cable duct - side wall       S       S         V95       Cable duct - rear portal       S       S	SH9	Airbag, driver/passenger window	S	S	S
V93     Without factory installed flooring     S     S       V94     Cable duct - side wall     S     S       V95     Cable duct - rear portal     S     S	SK2	Seat occupancy sensor, driver's seat	S	S	S
V94         Cable duct - side wall         S         S           V95         Cable duct - rear portal         S         S	T16	Sliding door, passenger side	S	S	S
V95 Cable duct - rear portal S S S	V93	Without factory installed flooring	S	S	S
·	V94	Cable duct - side wall	S	S	S
W54 Rear doors, opening to side wall	V95	Cable duct - rear portal	S	S	S
TVOT Incar adors, opening to side wan	W54	Rear doors, opening to side wall	0	0	S
XB3 GVWR 9,990 lbs. / 4,531 kg S S			S	S	S
X64 Plates/booklets in English (US) S S S	X64	Plates/booklets in English (US)	S	S	S
X99 Manufacturer Mercedes-Benz AG S S S	X99	Manufacturer Mercedes-Benz AG	S	S	S
XC8 VIN visible from outside S S S	XC8	VIN visible from outside	S	S	S
XI2 Change Year G2-I S S	XI2	Change Year G2-I	S	S	S
XY4 Model Year 2024 S S S	XY4	Model Year 2024	S	S	S
Y43 Jack, hydraulic S S S	Y43	Jack, hydraulic	S	S	S
ZU8 USA country version S S S	ZU8	USA country version	S	S	S
ZZ4 Brand content Mercedes-Benz North America S S S	ZZ4	Brand content Mercedes-Benz North America	S	S	S

144" 4D Std

170" 4D Std

170" E 4D Std

		144" 4D Std	170" 4D Std	170" E 4D Std
		M3CA4S	M3CA7S	M3CAES
		907.653	907.655	907.657
A50	Front axle reinforced	\$387	\$387	\$387
AP2	Addtl. bar for driveshaft & exhaust extension	\$77	\$77	-
B01	ESP for increased Center of Gravity above 39.4"	-	\$0	\$0
	must have CB4/CB8/X55; not with RH0/CB7			
BE2	Handbrake lever, folding	\$62	\$62	\$62
	not with B25; X69 choose B25/BE2			
C72	Bumpers front/rear primed	\$300	\$300	\$300
	must have CN2 (part of X67), not with CM0			
CE8	Raised rear body mounts	\$282	\$282	\$282
CM0	Painted metallic front & rear bumper	\$657	\$657	\$657
	must have (CN2/X67) + (JA7/C01) + (JB6/JB7) + (7755/9197/9775)			
CM9	Primed side moldings	\$408	\$408	\$408
D03	High roof	\$3,500	S	S
D13	Mounting rails for roof rack	\$336	\$336	\$336
D22	Fixed sunroof (rear roof section)	\$377	\$377	\$377
	not with H08/HK4/H72/V36/ZK4			
D50	Cargo partition	\$322	\$322	\$322
	not with D51/D93/H08/HK4/T74/V36; must have one of T93/T77			
D51	Cargo partition with 1 window	\$376	\$376	\$376
	not with D50/D93/H08/HK4/T74/V37/D17; must have one of T93/T77		-	•
E1B	Tray for smartphones incl. wireless charging	\$175	\$175	\$175
	must have CO2/E3M + H1I			
E1E	Navigation	\$815	\$815	\$815
	must have CO2/E3M, not with CO3			
E1S	Sirius XM, satellite radio	\$285	\$285	\$285
	must have CO2/E3M/CO3			
E1R	Additional Fuses (40/80/150/100 Ampere)	i	\$57	\$57
	must have X2R/ not with E1Y			
E1Y	Additional Fuses (40/80/80/100 Ampere)	-	\$57	\$57
	must have X2R / not with E1R			
E1X	MBUX multimedia 6-hour runtime	-	\$0	\$0
	must have X2R + (C02+E1E/E1S)/C03/(E3M+E1E/E1S)			
E2A	Access point for BB special signals in cockpit	\$32	\$32	\$32
E2I	Additional battery, co-driver seat base	\$277	\$277	\$277
	must have E36/C06; not with E2M/F09; CHS production only			
E2M	Additional battery, engine compartment	\$277	\$277	\$277
	must have X01+ (E36/C06); not with E2I/X69/F09			
E3M	MBUX Multimedia System with 7" touchscreen	\$531	\$531	\$531
	not with C02/C03; must have JK5+(JB7/JB6/JB8/FR8)			
E36	Cutoff relay for additional battery	\$124	\$124	\$124
	standard with E2I/E2M			
E46	12 V power outlet, driver seat base	\$103	\$103	\$103
E5M	Extension of PSM standard contact	\$65	\$65	\$65
ED5	Parametric special module (PSM)	\$354	\$354	\$354
	not with ED8			
EE3	115 V socket	\$140	\$140	\$140
EP7	Basic electric fitting for rear loudspeakers	\$76	\$76	\$76
ES2	12 V power outlet, rear compartment	\$103	\$103	\$103
ES5	Charging package, dashboard	\$92	\$92	\$92

		144" 4D Std	170" 4D Std	170" E 4D Std
		M3CA4S	M3CA7S	M3CAES
		907.653	907.655	907.657
ET4	Active Distance Assist DISTRONIC	\$294	\$294	\$294
L14	must have CO3	Ş2 <del>34</del>	Ş25 <del>4</del>	Ş254
F1K	Coat hooks in driver cabin	\$15	\$15	\$15
IIK	must have D50/D51	\$13	ŞΙJ	\$10
F49	Electrically heated windshield	\$244	\$244	\$244
143	no restriction	7244	Y244	7244
F61	Interior rear view mirror	\$41	\$41	\$41
. 01	not with D50; must have C02/E3M/C03	Ϋ́T	ŲΨI	Ϋ́т±
F64	Electrically folding exterior mirrors	\$55	\$55	\$55
	no restriction	γoo	φσσ	ΨOO
F84	Digital Rearview Mirror	\$736	\$736	\$736
	must have LA2- Not with F61	γ, σο	ψ/ 30	ψ, σσ
FE9	Additional DIN-slot	\$91	\$91	\$91
FF8	Overhead storage slot, front center	\$117	\$117	\$117
FJ1	Hinged lid for storage compartment	\$105	\$105	\$105
FR8	Rear view camera (head unit display)	\$377	\$377	\$377
	must have CO2/E3M; not with FR3/JB7/JB6/JB8	7	7011	7011
FY1	Security alarm w. interior motion sensor	\$654	\$654	\$654
	must have LC4/C00	,		,
FY7	Optional 3-button keys	\$41	\$41	\$41
FZ9	Keys, two additional masters	\$136	\$136	\$136
H00	Warm/cool air duct to rear compartment	\$66	\$66	\$66
	not with D50/D51/Y2A			
H01	Heat insulation, rear compartment	\$175	\$175	\$175
	must have V21/V25/VA3/VA1/C07/X66			
H04	Heat insulation, front compartment	\$209	\$209	\$209
	if + D50/D51 must have V07	•		
H08	Air conditioning rear, roof-mounted	\$3,216	\$3,216	\$3,216
	must have D93 +V36+M61; not with HK4/C06/X66/C07	-		
H12	Fuel-fired pre-heater/booster (17K BTU)	\$1,249	\$1,249	\$1,249
	not with HZ9			
H13	Rear cabin heater and vents	\$880	\$880	\$880
	must have H12/HZ9			
H15	Heated front passenger seat	\$318	\$318	\$318
	must have H16; not with X68			
H22	Rear window defroster	\$283	\$283	\$283
	must have W61/W78; standard for W61+W70			_
H72	Roof fan, electric	\$448	\$448	\$448
	not with D22/V36			
H88	Rear heater prep	\$453	\$453	\$453
	must have H12/HZ9; not with H13/T19			
H1I	Front-to-rear outlet in instrument panel	\$0	\$0	\$0
	must have FJ1/C01			
HH4	Thermotronic automatic climate control	\$378	\$378	\$378
	must have JF1; if +H13 must have H08/HK4			
HK4	Rear air conditioner, heavyduty	\$4,411	\$4,411	\$4,411
	must have D03+V36+D93; not with H08/ZB6/ZE6/N62/N63		-	
HZ9	Fuel-fired heater booster (18,000 BTU)	\$756	\$756	\$756
	not with H12			
J51	Fuel gauge, optimized for aux. fuel tap	\$80	\$80	\$80
	not with HZ9/H12			
J52	Engine oil level display at cold start	\$0	\$0	\$0

		144" 4D Std	170" 4D Std	170" E 4D Std
		M3CA4S	M3CA7S	M3CAES
		907.653	907.655	907.657
JA7	Blind Spot Assist	\$504	\$504	\$504
	must have F64	•		
JB4	Active Lane Keeping Assist	\$322	\$322	\$322
	standard with CO2/CA2	•		
JB6	Parking Package with 360 degree camera	\$867	\$867	\$867
	must have CO2/CO3/E3M; not with W75/W76/JB7	•		
JB7	Parking Package	\$688	\$688	\$688
	must have C02/C03/E3M; not with W75/W76/JB6			
JB8	360 Degree Camera	\$766	\$766	\$766
	must have CO2/CO3/E3M, not with JB6/JB7			
JF1	Rain sensor	\$118	\$118	\$118
JW0	Backup alarm	\$111	\$111	\$111
JW2	Deactivation lamp monitoring failure	\$30	\$30	\$30
JW8	Attention Assist	\$55	\$55	\$55
K51	Misfueling prevention for Diesel	\$55	\$55	\$55
K52	DEF fluid filler cap - lockable	\$30	\$30	\$30
L13	Fog lamp with cornering light function	\$223	\$223	\$223
L71	Light/motion sensor in rear compartment	\$61	\$61	\$61
	not with V36			
LB9	Illuminated front exits	\$170	\$170	\$170
LC2	LED light strip in load compartment	\$294	\$294	\$294
	not with H08/HK4/V36/C06			
LC4	Comfort overhead control panel	\$105	\$105	\$105
M20	Speed limitation 65 mph	\$67	\$67	\$67
	not with MD3			
M61	Alternator 14 V / 280 A	\$188	\$188	\$188
MD3	Top speed limitation 75 mph	S	\$71	\$71
	not with M20			
N62	Front engine bracket for additional alternator	\$523	\$523	\$523
	not with HK4/N63			
N63	Front engine bracket for auxiliary A/C compressor	\$523	\$523	\$523
	not with HK4/N62			
P93	Omission of D-rings	-\$15	-\$15	-\$15
	not with D93/V43/VK8			
QA2	Trailer cross member 7,500 lbs capacity	\$208	\$208	-
	not with W73/W75/W76/Q24/Q67			
QA9	Half-sided step rear (for trailer hitch)	\$113	\$113	\$113
	must have Q24/QA2; not with W73/W75/W76			
Q24	Trailer hitch, 5,000 lbs	-	-	\$164
	not with W73/W75/W76			
R91	Spare tire deletion	-\$110	-\$110	-\$110
	must have R92; not with R87			
R92	Spare tire carrier deletion	\$0	\$0	\$0
	must have R91; not with R65	·	=	=
R98	Rims painted jet black	\$91	\$91	\$91
	not with RL5/RM2			• ————
RF1	Tire brand Continental	\$0	\$0	\$0
	must have RM1 + RM9			
RF8	Tire brand Michelin	\$0	\$0	\$0
	must have RM9; not with RM1			
RH0	Tire brand Kumho	\$0	\$0	\$0
	must have RM9; not with RM1			

		144" 4D Std	170" 4D Std	170" E 4D Std
		M3CA4S	M3CA7S	M3CAES
		907.653	907.655	907.657
RM1	M+S winter tires	\$190	\$190	\$190
	must have RF1/RD9; not with RF8/RH0/X31	·		
RM2	Rims painted arctic white	\$91	\$91	\$91
	not with R98/RL5		•	ı ·
RM9	Specially requested tires	\$113	\$113	\$113
	must have RF1/RF8/RH0; not with RD9	. · · · · · · · · · · · · · · · · · · ·	•	
S23	Twin front passenger seat	\$448	\$448	\$448
	not with C00/X68/X01	•		
S28	Armrest, driver and passenger door	\$58	\$58	\$58
S62	Seat belts orange, driver and front passenger	\$36	\$36	\$36
	not with S23	•		
SB9	Driver's seat plus	\$267	\$267	\$267
	must have VF7; not with C00/X68/X69		•	
SZ7	Storage net, driver's seat backrest	\$71	\$71	\$71
SZ8	Storage net, passenger seat backrest	\$71	\$71	\$71
T12	Sliding door two stage opening	\$92	\$92	\$92
	not with T55		•	ı ·
T50	Electric closing assist right sliding door	\$376	\$376	\$376
	must have D03; not with T55/T93	. · · · · · · · · · · · · · · · · · · ·	•	
T51	Electric closing assist left sliding door	\$376	\$376	\$376
	must have T19 + D03	. · · · · · · · · · · · · · · · · · · ·	•	
T55	Electric sliding door right	\$930	\$930	\$930
	must have D03 + (FY7+T16); not with T12/T50	. · · · · · · · · · · · · · · · · · · ·	•	
T57	Electric sliding step	\$1,199	\$1,199	\$1,199
	must have ED5; not with T93	. ,	. ,	. ,
T60	Opening limiter electrically operated sliding door	\$134	\$134	\$134
	must have T55	·	•	
T74	Assist handle, B-pillar	\$36	\$36	\$36
	must have D93; not with T77	,	,	, , , ,
T75	Door-mounted assist handles, driver & passenger	\$66	\$66	\$66
T77	Assist handle w/ partition	\$36	\$36	\$36
	must have D50/D51/D64	,	,	, , , ,
T85	Assist handle, left rear door	\$36	\$36	\$36
T86	Assist handles, right rear door	\$36	\$36	\$36
	Sliding door right side deletion	\$0	\$0	\$0
	not with T16/T50/T57/VK8/VC5		7.5	7.5
V07	Cab rear wall liner	\$403	\$403	\$403
	must have (D50/D51)+F1K; standard with H04	¥ 100	7 100	Ţ 100
V21	Luxury interior Trim	\$740	\$740	\$740
	must have VA5/VA7; not with V52/VA1/VA3	φ, .σ	φ7.10	φ
V24	Pallet support in sliding door step	\$108	\$108	\$108
	must have (V43/X66)+(D50/D51); not with VK8/V93/C07	7-55	7200	7200
V25	Half height load compartment trim	\$225	\$225	\$225
5	not with VA1/VA3/VA5/V52/X66	Ψ223	Ÿ220	<b>¥</b> 223
V31	Window pillar trim	\$574	\$574	\$574
	must have V36 + (V21/VA1) + (F02/F03/F07); not with V42	7	7	+
V35	Wheel house covering	\$117	\$117	\$117
	if +V43 must have V25/VA1/VA3; not with V52	γ/	7/	T/
V36	Roof trim	\$982	\$982	\$982
	must have D93; not with D17/D22/H72/L65/L71/LC2/VA3/V42/ZE6/(7			7502
V42	Lashing rails, waist level	\$310	\$310	\$310
	not with V36/ZE6	Ç310	<b>\$310</b>	<b>\$310</b>

		144" 4D Std	170" 4D Std	170" E 4D Std
		M3CA4S	M3CA7S	M3CAES 907.657
		907.653	907.655	
	hu ia week			
V43	Wood floor with 6 D-rings	\$473	\$473	\$473
1/40	not with P93/V93/VL4/VK8/C07; standard with D93/H13/V24/V52/VC		¢20	<b>420</b>
V48	Floor cover behind seat box	\$30	\$30	\$30
	must have D93; not with D50/D51/D56/D62/D64/V43/VK8	6422	64.22	<b>ć</b> 422
V4A	Full paneling, right sliding door	\$123	\$123	\$123
\	not with P93/V93/VL4/VK8/C07; standard with D93/H13/V24/V52/VC		Ċ A A	Ċ A A
V85	Cigarette lighter & ash cup, front	\$44	\$44	\$44
VA1	Side wall paneling waist height PVC	\$356	\$356	\$356
1//2	must have VA5/VA7; not with V52	¢407	¢407	¢407
VA3	Side wall paneling full hardboard	\$497	\$497	\$497
\	not with V36/F02; if T93 must have (D50/D51)	642	642	ć 42
VA5	Full paneling, hinged rear doors	\$43	\$43	\$43
	must have D03+VA7+(W61/W78); not with V25	64.42	64.42	64.42
VA7	Storage compart. w/ net in rear doors	\$142	\$142	\$142
1/64	must have W61/W78; not with V52	Ć4CF	Ć 4 C E	Ć 4 C E
VC4	Cargo lashing rails, head height	\$465	\$465	\$465
VCE	must have V42/C07/X66; not with ZE6	670	670	Ć70
VC5	Door sill - protective edge	\$79	\$79	\$79
\//\O	must have V43/X66; not with T19/T93/VK8/VV2/V93/C07	Ċ44.4	Ċ 4.4.4	¢44.4
VK8	Floor covering, plastic	\$414	\$414	\$414
1/1/2	not with V43/P93/T19/T93/V52/VC5/X66	¢202	¢20C	¢424
VV2	Lashing rails, floor level (plus 4 anchors)	\$302	\$386	\$421
VV4	must have V43; not with V93/VC5/ZE6	\$50	\$50	¢r0
V V 4	Additional Ground Weld Studs no restriction	\$50	\$5U	\$50
\\/16	2nd row, fixed window, driver side	\$162	\$162	\$162
VVIO	if D93 must have F43+W70; if D93 & standard roof CHS production red	•	\$102	Ş10Z
\\/17	2nd row, fixed window, passenger side	\$162	\$162	\$162
VV 17	if D93 must have F43+W70; if D93 & standard roof CHS production rec		\$102	Ş10Z
\ <b>\</b> /33	FMVSS 217 emergency exit	\$424	\$424	\$424
VV 33	must have V31; not with D50/T19/W16	УчZч	УчZч	7424
\\/5/	Rear doors, opening to side wall	\$403	\$403	S
	90 Degree fixation point- Rear Doors	\$90	\$90	\$90
***	must habe W54 / not with V21/V36/VA1/VA7	<b>\$30</b>	<b></b>	<del>-</del> <del>-</del> <del>-</del> <del>-</del> <del>-</del> <del>-</del> <del>-</del> - <del>-</del> <del>-</del> - <del>-</del>
W61	Windows in rear doors	\$105	\$105	\$105
****	must have VA7/ if D51 must have F61; not with W78/(W70+-(H22/F02		<b>\$103</b>	Ţ105
W70	Black tinting (90%) for rear windows	\$155	\$155	\$155
***	not with W94; must have W16/W17/F02/((W61/W78)+H22); standard			<b>Ų133</b>
W73	Bumper step, rear, grey	\$209	\$209	\$209
VV / 3	not with Q24/W75/W76	<b>720</b> 3	7203	<b>720</b> 3
W75	Step, wide, at rear end	\$345	\$345	\$345
****	not with JB6/JB7/Q24/QA9; must have R91+R92	<b>γ</b> υ-υ	<b>₽</b> 3∓3	<b>73</b> -73
W76	Bumper step, rear, spring-loaded	_	\$673	\$673
****	must have R91+R92; not with JB6/JB7/X55/Q24	<u>!</u>	φ0/3	<b>7073</b>
W78	Heated rear window(s) w/ washers/wipers	\$376	\$376	\$376
	Must have H22+VA7 / if D51 must have F61; not with W61	+3,0	<del>+</del> 3,5	<del>+</del> 3,0
X90	Deletion of Sprinter badge, left rear door	\$0	\$0	\$0
X93	Deletion of model badge, right rear door	\$0 \$0	\$0	\$0 \$0
X2R	Conversion to RV requirement	- -	\$0	\$0 \$0
\_I\	must have B01+D93+E1X		γo	γŪ
XM4	Acoustic package	\$97	\$97	\$97
/\IVI+	ποσαστιο ρασκαξο	731	<b>γ</b> 31	١٤٦

		144" 4D Std	170" 4D Std	170" E 4D Std
		M3CA4S	M3CA7S	M3CAES
		907.653	907.655	907.657
Y10	First-aid kit	\$30	\$30	\$30
Y26	Wheel chocks	\$43	\$43	\$43
Y45	Emergency flashlight	\$30	\$30	\$30
Y68	Paint preservative	\$209	\$238	\$252
Y69	Surface protection for stock vehicles	\$352	\$352	\$352
YK3	Cargo straps, D-rings	\$91	\$91	\$91
YK4	Cargo straps, lashing rails	\$116	\$116	\$116
	must have V42/VV2; not with ZE6			
ZE6	Shelving prep	\$717	\$717	\$717
	not with T93/H13/T19/V36/V42/VC4/VK8/VV2/YK4			

		144" 4D Std	170" 4D Std	170" E 4D Std
		M3CA4S	M3CA7S	M3CAES
		907.653	907.655	907.657
C00	Comfort Package	\$307	\$307	\$307
LC4	Comfort overhead control panel	Х	X	Х
SE4	Lumbar support, co-driver's seat	X	X	X
SE5	Lumbar support, driver's seat	Х	X	Х
SK0	Comfort head restraint, driver	Х	X	Х
SK1	Comfort head restraint, co-driver	Х	Х	Х
must	have COS OR X68; CA/CC only: not with S23			

COS	Comfort Package (Seat addition)	\$426	\$426	\$426	
SB1	Comfort driver's seat	Х	Х	X	
SB2	Comfort passenger seat	Х	Х	Х	
must	must have COO				

X68	Comfort Plus Package	\$1,898	\$1,898	\$1,898	
H15	Heated front passenger seat	X	X	Х	
SF1	Driver's seat electrically adjustable	Х	Х	Х	
SF2	Co-driver's seat electrically adjustable	Х	X	Х	
must	nust have COO and VF4 OR VF6, CA/CC only: not with S23				

C01	Driver Convenience Package	\$449	\$449	\$449
E46	12 V power outlet, driver seat base	Х	Х	Х
F64	Electrically folding exterior mirrors	Х	Х	Х
FJ1	Hinged lid for storage compartment	Х	Х	Х
FJ5	Hinged Lid for Storage Compartments left and right	Х	Х	X
FZ9	Keys, two additional masters	Х	Х	X
JW8	Attention Assist	Х	Х	Х

C02	Premium Package	\$805	\$805	\$805
E3M	MBUX Multimedia System with 7" touchscreen	Х	Х	X
FM3	Wet Wiper System	Х	Х	X
JB4	Active Lane Keeping Assist	Х	Х	Х
must have JF1 + XM4; must choose FR8/JB7/JB6				

CA2	C02 in combination with C03	\$547	\$547	\$547	
CL3	Leather steering wheel	X	X	X	
FM3	Wet Wiper System	X	Х	X	
JB4	Active Lane Keeping Assist	Х	Х	Х	
must	must have CO3 + JF1				

144" 4D Std	170" 4D Std	170" E 4D Std
M3CA4S	M3CA7S	M3CAES
907.653	907.655	907.657

C03	Premium Plus Package	\$2,008	\$2,008	\$2,008
E1B	Tray for smartphones incl. wireless charging	Х	Х	X
	Navigation	Х	Х	Х
EY2	Intelligent navigation	Х	Х	Х
E4M	MBUX Multimedia System with 10.25" touchscreen	Х	Х	Х
EX9	Free map data updates for 3 years	Х	Х	Х
H1I	Front-to-rear outlet in instrument panel	Х	Х	Х
JA9	Traffic Sign Assist	Х	Х	Х
XM4	Acoustic package	Х	Х	Х
must	have (CA2+(JB7/JB6/JB8)); not with FR8 and CO2			

X67	Chrome Grille Package	\$325	\$325	\$325	
CN2	Radiator grille frame in vehicle color	X	Х	X	
FK3	Chrome plated radiator grille (MB only)	Х	Х	X	
no re	no restrictions				

X13	Exterior Lighting Package	\$1,801	\$1,801	\$1,801	
L13	Fog lamp with cornering light function	Х	Х	Х	
L22	Partial LED tail lights	Х	Х	Х	
LA1	High beam assist	Х	Х	Х	
LG7	LED high performance headlamps	Х	Х	Х	
no re	no restrictions				

C07	Cargo Protection Package	\$1,250	\$1,250	\$1,250	
V25	Half height load compartment trim	X	Х	X	
V42	Lashing rails, waist level	Х	Х	X	
VC4	Cargo lashing rails, head height	Х	Х	Х	
VK8	Floor covering, plastic	X	Х	X	
YK3	Cargo straps, D-rings	Х	Х	Х	
not v	not with X66				

CR1	Rear Door Convenience Package	\$508	\$508	\$508
T85	Assist handle, left rear door	X	X	X
T86	Assist handles, right rear door	X	X	X
W54	Rear doors, opening to side wall	X	Х	Х
W5F	90 Degree fixation point- Rear Doors	X	Х	X

UL1	Upfit Prep and Load Restraining Package	\$1,768	\$1,768	\$1,768
V43	Wood floor with 6 D-rings	Х	Х	Х
V42	Lashing rails, waist level	Х	Х	Х
VC4	Cargo lashing rails, head height	Х	Х	Х
VA3	Side wall paneling full hardboard	Х	Х	Х
VV2	Lashing rails, floor level (plus 4 anchors)	Х	Х	X

144" 4D Std	170" 4D Std	170" E 4D Std
M3CA4S	M3CA7S	M3CAES
907.653	907.655	907.657

X66	Heavy-Duty-Cargo Protection Package	\$1,952	\$1,952	\$1,952	
V43	Wood floor with 6 D-rings	Χ	Х	Х	
V42	Lashing rails, waist level	Х	Х	Х	
VA3	Side wall paneling full hardboard	Х	Х	Х	
VC4	Cargo lashing rails, head height	Х	Х	Х	
VV2	Lashing rails, floor level (plus 4 anchors)	Х	Х	Х	
YK3	Cargo straps, D-rings	Х	Х	Х	
YK4	Cargo straps, lashing rails	Х	Х	Х	
not v	not with CO7				

X69	Swivel Seat Package	\$595	\$595	\$595
SR8	Swivel base for driver's seat	X	X	X
SR9	Swivel base for front passenger seat	Х	Х	X
S87	Driver's seat frame, low	Х	Х	Х
S88	Passenger seat frame, low	Х	Х	Х
must	must have (C00+C0S) OR (C00+X68), choose BE2 or B25 (1500/2500 only)			

144" 4D High	170" 4D High	170" E 4D High
М3СА4Н	М3СА7Н	M3CAEH
907.653	907.655	907.657

Engin	е			
_	High Output Engine/9-Speed Trans.	S	S	S
	AGM battery 12V 92 AH 850 A	S	S	S
G43	Automatic transmission, 9G-tronic	S	S	S
MH8	SULEV emissions	S	S	S
M5N	2.0L 4-cylinder diesel engine (208hp output)	S	S	S
	Alternator 14 V / 250 A	S	S	S
M71	Approval Bio-Diesel B20	S	S	S
Tires -	choose while ordering	1		
X34	Dual Rear Wheel	<i>\$0</i>	\$0	\$0
RH7	Tires LT 215/85 R16- DRW	S	S	S
RS6	5.5 J x 16 steel wheels	S	S	S
RD9	Unspecified tire brand	S	S	S
X31	Super Single Tire	\$431	\$431	\$431
R9A	285/65 R 16 C super single tires	0	0	0
RS5	Steel wheels: 8.5Jx16 Rr; 6.5Jx16 Fr	0	0	0
RD9	Unspecified tire brand	0	0	0
RY2	Tire pressure monitoring sensors	0	0	0
Equip	ment			
AR2	Axle ratio 3.923	S	S	S
BA3	Active Brake Assist	S	S	S
BH1	Hold Function	S	S	S
C6L	Multifunction steering wheel	S	S	S
CB8	Stabilization Level II	S	S	S
CL1	Adjustable steering wheel (angle)	S	S	S
D03	High roof	0	S	S
D93	Omission bulkhead	S	S	S
E07	Hill Start Assist	S	S	S
E10	Standard radio	S	S	S
E1U	USB-C socket, 5 V	S	S	S
E30	Starter battery disconnect	S	S	S
E3J	Pre-installation for switch panel	S	S	S
E40	Trailer hitch prep. wiring	S	S	S
ED8	Preinstallation PSM	S	S	S
EE5	Ultracapacitor discharge module	S	S	S
EK1	Body Builder Connector	S	S	S
	Jump start terminal	S	S	S
_	Pre-installation for Mercedes me Remote Services	S	S	S
EY5	Emergency Call System	S	S	S
EY6	Breakdown management	S	S	S
FF5	Shelf above windshield	S	S	S
F68	Heated & electrically adjustable exterior mirrors	S	S	S
FG8	Cupholder front	S	S	S
FI1	Remote key (315 mhz) w/central locking	S	S	S
FJ4	Storage compartment underneath cockpit	S	S	S
FR3	Rear view camera (rear-view mirror display)	S	S	S
H16	Heated driver's seat	S	S	S
H21	Windshield with filter band	S	S	S
HH2	Heater, auxiliary electric hot air	S	S	S
HH9	Air Condition, Front	S	S	S
IH7	Headunit	S	S	S
J11	Speedometer, miles and km/h	S	S	S
J55	Seat belt warning for co-driver seat	S	S	S
J58	Seat belt reminder driver	S	S	S
J65	Outside temperature gauge	S	S	S

		144" 4D High 170" 4D High		170" E 4D High
		М3СА4Н	М3СА7Н	МЗСАЕН
		907.653	907.655	907.657
JA8	Crosswind Assist	S	S	S
JH3	Communication module (LTE) for dig. services	S	S	S
JI9	Service interval 20.000 miles	S	S	S
JK5	Instrument cluster with color display	S	S	S
	Black diesel filler cap	S	S	S
K60	Exhaust straight to rear	S	S	S
KB7	24.5 gallon fuel tank	S	S	S
KL1	Aux fuel sending unit w/ fuel tap	S	S	S
M15	Fuel/water seprarator & lubrication package	S	S	S
MD3	Top speed limitation 75 mph	S	0	0
KP7	4rd generation SCR emission control system	S	S	S
L65	Interior lights, cargo compartment	S	S	S
L94	Parking lights deletion	S	S	S
LA2	Headlight assistant	S	S	S
LB5	3rd brake light	S	S	S
MS1	Cruise control	S	S	S
P47	Front mudflaps	S	S	S
P48	Rear mudflaps	S	S	S
Q11	Longitudinal member reinforcement	S	S	S
R65	Spare tire bracket below frame	S	S	S
R87	Spare tire	S	S	S
RM0	All-season tires	S	S	S
S02	Standard driver seat	S	S	S
S04	Standard front passenger seat	S	S	S
S22	Armrest for driver's seat	S	S	S
S25	Armrest for front passenger seat	S	S	S
SA5	Front airbag, driver	S	S	S
SA6	Front airbag, passenger	S	S	S
SH1	Thorax-pelvis sidebag, driver	S	S	S
SH2	Thorax-pelvis sidebag, co-driver	S	S	S
SH9	Airbag, driver/passenger window	S	S	S
SK2	Seat occupancy sensor, driver's seat	S	S	S
T16	Sliding door, passenger side	S	S	S
V93	Without factory installed flooring	S	S	S
	Cable duct - side wall	S	S	S
V95	Cable duct - rear portal	S	S	S
W54	Rear doors, opening to side wall	0	0	S
XB3	GVWR 9,990 lbs. / 4,531 kg	S	S	S
X64	Plates/booklets in English (US)	S	S	S
X99	Manufacturer Mercedes-Benz AG	S	S	S
XC8	VIN visible from outside	S	S	S
XI2	Change Year G2-I	S	S	S
XY4	Model Year 2024	S	S	S
Y43	Jack, hydraulic	S	S	S
ZU8	USA country version	S	S	S
ZZ4	Brand content Mercedes-Benz North America	S	S	S
<b>44</b>	Diana Content Merceaes-Denz North America	3	3	3

		144" 4D High	170" 4D High	170" Ext.6C
		М3СА4Н	М3СА7Н	МЗСАЕН
		907.653	907.655	907.657
A50	Front axle reinforced	\$387	\$387	\$387
AP2	Addtl. bar for driveshaft & exhaust extension	\$77	\$77	-
B01	ESP for increased Center of Gravity above 39.4"	-	\$0	\$0
	must have CB4/CB8/X55; not with RH0/CB7			
BE2	Handbrake lever, folding	\$62	\$62	\$62
	not with B25; X69 choose B25/BE2			
C72	Bumpers front/rear primed	\$300	\$300	\$300
	must have CN2 (part of X67), not with CM0			
CB4	Stabilization Level III	\$209	\$209	\$209
	not with CB1/CB7/CB8/X55			
CE8	Raised rear body mounts	\$282	\$282	\$282
CM0	Painted metallic front & rear bumper	\$657	\$657	\$657
	must have (CN2/X67) + (JA7/C01) + (JB6/JB7) + (7755/9197/9775)			
CM9	Primed side moldings	\$408	\$408	\$408
D03	High roof	\$3,500	S	S
D13	Mounting rails for roof rack	\$336	\$336	\$336
D22	Fixed sunroof (rear roof section)	\$377	\$377	\$377
	not with H08/HK4/H72/V36/ZK4			
D50	Cargo partition	\$322	\$322	\$322
	not with D51/D93/H08/HK4/T74/V36; must have one of T93/T77			
D51	Cargo partition with 1 window	\$376	\$376	\$376
	not with D50/D93/H08/HK4/T74/V37/D17; must have one of T93/T77			
E1B	Tray for smartphones incl. wireless charging	\$175	\$175	\$175
	must have CO2/E3M + H1I			
E1E	Navigation	\$815	\$815	\$815
	must have CO2/E3M, not with CO3			
E1S	Sirius XM, satellite radio	\$285	\$285	\$285
	must have CO2/E3M/CO3			
E1X	MBUX multimedia 6-hour runtime	-	\$0	\$0
	must have X2R + (C02+E1E/E1S)/C03/(E3M+E1E/E1S)			
E1R	Additional Fuses (40/80/150/100 Ampere)	-	\$57	\$57
	must have X2R/ not with E1Y			
E1Y	Additional Fuses (40/80/80/100 Ampere)	·	\$57	\$57
	must have X2R / not with E1R			
E2A	Access point for BB special signals in cockpit	\$32	\$32	\$32
E2I	Additional battery, co-driver seat base	\$277	\$277	\$277
	must have E36/C06; not with E2M/F09; CHS production only			
E2M	Additional battery, engine compartment	\$277	\$277	\$277
	must have X01+ (E36/C06); not with E2I/X69/F09			
E3M	MBUX Multimedia System with 7" touchscreen	\$531	\$531	\$531
	not with CO2/CO3; must have JK5+(JB7/JB6/JB8/FR8)			
E36	Cutoff relay for additional battery	\$124	\$124	\$124
	standard with E2I/E2M			
E46	12 V power outlet, driver seat base	\$103	\$103	\$103
E5M	Extension of PSM standard contact	\$65	\$65	\$65
ED5	Parametric special module (PSM)	\$354	\$354	\$354
	not with ED8			
EE3	115 V socket	\$140	\$140	\$140
EP7	Basic electric fitting for rear loudspeakers	\$76	\$76	\$76
ES2	12 V power outlet, rear compartment	\$103	\$103	\$103
ES5	Charging package, dashboard	\$92	\$92	\$92

		144" 4D High	170" 4D High	170" Ext.6C
		М3СА4Н	М3СА7Н	МЗСАЕН
		907.653	907.655	907.657
ET4	Active Distance Assist DISTRONIC	\$294	\$294	\$294
	must have CO3	Ψ23.	<b>423</b> .	Ψ <b>2</b> 3.
F1K	Coat hooks in driver cabin	\$15	\$15	\$15
	must have D50/D51	<b>¥</b> 25	<b>Ÿ</b> 23	Ψ10
F49	Electrically heated windshield	\$244	\$244	\$244
5	no restriction	72.11	Ÿ2.11	Ψ2.11
F61	Interior rear view mirror	\$41	\$41	\$41
	not with D50; must have C02/E3M/C03	Ų 1 <u>1</u>	Ψ1 <u>1</u>	Ψ1±
F64	Electrically folding exterior mirrors	\$55	\$55	\$55
	no restriction	400	ψSS	γοσ
F84	Digital Rearview Mirror	\$736	\$736	\$736
107	must have LA2- Not with F61	<i>\$130</i>	<i>\$130</i>	Ţ/30
FE9	Additional DIN-slot	\$91	\$91	\$91
FF8	Overhead storage slot, front center	\$117	\$117	\$117
FJ1	Hinged lid for storage compartment	\$105	\$105	\$105
FR8	Rear view camera (head unit display)	\$377	\$377	\$377
1110	must have CO2/E3M; not with FR3/JB7/JB6/JB8	<b>3311</b>	7511	7377
FY1	Security alarm w. interior motion sensor	\$654	\$654	\$654
	must have LC4/C00	<del>7</del> 054	<del>7</del> 054	7054
FY7	Optional 3-button keys	\$41	\$41	\$41
FZ9	Keys, two additional masters	\$136	\$136	\$136
H00	Warm/cool air duct to rear compartment	\$66	\$66	\$66
1100	not with D50/D51/Y2A	300	<b>300</b>	<b>300</b>
H01	Heat insulation, rear compartment	\$175	\$175	\$175
1101	must have V21/V25/VA3/VA1/C07/X66	\$175	\$175	\$175
H04	Heat insulation, front compartment	\$209	\$209	\$209
1104	if + D50/D51 must have V07	\$209	<b>3209</b>	\$209
H08	Air conditioning rear, roof-mounted	\$3,216	\$3,216	\$3,216
1106	must have D93 +V36+M61; not with HK4/C06/X66/C07	\$5,210	\$5,210	\$3,210
H12	Fuel-fired pre-heater/booster (17K BTU)	\$1,249	\$1,249	\$1,249
1112	not with HZ9	Ş1,24 <i>3</i>	\$1,249	Ş1,24 <i>9</i>
H13	Rear cabin heater and vents	\$880	\$880	\$880
1113	must have H12/HZ9	3000	300U	300U
H15	Heated front passenger seat	\$318	\$318	\$318
1113	must have H16; not with X68	3310	3310	2210
H22	Rear window defroster	\$283	\$283	\$283
1122		3203	<b>3203</b>	<i>\$</i> 203
H72	must have W61/W78; standard for W61+W70 Roof fan, electric	\$448	\$448	\$448
п/2		<del>344</del> 6	Ş <del>44</del> 6	\$ <del>44</del> 6
цоо	not with D22/V36	¢452	Ć4F2	Ć4F2
H88	Rear heater prep	\$453	\$453	\$453
1141	must have H12/HZ9; not with H13/T19	ćo	ćo	ćo
H1I	Front-to-rear outlet in instrument panel	\$0	\$0	\$0
11114	must have FJ1/C01	¢270	¢270	ć270
HH4	Thermotronic automatic climate control	\$378	\$378	\$378
LIK 4	must have JF1; if +H13 must have H08/HK4	64.444	¢4.444	¢4.444
HK4	Rear air conditioner, heavyduty	\$4,411	\$4,411	\$4,411
1170	must have D03+V36+D93; not with H08/ZB6/ZE6/N62/N63	6756	6756	Ć756
HZ9	Fuel-fired heater booster (18,000 BTU)	\$756	\$756	\$756
15.4	not with H12	400	do:	ģc.
J51	Fuel gauge, optimized for aux. fuel tap	\$80	\$80	\$80
	not with HZ9/H12			

		144" 4D High	170" 4D High	170" Ext.6C
		М3СА4Н	М3СА7Н	МЗСАЕН
		907.653	907.655	907.657
J52	Engine oil level display at cold start	\$0	\$0	\$0
JA7	Blind Spot Assist	\$504	\$504	\$504
	must have F64	· ·		·
JB4	Active Lane Keeping Assist	\$322	\$322	\$322
	standard with CO2/CA2	· ·		·
JB6	Parking Package with 360 degree camera	\$867	\$867	\$867
	must have CO2/CO3/E3M; not with W75/W76/JB7		·	·
JB7	Parking Package	\$688	\$688	\$688
	must have CO2/CO3/E3M; not with W75/W76/JB6		·	·
JB8	360 Degree Camera	\$766	\$766	\$766
	must have CO2/CO3/E3M, not with JB6/JB7		·	·
JF1	Rain sensor	\$118	\$118	\$118
JW0	Backup alarm	\$111	\$111	\$111
JW2	Deactivation lamp monitoring failure	\$30	\$30	\$30
JW8	Attention Assist	\$55	\$55	\$55
	Misfueling prevention for Diesel	\$55	\$55	\$55
	DEF fluid filler cap - lockable	\$30	\$30	\$30
	Fog lamp with cornering light function	\$223	\$223	\$223
L71	Light/motion sensor in rear compartment	\$61	\$61	\$61
	not with V36	701	ΨOI	<b>701</b>
LB9	Illuminated front exits	\$170	\$170	\$170
	LED light strip in load compartment	\$294	\$294	\$294
	not with H08/HK4/V36/C06	7254	<b>723</b> 4	<b>Ψ</b> 234
LC4	Comfort overhead control panel	\$105	\$105	\$105
	Speed limitation 65 mph	\$67	\$67	\$67
11120	not with MD3	707	<b>307</b>	<b>307</b>
M61	Alternator 14 V / 280 A	\$188	\$188	\$188
	Top speed limitation 75 mph	7100	\$71	\$71
IVIDS	not with M20		<b>Υ</b> /1	<b>Ψ/1</b>
N62	Front engine bracket for additional alternator	\$523	\$523	\$523
1102	not with HK4/N63	7323	<del>-</del>	<b></b>
N63	Front engine bracket for auxiliary A/C compressor	\$523	\$523	\$523
1103	not with HK4/N62	7323	<del>-</del>	<b></b>
P93	Omission of D-rings	-\$15	-\$15	-\$15
. 55	not with D93/V43/VK8	713	<b>71</b> 3	715
ΩΔ2	Trailer cross member 7,500 lbs capacity	\$208	\$208	-
۵,۱2	not with W73/W75/W76/Q24/Q67	7200	<b>Ş200</b>	
ΩΔ9	Half-sided step rear (for trailer hitch)	\$111	\$111	\$111
QΛJ	must have Q24/QA2; not with W73/W75/W76	γIII	γιιι	γIII
Q24	Trailer hitch, 5,000 lbs	-		\$164
QZ4		_	_	2104
R91	not with W73/W75/W76 Spare tire deletion	-\$110	-\$110	-\$110
	must have R92; not with R87	-3110	7110	7110
R92	Spare tire carrier deletion	\$0	\$0	\$0
	must have R91; not with R65	٥٦	γU	γŪ
R98	Rims painted jet black	\$91	\$91	\$91
.1.50	not with RL5/RM2	731	791	<b>1</b> 2Σ
RF1	Tire brand Continental	\$0	\$0	\$0
111 1	must have RM1 + RM9	Ų	γU	γU
RF8	Tire brand Michelin	\$0	\$0	\$0
IVLQ	must have RM9; not with RM1	ŞU	ŞÜ	Ų

		144" 4D High	170" 4D High	170" Ext.6C
		М3СА4Н	М3СА7Н	МЗСАЕН
		907.653	907.655	907.657
RH0	Tire brand Kumho	\$0	\$0	\$0
	must have RM9; not with RM1	7.0	7.5	7-5
RM1	M+S winter tires	\$190	\$190	\$190
	must have RF1/RD9; not with RF8/RH0/X31	,	,	,
RM2	Rims painted arctic white	\$91	\$91	\$91
	not with R98/RL5		, -	, -
RM9	Specially requested tires	\$113	\$113	\$113
	must have RF1/RF8/RH0; not with RD9	·	·	
S23	Twin front passenger seat	\$448	\$448	\$448
	not with C00/X68/X01		· · · · · · · · · · · · · · · · · · ·	•
S28	Armrest, driver and passenger door	\$58	\$58	\$58
S62	Seat belts orange, driver and front passenger	\$36	\$36	\$36
	not with S23		·	·
SB9	Driver's seat plus	\$267	\$267	\$267
	must have VF7; not with C00/X68/X69	· · · · · · · · · · · · · · · · · · ·		
SZ7	Storage net, driver's seat backrest	\$71	\$71	\$71
	Storage net, passenger seat backrest	\$71	\$71	\$71
T12	Sliding door two stage opening	\$92	\$92	\$92
	not with T55			
T50	Electric closing assist right sliding door	\$376	\$376	\$376
	must have D03; not with T55/T93			
T55	Electric sliding door right	\$930	\$930	\$930
	must have D03 + (FY7+T16); not with T12/T50			
T57	Electric sliding step	\$1,199	\$1,199	\$1,199
	must have ED5; not with T93	•		
T60	Opening limiter electrically operated sliding door	\$134	\$134	\$134
	must have T55			
T74	Assist handle, B-pillar	\$36	\$36	\$36
	must have D93; not with T77			
T75	Door-mounted assist handles, driver & passenger	\$66	\$66	\$66
T77	Assist handle w/ partition	\$36	\$36	\$36
	must have D50/D51/D64			
T85	Assist handle, left rear door	\$36	\$36	\$36
T86	Assist handles, right rear door	\$36	\$36	\$36
T93	Sliding door right side deletion	\$0	\$0	\$0
	not with T16/T50/T57/VK8/VC5			
V07	Cab rear wall liner	\$403	\$403	\$403
	must have (D50/D51)+F1K; standard with H04			
V21	Luxury interior Trim	\$740	\$740	\$740
	must have VA5/VA7; not with V52/VA1/VA3			
V24	Pallet support in sliding door step	\$108	\$108	\$108
	must have (V43/X66)+(D50/D51); not with VK8/V93/C07			
V25	Half height load compartment trim	\$225	\$225	\$225
	not with VA1/VA3/VA5/V52/X66			
V31	Window pillar trim	\$574	\$574	\$574
	must have V36 + (V21/VA1) + (F02/F03/F07); not with V42			
V35	Wheel house covering	\$117	\$117	\$117
	if +V43 must have V25/VA1/VA3; not with V52			
V36	Roof trim	\$982	\$982	\$982
	must have D93; not with D17/D22/H72/L65/L71/LC2/VA3/V42/ZE6/(1	93+-D03)/X66/0	C06/C07	
V42	Lashing rails, waist level	\$310	\$310	\$310
	not with V36/ZE6			

		144" 4D High	170" 4D High	170" Ext.6C
		М3СА4Н	М3СА7Н	МЗСАЕН
		907.653	907.655	907.657
V43	Wood floor with 6 D-rings	\$473	\$473	\$473
	not with P93/V93/VL4/VK8/C07; standard with D93/H13/V24/V52/VC	5/VV2/ZE6		
V48	Floor cover behind seat box	\$30	\$30	\$30
	must have D93; not with D50/D51/D56/D62/D64/V43/VK8			
V4A	Full paneling, right sliding door	\$123	\$123	\$123
	not with P93/V93/VL4/VK8/C07; standard with D93/H13/V24/V52/VC	5/VV2/ZE6		
V85	Cigarette lighter & ash cup, front	\$44	\$44	\$44
VA1	Side wall paneling waist height PVC	\$356	\$356	\$356
	must have VA5/VA7; not with V52			
VA3	Side wall paneling full hardboard	\$497	\$497	\$497
	not with V36/F02; if T93 must have (D50/D51)		-	
VA5	Full paneling, hinged rear doors	\$43	\$43	\$43
	must have D03+VA7+(W61/W78); not with V25		·	·
VA7	Storage compart. w/ net in rear doors	\$142	\$142	\$142
	must have W61/W78; not with V52		·	
VC4	Cargo lashing rails, head height	\$465	\$465	\$465
	must have V42/C07/X66; not with ZE6			
VC5	Door sill - protective edge	\$79	\$79	\$79
	must have V43/X66; not with T19/T93/VK8/VV2/V93/C07	7.0	7.0	4.0
VK8	Floor covering, plastic	\$414	\$414	\$414
	not with V43/P93/T19/T93/V52/VC5/X66	Ψ.=.	Ψ.2.	Ψ
VV2	Lashing rails, floor level (plus 4 anchors)	\$302	\$386	\$421
	must have V43; not with V93/VC5/ZE6	<b>700</b> 2	γοσο	Ψ
VV4	Additional Ground Weld Studs	\$50	\$50	\$50
	no restriction	φσσ	φσσ	γου
W16	2nd row, fixed window, driver side	\$162	\$162	\$162
	if D93 must have F43+W70; if D93 & standard roof CHS production rec		Ų10 <u>2</u>	<b>V102</b>
	2nd row, fixed window, passenger side	\$162	\$162	\$162
	if D93 must have F43+W70; if D93 & standard roof CHS production red	•	Ų10 <u>2</u>	<b>V102</b>
	FMVSS 217 emergency exit	\$424	\$424	\$424
****	must have V31; not with D50/T19/W16	<b>У</b> -т2-т	<b>ү</b> -г	<b>γ</b> π2π
W54	Rear doors, opening to side wall	\$403	\$403	S
	90 Degree fixation point- Rear Doors	\$90	\$90	\$90
VVJI	must habe W54 / not with V21/V36/VA1/VA7	750	<b>730</b>	<b>7</b> 50
W61	Windows in rear doors	\$105	\$105	\$105
*****	must have VA7/ if D51 must have F61; not with W78/(W70+-(H22/F02		7103	7±03
\/\/7∩	Black tinting (90%) for rear windows	)) \$155	\$155	\$155
** 7 0	not with W94; must have W16/W17/F02/((W61/W78)+H22); standard		·	7133
W/73	Bumper step, rear, grey	\$209	\$209	\$209
**/3	not with Q24/W75/W76	7203	7203	72U3
\\\/75	Step, wide, at rear end	\$345	\$345	\$345
**/5	not with JB6/JB7/Q24/QA9; must have R91+R92	7545	7545	- C+C
\ <i>\\</i> /76	Bumper step, rear, spring-loaded	_	\$673	\$673
**/0	must have R91+R92; not with JB6/JB7/X55/Q24		<del>7</del> 0/3	<del>7</del> 0/3
۱۸/7Ω	Heated rear window(s) w/ washers/wipers	\$376	\$376	\$376
VV / O	Must have H22+VA7 / if D51 must have F61; not with W61	<i>337</i> 0	<i>3370</i>	<b>γ3/0</b>
X90	Deletion of Sprinter badge, left rear door	\$0	\$0	\$0
X93	Deletion of Sprinter badge, right rear door  Deletion of model badge, right rear door	\$0 \$0	\$0 \$0	\$0 \$0
X2R		\$U -	\$0 \$0	\$0 \$0
ΛZΚ	Conversion to RV requirement	-	ŞU	ŞU
V1.11	must have B01+D93+E1X	¢07	¢07	¢07
AIVI4	Acoustic package	\$97	\$97	\$97
V1.0	standard with CO2/CO3	ćao	620	620
Y10	First-aid kit	\$30	\$30	\$30

		144" 4D High	170" 4D High	170" Ext.6C
		М3СА4Н	М3СА7Н	МЗСАЕН
		907.653	907.655	907.657
Y26	Wheel chocks	\$43	\$43	\$43
Y45	Emergency flashlight	\$30	\$30	\$30
Y68	Paint preservative	\$209	\$238	\$252
Y69	Surface protection for stock vehicles	\$352	\$352	\$352
YK3	Cargo straps, D-rings	\$91	\$91	\$91
YK4	Cargo straps, lashing rails	\$116	\$116	\$116
	must have V42/VV2; not with ZE6			
ZE6	Shelving prep	\$717	\$717	\$717
	not with T93/H13/T19/V36/V42/VC4/VK8/VV2/YK4			

		144" 4D High	170" 4D High	170" E 4D High
		М3СА4Н	М3СА7Н	МЗСАЕН
		907.653	907.655	907.657
C00	Comfort Package	\$307	\$307	\$307
LC4	Comfort overhead control panel	Х	Х	X
SE4	Lumbar support, co-driver's seat	Х	Х	X
SE5	Lumbar support, driver's seat	Х	Х	X
SK0	Comfort head restraint, driver	Х	Х	X
SK1	Comfort head restraint, co-driver	Х	Х	X
must	have COS OR X68; CA/CC only: not with S23			

COS	Comfort Package (Seat addition)	\$426	\$426	\$426
SB1	Comfort driver's seat	Х	Х	Х
SB2	Comfort passenger seat	Х	X	Х
must	nust have COO			

X68	Comfort Plus Package	\$1,898	\$1,898	\$1,898
H15	Heated front passenger seat	X	X	X
SF1	Driver's seat electrically adjustable	Х	Х	Х
SF2	Co-driver's seat electrically adjustable	Х	Х	Х
must	have COO and VF4 OR VF6, CA/CC only: not with S23	_	_	_

C01	Driver Convenience Package	\$449	\$449	\$449
E46	12 V power outlet, driver seat base	X	X	X
F64	64 Electrically folding exterior mirrors		Х	Х
FJ1	Hinged lid for storage compartment		Х	X
FJ5	J5 Hinged Lid for Storage Compartments left and right		Х	X
FZ9	Keys, two additional masters	X	Х	X
JW8	Attention Assist	X	Х	X

C02	Premium Package	\$805	\$805	\$805
E3M	MBUX Multimedia System with 7" touchscreen	X	X	Х
FM3	Wet Wiper System	Х	Х	Х
JB4	Active Lane Keeping Assist	X	Х	Х
must	must have JF1 + XM4; must choose FR8/JB7/JB6			

CA2	C02 in combination with C03	\$547	\$547	\$547
CL3	Leather steering wheel	X	X	Х
FM3	Wet Wiper System	X	X	X
JB4	Active Lane Keeping Assist	X	X	X
must	nust have CO3 + JF1			

144" 4D High	170" 4D High	170" E 4D High
М3СА4Н	М3СА7Н	МЗСАЕН
907.653	907.655	907.657

C03	Premium Plus Package	\$2,008	\$2,008	\$2,008			
E1B	Tray for smartphones incl. wireless charging	X	Х	X			
	Navigation	X	Х	X			
EY2	Intelligent navigation	X	Х	X			
E4M	MBUX Multimedia System with 10.25" touchscreen	X	Х	X			
EX9	Free map data updates for 3 years	X	Х	X			
H1I	Front-to-rear outlet in instrument panel	X	Х	X			
JA9	Traffic Sign Assist	X	Х	Х			
XM4	Acoustic package	Х	Х	Х			
must have (CA2+(JB7/JB6/JB8)); not with FR8 and CO2							

X67	Chrome Grille Package	\$325	\$325	\$325			
CN2	Radiator grille frame in vehicle color	Х	X	X			
FK3	Chrome plated radiator grille (MB only)	Х	Х	Х			
no re	no restrictions						

X13	Exterior Lighting Package	\$1,801	\$1,801	\$1,801		
L13	Fog lamp with cornering light function	X	X	X		
L22	Partial LED tail lights	Х	Х	X		
LA1	High beam assist	Х	Х	X		
LG7	LED high performance headlamps	Х	Х	X		
no restrictions						

C07	Cargo Protection Package	\$1,250	\$1,250	\$1,250		
V25	Half height load compartment trim	Х	Х	Х		
V42	Lashing rails, waist level	Х	Х	X		
VC4	Cargo lashing rails, head height	Х	Х	Х		
VK8	Floor covering, plastic	Х	Х	Х		
YK3	Cargo straps, D-rings	Х	Х	Х		
not with X66						

CR1	Rear Door Convenience Package	\$508	\$508	\$508
T85	Assist handle, left rear door	X	X	X
T86	Assist handles, right rear door	X	X	X
W54	Rear doors, opening to side wall	X	X	X
W5F	90 Degree fixation point- Rear Doors	X	X	X

UL1	Upfit Prep and Load Restraining Package	\$1,768	\$1,768	\$1,768
V43	Wood floor with 6 D-rings	X	X	X
V42	Lashing rails, waist level	X	X	X
VC4	Cargo lashing rails, head height	X	X	X
VA3	Side wall paneling full hardboard	Х	Х	X
VV2	Lashing rails, floor level (plus 4 anchors)	X	X	X

144" 4D High	170" 4D High	170" E 4D High
М3СА4Н	М3СА7Н	МЗСАЕН
907.653	907.655	907.657

X66	Heavy-Duty-Cargo Protection Package	\$1,952	\$1,952	\$1,952			
V43	Wood floor with 6 D-rings	Х	Х	Х			
V42	Lashing rails, waist level	Х	Х	Х			
VA3	Side wall paneling full hardboard	Х	Χ	Х			
VC4	Cargo lashing rails, head height	Х	Χ	Х			
VV2	Lashing rails, floor level (plus 4 anchors)	Х	X	Х			
YK3	Cargo straps, D-rings	Х	Χ	Х			
YK4	Cargo straps, lashing rails	Х	Х	Х			
not with CO7							

X69	Swivel Seat Package	\$595	\$595	\$595		
SR8	Swivel base for driver's seat	Х	Х	X		
SR9	Swivel base for front passenger seat	Х	Х	Х		
S87	Driver's seat frame, low	Х	Х	Х		
S88	Passenger seat frame, low	Х	Х	Х		
must	must have (C00+C0S) OR (C00+X68), choose BE2 or B25 (1500/2500 only)					

Bright   Michael   Micha			144" 4D High	144" AWD	170" 4D High	170" AWD	170" E 4D High	170" E AWD
Fingine			MXCA4H	MXCA4A	MXCA7H	MXCA7A	MXCAEH	MXCAEA
### ### ### ### ### ### ### ### ### ##			907.653	907.653	907.655	907.655	907.657	907.657
### ### ### ### ### ### ### ### ### ##	Enain	e						
End   AGM battery 12V 92 Att 890 A			S	S	S	S	S	S
Month   Mile			S	S	S		S	S
M72   Approved Bio-Discel B20	G43	Automatic transmission, 9G-tronic	S	S	S	S	S	S
MSS   20.4 - Cylinder dissel engine (208hp output)   S   S   S   S   S   S   S   S   S		·	S	S	S	S	S	S
Section   Sect	M71	Approval Bio-Diesel B20	S	S	S	S	S	S
MIRIS   SILEY emissions	M5N	2.0L 4-cylinder diesel engine (208hp output)	S	S	S	S	S	S
TSD   Door-mounted assist handles, driver & passenger   -	_		S	S	S	S	S	S
AMM   All Wheel Drive with torque on demand   -	X55	All Wheel Drive Package	-	\$6,700	-	\$6,700	-	\$6,700
	T75	Door-mounted assist handles, driver & passenger	-	S	-	S	-	S
Main			-	S	-	S	-	S
RHT   Tires LT 215/85 R16- DRW	Tires -	- choose while ordering	•				•	
RS6         S. S. J. x 16 steel wheels         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S	X34	Dual Rear Wheel	\$0	\$0	<i>\$0</i>	<b>\$0</b>	\$0	\$0
RO9   Unspecified tire brand	RH7	Tires LT 215/85 R16- DRW	S	S	S	S	S	S
X31   Super Single Tire	RS6	5.5 J x 16 steel wheels	S	S	S	S	S	S
R9A         285/65 R 16 C super single tires         O         -         O         -         O         -         O         -         O         -         O         -         O         -         O         -         O         -         O         -         O         -         O         -         O         -         O         -         O         -         O         -         O         -         O         -         O         -         O         -         O         -         O         -         O         -         O         -         O         -         O         -         O         -         O         -         O         -         O         -         O         -         O         -         O         -         O         -         O         O         -         D         O         -         D         O         D         -         D         D         -         D         D         -         D         D         D         D         D         D         D         D         D         D         D         D         D         D         D         D         D         D         D	RD9	Unspecified tire brand	S	S	S	S	S	S
RSD         Steel wheels: 8.5Jx16 Rr; 6.5Jx16 Fr         O         -         O         -         O         -         O         -         O         -         O         -         O         -         O         -         O         -         O         -         O         -         O         -         O         -         O         -         O         -         O         -         O         -         O         -         O         -         O         -         O         -         O         -         O         -         O         -         O         -         O         -         O         -         O         -         O         -         O         -         O         -         O         O         -         O         O         -         O         O         -         O         O         -         D         O         O         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S	X31	Super Single Tire	\$431	-	\$431	•	\$431	-
RD9   Unspecified tire brand   O	R9A	285/65 R 16 C super single tires	0	-	0	-	0	-
RY2   Tire pressure monitoring sensors   O	RS5	Steel wheels: 8.5Jx16 Rr; 6.5Jx16 Fr	0	-	0	-	0	-
RAR2   Axler ratio 3.923	RD9	Unspecified tire brand	0	-	0	-	0	-
AR2	RY2	Tire pressure monitoring sensors	0	-	0	-	0	-
BA3	Equip	ment	•	•			•	
BH1   Hold Function	AR2	Axle ratio 3.923	S	S	S	S	S	S
C6L         Multifunction steering wheel         S         S         S         S         S         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C         C <th< td=""><td>BA3</td><td>Active Brake Assist</td><td>S</td><td>S</td><td>S</td><td>S</td><td>S</td><td>S</td></th<>	BA3	Active Brake Assist	S	S	S	S	S	S
CB8         Stabilization Level II         S         -         S         -         S         -         S         -         S         -         S         -         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S <td>BH1</td> <td>Hold Function</td> <td>S</td> <td>S</td> <td>S</td> <td>S</td> <td>S</td> <td>S</td>	BH1	Hold Function	S	S	S	S	S	S
CL1         Adjustable steering wheel (angle)         S         S         S         S         S         S         D         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S	C6L	Multifunction steering wheel	S	S	S	S	S	S
D03   High roof	CB8	Stabilization Level II	S	-	S	-	S	-
D93         Omission bulkhead         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S	CL1	Adjustable steering wheel (angle)	S	S	S	S	S	S
E07         Hill Start Assist         S         S         S         S           E10         Standard radio         S         S         S         S         S           E10         USB-C socket, 5 V         S         S         S         S         S         S           E30         Starter battery disconnect         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S	D03	High roof	0	0	S	S	S	S
E10         Standard radio         S         S         S         S           E10         USB-C socket, 5 V         S         S         S         S         S           E30         Starter battery disconnect         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S	D93	Omission bulkhead	S	S	S	S	S	S
E1U         USB-C socket, 5 V         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S	E07	Hill Start Assist	S	S	S	S	S	S
E30         Starter battery disconnect         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S	E10	Standard radio	S	S	S	S	S	S
E3J         Pre-installation for switch panel         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S	E1U	USB-C socket, 5 V	S	S	S	S	S	S
E40         Trailer hitch prep. wiring         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S	E30	Starter battery disconnect	S	S	S	S	S	S
ED8         Preinstallation PSM         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S	E3J	Pre-installation for switch panel	S	S	S	S	S	S
EE5 Ultracapacitor discharge module S S S S S S S S S S S S S S S S S S S	E40	Trailer hitch prep. wiring	S	S	S	S	S	S
EK1         Body Builder Connector         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S <td>ED8</td> <td>Preinstallation PSM</td> <td>S</td> <td>S</td> <td>S</td> <td>S</td> <td>S</td> <td>S</td>	ED8	Preinstallation PSM	S	S	S	S	S	S
ESO         Jump start terminal         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S	EE5	Ultracapacitor discharge module	S	S	S	S	S	S
EW6         Pre-installation for Mercedes me Remote Services         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S <t< td=""><td>EK1</td><td>Body Builder Connector</td><td>S</td><td>S</td><td>S</td><td>S</td><td>S</td><td>S</td></t<>	EK1	Body Builder Connector	S	S	S	S	S	S
EY5         Emergency Call System         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S	ES0	Jump start terminal	S	S	S	S	S	S
EY6         Breakdown management         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S	EW6	Pre-installation for Mercedes me Remote Services	S	S	S	S	S	S
F68         Heated & electrically adjustable exterior mirrors         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         <	EY5	Emergency Call System	S	S	S	S	S	S
FF5         Shelf above windshield         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S <td>EY6</td> <td>Breakdown management</td> <td>S</td> <td>S</td> <td>S</td> <td>S</td> <td>S</td> <td>S</td>	EY6	Breakdown management	S	S	S	S	S	S
FG8         Cupholder front         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S	F68	Heated & electrically adjustable exterior mirrors	S	S	S	S	S	S
F11         Remote key (315 mhz) w/central locking         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S	FF5	Shelf above windshield	S	S	S	S	S	S
FJ4         Storage compartment underneath cockpit         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S	FG8	Cupholder front	S	S	S	S	S	S
FR3         Rear view camera (rear-view mirror display)         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S </td <td>FI1</td> <td>Remote key (315 mhz) w/central locking</td> <td>S</td> <td>S</td> <td>S</td> <td>S</td> <td>S</td> <td>S</td>	FI1	Remote key (315 mhz) w/central locking	S	S	S	S	S	S
H16         Heated driver's seat         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S	FJ4	Storage compartment underneath cockpit	S	S	S	S	S	S
H21         Windshield with filter band         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S	FR3	Rear view camera (rear-view mirror display)	S	S	S	S	S	S
H21         Windshield with filter band         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S         S	H16		S	S	S	S	S	S
HH2         Heater, auxiliary electric hot air         S         S         S         S           HH9         Air Condition, Front         S         S         S         S         S           IH7         Headunit         S         S         S         S         S								
HH9 Air Condition, Front         S         S         S         S           IH7 Headunit         S         S         S         S								S
IH7 Headunit S S S S S								S
			S				S	S
	J11	Speedometer, miles and km/h	S	S	S	S	S	S

907.653   907.653	MXCA7H 907.655  S S S S S S S S S S S S S S S S S S	MXCA7A 907.655 S S S S S	907.657  S S S S	MXCAEA 907.657  S S S S
J55 Seat belt warning for co-driver seat S S S J58 Seat belt reminder driver S S S J65 Outside temperature gauge S S S JA8 Crosswind Assist S S S JH3 Communication module (LTE) for dig. services S S S JP3 Service interval 20.000 miles S S S JK5 Instrument cluster with color display S S S	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	\$ \$ \$ \$ \$	S S S	S S
J58       Seat belt reminder driver       S       S         J65       Outside temperature gauge       S       S         JA8       Crosswind Assist       S       S         JH3       Communication module (LTE) for dig. services       S       S         JI9       Service interval 20.000 miles       S       S         JK5       Instrument cluster with color display       S       S	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	\$ \$ \$ \$	S S	S
J65       Outside temperature gauge       S       S         JA8       Crosswind Assist       S       S         JH3       Communication module (LTE) for dig. services       S       S         JI9       Service interval 20.000 miles       S       S         JK5       Instrument cluster with color display       S       S	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	\$ \$ \$	S	
JA8 Crosswind Assist  S S  JH3 Communication module (LTE) for dig. services  S S  JI9 Service interval 20.000 miles  S S  JK5 Instrument cluster with color display  S S	\$ \$ \$ \$	S S	_	S
JH3       Communication module (LTE) for dig. services       S       S         JI9       Service interval 20.000 miles       S       S         JK5       Instrument cluster with color display       S       S	S S S	S	S	
JI9 Service interval 20.000 miles S S  JK5 Instrument cluster with color display S S	S S			S
JK5 Instrument cluster with color display S S	S	S	S	S
			S	S
	S	S	S	S
Black diesel filler cap S S		S	S	S
K60 Exhaust straight to rear S S	S	S	S	S
KB7 24.5 gallon fuel tank	S	S	S	S
KL1 Aux fuel sending unit w/ fuel tap S S	S	S	S	S
MD3 Top speed limitation 75 mph S O	0	0	0	0
M15 Fuel/water seprarator & lubrication package S S	S	S	S	S
KP7 4rd generation SCR emission control system S S	S	S	S	S
L65 Interior lights, cargo compartment S S	S	S	S	S
L94 Parking lights deletion S S	S	S	S	S
LA2 Headlight assistant S S	S	S	S	S
LB5 3rd brake light S S	S	S	S	S
MS1 Cruise control S S	S	S	S	S
P47 Front mudflaps S S	S	S	S	S
P48 Rear mudflaps S S	S	S	S	S
Q11 Longitudinal member reinforcement S S	S	S	S	S
R65 Spare tire bracket below frame S S	S	S	S	S
R87 Spare tire S S	S	S	S	S
RMO All-season tires S S	S	S	S	S
S02 Standard driver seat S S	S	S	S	S
S04 Standard front passenger seat S S	S	S	S	S
S22 Armrest for driver's seat S S	S	S	S	S
S25 Armrest for front passenger seat S S	S	S	S	S
SA5 Front airbag, driver S S	S	S	S	S
SA6 Front airbag, passenger S S	S	S	S	S
SH1 Thorax-pelvis sidebag, driver S S	S	S	S	S
SH2 Thorax-pelvis sidebag, co-driver S S	S	S	S	S
SH9 Airbag, driver/passenger window S S	S	S	S	S
SK2 Seat occupancy sensor, driver's seat S S	S	S	S	S
T16 Sliding door, passenger side S S	S	S	S	S
V93 Without factory installed flooring S S	S	S	S	S
V94 Cable duct - side wall S S	S	S	S	S
V95 Cable duct - rear portal S S	S	S	S	S
W54 Rear doors, opening to side wall O O	0	0	S	S
X5G Witout load uprating/derating 5,000 kg S S	S	S	S	S
X64 Plates/booklets in English (US)	S	S	S	S
X99 Manufacturer Mercedes-Benz AG S S	S	S	S	S
XC8 VIN visible from outside S S	S	S	S	S
XI2 Change Year G2-I S S	S	S	S	S
XY4 Model Year 2024 S S	S	S	S	S
Y43 Jack, hydraulic S S	S	S	S	S
ZU8 USA country version S S	S	S	S	S
ZZ4 Brand content Mercedes-Benz North America S S	S	S	S	S

	1	144" 4D High	144" AWD	170" 4D High	170" AWD	L70" E 4D Higl	170" E AWD
		MXCA4H	MXCA4A	MXCA7H	MXCA7A	MXCAEH	MXCAEA
		907.653	907.653	907.655	907.655	907.657	907.657
_		307.033	307.033	307.033	307.033	307.037	307.037
A50	Front axle reinforced	\$387	-	\$387	-	\$387	-
AP2	Addtl. bar for driveshaft & exhaust extension	\$77	\$77	\$77	\$77	-	-
B01	ESP for increased Center of Gravity above 39.4"	-	-	\$0	\$0	\$0	\$0
	must have CB4/CB8/X55; not with RH0/CB7						
BE2	Handbrake lever, folding	\$62	\$62	\$62	\$62	\$62	\$62
	X69 must have BE2						
CB4	Stabilization Level III	\$209	-	\$209	-	\$209	-
	not with CB7/CB8/X55						
C72	Bumpers front/rear primed	\$300	\$300	\$300	\$300	\$300	\$300
	must have CN2 (part of X67), not with CM0						
CE8	Raised rear body mounts	\$282	-	\$282	-	\$282	-
CM0	Painted metallic front & rear bumper	\$657	\$657	\$657	\$657	\$657	\$657
	must have (CN2/X67) + (JA7/C01) + JB7 + (7755/9197/9775)						
CM9	Primed side moldings	\$408	\$408	\$408	\$408	\$408	\$408
D03	High roof	\$3,500	\$3,500	S	S	S	S
D13	Mounting rails for roof rack	\$336	\$336	\$336	\$336	\$336	\$336
D22	Fixed sunroof (rear roof section)	\$377	\$377	\$377	\$377	\$377	\$377
	not with H08/HK4/H72/V36/ZK4						
D50	Cargo partition	\$322	\$322	\$322	\$322	\$322	\$322
	not with D51/D93/H08/HK4/T74/V36; must have one of T93/T77						
D51	Cargo partition with 1 window	\$376	\$376	\$376	\$376	\$376	\$376
	not with D50/D93/H08/HK4/T74/V37/D17; must have one of T93/T77	,				•	
E1B	Tray for smartphones incl. wireless charging	\$175	\$175	\$175	\$175	\$175	\$175
	must have CO2/E3M + H1I					!	
E1E	Navigation	\$815	\$815	\$815	\$815	\$815	\$815
	must have CO2/E3M, not with CO3						
E1S	Sirius XM, satellite radio	\$285	\$285	\$285	\$285	\$285	\$285
	must have CO2/E3M/CO3						
E1X	MBUX multimedia 6-hour runtime	-	-	\$0	\$0	\$0	\$0
	must have X2R + (C02+E1E/E1S)/C03/(E3M+E1E/E1S)						
E1R	Additional Fuses (40/80/150/100 Ampere)	-	-	\$57	\$57	\$57	\$57
	must have X2R						·
E2A	Access point for BB special signals in cockpit	\$32	\$32	\$32	\$32	\$32	\$32
E2I	Additional battery, co-driver seat base	\$277	\$277	\$277	\$277	\$277	\$277
	must have E36/C06; not with E2M/F09; CHS production only	7	<b>T</b>	7	<b>T</b>	7-11	7
E2M	Additional battery, engine compartment	\$277	\$277	\$277	\$277	\$277	\$277
	must have X01+ (E36/C06); not with E2I/X69/F09	72//	Ψ2//	<b>Ϋ</b> Ζ///	Ψ2//	Ψ2//	<b>Ψ</b> 277
ESM	MBUX Multimedia System with 7" touchscreen	\$531	\$531	\$531	\$531	\$531	\$531
LJIVI	not with CO2/CO3; must have JK5+(JB7/FR8)	7551	7551	7331	7551	7331	7331
E36		¢124	¢124	\$124	¢124	¢124	\$124
E30	Cutoff relay for additional battery	\$124	\$124	\$124	\$124	\$124	\$124
E16	standard with E2I/E2M	¢102	¢102	¢102	¢102	¢102	¢102
E46	12 V power outlet, driver seat base	\$103	\$103	\$103	\$103	\$103	\$103
E5M	Extension of PSM standard contact	\$65	\$65	\$65	\$65	\$65	\$65
ED5	Parametric special module (PSM)	\$354	\$354	\$354	\$354	\$354	\$354
LL3	not with ED8	¢140	¢140	¢140	¢140	¢140	¢140
EE3	115 V socket	\$140	\$140	\$140	\$140	\$140	\$140
EP7	Basic electric fitting for rear loudspeakers	\$76	\$76	\$76	\$76	\$76	\$76
ES2	12 V power outlet, rear compartment	\$103	\$103	\$103	\$103	\$103	\$103
ES5	Charging package, dashboard	\$92	\$92	\$92	\$92	\$92	\$92
ET4	Active Distance Assist DISTRONIC	\$294	\$294	\$294	\$294	\$294	\$294
	must have CO3						

		144" 4D High	144" AWD	170" 4D High	170" AWD	L70" E 4D Higl	170" E AWD
		MXCA4H	MXCA4A	МХСА7Н	MXCA7A	MXCAEH	MXCAEA
		907.653	907.653	907.655	907.655	907.657	907.657
F1K	Coat hooks in driver cabin	\$15	\$15	\$15	\$15	\$15	\$15
	must have D50/D51						
F49	Electrically heated windshield	\$244	\$244	\$244	\$244	\$244	\$244
	no restriction			•			
F61	Interior rear view mirror	\$41	\$41	\$41	\$41	\$41	\$41
	not with D50; must have C02/E3M/C03	•		!			
F84	Digital Rearview Mirror	\$736	\$736	\$736	\$736	\$736	\$736
	must have LA2- Not with F61	-		•		•	
FE9	Additional DIN-slot	\$91	\$91	\$91	\$91	\$91	\$91
FF4	Storage compartment above cabin	\$208	\$208	\$208	\$208	\$208	\$208
	must have D03, not with D17/D64/H08/HK4						
FF8	Overhead storage slot, front center	\$117	\$117	\$117	\$117	\$117	\$117
FJ1	Hinged lid for storage compartment	\$105	\$105	\$105	\$105	\$105	\$105
FR8	Rear view camera (head unit display)	\$377	\$377	\$377	\$377	\$377	\$377
	must have CO2/E3M; not with FR3/JB7; 3500XD not with JB8			•			
FY1	Security alarm w. interior motion sensor	\$654	\$654	\$654	\$654	\$654	\$654
	must have LC4/C00						
FY7	Optional 3-button keys	\$41	\$41	\$41	\$41	\$41	\$41
FZ9	Keys, two additional masters	\$136	\$136	\$136	\$136	\$136	\$136
H00	Warm/cool air duct to rear compartment	\$66	\$66	\$66	\$66	\$66	\$66
	not with D50/D51/Y2A						
H01	Heat insulation, rear compartment	\$175	\$175	\$175	\$175	\$175	\$175
	must have V21/V25/VA3/VA1/C07/X66			•			
H04	Heat insulation, front compartment	\$209	\$209	\$209	\$209	\$209	\$209
	if + D50/D51 must have V07						
H08	Air conditioning rear, roof-mounted	\$3,216	\$3,216	\$3,216	\$3,216	\$3,216	\$3,216
	must have D93 +V36+M61; not with HK4/C06/X66/C07						
H12	Fuel-fired pre-heater/booster (17K BTU)	\$1,249	\$1,249	\$1,249	\$1,249	\$1,249	\$1,249
	not with HZ9						
H13	Rear cabin heater and vents	\$880	\$880	\$880	\$880	\$880	\$880
	must have H12/HZ9						
H15	Heated front passenger seat	\$318	\$318	\$318	\$318	\$318	\$318
	must have H16; not with X68						
H22	Rear window defroster	\$283	\$283	\$283	\$283	\$283	\$283
	must have W61/W78; standard for W61+W70						
H72	Roof fan, electric	\$448	\$448	\$448	\$448	\$448	\$448
	not with D22/V36						
H88	Rear heater prep	\$453	\$453	\$453	\$453	\$453	\$453
	must have H12/HZ9; not with H13/T19						
H1I	Front-to-rear outlet in instrument panel	\$0	\$0	\$0	\$0	\$0	\$0
	must have FJ1/C01						
HH4	Thermotronic automatic climate control	\$378	\$378	\$378	\$378	\$378	\$378
	must have JF1; if +H13 must have H08/HK4						
HK4	Rear air conditioner, heavyduty	\$4,411	\$4,411	\$4,411	\$4,411	\$4,411	\$4,411
	must have D03+V36+D93; not with H08/ZB6/ZE6/N62/N63						
HZ9	Fuel-fired heater booster (18,000 BTU)	\$756	\$756	\$756	\$756	\$756	\$756
	not with H12						
J51	Fuel gauge, optimized for aux. fuel tap	\$80	\$80	\$80	\$80	\$80	\$80
	not with HZ9/H12						
J52	Engine oil level display at cold start	\$0	\$0	\$0	\$0	\$0	\$0
JA7	Blind Spot Assist	\$504	\$504	\$504	\$504	\$504	\$504
1	must have F64						

		144" 4D High	144" AWD	170" 4D High	170" AWD	170" E 4D Higl	170" E AWD
		MXCA4H	MXCA4A	MXCA7H	MXCA7A	MXCAEH	MXCAEA
		907.653	907.653	907.655	907.655	907.657	907.657
ID 4	Active Lane Keening Assist	ćana	¢ລລລ	່ວາາ	່ວາາ	່ວາາ	່ວວວ
JB4	Active Lane Keeping Assist standard with CO2/CA2	\$322	\$322	\$322	\$322	\$322	\$322
JB7	Parking Package	\$688	\$688	\$688	\$688	\$688	\$688
JD/	must have CO2/CO3/E3M; not with W75/W76/JB6	<b>3000</b>	3000	3000	3000	3000	3000
JF1	Rain sensor	\$118	\$118	\$118	\$118	\$118	\$118
_	Backup alarm	\$110	\$111	\$110	\$110	\$110	\$110
JW2	Deactivation lamp monitoring failure	\$30	\$30	\$30	\$30	\$30	\$30
JW8	Attention Assist	\$55	\$55	\$55	\$55	\$55	\$55
K51	Misfueling prevention for Diesel	\$55	\$55	\$55	\$55	\$55	\$55
K52	DEF fluid filler cap - lockable	\$30	\$30	\$30	\$30	\$30	\$30
L13	Fog lamp with cornering light function	\$223	\$223	\$223	\$223	\$223	\$223
L71	Light/motion sensor in rear compartment	\$61	\$61	\$61	\$61	\$61	\$61
L/1	not with V36	701	701	701	701	701	701
LB9	Illuminated front exits	\$170	\$170	\$170	\$170	\$170	\$170
	LED light strip in load compartment	\$294	\$294	\$294	\$294	\$294	\$294
LCZ	not with H08/HK4/V36/C06	3234	<b>γ2</b> 54	<b>7234</b>	<b>7234</b>	<b>7234</b>	Ş25 <del>4</del>
LC4	Comfort overhead control panel	\$105	\$105	\$105	\$105	\$105	\$105
	Speed limitation 65 mph	\$67	\$67	\$67	\$67	\$103	\$67
10120	not with MD3	Ş07	707	<b>Ψ</b> 07	707	<b>707</b>	707
M61	Alternator 14 V / 280 A	\$188	\$188	\$188	\$188	\$188	\$188
	Top speed limitation 75 mph	\$188 S	\$71	\$71	\$71	\$71	\$71
IVIDS	not with M20	3	7/1	7/1	7/1	7/1	٧/١
N62	Front engine bracket for additional alternator	\$523	\$523	\$523	\$523	\$523	\$523
INUZ	not with HK4/N63	<del>-</del>	7323	7323	7323	7323	<b>7323</b>
N63	Front engine bracket for auxiliary A/C compressor	\$523	\$523	\$523	\$523	\$523	\$523
1103	not with HK4/N62	<del>-</del>	7323	7323	7323	7323	7323
P93	Omission of D-rings	-\$15	-\$15	-\$15	-\$15	-\$15	-\$15
1 33	not with D93/V43/VK8	713	713	713	713	713	713
QA2	Trailer cross member 7,500 lbs capacity	\$208	\$208	\$208	\$208	-	-
QAZ	not with W73/W75/W76/Q24/Q67	7200	7200	7200	7200		
QA9	Half-sided step rear (for trailer hitch)	\$113	\$113	\$113	\$113	\$113	\$113
QAS	must have QA2; not with W73/W75/W76	<b>VII</b> 3	7113	7113	7113	7113	<b>V113</b>
Q24	Trailer hitch, 5,000 lbs	-	-	-	_	\$164	\$164
QZT	not with W73/W75/W76					7104	7104
R91	Spare tire deletion	-\$110	-\$110	-\$110	-\$110	-\$110	-\$110
11.51	must have R92; not with R87	7110	7110	Ų110	Ų110	Ų110	7110
R92	Spare tire carrier deletion	\$0	\$0	\$0	\$0	\$0	\$0
1132	must have R91; not with R65	ΨO	γo	γo	γo	γo	γo
R98	Rims painted jet black	\$91	\$91	\$91	\$91	\$91	\$91
1130	not with RL5/RM2	<b>431</b>	771	731	731	731	<b>431</b>
RF1	Tire brand Continental	\$0	\$0	\$0	\$0	\$0	\$0
	must have RM1 + RM9	ΨO	70	γo	ΨŪ	γo	γo
RF8	Tire brand Michelin	\$0	\$0	\$0	\$0	\$0	\$0
1110	must have RM9; not with RM1	γo	70	γo	γo	70	γU
RH0	Tire brand Kumho	\$0	\$0	\$0	\$0	\$0	\$0
1110	must have RM9; not with RM1	ΨO	γo	γo	γo	γo	γo
RM1	M+S winter tires	\$190	\$190	\$190	\$190	\$190	\$190
	must have RF1/RD9; not with RF8/RH0/X31	7150	7130	7130	Ŷ±30	7130	<b>9130</b>
RM2	Rims painted arctic white	\$91	\$91	\$91	\$91	\$91	\$91
11112	not with R98/RL5	771	771	731	731	731	771
RM9	Specially requested tires	\$113	\$113	\$113	\$113	\$113	\$113
	must have RF1/RF8/RH0; not with RD9	7113	7113	7113	7110	7113	<b>7113</b>
Ь							

		144" 4D High	144" AWD	170" 4D High	170" AWD	170" E 4D Higl	170" E AWD
		MXCA4H	MXCA4A	МХСА7Н	MXCA7A	MXCAEH	MXCAEA
		907.653	907.653	907.655	907.655	907.657	907.657
S23	Twin front passenger seat	\$448	\$448	\$448	\$448	\$448	\$448
	not with C00/X68/X01	,		,		,	
S28	Armrest, driver and passenger door	\$58	\$58	\$58	\$58	\$58	\$58
S62	Seat belts orange, driver and front passenger	\$36	\$36	\$36	\$36	\$36	\$36
	not with S23	,	,	,	,	1	1
SB9	Driver's seat plus	\$267	\$267	\$267	\$267	\$267	\$267
	must have VF7; not with C00/X68/X69	, -		, -	, -	, -	
SZ7	Storage net, driver's seat backrest	\$71	\$71	\$71	\$71	\$71	\$71
SZ8	Storage net, passenger seat backrest	\$71	\$71	\$71	\$71	\$71	\$71
T12	Sliding door two stage opening	\$92	\$92	\$92	\$92	\$92	\$92
	not with T55	,	,	,			
T50	Electric closing assist right sliding door	\$376	\$376	\$376	\$376	\$376	\$376
	must have D03; not with T55/T93	,		,		,	
T55	Electric sliding door right	\$930	\$930	\$930	\$930	\$930	\$930
	must have D03 + (FY7+T16); not with T12/T50	,	,	,	,	,	1222
T57	Electric sliding step	\$1,199	\$1,199	\$1,199	\$1,199	\$1,199	\$1,199
	must have ED5; not with T93	, ,	, ,	, ,	, ,	1 /	1 /
T60	Opening limiter electrically operated sliding door	\$134	\$134	\$134	\$134	\$134	\$134
	must have T55	,		,		,	
T74	Assist handle, B-pillar	\$36	\$36	\$36	\$36	\$36	\$36
	must have D93; not with T77	,	,	,			
T75	Door-mounted assist handles, driver & passenger	\$66	S	\$66	S	\$66	\$66
T77	Assist handle w/ partition	\$36	\$36	\$36	\$36	\$36	\$36
	must have D50/D51/D64	,	,	1	,	1	1
T85	Assist handle, left rear door	\$36	\$36	\$36	\$36	\$36	\$36
	Assist handles, right rear door	\$36	\$36	\$36	\$36	\$36	\$36
T93	Sliding door right side deletion	\$0	\$0	\$0	\$0	\$0	\$0
	not with T16/T50/T57/VK8/VC5						
V07	Cab rear wall liner	\$403	\$403	\$403	\$403	\$403	\$403
	must have (D50/D51)+F1K; standard with H04						
V21	Luxury interior Trim	\$740	\$740	\$740	\$740	\$740	\$740
	must have VA5/VA7; not with V52/VA1/VA3		•				
V24	Pallet support in sliding door step	\$108	\$108	\$108	\$108	\$108	\$108
	must have (V43/X66)+(D50/D51); not with VK8/V93/C07						
V25	Half height load compartment trim	\$225	\$225	\$225	\$225	\$225	\$225
	not with VA1/VA3/VA5/V52/X66						
V31	Window pillar trim	\$574	\$574	\$574	\$574	\$574	\$574
	must have V36 + (V21/VA1) + (F02/F03/F07); not with V42						
V35	Wheel house covering	\$117	\$117	\$117	\$117	\$117	\$117
	if +V43 must have V25/VA1/VA3; not with V52		•		•		
V36	Roof trim	\$982	\$982	\$982	\$982	\$982	\$982
	must have D93; not with D17/D22/H72/L65/L71/LC2/VA3/V42/ZE6/(	T93+-D03)/XI	56/C06/C07				
V42	Lashing rails, waist level	\$310	\$310	\$310	\$310	\$310	\$310
	not with V36/ZE6						
V43	Wood floor with 6 D-rings	\$473	\$473	\$473	\$473	\$473	\$473
	not with P93/V93/VL4/VK8/C07; standard with D93/H13/V24/V52/V0						
V48	Floor cover behind seat box	\$30	\$30	\$30	\$30	\$30	\$30
	must have D93; not with D50/D51/D56/D62/D64/V43/VK8						
V4A	Full paneling, right sliding door	\$123	\$123	\$123	\$123	\$123	\$123
	must have D03+T16+V21+VA5+W17; not with T19						
V85	Cigarette lighter & ash cup, front	\$44	\$44	\$44	\$44	\$44	\$44
<u> </u>							•

			l <b></b>			l	
			l e	170" 4D High		_	
		MXCA4H	MXCA4A	MXCA7H	MXCA7A	MXCAEH	MXCAEA
		907.653	907.653	907.655	907.655	907.657	907.657
VA1	Side wall paneling waist height PVC	\$356	\$356	\$356	\$356	\$356	\$356
•	must have VA5/VA7; not with V52	7000	7000	7000	7,000	7000	7000
VA3	Side wall paneling full hardboard	\$497	\$497	\$497	\$497	\$497	\$497
VAS	not with V36/F02; if T93 must have (D50/D51)	ψ 13 <i>i</i>	Ψ 137	Ψ 137	ψ 13 <i>7</i>	ψ 137	ψ 137
VA5	Full paneling, hinged rear doors	\$43	\$43	\$43	\$43	\$43	\$43
٧٨٥	must have D03+VA7+(W61/W78); not with V25	743	743	<del>7-1</del> 3	7+3	Ş <del>+</del> 3	۲۳۰
VA7	Storage compart. w/ net in rear doors	\$142	\$142	\$142	\$142	\$142	\$142
VA		<b>7142</b>	\$14Z	Ş14Z	Ş14Z	<b>7142</b>	\$14Z
VCA	must have W61/W78; not with V52	¢46E	¢46E	¢46E	¢46E	¢46E	¢46E
VC4	Cargo lashing rails, head height	\$465	\$465	\$465	\$465	\$465	\$465
VCE	must have V42/C07/X66; not with ZE6	ć70	ć70	ć70	Ċ70	ć70	Ċ70
VC5	Door sill - protective edge	\$79	\$79	\$79	\$79	\$79	\$79
	must have V43/X66; not with T19/T93/VK8/VV2/V93/C07		4		4	4	4
VK8	Floor covering, plastic	\$414	\$414	\$414	\$414	\$414	\$414
	not with V43/P93/T19/T93/V52/VC5/X66					,	
VV2	Lashing rails, floor level (plus 4 anchors)	\$302	\$302	\$386	\$386	\$421	\$421
	must have V43; not with V93/VC5/ZE6						
VV4	Additional Ground Weld Studs	\$50	\$50	\$50	\$50	\$50	\$50
	no restriction	_					
W16	2nd row, fixed window, driver side	\$162	\$162	\$162	\$162	\$162	\$162
	if D93 must have F43+W70; if D93 & standard roof CHS production re	quired					
W17	2nd row, fixed window, passenger side	\$162	\$162	\$162	\$162	\$162	\$162
	if D93 must have F43+W70; if D93 & standard roof CHS production re	quired					
W33	FMVSS 217 emergency exit	\$424	\$424	\$424	\$424	\$424	\$424
	must have V31; not with D50/T19/W16				•		•
W54	Rear doors, opening to side wall	\$403	\$403	\$403	\$403	S	S
W5F	90 Degree fixation point- Rear Doors	\$90	\$90	\$90	\$90	\$90	\$90
	must habe W54 / not with V21/V36/VA1/VA7	_					
W61	Windows in rear doors	\$105	\$105	\$105	\$105	\$105	\$105
	must have VA7/ if D51 must have F61; not with W78/(W70+-(H22/F0	2))	l .	'			
W70	Black tinting (90%) for rear windows	\$155	\$155	\$155	\$155	\$155	\$155
	not with W94; must have W16/W17/F02/((W61/W78)+H22); standar	d with F43/V	V33/F07	!			
W73	Bumper step, rear, grey	\$209	\$209	\$209	\$209	\$209	\$209
	not with QA2/W75/W76	7	7-00	7-00	7-00	7-55	7-00
W75	Step, wide, at rear end	\$345	-	\$345	_	\$345	-
*****	not with JB6/JB7/Q24/QA9; must have R91+R92	70.0		70.0		70.0	
W/76	Bumper step, rear, spring-loaded	-	-	\$673		\$673	
***	must have R91+R92; not with JB6/JB7/X55/Q24			<b>7073</b>		7073	
\\/70	Heated rear window(s) w/ washers/wipers	\$376	\$376	\$376	\$376	\$376	\$376
VV / 6	Must have H22+VA7 / if D51 must have F61; not with W61	3370	<b>3370</b>	Ş370	Ş370	Ş370 -	<b>3370</b>
X2R	Conversion to RV requirement			\$0	\$0	\$0	\$0
AZN	must have B01+D93+E1X	-	-	ŞU	ŞÜ	ŞU	ŞU
V00		ćo	ćo	ćo	ćo	ćo	ć٥
X90	Deletion of Sprinter badge, left rear door	\$0	\$0	\$0	\$0	\$0	\$0
X93	Deletion of model badge, right rear door	\$0	\$0 \$07	\$0 \$07	\$0 \$07	\$0 607	\$0 \$07
XM4	Acoustic package	\$97	\$97	\$97	\$97	\$97	\$97
	standard with CO2/CO3	400	400	400	400	400	400
Y10	First-aid kit	\$30	\$30	\$30	\$30	\$30	\$30
Y26	Wheel chocks	\$43	\$43	\$43	\$43	\$43	\$43
Y45	Emergency flashlight	\$30	\$30	\$30	\$30	\$30	\$30
Y68	Paint preservative	\$209	\$209	\$238	\$238	\$252	\$252
Y69	Surface protection for stock vehicles	\$352	\$352	\$352	\$352	\$352	\$352
YK3	Cargo straps, D-rings	\$91	\$91	\$91	\$91	\$91	\$91
YK4	Cargo straps, lashing rails	\$116	\$116	\$116	\$116	\$116	\$116
	must have V42/VV2; not with ZE6						
ZE6	Shelving prep	\$717	\$717	\$717	\$717	\$717	\$717
	not with T93/H13/T19/V36/V42/VC4/VK8/VV2/YK4						
ZH4	Downhill speed regulation for 4x4	-	\$61	-	\$61	-	\$61
	must have ED5						
	<u> </u>						

		144" 4D High	144" AWD	170" 4D High	170" AWD	170" E 4D High	170" E AWD
		MXCA4H	MXCA4A	MXCA7H	MXCA7A	MXCAEH	MXCAEA
		907.653	907.653	907.655	907.655	907.657	907.657
C00	Comfort Package	\$307	\$307	\$307	\$307	\$307	\$307
LC4	Comfort overhead control panel	X	Х	X	Х	X	Х
SE4	Lumbar support, co-driver's seat	Х	Х	Х	Х	X	Х
SE5	Lumbar support, driver's seat	Х	Х	Х	Х	Х	Х
SK0	Comfort head restraint, driver	Х	Х	Х	Х	X	Х
SK1	Comfort head restraint, co-driver	Х	Х	Х	Х	Х	Х
must	have COS OR X68; CA/CC only: not with S23					-	

COS	Comfort Package (Seat addition)	\$426	\$426	\$426	\$426	\$426	\$426	
SB1	Comfort driver's seat	Х	Х	Х	Х	Х	X	
SB2	Comfort passenger seat	Х	X	Х	Х	Х	Х	
must	must have COO							

X68	Comfort Plus Package	\$1,898	\$1,898	\$1,898	\$1,898	\$1,898	\$1,898	
H15	Heated front passenger seat	Х	Х	Х	Х	Х	Х	
SF1	Driver's seat electrically adjustable	Х	Х	Х	Х	Х	Х	
SF2	Co-driver's seat electrically adjustable	Х	Х	Х	Х	Х	Х	
must	nust have COO and VF4 OR VF6, CA/CC only: not with S23							

C01	Driver Convenience Package	\$449	\$449	\$449	\$449	\$449	\$449
E46	12 V power outlet, driver seat base	Х	X	Х	X	X	X
FJ1	Hinged lid for storage compartment	Х	Х	Х	Х	Х	X
FJ5	Hinged Lid for Storage Compartments left and right	Х	Х	Х	Х	Х	Х
FZ9	Keys, two additional masters	Х	Х	Х	Х	Х	Х
JW8	Attention Assist	Х	X	Х	Х	Х	X

C02	Premium Package	\$805	\$805	\$805	\$805	\$805	\$805	
E3M	MBUX Multimedia System with 7" touchscreen	X	X	X	Х	X	X	
FM3	Wet Wiper System	X	X	X	Х	Х	X	
JB4	Active Lane Keeping Assist	X	X	X	Х	X	X	
must	nust have JF1 + XM4; must choose FR8/JB7							

CA2	CO2 in combination with CO3	\$547	\$547	\$547	\$547	\$547	\$547
CL3	Leather steering wheel	X	X	Х	Х	Х	X
FM3	Wet Wiper System	X	X	Х	Х	X	X
JB4	Active Lane Keeping Assist	X	X	Х	Х	X	X
must	have CO3 + JF1						

144" 4D High	144" AWD	170" 4D High	170" AWD	170" E 4D High	170" E AWD
MXCA4H	MXCA4A	МХСА7Н	MXCA7A	MXCAEH	MXCAEA
907.653	907.653	907.655	907.655	907.657	907.657

C03	Premium Plus Package	\$2,008	\$2,008	\$2,008	\$2,008	\$2,008	\$2,008
E1B	Tray for smartphones incl. wireless charging	Х	Х	Х	Х	Х	Х
	Navigation	Х	X	Х	Х	Х	Х
EY2	Intelligent navigation	X	X	Х	Х	X	X
E4M	MBUX Multimedia System with 10.25" touchscreen	X	X	Х	Х	X	X
EX9	Free map data updates for 3 years	Х	X	Х	Х	Х	Х
H1I	Front-to-rear outlet in instrument panel	Х	Х	Х	Х	Х	Х
JA9	Traffic Sign Assist	X	X	Х	Х	X	X
XM4	Acoustic package	Х	Х	Х	Х	Х	Х
must	have (CA2+(JB7/JB6/JB8)); not with FR8 and CO2	•	_	•	_	_	•

X67	Chrome Grille Package	\$325	\$325	\$325	\$325	\$325	\$325
CN2	Radiator grille frame in vehicle color	X	Х	X	X	X	Х
FK3	Chrome plated radiator grille (MB only)	X	Х	X	X	X	Х
no re	no restrictions						

X13	Exterior Lighting Package	\$1,801	\$1,801	\$1,801	\$1,801	\$1,801	\$1,801
L13	Fog lamp with cornering light function	Х	Х	Х	Х	Х	X
L22	Partial LED tail lights	Х	Х	Х	Х	Х	X
LA1	High beam assist	Х	Х	Х	Х	Х	Х
LG7	LED high performance headlamps	Х	Х	Х	Х	Х	X
no re	no restrictions						

C07	Cargo Protection Package	\$1,250	\$1,250	\$1,250	\$1,250	\$1,250	\$1,250
V25	Half height load compartment trim	Х	Х	Х	Х	Х	Х
V42	Lashing rails, waist level	Х	Х	Х	Х	Х	Х
VC4	Cargo lashing rails, head height	Х	Х	Х	Х	Х	Х
VK8	Floor covering, plastic	Х	Х	Х	Х	Х	Х
YK3	Cargo straps, D-rings	Х	Х	Х	Х	Х	Х
not v	not with X66						

144" 4D High	144" AWD	170" 4D High	170" AWD	170" E 4D High	170" E AWD
МХСА4Н	MXCA4A	МХСА7Н	MXCA7A	MXCAEH	MXCAEA
907.653	907.653	907.655	907.655	907.657	907.657

UL1	Upfit Prep and Load Restraining Package	\$1,768	\$1,768	\$1,768	\$1,768	\$1,768	\$1,768
V43	Wood floor with 6 D-rings	X	X	Х	Х	X	X
V42	Lashing rails, waist level	Х	Х	Х	Х	Х	Х
VC4	Cargo lashing rails, head height	X	X	Х	Х	X	X
VA3	Side wall paneling full hardboard	Х	Х	Х	Х	Х	Х
VV2	Lashing rails, floor level (plus 4 anchors)	Х	Х	X	X	Х	X

X66	Heavy-Duty-Cargo Protection Package	\$1,952	\$1,952	\$1,952	\$1,952	\$1,952	\$1,952
V43	Wood floor with 6 D-rings	X	X	Х	X	X	X
V42	Lashing rails, waist level	Х	Х	Х	Х	Х	X
VA3	Side wall paneling full hardboard	Х	Х	Х	Х	Х	Х
VC4	Cargo lashing rails, head height	Х	Х	Х	Х	Х	X
VV2	Lashing rails, floor level (plus 4 anchors)	Х	Х	Х	Х	Х	X
YK3	Cargo straps, D-rings	Х	Х	Х	Х	Х	Х
YK4	Cargo straps, lashing rails	Х	Х	Х	Х	Х	X
not v	not with CO7						

X69	Swivel Seat Package	\$595	\$595	\$595	\$595	\$595	\$595
SR8	Swivel base for driver's seat	Х	Х	Х	Х	Х	Х
SR9	Swivel base for front passenger seat	Х	Х	Х	Х	Х	Х
S87	Driver's seat frame, low	Х	Х	Х	Х	Х	Х
S88	Passenger seat frame, low	Х	Х	Х	Х	Х	Х
must	must have (COO+COS) OR (COO+X68)						

F09	SHUTTLE DOOR PREP PACKAGE	\$0	\$0	<b>\$0</b>	\$0	\$0	\$0
SW1	Seat belt deletion, passenger	Χ	Х	Χ	Х	Х	Х
S91	Passener seat, deleted	Х	Х	Х	Х	Х	Х
S99	Passenger seat pedestal - deletion	Х	Х	Х	Х	Х	Х
Pack	Package deletes standard options: SH2 Thorax-Pelvis sidebag, co-driver; To add/delete from order must call distirbution team						

144" 4D High	170" 4D High	170" E 4D High
М4СА4Н	М4СА7Н	M4CAEH
907.653	907.655	907.657

		307.033	307.033	307.037
Engin	e			
	High Output Engine/9-Speed Trans.	S	S	S
ED4	AGM battery 12V 92 AH 850 A	S	S	S
G43	Automatic transmission, 9G-tronic	S	S	S
M60	Alternator 14 V / 250 A	S	S	S
	Approval Bio-Diesel B20	S	S	S
	2.0L 4-cylinder diesel engine (208hp output)	S	S	S
	SULEV emissions	S	S	S
Equip			_	
A50	Front axle reinforced	S	S	S
AR2	Axle ratio 3.923	S	S	S
BA3	Active Brake Assist	S	S	S
BH1	Hold Function	S	S	S
C6L	Multifunction steering wheel	S	S	S
CB8	Stabilization Level II	S	S	S
CL1	Adjustable steering wheel (angle)	S	S	S
	High roof	0	S	S
D93	Omission bulkhead	S	S	S
E07	Hill Start Assist	S	S	S
E10	Standard radio	S	S	S
	USB-C socket, 5 V	S	S	S
E30	Starter battery disconnect	S	S	S
E3J	Pre-installation for switch panel	S	S	S
E40	Trailer hitch prep. wiring	S	S	S
ED8	Preinstallation PSM	S	S	S
EE5	Ultracapacitor discharge module	S	S	S
EK1	Body Builder Connector	S	S	S
ES0	Jump start terminal	S	S	S
EW6	Pre-installation for Mercedes me Remote Services	S	S	S
EY5	Emergency Call System	S	S	S
EY6	Breakdown management	S	S	S
F68	Heated & electrically adjustable exterior mirrors	S	S	S
FF5	Shelf above windshield	S	S	S
FG8	Cupholder front	S	S	S
FI1	Remote key (315 mhz) w/central locking	S	S	S
FJ4	Storage compartment underneath cockpit	S	S	S
FR3	Rear view camera (rear-view mirror display)	S	S	S
H16	Heated driver's seat	S	S	S
H21	Windshield with filter band	S	S	S
HH2	Heater, auxiliary electric hot air	S	S	S
HH9	Air Condition, Front	S	S	S
IH7	Headunit	S	S	S
J11	Speedometer, miles and km/h	S	S	S
J55	Seat belt warning for co-driver seat	S	S	S
J58	Seat belt reminder driver	S	S	S
J65	Outside temperature gauge	S	S	S
JA8	Crosswind Assist	S	S	S
JH3	Communication module (LTE) for dig. services	S	S	S
JII3	Service interval 20.000 miles	S	S	S
JK5	Instrument cluster with color display	S	S	S
11/2	Black diesel filler cap	S	S	S
K60	Exhaust straight to rear	S	S S	S
KB7	24.5 gallon fuel tank	S	S S	S S
KD/		S	S S	S
KI 1	Aux fuel conding unit w/ fuel tan			
KL1	Aux fuel sending unit w/ fuel tap			
KL1 M15 KP7	Aux fuel sending unit w/ fuel tap  Fuel/water seprarator & lubrication package  4rd generation SCR emission control system	S S	S	S S

		144" 4D High	170" 4D High	170" E 4D High
		М4СА4Н	М4СА7Н	M4CAEH
		907.653	907.655	907.657
L94	Parking lights deletion	S	S	S
LA2	Headlight assistant	S	S	S
LB5	3rd brake light	S	S	S
MD3	Top speed limitation 75 mph	S	0	0
MS1	Cruise control	S	S	S
P47	Front mudflaps	S	S	S
P48	Rear mudflaps	S	S	S
Q11	Longitudinal member reinforcement	S	S	S
R65	Spare tire bracket below frame	S	S	S
R87	Spare tire	S	S	S
RH7	Tires LT 215/85 R16- DRW	S	S	S
RD9	Unspecified tire brand	S	S	S
RM0	All-season tires	S	S	S
RS6	5.5 J x 16 steel wheels	S	S	S
-	Standard driver seat	S	S	S
S04	Standard front passenger seat	S	S	S
S22	Armrest for driver's seat	S	S	S
S25	Armrest for front passenger seat	S	S	S
-	Front airbag, driver	S	S	S
SA6	Front airbag, passenger	S	S	S
	Thorax-pelvis sidebag, driver	S	S	S
SH2	Thorax-pelvis sidebag, co-driver	S	S	S
SH9	Airbag, driver/passenger window	S	S	S
SK2	Seat occupancy sensor, driver's seat	S	S	S
T16	Sliding door, passenger side	S	S	S
V93	Without factory installed flooring	S	S	S
V94	Cable duct - side wall	S	S	S
V95	Cable duct - rear portal	S	S	S
W54	Rear doors, opening to side wall	0	0	S
	GVWR 12,125 lbs. / 5.500 Kg	S	S	S
X64	Plates/booklets in English (US)	S	S	S
X99	Manufacturer Mercedes-Benz AG	S	S	S
XC8	VIN visible from outside	S	S	S
XI2	Change Year G2-I	S	S	S
XY4	Model Year 2024	S	S	S
Y43	Jack, hydraulic	S	S	S
ZU8	USA country version	S	S	S
ZZ4	Brand content Mercedes-Benz North America	S	S	S

		144" 4D High	170" 4D High	170" E 4D High
		М4СА4Н	М4СА7Н	M4CAEH
		907.653	907.655	907.657
AP2	Addtl. bar for driveshaft & exhaust extension	\$77	\$77	-
B01	ESP for increased Center of Gravity above 39.4"	-	\$0	\$0
	must have CB4/CB8/X55; not with RH0/CB7		•	
BE2	Handbrake lever, folding	\$62	\$62	\$62
	X69 must have BE2			
C72	Bumpers front/rear primed	\$300	\$300	\$300
	must have CN2 (part of X67), not with CM0			
CB4	Stabilization Level III	\$209	\$209	\$209
	not with CB7/CB8/X55			
CE8	Raised rear body mounts	\$282	\$282	\$282
CM0	Painted metallic front & rear bumper	\$657	\$657	\$657
	must have (CN2/X67) + (JA7/C01) + JB7 + (7755/9197/9775)			
CM9	Primed side moldings	\$408	\$408	\$408
D03	High roof	\$3,500	S	S
D13	Mounting rails for roof rack	\$336	\$336	\$336
D22	Fixed sunroof (rear roof section)	\$377	\$377	\$377
	not with H08/HK4/H72/V36/ZK4		•	
D50	Cargo partition	\$322	\$322	\$322
	not with D51/D93/H08/HK4/T74/V36; must have one of T93/T77			,
D51	Cargo partition with 1 window	\$376	\$376	\$376
	not with D50/D93/H08/HK4/T74/V37/D17; must have one of T93/T77	,		
E1B	Tray for smartphones incl. wireless charging	\$175	\$175	\$175
	must have CO2/E3M + H1I			
E1E	Navigation	\$815	\$815	\$815
	must have CO2/E3M, not with CO3	·		
E1S	Sirius XM, satellite radio	\$285	\$285	\$285
	must have CO2/E3M/CO3	·		
E1X	MBUX multimedia 6-hour runtime	-	\$0	\$0
	must have X2R + (C02+E1E/E1S)/C03/(E3M+E1E/E1S)			
E1R	Additional Fuses (40/80/150/100 Ampere)	-	\$57	\$57
	must have X2R		,	,
E1Y	Additional Fuses (40/80/80/100 Ampere)	-	\$57	\$57
	must have X2R / not with E1R			
E2A	Access point for BB special signals in cockpit	\$32	\$32	\$32
E2I	Additional battery, co-driver seat base	\$277	\$277	\$277
	must have E36/C06; not with E2M/F09; CHS production only	·		·
E2M	Additional battery, engine compartment	\$277	\$277	\$277
	must have X01+ (E36/C06); not with E2I/X69/F09	·		·
E3M	MBUX Multimedia System with 7" touchscreen	\$531	\$531	\$531
	not with CO2/CO3; must have JK5+(JB7/FR8)	•	•	
E36	Cutoff relay for additional battery	\$124	\$124	\$124
	standard with E2I/E2M		,	,
E46	12 V power outlet, driver seat base	\$103	\$103	\$103
E5M	Extension of PSM standard contact	\$65	\$65	\$65
ED5	Parametric special module (PSM)	\$354	\$354	\$354
	not with ED8	·		·
EE3	115 V socket	\$140	\$140	\$140
EP7	Basic electric fitting for rear loudspeakers	\$76	\$76	\$76
ES2	12 V power outlet, rear compartment	\$103	\$103	\$103
ES5	Charging package, dashboard	\$92	\$92	\$92
ET4	Active Distance Assist DISTRONIC	\$290	\$290	\$290
	must have CO3			
F1K	Coat hooks in driver cabin	\$15	\$15	\$15
	must have D50/D51			
<u> </u>	· · · · · · · · · · · · · · · · · · ·			

F49 Electrically heated windshield no restriction F61 Interior rear view mirror not with D50; must have C02/E3M/C03 F84 Digital Rearview Mirror must have LA2- Not with F61 F89 Additional DIN-slot FF4 Storage compartment above cabin must have D03, not with D17/D64/H08/HK4 FF8 Overhead storage slot, front center FJ1 Hinged lid for storage compartment FR8 Rear view camera (head unit display) must have C02/E3M; not with FR3/JB7; 3500XD not w FY1 Security alarm w. interior motion sensor must have LC4/C00 FY7 Optional 3-button keys F29 Keys, two additional masters H00 Warm/cool air duct to rear compartment not with D50/D51/Y2A H01 Heat insulation, rear compartment must have V21/V25/VA3/VA1/C07/X66 H04 Heat insulation, front compartment if + D50/D51 must have V07 H08 Air conditioning rear, roof-mounted must have D93 + V36+M61; not with HK4/C06/X66/C0 H12 Fuel-fired pre-heater/booster (17K BTU) not with H29 H13 Rear cabin heater and vents must have H12/H29 H15 Heated front passenger seat must have H16; not with X68 H22 Rear window defroster must have W61/W78; standard for W61+W70 H72 Roof fan, electric not with D22/V36 H88 Rear heater prep must have H12/H29; not with H13/T19 H11 Front-to-rear outlet in instrument panel must have F11/C01	\$654 \$41 \$136 \$66 \$175 \$209	\$244 \$41 \$736 \$91 \$208 \$117 \$105 \$377 \$654 \$41 \$136 \$66 \$175 \$209 \$3,216 \$1,249 \$880	\$244 \$41 \$736 \$291 \$208 \$117 \$105 \$377 \$654 \$41 \$136 \$66 \$175 \$209 \$3,216 \$1,249
no restriction  F61 Interior rear view mirror not with D50; must have C02/E3M/C03  F84 Digital Rearview Mirror must have LA2- Not with F61  FE9 Additional DIN-slot  FF4 Storage compartment above cabin must have D03, not with D17/D64/H08/HK4  FF8 Overhead storage slot, front center  FJ1 Hinged lid for storage compartment  FR8 Rear view camera (head unit display) must have C02/E3M; not with FR3/JB7; 3500XD not with F71 Security alarm w. interior motion sensor must have LC4/C00  F77 Optional 3-button keys  F29 Keys, two additional masters  H00 Warm/cool air duct to rear compartment not with D50/D51/Y2A  H01 Heat insulation, rear compartment must have V21/V25/VA3/VA1/C07/X66  H04 Heat insulation, front compartment if + D50/D51 must have V07  H08 Air conditioning rear, roof-mounted must have D93 + V36+M61; not with HK4/C06/X66/C0  H12 Fuel-fired pre-heater/booster (17K BTU) not with HZ9  H13 Rear cabin heater and vents must have H12/HZ9  H15 Heated front passenger seat must have H16; not with X68  H22 Rear window defroster must have W61/W78; standard for W61+W70  H72 Roof fan, electric not with D22/V36  H88 Rear heater prep must have H12/HZ9; not with H13/T19  H11 Front-to-rear outlet in instrument panel	\$244 \$41 \$736 \$91 \$208 \$117 \$105 \$377 th JB8 \$654 \$41 \$136 \$66 \$175 \$209 \$3,216	\$244 \$41 \$736 \$91 \$208 \$117 \$105 \$377 \$654 \$41 \$136 \$66 \$175 \$209 \$3,216	\$244 \$41 \$736 \$91 \$208 \$117 \$105 \$377 \$654 \$41 \$136 \$66 \$175 \$209 \$3,216
no restriction  F61 Interior rear view mirror not with D50; must have C02/E3M/C03  F84 Digital Rearview Mirror must have LA2- Not with F61  FE9 Additional DIN-slot  FF4 Storage compartment above cabin must have D03, not with D17/D64/H08/HK4  FF8 Overhead storage slot, front center  FJ1 Hinged lid for storage compartment  FR8 Rear view camera (head unit display) must have C02/E3M; not with FR3/JB7; 3500XD not with F71 Security alarm w. interior motion sensor must have LC4/C00  FY7 Optional 3-button keys  F29 Keys, two additional masters  H00 Warm/cool air duct to rear compartment not with D50/D51/Y2A  H01 Heat insulation, rear compartment must have V21/V25/VA3/VA1/C07/X66  H04 Heat insulation, front compartment if + D50/D51 must have V07  H08 Air conditioning rear, roof-mounted must have D93 + V36+M61; not with HK4/C06/X66/C0  H12 Fuel-fired pre-heater/booster (17K BTU) not with HZ9  H13 Rear cabin heater and vents must have H12/HZ9  H15 Heated front passenger seat must have H16; not with X68  H22 Rear window defroster must have W61/W78; standard for W61+W70  H72 Roof fan, electric not with D22/V36  H88 Rear heater prep must have H12/HZ9; not with H13/T19  H11 Front-to-rear outlet in instrument panel	\$41  \$736  \$91  \$208  \$117  \$105  \$377  th JB8  \$654  \$41  \$136  \$66  \$175  \$209  \$3,216  \$1,249	\$41 \$736 \$91 \$208 \$117 \$105 \$377 \$654 \$41 \$136 \$66 \$175 \$209 \$3,216	\$41 \$736 \$91 \$208 \$117 \$105 \$377 \$654 \$41 \$136 \$66 \$175 \$209 \$3,216
F61 Interior rear view mirror  not with D50; must have C02/E3M/C03 F84 Digital Rearview Mirror  must have LA2- Not with F61 FF9 Additional DIN-slot FF4 Storage compartment above cabin  must have D03, not with D17/D64/H08/HK4 FF8 Overhead storage slot, front center FJ1 Hinged lid for storage compartment FR8 Rear view camera (head unit display)  must have C02/E3M; not with FR3/JB7; 3500XD not w FY1 Security alarm w. interior motion sensor  must have LC4/C00 FY7 Optional 3-button keys F29 Keys, two additional masters H00 Warm/cool air duct to rear compartment  not with D50/D51/Y2A H01 Heat insulation, rear compartment  must have V21/V25/VA3/VA1/C07/X66 H04 Heat insulation, front compartment  if + D50/D51 must have V07 H08 Air conditioning rear, roof-mounted  must have D93 + V36+M61; not with HK4/C06/X66/C0 H12 Fuel-fired pre-heater/booster (17K BTU)  not with HZ9 H13 Rear cabin heater and vents  must have H12/H29 H15 Heated front passenger seat  must have H16; not with X68 H22 Rear window defroster  must have W61/W78; standard for W61+W70 H72 Roof fan, electric  not with D22/V36 H88 Rear heater prep  must have H12/H29; not with H13/T19 H11 Front-to-rear outlet in instrument panel	\$736  \$91 \$208  \$117 \$105 \$377  th JB8  \$654  \$41 \$136 \$66  \$175  \$209  \$3,216	\$736 \$91 \$208 \$117 \$105 \$377 \$654 \$41 \$136 \$66 \$175 \$209 \$3,216	\$736 \$91 \$208 \$117 \$105 \$377 \$654 \$41 \$136 \$66 \$175 \$209 \$3,216
not with D50; must have CO2/E3M/CO3 F84 Digital Rearview Mirror must have LA2- Not with F61 FE9 Additional DIN-slot FF4 Storage compartment above cabin must have D03, not with D17/D64/H08/HK4 FF8 Overhead storage slot, front center FJ1 Hinged lid for storage compartment FR8 Rear view camera (head unit display) must have CO2/E3M; not with FR3/JB7; 3500XD not w FY1 Security alarm w. interior motion sensor must have LC4/C00 FY7 Optional 3-button keys F29 Keys, two additional masters H00 Warm/cool air duct to rear compartment not with D50/D51/Y2A H01 Heat insulation, rear compartment must have V21/V25/VA3/VA1/C07/X66 H04 Heat insulation, front compartment if + D50/D51 must have V07 H08 Air conditioning rear, roof-mounted must have D93 +V36+M61; not with HK4/C06/X66/C0 H12 Fuel-fired pre-heater/booster (17K BTU) not with HZ9 H13 Rear cabin heater and vents must have H12/H29 H15 Heated front passenger seat must have H16; not with X68 H22 Rear window defroster must have W61/W78; standard for W61+W70 H72 Roof fan, electric not with D22/V36 H88 Rear heater prep must have H12/H29; not with H13/T19 H11 Front-to-rear outlet in instrument panel	\$736  \$91 \$208  \$117 \$105 \$377  th JB8  \$654  \$41 \$136 \$66  \$175  \$209  \$3,216	\$736 \$91 \$208 \$117 \$105 \$377 \$654 \$41 \$136 \$66 \$175 \$209 \$3,216	\$736 \$91 \$208 \$117 \$105 \$377 \$654 \$41 \$136 \$66 \$175 \$209 \$3,216
F84 Digital Rearview Mirror  must have LA2- Not with F61 FF9 Additional DIN-slot FF4 Storage compartment above cabin  must have D03, not with D17/D64/H08/HK4 FF8 Overhead storage slot, front center FJ1 Hinged lid for storage compartment FR8 Rear view camera (head unit display)  must have C02/E3M; not with FR3/JB7; 3500XD not w FY1 Security alarm w. interior motion sensor  must have LC4/C00 FY7 Optional 3-button keys F29 Keys, two additional masters H00 Warm/cool air duct to rear compartment  not with D50/D51/Y2A H01 Heat insulation, rear compartment  must have V21/V25/VA3/VA1/C07/X66 H04 Heat insulation, front compartment  if + D50/D51 must have V07 H08 Air conditioning rear, roof-mounted  must have D93 + V36+M61; not with HK4/C06/X66/C0 H12 Fuel-fired pre-heater/booster (17K BTU)  not with HZ9 H13 Rear cabin heater and vents  must have H12/HZ9 H15 Heated front passenger seat  must have H16; not with X68 H22 Rear window defroster  must have W61/W78; standard for W61+W70 H72 Roof fan, electric  not with D22/V36 H88 Rear heater prep  must have H12/HZ9; not with H13/T19 H11 Front-to-rear outlet in instrument panel	\$91 \$208 \$117 \$105 \$377 th JB8 \$654 \$41 \$136 \$66 \$175 \$209 \$3,216	\$91 \$208 \$117 \$105 \$377 \$654 \$41 \$136 \$66 \$175 \$209 \$3,216	\$91 \$208 \$117 \$105 \$377 \$654 \$41 \$136 \$66 \$175 \$209 \$3,216
must have LA2- Not with F61 FE9 Additional DIN-slot FF4 Storage compartment above cabin must have D03, not with D17/D64/H08/HK4 FF8 Overhead storage slot, front center FJ1 Hinged lid for storage compartment FR8 Rear view camera (head unit display) must have C02/E3M; not with FR3/JB7; 3500XD not w FY1 Security alarm w. interior motion sensor must have LC4/C00 FY7 Optional 3-button keys F29 Keys, two additional masters H00 Warm/cool air duct to rear compartment not with D50/D51/Y2A H01 Heat insulation, rear compartment must have V21/V25/VA3/VA1/C07/X66 H04 Heat insulation, front compartment if + D50/D51 must have V07 H08 Air conditioning rear, roof-mounted must have D93 +V36+M61; not with HK4/C06/X66/C0 H12 Fuel-fired pre-heater/booster (17K BTU) not with HZ9 H13 Rear cabin heater and vents must have H12/HZ9 H15 Heated front passenger seat must have H16; not with X68 H22 Rear window defroster must have W61/W78; standard for W61+W70 H72 Roof fan, electric not with D22/V36 H88 Rear heater prep must have H12/HZ9; not with H13/T19 H11 Front-to-rear outlet in instrument panel	\$91 \$208 \$117 \$105 \$377 th JB8 \$654 \$41 \$136 \$66 \$175 \$209 \$3,216	\$91 \$208 \$117 \$105 \$377 \$654 \$41 \$136 \$66 \$175 \$209 \$3,216	\$91 \$208 \$117 \$105 \$377 \$654 \$41 \$136 \$66 \$175 \$209 \$3,216
FE9 Additional DIN-slot FF4 Storage compartment above cabin  must have D03, not with D17/D64/H08/HK4 FF8 Overhead storage slot, front center FJ1 Hinged lid for storage compartment FR8 Rear view camera (head unit display)  must have C02/E3M; not with FR3/JB7; 3500XD not w FY1 Security alarm w. interior motion sensor  must have LC4/C00 FY7 Optional 3-button keys FZ9 Keys, two additional masters H00 Warm/cool air duct to rear compartment  not with D50/D51/Y2A H01 Heat insulation, rear compartment  must have V21/V25/VA3/VA1/C07/X66 H04 Heat insulation, front compartment  if + D50/D51 must have V07 H08 Air conditioning rear, roof-mounted  must have D93 +V36+M61; not with HK4/C06/X66/C0 H12 Fuel-fired pre-heater/booster (17K BTU)  not with HZ9 H13 Rear cabin heater and vents  must have H12/HZ9 H15 Heated front passenger seat  must have H16; not with X68 H22 Rear window defroster  must have W61/W78; standard for W61+W70 H72 Roof fan, electric  not with D22/V36 H88 Rear heater prep  must have H12/HZ9; not with H13/T19 H11 Front-to-rear outlet in instrument panel	\$208 \$117 \$105 \$377 th JB8 \$654 \$41 \$136 \$66 \$175 \$209 \$3,216	\$208 \$117 \$105 \$377 \$654 \$41 \$136 \$66 \$175 \$209 \$3,216 \$1,249	\$208 \$117 \$105 \$377 \$654 \$41 \$136 \$66 \$175 \$209 \$3,216
FF4 Storage compartment above cabin  must have D03, not with D17/D64/H08/HK4  FF8 Overhead storage slot, front center  FJ1 Hinged lid for storage compartment  FR8 Rear view camera (head unit display)  must have C02/E3M; not with FR3/JB7; 3500XD not w  FY1 Security alarm w. interior motion sensor  must have LC4/C00  FY7 Optional 3-button keys  FZ9 Keys, two additional masters  H00 Warm/cool air duct to rear compartment  not with D50/D51/Y2A  H01 Heat insulation, rear compartment  must have V21/V25/VA3/VA1/C07/X66  H04 Heat insulation, front compartment  if + D50/D51 must have V07  H08 Air conditioning rear, roof-mounted  must have D93 +V36+M61; not with HK4/C06/X66/C0  H12 Fuel-fired pre-heater/booster (17K BTU)  not with HZ9  H13 Rear cabin heater and vents  must have H12/HZ9  H15 Heated front passenger seat  must have H16; not with X68  H22 Rear window defroster  must have W61/W78; standard for W61+W70  H72 Roof fan, electric  not with D22/V36  H88 Rear heater prep  must have H12/HZ9; not with H13/T19  H11 Front-to-rear outlet in instrument panel	\$208 \$117 \$105 \$377 th JB8 \$654 \$41 \$136 \$66 \$175 \$209 \$3,216	\$208 \$117 \$105 \$377 \$654 \$41 \$136 \$66 \$175 \$209 \$3,216 \$1,249	\$208 \$117 \$105 \$377 \$654 \$41 \$136 \$66 \$175 \$209 \$3,216
must have D03, not with D17/D64/H08/HK4 FF8 Overhead storage slot, front center FJ1 Hinged lid for storage compartment FR8 Rear view camera (head unit display) must have C02/E3M; not with FR3/JB7; 3500XD not w FY1 Security alarm w. interior motion sensor must have LC4/C00 FY7 Optional 3-button keys FZ9 Keys, two additional masters H00 Warm/cool air duct to rear compartment not with D50/D51/Y2A H01 Heat insulation, rear compartment must have V21/V25/VA3/VA1/C07/X66 H04 Heat insulation, front compartment if + D50/D51 must have V07 H08 Air conditioning rear, roof-mounted must have D93 +V36+M61; not with HK4/C06/X66/C0 H12 Fuel-fired pre-heater/booster (17K BTU) not with HZ9 H13 Rear cabin heater and vents must have H12/HZ9 H15 Heated front passenger seat must have H16; not with X68 H22 Rear window defroster must have W61/W78; standard for W61+W70 H72 Roof fan, electric not with D22/V36 H88 Rear heater prep must have H12/HZ9; not with H13/T19 H11 Front-to-rear outlet in instrument panel	\$117 \$105 \$377 th JB8 \$654 \$41 \$136 \$66 \$175 \$209 \$3,216	\$117 \$105 \$377 \$654 \$41 \$136 \$66 \$175 \$209 \$3,216	\$117 \$105 \$377 \$654 \$41 \$136 \$66 \$175 \$209 \$3,216
FF8 Overhead storage slot, front center FJ1 Hinged lid for storage compartment FR8 Rear view camera (head unit display)  must have CO2/E3M; not with FR3/JB7; 3500XD not w FY1 Security alarm w. interior motion sensor  must have LC4/C00 FY7 Optional 3-button keys FZ9 Keys, two additional masters H00 Warm/cool air duct to rear compartment  not with D50/D51/Y2A H01 Heat insulation, rear compartment  must have V21/V25/VA3/VA1/C07/X66 H04 Heat insulation, front compartment  if + D50/D51 must have V07 H08 Air conditioning rear, roof-mounted  must have D93 +V36+M61; not with HK4/C06/X66/C0 H12 Fuel-fired pre-heater/booster (17K BTU)  not with HZ9 H13 Rear cabin heater and vents  must have H12/HZ9 H15 Heated front passenger seat  must have H16; not with X68 H22 Rear window defroster  must have W61/W78; standard for W61+W70 H72 Roof fan, electric  not with D22/V36 H88 Rear heater prep  must have H12/HZ9; not with H13/T19 H11 Front-to-rear outlet in instrument panel	\$105 \$377 \$377 \$654 \$654 \$41 \$136 \$66 \$175 \$209 \$3,216	\$105 \$377 \$654 \$41 \$136 \$66 \$175 \$209 \$3,216 \$1,249	\$105 \$377 \$654 \$41 \$136 \$66 \$175 \$209 \$3,216
FJ1 Hinged lid for storage compartment FR8 Rear view camera (head unit display)  must have CO2/E3M; not with FR3/JB7; 3500XD not w FY1 Security alarm w. interior motion sensor  must have LC4/C00 FY7 Optional 3-button keys FZ9 Keys, two additional masters H00 Warm/cool air duct to rear compartment  not with D50/D51/Y2A H01 Heat insulation, rear compartment  must have V21/V25/VA3/VA1/C07/X66 H04 Heat insulation, front compartment  if + D50/D51 must have V07 H08 Air conditioning rear, roof-mounted  must have D93 +V36+M61; not with HK4/C06/X66/C0 H12 Fuel-fired pre-heater/booster (17K BTU)  not with HZ9 H13 Rear cabin heater and vents  must have H12/HZ9 H15 Heated front passenger seat  must have H16; not with X68 H22 Rear window defroster  must have W61/W78; standard for W61+W70 H72 Roof fan, electric  not with D22/V36 H88 Rear heater prep  must have H12/HZ9; not with H13/T19 H11 Front-to-rear outlet in instrument panel	\$105 \$377 \$377 \$654 \$654 \$41 \$136 \$66 \$175 \$209 \$3,216	\$105 \$377 \$654 \$41 \$136 \$66 \$175 \$209 \$3,216 \$1,249	\$105 \$377 \$654 \$41 \$136 \$66 \$175 \$209 \$3,216
FR8 Rear view camera (head unit display)  must have CO2/E3M; not with FR3/JB7; 3500XD not w FY1 Security alarm w. interior motion sensor  must have LC4/C00 FY7 Optional 3-button keys FZ9 Keys, two additional masters H00 Warm/cool air duct to rear compartment  not with D50/D51/Y2A H01 Heat insulation, rear compartment  must have V21/V25/VA3/VA1/C07/X66 H04 Heat insulation, front compartment  if + D50/D51 must have V07 H08 Air conditioning rear, roof-mounted  must have D93 +V36+M61; not with HK4/C06/X66/C0 H12 Fuel-fired pre-heater/booster (17K BTU)  not with HZ9 H13 Rear cabin heater and vents  must have H12/HZ9 H15 Heated front passenger seat  must have H16; not with X68 H22 Rear window defroster  must have W61/W78; standard for W61+W70 H72 Roof fan, electric  not with D22/V36 H88 Rear heater prep  must have H12/HZ9; not with H13/T19 H11 Front-to-rear outlet in instrument panel	\$377  th JB8  \$654  \$41  \$136  \$66  \$175  \$209  \$3,216	\$377 \$654 \$41 \$136 \$66 \$175 \$209 \$3,216 \$1,249	\$377 \$654 \$41 \$136 \$66 \$175 \$209 \$3,216
must have CO2/E3M; not with FR3/JB7; 3500XD not with Security alarm w. interior motion sensor must have LC4/C00 FY7 Optional 3-button keys FZ9 Keys, two additional masters H00 Warm/cool air duct to rear compartment not with D50/D51/Y2A H01 Heat insulation, rear compartment must have V21/V25/VA3/VA1/C07/X66 H04 Heat insulation, front compartment if + D50/D51 must have V07 H08 Air conditioning rear, roof-mounted must have D93 +V36+M61; not with HK4/C06/X66/C0 H12 Fuel-fired pre-heater/booster (17K BTU) not with HZ9 H13 Rear cabin heater and vents must have H12/HZ9 H15 Heated front passenger seat must have H16; not with X68 H22 Rear window defroster must have W61/W78; standard for W61+W70 H72 Roof fan, electric not with D22/V36 H88 Rear heater prep must have H12/HZ9; not with H13/T19 H11 Front-to-rear outlet in instrument panel	\$654 \$41 \$136 \$136 \$66 \$175 \$209 \$3,216	\$654 \$41 \$136 \$66 \$175 \$209 \$3,216 \$1,249	\$654 \$41 \$136 \$66 \$175 \$209 \$3,216
FY1 Security alarm w. interior motion sensor  must have LC4/C00  FY7 Optional 3-button keys  FZ9 Keys, two additional masters  H00 Warm/cool air duct to rear compartment  not with D50/D51/Y2A  H01 Heat insulation, rear compartment  must have V21/V25/VA3/VA1/C07/X66  H04 Heat insulation, front compartment  if + D50/D51 must have V07  H08 Air conditioning rear, roof-mounted  must have D93 +V36+M61; not with HK4/C06/X66/C0  H12 Fuel-fired pre-heater/booster (17K BTU)  not with HZ9  H13 Rear cabin heater and vents  must have H12/HZ9  H15 Heated front passenger seat  must have H16; not with X68  H22 Rear window defroster  must have W61/W78; standard for W61+W70  H72 Roof fan, electric  not with D22/V36  H88 Rear heater prep  must have H12/HZ9; not with H13/T19  H11 Front-to-rear outlet in instrument panel	\$654 \$41 \$136 \$166 \$175 \$209 \$3,216	\$41 \$136 \$66 \$175 \$209 \$3,216 \$1,249	\$41 \$136 \$66 \$175 \$209 \$3,216 \$1,249
must have LC4/C00 FY7 Optional 3-button keys FZ9 Keys, two additional masters H00 Warm/cool air duct to rear compartment not with D50/D51/Y2A H01 Heat insulation, rear compartment must have V21/V25/VA3/VA1/C07/X66 H04 Heat insulation, front compartment if + D50/D51 must have V07 H08 Air conditioning rear, roof-mounted must have D93 +V36+M61; not with HK4/C06/X66/C0 H12 Fuel-fired pre-heater/booster (17K BTU) not with HZ9 H13 Rear cabin heater and vents must have H12/HZ9 H15 Heated front passenger seat must have H16; not with X68 H22 Rear window defroster must have W61/W78; standard for W61+W70 H72 Roof fan, electric not with D22/V36 H88 Rear heater prep must have H12/HZ9; not with H13/T19 H11 Front-to-rear outlet in instrument panel	\$41 \$136 \$66 \$175 \$209 \$3,216	\$41 \$136 \$66 \$175 \$209 \$3,216 \$1,249	\$41 \$136 \$66 \$175 \$209 \$3,216 \$1,249
FY7 Optional 3-button keys FZ9 Keys, two additional masters H00 Warm/cool air duct to rear compartment not with D50/D51/Y2A H01 Heat insulation, rear compartment must have V21/V25/VA3/VA1/C07/X66 H04 Heat insulation, front compartment if + D50/D51 must have V07 H08 Air conditioning rear, roof-mounted must have D93 +V36+M61; not with HK4/C06/X66/C0 H12 Fuel-fired pre-heater/booster (17K BTU) not with HZ9 H13 Rear cabin heater and vents must have H12/HZ9 H15 Heated front passenger seat must have H16; not with X68 H22 Rear window defroster must have W61/W78; standard for W61+W70 H72 Roof fan, electric not with D22/V36 H88 Rear heater prep must have H12/HZ9; not with H13/T19 H11 Front-to-rear outlet in instrument panel	\$136 \$66 \$175 \$209 \$3,216	\$136 \$66 \$175 \$209 \$3,216 \$1,249	\$136 \$66 \$175 \$209 \$3,216 \$1,249
FZ9 Keys, two additional masters H00 Warm/cool air duct to rear compartment not with D50/D51/Y2A H01 Heat insulation, rear compartment must have V21/V25/VA3/VA1/C07/X66 H04 Heat insulation, front compartment if + D50/D51 must have V07 H08 Air conditioning rear, roof-mounted must have D93 + V36+M61; not with HK4/C06/X66/C0 H12 Fuel-fired pre-heater/booster (17K BTU) not with HZ9 H13 Rear cabin heater and vents must have H12/HZ9 H15 Heated front passenger seat must have H16; not with X68 H22 Rear window defroster must have W61/W78; standard for W61+W70 H72 Roof fan, electric not with D22/V36 H88 Rear heater prep must have H12/HZ9; not with H13/T19 H11 Front-to-rear outlet in instrument panel	\$136 \$66 \$175 \$209 \$3,216	\$136 \$66 \$175 \$209 \$3,216 \$1,249	\$136 \$66 \$175 \$209 \$3,216 \$1,249
H00 Warm/cool air duct to rear compartment  not with D50/D51/Y2A  H01 Heat insulation, rear compartment  must have V21/V25/VA3/VA1/C07/X66  H04 Heat insulation, front compartment  if + D50/D51 must have V07  H08 Air conditioning rear, roof-mounted  must have D93 + V36+M61; not with HK4/C06/X66/C0  H12 Fuel-fired pre-heater/booster (17K BTU)  not with HZ9  H13 Rear cabin heater and vents  must have H12/HZ9  H15 Heated front passenger seat  must have H16; not with X68  H22 Rear window defroster  must have W61/W78; standard for W61+W70  H72 Roof fan, electric  not with D22/V36  H88 Rear heater prep  must have H12/HZ9; not with H13/T19  H11 Front-to-rear outlet in instrument panel	\$66 \$175 \$209 \$3,216	\$66 \$175 \$209 \$3,216 \$1,249	\$66 \$175 \$209 \$3,216 \$1,249
not with D50/D51/Y2A  H01 Heat insulation, rear compartment  must have V21/V25/VA3/VA1/C07/X66  H04 Heat insulation, front compartment  if + D50/D51 must have V07  H08 Air conditioning rear, roof-mounted  must have D93 + V36+M61; not with HK4/C06/X66/C0  H12 Fuel-fired pre-heater/booster (17K BTU)  not with HZ9  H13 Rear cabin heater and vents  must have H12/HZ9  H15 Heated front passenger seat  must have H16; not with X68  H22 Rear window defroster  must have W61/W78; standard for W61+W70  H72 Roof fan, electric  not with D22/V36  H88 Rear heater prep  must have H12/HZ9; not with H13/T19  H11 Front-to-rear outlet in instrument panel	\$175 \$209 \$3,216 7	\$175 \$209 \$3,216 \$1,249	\$175 \$209 \$3,216 \$1,249
H01 Heat insulation, rear compartment  must have V21/V25/VA3/VA1/C07/X66  H04 Heat insulation, front compartment  if + D50/D51 must have V07  H08 Air conditioning rear, roof-mounted  must have D93 +V36+M61; not with HK4/C06/X66/C0  H12 Fuel-fired pre-heater/booster (17K BTU)  not with HZ9  H13 Rear cabin heater and vents  must have H12/HZ9  H15 Heated front passenger seat  must have H16; not with X68  H22 Rear window defroster  must have W61/W78; standard for W61+W70  H72 Roof fan, electric  not with D22/V36  H88 Rear heater prep  must have H12/HZ9; not with H13/T19  H11 Front-to-rear outlet in instrument panel	\$209 \$3,216 \$1,249	\$209 \$3,216 \$1,249	\$209 \$3,216 \$1,249
must have V21/V25/VA3/VA1/C07/X66  H04 Heat insulation, front compartment  if + D50/D51 must have V07  H08 Air conditioning rear, roof-mounted  must have D93 +V36+M61; not with HK4/C06/X66/C0  H12 Fuel-fired pre-heater/booster (17K BTU)  not with HZ9  H13 Rear cabin heater and vents  must have H12/HZ9  H15 Heated front passenger seat  must have H16; not with X68  H22 Rear window defroster  must have W61/W78; standard for W61+W70  H72 Roof fan, electric  not with D22/V36  H88 Rear heater prep  must have H12/HZ9; not with H13/T19  H11 Front-to-rear outlet in instrument panel	\$209 \$3,216 \$1,249	\$209 \$3,216 \$1,249	\$209 \$3,216 \$1,249
H04 Heat insulation, front compartment  if + D50/D51 must have V07  H08 Air conditioning rear, roof-mounted  must have D93 +V36+M61; not with HK4/C06/X66/C0  H12 Fuel-fired pre-heater/booster (17K BTU)  not with HZ9  H13 Rear cabin heater and vents  must have H12/HZ9  H15 Heated front passenger seat  must have H16; not with X68  H22 Rear window defroster  must have W61/W78; standard for W61+W70  H72 Roof fan, electric  not with D22/V36  H88 Rear heater prep  must have H12/HZ9; not with H13/T19  H11 Front-to-rear outlet in instrument panel	\$3,216	\$3,216	\$3,216
if + D50/D51 must have V07  H08 Air conditioning rear, roof-mounted  must have D93 +V36+M61; not with HK4/C06/X66/C0  H12 Fuel-fired pre-heater/booster (17K BTU)  not with HZ9  H13 Rear cabin heater and vents  must have H12/HZ9  H15 Heated front passenger seat  must have H16; not with X68  H22 Rear window defroster  must have W61/W78; standard for W61+W70  H72 Roof fan, electric  not with D22/V36  H88 Rear heater prep  must have H12/HZ9; not with H13/T19  H11 Front-to-rear outlet in instrument panel	\$3,216	\$3,216	\$3,216
H08 Air conditioning rear, roof-mounted  must have D93 +V36+M61; not with HK4/C06/X66/C0 H12 Fuel-fired pre-heater/booster (17K BTU)  not with HZ9 H13 Rear cabin heater and vents  must have H12/HZ9 H15 Heated front passenger seat  must have H16; not with X68 H22 Rear window defroster  must have W61/W78; standard for W61+W70 H72 Roof fan, electric  not with D22/V36 H88 Rear heater prep  must have H12/HZ9; not with H13/T19 H11 Front-to-rear outlet in instrument panel	\$1,249	\$1,249	\$1,249
must have D93 +V36+M61; not with HK4/C06/X66/C0 H12 Fuel-fired pre-heater/booster (17K BTU) not with HZ9 H13 Rear cabin heater and vents must have H12/HZ9 H15 Heated front passenger seat must have H16; not with X68 H22 Rear window defroster must have W61/W78; standard for W61+W70 H72 Roof fan, electric not with D22/V36 H88 Rear heater prep must have H12/HZ9; not with H13/T19 H11 Front-to-rear outlet in instrument panel	\$1,249	\$1,249	\$1,249
H12 Fuel-fired pre-heater/booster (17K BTU)  not with HZ9 H13 Rear cabin heater and vents  must have H12/HZ9 H15 Heated front passenger seat  must have H16; not with X68 H22 Rear window defroster  must have W61/W78; standard for W61+W70 H72 Roof fan, electric  not with D22/V36 H88 Rear heater prep  must have H12/HZ9; not with H13/T19 H11 Front-to-rear outlet in instrument panel	\$1,249	<del>'</del>	
not with HZ9 H13 Rear cabin heater and vents  must have H12/HZ9 H15 Heated front passenger seat  must have H16; not with X68 H22 Rear window defroster  must have W61/W78; standard for W61+W70 H72 Roof fan, electric  not with D22/V36 H88 Rear heater prep  must have H12/HZ9; not with H13/T19 H11 Front-to-rear outlet in instrument panel		<del>'</del>	
H13 Rear cabin heater and vents  must have H12/H29  H15 Heated front passenger seat  must have H16; not with X68  H22 Rear window defroster  must have W61/W78; standard for W61+W70  H72 Roof fan, electric  not with D22/V36  H88 Rear heater prep  must have H12/HZ9; not with H13/T19  H11 Front-to-rear outlet in instrument panel	\$880	\$880	ร่อยก
must have H12/HZ9 H15 Heated front passenger seat  must have H16; not with X68 H22 Rear window defroster  must have W61/W78; standard for W61+W70 H72 Roof fan, electric  not with D22/V36 H88 Rear heater prep  must have H12/HZ9; not with H13/T19 H11 Front-to-rear outlet in instrument panel	\$880	\$880	\$880
H15 Heated front passenger seat  must have H16; not with X68  H22 Rear window defroster  must have W61/W78; standard for W61+W70  H72 Roof fan, electric  not with D22/V36  H88 Rear heater prep  must have H12/HZ9; not with H13/T19  H11 Front-to-rear outlet in instrument panel	·		7000
must have H16; not with X68  H22 Rear window defroster  must have W61/W78; standard for W61+W70  H72 Roof fan, electric  not with D22/V36  H88 Rear heater prep  must have H12/HZ9; not with H13/T19  H11 Front-to-rear outlet in instrument panel			
H22 Rear window defroster  must have W61/W78; standard for W61+W70 H72 Roof fan, electric  not with D22/V36 H88 Rear heater prep  must have H12/HZ9; not with H13/T19 H11 Front-to-rear outlet in instrument panel	\$318	\$318	\$318
must have W61/W78; standard for W61+W70 H72 Roof fan, electric not with D22/V36 H88 Rear heater prep must have H12/HZ9; not with H13/T19 H11 Front-to-rear outlet in instrument panel		•	
H72 Roof fan, electric  not with D22/V36  H88 Rear heater prep  must have H12/HZ9; not with H13/T19  H11 Front-to-rear outlet in instrument panel	\$283	\$283	\$283
not with D22/V36  H88 Rear heater prep  must have H12/HZ9; not with H13/T19  H11 Front-to-rear outlet in instrument panel	•	•	
H88 Rear heater prep  must have H12/HZ9; not with H13/T19  H11 Front-to-rear outlet in instrument panel	\$448	\$448	\$448
must have H12/HZ9; not with H13/T19 H11 Front-to-rear outlet in instrument panel		•	
H1I Front-to-rear outlet in instrument panel	\$453	\$453	\$453
		•	
must have FJ1/C01	\$0	\$0	\$0
		•	
HH4 Thermotronic automatic climate control	\$378	\$378	\$378
must have JF1; if +H13 must have H08/HK4	•	•	
HK4 Rear air conditioner, heavyduty	\$4,411	\$4,411	\$4,411
must have D03+V36+D93; not with H08/ZB6/ZE6/N62	N63	•	•
HZ9 Fuel-fired heater booster (18,000 BTU)	\$756	\$756	\$756
not with H12	•	•	•
J51 Fuel gauge, optimized for aux. fuel tap	\$80	\$80	\$80
not with HZ9/H12			
J52 Engine oil level display at cold start		\$0	\$0
JA7 Blind Spot Assist	\$0		\$504
must have F64	\$0 \$504	\$504	
JB4 Active Lane Keeping Assist		\$504	
standard with CO2/CA2		\$504	\$322

must h  JF1 Rain se  JW0 Backup  JW2 Deacti  JW8 Attent  K51 Misfue  K52 DEF flu  L13 Fog lan  L71 Light/n  not wi  LB9 Illumir  LC2 LED lig  not wi  LC4 Comfo  M20 Speed  not wi  M61 Altern  MD3 Top sp  not wi  N62 Front e  not wi	o alarm vation lamp monitoring failure ion Assist  ling prevention for Diesel id filler cap - lockable inp with cornering light function motion sensor in rear compartment th V36 lated front exits ht strip in load compartment th H08/HK4/V36/C06 rt overhead control panel limitation 65 mph th MD3 actor 14 V / 280 A leed limitation 75 mph th M20 lengine bracket for additional alternator	144" 4D High  M4CA4H  907.653  \$688  \$118  \$111  \$30  \$55  \$55  \$30  \$223  \$61  \$170  \$294  \$105  \$67	\$170" 4D High  M4CA7H  907.655  \$688  \$118  \$111  \$30  \$55  \$55  \$30  \$223  \$61  \$170  \$294  \$105  \$67	\$118 \$111 \$30 \$55 \$55 \$55 \$30 \$223 \$61 \$170 \$294 \$105 \$67
must h  JF1 Rain se  JW0 Backup  JW2 Deacti  JW8 Attent  K51 Misfue  K52 DEF flu  L13 Fog lan  L71 Light/n  not wi  LB9 Illumir  LC2 LED lig  not wi  LC4 Comfo  M20 Speed  not wi  M61 Altern  MD3 Top sp  not wi  N62 Front e  not wi	ave CO2/CO3/E3M; not with W75/W76/JB6 ensor o alarm vation lamp monitoring failure ion Assist ling prevention for Diesel uid filler cap - lockable mp with cornering light function motion sensor in rear compartment th V36 tated front exits ht strip in load compartment th HO8/HK4/V36/CO6 rt overhead control panel limitation 65 mph th MD3 ator 14 V / 280 A eed limitation 75 mph th M20 engine bracket for additional alternator	\$688 \$118 \$111 \$30 \$55 \$55 \$30 \$223 \$61 \$170 \$294 \$105 \$67	\$688 \$118 \$111 \$30 \$55 \$55 \$30 \$223 \$61 \$170 \$294 \$105 \$67	\$688 \$118 \$111 \$30 \$55 \$55 \$30 \$223 \$61 \$170 \$294 \$105 \$67
must h  JF1 Rain se  JW0 Backup  JW2 Deacti  JW8 Attent  K51 Misfue  K52 DEF flu  L13 Fog lan  L71 Light/n  not wi  LB9 Illumir  LC2 LED lig  not wi  LC4 Comfo  M20 Speed  not wi  M61 Altern  MD3 Top sp  not wi  N62 Front e  not wi	ave CO2/CO3/E3M; not with W75/W76/JB6 ensor o alarm vation lamp monitoring failure ion Assist ling prevention for Diesel uid filler cap - lockable mp with cornering light function motion sensor in rear compartment th V36 tated front exits ht strip in load compartment th HO8/HK4/V36/CO6 rt overhead control panel limitation 65 mph th MD3 ator 14 V / 280 A eed limitation 75 mph th M20 engine bracket for additional alternator	\$118 \$111 \$30 \$55 \$55 \$55 \$30 \$223 \$61 \$170 \$294 \$105 \$67	\$118 \$111 \$30 \$55 \$55 \$30 \$223 \$61 \$170 \$294 \$105 \$67	\$118 \$111 \$30 \$55 \$55 \$30 \$223 \$61 \$170 \$294 \$105 \$67
must h  JF1 Rain se JW0 Backup JW2 Deacti JW8 Attent K51 Misfue K52 DEF flu L13 Fog lan L71 Light/n not wi LB9 Illumir LC2 LED lig not wi LC4 Comfo M20 Speed not wi M61 Altern MD3 Top sp not wi N62 Front e not wi	ave CO2/CO3/E3M; not with W75/W76/JB6 ensor o alarm vation lamp monitoring failure ion Assist ling prevention for Diesel uid filler cap - lockable mp with cornering light function motion sensor in rear compartment th V36 tated front exits ht strip in load compartment th HO8/HK4/V36/CO6 rt overhead control panel limitation 65 mph th MD3 ator 14 V / 280 A eed limitation 75 mph th M20 engine bracket for additional alternator	\$118 \$111 \$30 \$55 \$55 \$55 \$30 \$223 \$61 \$170 \$294 \$105 \$67	\$118 \$111 \$30 \$55 \$55 \$30 \$223 \$61 \$170 \$294 \$105 \$67	\$118 \$111 \$30 \$55 \$55 \$30 \$223 \$61 \$170 \$294 \$105 \$67
JF1 Rain se JW0 Backul JW2 Deacti JW8 Attent K51 Misfue K52 DEF flu L13 Fog lan L71 Light/r not wi LB9 Illumir LC2 LED lig not wi LC4 Comfo M20 Speed not wi M61 Altern MD3 Top sp not wi N62 Front e not wi	ensor o alarm vation lamp monitoring failure ion Assist ling prevention for Diesel uid filler cap - lockable inp with cornering light function motion sensor in rear compartment th V36 lated front exits ht strip in load compartment th H08/HK4/V36/C06 rt overhead control panel limitation 65 mph th MD3 ator 14 V / 280 A leed limitation 75 mph th M20 lengine bracket for additional alternator	\$111 \$30 \$55 \$55 \$55 \$30 \$223 \$61 \$170 \$294 \$105 \$67	\$111 \$30 \$55 \$55 \$55 \$30 \$223 \$61 \$170 \$294 \$105 \$67	\$111 \$30 \$55 \$55 \$30 \$223 \$61 \$170 \$294 \$105 \$67
JWO Backur JW2 Deacti JW8 Attent K51 Misfue K52 DEF flu L13 Fog lar L71 Light/r not wi LB9 Illumir LC2 LED lig not wi LC4 Comfo M20 Speed not wi M61 Altern MD3 Top sp not wi N62 Front e	o alarm vation lamp monitoring failure ion Assist  ling prevention for Diesel id filler cap - lockable inp with cornering light function motion sensor in rear compartment th V36 lated front exits ht strip in load compartment th H08/HK4/V36/C06 rt overhead control panel limitation 65 mph th MD3 actor 14 V / 280 A leed limitation 75 mph th M20 lengine bracket for additional alternator	\$111 \$30 \$55 \$55 \$55 \$30 \$223 \$61 \$170 \$294 \$105 \$67	\$111 \$30 \$55 \$55 \$55 \$30 \$223 \$61 \$170 \$294 \$105 \$67	\$111 \$30 \$55 \$55 \$30 \$223 \$61 \$170 \$294 \$105 \$67
JW2 Deacti JW8 Attent K51 Misfue K52 DEF flu L13 Fog lar L71 Light/r not wi LB9 Illumir LC2 LED lig not wi LC4 Comfo M20 Speed not wi M61 Altern MD3 Top sp not wi N62 Front e not wi	vation lamp monitoring failure ion Assist  ling prevention for Diesel aid filler cap - lockable mp with cornering light function motion sensor in rear compartment th V36 lated front exits ht strip in load compartment th H08/HK4/V36/C06 rt overhead control panel limitation 65 mph th MD3 ator 14 V / 280 A leed limitation 75 mph th M20 lengine bracket for additional alternator	\$30 \$55 \$55 \$30 \$223 \$61 \$170 \$294 \$105 \$67	\$30 \$55 \$55 \$30 \$223 \$61 \$170 \$294 \$105 \$67	\$30 \$55 \$55 \$30 \$223 \$61 \$170 \$294 \$105 \$67
JW8 Attent K51 Misfue K52 DEF flu L13 Fog lan L71 Light/r not wi LB9 Illumir LC2 LED lig not wi LC4 Comfo M20 Speed not wi M61 Altern MD3 Top sp not wi N62 Front e not wi	ion Assist  Iling prevention for Diesel  Iding prevention for Diesel  Indig filler cap - lockable Inp with cornering light function Indion sensor in rear compartment  Ith V36  Indied front exits Indied f	\$55 \$55 \$30 \$223 \$61 \$170 \$294 \$105 \$67	\$55 \$55 \$30 \$223 \$61 \$170 \$294 \$105 \$67	\$55 \$55 \$30 \$223 \$61 \$170 \$294 \$105 \$67
K51 Misfue K52 DEF flu L13 Fog lan L71 Light/r not wi LB9 Illumir LC2 LED lig not wi LC4 Comfo M20 Speed not wi M61 Altern MD3 Top sp not wi N62 Front e not wi	ling prevention for Diesel  id filler cap - lockable  mp with cornering light function  motion sensor in rear compartment  th V36  lated front exits  ht strip in load compartment  th H08/HK4/V36/C06  rt overhead control panel  limitation 65 mph  th MD3  ator 14 V / 280 A  eed limitation 75 mph  th M20  engine bracket for additional alternator	\$55 \$30 \$223 \$61 \$170 \$294 \$105 \$67	\$55 \$30 \$223 \$61 \$170 \$294 \$105 \$67	\$55 \$30 \$223 \$61 \$170 \$294 \$105 \$67
K52 DEF flu L13 Fog lan L71 Light/n not wi LB9 Illumir LC2 LED lig not wi LC4 Comfo M20 Speed not wi M61 Altern MD3 Top sp not wi N62 Front c not wi	init filler cap - lockable inp with cornering light function motion sensor in rear compartment th V36 lated front exits ht strip in load compartment th H08/HK4/V36/C06 rt overhead control panel limitation 65 mph th MD3 later 14 V / 280 A leed limitation 75 mph th M20 lengine bracket for additional alternator	\$30 \$223 \$61 \$170 \$294 \$105 \$67 \$188 \$	\$30 \$223 \$61 \$170 \$294 \$105 \$67	\$30 \$223 \$61 \$170 \$294 \$105 \$67
L13 Fog lan L71 Light/r not wi LB9 Illumir LC2 LED lig not wi LC4 Comfo M20 Speed not wi M61 Altern MD3 Top sp not wi N62 Front of not wi	np with cornering light function notion sensor in rear compartment th V36 sated front exits ht strip in load compartment th H08/HK4/V36/C06 rt overhead control panel limitation 65 mph th MD3 sator 14 V / 280 A eed limitation 75 mph th M20 engine bracket for additional alternator	\$223 \$61 \$170 \$294 \$105 \$67 \$188 \$	\$223 \$61 \$170 \$294 \$105 \$67	\$223 \$61 \$170 \$294 \$105 \$67
L71 Light/r not wi LB9 Illumir LC2 LED lig not wi LC4 Comfo M20 Speed not wi M61 Altern. MD3 Top sp not wi N62 Front o not wi	notion sensor in rear compartment th V36 lated front exits ht strip in load compartment th H08/HK4/V36/C06 rt overhead control panel limitation 65 mph th MD3 later 14 V / 280 A leed limitation 75 mph th M20 lengine bracket for additional alternator	\$61 \$170 \$294 \$105 \$67 \$188 \$	\$61 \$170 \$294 \$105 \$67	\$61 \$170 \$294 \$105 \$67 \$188
not wi LB9 Illumir LC2 LED lig not wi LC4 Comfo M20 Speed not wi M61 Altern MD3 Top sp not wi N62 Front o not wi	th V36 nated front exits ht strip in load compartment th H08/HK4/V36/C06 rt overhead control panel limitation 65 mph th MD3 ator 14 V / 280 A eed limitation 75 mph th M20 engine bracket for additional alternator	\$170 \$294 \$105 \$67 \$188 \$	\$170 \$294 \$105 \$67	\$170 \$294 \$105 \$67 \$188
LB9 Illumir LC2 LED lig not wi LC4 Comfo M20 Speed not wi M61 Altern MD3 Top sp not wi N62 Front o not wi	ht strip in load compartment th H08/HK4/V36/C06 rt overhead control panel limitation 65 mph th MD3 ator 14 V / 280 A eed limitation 75 mph th M20 engine bracket for additional alternator	\$294 \$105 \$67 \$188 \$	\$294 \$105 \$67 \$188	\$294 \$105 \$67 \$188
LC2 LED lig not wi LC4 Comfo M20 Speed not wi M61 Altern MD3 Top sp not wi N62 Front e not wi	ht strip in load compartment th HO8/HK4/V36/C06 rt overhead control panel limitation 65 mph th MD3 ator 14 V / 280 A eed limitation 75 mph th M20 engine bracket for additional alternator	\$294 \$105 \$67 \$188 \$	\$294 \$105 \$67 \$188	\$294 \$105 \$67 \$188
not wi LC4 Comfo M20 Speed not wi M61 Altern MD3 Top sp not wi N62 Front e not wi	th HO8/HK4/V36/C06  rt overhead control panel limitation 65 mph th MD3 ator 14 V / 280 A eed limitation 75 mph th M20 engine bracket for additional alternator	\$105 \$67 \$188 \$	\$105 \$67 \$188	\$105 \$67 \$188
LC4 Comfo M20 Speed not wi M61 Altern MD3 Top sp not wi N62 Front e not wi	rt overhead control panel limitation 65 mph th MD3 ator 14 V / 280 A eed limitation 75 mph th M20 engine bracket for additional alternator	\$67 \$188 \$	\$67 \$188	\$67 \$188
M20 Speed not wi M61 Altern MD3 Top sp not wi N62 Front of not wi	limitation 65 mph th MD3 ator 14 V / 280 A eed limitation 75 mph th M20 engine bracket for additional alternator	\$67 \$188 \$	\$67 \$188	\$67 \$188
M61 Altern MD3 Top sp not wi N62 Front of not wi	th MD3 ator 14 V / 280 A eed limitation 75 mph th M20 engine bracket for additional alternator	\$188 S	\$188	\$188
M61 Altern MD3 Top sp not wi N62 Front of not wi	ator 14 V / 280 A eed limitation 75 mph th M20 engine bracket for additional alternator	S		
MD3 Top sp not wi N62 Front e not wi	eed limitation 75 mph th M20 engine bracket for additional alternator	S		
not wi	th M20 engine bracket for additional alternator	-	7/1	7/1
N62 Front of not wi	engine bracket for additional alternator	\$523		
not wi	-	<b>4323</b>	\$523	\$523
			<b>7323</b>	<b>4323</b>
	engine bracket for auxiliary A/C compressor	\$523	\$523	\$523
<del>                                     </del>	th HK4/N62	Ų323	<b></b> <del>7</del> 323	<b>7323</b>
	on of D-rings	-\$15	-\$15	-\$15
<del>                                     </del>	th D93/V43/VK8	<b>V</b> 25	<b>425</b>	<b>V</b> 25
	cross member 7,500 lbs capacity	\$208	\$208	_
	th W73/W75/W76/Q24/Q67	Ψ200	Ψ200	
	ded step rear (for trailer hitch)	\$113	\$113	\$113
	ave QA2; not with W73/W75/W76	<b>V</b> 110	Ψ110	¥220
<del>                                     </del>	hitch, 5,000 lbs	-	-	-
	th W73/W75/W76			
<b>-</b>	tire deletion	-\$110	-\$110	-\$110
<del> </del>	ave R92; not with R87	7	7220	7-2-0
	tire carrier deletion	\$0	\$0	\$0
	ave R91; not with R65	7-	7-	7.0
	ainted jet black	\$91	\$91	\$91
_	th RL5/RM2	. , , ,	, -	1.5
	and Continental	\$0	\$0	\$0
	ave RM1 + RM9	, -	, -	, ,
	and Michelin	\$0	\$0	\$0
-	ave RM9; not with RM1	, -	, -	, ,
	and Kumho	\$0	\$0	\$0
must h	ave RM9; not with RM1			
<del>                                     </del>	inter tires	\$190	\$190	\$190
	ave RF1/RD9; not with RF8/RH0/X31	,		
	ainted arctic white	\$91	\$91	\$91
	th R98/RL5			
	lly requested tires	\$113	\$113	\$113
h	ave RF1/RF8/RH0; not with RD9			
h + + + + + + + + + + + + + + + + + + +	ont passenger seat	\$448	\$448	\$448
	th C00/X68/X01			•

MACAHH   MACATH   MACATH   MACATH   MOTOSTS			144" 4D High	170" 4D High	170" E 4D High
S28			М4СА4Н	М4СА7Н	M4CAEH
Seat belts orange, driver and front passenger			907.653	907.655	907.657
Not with \$23   S267   \$267   \$267   \$267   \$267   must have WF2; not with COO/X68/X69   S27   Storage net, driver's seat backrest   \$71   \$71   \$71   \$71   \$71   \$71   \$72   S10   S10	S28	Armrest, driver and passenger door	\$58	\$58	\$58
Separate	S62	Seat belts orange, driver and front passenger	\$36	\$36	\$36
must have VF7; not with C00/K68/K69           \$27         Storage net, driver's seat backrest         \$71         \$71         \$71           \$28         Storage net, passenger seat backrest         \$71         \$71         \$71           \$112         Silding door two stage opening         \$92         \$92         \$92           \$12         Silding door two stage opening         \$93         \$930         \$930           \$15         Electric closing assist right sliding door         \$376         \$376         \$376           \$15         Electric sliding step         \$930         \$930         \$930           \$15         Electric sliding step         \$1,199         \$1,199         \$1,199           \$17         Electric sliding step         \$1,199         \$1,199         \$1,199           \$17         Electric sliding step         \$1,199         \$1,199         \$1,199           \$17         Passid sliding door right         \$930         \$930         \$930           \$17         Passid sliding door with \$73         \$1,199         \$1,199         \$1,199           \$17         Passid shade electrically operated sliding door         \$1,34         \$1,34         \$1,34           \$17         Assist handle, Brilliar         \$36         \$36 </td <td></td> <td>not with S23</td> <td>1</td> <td></td> <td></td>		not with S23	1		
must have VF7; not with C00/K68/K69           \$27         Storage net, driver's seat backrest         \$71         \$71         \$71           \$28         Storage net, passenger seat backrest         \$71         \$71         \$71           \$112         Silding door two stage opening         \$92         \$92         \$92           \$12         Silding door two stage opening         \$93         \$930         \$930           \$15         Electric closing assist right sliding door         \$376         \$376         \$376           \$15         Electric sliding step         \$930         \$930         \$930           \$15         Electric sliding step         \$1,199         \$1,199         \$1,199           \$17         Electric sliding step         \$1,199         \$1,199         \$1,199           \$17         Electric sliding step         \$1,199         \$1,199         \$1,199           \$17         Passid sliding door right         \$930         \$930         \$930           \$17         Passid sliding door with \$73         \$1,199         \$1,199         \$1,199           \$17         Passid shade electrically operated sliding door         \$1,34         \$1,34         \$1,34           \$17         Assist handle, Brilliar         \$36         \$36 </td <td>SB9</td> <td></td> <td>\$267</td> <td>\$267</td> <td>\$267</td>	SB9		\$267	\$267	\$267
Storage net, driver's seat backrest		·	· ·		,
Storage net, passenger seat backrest	SZ7		\$71	\$71	\$71
Silding door two stage opening	SZ8		\$71	\$71	\$71
	T12		\$92	\$92	\$92
### ### ### ### ### ### ### ### ### ##			<u>'</u>	,	,
### ### ### ### ### ### ### ### ### ##	T50	Electric closing assist right sliding door	\$376	\$376	\$376
TS5   Electric sliding door right   S930   S930   S930   S930   must have D03 + (FY7+T16); not with T12/T50   S1,199   S1,199   S1,199   S1,199   must have ED5; not with T93   TS7   Electric sliding step   S1,199   S1,199   S1,199   must have ED5; not with T93   TS7   S117			1 - 1 - 1	,	,
### ### ### ### ### ### ### ### ### ##	T55		\$930	\$930	\$930
T57   Electric sliding step			·		,
must have ED5; not with T93         Must have ED5; not with T93           T60 Opening limiter electrically operated sliding door         \$134         \$134         \$134           must have T55         \$36         \$36         \$36           T74         Assist handle, B-pillar         \$36         \$36         \$36           must have D93; not with T77         \$36         \$36         \$36         \$36         \$36         \$36         \$36         \$36         \$36         \$36         \$36         \$36         \$36         \$36         \$36         \$36         \$36         \$36         \$36         \$36         \$36         \$36         \$36         \$36         \$36         \$36         \$36         \$36         \$36         \$36         \$36         \$36         \$36         \$36         \$36         \$36         \$36         \$36         \$36         \$36         \$36         \$36         \$36         \$36         \$36         \$36         \$36         \$36         \$36         \$36         \$36         \$36         \$36         \$36         \$36         \$36         \$36         \$36         \$36         \$36         \$36         \$36         \$36         \$36         \$36         \$36         \$36         \$36         \$36         \$36 <td>T57</td> <td></td> <td>\$1,199</td> <td>\$1,199</td> <td>\$1,199</td>	T57		\$1,199	\$1,199	\$1,199
Tool   Opening limiter electrically operated sliding door   S134   S134   S134   must have T55		<u> </u>			, ,
must have 755         336         \$36         \$36           must have D93; not with 777         500-mounted assist handles, driver & passenger         \$66         \$66         \$66           777         Assist handle w/ partition         \$36         \$36         \$36           777         Assist handle w/ partition         \$36         \$36         \$36           778         Assist handle, left rear door         \$36         \$36         \$36           785         Assist handles, right rear door         \$36         \$36         \$36           780         Assist handles, right rear door         \$36         \$36         \$36           783         Sliding door right side deletion         \$0         \$0         \$0           793         Sliding door right side deletion         \$0         \$0         \$0           796         Assist handles, right rear door         \$403         \$403         \$403           791         Start with trip of the side deletion         \$0         \$0         \$0           792         Start with 716/T50/T57/YK8/YCS         \$0         \$0         \$0           793         Sliding door right side deletion         \$0         \$0         \$0           794         Start with 716/T50/T50/T57/YK8/YCS	T60	·	\$134	\$134	\$134
T74			· ·		,
must have D93, not with T77           T75         Door-mounted assist handles, driver & passenger         \$66         \$66         \$66           T77         Assist handle w/ partition         \$36         \$36         \$36           must have D50/D51/D64         \$36         \$36         \$36         \$36           T85         Assist handle, left rear door         \$36         \$36         \$36         \$36           T86         Assist handles, right rear door         \$36         \$36         \$36         \$36           T83         Sliding door right side deletion         \$0         \$0         \$0         \$0           not with T16/T50/T57/K8/VC5         not with T16/T50/T57/VK8/VC5         \$403         \$403         \$403           700         Cab rear wall liner         \$403         \$403         \$403           800         must have (D50/D51)F1K; standard with H04         \$740         \$740         \$740           801         Must have V35/VA7; not with V52/VA1/VA3         \$108         \$108         \$108           802         Pallet suprot in sliding door step         \$108         \$108         \$108           803         \$403         \$403         \$403         \$403           804         \$10         \$108	T74		\$36	\$36	\$36
175         Door-mounted assist handles, driver & passenger         \$66         \$66         \$66           177         Assist handle w/ partition         \$36         \$36         \$36           178         Assist handle, left rear door         \$36         \$36         \$36           186         Assist handles, right rear door         \$36         \$36         \$36           179         Sliding door right side deletion         \$0         \$0         \$0           170         not with 716/750/757/VK8/VC5              170         Cab rear wall liner         \$403         \$403         \$403           170         Cab rear wall liner         \$403         \$403         \$403           170         Cab rear wall liner         \$403         \$403         \$403           170         Assist handles, right rear door         \$403         \$403         \$403           170         Assist handles, right rear door         \$403         \$403         \$403           170         Assist handles, right rear door         \$403         \$403         \$403           170         Assist handles, right rear door         \$403         \$403         \$403           170         Assist handles, right rear door		•	,	,	,
177       Assist handle w/ partition       \$36       \$36       \$36         must have D50/D51/D64       \$36       \$36       \$36       \$36         185       Assist handle, left rear door       \$36       \$36       \$36       \$36         186       Assist handles, right rear door       \$36       \$36       \$36       \$36         179       Sliding door right side deletion       \$0       \$0       \$0       \$0         not with T16/T50/T57/VK8/VC5       not with T16/T50/T57/VK8/VC5       \$403       \$403       \$403         W07       Cab rear wall liner       \$403       \$403       \$403         must have (D50/D51)+F1K; standard with H04       \$740       \$740       \$740         wust have (V35/V67; not with V52/VA1/VA3       \$740       \$740       \$740         must have V35/VA7; not with V52/VA1/VA3       \$108       \$108       \$108         wust have (V43/X66)+(D50/D51); not with VK8/V93/C07       \$225       \$225       \$225         V25       Half height load compartment trim       \$225       \$225       \$225         wid with V41/VA3/VA5/V52/X66       \$310       \$574       \$574         wid with V36 / V25 / V40 / V41 / V41 + (F02/F03/F07); not with V42       \$257       \$574       \$574	T75	·	\$66	\$66	\$66
must have D50/D51/D64           T85         Assist handle, left rear door         \$36         \$36         \$36           T86         Assist handles, right rear door         \$36         \$36         \$36           T89         Sliding door right side deletion         \$0         \$0         \$0           90         xot with T16/T50/T57/VK8/VC5         \$0         \$0         \$0           V07         Cab rear wall liner         \$403         \$403         \$403           must have (D50/D51)+F1K; standard with H04         \$740         \$740         \$740           V21         Luxury interior Trim         \$740         \$740         \$740           must have VA5/VA7; not with V52/VA1/VA3         \$108         \$108         \$108           Must have V45/VA7; not with V52/VA1/VA3         \$108         \$108         \$108           Must have (V43/X66)+(D50/D51); not with VK8/V93/C07         \$25         \$225         \$225         \$225           V25         Half height load compartment trim         \$225         \$225         \$225           V21         Window pillal trim         \$574         \$574         \$574           Must have V36 + (V21/VA1) + (F02/F03/F07); not with V42         \$25         \$225         \$225           V35		, , , ,	· ·		
T85       Assist handle, left rear door       \$36       \$36       \$36         T86       Assist handles, right rear door       \$36       \$36       \$36         T93       Sliding door right side deletion       \$0       \$0       \$0         NOT       Cab rear wall liner       \$403       \$403       \$403         Ward Hove (D50/D51)+F1K; standard with H04       \$740       \$740       \$740         V21       Luxury interior Trim       \$740       \$740       \$740         Must have VA5/VA7; not with V52/VA1/VA3       \$108       \$108       \$108         W24       Pallet support in sliding door step       \$108       \$108       \$108         Must have V43/X66)+(D50/D51); not with VK8/V93/C07       \$225       \$225       \$225       \$225       \$225       \$225       \$225       \$225       \$225       \$225       \$225       \$225       \$225       \$225       \$225       \$225       \$225       \$225       \$225       \$225       \$225       \$225       \$225       \$225       \$225       \$225       \$225       \$225       \$225       \$225       \$225       \$225       \$225       \$225       \$225       \$225       \$225       \$225       \$225       \$225       \$225       \$225			,	,	,
T86       Assist handles, right rear door       \$36       \$36       \$36         T93       Sliding door right side deletion       \$0       \$0         not with T16/T50/T57/VK8/VC5       \$403       \$403       \$403         V07       Cab rear wall liner       \$403       \$403       \$403         must have (D50/D51)+F1K; standard with H04       \$740       \$740       \$740         V21       Luxury interior Trim       \$740       \$740       \$740         must have VA5/VA7; not with V52/VA1/VA3       \$108       \$108       \$108         must have (V43/X66)+(D50/D51); not with VK8/V93/C07       \$108       \$108       \$108         must have (V43/X66)+(D50/D51); not with VK8/V93/C07       \$108       \$108       \$108         must have (V43/X66)+(D50/D51); not with VK8/V93/C07       \$108       \$108       \$108         with V41/V43/VA5/V52/X66       \$108       \$108       \$108         Window pillar trim       \$574       \$574       \$574         must have V36 + (V21/VA1) + (F02/F03/F07); not with V42       \$117       \$117       \$117         y35       Wheel house covering       \$117       \$117       \$117         y47       \$743 must have V25/VA1/VA3; not with V52       \$982       \$982       \$982	T85		\$36	\$36	\$36
T93         Sliding door right side deletion         \$0         \$0         \$0           not with T16/T50/T57/VK8/VC5			·		
not with T16/T50/T57/VK8/VC5           V07 Cab rear wall liner         \$403         \$403           must have (D50/D51)+F1K; standard with H04           V21 Luxury interior Trim         \$740         \$740           must have VA5/VA7; not with V52/VA1/VA3         \$108         \$108           V24 Pallet support in sliding door step         \$108         \$108           was thave (V43/X66)+(D50/D51); not with VK8/V93/C07         \$108         \$108           V25 Half height load compartment trim         \$225         \$225         \$225           not with VA1/VA3/VA5/V52/X66         \$574         \$574         \$574           W11 Window pillar trim         \$574         \$574         \$574           must have V36 + (V21/VA1) + (F02/F03/F07); not with V42         \$117         \$117         \$117           V35 Wheel house covering         \$117         \$117         \$117           if +V43 must have V25/VA1/VA3; not with V52         \$982         \$982         \$982           must have D93; not with D17/D22/H72/L65/L71/LC2/VA3/V42/ZE6/(T93+-D03)/X66/C06/C07         \$310         \$310         \$310           V42 Lashing rails, waist level         \$310         \$310         \$310           not with V36/ZE6         \$473         \$473         \$473           V48 Floor cover behind seat box <td></td> <td></td> <td>· ·</td> <td></td> <td></td>			· ·		
V07         Cab rear wall liner         \$403         \$403         \$403           must have (D50/D51)+F1K; standard with H04         \$740         \$740         \$740           V21         Luxury interior Trim         \$740         \$740         \$740           must have VA5/VA7; not with V52/VA1/VA3         \$108         \$108         \$108           V24         Pallet support in sliding door step         \$108         \$108         \$108           must have (V43/X66)+(D50/D51); not with VK8/V93/C07         \$108         \$108         \$108           wish there (V43/X66)+(D50/D51); not with VK8/V93/C07         \$225         \$225         \$225         \$225           V31         Window pillar trim         \$574         \$574         \$574         \$574         \$574         \$574         \$574         \$574         \$574         \$574         \$574         \$574         \$574         \$574         \$574         \$574         \$574         \$574         \$574         \$574         \$574         \$574         \$574         \$574         \$574         \$574         \$574         \$574         \$574         \$574         \$574         \$574         \$574         \$574         \$574         \$574         \$574         \$574         \$574         \$574         \$574			· · · · · · · · · · · · · · · · · · ·		,
must have (D50/D51)+F1K; standard with H04           V21         Luxury interior Trim         \$740         \$740           must have VA5/VA7; not with V52/VA1/VA3         \$108         \$108           V24         Pallet support in sliding door step         \$108         \$108           must have (V43/X66)+(D50/D51); not with VK8/V93/C07         \$225         \$225           V25         Half height load compartment trim         \$225         \$225           not with V41/VA3/VA5/V52/X66         \$574         \$574         \$574           Window pillar trim         \$574         \$574         \$574           must have V36 + (V21/VA1) + (F02/F03/F07); not with V42         \$117         \$117         \$117           V35         Wheel house covering         \$117         \$117         \$117           if +V43 must have V25/VA1/VA3; not with V52         \$982         \$982         \$982           V36         Roof trim         \$982         \$982         \$982           must have D93; not with D17/D22/H72/L65/L71/LC2/VA3/V42/ZE6/(T93+-D03)/X66/C06/C07         \$310         \$310           V42         Lashing rails, waist level         \$310         \$310         \$310           not with V36/ZE6         \$473         \$473         \$473           V43         Wood floor w	V07		\$403	\$403	\$403
V21         Luxury interior Trim         \$740         \$740         \$740           must have VA5/VA7; not with V52/VA1/VA3         \$108         \$108           V24         Pallet support in sliding door step         \$108         \$108           must have (V43/X66)+(D50/D51); not with VK8/V93/C07         \$225         \$225         \$225           V31         Window pillar trim         \$574         \$574         \$574           must have V36 + (V21/VA1) + (F02/F03/F07); not with V42         \$117         \$117         \$117           V35         Wheel house covering         \$117         \$117         \$117           if +V43 must have V25/VA1/VA3; not with V52         \$982         \$982         \$982           V36         Roof trim         \$982         \$982         \$982           must have D93; not with D17/D22/H72/L65/L71/LC2/VA3/V42/ZE6/(T93+-D03)/X66/C06/C07         \$310         \$310         \$310           v42         Lashing rails, waist level         \$310         \$310         \$310           not with V36/ZE6         \$473         \$473         \$473           v43         Wood floor with 6 D-rings         \$473         \$473         \$473           not with P93/V93/V14/VK8/C07; standard with D93/H13/V24/V52/VC5/VV2/ZE6         \$30         \$30		must have (D50/D51)+F1K; standard with H04	· ·		,
must have VA5/VA7; not with V52/VA1/VA3         V24       Pallet support in sliding door step       \$108       \$108         must have (V43/X66)+(D50/D51); not with VK8/V93/C07         V25       Half height load compartment trim       \$225       \$225         not with VA1/VA3/VA5/V52/X66         V31       Window pillar trim       \$574       \$574         must have V36 + (V21/VA1) + (F02/F03/F07); not with V42         V35       Wheel house covering       \$117       \$117         if +V43 must have V25/VA1/VA3; not with V52         V36       Roof trim       \$982       \$982         must have D93; not with D17/D22/H72/L65/L71/LC2/VA3/V42/ZE6/(T93+-D03)/X66/C06/C07         V42       Lashing rails, waist level       \$310       \$310         not with V36/ZE6         V43       Wood floor with 6 D-rings       \$473       \$473         not with P93/V93/V14/VK8/C07; standard with D93/H13/V24/V52/VC5/VV2/ZE6         V48       Floor cover behind seat box       \$30       \$30         must have D93; not with D50/D51/D56/D62/D64/V43/VK8         V4A       Full paneling, right sliding door       \$123       \$123         Must have D03+T16+V21+VA5+W17; not with T19	V21		\$740	\$740	\$740
V24       Pallet support in sliding door step       \$108       \$108         must have (V43/X66)+(D50/D51); not with VK8/V93/C07         V25       Half height load compartment trim       \$225       \$225         not with VA1/VA3/VA5/V52/X66       \$574       \$574       \$574         V31       Window pillar trim       \$574       \$574       \$574         must have V36 + (V21/VA1) + (F02/F03/F07); not with V42       \$117       \$117       \$117         V35       Wheel house covering       \$117       \$117       \$117         if +V43 must have V25/VA1/VA3; not with V52       \$982       \$982       \$982         V36       Roof trim       \$982       \$982       \$982         must have D93; not with D17/D22/H72/L65/L71/LC2/VA3/V42/ZE6/(T93+-D03)/X66/C06/C07       \$310       \$310         V42       Lashing rails, waist level       \$310       \$310         not with V36/ZE6       \$473       \$473       \$473         V43       Wood floor with 6 D-rings       \$473       \$473       \$473         not with P93/V93/V14/VK8/C07; standard with D93/H13/V24/V52/VC5/VV2/ZE6       \$30       \$30       \$30         V48       Floor cover behind seat box       \$30       \$30       \$30         was have D93; not with D50/D51/D56/D62/D64/V4			· ·		,
must have (V43/X66)+(D50/D51); not with VK8/V93/C07           V25         Half height load compartment trim         \$225         \$225           not with VA1/VA3/VA5/V52/X66         \$574         \$574         \$574           V31         Window pillar trim         \$574         \$574         \$574           must have V36 + (V21/VA1) + (F02/F03/F07); not with V42         \$117         \$117         \$117           V35         Wheel house covering         \$117         \$117         \$117           if +V43 must have V25/VA1/VA3; not with V52         \$982         \$982         \$982           V36         Roof trim         \$982         \$982         \$982           must have D93; not with D17/D22/H72/L65/L71/LC2/VA3/V42/ZE6/(T93+-D03)/X66/C06/C07         \$310         \$310           V42         Lashing rails, waist level         \$310         \$310         \$310           not with V36/ZE6         \$473         \$473         \$473         \$473           V43         Wood floor with 6 D-rings         \$473         \$473         \$473           not with P93/V93/V14/VK8/C07; standard with D93/H13/V24/V52/VC5/VV2/ZE6         \$30         \$30         \$30           V48         Floor cover behind seat box         \$30         \$30         \$30           must have D93; not with	V24		\$108	\$108	\$108
V25         Half height load compartment trim         \$225         \$225           not with VA1/VA3/VA5/V52/X66         \$574         \$574         \$574           V31         Window pillar trim         \$574         \$574         \$574           must have V36 + (V21/VA1) + (F02/F03/F07); not with V42         \$117         \$117         \$117           V35         Wheel house covering         \$117         \$117         \$117           if +V43 must have V25/VA1/VA3; not with V52         \$982         \$982         \$982           V36         Roof trim         \$982         \$982         \$982           must have D93; not with D17/D22/H72/L65/L71/LC2/VA3/V42/ZE6/(T93+-D03)/X66/C06/C07         V42         Lashing rails, waist level         \$310         \$310         \$310           not with V36/ZE6         \$310         \$310         \$310         \$310         \$310           V43         Wood floor with 6 D-rings         \$473         \$473         \$473         \$473           not with P93/V93/VL4/VK8/C07; standard with D93/H13/V24/V52/VC5/VV2/ZE6         \$30         \$30         \$30           W48         Floor cover behind seat box         \$30         \$30         \$30           must have D93; not with D50/D51/D56/D62/D64/V43/VK8         \$123         \$123         \$123 <td></td> <td></td> <td>· ·</td> <td></td> <td>,</td>			· ·		,
not with VA1/VA3/VA5/V52/X66         V31 Window pillar trim       \$574       \$574         must have V36 + (V21/VA1) + (F02/F03/F07); not with V42         V35 Wheel house covering       \$117       \$117         if +V43 must have V25/VA1/VA3; not with V52         V36 Roof trim       \$982       \$982         must have D93; not with D17/D22/H72/L65/L71/LC2/VA3/V42/ZE6/(T93+-D03)/X66/C06/C07         V42 Lashing rails, waist level       \$310       \$310         not with V36/ZE6         V43 Wood floor with 6 D-rings       \$473       \$473       \$473         not with P93/V93/VL4/VK8/C07; standard with D93/H13/V24/V52/VC5/VV2/ZE6         V48 Floor cover behind seat box       \$30       \$30       \$30         must have D93; not with D50/D51/D56/D62/D64/V43/VK8         V4A Full paneling, right sliding door       \$123       \$123       \$123         must have D03+T16+V21+VA5+W17; not with T19	V25		\$225	\$225	\$225
V31       Window pillar trim       \$574       \$574       \$574         must have V36 + (V21/VA1) + (F02/F03/F07); not with V42       \$117       \$117       \$117         V35       Wheel house covering       \$117       \$117       \$117         if +V43 must have V25/VA1/VA3; not with V52       \$982       \$982       \$982         V36       Roof trim       \$982       \$982       \$982         must have D93; not with D17/D22/H72/L65/L71/LC2/VA3/V42/ZE6/(T93+-D03)/X66/C06/C07       \$310       \$310         V42       Lashing rails, waist level       \$310       \$310       \$310         not with V36/ZE6       \$473       \$473       \$473       \$473         V43       Wood floor with 6 D-rings       \$473       \$473       \$473         not with P93/V93/VL4/VK8/C07; standard with D93/H13/V24/V52/VC5/VV2/ZE6       \$30       \$30       \$30         V48       Floor cover behind seat box       \$30       \$30       \$30         must have D93; not with D50/D51/D56/D62/D64/V43/VK8       \$123       \$123       \$123         V4A       Full paneling, right sliding door       \$123       \$123       \$123         must have D03+T16+V21+VA5+W17; not with T19			' -	, -	, -
must have V36 + (V21/VA1) + (F02/F03/F07); not with V42         V35       Wheel house covering       \$117       \$117       \$117         if +V43 must have V25/VA1/VA3; not with V52         V36       Roof trim       \$982       \$982       \$982         must have D93; not with D17/D22/H72/L65/L71/LC2/VA3/V42/ZE6/(T93+-D03)/X66/C06/C07         V42       Lashing rails, waist level       \$310       \$310       \$310         not with V36/ZE6       \$473       \$473       \$473       \$473         V43       Wood floor with 6 D-rings       \$473       \$473       \$473         not with P93/V93/VL4/VK8/C07; standard with D93/H13/V24/V52/VC5/VV2/ZE6       \$30       \$30       \$30         V48       Floor cover behind seat box       \$30       \$30       \$30         must have D93; not with D50/D51/D56/D62/D64/V43/VK8       \$123       \$123       \$123         V4A       Full paneling, right sliding door       \$123       \$123       \$123         must have D03+T16+V21+VA5+W17; not with T19	V31		\$574	\$574	\$574
V35       Wheel house covering       \$117       \$117         if +V43 must have V25/VA1/VA3; not with V52       \$982       \$982         V36       Roof trim       \$982       \$982         must have D93; not with D17/D22/H72/L65/L71/LC2/VA3/V42/ZE6/(T93+-D03)/X66/C06/C07         V42       Lashing rails, waist level       \$310       \$310         not with V36/ZE6         V43       Wood floor with 6 D-rings       \$473       \$473       \$473         not with P93/V93/VL4/VK8/C07; standard with D93/H13/V24/V52/VC5/VV2/ZE6         V48       Floor cover behind seat box       \$30       \$30       \$30         must have D93; not with D50/D51/D56/D62/D64/V43/VK8         V4A       Full paneling, right sliding door       \$123       \$123       \$123         must have D03+T16+V21+VA5+W17; not with T19		·	<u>'</u>	,	,
if +V43 must have V25/VA1/VA3; not with V52         V36       Roof trim       \$982       \$982       \$982         must have D93; not with D17/D22/H72/L65/L71/LC2/VA3/V42/ZE6/(T93+-D03)/X66/C06/C07         V42       Lashing rails, waist level       \$310       \$310       \$310         not with V36/ZE6         V43       Wood floor with 6 D-rings       \$473       \$473       \$473         not with P93/V93/VL4/VK8/C07; standard with D93/H13/V24/V52/VC5/VV2/ZE6       V48       Floor cover behind seat box       \$30       \$30       \$30         must have D93; not with D50/D51/D56/D62/D64/V43/VK8       \$123       \$123       \$123         V4A       Full paneling, right sliding door       \$123       \$123       \$123         must have D03+T16+V21+VA5+W17; not with T19	V35		\$117	\$117	\$117
must have D93; not with D17/D22/H72/L65/L71/LC2/VA3/V42/ZE6/(T93+-D03)/X66/C06/C07         V42       Lashing rails, waist level       \$310       \$310       \$310         Not with V36/ZE6       \$473       \$473       \$473       \$473         Not with P93/V93/VL4/VK8/C07; standard with D93/H13/V24/V52/VC5/VV2/ZE6       \$30       \$30       \$30         V48       Floor cover behind seat box       \$30       \$30       \$30         must have D93; not with D50/D51/D56/D62/D64/V43/VK8       \$123       \$123       \$123         V4A       Full paneling, right sliding door       \$123       \$123       \$123         must have D03+T16+V21+VA5+W17; not with T19			·	•	
V42       Lashing rails, waist level       \$310       \$310       \$310         not with V36/ZE6       \$473       \$473       \$473         V43       Wood floor with 6 D-rings       \$473       \$473       \$473         not with P93/V93/VL4/VK8/C07; standard with D93/H13/V24/V52/VC5/VV2/ZE6       \$30       \$30       \$30         V48       Floor cover behind seat box       \$30       \$30       \$30         must have D93; not with D50/D51/D56/D62/D64/V43/VK8       \$123       \$123       \$123         V4A       Full paneling, right sliding door       \$123       \$123       \$123         must have D03+T16+V21+VA5+W17; not with T19	V36	Roof trim	\$982	\$982	\$982
not with V36/ZE6         V43       Wood floor with 6 D-rings       \$473       \$473       \$473         not with P93/V93/VL4/VK8/C07; standard with D93/H13/V24/V52/VC5/VV2/ZE6       V48       Floor cover behind seat box       \$30       \$30       \$30         must have D93; not with D50/D51/D56/D62/D64/V43/VK8       V4A       Full paneling, right sliding door       \$123       \$123         must have D03+T16+V21+VA5+W17; not with T19		must have D93; not with D17/D22/H72/L65/L71/LC2/VA3/V42/ZE6/(	/T93+-D03)/X66/C	.06/C07	·
V43       Wood floor with 6 D-rings       \$473       \$473       \$473         not with P93/V93/VL4/VK8/C07; standard with D93/H13/V24/V52/VC5/VV2/ZE6         V48       Floor cover behind seat box       \$30       \$30       \$30         must have D93; not with D50/D51/D56/D62/D64/V43/VK8         V4A       Full paneling, right sliding door       \$123       \$123         must have D03+T16+V21+VA5+W17; not with T19	V42			_	\$310
V43       Wood floor with 6 D-rings       \$473       \$473       \$473         not with P93/V93/VL4/VK8/C07; standard with D93/H13/V24/V52/VC5/VV2/ZE6         V48       Floor cover behind seat box       \$30       \$30       \$30         must have D93; not with D50/D51/D56/D62/D64/V43/VK8         V4A       Full paneling, right sliding door       \$123       \$123         must have D03+T16+V21+VA5+W17; not with T19		not with V36/ZE6	·		·
not with P93/V93/VL4/VK8/C07; standard with D93/H13/V24/V52/VC5/VV2/ZE6         V48 Floor cover behind seat box       \$30       \$30       \$30         must have D93; not with D50/D51/D56/D62/D64/V43/VK8         V4A Full paneling, right sliding door       \$123       \$123         must have D03+T16+V21+VA5+W17; not with T19	V43		\$473	\$473	\$473
V48       Floor cover behind seat box       \$30       \$30       \$30         must have D93; not with D50/D51/D56/D62/D64/V43/VK8       \$123       \$123       \$123         V4A       Full paneling, right sliding door       \$123       \$123       \$123         must have D03+T16+V21+VA5+W17; not with T19       \$123       \$123       \$123					
must have D93; not with D50/D51/D56/D62/D64/V43/VK8         V4A       Full paneling, right sliding door       \$123       \$123         must have D03+T16+V21+VA5+W17; not with T19	V48			\$30	\$30
V4A         Full paneling, right sliding door         \$123         \$123           must have D03+T16+V21+VA5+W17; not with T19         \$123         \$123					
must have D03+T16+V21+VA5+W17; not with T19	V4A		\$123	\$123	\$123
		. 5. 5			
	V85	Cigarette lighter & ash cup, front	\$44	\$44	\$44

		144" 4D High	170" 4D High	170" E 4D High
		M4CA4H	M4CA7H	M4CAEH
		907.653	907.655	907.657
١/٨1	Cide wall paneling weight height DVC	¢3E6	¢3E6	¢2F6
VA1	Side wall paneling waist height PVC must have VA5/VA7; not with V52	\$356	\$356	\$356
VA3	Side wall paneling full hardboard	\$497	\$497	\$497
VAS	not with V36/F02; if T93 must have (D50/D51)	Ş4 <i>31</i>	<b>3437</b>	Ş4 <i>31</i>
VA5	Full paneling, hinged rear doors	\$43	\$43	\$43
V // J	must have D03+VA7+(W61/W78); not with V25	Ş-13	<b>ў</b> -13	<b>7-13</b>
VA7	Storage compart. w/ net in rear doors	\$142	\$142	\$142
•,,,,	must have W61/W78; not with V52	7-1-	7-1-	7-1-
VC4	Cargo lashing rails, head height	\$465	\$465	\$465
	must have V42/C07/X66; not with ZE6	:	·	
VC5	Door sill - protective edge	\$79	\$79	\$79
	must have V43/X66; not with T19/T93/VK8/VV2/V93/C07			
VK8	Floor covering, plastic	\$414	\$414	\$414
	not with V43/P93/T19/T93/V52/VC5/X66			
VV2	Lashing rails, floor level (plus 4 anchors)	\$302	\$386	\$421
	must have V43; not with V93/VC5/ZE6			
VV4	Additional Ground Weld Studs	\$50	\$50	\$50
	no restriction			
W16	2nd row, fixed window, driver side	\$162	\$162	\$162
	if D93 must have F43+W70; if D93 & standard roof CHS production re	quired		
W17	2nd row, fixed window, passenger side	\$162	\$162	\$162
	if D93 must have F43+W70; if D93 & standard roof CHS production re	quired		
W33	FMVSS 217 emergency exit	-	\$424	\$424
	must have V31; not with D50/T19/W16			
	Rear doors, opening to side wall	\$403	\$403	S
W5F	90 Degree fixation point- Rear Doors	\$90	\$90	\$90
	must habe W54 / not with V21/V36/VA1/VA7			
W61	Windows in rear doors	\$105	\$105	\$105
=	must have VA7/ if D51 must have F61; not with W78/(W70+-(H22/F0.		6455	6455
W/0	Black tinting (90%) for rear windows	\$155	\$155	\$155
14/72	not with W94; must have W16/W17/F02/((W61/W78)+H22); standar			¢200
W/3	Bumper step, rear, grey	\$209	\$209	\$209
	not with QA2/W75/W76	42.45	6245	6245
W/5	Step, wide, at rear end	\$345	\$345	\$345
	not with JB6/JB7/Q24/QA9; must have R91+R92		4	
W76	Bumper step, rear, spring-loaded	-	\$673	\$673
	must have R91+R92; not with JB6/JB7/X55/Q24			
W78	Heated rear window(s) w/ washers/wipers	\$376	\$376	\$376
	Must have H22+VA7 / if D51 must have F61; not with W61			
X90	Deletion of Sprinter badge, left rear door	\$0	\$0	\$0
X93	Deletion of model badge, right rear door	\$0	\$0	\$0
X2R	Conversion to RV requirement	-	\$0	\$0
	must have B01+D93+E1X			
XM4	Acoustic package	\$97	\$97	\$97
	standard with CO2/CO3			
Y10	First-aid kit	\$30	\$30	\$30
Y26	Wheel chocks	\$43	\$43	\$43
Y45	Emergency flashlight	\$30	\$30	\$30
Y68	Paint preservative	\$209	\$238	\$252
Y69	Surface protection for stock vehicles	\$352	\$352	\$352
YK3	Cargo straps, D-rings	\$91	\$91	\$91
YK4	Cargo straps, lashing rails	\$116	\$116	\$116
	must have V42/VV2; not with ZE6			
ZE6	Shelving prep	\$717	\$717	\$717
	not with T93/H13/T19/V36/V42/VC4/VK8/VV2/YK4			

		144" 4D High	170" 4D High	170" E 4D High
		М4СА4Н	М4СА7Н	M4CAEH
		907.653	907.655	907.657
C00	Comfort Package	\$307	\$307	\$307
LC4	Comfort overhead control panel	Х	X	X
SE4	Lumbar support, co-driver's seat	Х	X	X
SE5	Lumbar support, driver's seat	Х	X	X
SK0	Comfort head restraint, driver	Х	X	X
SK1	Comfort head restraint, co-driver	Х	X	X
must	have COS OR X68; CA/CC only: not with S23			

COS	Comfort Package (Seat addition)	\$426	\$426	\$426
SB1	Comfort driver's seat	Х	Х	X
SB2	Comfort passenger seat	Х	Х	X
must	have COO		_	_

X68	Comfort Plus Package	\$1,898	\$1,898	\$1,898
H15	Heated front passenger seat	X	Х	Х
SF1	Driver's seat electrically adjustable	Х	Х	X
SF2	Co-driver's seat electrically adjustable	Х	Х	X
must	must have COO and VF4 OR VF6, CA/CC only: not with S23			

C01	Driver Convenience Package	\$449	\$449	\$449
E46	12 V power outlet, driver seat base	X	X	X
FJ1	Hinged lid for storage compartment	X	Х	X
FJ5	Hinged Lid for Storage Compartments left and right	X	Х	X
FZ9	Keys, two additional masters	Х	Х	X
JW8	Attention Assist	Х	Х	X

		\$805			
X	Х	Х			
X	X	Х			
X	X	Х			
must have JF1 + XM4; must choose FR8/JB7					
	X X X	V			

CA2	C02 in combination with C03	\$547	\$547	\$547
CL3	Leather steering wheel	X	Х	X
FM3	Wet Wiper System	X	Х	X
JB4	Active Lane Keeping Assist	X	Х	X
must	have CO3 + JF1	•		

144" 4D High	170" 4D High	170" E 4D High
М4СА4Н	М4СА7Н	M4CAEH
907.653	907.655	907.657

C03	Premium Plus Package	\$2,008	\$2,008	\$2,008
E1B	Tray for smartphones incl. wireless charging	X	Х	X
	Navigation	X	Х	X
EY2	Intelligent navigation	X	Х	X
E4M	MBUX Multimedia System with 10.25" touchscreen	X	Х	X
EX9	Free map data updates for 3 years	X	Х	X
H1I	Front-to-rear outlet in instrument panel	X	Х	X
JA9	Traffic Sign Assist	X	Х	Х
XM4	Acoustic package	Х	X	Х
must	have (CA2+(JB7/JB6/JB8)); not with FR8 and CO2		_	

X67	Chrome Grille Package	\$325	\$325	\$325	
CN2	Radiator grille frame in vehicle color	X	X	X	
FK3	Chrome plated radiator grille (MB only)	X	X	X	
no re	no restrictions				

X13	Exterior Lighting Package	\$1,801	\$1,801	\$1,801
L13	Fog lamp with cornering light function	X	X	X
L22	Partial LED tail lights	Х	X	X
LA1	High beam assist	Х	X	X
LG7	LED high performance headlamps	Х	X	X
no re	no restrictions			

C07	Cargo Protection Package	\$1,250	\$1,250	\$1,250
V25	Half height load compartment trim	X	Х	Х
V42	Lashing rails, waist level	Х	Х	Х
VC4	Cargo lashing rails, head height	X	Х	Х
VK8	Floor covering, plastic	Х	Х	Х
YK3	Cargo straps, D-rings	Х	Х	Х
not v	not with X66			

UL1	Upfit Prep and Load Restraining Package	\$1,768	\$1,768	\$1,768
V43	Wood floor with 6 D-rings	X	X	X
V42	Lashing rails, waist level	X	X	X
VC4	Cargo lashing rails, head height	X	X	X
VA3	Side wall paneling full hardboard	X	X	X
VV2	Lashing rails, floor level (plus 4 anchors)	X	X	X

X66	Heavy-Duty-Cargo Protection Package	\$1,952	\$1,952	\$1,952
V43	Wood floor with 6 D-rings	Х	Х	X
V42	Lashing rails, waist level	Х	Х	Х
VA3	Side wall paneling full hardboard	Х	Х	Х
VC4	Cargo lashing rails, head height	Х	Х	Х
VV2	Lashing rails, floor level (plus 4 anchors)	Х	Х	Х
YK3	Cargo straps, D-rings	Х	Х	Х
YK4	Cargo straps, lashing rails	Х	Х	Х
not v	vith CO7			_

		144" 4D High	170" 4D High	170" E 4D High
		М4СА4Н	М4СА7Н	M4CAEH
		907.653	907.655	907.657
X69	Swivel Seat Package	\$595	\$595	\$595
SR8	Swivel base for driver's seat	Х	Х	Х
SR9	Swivel base for front passenger seat	X	X	X
S87	Driver's seat frame, low	Х	Х	Х
S88	Passenger seat frame, low	Х	Х	Х
must	have (C00+C0S) OR (C00+X68)			

F09	SHUTTLE DOOR PREP PACKAGE	\$0	\$0	\$0
SW1	Seat belt deletion, passenger	Х	Х	X
S91	Passener seat, deleted	X	X	X
S99	Passenger seat pedestal - deletion	X	Х	Х

Package deletes standard options: SH2 Thorax-Pelvis sidebag, co-driver; To add/delete from order must call distirbution team

144" 4D Std	170" 4D Std
M2CV4S	M2CV7S
907.643	907.645

Engine  4-Cyl Standard Output Engine/9-Speed Trans.  ED4 AGM battery 12V 92 AH 850 A  G43 Automatic transmission, 9G-tronic  M60 Alternator 14 V / 250 A  M71 Approval Bio-Diesel B20  MU5 2.0L 4-cylinder diesel engine (168hp output)  MH8 SULEV emissions  Seating and Trim Packages  X75 Standard Rear Seats  U62 3-seater bench rear, 1st row (narrow)  U74 Wall-side armrest  U75 Aisle-side armrest  S Can have VF7/VF6 only; with X68 must have VF6  X2V Standard Trim Crew Van Package  V25 Half height load compartment trim  S Wheel house covering  V43 Wood floor with 6 D-rings  CHS production only  Equipment	\$ S S S S S S S S S S S S S S S S S S S
ED4 AGM battery 12V 92 AH 850 A S G43 Automatic transmission, 9G-tronic S M60 Alternator 14 V / 250 A S M71 Approval Bio-Diesel B20 S MU5 2.0L 4-cylinder diesel engine (168hp output) S MH8 SULEV emissions S Seating and Trim Packages  X75 Standard Rear Seats S U62 3-seater bench rear, 1st row (narrow) S U74 Wall-side armrest S U75 Aisle-side armrest S Can have VF7/VF6 only; with X68 must have VF6  X2V Standard Trim Crew Van Package S V25 Half height load compartment trim S V35 Wheel house covering S V43 Wood floor with 6 D-rings S CHS production only	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$
ED4 AGM battery 12V 92 AH 850 A S G43 Automatic transmission, 9G-tronic S M60 Alternator 14 V / 250 A S M71 Approval Bio-Diesel B20 S MU5 2.0L 4-cylinder diesel engine (168hp output) S MH8 SULEV emissions S Seating and Trim Packages  X75 Standard Rear Seats S U62 3-seater bench rear, 1st row (narrow) S U74 Wall-side armrest S U75 Aisle-side armrest S Can have VF7/VF6 only; with X68 must have VF6  X2V Standard Trim Crew Van Package S V25 Half height load compartment trim S V35 Wheel house covering S V43 Wood floor with 6 D-rings S CHS production only	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$
G43 Automatic transmission, 9G-tronic  M60 Alternator 14 V / 250 A  M71 Approval Bio-Diesel B20  S MU5 2.0L 4-cylinder diesel engine (168hp output)  S Seating and Trim Packages  X75 Standard Rear Seats  U62 3-seater bench rear, 1st row (narrow)  U74 Wall-side armrest  U75 Aisle-side armrest  S Can have VF7/VF6 only; with X68 must have VF6  X2V Standard Trim Crew Van Package  V25 Half height load compartment trim  S Wheel house covering  V43 Wood floor with 6 D-rings  CHS production only	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$
M60 Alternator 14 V / 250 A S M71 Approval Bio-Diesel B20 S MU5 2.0L 4-cylinder diesel engine (168hp output) S MH8 SULEV emissions S Seating and Trim Packages  X75 Standard Rear Seats S U62 3-seater bench rear, 1st row (narrow) S U74 Wall-side armrest S U75 Aisle-side armrest S Can have VF7/VF6 only; with X68 must have VF6  X2V Standard Trim Crew Van Package S V25 Half height load compartment trim S V35 Wheel house covering S V43 Wood floor with 6 D-rings S CHS production only	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$
M71 Approval Bio-Diesel B20 S MU5 2.0L 4-cylinder diesel engine (168hp output) S MH8 SULEV emissions S Seating and Trim Packages  X75 Standard Rear Seats S U62 3-seater bench rear, 1st row (narrow) S U74 Wall-side armrest S U75 Aisle-side armrest S Can have VF7/VF6 only; with X68 must have VF6  X2V Standard Trim Crew Van Package S V25 Half height load compartment trim S V35 Wheel house covering S V43 Wood floor with 6 D-rings S CHS production only	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$
MUS 2.0L 4-cylinder diesel engine (168hp output)  MH8 SULEV emissions  Seating and Trim Packages  X75 Standard Rear Seats  U62 3-seater bench rear, 1st row (narrow)  U74 Wall-side armrest  U75 Aisle-side armrest  S  Can have VF7/VF6 only; with X68 must have VF6  X2V Standard Trim Crew Van Package  V25 Half height load compartment trim  S  V35 Wheel house covering  V43 Wood floor with 6 D-rings  CHS production only	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$
MH8 SULEV emissions S  Seating and Trim Packages  X75 Standard Rear Seats S U62 3-seater bench rear, 1st row (narrow) S U74 Wall-side armrest S U75 Aisle-side armrest S Can have VF7/VF6 only; with X68 must have VF6  X2V Standard Trim Crew Van Package S V25 Half height load compartment trim S V35 Wheel house covering S V43 Wood floor with 6 D-rings S CHS production only	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$
Seating and Trim Packages       X75     Standard Rear Seats     S       U62     3-seater bench rear, 1st row (narrow)     S       U74     Wall-side armrest     S       U75     Aisle-side armrest     S       can have VF7/VF6 only; with X68 must have VF6       X2V     Standard Trim Crew Van Package     S       V25     Half height load compartment trim     S       V35     Wheel house covering     S       V43     Wood floor with 6 D-rings     S       CHS production only	\$ S S S S
X7S Standard Rear Seats  U62 3-seater bench rear, 1st row (narrow)  U74 Wall-side armrest  U75 Aisle-side armrest  S  Can have VF7/VF6 only; with X68 must have VF6  X2V Standard Trim Crew Van Package  V25 Half height load compartment trim  S  V35 Wheel house covering  V43 Wood floor with 6 D-rings  CHS production only	\$ \$ \$ \$ \$ \$
U62 3-seater bench rear, 1st row (narrow)  U74 Wall-side armrest  U75 Aisle-side armrest  S  can have VF7/VF6 only; with X68 must have VF6  X2V Standard Trim Crew Van Package  V25 Half height load compartment trim  S  V35 Wheel house covering  V43 Wood floor with 6 D-rings  CHS production only	\$ \$ \$ \$ \$ \$
U74 Wall-side armrest S U75 Aisle-side armrest S can have VF7/VF6 only; with X68 must have VF6  X2V Standard Trim Crew Van Package S V25 Half height load compartment trim S V35 Wheel house covering S V43 Wood floor with 6 D-rings S CHS production only	\$ \$ <b>\$</b>
U75 Aisle-side armrest  can have VF7/VF6 only; with X68 must have VF6  X2V Standard Trim Crew Van Package  V25 Half height load compartment trim  S  V35 Wheel house covering  V43 Wood floor with 6 D-rings  CHS production only	\$ <b>\$</b>
can have VF7/VF6 only; with X68 must have VF6       X2V     Standard Trim Crew Van Package     S       V25     Half height load compartment trim     S       V35     Wheel house covering     S       V43     Wood floor with 6 D-rings     S       CHS production only	S
X2V     Standard Trim Crew Van Package     S       V25     Half height load compartment trim     S       V35     Wheel house covering     S       V43     Wood floor with 6 D-rings     S       CHS production only	
V25     Half height load compartment trim     S       V35     Wheel house covering     S       V43     Wood floor with 6 D-rings     S       CHS production only	
V35 Wheel house covering S V43 Wood floor with 6 D-rings S CHS production only	S
V43 Wood floor with 6 D-rings S  CHS production only	J
CHS production only	S
,	S
Equipment	
AR2 Axle ratio 3.923	S
BA3 Active Brake Assist S	S
BH1 Hold Function S	S
CGL Multifunction steering wheel S	S
CL1 Adjustable steering wheel (angle)	S
D03 High roof 0	S
D93 Omission bulkhead S	S
E07 Hill Start Assist S	S
E10 Standard radio S	S
E1U USB-C socket, 5 V S	S
E30 Starter battery disconnect S	S
E3J Pre-installation for switch panel	S
E40 Trailer hitch prep. wiring S	S
ED8 Preinstallation PSM S	S
EE5 Ultracapacitor discharge module S	S
EK1 Body Builder Connector S	S
ESO Jump start terminal S	S
EW6 Pre-installation for Mercedes me Remote Services	S
EY5 Emergency Call System S	S
EY6 Breakdown management S	S
F43 Laminated glass rear S	S
F68 Heated & electrically adjustable exterior mirrors	S
FF3 Cupholder rear compartment S	S
FF5 Shelf above windshield S	S
FG8 Cupholder front S	S
FI1 Remote key (315 mhz) w/central locking S	S
FJ4 Storage compartment underneath cockpit S	S
FR3 Rear view camera (rear-view mirror display)	S
H00 Warm/cool air duct to rear compartment S	S
H16 Heated driver's seat S	S
H21 Windshield with filter band S	S
H22 Rear window defroster S	S
	S
HH2 Heater, auxiliary electric hot air S	
HH9 Air Condition, Front	S
Incention to the	
IH7 Headunit S  J11 Speedometer, miles and km/h S	S S

		144" 4D Std	170" 4D Std
		M2CV4S	M2CV7S
		907.643	907.645
J55 :	Seat belt warning for co-driver seat	S	S
J58	Seat belt reminder driver	S	S
J65	Outside temperature gauge	S	S
JA8	Crosswind Assist	S	S
JH3	Communication module (LTE) for dig. services	S	S
JI9	Service interval 20.000 miles	S	S
Jk5	Instrument cluster with color display	S	S
	Black diesel filler cap	S	S
	Exhaust straight to rear	S	S
	24.5 gallon fuel tank	S	S
	Aux fuel sending unit w/ fuel tap	S	S
	Fuel/water seprarator & lubrication package	S	S
	4rd generation SCR emission control system	S	S
	Parking lights deletion	S	S
	Headlight assistant	S	S
	3rd brake light	S	S
	Cruise control	S	S
	Front mudflaps	S	S
	Rear mudflaps	S	S
	Longitudinal member reinforcement	S	S
_	Spare tire bracket below frame	S	S
	Spare tire	S	S
	Unspecified tire brand	S	S
	Tires LT 245/75 R16	S	S
	All-season tires	S	S
	6.5 J x 16 steel wheels	S	S
	Tire pressure monitoring sensors	S	S
	Standard driver seat	S	S
	Standard front passenger seat	S	S
	Armrest for driver's seat	S	S
	Armrest for front passenger seat	S	S
	Front airbag, driver	S	S
	Front airbag, passenger	S	S
	Thorax-pelvis sidebag, driver	S S	S S
_	Thorax-pelvis sidebag, co-driver		
	Airbag, driver/passenger window	S S	S
	Seat occupancy sensor, driver's seat	S	S S
	Sliding door, passenger side	S S	
	Assist handle, B-pillar Pre-inst. for seating configuration Crew Van	S S	S S
	Roof trim	S S	S S
	Floor anchors for rear seat bench	S	S
	Storage compart. w/ net in rear doors	S	S
	2nd row, fixed window, driver side	S	S
_	2nd row, fixed window, driver side  2nd row, fixed window, passenger side	S	S
	Windows in rear doors	S	S
	Black tinting (90%) for rear windows	S	S
	GVWR 9,050 lbs. / 4.100 Kg	S	S
	Plates/booklets in English (US)	S	S
_	Manufacturer Mercedes-Benz AG	S	S
_	VIN visible from outside	S	S
* 1 2		S S	S
			3
XI2	Change Year G2-I		c
XI2 XY4	Model Year 2024	S	S
XI2 XY4 Y43			S S S

		144" 4D Std	170" 4D Std
		M2CV4S	M2CV7S
		907.643	907.645
A50	Front axle reinforced	\$387	\$387
AP2	Addtl. bar for driveshaft & exhaust extension	\$77	\$77
B01	ESP for increased Center of Gravity above 39.4"	\$0	\$0
	must have CB4/CB8/X55; not with RH0/CB7	Ţ.	Ψ°
B25	Electric parking brake	\$313	\$313
523	no restrictions	3313	<b>3313</b>
C72	Bumpers front/rear primed	\$300	\$300
C, 2	must have CN2/X67, not with CM0	7300	<b>\$300</b>
CB1	Suspension for comfort and load protection	\$270	\$270
CB7	Stabilization Level I	\$344	\$344
CD7	not with CB1/CB7/CB8/A4M/X55	7344	<del>-</del>
CB8	Stabilization Level II	\$810	\$810
СВО	not with CB4/CB8/A4M/X55	3010	3010
CNAO		¢6E7	¢6E7
CM0	Painted metallic front & rear bumper	\$657	\$657
CN 40	must have (CN2/X67) + (JA7/C01) + (JB6/JB7) + (7755/9197/9775)	Ć 400	Ć400
CM9	Primed side moldings	\$408	\$408
CT1	Rear spring vibration absorbers	\$155	\$155
D03	High roof	\$3,500	S
	D03 must be added for Duesseldorf production	1000	4
D13	Mounting rails for roof rack	\$336	\$336
E1B	Tray for smartphones incl. wireless charging	\$175	\$175
	must have CO2/E3M + H1I		
E1E	Navigation	\$815	\$815
	must have CO2/E3M, not with CO3		
E1S	Sirius XM, satellite radio	\$285	\$285
	must have CO2/E3M/CO3		
E1R	Additional Fuses (40/80/150/100 Ampere)	\$57	\$57
	must have X2R/ not with E1Y		
E2A	Access point for BB special signals in cockpit	\$32	\$32
E2I	Additional battery, co-driver seat base	\$277	\$277
	Must have E36; not with E2M; CHS production only	_	
E36	Cutoff relay for additional battery	\$124	\$124
	standard with E2I/E2M		
E3M	MBUX Multimedia System with 7" touchscreen	\$531	\$531
	not with CO2/CO3; must have JK5+(JB7/JB6/JB8/FR8)		
E5M	Extension of PSM standard contact	\$65	\$65
ED5	Parametric special module (PSM)	\$354	\$354
	not with ED8		
EE3	115 V socket	\$140	\$140
ES2	12 V power outlet, rear compartment	\$103	\$103
ES5	Charging package, dashboard	\$92	\$92
ET4	Active Distance Assist DISTRONIC	\$294	\$294
	must have CO3		
F49	Electrically heated windshield	\$244	\$244
	no restrictions	•	
F61	Interior rear view mirror	\$41	\$41
	must have E3M/C02/C03	•	
F84	Digital Rearview Mirror	\$736	\$736
	must have LA2- Not with F61	,	
F64	Electrically folding exterior mirrors	\$55	\$55
FE9	Additional DIN-slot	\$91	\$91
FF8	Overhead storage slot, front center	\$117	\$117
FJ1	Hinged lid for storage compartment	\$105	\$105
. , , ,	Imped na for storage compartment	7103	7103

		144" 4D Std	170" 4D Std
		M2CV4S	M2CV7S
		907.643	907.645
FR8	Rear view camera (head unit display)	\$377	\$377
	must have CO2/E3M; not with FR3/JB7/JB6/JB8	•	
FY1	Security alarm w. interior motion sensor	\$654	\$654
	must have LC4/C00		
FY7	Optional 3-button keys	\$41	\$41
FZ9	Keys, two additional masters	\$136	\$136
H01	Heat insulation, rear compartment	\$175	\$175
	must have V25/VA3/VA1/C07/X66	Ÿ2,3	Ψ2.0
H04	Heat insulation, front compartment	\$209	\$209
	if + D50/D51 must have V07	7-00	7200
H12	Fuel-fired pre-heater/booster (17K BTU)	\$1,249	\$1,249
	not with HZ9	Ψ±,2 13	Ψ1,2 13
H13	Rear cabin heater and vents	\$880	\$880
	must have V43 + (H12/HZ9); not with VK8	γοσο	<b>\$</b> 000
H15	Heated front passenger seat	\$318	\$318
1113	must have H16; not with X68	7310	7510
H88	Rear heater prep	\$453	\$453
1100	must have H12/HZ9; not with H13/T19	<b>7433</b>	\$4J3
H1I	Front-to-rear outlet in instrument panel	\$0	\$0
ПТІ		ŞŪ	ŞÜ
ши	must have FJ1/C01 Thermotronic automatic climate control	\$378	\$378
HH4		Ş3/6	Ş376
1170	must have JF1; if +H13 must have H08/HK4	Ċ7F.C	ĊZEC
HZ9	Fuel-fired heater booster (18,000 BTU)	\$756	\$756
J51	not with H12	ćoo	ćoo
131	Fuel gauge, optimized for aux. fuel tap  not with HZ9/H12	\$80	\$80
J52	Engine oil level display at cold start	\$0	\$0
		•	
JA7	Blind Spot Assist	\$504	\$504
ID 4	must have F64	ćana	ćana
JB4	Active Lane Keeping Assist	\$322	\$322
IDC	standard with CO2/CA2	¢067	¢0C7
JB6	Parking Package with 360 degree camera	\$867	\$867
107	must have E3M/C02/C03; not with W75/W76/JB7	¢coo.	¢coo
JB7	Parking Package	\$688	\$688
100	must have E3M/C02/C03; not with W75/W76/JB6	¢7CC	¢7CC
JB8	360 Degree Camera	\$766	\$766
154	must have CO2/CO3/E3M, not with JB6/JB7	Ć440	Ć110
JF1	Rain sensor	\$118	\$118
	Standard with C02/CA2/X11		Å
JW0	Backup alarm	\$111	\$111
JW2	Deactivation lamp monitoring failure	\$30	\$30
JW8	Attention Assist	\$55	\$55
K51	Misfueling prevention for Diesel	\$55	\$55
K52	DEF fluid filler cap - lockable	\$30	\$30
L13	Fog lamp with cornering light function	\$223	\$223
LB9	Illuminated front exits	\$170	\$170
LC4	Comfort overhead control panel	\$105	\$105
M20	Speed limitation 65 mph	\$67	\$67
<u> </u>	not with MD3		
M61	Alternator 14 V / 280 A	\$188	\$188

		144" 4D Std	170" 4D Std
		M2CV4S	M2CV7S
		907.643	907.645
MD3	Top speed limitation 75 mph	\$71	\$71
	not with M20		
N62	Front engine bracket for additional alternator	\$523	\$523
	not with HK4/N63		
N63	Front engine bracket for auxiliary A/C compressor	\$523	\$523
	not with HK4/N62		
Q24	Trailer hitch, 5,000 lbs	\$164	\$164
	not with W73/W75/W76		
QA9	Half-sided step rear (for trailer hitch)	\$113	\$113
	must have Q24/QA2; not with W73/W75/W76		
R91	Spare tire deletion	-\$110	-\$110
	must have R92; not with R87		
R92	Spare tire carrier deletion	\$0	\$0
	must have R91; not with R65		
R98	Rims painted jet black	\$91	\$91
	not with RL5/RM2		
RF1	Tire brand Continental	\$0	\$0
	must have RM1 + RM9		
RF8	Tire brand Michelin	\$0	\$0
	must have RM9; not with RM1		
RH0	Tire brand Kumho	\$0	\$0
	must have RM9; not with RM1		
RL5	Light-alloy wheels 6.5 J x 16	\$1,015	\$1,015
	not with RS3/RM2/R98		
RM1	M+S winter tires	\$190	\$190
	must have RF1/RD9; not with RF8/RH0/X31		
RM2	Rims painted arctic white	\$91	\$91
	not with R98/RL5		
RM9	Specially requested tires	\$113	\$113
	must have RF1/RF8/RH0; not with RD9	4	4==
S28	Armrest, driver and passenger door	\$58	\$58
T12	Sliding door two stage opening	\$92	\$92
	not with T55	4	4
T50	Electric closing assist right sliding door	\$376	\$376
TC C	must have D03; not with T55/T93	4000	4000
T55	Electric sliding door right	\$930	\$930
TC 7	must have D03 + (FY7+T16); not with T12/T50	¢1.100	¢4.400
T57	Electric sliding step	\$1,199	\$1,199
TCO	must have D03 + ED5; not with T93	ć12 <i>1</i>	ć12 <i>4</i>
T60	Opening limiter electrically operated sliding door	\$134	\$134
T75	must have T55	ĊCC	¢ee
T75	Door-mounted assist handles, driver & passenger	\$66	\$66
T85	Assist handle, left rear door	\$36	\$36
T86	Assist handles, right rear door	\$36	\$36
V43	Wood floor with 6 D-rings	\$473	\$473
	not with P93/V93/VL4/VK8/C07; standard with D93/H13/V24/V52		4
V85	Cigarette lighter & ash cup, front	\$44	\$44
VC5	Door sill - protective edge	\$79	\$79
	must have V43/X66; not with T19/T93/VK8/VV2/V93/C07		
VK8	Floor covering, plastic	\$414	\$414
	not with V43/P93/T19/T93/V52/VC5/X66		

		144" 4D Std	170" 4D Std
		M2CV4S	M2CV7S
		907.643	907.645
W54	Rear doors, opening to side wall	\$403	\$403
W73	Bumper step, rear, grey	\$209	\$209
	not with Q24/W75/W76		
W75	Step, wide, at rear end	\$345	\$345
	not with JB6/JB7/Q24/QA9; must have R91+R92		
W76	Bumper step, rear, spring-loaded	\$673	\$673
	must have R91+R92; not with JB6/JB7/X55/Q24		
W78	Heated rear window(s) w/ washers/wipers	\$376	\$376
	Must have H22+VA7 / if D51 must have F61; not with W61		
X90	Deletion of Sprinter badge, left rear door	\$0	\$0
X93	Deletion of model badge, right rear door	\$0	\$0
XM4	Acoustic package	\$97	\$97
	standard with CO2/CO3		
Y10	First-aid kit	\$30	\$30
Y26	Wheel chocks	\$43	\$43
Y45	Emergency flashlight	\$30	\$30
Y68	Paint preservative	\$209	\$238
Y69	Surface protection for stock vehicles	\$352	\$352
YK3	Cargo straps, D-rings	\$91	\$91

		144" 4D Std	170" 4D Std
		M2CV4S	M2CV7S
		907.643	907.645
C00	Comfort Package	\$307	\$307
LC4	Comfort overhead control panel	Х	X
SE4	Lumbar support, co-driver's seat	Х	X
SE5	Lumbar support, driver's seat	X	Х
SK0	Comfort head restraint, driver	Х	Х
SK1	Comfort head restraint, co-driver	Х	Х
must	have COS OR X68; CA/CC only: not with S23		
	·		

COS	Comfort Package (Seat addition)	\$426	\$426
SB1	Comfort driver's seat	Х	X
SB2	Comfort passenger seat	Х	X
must	have COO	_	

X68	Comfort Plus Package	\$1,898	\$1,898	
H15	Heated front passenger seat	Х	X	
SF1	Driver's seat electrically adjustable	Х	Х	
SF2	Co-driver's seat electrically adjustable	Х	Х	
must	must have COO and VF4 OR VF6, CA/CC only: not with S23			

C01	Driver Convenience Package	\$449	\$449
E46	12 V power outlet, driver seat base	Х	X
F64	Electrically folding exterior mirrors	Х	X
FJ1	Hinged lid for storage compartment	Х	X
FJ5	Hinged Lid for Storage Compartments left and right	Х	X
FZ9	Keys, two additional masters	Х	Х
JW8	Attention Assist	Х	Х

C02	Premium Package	\$805	\$805	
E3M	MBUX Multimedia System with 7" touchscreen	Х	Х	
FM3	Wet Wiper System	Х	Х	
JB4	Active Lane Keeping Assist	Х	Х	
must	have JF1 + XM4; must choose FR8/JB7/JB6			

CA2	C02 in combination with C03	\$547	\$547
CL3	Leather steering wheel	Х	X
FM3	Wet Wiper System	Х	X
JB4	Active Lane Keeping Assist	Х	X
must	have CO3 + JF1		

144" 4D Std	170" 4D Std
M2CV4S	M2CV7S
907.643	907.645

C03	Premium Plus Package	\$2,008	\$2,008
E1B	Tray for smartphones incl. wireless charging	Х	X
	Navigation	X	X
EY2	Intelligent navigation	X	X
E4M	MBUX Multimedia System with 10.25" touchscreen	X	X
EX9	Free map data updates for 3 years	Х	Х
H1I	Front-to-rear outlet in instrument panel	Х	Х
JA9	Traffic Sign Assist	Х	Х
XM4	Acoustic package	Х	Х
must	have (CA2+(JB7/JB6/JB8)); not with FR8 and CO2	_	·

X67	Chrome Grille Package	\$325	\$325		
CN2	Radiator grille frame in vehicle color	X	Х		
FK3	Chrome plated radiator grille (MB only)	X	Х		
no restrictions					

X13	Exterior Lighting Package	\$1,801	\$1,801		
L13	Fog lamp with cornering light function	Х	X		
L22	Partial LED tail lights	Х	Х		
LA1	High beam assist	Х	Х		
LG7	LED high performance headlamps	Х	Х		
no restrictions					

X72	Crew Van Comfort Package	\$246	\$246		
S31	Convenice head restraints for pass. compartment	Х	X		
UY1	3-seater comfort bench rear, 1st row (narrow)	Х	X		
can have VF4/VF6 only					

X4Z	Interior Trim Upgrade Package	\$683	\$683		
VA1	Side wall paneling waist height PVC	X	Х		
VA3	Side wall paneling full hardboard	Х	Х		
ZK4	Crew Van, produced in Germany	Х	Х		
must	must have (V43+VC5) OR VK8				

144" 4D High	144" 4D High AWD	170" 4D High	170" 4D High AWD
M2CV4H	M2CV4A	M2CV7H	M2CV7A
907.643	907.643	907.645	907.645

Engin	e				
	High Output Engine/9-Speed Trans.	S	S	S	S
	AGM battery 12V 92 AH 850 A	S	S	S	S
G43	Automatic transmission, 9G-tronic	S	S	S	S
	SULEV emissions	S	S	S	S
	2.0L 4-cylinder diesel engine (208hp output)	S	S	S	S
	Alternator 14 V / 250 A	S	S	S	S
	Approval Bio-Diesel B20	S	S	S	S
	All Wheel Drive Package	-	\$6,400	-	\$6,400
	Door-mounted assist handles, driver & passenger	-	S S	-	S S
	All Wheel Drive with torque on demand	_	S	-	S
	ng and Trim Packages	ļ			J
_	Standard Rear Seats	S	S	S	S
-	3-seater bench rear, 1st row (narrow)	S	S	S	S
	Wall-side armrest	S	S	S	S
	Aisle-side armrest	S	S	S	S
	ave VF7/VF6 only; with X68 must have VF6	3		3	J
	Standard Trim Crew Van Package	S	S	S	S
	Half height load compartment trim	S	S	S	S
-	Wheel house covering	S	S	S	S
	Wood floor with 6 D-rings	S	S	S	S
	production only	3	3	3	3
Equip					
<u> </u>	Axle ratio 3.923	S	S	S	S
BA3	Active Brake Assist	S	S	S	S
	Hold Function	S	S S	S S	S
-		S			
C6L	Multifunction steering wheel	S S	S S	S S	S S
CL1	Adjustable steering wheel (angle)			_	
D03	High roof	0	0	S	S
D93	Omission bulkhead	S	S	S	S
E07	Hill Start Assist	S	S	S	S
E10	Standard radio	S	S	S	S
E1U	USB-C socket, 5 V	S	S S	S S	S S
E30	Starter battery disconnect				
E3J	Pre-installation for switch panel	S	S	S	S
E40	Trailer hitch prep. wiring	S S	S S	S S	S S
ED8	Preinstallation PSM	S	S S	S	S
EE5	Ultracapacitor discharge module	S		S	
EK1	Body Builder Connector		S		S
ESO	Jump start terminal	S	S	S	S
	Pre-installation for Mercedes me Remote Services	S	S	S	S
	Emergency Call System	S	S	S	S
EY6	Breakdown management	S	S	S	S
F43	Laminated glass rear	S	S	S	S
F68	Heated & electrically adjustable exterior mirrors	S	S	S	S
FF3	Cupholder rear compartment Shelf above windshield	S	S S	S	S
FF5				S	S
FG8	Cupholder front	S	S	S	S
FI1	Remote key (315 mhz) w/central locking	S	S	S	S
FJ4	Storage compartment underneath cockpit	S	S	S	S
FR3	Rear view camera (rear-view mirror display)	S	S	S	S
H00	Warm/cool air duct to rear compartment	S	S	S	S
H16	Heated driver's seat	S	S	S	S
H21	Windshield with filter band	S	S	S	S
H22	Rear window defroster	S	S	S	S
HH2	Heater, auxiliary electric hot air	S	S	S	S
HH9	Air Condition, Front	S	S	S	S

		144" 4D High	144" 4D High AWD	170" 4D High	170" 4D High AWD
		M2CV4H	M2CV4A	M2CV7H	M2CV7A
		907.643	907.643	907.645	907.645
IH7	Headunit	S	S	S	S
J11	Speedometer, miles and km/h	S	S	S	S
J55	Seat belt warning for co-driver seat	S	S	S	S
J58	Seat belt reminder driver	S	S	S	S
J65	Outside temperature gauge	S	S	S	S
JA8	Crosswind Assist	S	S	S	S
JH3	Communication module (LTE) for dig. services	S	S	S	S
JI9	Service interval 20.000 miles	S	S	S	S
Jk5	Instrument cluster with color display	S	S	S	S
	Black diesel filler cap	S	S	S	S
K60	Exhaust straight to rear	S	S	S	S
	24.5 gallon fuel tank	S	S	S	S
KL1	Aux fuel sending unit w/ fuel tap	S	S	S	S
-	Fuel/water seprarator & lubrication package	S	S	S	S
KP7	4rd generation SCR emission control system	S	S	S	S
L94	Parking lights deletion	S	S	S	S
LA2	Headlight assistant	S	S	<u>s</u>	S
LB5	3rd brake light	S	S	S	S
-	Cruise control	S	S	S	S
P47	Front mudflaps	S	S	S	S
P48	Rear mudflaps	S	S	S	S
		S S	S	s	S
Q11	Longitudinal member reinforcement	S S	S	<u> </u>	S
R65	Spare tire bracket below frame	S S	S	<u> </u>	
R87	Spare tire				S
RD9	Unspecified tire brand	S	S	S	S
RH8	Tires LT 245/75 R16	S	S	S	S
	All-season tires	S	S	S	S
	6.5 J x 16 steel wheels	S	S	<u> </u>	S
RY2	Tire pressure monitoring sensors	S	S	S	S
	Standard driver seat	S	S	S	S
	Standard front passenger seat	S	S	S	S
-	Armrest for driver's seat	S	S	S	S
	Armrest for front passenger seat	S	S	S	S
SA5	Front airbag, driver	S	S	S	S
SA6	Front airbag, passenger	S	S	S	S
SH1	Thorax-pelvis sidebag, driver	S	S	S	S
SH2	Thorax-pelvis sidebag, co-driver	S	S	S	S
	Airbag, driver/passenger window	S	S	S	S
SK2	Seat occupancy sensor, driver's seat	S	S	S	S
T16	Sliding door, passenger side	S	S	S	S
T74	Assist handle, B-pillar	S	S	S	S
U22	Pre-inst. for seating configuration Crew Van	S	S	S	S
V36	Roof trim	S	S	S	S
V40	Floor anchors for rear seat bench	S	S	S	S
VA7	Storage compart. w/ net in rear doors	S	S	S	S
W16	2nd row, fixed window, driver side	S	S	S	S
	2nd row, fixed window, passenger side	S	S	S	S
	Windows in rear doors	S	S	S	S
_	Black tinting (90%) for rear windows	S	S	S	S
	GVWR 9,050 lbs. / 4.100 Kg	S	S	S	S
X64	Plates/booklets in English (US)	S	S	S	S
X99	Manufacturer Mercedes-Benz AG	S	S	S	S
XC8	VIN visible from outside	S	S	S	S
XI2	Change Year G2-I	S	S	S	S
XY4	Model Year 2024	S	S	S	S
Y43	Jack, hydraulic	S	S	S	S
ZU8	USA country version	S S	S	S	S
		S S	S	S	S
ZZ4	Brand content Mercedes-Benz North America	3	3	3	3

		144" 4D High	144" 4D High AWD	170" 4D High	170" 4D High AWD
		M2CV4H	M2CV4A	M2CV7H	M2CV7A
		907.643	907.643	907.645	907.645
A50	Front axle reinforced	\$387	-	\$387	-
AP2	Addtl. bar for driveshaft & exhaust extension	\$77	\$77	\$77	\$77
$\vdash$	ESP for increased Center of Gravity above 39.4"	\$0	\$0	\$0	\$0
	must have CB4/CB8/X55; not with RH0/CB7	7.5	7.5	7.5	7.5
B25	Electric parking brake	\$313	\$313	\$313	\$313
-	no restrictions	ψ010	ψ0.13	ψ020	ψ020
C72	Bumpers front/rear primed	\$300	\$300	\$300	\$300
	must have CN2/X67, not with CM0	,	,	,	,
CB1	Suspension for comfort and load protection	\$270	-	\$270	-
	Stabilization Level I	\$344	_	\$344	_
	not with CB1/CB7/CB8/A4M/X55	72		75.11	
CB8	Stabilization Level II	\$810	-	\$810	-
-	not with CB4/CB8/A4M/X55	<b>7010</b>		ψ020	
CM0	Painted metallic front & rear bumper	\$657	\$657	\$657	\$657
	must have (CN2/X67) + (JA7/C01) + (JB6/JB7) + (7755/9197/9775)	, 30 <i>,</i>	, 30.	+ 20,	, 30.
CM9	Primed side moldings	\$408	\$408	\$408	\$408
<b>—</b>	Rear spring vibration absorbers	\$155	\$155	\$155	\$155
	High roof	\$3,500	\$3,500	\$155 S	\$155 S
	D03 must be added for Duesseldorf production	75,550	75,550	<u> </u>	
D13	Mounting rails for roof rack	\$336	\$336	\$336	\$336
	Tray for smartphones incl. wireless charging	\$175	\$175	\$175	\$175
	must have CO2/E3M + H1I	Ş17 <i>3</i>	7175	7175	Ş17 <i>3</i>
E1E		\$815	\$815	\$815	\$815
E1E	Navigation	\$012	\$912	\$012	\$912
F1C	must have CO2/E3M, not with CO3	¢20F	¢20F	¢20E	¢20F
E1S	Sirius XM, satellite radio	\$285	\$285	\$285	\$285
E1R	must have CO2/E3M/CO3 Additional Fuses (40/80/150/100 Ampere)	\$57	\$57	\$57	\$57
EIK	must have X2R/ not with E1Y	\$5 <i>1</i>	<b>\$57</b>	<b>ఫ</b> 57	Ş5/
E2.4	·	622	ćaa	ຕ່ວງ	\$32
	Access point for BB special signals in cockpit	\$32	\$32	\$32	
E2I	Additional battery, co-driver seat base	\$277	\$277	\$277	\$277
E26	Must have E36; not with E2M; CHS production only	¢124	\$124	¢124	\$124
E36	Cutoff relay for additional battery	\$124	\$124	\$124	\$124
E3M	standard with E2I/E2M  MBUX Multimedia System with 7" touchscreen	\$531	¢E21	¢E21	\$531
ESIVI	not with CO2/CO3; must have JK5+(JB7/JB6/JB8/FR8)	\$221	\$531	\$531	\$221
		¢cr.	¢c.	¢c.	¢c.
	Extension of PSM standard contact	\$65	\$65	\$65	\$65
ED5	Parametric special module (PSM)	\$354	\$354	\$354	\$354
EES	not with ED8	¢1.40	6140	6140	¢140
	115 V socket	\$140	\$140	\$140	\$140
ES2	12 V power outlet, rear compartment	\$103	\$103	\$103	\$103
ES5	Charging package, dashboard	\$92	\$92	\$92	\$92
ET4	Active Distance Assist DISTRONIC	\$294	\$294	\$294	\$294
	must have CO3	40	10	40.1	40.0
F49	Electrically heated windshield	\$244	\$244	\$244	\$244
	no restrictions	4	4		4
F61	Interior rear view mirror	\$41	\$41	\$41	\$41
	must have E3M/C02/C03				
F64	Electrically folding exterior mirrors	\$55	\$55	\$55	\$55
<u> </u>	no restrictions				
F84	Digital Rearview Mirror	\$736	\$736	\$736	\$736
<u></u>	must have LA2- Not with F61		1		
FE9	Additional DIN-slot	\$91	\$91	\$91	\$91
FF8	Overhead storage slot, front center	\$117	\$117	\$117	\$117
FJ1	Hinged lid for storage compartment	\$105	\$105	\$105	\$105

		144" 4D High	144" 4D High AWD	170" 4D High	170" 4D High AWD
		M2CV4H	M2CV4A	M2CV7H	M2CV7A
		907.643	907.643	907.645	907.645
FR8	Rear view camera (head unit display)	\$377	\$377	\$377	\$377
	must have CO2/E3M; not with FR3/JB7; 3500XD not with JB8				
FY1	Security alarm w. interior motion sensor	\$654	\$654	\$654	\$654
	must have LC4/C00				
FY7	Optional 3-button keys	\$41	\$41	\$41	\$41
FZ9	Keys, two additional masters	\$136	\$136	\$136	\$136
H01	Heat insulation, rear compartment	\$175	\$175	\$175	\$175
	must have V25/VA3/VA1/C07/X66				
H04	Heat insulation, front compartment	\$209	\$209	\$209	\$209
	if + D50/D51 must have V07				
H12	Fuel-fired pre-heater/booster (17K BTU)	\$1,249	\$1,249	\$1,249	\$1,249
	not with HZ9				
H13	Rear cabin heater and vents	\$880	\$880	\$880	\$880
	must have V43 + (H12/HZ9); not with VK8				
H15	Heated front passenger seat	\$318	\$318	\$318	\$318
	must have H16; not with X68	•			
H88	Rear heater prep	\$453	\$453	\$453	\$453
	must have H12/HZ9; not with H13/T19	•			
H1I	Front-to-rear outlet in instrument panel	\$0	\$0	\$0	\$0
	must have FJ1/C01	•			•
HH4	Thermotronic automatic climate control	\$378	\$378	\$378	\$378
	must have JF1; if +H13 must have H08/HK4	•			•
HZ9	Fuel-fired heater booster (18,000 BTU)	\$756	\$756	\$756	\$756
	not with H12		•		•
J51	Fuel gauge, optimized for aux. fuel tap	\$80	\$80	\$80	\$80
	not with HZ9/H12	•			•
J52	Engine oil level display at cold start	\$0	\$0	\$0	\$0
JA7	Blind Spot Assist	\$504	\$504	\$504	\$504
	must have F64	•			•
JB4	Active Lane Keeping Assist	\$322	\$322	\$322	\$322
	standard with CO2/CA2	•			•
JB6	Parking Package with 360 degree camera	\$867	\$867	\$867	\$867
	must have E3M/C02/C03; not with W75/W76/JB7	•			•
JB7	Parking Package	\$688	\$688	\$688	\$688
	must have E3M/C02/C03; not with W75/W76/JB6				•
JB8	360 Degree Camera	\$766	\$766	\$766	\$766
	must have CO2/CO3/E3M, not with JB6/JB7	•			•
JF1	Rain sensor	\$118	\$118	\$118	\$118
	Standard with CO2/CA2/X11	•			•
JW0	Backup alarm	\$111	\$111	\$111	\$111
JW2	Deactivation lamp monitoring failure	\$30	\$30	\$30	\$30
	Attention Assist	\$55	\$55	\$55	\$55
K51	Misfueling prevention for Diesel	\$55	\$55	\$55	\$55
	DEF fluid filler cap - lockable	\$30	\$30	\$30	\$30
L13	Fog lamp with cornering light function	\$223	\$223	\$223	\$223
LB9	Illuminated front exits	\$170	\$170	\$170	\$170
LC4	Comfort overhead control panel	\$105	\$105	\$105	\$105
M20	Speed limitation 65 mph	\$67	\$67	\$67	\$67
	not with MD3				
M61	Alternator 14 V / 280 A	\$188	\$188	\$188	\$188

		144" 4D High	144" 4D High AWD	170" 4D High	170" 4D High AWD
		M2CV4H	M2CV4A	M2CV7H	M2CV7A
		907.643	907.643	907.645	907.645
MD3	Top speed limitation 75 mph	\$71	\$71	\$71	\$71
11123	not with M20	Ψ, 1	Ψ, ±	Ψ/1	Ψ/1
N62	Front engine bracket for additional alternator	\$523	\$523	\$523	\$523
	not with HK4/N63	ψ323	<del>4</del> 020	Ψ020	<b>4020</b>
N63	Front engine bracket for auxiliary A/C compressor	\$523	\$523	\$523	\$523
	not with HK4/N62	·			ı ·
Q24	Trailer hitch, 5,000 lbs	\$164	\$164	\$164	\$164
	not with W73/W75/W76				
QA9	Half-sided step rear (for trailer hitch)	\$113	\$113	\$113	\$113
	must have Q24/QA2; not with W73/W75/W76				
R91	Spare tire deletion	-\$110	-\$110	-\$110	-\$110
	must have R92; not with R87				
R92	Spare tire carrier deletion	\$0	\$0	\$0	\$0
	must have R91; not with R65		-		
R98	Rims painted jet black	\$91	\$91	\$91	\$91
	not with RL5/RM2		-		
RF1	Tire brand Continental	\$0	\$0	\$0	\$0
	must have RM1 + RM9		_		
RF8	Tire brand Michelin	\$0	\$0	\$0	\$0
	must have RM9; not with RM1		1		•
RH0	Tire brand Kumho	\$0	\$0	\$0	\$0
	must have RM9; not with RM1				
RL5	Light-alloy wheels 6.5 J x 16	\$1,015	\$1,015	\$1,015	\$1,015
	not with RS3/RM2/R98	1			
RM1	M+S winter tires	\$190	\$190	\$190	\$190
	must have RF1/RD9; not with RF8/RH0/X31	4	1 4	4	
RM2	Rims painted arctic white	\$91	\$91	\$91	\$91
DN 40	not with R98/RL5	¢442	Ć442	ć112	¢112
RIVI9	Specially requested tires	\$113	\$113	\$113	\$113
620	must have RF1/RF8/RH0; not with RD9	ĆE0.	ĆE0.	Ċ.C.O.	ĆE0.
	Armrest, driver and passenger door	\$58	\$58	\$58	\$58
T12	Sliding door two stage opening	\$92	\$92	\$92	\$92
T50	not with T55 Electric closing assist right sliding door	\$376	\$376	\$376	\$376
130	must have DO3; not with T55/T93	Ş3/O	Ş3/O	Ş3/ <b>0</b>	Ş3/O
T55	Electric sliding door right	\$930	\$930	\$930	\$930
133	must have DO3 + (FY7+T16); not with T12/T50	Ş <del>3</del> 30	7930	<del>9930</del>	<b>7930</b>
T57	Electric sliding step	\$1,199	\$1,199	\$1,199	\$1,199
137	must have D03 + ED5; not with T93	71,133	71,133	71,133	71,133
T60	Opening limiter electrically operated sliding door	\$134	\$134	\$134	\$134
	must have T55	Ų13 i	<b>710</b> 1	ψ <u>1</u> 31	<b>V</b> 131
T75	Door-mounted assist handles, driver & passenger	\$66	S	\$66	S
T85	Assist handle, left rear door	\$36	\$36	\$36	\$36
T86	Assist handles, right rear door	\$36	\$36	\$36	\$36
V43	Wood floor with 6 D-rings	\$473	\$473	\$473	\$473
V 7.3	not with P93/V93/VL4/VK8/C07; standard with D93/H13/V24/V52/	•	د / +ر	<b>→</b> +/3	<del>7+</del> /3
V85	Cigarette lighter & ash cup, front	\$44	\$44	\$44	\$44
	Door sill - protective edge	\$44	\$44 \$79	\$ <del>44</del> \$79	\$44 \$79
vcs	must have V43/X66; not with T19/T93/VK8/VV2/V93/C07	\$13	5/5	919	۶/۶
VIVO		6444	6414	6414	6111
VK8	Floor covering, plastic	\$414	\$414	\$414	\$414
\A/F :	not with V43/P93/T19/T93/V52/VC5/X66	4400	<b>0.402</b>	4400	4400
	Rear doors, opening to side wall	\$403	\$403	\$403	\$403
W73	Bumper step, rear, grey	\$209	\$209	\$209	\$209
	not with Q24/W75/W76				

		144" 4D High	144" 4D High AWD	170" 4D High	170" 4D High AWD
		M2CV4H	M2CV4A	M2CV7H	M2CV7A
		907.643	907.643	907.645	907.645
W75	Step, wide, at rear end	\$345	\$345	\$345	\$345
	not with JB6/JB7/Q24/QA9; must have R91+R92				
W76	Bumper step, rear, spring-loaded	\$673	-	\$673	-
	must have R91+R92; not with JB6/JB7/X55/Q24				
W78	Heated rear window(s) w/ washers/wipers	\$376	\$376	\$376	\$376
	Must have H22+VA7 / if D51 must have F61; not with W61				
X90	Deletion of Sprinter badge, left rear door	\$0	\$0	\$0	\$0
X93	Deletion of model badge, right rear door	\$0	\$0	\$0	\$0
XM4	Acoustic package	\$97	\$97	\$97	\$97
	standard with CO2/CO3				
Y10	First-aid kit	\$30	\$30	\$30	\$30
Y26	Wheel chocks	\$43	\$43	\$43	\$43
Y45	Emergency flashlight	\$30	\$30	\$30	\$30
Y68	Paint preservative	\$209	\$209	\$238	\$238
Y69	Surface protection for stock vehicles	\$352	\$352	\$352	\$352
YK3	Cargo straps, D-rings	\$91	\$91	\$91	\$91
ZH4	Downhill speed regulation for AWD	-	\$61	-	\$61
	must have ED5		·		

		144" 4D High	144" 4D High AWD	170" 4D High	170" 4D High AWD			
		M2CV4H	M2CV4A	M2CV7H	M2CV7A			
		907.643	907.643	907.645	907.645			
C00	Comfort Package	\$307	\$307	\$307	\$307			
LC4	Comfort overhead control panel	Х	Χ	X	Х			
SE4	Lumbar support, co-driver's seat	X	Χ	X	X			
SE5	Lumbar support, driver's seat	X	Χ	X	X			
SK0	Comfort head restraint, driver	X	Χ	X	X			
SK1	Comfort head restraint, co-driver	X	Χ	X	X			
must	must have COS OR X68; CA/CC only: not with S23							

COS	Comfort Package (Seat addition)	\$426	\$426	\$426	\$426	
SB1	Comfort driver's seat	Х	Х	Х	X	
SB2	Comfort passenger seat	Х	Х	Х	X	
must	must have COO					

X68	Comfort Plus Package	\$1,898	\$1,898	\$1,898	\$1,898	
H15	Heated front passenger seat	X	X	Х	X	
SF1	Driver's seat electrically adjustable	X	X	X	X	
SF2	Co-driver's seat electrically adjustable	X	Х	Х	Х	
must	must have COO and VF4 OR VF6, CA/CC only: not with S23					

C01	Driver Convenience Package	\$449	\$449	\$449	\$449
E46	12 V power outlet, driver seat base	X	X	Х	Х
F64	Electrically folding exterior mirrors	X	X	X	X
FJ1	Hinged lid for storage compartment	X	X	Х	X
FJ5	Hinged Lid for Storage Compartments left and right	Х	Х	Х	Х
FZ9	Keys, two additional masters	Х	Х	Х	Х
JW8	Attention Assist	X	Χ	X	X

C02	Premium Package	\$805	\$805	\$805	\$805
E3M	MBUX Multimedia System with 7" touchscreen	X	X	X	X
FM3	Wet Wiper System	Х	X	Х	X
JB4	Active Lane Keeping Assist	X	X	X	X
must have JF1 + XM4; must choose FR8/JB7/JB6					

CA2	C02 in combination with C03	\$547	\$547	\$547	\$547	
CL3	Leather steering wheel	X	X	X	X	
FM3	Wet Wiper System	Х	X	X	Х	
JB4	Active Lane Keeping Assist	Х	Х	Х	Х	
must	must have CO3 + JF1					

144" 4D High	144" 4D High AWD	170" 4D High	170" 4D High AWD
M2CV4H	M2CV4A	M2CV7H	M2CV7A
907.643	907.643	907.645	907.645

C03	Premium Plus Package	\$2,008	\$2,008	\$2,008	\$2,008
E1B	Tray for smartphones incl. wireless charging	X	Х	Х	Х
	Navigation	X	Х	Х	Х
EY2	Intelligent navigation	Х	Х	Х	Х
E4M	MBUX Multimedia System with 10.25" touchscreen	Х	Х	Х	Х
EX9	Free map data updates for 3 years	X	Х	Х	Х
H1I	Front-to-rear outlet in instrument panel	X	Х	Х	X
JA9	Traffic Sign Assist	X	Х	Х	X
XM4	Acoustic package	X	Х	Х	X
H1I	Front-To-Rear Outlet In Instrument Panel	Х	Х	Х	Х
must	have (CA2+(JB7/JB6/JB8)); not with FR8 and CO2		•		

X67	Chrome Grille Package	\$325	\$325	\$325	\$325	
CN2	Radiator grille frame in vehicle color	X	X	X	X	
FK3	Chrome plated radiator grille (MB only)	Х	X	Х	Х	
no res	no restrictions					

X13	Exterior Lighting Package	\$1,801	\$1,801	\$1,801	\$1,801	
L13	Fog lamp with cornering light function	Х	Х	Х	Х	
L22	Partial LED tail lights	Х	Х	Х	X	
LA1	High Beam Assist	Х	Х	Х	Х	
LG7	LED High Performance headlamps	Х	Х	Х	Х	
no res	no restrictions					

X72	Crew Van Comfort Package	\$246	\$246	\$246	\$246	
S31	Convenience Head Restraints For Pass. Comp.	X	Χ	X	Χ	
UY1	Three-seater comfort bench in passenger compartment, first row (na	Х	Х	Х	X	
can h	can have VF4/VF6 only					

X4Z	Interior Trim Upgrade Package	\$683	\$683	\$683	\$683	
VA1	Side wall paneling waist height PVC	X	X	X	X	
VA3	Side wall paneling full hardboard	X	X	X	X	
ZK4	Mixto	X	X	Х	Х	
must	must have (V43+VC5) OR VK8					

144" 4D Std	170" 4D Std
12 seats	15 seats
M2PV4S	M2PV7S
907.743	907.745

	tandard Output Engine/9-Speed Trans.		
4-Cyl S			
		S	S
ED4	AGM battery 12V 92 AH 850 A	S	S
	Automatic transmission, 9G-tronic	S	S
	Alternator 14 V / 280 A	S	S
	Approval Bio-Diesel B20	S	S
	2.0L 4-cylinder diesel engine (168hp output)	S	S
	SULEV emissions	S	S
	eating Configuration	3	3
	Standard Rear Seats	S	S
		S	S
	3-seater bench rear, 1st row (narrow)		
	3-seater bench rear, 2nd row (narrow)	S	S
	4-seater bench in rear, 3rd row	S	-
	3-seater bench in rear, 3rd row (narrow)	-	S
_	1-seater bench in rear, 4th row	-	S
Equipn			_
A50 F	Front axle reinforced	-	S
AP2	Addtl. bar for driveshaft & exhaust extension	S	S
AR2	Axle ratio 3.923	S	S
BA3	Active Brake Assist	S	S
BH1 H	Hold Function	S	S
C6L N	Multifunction steering wheel	S	S
CB1	Suspension for comfort and load protection	S	S
CL1 A	Adjustable steering wheel (angle)	S	S
CT1 F	Rear spring vibration absorbers	S	S
D03 H	High roof	0	S
E07 H	Hill Start Assist	S	S
E10 S	Standard radio	S	S
E1U l	JSB-C socket, 5 V	S	S
E30 S	Starter battery disconnect	S	S
E3J F	Pre-installation for switch panel	S	S
E40 1	Frailer hitch prep. wiring	S	-
ED8 F	Preinstallation PSM	S	S
EE5 l	Ultracapacitor discharge module	S	S
EK1 E	Body Builder Connector	S	S
EL9	Audio systems speakers, 5 front, 8 rear	S	S
ESO J	lump start terminal	S	S
ES2 1	12 V power outlet, rear compartment	S	S
EW6 F	Pre-installation for Mercedes me Remote Services	S	S
EY5 E	Emergency Call System	S	S
	Breakdown management	S	S
	_aminated glass rear	S	S
	Heated & electrically adjustable exterior mirrors	S	S
	Coat hooks	S	S
-	Cupholder rear compartment	S	S
	Shelf above windshield	S	S
	Cupholder front	S	S
	Remote key (315 mhz) w/central locking	S	S
	Hinged lid for storage compartment	S	S
	Storage compartment underneath cockpit	S	S
_	Rear view camera (rear-view mirror display)	S	S
_	Warm/cool air duct to rear compartment	S	S
H00 \	Walliftool all duct to real collinartifient		

		144" 4D Std	170" 4D Std
		12 seats	15 seats
		M2PV4S	M2PV7S
		907.743	907.745
	lu er er e e e e		
H04	Heat insulation, front compartment	S	S
H08	Air conditioning rear, roof-mounted	S	S
H13	Rear cabin heater and vents	S	S
H16	Heated driver's seat	S	S
H1I	Front-to-rear outlet in instrument panel	S	S
H21	Windshield with filter band	S	S
H22	Rear window defroster	S	S
HH2	Heater, auxiliary electric hot air	S	S
HH9	Air Condition, Front	S	S
HZ9	Fuel-fired heater booster (18,000 BTU)	S	S
IH7	Headunit	S	S
J11	Speedometer, miles and km/h	S	S
J55	Seat belt warning for co-driver seat	S	S
J58	Seat belt reminder driver	S	S
J65	Outside temperature gauge	S	S
JA8	Crosswind Assist	S	S
JH3	Communication module (LTE) for dig. services	S	S
JI9	Service interval 20.000 miles	S	S
Jk5	Instrument cluster with color display	S	S
	Black diesel filler cap	S	S
K60	Exhaust straight to rear	S	S
KB7	24.5 gallon fuel tank	S	S
M15	Fuel/water seprarator & lubrication package	S	S
KP7	4rd generation SCR emission control system	S	S
L94	Parking lights deletion	S	S
LA2	Headlight assistant	S	S
LB5	3rd brake light	S	S
LB9	Illuminated front exits	S	S
MS1	Cruise control	S	S
P47	Front mudflaps	S	S
P48	Rear mudflaps	S	S
Q00	#N/A	-	S
Q11	Longitudinal member reinforcement	S	S
Q67	Tow hook rear	S	S
R65	Spare tire bracket below frame	S	S
R87	Spare tire	S	S
RD9	Unspecified tire brand	S	S
RH8	Tires LT 245/75 R16	S	S
RM0	All-season tires	S	S
RS3	6.5 J x 16 steel wheels	S	S
RY2	Tire pressure monitoring sensors	S	S
S02	Standard driver seat	S	S
S04	Standard front passenger seat	S	S
S22	Armrest for driver's seat	S	S
S25	Armrest for front passenger seat	S	S
SA5	Front airbag, driver	S	S
SA6	Front airbag, passenger	S	S
SH1	Thorax-pelvis sidebag, driver	S	S
SH2	Thorax-pelvis sidebag, co-driver	S	S
SH9	Airbag, driver/passenger window	S	S
SK2	Seat occupancy sensor, driver's seat	S	S
SZ7	Storage net, driver's seat backrest	S	S
SZ8	Storage net, passenger seat backrest	S	S
T16	Sliding door, passenger side	S	S
	- · · · · · · /	<u> </u>	-

		144" 4D Std	170" 4D Std
		12 seats	15 seats
		M2PV4S	M2PV7S
		907.743	907.745
T74	Assist handle, B-pillar	S	S
U1A	14+1-seater version	-	S
U28	Pre-inst. for seating configuration 12-seater	S	-
U29	Pre-inst. for seating configuration 15-seater	-	S
U74	Wall-side armrest	S	S
U75	Aisle-side armrest	S	S
V21	Luxury interior Trim	S	S
V31	Window pillar trim	S	S
V35	Wheel house covering	S	S
V36	Roof trim	S	S
V39	Weight optimized plastic floor	S	S
V40	Floor anchors for rear seat bench	S	S
VA7	Storage compart. w/ net in rear doors	S	S
W02	Panel van w/windows all round	S	S
W17	2nd row, fixed window, passenger side	S	S
W22	Fixed window, center left	-	S
W23	Fixed window, center right	-	S
W27	Fixed window, rear left	S	S
W28	Fixed window, rear right	S	S
W33	FMVSS 217 emergency exit	S	S
W61	Windows in rear doors	S	S
W70	Black tinting (90%) for rear windows	S	S
X2B	GVWR 9,480 lbs. / 4,300 kg	-	S
XL2	GVWR 9,050 lbs. / 4.100 Kg	S	-
X64	Plates/booklets in English (US)	S	S
X99	Manufacturer Mercedes-Benz AG	S	S
XC8	VIN visible from outside	S	S
XI2	Change Year G2-I	S	S
XY4	Model Year 2024	S	S
Y43	Jack, hydraulic	S	S
ZU8	USA country version	S	S
ZZ4	Brand content Mercedes-Benz North America	S	S

		144" 4D Std	170" 4D Std
		12 seats	15 seats
		M2PV4S	M2PV7S
		907.743	907.745
B25	Electric parking brake	\$313	\$313
C72	Bumpers front/rear primed	\$300	\$300
-	must have CN2/X67, not with CM0	7000	7000
CB7	Stabilization Level I	\$344	\$344
	not with A4M/X55	70	7011
CM0	Painted metallic front & rear bumper	\$657	\$657
	must have CN2 (part of X67) + (JA7/C01) + (JB6/JB7) + (7755/9197/97	•	7001
CM9	Primed side moldings	\$408	\$408
D03	High roof	\$3,500	S
D13	Mounting rails for roof rack	\$336	\$336
E1B	Tray for smartphones incl. wireless charging	\$175	\$175
	must have CO2/E3M	Ψ270	<b>41.0</b>
E1E	Navigation	\$815	\$815
	must have CO2/E3M, not with CO3	ψ020	<b>4020</b>
E1S	Sirius XM, satellite radio	\$285	\$285
	must have CO2/E3M/CO3	Ψ200	<b>¥</b> 200
E1R	Additional Fuses (40/80/150/100 Ampere)	\$57	\$57
	must have X2R/ not with E1Y	Ų,	ŲJ,
E2A	Access point for BB special signals in cockpit	\$32	\$32
E2I	Additional battery, co-driver seat base	\$277	\$277
	Must have E36; not with E2M	γ2,,	Ψ2.,,
E36	Cutoff relay for additional battery	\$124	\$124
	standard with E2I/E2M	<b>712</b> 4	<b>7124</b>
E3M	MBUX Multimedia System with 7" touchscreen	\$531	\$531
LOW	not with CO2/CO3; must have JK5+(JB7/JB6/JB8/FR8)	<del>-</del>	\$331
E5M	Extension of PSM standard contact	\$65	\$65
ED5	Parametric special module (PSM)	\$354	\$354
LDJ	not with ED8	<del>-</del>	<del>3</del> 334
EE3	115 V socket	\$140	\$140
ES5	Charging package, dashboard	\$92	\$92
ET4	Active Distance Assist DISTRONIC	\$294	\$294
	must have CO3	<b>7234</b>	Ş2J <del>4</del>
F49	Electrically heated windshield	\$244	\$244
	Interior rear view mirror	\$0	\$0
	must have CO2/CO3/E3M	ΨO	ΨO
F64	Electrically folding exterior mirrors	\$55	\$55
F84	Digital Rearview Mirror	\$736	\$736
	must have LA2/ not with F61	φ.σσ	φ
FE9	Additional DIN-slot	\$91	\$91
FF8	Overhead storage slot, front center	\$117	\$117
FR8	Rear view camera (head unit display)	\$377	\$377
	must have CO2/E3M; not with FR3/JB7/JB6/JB8	,	+
FY1	Security alarm w. interior motion sensor	\$654	\$654
	must have LC4/C00	,	
FY7	Optional 3-button keys	\$41	\$41
FZ9	Keys, two additional masters	\$136	\$136
H12	Fuel-fired pre-heater/booster (17K BTU)	\$925	\$925
	not with HZ9/J51/KL1	,	
H15	Heated front passenger seat	\$318	\$318
	must have H16; not with X68		

		144" 4D Std	170" 4D Std 15 seats M2PV7S 907.745
		12 seats	
		M2PV4S	
		907.743	
	I	4070	
HH4	Thermotronic automatic climate control	\$378	\$378
15.4	must have JF1	400	400
J5 1	Fuel gauge, optimized for aux. fuel tap	\$80	\$80
15.0	not with HZ9/H12	40	Ġ0.
J52	Engine oil level display at cold start	\$0	\$0
JA7	Blind Spot Assist	\$504	\$504
ID 4	must have F64	ćaaa	6222
JB4	Active Lane Keeping Assist	\$322	\$322
ID.	standard with CO2/CA2	¢067	¢0C7
JB6	Parking Package with 360 degree camera	\$867	\$867
ID 7	must have CO2/CO3/E3M; not with JB7	¢coo.	¢coo
JB7	Parking Package	\$688	\$688
IDO	must have CO2/CO3/E3M; not with JB6	¢7CC	¢ZCC
JB8	360 Degree Camera	\$766	\$766
JF1	must have CO2/CO3/E3M, not with JB6/JB7	\$118	\$118
JF I	Rain sensor	\$110	\$110
JW0	Standard with C02/CA2/X11 Backup alarm	\$111	\$111
JW2	Deactivation lamp monitoring failure	\$38	\$38
JW8	Attention Assist	\$55	\$55
K51	Misfueling prevention for Diesel	\$55	\$55
K52	DEF fluid filler cap - lockable	\$30	\$30
L13	Fog lamp with cornering light function	\$223	\$223
LC4	Comfort overhead control panel	\$105	\$105
M20	Speed limitation 65 mph	\$67	\$67
IVIZO	not with MD3	<b>, 707</b>	707
MD3		\$71	\$67
WIDO	not with M20	7/1	<b>307</b>
N62	Front engine bracket for additional alternator	\$523	\$523
1102	not with X11	<b>\$323</b>	Ų323
Q24	Trailer hitch, 5,000 lbs	\$164	-
QZ-T	not with W73	Ş10 <del>1</del>	
QA9	Half-sided step rear (for trailer hitch)	\$113	-
ω, ι,	must have Q24, not with W73	<b>7113</b>	
R91	Spare tire deletion	-\$110	-\$110
, .	must have R92; not with R87	<b>Y</b> 110	<b></b>
R92	Spare tire carrier deletion	\$0	\$0
	must have R91; not with R65	7.5	7-
R98	Rims painted jet black	\$91	\$91
	not with RL5/RM2	Y	77-
RF1	Tire brand Continental	\$0	\$0
	must have RM1 + RM9	70	7-
RF8	Tire brand Michelin	\$0	\$0
	must have RM9; not with RM1	7 -	, -
RH0	Tire brand Kumho	\$0	\$0
	must have RM9; not with RM1		
RL5	Light-alloy wheels 6.5 J x 16	\$1,015	\$1,015
	not with RS3/RM2/R98	. ,	
RM1	M+S winter tires	\$190	\$190
	must have RF1/RD9; not with RF8/RH0		
RM2	Rims painted arctic white	\$91	\$91
	not with R98/RL5		

		144" 4D Std	170" 4D Std 15 seats M2PV7S 907.745
		12 seats	
		M2PV4S	
		907.743	
RM9	Specially requested tires	\$113	\$113
	must have RF1/RF8/RH0; not with RD9		
S28	Armrest, driver and passenger door	\$58	\$58
T12	Sliding door two stage opening	\$92	\$92
	not with T55/X71		
T50	Electric closing assist right sliding door	\$376	\$376
	must have D03; not with T55		
T55	Electric sliding door right	\$930	\$930
	must have D03 + (FY7+T16); not with T12/T50		
T57	Electric sliding step	\$1,199	\$1,199
	must have ED5	•	
T60	Opening limiter electrically operated sliding door	\$134	\$134
	must have T55	•	
T75	Door-mounted assist handles, driver & passenger	\$66	\$66
T85	Assist handle, left rear door	\$36	\$36
T86	Assist handles, right rear door	\$36	\$36
V85	Cigarette lighter & ash cup, front	\$44	\$44
V4A	Full paneling, right sliding door	\$123	\$123
	must have D03+VA5	•	
VA5	Full paneling, hinged rear doors	\$43	\$43
	must have DO3	•	
W54	Rear doors, opening to side wall	\$403	\$403
W73	Bumper step, rear, grey	\$209	\$209
	not with Q24	•	
W78	Heated rear window(s) w/ washers/wipers	\$376	\$376
	not with W61	•	
X90	Deletion of Sprinter badge, left rear door	\$0	\$0
X93	Deletion of model badge, right rear door	\$0	\$0
XM4	Acoustic package	\$97	\$97
	standard with C02/C03	•	
Y10	First-aid kit	\$30	\$30
Y45	Emergency flashlight	\$30	\$30
Y68	Paint preservative	\$209	\$238
Y69	Surface protection for stock vehicles	\$352	\$352

144" 4D Std	170" 4D Std
12 seats	15 seats
M2PV4S	M2PV7S
907.743	907.745

C00	Comfort Package	\$307	\$307
LC4	Comfort overhead control panel	X	X
SE4	Lumbar support, co-driver's seat	X	X
SE5	Lumbar support, driver's seat	X	X
SK0	Comfort head restraint, driver	X	X
SK1	Comfort head restraint, co-driver	Х	X
must	must have S28 + (COS OR X68); not with S23		

COS	Comfort Package (Seat addition)	\$426	\$426
SB1	Comfort driver's seat	X	X
SB2	Comfort passenger seat	Х	Х
must	have COO		

X68	Comfort Plus Package	\$1,898	\$1,898
H15	Heated front passenger seat	Х	X
SF1	Driver's seat electrically adjustable	Х	X
SF2	Co-driver's seat electrically adjustable	Х	X
must	must have COO and VF4 OR VF6, CA/CC only: not with S23		

C01	Driver Convenience Package	\$449	\$449
E46	12 V power outlet, driver seat base	X	X
F64	Electrically folding exterior mirrors	X	X
FJ1	Hinged lid for storage compartment	S	S
FJ5	Hinged Lid for Storage Compartments left and right	X	X
FZ9	Keys, two additional masters	X	X
JW8	Attention Assist	X	X
no re	strictions		

C02	Premium Package	\$805	\$805	
E3M	MBUX Multimedia System with 7" touchscreen	Х	Х	
FM3	Wet Wiper System	X	X	
JB4	Active Lane Keeping Assist	X	X	
must	must have JF1 + XM4; must choose FR8/JB7/JB6			

CA2	C02 in combination with C03	\$547	\$547		
CL3	Leather steering wheel	Х	Х		
FM3	Wet Wiper System	Х	X		
JB4	Active Lane Keeping Assist	Х	X		
must have CO3 + JF1					

144" 4D Std	170" 4D Std
12 seats	15 seats
M2PV4S	M2PV7S
907.743	907.745

C03	Premium Plus Package	\$2,008	\$2,008		
E1B	Tray for smartphones incl. wireless charging	X	X		
	Navigation	X	X		
EY2	Intelligent navigation	X	X		
E4M	MBUX Multimedia System with 10.25" touchscreen	X	X		
EX9	Free map data updates for 3 years	X	X		
H1I	Front-to-rear outlet in instrument panel	X	X		
JA9	Traffic Sign Assist	X	X		
XM4	Acoustic package	X	X		
must	must have (CA2+(JB7/JB6/JB8)); not with FR8 and CO2				

X67	Chrome Grille Package	\$325	\$325		
CN2	Radiator grille frame in vehicle color	X	X		
FK3	Chrome plated radiator grille (MB only)	X	X		
no re	no restrictions				

X13	Exterior Lighting Package	\$1,801	\$1,801		
L13	Fog lamp with cornering light function	X	X		
L22	Partial LED tail lights	X	X		
LA1	High beam assist	Х	X		
LG7	LED high performance headlamps	Х	X		
no re	no restrictions				

X70	Rear Comfort Package	\$1,703	\$1,703	
S31	Convenice head restraints for pass. compartment	X	X	
U3Y	3-seater comfort bench rear - 3rd row (narrow)	-	X	
UY1	3-seater comfort bench rear, 1st row (narrow)	X	Х	
UY2	3-seater comfort bench rear, 2nd row (narrow)	X	Х	
UY3	4-seater comfort bench rear, 3rd row	X	-	
UY6	4-seater comfort bench rear, 4th row	-	Х	
can h	can have VF4/VF6 only			

X71	Passenger Accessibility Package	\$1,684	\$1,684
T55	Electric sliding door right	X	X
ED5	Parametric special module (PSM)	X	X
T57	Electric sliding step	X	X
FY7	Optional 3-button keys	X	X

Opening limiter for electrically operated sliding door (T60) can be added in combination with the package

X11	High-Performance Rear Air Conditioning Package	\$1,258	\$1,258		
HK4	Rear air conditioner, heavyduty	X	X		
HH4	Thermotronic automatic climate control	Х	Х		
must	must have D03; HK4 n/a on gas models				

Engine  4-Cyl High Output Engine/9-Spe ED4 AGM battery 12V 92 AH 8 G43 Automatic transmission, 9 M61 Alternator 14 V / 280 A M5N 2.0L 4-cylinder diesel engi MH8 SULEV emissions	50 A	12 seats M2PV4H 907.743  S S	12 seats M2PV4A 907.743	15 seats M2PV7H 907.745
4-Cyl High Output Engine/9-Spe ED4 AGM battery 12V 92 AH 8 G43 Automatic transmission, 9 M61 Alternator 14 V / 280 A M5N 2.0L 4-cylinder diesel engi MH8 SULEV emissions	50 A	907.743 S	907.743	
4-Cyl High Output Engine/9-Spe ED4 AGM battery 12V 92 AH 8 G43 Automatic transmission, 9 M61 Alternator 14 V / 280 A M5N 2.0L 4-cylinder diesel engi MH8 SULEV emissions	50 A	S		907.745
4-Cyl High Output Engine/9-Spe ED4 AGM battery 12V 92 AH 8 G43 Automatic transmission, 9 M61 Alternator 14 V / 280 A M5N 2.0L 4-cylinder diesel engi MH8 SULEV emissions	50 A		S	
ED4 AGM battery 12V 92 AH 8 G43 Automatic transmission, 9 M61 Alternator 14 V / 280 A M5N 2.0L 4-cylinder diesel engi MH8 SULEV emissions	50 A		ς	
ED4 AGM battery 12V 92 AH 8 G43 Automatic transmission, 9 M61 Alternator 14 V / 280 A M5N 2.0L 4-cylinder diesel engi MH8 SULEV emissions	50 A	S		S
M61 Alternator 14 V / 280 A M5N 2.0L 4-cylinder diesel engi MH8 SULEV emissions	G-tronic		S	S
M5N 2.0L 4-cylinder diesel engi MH8 SULEV emissions		S	S	S
MH8 SULEV emissions		S	S	S
	ne (208hp output)	S	S	S
		S	S	S
X55 All Wheel Drive Package		-	\$6,700	-
T75 Door-mounted assist hand	lles, driver & passenger	-	S	-
A4M All Wheel Drive with torqu	ue on demand	-	S	-
Rear Seating Configuration				
X7S Standard Rear Seats		S	S	S
U62 3-seater bench rear, 1st ro	ow (narrow)	S	S	S
UC3 3-seater bench rear, 2nd r	ow (narrow)	S	S	S
UD6 4-seater bench in rear, 3rd	d row	S	S	-
U3S 3-seater bench in rear, 3rd	d row (narrow)	-	-	S
UD7 4-seater bench in rear, 4th	n row	-	-	S
Equipment				
A50 Front axle reinforced		-	-	S
AP2 Addtl. bar for driveshaft &	exhaust extension	S	S	S
AR2 Axle ratio 3.923		S	S	S
BA3 Active Brake Assist		S	S	S
BH1 Hold Function		S	S	S
C6L Multifunction steering wh	eel	S	S	S
CB1 Suspension for comfort ar	nd load protection	S	-	S
CL1 Adjustable steering wheel	(angle)	S	S	S
CT1 Rear spring vibration abso	rbers	S	S	S
D03 High roof		0	0	S
E07 Hill Start Assist		S	S	S
E10 Standard radio		S	S	S
E1U USB-C socket, 5 V		S	S	S
E30 Starter battery disconnect		S	S	S
E3J Pre-installation for switch	panel	S	S	S
E40 Trailer hitch prep. wiring		S	S	-
ED8 Preinstallation PSM		S	S	S
EE5 Ultracapacitor discharge n	nodule	S	S	S
EK1 Body Builder Connector		S	S	S
EL9 Audio systems speakers, 5	front, 8 rear	S	S	S
ESO Jump start terminal		S	S	S
ES2 12 V power outlet, rear co	•	S	S	S
EW6 Pre-installation for Merce	des me Remote Services	S	S	S
EY5 Emergency Call System		S	S	S
EY6 Breakdown management		S	S	S
F43 Laminated glass rear		S	S	S
F68 Heated & electrically adjust	stable exterior mirrors	S	S	S
FFO Coat hooks	ont	S	S	S
FF3 Cupholder rear compartm	ent	S	S	S
FF5 Shelf above windshield		S	S	S
FG8 Cupholder front	control locking	S	S	S S
FI1 Remote key (315 mhz) w/		S	S	
FJ1 Hinged lid for storage com FJ4 Storage compartment und		S S	S S	S S
FJ4 Storage compartment und FR3 Rear view camera (rear-view)	•	S	S	<u> </u>

144" 4D High 44" 4D High AW 170" 4D High

		144" 4D High	44" 4D High AW	170" 4D High
		12 seats	12 seats	15 seats
		M2PV4H	M2PV4A	M2PV7H
		907.743	907.743	907.745
H00	Warm/cool air duct to rear compartment	S	S	S
H01	Heat insulation, rear compartment	S	S	S
	Heat insulation, front compartment	S	S	S
H08	Air conditioning rear, roof-mounted	S	S	S
H13	Rear cabin heater and vents	S	S	S
H1I	Front-to-rear outlet in instrument panel	S	S	S
H16	Heated driver's seat	S	S	S
H21	Windshield with filter band	S	S	S
H22	Rear window defroster	S	S	S
HH2	Heater, auxiliary electric hot air	S	S	S
нн9	Air Condition, Front	S	S	S
HZ9	Fuel-fired heater booster (18,000 BTU)	S	S	S
IH7	Headunit	S	S	S
J11	Speedometer, miles and km/h	S	S	S
J55	Seat belt warning for co-driver seat	S	S	S
J58	Seat belt reminder driver	S	S	S
J65	Outside temperature gauge	S	S	S
JA8	Crosswind Assist	S	S	S
JH3	Communication module (LTE) for dig. services	S	S	S
JI9	Service interval 20.000 miles	S	S	S
JK5	Instrument cluster with color display	S	S	S
	Black diesel filler cap	S	S	S
K60	Exhaust straight to rear	S	S	S
KB7	24.5 gallon fuel tank	S	S	S
M15	Fuel/water seprarator & lubrication package	S	S	S
KP7	4rd generation SCR emission control system	S	S	S
L94	Parking lights deletion	S	S	S
LA2	Headlight assistant	S	S	S
LB5	3rd brake light	S	S	S
LB9	Illuminated front exits	S	S	S
_	Cruise control	S	S	S
	Front mudflaps	S	S	S
	Rear mudflaps	S	S	S
	tbd	-	-	S
	Longitudinal member reinforcement	S	S	S
Q67	Tow hook rear	S	S	S
R65	Spare tire bracket below frame	S	S	S
R87	Spare tire	S	S	S
RD9	Unspecified tire brand	S	S	S
RH8	Tires LT 245/75 R16	S S	S S	S S
	All-season tires	S S	S	S S
RS3 RY2	6.5 J x 16 steel wheels  Tire pressure monitoring sensors	S	S	S
S02	Tire pressure monitoring sensors Standard driver seat	S	S	S
S04	Standard driver seat Standard front passenger seat	S	S	S S
S22	Armrest for driver's seat	S	S	S S
S25	Armrest for front passenger seat	S	S	S S
SA5	Front airbag, driver	S	S	S
SA6	Front airbag, passenger	S	S	S
	Thorax-pelvis sidebag, driver	S	S	S
SH2	Thorax-pelvis sidebag, co-driver	S	S	S S
SH9	Airbag, driver/passenger window	S	S	S
SK2	Seat occupancy sensor, driver's seat	S	S	S S
SZ7	Storage net, driver's seat backrest	S	S	S S
JL /	Storage net, anver 3 seat Dackiest	3	3	J

		144" 4D High	144" 4D High 44" 4D High AW	
		12 seats	12 seats	15 seats
		M2PV4H	M2PV4A	M2PV7H
		907.743	907.743	907.745
SZ8	Storage net, passenger seat backrest	S	S	S
T16	Sliding door, passenger side	S	S	S
T74	Assist handle, B-pillar	S	S	S
U1A	14+1-seater version	-	-	S
U28	Pre-inst. for seating configuration 12-seater	S	S	-
U29	Pre-inst. for seating configuration 15-seater	-	-	S
U74	Wall-side armrest	S	S	S
U75	Aisle-side armrest	S	S	S
V21	Luxury interior Trim	S	S	S
V31	Window pillar trim	S	S	S
V35	Wheel house covering	S	S	S
V36	Roof trim	S	S	S
V39	Weight optimized plastic floor	S	S	S
V40	Floor anchors for rear seat bench	S	S	S
VA7	Storage compart. w/ net in rear doors	S	S	S
W02	Panel van w/windows all round	S	S	S
W17	2nd row, fixed window, passenger side	S	S	S
W22	Fixed window, center left	-	-	S
W23	Fixed window, center right	-	-	S
W27	Fixed window, rear left	S	S	S
W28	Fixed window, rear right	S	S	S
W33	FMVSS 217 emergency exit	S	S	S
W61	Windows in rear doors	S	S	S
W70	Black tinting (90%) for rear windows	S	S	S
X2B	GVWR 9,480 lbs. / 4,300 kg	-	-	S
XL2	GVWR 9,050 lbs. / 4.100 Kg	S	S	-
X64	Plates/booklets in English (US)	S	S	S
X99	Manufacturer Mercedes-Benz AG	S	S	S
XC8	VIN visible from outside	S	S	S
XI2	Change Year G2-I	S	S	S
XY4	Model Year 2024	S	S	S
Y43	Jack, hydraulic	S	S	S
ZU8	USA country version	S	S	S
ZZ4	Brand content Mercedes-Benz North America	S	S	S

12 sec   M2PV   907.7	4H M2PV4A	15 seats
B25 Electric parking brake		
B25 Electric parking brake \$31: CB7 Stabilization Level 1 \$334: not with A4M/X55 C72 Bumpers front/rear primed \$300 must have CN2/X67, not with CMO CMO Painted metallic front & rear bumper \$65: must have CN2 (part of X67) + (JA7/C01) + (JB6/JB7) + (7755/9197/9775) CM9 Primed side moldings \$400 D03 High roof \$3,50 D13 Mounting rails for roof rack \$336 E1B Tray for smartphones incl. wireless charging \$17: must have CO2/E3M E1E Navigation \$81: must have CO2/E3M, not with CO3 E1S Sirius XM, satellite radio \$28: must have CO2/E3M/CO3 E1R Additional Fuses (40/80/150/100 Ampere) \$57 must have X2R/ not with E1Y E2A Access point for B8 special signals in cockpit \$32 E2I Additional battery, co-driver seat base \$27: Must have E36; not with E2M E30 Cutoff relay for additional battery \$12 standard with E2J/E2M E3M MBUX Multimedia System with 7" touchscreen \$53: not with CO2/CO3; must have JK5+(JB7/JB6/JB8/FR8) E5M Extension of PSM standard contact \$65 E05 Parametric special module (PSM) \$35 not with E08 E63 115 V socket \$144 E55 Charging package, dashboard \$92 E74 Active Distance Assist DISTRONIC \$296 must have CO3/CO3/E3M F64 Electrically heated windshield \$244 E65 Charging package, dashboard \$92 E74 Active Distance Assist DISTRONIC \$296 must have CO3/CO3/E3M E64 Electrically folding exterior mirror \$0 must have CO3/CO3/E3M E65 Digital Rearview Mirror \$730 must have CO3/CO3/E3M E66 Electrically folding exterior mirrors \$95 no restrictions E76 Overhead storage slot, front center \$911 E778 Rear view camera (head unit display) \$937 must have CO3/E3M; not with F61 E789 Rear view camera (head unit display) \$937 must have CO3/E3M; not with F63/B6/JB8/B6/JB8 E77 Security alarm w. interior motion sensor \$655 must have LC4/CO00	43 907.743	M2PV7H
CB7 Stabilization Level I	•	907.745
CB7         Stabilization Level I         \$344           not with AAM/X55         \$300           C72         Bumpers front/rear primed         \$300           must have CN2/K67, not with CMO         \$655           CM0         Painted metallic front & rear bumper         \$655           must have CN2 (part of X67) + (IAT/C01) + (IB6/IB7) + (7755/9197/9775)         \$400           D31         High roof         \$3,56           D31         Mounting rails for roof rack         \$333           E1B         Tray for smartphones incl. wireless charging         \$175           must have CO2/E3M         \$815           E1E         Navigation         \$815           must have CO2/E3M, not with CO3         \$815           E1S         Sirius XM, satellite radio         \$285           must have CO2/E3M/CO3         \$815           E1R         Additional Fuses (40/80/150/100 Ampere)         \$57           must have X2R/ not with E1Y         \$22           E2A         Access point for BB special signals in cockpit         \$32           E21         Additional battery, co-driver seat base         \$277           Must have E36, not with E2M         \$12           E34         Cutoff relay for additional battery         \$12           <	3 \$313	\$313
not with A4M/X55         \$300           C72         Bumpers front/rear primed         \$300           must have CN2/X67, not with CMO         \$650           CMO         Painted metallic front & rear bumper         \$650           must have CN2 (part of X67) + (IAT/C01) + (IB6/IB7) + (7755/9197/9775)         \$300           CM9         Primed side moldings         \$400           D03         High roof         \$336           E18         Tray for smartphones incl. wireless charging         \$175           must have CO2/E3M         \$310           E18         Iray for smartphones incl. wireless charging         \$175           must have CO2/E3M         \$181           must have CO2/E3M         \$181           must have CO2/E3M         \$281           must have CO2/E3M, not with CO3         \$181           E18         Sirius XM, satellite radio         \$285           must have CO2/E3M/CO3         \$281           E18         Additional Fuses (40/80/150/100 Ampere)         \$57           must have CO2/E3M/CO3         \$281           E21         Additional battery, co-driver seat base         \$277           Must have E36; not with E2M         \$120           E30         Cutoff relay for additional battery         \$12     <		\$344
C72 Bumpers front/rear primed	+ 5544	\$544
must have CN2/K67, not with CM0  CM0 Painted metallic front & rear bumper must have CN2 (part of K67) + (IA7/C01) + (IB6/IB7) + (7755/9197/9775)  CM9 Primed side moldings S400  D31 High roof S3,55  D13 Mounting rails for roof rack E1B Tray for smartphones incl. wireless charging must have CO2/E3M  E1E Navigation must have CO2/E3M, not with CO3  E1S Sirius XM, satellite radio must have CO2/E3M/CO3  E1R Additional Fuses (40/80/150/100 Ampere) S57 must have X2R/ not with E1Y  E2A Access point for BB special signals in cockpit S21 Additional battery, co-driver seat base Must have E36; not with E2M  E36 Cutoff relay for additional battery standard with E2I/E2M  E3M MBUX Multimedia System with 7" touchscreen soft with CO2/C03; must have JK5+(JB7/JB6/JB8/FR8)  E5M Extension of PSM standard contact ED5 Parametric special module (PSM) safe since with E0B  E55 Charging package, dashboard S55 not with E0B  E61 Its V socket E55 Charging package, dashboard S92  E74 Active Distance Assist DISTRONIC must have CO3/E3M  E64 Electrically heated windshield F65 Lectrically folding exterior mirrors must have CO3/E3M  E64 Electrically folding exterior mirrors must have CO3/E3M/Rot Society F65 Overhead storage slot, front center F67 Additional DIN-slot F68 Rear view camera (head unit display) must have CO2/E3M; not with F61 F69 Additional DIN-slot must have CO2/E3M; not with F73/JB7/JB6/JB8 F71 Security alarm w. interior motion sensor S65 must have LC4/C00	0 \$300	\$300
CMO Painted metallic front & rear bumper  must have CN2 (part of X67) + (IAT/C01) + (IB6/IB7) + (7755/9197/9775)  CM9 Primed side moldings  \$400  D13 High roof  D13 Mounting rails for roof rack  E1B Tray for smartphones incl. wireless charging  must have CO2/E3M  E1E Navigation  E1S Sirius XM, satellite radio  must have CO2/E3M/C03  E1R Additional Fuses (40/80/150/100 Ampere)  must have X2R/ not with E1Y  E2A Access point for BB special signals in cockpit  E21 Additional battery, co-driver seat base  Must have E36; not with E2M  E36 Cutoff relay for additional battery  standard with E2I/E2M  E3M MBUX Multimedia System with 7" touchscreen  not with CO2/C03; must have JK5+(JB7/JB6/JB8/FR8)  E5M Extension of PSM standard contact  E5D5 Parametric special module (PSM)  not with ED8  E53 115 V socket  E55 Charging package, dashboard  E174 Active Distance Assist DISTRONIC  must have CO3/C03/E3M  F64 Electrically heated windshield  \$244  E665  E676 PB Padra William PSM	5300	\$300
must have CN2 (part of X67) + (JA7/C01) + (JB6/JB7) + (7755/9197/9775)  CM9 Primed side moldings \$406 Primed side moldings \$3,50  D13 Mounting rails for roof rack \$336 E1B Tray for smartphones incl. wireless charging \$175 must have CO2/E3M  E1E Navigation \$815 must have CO2/E3M, not with CO3  E1S Sirius XM, satellite radio \$288 must have CO2/E3M/CO3  E1R Additional Fuses (40/80/150/100 Ampere) \$57 must have X2R/ not with E1Y  E2A Access point for BB special signals in cockpit \$32 E21 Additional battery, co-driver seat base \$277 Must have E36; not with E2M  E36 Cutoff relay for additional battery \$124 standard with E2I/E2M  E3M MBUX Multimedia System with 7" touchscreen \$537 not with CO2/CO3; must have JK5+(JB7/JB6/JB8/FR8)  E5M Extension of PSM standard contact \$65 ED5 Parametric special module (PSM) \$356 not with ED8  E3 115 V socket \$144 E55 Charging package, dashboard \$92 E14 Active Distance Assist DISTRONIC \$296 must have CO3/E3M  E64 Electrically heated windshield \$244 E65 Interior rear view mirror \$0 must have CO3/E3M  E64 Electrically folding exterior mirrors \$55 mo restrictions E65 Additional DIN-slot \$91 E78 Qverhead storage slot, front center \$117 E78 Rear view camera (head unit display) must have CO2/E3M; not with FR3/JB7/JB6/JB8 E71 Security alarm w. interior motion sensor \$656 must have LC4/CO0	7 \$657	\$657
CM9         Primed side moldings         \$400           D03         High roof         \$3,50           D13         Mounting rails for roof rack         \$336           E1B         Tray for smartphones incl. wireless charging         \$175           must have C02/E3M         \$175           E1E         Navigation         \$815           must have C02/E3M, not with C03         \$285           E1S         Sirius XM, satellite radio         \$285           must have C02/E3M/C03         \$285           E1R         Additional Fuses (40/80/150/100 Ampere)         \$57           must have X2R/ not with E1Y         \$22           E2A         Access point for BB special signals in cockpit         \$32           E21         Additional battery, co-driver seat base         \$277           Must have E36; not with E2M         \$32           E36         Cutoff relay for additional battery         \$12           standard with E2I/E2M         \$32           E3M         MBUX Multimedia System with 7" touchscreen         \$53:           not with C02/C03; must have JK5+(JB7/JB6/JB8/FR8)         \$53:           E5M         Extension of PSM standard contact         \$65           E5D         Parametric special module (PSM)         \$35:	7 3037	Ş03 <i>1</i>
D03 High roof \$3,50 D13 Mounting rails for roof rack \$336 E1B Tray for smartphones incl. wireless charging \$177 must have CO2/E3M E1E Navigation \$811 must have CO2/E3M, not with CO3 E1S Sirius XM, satellite radio \$285 must have CO2/E3M/CO3 E1R Additional Fuses (40/80/150/100 Ampere) \$57 must have X2R/ not with E1Y E2A Access point for BB special signals in cockpit \$32 E2I Additional battery, co-driver seat base \$277 Must have E36; not with E2M E36 Cutoff relay for additional battery \$126 Standard with E2I/E2M E3M MBUX Multinedia System with 7" touchscreen \$530 mot with CO2/CO3; must have JK5+(JB7/JB6/JB8/FR8) E5M Extension of PSM standard contact \$550 ED5 Parametric special module (PSM) \$356 not with ED8 EE3 115 V socket \$144 E55 Charging package, dashboard \$992 E14 Active Distance Assist DISTRONIC \$296 must have CO2/CO3/E3M E64 Electrically heated windshield \$244 E65 Interior rear view mirror \$0 must have CO2/CO3/E3M E65 Clearging package, dashboard \$555 mo restrictions E66 Digital Rearview Mirror \$500 must have CO2/CO3/E3M E67 Digital Rearview Mirror \$736 must have LO2/CO3/E3M; not with F61 E69 Additional DIN-slot \$91 EFR Rear view camera (head unit display) must have CO2/E3M; not with F78/JB7/JB6/JB8 E71 Security alarm w. interior motion sensor \$656 must have LC4/COO	8 \$408	\$408
D13 Mounting rails for roof rack  E1B Tray for smartphones incl. wireless charging  must have C02/E3M  E1E Navigation  E1S Sirius XM, satellite radio  must have C02/E3M/C03  E1R Additional Fuses (40/80/150/100 Ampere)  must have X2R/ not with E1Y  E2A Access point for BB special signals in cockpit  E2I Additional battery, co-driver seat base  E2I Additional battery, co-driver seat base  E3C Cutoff relay for additional battery  standard with E2I/E2M  E3M MBUX Multimedia System with 7" touchscreen  not with C02/C03; must have JK5+(JB7/JB6/JB8/FR8)  E5M Extension of PSM standard contact  E5S Charging package, dashboard  E3S Charging package, dashboard  E4S Charging package, dashboard  E5S Charging package, dashboard  E6 Electrically heated windshield  E64 Electrically heated windshield  E65 Digital Rearview Mirror  must have C02/C03/E3M  E64 Electrically folding exterior mirrors  more strictions  E78 Additional DiN-slot  E78 Rear view camera (head unit display)  must have C02/E3M; not with F61  E78 Rear view camera (head unit display)  must have C02/E3M; not with FR3/JB7/JB6/JB8  E71 Security alarm w. interior motion sensor  must have C02/E3M; not with FR3/JB7/JB6/JB8  E71 Security alarm w. interior motion sensor  must have LC4/C00	· · · · · · · · · · · · · · · · · · ·	
E1B Tray for smartphones incl. wireless charging  must have C02/E3M  E1E Navigation  must have C02/E3M, not with C03  E1S Sirius XM, satellite radio  must have C02/E3M/C03  E1R Additional Fuses (40/80/150/100 Ampere)  must have X2R/ not with E1Y  E2A Access point for BB special signals in cockpit  E2I Additional battery, co-driver seat base  Must have E36; not with E2M  E36 Cutoff relay for additional battery  standard with E2I/E2M  E3M MBUX Multimedia System with 7" touchscreen  not with C02/C03; must have JK5+(JB7/JB6/JB8/FR8)  E5M Extension of PSM standard contact  E5D Parametric special module (PSM)  not with ED8  E3 115 V socket  E31 115 V socket  E55 Charging package, dashboard  E74 Active Distance Assist DISTRONIC  must have C03  E149 Electrically heated windshield  E61 Interior rear view mirror  must have C02/C03/E3M  F64 Electrically folding exterior mirrors  no restrictions  E84 Digital Rearview Mirror  must have L02/C03/E3M; not with F61  FF9 Additional DIN-slot  FR8 Rear view camera (head unit display)  must have C02/E3M; not with FR3/JB7/JB6/JB8  FY1 Security alarm w. interior motion sensor  must have L02/C00  must have L02/C00  must have L02/C00  must have C02/E3M; not with FR3/JB7/JB6/JB8  FY1 Security alarm w. interior motion sensor  must have L02/C00		\$336
must have CO2/E3M  E1E Navigation \$81:  must have CO2/E3M, not with CO3  E1S Sirius XM, satellite radio \$28:  must have CO2/E3M/CO3  E1R Additional Fuses (40/80/150/100 Ampere) \$57  must have X2R/ not with E1Y  E2A Access point for BB special signals in cockpit \$32  E2I Additional battery, co-driver seat base \$277  Must have E36; not with E2M  E36 Cutoff relay for additional battery \$126  standard with E2I/E2M  E3M MBUX Multimedia System with 7" touchscreen \$53:  not with CO2/CO3; must have JK5+(JB7/JB6/JB8/FR8)  E5M Extension of PSM standard contact \$65  ED5 Parametric special module (PSM) \$356  not with ED8  E3 115 V socket \$146  E55 Charging package, dashboard \$92  E74 Active Distance Assist DISTRONIC \$296  must have CO3  F49 Electrically heated windshield \$246  F61 Interior rear view mirror \$90  must have CO2/CO3/E3M  F64 Electrically folding exterior mirrors \$55  no restrictions  F84 Digital Rearview Mirror \$736  must have LA2/ not with F61  FF9 Additional DIN-slot \$91  must have CO2/E3M; not with FR3/JB7/JB6/JB8  F71 Security alarm w. interior motion sensor \$656  must have LC4/COO		
E1E Navigation \$81:  must have C02/E3M, not with C03  E1S Sirius XM, satellite radio \$28:  must have C02/E3M/C03  E1R Additional Fuses (40/80/150/100 Ampere) \$57  must have X2R/ not with E1Y  E2A Access point for BB special signals in cockpit \$32  E2I Additional battery, co-driver seat base \$27:  Must have E36; not with E2M  E36 Cutoff relay for additional battery \$12c  standard with E2I/E2M  E3M MBUX Multimedia System with 7" touchscreen \$53:  not with C02/C03; must have JK5+(JB7/JB6/JB8/FR8)  E5M Extension of PSM standard contact \$65  ED5 Parametric special module (PSM) \$35c  not with ED8  EE3 115 V socket \$140  E55 Charging package, dashboard \$92  ET4 Active Distance Assist DISTRONIC \$29c  must have C03  F49 Electrically heated windshield \$24c  F61 Interior rear view mirror \$0  must have C02/C03/E3M  F64 Electrically folding exterior mirrors \$55  no restrictions  F84 Digital Rearview Mirror \$73c  must have L02/ not with F61  FE9 Additional DIN-slot \$91  FR8 Rear view camera (head unit display) \$37c  must have C02/E3M; not with FR3/JB7/JB6/JB8  FY1 Security alarm w. interior motion sensor \$65c  must have L02/C00  must have L02/C00  must have L02/C00  must have C02/E3M; not with FR3/JB7/JB6/JB8  FY1 Security alarm w. interior motion sensor \$65c	5 \$175	\$175
must have CO2/E3M, not with CO3  E1S Sirius XM, satellite radio \$285  must have CO2/E3M/CO3  E1R Additional Fuses (40/80/150/100 Ampere) \$57  must have X2R/ not with E1Y  E2A Access point for BB special signals in cockpit \$32  E2I Additional battery, co-driver seat base \$277  Must have E36; not with E2M  E36 Cutoff relay for additional battery \$126  standard with E2I/E2M  E3M MBUX Multimedia System with 7" touchscreen \$530  not with CO2/CO3; must have JK5+(JB7/JB6/JB8/FR8)  E5M Extension of PSM standard contact \$65  ED5 Parametric special module (PSM) \$356  not with ED8  EE3 115 V socket \$144  E55 Charging package, dashboard \$92  ET4 Active Distance Assist DISTRONIC \$296  must have CO3  F49 Electrically heated windshield \$244  F61 Interior rear view mirror \$0  must have CO2/CO3/E3M  F64 Electrically folding exterior mirrors \$55  no restrictions  F84 Digital Rearview Mirror \$736  must have LA2/ not with F61  FF9 Additional DIN-slot \$991  must have CO2/E3M; not with FR3/JB7/JB6/JB8  FY1 Security alarm w. interior motion sensor \$654  must have LC4/COO	- ¢045	Ć045
E1S Sirius XM, satellite radio  must have C02/E3M/C03  E1R Additional Fuses (40/80/150/100 Ampere)  pust have X2R/ not with E1Y  E2A Access point for BB special signals in cockpit  E2I Additional battery, co-driver seat base  S27:  Must have E36; not with E2M  E36 Cutoff relay for additional battery  standard with E2I/E2M  E3M MBUX Multimedia System with 7" touchscreen  not with C02/C03; must have JK5+(JB7/JB6/JB8/FR8)  E5M Extension of PSM standard contact  ED5 Parametric special module (PSM)  not with ED8  EE3 115 V socket  ES5 Charging package, dashboard  ES5 Charging package, dashboard  E74 Active Distance Assist DISTRONIC  must have C03  F49 Electrically heated windshield  F61 Interior rear view mirror  must have C02/C03/E3M  F64 Electrically folding exterior mirrors  so no restrictions  F84 Digital Rearview Mirror  must have LA2/ not with F61  EF9 Additional DIN-slot  FF8 Overhead storage slot, front center  FR8 Rear view camera (head unit display)  must have LC4/C00  must have LC4/C00  \$528  \$654	5 \$815	\$815
must have CO2/E3M/CO3  E1R Additional Fuses (40/80/150/100 Ampere) \$57  must have X2R/ not with E1Y  E2A Access point for BB special signals in cockpit \$32  E2I Additional battery, co-driver seat base \$277  Must have E36; not with E2M  E36 Cutoff relay for additional battery \$120  standard with E2I/E2M  E3M MBUX Multimedia System with 7" touchscreen \$530  not with CO2/CO3; must have JK5+(JB7/JB6/JB8/FR8)  E5M Extension of PSM standard contact \$655  ED5 Parametric special module (PSM) \$350  not with ED8  EE3 115 V socket \$144  ES5 Charging package, dashboard \$92  ET4 Active Distance Assist DISTRONIC \$290  must have CO3  F49 Electrically heated windshield \$244  F61 Interior rear view mirror \$0  must have CO2/CO3/E3M  F64 Electrically folding exterior mirrors \$55  no restrictions  F84 Digital Rearview Mirror \$736  must have LA2/ not with F61  E59 Additional DIN-slot \$91  FR8 Rear view camera (head unit display) \$375  must have CO2/E3M; not with FR3/JB7/JB6/JB8  FY1 Security alarm w. interior motion sensor \$654	- 400-	4225
E1R Additional Fuses (40/80/150/100 Ampere)  must have X2R/ not with E1Y  E2A Access point for BB special signals in cockpit  E2I Additional battery, co-driver seat base  E2I Additional battery, co-driver seat base  E36 Cutoff relay for additional battery  standard with E2I/E2M  E3M MBUX Multimedia System with 7" touchscreen  s53:  not with C02/C03; must have JK5+(JB7/JB6/JB8/FR8)  E5M Extension of PSM standard contact  ED5 Parametric special module (PSM)  not with ED8  EE3 115 V socket  E55 Charging package, dashboard  E74 Active Distance Assist DISTRONIC  must have C03  F49 Electrically heated windshield  \$244  F61 Interior rear view mirror  must have C02/C03/E3M  F64 Electrically folding exterior mirrors  por restrictions  F84 Digital Rearview Mirror  must have LA2/ not with F61  FE9 Additional DIN-slot  F88 Rear view camera (head unit display)  must have LC4/C00  #ust have LC4/C00  #ust have LC4/C00	5 \$285	\$285
must have X2R/ not with E1Y  E2A Access point for BB special signals in cockpit \$32  E2I Additional battery, co-driver seat base \$277  Must have E36; not with E2M  E36 Cutoff relay for additional battery \$126  standard with E2I/E2M  E3M MBUX Multimedia System with 7" touchscreen \$537  not with C02/C03; must have JK5+(JB7/JB6/JB8/FR8)  E5M Extension of PSM standard contact \$65  ED5 Parametric special module (PSM) \$356  not with ED8  EE3 115 V socket \$140  ES5 Charging package, dashboard \$92  ET4 Active Distance Assist DISTRONIC \$296  must have C03  F49 Electrically heated windshield \$246  F61 Interior rear view mirror \$0  must have C02/C03/E3M  F64 Electrically folding exterior mirrors \$55  no restrictions  F84 Digital Rearview Mirror \$736  must have LA2/ not with F61  FE9 Additional DIN-slot \$91  FR8 Rear view camera (head unit display) \$375  must have C02/E3M; not with FR3/JB7/JB6/JB8  FY1 Security alarm w. interior motion sensor \$654		
E2A Access point for BB special signals in cockpit \$32 E2I Additional battery, co-driver seat base \$277  Must have E36; not with E2M E36 Cutoff relay for additional battery \$124  standard with E2I/E2M E3M MBUX Multimedia System with 7" touchscreen \$533  not with C02/C03; must have JK5+(JB7/JB6/JB8/FR8) E5M Extension of PSM standard contact \$65 ED5 Parametric special module (PSM) \$354  not with ED8 EE3 115 V socket \$144 ES5 Charging package, dashboard \$92 ET4 Active Distance Assist DISTRONIC \$294  must have C03 F49 Electrically heated windshield \$244 F61 Interior rear view mirror \$0  must have C02/C03/E3M F64 Electrically folding exterior mirrors \$55  no restrictions F84 Digital Rearview Mirror \$736  must have LA2/ not with F61 FE9 Additional DIN-slot \$91 FR8 Rear view camera (head unit display) \$375  must have C02/E3M; not with FR3/JB7/JB6/JB8 FY1 Security alarm w. interior motion sensor \$654	\$57	\$57
E21 Additional battery, co-driver seat base \$27  Must have E36; not with E2M  E36 Cutoff relay for additional battery \$124  standard with E2I/E2M  E3M MBUX Multimedia System with 7" touchscreen \$533  not with C02/C03; must have JK5+(JB7/JB6/JB8/FR8)  E5M Extension of PSM standard contact \$65  ED5 Parametric special module (PSM) \$354  not with ED8  EE3 115 V socket \$144  ES5 Charging package, dashboard \$92  ET4 Active Distance Assist DISTRONIC \$294  must have C03  F49 Electrically heated windshield \$244  F61 Interior rear view mirror \$0  must have C02/C03/E3M  F64 Electrically folding exterior mirrors \$55  no restrictions  F84 Digital Rearview Mirror \$736  must have LA2/ not with F61  FE9 Additional DIN-slot \$91  FF8 Overhead storage slot, front center \$117  FR8 Rear view camera (head unit display)  must have C02/E3M; not with FR3/JB7/JB6/JB8  FY1 Security alarm w. interior motion sensor \$654		
Must have E36; not with E2M  E36 Cutoff relay for additional battery  standard with E2I/E2M  E3M MBUX Multimedia System with 7" touchscreen  not with C02/C03; must have JK5+(JB7/JB6/JB8/FR8)  E5M Extension of PSM standard contact  ED5 Parametric special module (PSM)  not with ED8  EE3 115 V socket  ES5 Charging package, dashboard  E74 Active Distance Assist DISTRONIC  must have C03  F49 Electrically heated windshield  F61 Interior rear view mirror  must have C02/C03/E3M  F64 Electrically folding exterior mirrors  no restrictions  F84 Digital Rearview Mirror  must have L02/ not with F61  FE9 Additional DIN-slot  FR8 Rear view camera (head unit display)  must have C02/E3M; not with FR3/JB7/JB6/JB8  FY1 Security alarm w. interior motion sensor  \$654  must have LC4/C00		\$32
E36 Cutoff relay for additional battery  standard with E2I/E2M  E3M MBUX Multimedia System with 7" touchscreen  not with C02/C03; must have JK5+(JB7/JB6/JB8/FR8)  E5M Extension of PSM standard contact  ED5 Parametric special module (PSM)  not with ED8  EE3 115 V socket  ES5 Charging package, dashboard  E74 Active Distance Assist DISTRONIC  must have C03  F49 Electrically heated windshield  \$244  F61 Interior rear view mirror  must have C02/C03/E3M  F64 Electrically folding exterior mirrors  no restrictions  F84 Digital Rearview Mirror  must have LA2/ not with F61  FE9 Additional DIN-slot  FR8 Rear view camera (head unit display)  must have C02/E3M; not with FR3/JB7/JB6/JB8  FY1 Security alarm w. interior motion sensor  \$654  must have LC4/C00	7 \$277	\$277
standard with E2I/E2M  E3M MBUX Multimedia System with 7" touchscreen  not with C02/C03; must have JK5+(JB7/JB6/JB8/FR8)  E5M Extension of PSM standard contact  ED5 Parametric special module (PSM)  not with ED8  EE3 115 V socket  ES5 Charging package, dashboard  E74 Active Distance Assist DISTRONIC  must have C03  F49 Electrically heated windshield  F61 Interior rear view mirror  must have C02/C03/E3M  F64 Electrically folding exterior mirrors  no restrictions  F84 Digital Rearview Mirror  must have LA2/ not with F61  FE9 Additional DIN-slot  FR8 Rear view camera (head unit display)  must have C02/E3M; not with FR3/JB7/JB6/JB8  FY1 Security alarm w. interior motion sensor  must have LC4/C00		
E3M MBUX Multimedia System with 7" touchscreen  not with C02/C03; must have JK5+(JB7/JB6/JB8/FR8)  E5M Extension of PSM standard contact  ED5 Parametric special module (PSM)  not with ED8  EE3 115 V socket  ES5 Charging package, dashboard  E74 Active Distance Assist DISTRONIC  must have C03  F49 Electrically heated windshield  F61 Interior rear view mirror  must have C02/C03/E3M  F64 Electrically folding exterior mirrors  no restrictions  F84 Digital Rearview Mirror  must have LA2/ not with F61  FE9 Additional DIN-slot  FR8 Rear view camera (head unit display)  must have C02/E3M; not with FR3/JB7/JB6/JB8  F71 Security alarm w. interior motion sensor  must have LC4/C00	4 \$124	\$124
not with CO2/CO3; must have JK5+(JB7/JB6/JB8/FR8)  E5M Extension of PSM standard contact  ED5 Parametric special module (PSM)  not with ED8  EE3 115 V socket  ES5 Charging package, dashboard  E74 Active Distance Assist DISTRONIC  must have CO3  F49 Electrically heated windshield  F61 Interior rear view mirror  must have CO2/CO3/E3M  F64 Electrically folding exterior mirrors  no restrictions  F84 Digital Rearview Mirror  must have LA2/ not with F61  FE9 Additional DIN-slot  FR8 Rear view camera (head unit display)  must have CO2/E3M; not with FR3/JB7/JB6/JB8  FY1 Security alarm w. interior motion sensor  \$654  must have LC4/COO		
E5M Extension of PSM standard contact  ED5 Parametric special module (PSM)  not with ED8  EE3 115 V socket  ES5 Charging package, dashboard  E74 Active Distance Assist DISTRONIC  must have C03  F49 Electrically heated windshield  F61 Interior rear view mirror  must have C02/C03/E3M  F64 Electrically folding exterior mirrors  no restrictions  F84 Digital Rearview Mirror  must have LA2/ not with F61  FE9 Additional DIN-slot  FR8 Rear view camera (head unit display)  must have C02/E3M; not with FR3/JB7/JB6/JB8  FY1 Security alarm w. interior motion sensor  \$654	1 \$531	\$531
ED5 Parametric special module (PSM)  not with ED8  EE3 115 V socket \$140  ES5 Charging package, dashboard \$92  ET4 Active Distance Assist DISTRONIC \$294  must have CO3  F49 Electrically heated windshield \$244  F61 Interior rear view mirror \$0  must have CO2/CO3/E3M  F64 Electrically folding exterior mirrors \$55  no restrictions  F84 Digital Rearview Mirror \$736  must have LA2/ not with F61  FE9 Additional DIN-slot \$91  FR8 Rear view camera (head unit display) \$375  must have CO2/E3M; not with FR3/JB7/JB6/JB8  FY1 Security alarm w. interior motion sensor \$654  must have LC4/COO		
not with ED8  EE3 115 V socket \$140  ES5 Charging package, dashboard \$92  ET4 Active Distance Assist DISTRONIC \$290  must have CO3  F49 Electrically heated windshield \$240  F61 Interior rear view mirror \$0  must have CO2/CO3/E3M  F64 Electrically folding exterior mirrors \$55  no restrictions  F84 Digital Rearview Mirror \$730  must have LA2/ not with F61  FE9 Additional DIN-slot \$91  FR8 Rear view camera (head unit display) \$375  must have CO2/E3M; not with FR3/JB7/JB6/JB8  FY1 Security alarm w. interior motion sensor \$654  must have LC4/COO	\$65	\$65
EE3 115 V socket \$140 ES5 Charging package, dashboard \$92 ET4 Active Distance Assist DISTRONIC \$294  must have CO3 F49 Electrically heated windshield \$244 F61 Interior rear view mirror \$0  must have CO2/CO3/E3M F64 Electrically folding exterior mirrors \$55  no restrictions F84 Digital Rearview Mirror \$736  must have LA2/ not with F61 FE9 Additional DIN-slot \$91 FR8 Rear view camera (head unit display) \$375  must have CO2/E3M; not with FR3/JB7/JB6/JB8 FY1 Security alarm w. interior motion sensor \$654  must have LC4/COO	4 \$354	\$354
ES5 Charging package, dashboard \$92 ET4 Active Distance Assist DISTRONIC \$294  must have CO3 F49 Electrically heated windshield \$244 F61 Interior rear view mirror \$0  must have CO2/CO3/E3M F64 Electrically folding exterior mirrors \$55  no restrictions F84 Digital Rearview Mirror \$736  must have LA2/ not with F61 FE9 Additional DIN-slot \$91 FF8 Overhead storage slot, front center \$115 FR8 Rear view camera (head unit display) \$375  must have CO2/E3M; not with FR3/JB7/JB6/JB8 FY1 Security alarm w. interior motion sensor \$654  must have LC4/COO		
ET4 Active Distance Assist DISTRONIC  must have CO3  F49 Electrically heated windshield  F61 Interior rear view mirror  must have CO2/CO3/E3M  F64 Electrically folding exterior mirrors  no restrictions  F84 Digital Rearview Mirror  must have LA2/ not with F61  FE9 Additional DIN-slot  F88 Rear view camera (head unit display)  must have CO2/E3M; not with FR3/JB7/JB6/JB8  FY1 Security alarm w. interior motion sensor  \$654  must have LC4/CO0	0 \$140	\$140
must have CO3  F49 Electrically heated windshield \$244  F61 Interior rear view mirror \$0  must have CO2/CO3/E3M  F64 Electrically folding exterior mirrors \$55  no restrictions  F84 Digital Rearview Mirror \$736  must have LA2/ not with F61  FE9 Additional DIN-slot \$91  FF8 Overhead storage slot, front center \$117  FR8 Rear view camera (head unit display) \$377  must have CO2/E3M; not with FR3/JB7/JB6/JB8  FY1 Security alarm w. interior motion sensor \$654  must have LC4/COO	\$92	\$92
F49 Electrically heated windshield \$244 F61 Interior rear view mirror \$0  must have CO2/CO3/E3M F64 Electrically folding exterior mirrors \$55  no restrictions F84 Digital Rearview Mirror \$736  must have LA2/ not with F61 FE9 Additional DIN-slot \$91 FF8 Overhead storage slot, front center \$117 FR8 Rear view camera (head unit display) \$377  must have CO2/E3M; not with FR3/JB7/JB6/JB8 FY1 Security alarm w. interior motion sensor \$654  must have LC4/CO0	4 \$294	\$294
F61 Interior rear view mirror \$0  must have CO2/CO3/E3M  F64 Electrically folding exterior mirrors \$55  no restrictions  F84 Digital Rearview Mirror \$736  must have LA2/ not with F61  FE9 Additional DIN-slot \$91  FF8 Overhead storage slot, front center \$117  FR8 Rear view camera (head unit display) \$377  must have CO2/E3M; not with FR3/JB7/JB6/JB8  FY1 Security alarm w. interior motion sensor \$654  must have LC4/CO0		
must have CO2/CO3/E3M  F64 Electrically folding exterior mirrors \$55  no restrictions  F84 Digital Rearview Mirror \$736  must have LA2/ not with F61  FE9 Additional DIN-slot \$91  FF8 Overhead storage slot, front center \$117  FR8 Rear view camera (head unit display) \$377  must have CO2/E3M; not with FR3/JB7/JB6/JB8  FY1 Security alarm w. interior motion sensor \$654  must have LC4/CO0	4 \$244	\$244
F64 Electrically folding exterior mirrors  no restrictions  F84 Digital Rearview Mirror  must have LA2/ not with F61  FE9 Additional DIN-slot  FF8 Overhead storage slot, front center  FR8 Rear view camera (head unit display)  must have C02/E3M; not with FR3/JB7/JB6/JB8  FY1 Security alarm w. interior motion sensor  must have LC4/C00	\$0	\$0
no restrictions  F84 Digital Rearview Mirror \$736  must have LA2/ not with F61  FE9 Additional DIN-slot \$91  FF8 Overhead storage slot, front center \$117  FR8 Rear view camera (head unit display) \$377  must have CO2/E3M; not with FR3/JB7/JB6/JB8  FY1 Security alarm w. interior motion sensor \$654  must have LC4/C00		
F84 Digital Rearview Mirror \$736  must have LA2/ not with F61  FE9 Additional DIN-slot \$91  FF8 Overhead storage slot, front center \$117  FR8 Rear view camera (head unit display) \$377  must have CO2/E3M; not with FR3/JB7/JB6/JB8  FY1 Security alarm w. interior motion sensor \$654  must have LC4/C00	\$55	\$55
must have LA2/ not with F61  FE9 Additional DIN-slot \$91  FF8 Overhead storage slot, front center \$117  FR8 Rear view camera (head unit display) \$377  must have CO2/E3M; not with FR3/JB7/JB6/JB8  FY1 Security alarm w. interior motion sensor \$654  must have LC4/C00		
FE9 Additional DIN-slot \$91 FF8 Overhead storage slot, front center \$11. FR8 Rear view camera (head unit display) \$37.  must have CO2/E3M; not with FR3/JB7/JB6/JB8 FY1 Security alarm w. interior motion sensor \$65.  must have LC4/C00	6 \$736	\$736
FF8 Overhead storage slot, front center \$117 FR8 Rear view camera (head unit display) \$377 must have CO2/E3M; not with FR3/JB7/JB6/JB8 FY1 Security alarm w. interior motion sensor \$654 must have LC4/C00	•	
FR8 Rear view camera (head unit display) \$377  must have CO2/E3M; not with FR3/JB7/JB6/JB8  FY1 Security alarm w. interior motion sensor \$654  must have LC4/C00	. \$91	\$91
FR8 Rear view camera (head unit display) \$377  must have CO2/E3M; not with FR3/JB7/JB6/JB8  FY1 Security alarm w. interior motion sensor \$654  must have LC4/C00		\$117
must have CO2/E3M; not with FR3/JB7/JB6/JB8  FY1 Security alarm w. interior motion sensor \$654  must have LC4/C00		\$377
FY1 Security alarm w. interior motion sensor \$654 must have LC4/C00		
must have LC4/C00	4 \$654	\$654
	,	
, , , , , , , , , , , , , , , , , , ,	. \$41	\$41
FZ9 Keys, two additional masters \$136		\$136
H12   Fuel-fired pre-heater/booster (17K BTU) \$925		\$925
not with HZ9/J51/KL1	7525	ŲJ23
H15 Heated front passenger seat \$318	8 \$318	\$318
must have H16; not with X68	, , , , , , , ,	7310
HH4 Thermotronic automatic climate control \$378		\$378
must have JF1	8 \$378	

		144" 4D High	144" 4D High AWD	170" 4D High
			12 seats	15 seats
		12 seats M2PV4H	M2PV4A	M2PV7H 907.745
		907.743	907.743	
		907.743	907.743	907.745
J5 1	Fuel gauge, optimized for aux. fuel tap	\$80	\$80	\$80
	not with HZ9/H12			
J52	Engine oil level display at cold start	\$0	\$0	\$0
JA7	Blind Spot Assist	\$504	\$504	\$504
	must have F64			
JB4	Active Lane Keeping Assist	\$322	\$322	\$322
	standard with CO2/CA2			
JB6	Parking Package with 360 degree camera	\$867	\$867	\$867
	must have CO2/CO3/E3M; not with JB7			
JB7	Parking Package	\$688	\$688	\$688
	must have CO2/CO3/E3M; not with JB6			
JB8	360 Degree Camera	\$766	\$766	\$766
	must have CO2/CO3/E3M, not with JB6/JB7			
JF1	Rain sensor	\$118	\$118	\$118
	Standard with C02/CA2/X11			
JW0	Backup alarm	\$111	\$111	\$111
JW2	Deactivation lamp monitoring failure	\$38	\$38	\$38
JW8	Attention Assist	\$55	\$55	\$55
K51	Misfueling prevention for Diesel	\$55	\$55	\$55
K52	DEF fluid filler cap - lockable	\$30	\$30	\$30
L13	Fog lamp with cornering light function	\$223	\$223	\$223
LC4	Comfort overhead control panel	\$105	\$105	\$105
	Speed limitation 65 mph	\$67	\$67	\$67
	not with MD3	<u>'</u>	· · · · · · · · · · · · · · · · · · ·	•
MD3	Top speed limitation 75 mph	\$71	\$71	\$71
	not with M20	,	<u>'</u>	,
N62	Front engine bracket for additional alternator	\$523	\$523	\$523
	not with X11	1	,,,,,,	,
Q24	Trailer hitch, 5,000 lbs	\$164	\$164	-
	not with W73	7-7:	7-0	
QA9	Half-sided step rear (for trailer hitch)	\$113	\$113	-
G. 17	must have Q24, not with W73	<b>¥</b> 110	Ÿ225	
R91	Spare tire deletion	-\$110	-\$110	-\$110
117	must have R92; not with R87	7110	<b>7110</b>	Ų110
R92	Spare tire carrier deletion	\$0	\$0	\$0
11/2	must have R91; not with R65	γV	γo	70
R98	Rims painted jet black	\$91	\$91	\$91
1170	not with RL5/RM2	731	731	ΤΩT
RF1	Tire brand Continental	\$0	\$0	\$0
	must have RM1 + RM9	γV	γo	70
RF8	Tire brand Michelin	\$0	\$0	\$0
111 0	must have RM9; not with RM1	υç	γU	70
RH0	Tire brand Kumho	\$0	\$0	\$0
MIO	must have RM9; not with RM1	ŞU	ŞU	ŞU
DIE		¢1 ∩1E	\$1.015	\$1.015
RL5	Light-alloy wheels 6.5 J x 16 not with RS3/RM2/R98	\$1,015	\$1,015	\$1,015
RM1	M+S winter tires	¢100	\$190	\$190
L/IAI/		\$190	\$130	9130
	must have RF1/RD9; not with RF8/RH0			

		144" 4D High	144" 4D High AWD	170" 4D High
		12 seats	12 seats	15 seats
		M2PV4H	M2PV4A	M2PV7H 907.745
		907.743	907.743	
RM2	Rims painted arctic white	\$91	\$91	\$91
TUVIZ	not with R98/RL5	731	Ψ31	Ų31
RM9	Specially requested tires	\$113	\$113	\$113
IXIVI	must have RF1/RF8/RH0; not with RD9	7113	7113	Ų113
S28	Armrest, driver and passenger door	\$58	\$58	\$58
T12	Sliding door two stage opening	\$92	\$92	\$92
	not with T55/X71	Ų 32	<b>732</b>	<b>432</b>
T50	Electric closing assist right sliding door	\$376	\$376	\$376
	must have D03; not with T55	<b>40.0</b>	φσ. σ	φσ. σ
T55	Electric sliding door right	\$930	\$930	\$930
100	must have D03 + (FY7+T16); not with T12/T50	<b>7550</b>	<b></b>	<b>4330</b>
T57	Electric sliding step	\$1,199	\$1,199	\$1,199
	must have ED5	Ψ 2/200	Ψ±/±33	ψ±)±33
T60	Opening limiter electrically operated sliding door	\$134	\$134	\$134
	must have T55			, -
T75	Door-mounted assist handles, driver & passenger	\$66	\$66	\$66
T85	Assist handle, left rear door	\$36	\$36	\$36
T86	Assist handles, right rear door	\$36	\$36	\$36
V85	Cigarette lighter & ash cup, front	\$44	\$44	\$44
V4A	Full paneling, right sliding door	\$123	\$123	\$123
	must have D03+VA5	•		
VA5	Full paneling, hinged rear doors	\$43	\$43	\$43
	must have DO3	•		
W54	Rear doors, opening to side wall	\$403	\$403	\$403
W73	Bumper step, rear, grey	\$209	\$209	\$209
	not with Q24	•		
W78	Heated rear window(s) w/ washers/wipers	\$376	\$376	\$376
	not with W61	•		
X90	Deletion of Sprinter badge, left rear door	\$0	\$0	\$0
X93	Deletion of model badge, right rear door	\$0	\$0	\$0
XM4	Acoustic package	\$97	\$97	\$97
	standard with C02/C03			
Y10	First-aid kit	\$30	\$30	\$30
Y45	Emergency flashlight	\$30	\$30	\$30
Y68	Paint preservative	\$209	\$209	\$238
Y69	Surface protection for stock vehicles	\$352	\$352	\$352
ZH4	Downhill speed regulation for AWD	-	\$61	-

		144" 4D High	144" 4D High AWD	170" 4D High
		12 seats	12 seats	15 seats
		M2PV4H	M2PV4A	M2PV7H
		907.743	907.743	907.745
C00	Comfort Package	\$307	\$307	\$307
LC4	Comfort overhead control panel	Х	Х	Х
SE4	Lumbar support, co-driver's seat	X	Х	Х
SE5	Lumbar support, driver's seat	X	X	X
SK0	Comfort head restraint, driver	X	X	X
SK1	Comfort head restraint, co-driver	X	Х	X
must	have S28 + (COS OR X68); not with S23			

COS	Comfort Package (Seat addition)	\$426	\$426	\$426	
SB1	Comfort driver's seat	Х	Х	X	
SB2	Comfort passenger seat	Х	Х	X	
must	must have COO				

X68	Comfort Plus Package	\$1,898	\$1,898	\$1,898
H15	Heated front passenger seat	X	X	Х
SF1	Driver's seat electrically adjustable	Х	Х	Х
SF2	Co-driver's seat electrically adjustable	X	X	Х
must	nust have COO and VF4 OR VF6, CA/CC only: not with S23			

C01	Driver Convenience Package	\$449	\$449	\$449
E46	12 V power outlet, driver seat base	Х	Х	X
F64	Electrically folding exterior mirrors	Х	Х	X
FJ1	Hinged lid for storage compartment	S	S	S
FJ5	Hinged Lid for Storage Compartments left and right	X	X	Х
FZ9	Keys, two additional masters	Х	Х	X
JW8	Attention Assist	X	X	X

C02	Premium Package	\$805	\$805	\$805	
E3M	MBUX Multimedia System with 7" touchscreen	X	Х	X	
FM3	Wet Wiper System	X	Х	X	
JB4	Active Lane Keeping Assist	X	Х	X	
must	must have JF1 + XM4; must choose FR8/JB7/JB6				

CA2	C02 in combination with C03	\$547	\$547	\$547
CL3	Leather steering wheel	X	X	Х
FM3	Wet Wiper System	Х	Х	Х
JB4	Active Lane Keeping Assist	X	X	Х
must	must have CO3 + JF1			

144" 4D High	144" 4D High AWD	170" 4D High
12 seats	12 seats	15 seats
M2PV4H	M2PV4A	M2PV7H
907.743	907.743	907.745

C03	Premium Plus Package	\$2,008	\$2,008	\$2,008
E1B	Tray for smartphones incl. wireless charging	Х	Х	Х
	Navigation	Х	Х	Х
EY2	Intelligent navigation	X	X	X
E4M	MBUX Multimedia System with 10.25" touchscreen	X	Х	X
EX9	Free map data updates for 3 years	X	Х	X
H1I	Front-to-rear outlet in instrument panel	X	Х	X
JA9	Traffic Sign Assist	X	Х	X
XM4	Acoustic package	Х	Х	Х
must	have (CA2+(JB7/JB6/JB8)); not with FR8 and CO2			

X67	Chrome Grille Package	\$325	\$325	\$325	
CN2	Radiator grille frame in vehicle color	X	X	X	
FK3	Chrome plated radiator grille (MB only)	X	Х	X	
no re	no restrictions				

X13	Exterior Lighting Package	\$1,801	\$1,801	\$1,801	
L13	Fog lamp with cornering light function	X	X	X	
L22	Partial LED tail lights	Х	Х	Х	
LA1	High beam assist	Х	Х	Х	
LG7	LED high performance headlamps	Х	Х	Х	
no re	no restrictions				

X70	Rear Comfort Package	\$1,703	\$1,703	\$1,703		
S31	Convenice head restraints for pass. compartment	X	X	Х		
U3Y	3-seater comfort bench rear - 3rd row (narrow)	-	-	Х		
UY1	3-seater comfort bench rear, 1st row (narrow)	X	X	Х		
UY2	3-seater comfort bench rear, 2nd row (narrow)	X	X	Х		
UY3	4-seater comfort bench rear, 3rd row	X	X	-		
UY6	4-seater comfort bench rear, 4th row	-	-	X		
can h	can have VF4/VF6 only					

X71	Passenger Accessibility Package	\$1,684	\$1,684	\$1,684
T55	Electric sliding door right	Х	X	X
ED5	Parametric special module (PSM)	X	X	X
T57	Electric sliding step	X	X	X
FY7	Optional 3-button keys	Х	X	X
Opening limiter for electrically operated sliding door (T60) can be added in combination with the package				

X11	High-Performance Rear Air Conditioning Package	\$1,258	\$1,258	\$1,258	
HK4	Rear air conditioner, heavyduty	X	X	X	
HH4	Thermotronic automatic climate control	Х	X	X	
must have D03; HK4 n/a on gas models					

		144" 4D High	144" AWD	170" 4D High	170" AWD
		МХСС4Н	MXCC4A	МХСС7Н	МХСС7А
		907.153	907.153	907.155	907.155
F					
Engin			-	c	
	High Output Engine/9-Speed Trans.	S	S	S	S
	AGM battery 12V 70AH	S	S	S	S
_	Automatic transmission, 9G-tronic	S	S	S	S
	Alternator 14 V / 250 A	S	S	S	S
	Approval Bio-Diesel B20	S	S	S	S
	2.0L 4-cylinder diesel engine (208hp output)	S	S	S	S
	SULEV emissions	S	S	S	S
	II Wheel Drive Package				
	All Wheel Drive with torque on demand	-	S	-	S
	Door-mounted assist handles, driver & passenger	-	S	-	S
_	- choose while ordering				
X34		\$0	\$0	\$0	<i>\$0</i>
RH7	Tires LT 215/85 R16- DRW	S	S	S	S
RS6	5.5 J x 16 steel wheels	S	S	S	S
RD9	Unspecified tire brand	S	S	S	S
X31	Super Single Tire	\$431	-	\$431	-
R9A	285/65 R 16 C super single tires	0	-	0	-
RS5	Steel wheels: 8.5Jx16 Rr; 6.5Jx16 Fr	0	-	0	-
RD9	Unspecified tire brand	0	-	0	-
RY2	Tire pressure monitoring sensors	0	•	0	-
Identi	fication Lights - choose while ordering				
V59	Identification Lamps Package	\$0	\$0	\$0	\$0
L49	Identification lamps	0	0	0	0
LV7	Clearance lights pre-wiring	0	0	0	0
For p	re-wiring only (recommended for RV)	\$0	<i>\$0</i>	<i>\$</i> 0	<i>\$0</i>
LV7	Clearance lights pre-wiring	0	0	0	0
Equipment					
AR2	Axle ratio 3.923	S	S	S	S
BA3	Active Brake Assist	S	S	S	S
BH1	Hold Function	S	S	S	S
C6L	Multifunction steering wheel	S	S	S	S
	Stabilization Level II	S	-	S	-
CL1	Adjustable steering wheel (angle)	S	S	S	S
	Hill Start Assist	S	S	S	S
E10	Standard radio	S	S	S	S
E1U	USB-C socket, 5 V	S	S	S	S
	Starter battery disconnect	S	S	S	S
E3J	Pre-installation for switch panel	S	S	S	S
E40	Trailer hitch prep. wiring	S	S	S	S
ED8	Preinstallation PSM	S	S	S	S
EE5	Ultracapacitor discharge module	S	S	S	S
EK1	Body Builder Connector	S	S	S	S
	Jump start terminal	S	S	S	S
	Pre-installation for Mercedes me Remote Services	S	S	S	S
	Emergency Call System	S	S	S	S
EY6	Breakdown management	S	S	S	S
F68	Heated & electrically adjustable exterior mirrors	S	S	S	S
FF5	Shelf above windshield	S	S	S	S
				S	
FG8	Cupholder front	S	S		S
FI1	Remote key (315 mhz) w/central locking	S	S	S	S
FJ4	Storage compartment underneath cockpit	S	S	S	S
FS2	Exterior mirror extended (for up to 96" box width)	S	S	S	S
H16	Heated driver's seat	S	S	S	S
H21	Windshield with filter band	S	S	S	S

		144" 4D High			170" AWD
		MXCC4H	MXCC4A	мхсс7н	MXCC7A
		907.153	907.153	907.155	907.155
HH2	Heater, auxiliary electric hot air	S	S	S	S
	Air Condition, Front	S	S	S	S
IH7	Headunit	S	S	S	S
J11	Speedometer, miles and km/h	S	S	S	S
J55	Seat belt warning for co-driver seat	S	S	S	S
J58	Seat belt reminder driver	S	S	S	S
J65	Outside temperature gauge	S	S	S	S
JA8	Crosswind Assist	S	S	S	S
JH3	Communication module (LTE) for dig. services	S	S	S	S
JI9	Service interval 20.000 miles	S	S	S	S
Jk5	Instrument cluster with color display	S	S	S	S
JW2	Deactivation lamp monitoring failure	S	S	S	S
7002	Black diesel filler cap	S	S	S	S
K60	Exhaust straight to rear	S	S	S	S
	24.5 gallon fuel tank	S	S	S	S
	Aux fuel sending unit w/ fuel tap	S	S	S	S
	Fuel/water seprarator & lubrication package	S	S	S	S
KP7	4rd generation SCR emission control system	S	S	S	S
	Parking lights deletion	S	S	S	S
	Headlight assistant	S	S	S	S
	Cruise control	S	S	S	S
	Front mudflaps	S	S	S	S
		S	S	S	S
	Longitudinal member reinforcement  Deletion of end cross member	S	S	S	S
R60		S	S	S	S
R87	Provisional spare wheel bracket frame mounted  Spare tire	S		S	S
		S	S	S	S
	All-season tires	S	S S	S	S S
S02	Standard driver seat	S	S	S	S
S04	Standard front passenger seat  Armrest for driver's seat	S	S	S	S
S22 S25		S	S	S	S
	Armrest for front passenger seat	S	S S	S	S
	Front airbag, driver	S	S	S	S S
	Front airbag, passenger Thorax polyic sidebag, driver	S	S	S	
	Thorax-pelvis sidebag, driver Thorax-pelvis sidebag, co-driver			S	S
		S S	S S	S	S S
	Airbag, driver/passenger window Seat occupancy sensor, driver's seat	S	S	S	S S
X5G	Witout load uprating/derating 5,000 kg	S S	S	S	S
X64	Plates/booklets in English (US)		S	S	S
X99	Manufacturer Mercedes-Benz AG	S	S	S	S
XC8	VIN visible from outside	S	S	S	S
XI2	Change Year G2-I	S	S	S	S
XY4	Model Year 2024	S	S	S	S
Y43	Jack, hydraulic	S	S	S	S
Z5U	Vehicle class, incomplete vehicle (49 CFR 571.3)	S	S	S	S
ZU8	USA country version	S	S	S	S
ZZ4	Brand content Mercedes-Benz North America	S	S	S	S

		144" 4D High	144" AWD	170" 4D High	170" AWD
		МХСС4Н	MXCC4A	мхсс7н	МХСС7А
		907.153	907.153	907.155	907.155
A50	Front axle reinforced	\$387	-	\$387	-
B01	Vehicle version for high load	-	-	\$0	\$0
	must have CB4/CB8; not with RF8			, -	, ,
BE2	Handbrake lever, folding	\$62	\$62	\$62	\$62
-	Bumpers front/rear primed	\$158	\$158	\$158	\$158
	must have CN2 (part of X67), not with CM2	7-55	7 - 5 - 5	7-00	7-00
CB2	Comfort suspension, air suspension	_	_	\$3,294	-
	Must have ED5+A50+KA3+B01. Not with CB8/CE8/A4M			1-7-	
CB4	Stabilization Level III	\$209	_	\$209	-
	must have X2R; not with CB8	·			
CE8	Raised rear body mounts	-	-	\$458	-
CM2	Bumpers/detachable body parts painted body colour	\$483	\$483	\$483	\$483
	must have CN2/X67 + (7755/9147/9197/9775)	·			
CM9	Primed side moldings	\$408	\$408	\$408	\$408
	must have C72, not with CM2	·	•	<u>'</u>	
E1B	Tray for smartphones incl. wireless charging	\$175	\$175	\$175	\$175
	must have CO2/E3M + H1I	· · · · · · · · · · · · · · · · · · ·	•	<del>'</del>	
E1E	Navigation	\$815	\$815	\$815	\$815
	must have CO2/E3M, not with CO3				
E1S	Sirius XM, satellite radio	\$285	\$285	\$285	\$285
	must have CO2/E3M/CO3		•	<u>'</u>	
E1X	MBUX multimedia 6-hour runtime	-	-	\$0	\$0
	must have X2R + (C02+E1E/E1S)/C03/(E3M+E1E/E1S)	<del>.</del>		+	
E1R	Additional Fuses (40/80/150/100 Ampere)	-	-	\$57	\$57
	must have X2R/ not with E1Y			·	·
E1Y	Additional Fuses (40/80/80/100 Ampere)	-	-	\$57	\$57
	must have X2R / not with E1R				
E2A	Access point for BB special signals in cockpit	\$32	\$32	\$32	\$32
E2I	Additional battery, co-driver seat base	\$277	\$277	\$277	\$277
	Must have E36; not with E2M	-			
E2M	Additional battery, engine compartment	\$277	\$277	\$277	\$277
	must have X01+E36; not with E2I/X69				
E3M	MBUX Multimedia System with 7" touchscreen	\$531	\$531	\$531	\$531
	not with C02/C03; must have JK5				
E36	Cutoff relay for additional battery	\$124	\$124	\$124	\$124
	standard with E2I/E2M	•			
E46	12 V power outlet, driver seat base	\$103	\$103	\$103	\$103
	Extension of PSM standard contact	\$65	\$65	\$65	\$65
EA5	Pre-wiring central locking (upfitter doors rear)	\$44	\$44	\$44	\$44
ED4	AGM battery 12V 92 AH 850 A	\$113	\$113	\$113	\$113
ED5	Parametric special module (PSM)	\$354	\$354	\$354	\$354
	not with ED8				
EE3	115 V socket	\$140	\$140	\$140	\$140
EP7	Basic electric fitting for rear loudspeakers	\$76	\$76	\$76	\$76
ET4	Active Distance Assist DISTRONIC	\$294	\$294	\$294	\$294
	must have CO3				
ES5	Charging package, dashboard	\$92	\$92	\$92	\$92
F35	Window in cab rear wall	\$149	\$149	\$149	\$149
	must have F61/FV1; not with FW1				
F49	Electrically heated windshield	\$244	\$244	\$244	\$244
	must have ED4; not with LA3				
F61	Interior rear view mirror	\$41	\$41	\$41	\$41
	must have CO2/CO3/E3M				
F85	Pre-Installation Digital Rearview Mirror	\$736	\$736	\$736	\$736
	must have LA2/LA3 - not with F61				
FE9	Additional DIN-slot	\$91	\$91	\$91	\$91
FF8	<u></u>				<u> </u>

must have COZ/COZ, not with PVI			144" 4D High	144" AWD	170" 4D High	170" AWD
Hinged lid for storage compartment			МХСС4Н	MXCC4A	МХСС7Н	МХСС7А
Fig.   Highed Lid for Storage Compartments left and right			907.153	907.153	907.155	907.155
Fig.   Highed Lid for Storage Compartments left and right	FI1	Hinged lid for storage compartment	\$105	\$105	\$105	\$105
### State ### St	_		·	· · · · · · · · · · · · · · · · · · ·		· ·
RRP   Pre-wring rear view camera (head unit display)   573   573   573   573   S73   mast have (20/CQ2), not with P1/1   FVE   Pre-wring rear view camera (mirror display)   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   52			<b>V</b> 200	Ų 200	<b>V</b> 200	<b>Ÿ</b> 200
must have COZ/COZ, not with PVI	FR7	•	\$73	\$73	\$73	\$73
FVI_Pre-wining rear view camera (mirror display)   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273   5273			, -	, -	, -	, -
	FV1		\$273	\$273	\$273	\$273
### Security alarm w. interior motion sensor			·	•		,
### Security alarm w, interior motion sensor    171   Security alarm w, interior motion sensor   172   Security alarm w, interior motion sensor   173   Security alarm w, interior motion sensor   174   Security alarm w, interior motion sensor   175   Security alarm w, interior motion sensor   176   Security alarm w, interior motion sensor   177   Optional 3-button keys   178   Set	FW1		\$0	\$0	\$0	\$0
FY1   Security alarm w. interior motion sensor			, -	, -	, , ,	, -
FY7   Optional 3-button keys   S41	FY1		\$654	\$654	\$654	\$654
Figure   F		must have LC4/C00; not with FW1/X2R	· · ·	•	!	·
Hotal Heat insulation, front compartment   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209   \$209	FY7	Optional 3-button keys	\$41	\$41	\$41	\$41
### ### #### #########################	FZ9	Keys, two additional masters	\$136	\$136	\$136	\$136
### H12   Fuel-fired pre-heater/booster (17K BTU)   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925   \$925	H04	Heat insulation, front compartment	\$209	\$209	\$209	\$209
Books   Fig.		must have FW1/V07	•			
Hasted front passenger seat	H12	Fuel-fired pre-heater/booster (17K BTU)	\$925	\$925	\$925	\$925
must have H16; not with X68         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$453         \$452         \$456         \$456         \$456 <t< td=""><td></td><td>must have ED4; not with HZ9</td><td><b>!</b></td><td></td><td>•</td><td></td></t<>		must have ED4; not with HZ9	<b>!</b>		•	
Rear heater prep   S453   S4	H15	Heated front passenger seat	\$318	\$318	\$318	\$318
### ### ### ### ### ### ### ### ### ##		must have H16; not with X68	•			
Hail   Front-to-rear outlet in instrument panel   \$0   \$0   \$0   \$0   \$0   \$0   \$0   \$	H88	Rear heater prep	\$453	\$453	\$453	\$453
must have F11/C01         \$378         \$378         \$378         \$378           HH4 Thermotronic automatic climate control         \$378         \$378         \$378         \$378           must have F1         ****         ****         ****         ****         ****         ****         ****         ****         ****         ****         ****         ****         ****         ****         ****         ****         ****         ****         ****         ****         ****         ****         ****         ****         ****         ****         ****         ***         ****         ****         ****         ****         ****         ****         ****         ****         ****         ****         ****         ****         ****         ****         ****         ****         ****         ****         ****         ****         ****         ****         ****         ****         ****         ****         ****         ****         ****         ****         ****         ****         ****         ****         ****         ****         ****         ****         ****         ****         ****         ****         ****         ****         ****         ****         ****         ****         ****		must have ED4+(H12/HZ9)				
HH4	H1I	Front-to-rear outlet in instrument panel	\$0	\$0	\$0	\$0
must have JF1         HZ9 Fuel-fired heater booster (18,000 BTU)         \$756         \$756         \$756         \$756           11V Pre-installation Blind Spot Assist         \$504         \$504         \$504         \$504           151 Fuel gauge, optimized for aux. fuel tap         \$80         \$80         \$80         \$80           152 Engine oil level display at cold start         \$0         \$0         \$0         \$0         \$0           181 360 Degree Camera For Cluster A Body         \$1,133         \$1,133         \$1,133         \$1,133         \$1,133         \$1,133         \$1,133         \$1,133         \$1,133         \$1,133         \$1,133         \$1,133         \$1,133         \$1,133         \$1,133         \$1,133         \$1,133         \$1,133         \$1,133         \$1,133         \$1,133         \$1,133         \$1,133         \$1,133         \$1,133         \$1,133         \$1,133         \$1,133         \$1,133         \$1,133         \$1,133         \$1,133         \$1,133         \$1,133         \$1,133         \$1,133         \$1,133         \$1,133         \$1,133         \$1,133         \$1,133         \$1,133         \$1,133         \$1,133         \$1,133         \$1,133         \$1,133         \$1,133         \$1,133         \$1,133         \$1,133         \$1,133         \$1,133		must have FJ1/C01	•			
### Fuel-fired heater booster (18,000 BTU)	HH4	Thermotronic automatic climate control	\$378	\$378	\$378	\$378
		must have JF1				
171	HZ9	Fuel-fired heater booster (18,000 BTU)	\$756	\$756	\$756	\$756
151   Fuel gauge, optimized for aux. fuel tap   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80   \$80		not with H12				
not with H29/H12         50         \$0         \$0         \$0           J52 Engine oil level display at cold start         \$0         \$0         \$0         \$0           JB1 360 Degree Camera For Cluster A Body         \$1,133         \$1,133         \$1,133         \$1,133           JB2 360 Degree Camera For Cluster B Body         \$1,133         \$1,133         \$1,133         \$1,133           JB3 360 Degree Camera For Cluster C Body         \$1,133         \$1,133         \$1,133         \$1,133           JB3 360 Degree Camera For Cluster C Body         \$1,133         \$1,133         \$1,133         \$1,133           JB4 Active Lane Keeping Assist         \$322         \$322         \$322         \$322           JB4 Active Lane Keeping Assist         \$322         \$322         \$322         \$322           JB5 Active Lane Keeping Assist         \$322         \$322         \$322         \$322           JB4 Active Lane Keeping Assist         \$322         \$322         \$322         \$322         \$322         \$322         \$322         \$322         \$322         \$322         \$322         \$322         \$322         \$322         \$322         \$322         \$322         \$322         \$322         \$322         \$322         \$322         \$322         \$322 <t< td=""><td>J1V</td><td>Pre-installation Blind Spot Assist</td><td>\$504</td><td>\$504</td><td>\$504</td><td>\$504</td></t<>	J1V	Pre-installation Blind Spot Assist	\$504	\$504	\$504	\$504
Section   Sect	J51	Fuel gauge, optimized for aux. fuel tap	\$80	\$80	\$80	\$80
Section   Sect		not with HZ9/H12	•			
Not with JB2/JB3   360 Degree Camera For Cluster B Body   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133	J52	Engine oil level display at cold start	\$0	\$0	\$0	\$0
Section   Sect	JB1	360 Degree Camera For Cluster A Body	\$1,133	\$1,133	\$1,133	\$1,133
Not with JB1/JB3   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133   \$1,133		Not with JB2/JB3				
Section   Sect	JB2	360 Degree Camera For Cluster B Body	\$1,133	\$1,133	\$1,133	\$1,133
Not with JB1/JB2   S322   S3		Not with JB1/JB3	•			
Standard with CO2/CA2   Standard with CO2/CA2/X11; not with LA3   Standard with LA3   Standard with LA3   Standard with CO2/CA2/X11; not with LA3   Standard with LA3   Standard with LA3   Standard with CO2/CA2/X11; not with LA3   Standard with LA3   Standard with CO2/CA2/X11; not with LA3   Standard with LA3   Standard with LA3   Standard with CO2/CA2/X11; not with LA3   Standard with LA3   Standard with CO2/CA2/X11; not with LA3   Standard with CO2/CA2/X11; not with LA3   Standard with LA3   Standard with CO2/CA2/X11; not with LA3   Standard with LA3   Standard with LA3   Standard with CO2/CA2/X11; not with LA3   Standard with LA3   Standard with CO2/CA2/X11; not with LA3   Standard with CO2/CA2/X11; not with LA3   Standard with LA3   Standard with CO2/CA2/X11; not with LA3   Standard with LA3   St	JB3	360 Degree Camera For Cluster C Body	\$1,133	\$1,133	\$1,133	\$1,133
not with CO2/CA2         \$118         \$118         \$118         \$118           JF1         Rain sensor         \$118         \$118         \$118         \$118           JW0         Backup alarm         \$111         \$111         \$111         \$111         \$111           not wit Q72         JW8         Attention Assist         \$55         \$55         \$55         \$55           KA3         Lateral exhaust pipe in front of rear axle, left         -         \$60         -         \$60           K51         Misfueling prevention for Diesel         \$55         \$55         \$55         \$55           K52         DEF fluid filler cap - lockable         \$30         \$30         \$30         \$30           L52         DEF gluid filler cap - lockable         \$30         \$30         \$30         \$30           L52         DEF gluid filler cap - lockable         \$30         \$30         \$30         \$30           L72         Pre-installation load compartment lighting         \$123         \$223         \$223         \$223           L72         Pre-installation load compartment lighting         \$148         \$148         \$148         \$148           L77         Wiring for additional turn signals         \$98         <		Not with JB1/JB2				
Standard with CO2/CA2/X11; not with LA3	JB4	Active Lane Keeping Assist	\$322	\$322	\$322	\$322
Standard with CO2/CA2/X11; not with LA3     JW0   Backup alarm   \$111   \$111   \$111   \$111     not wit Q72     JW8   Attention Assist   \$55   \$55   \$55     KA3   Lateral exhaust pipe in front of rear axle, left   - \$60   - \$60     K51   Misfueling prevention for Diesel   \$55   \$55   \$55     K52   DEF fluid filler cap - lockable   \$30   \$30   \$30     L13   Fog lamp with cornering light function   \$223   \$223   \$223     L72   Pre-installation load compartment lighting   \$195   \$195     L76   Wire harness tail lamp w/ extended wiring   \$148   \$148   \$148     L77   Wiring for additional turn signals   \$98   \$98   \$98     L90   Tail lamp deletion, non-LED   -\$26   -\$26   -\$26     not with L22     L91   Pre-wiring LED tail lights   \$55   \$55   \$55     not with L22/L90		not with CO2/CA2				
Since   Sinc	JF1	Rain sensor	\$118	\$118	\$118	\$118
not wit Q72         JW8 Attention Assist       \$55       \$55       \$55         KA3 Lateral exhaust pipe in front of rear axle, left       -       \$60       -       \$60         K51 Misfueling prevention for Diesel       \$55       \$55       \$55       \$55         K52 DEF fluid filler cap - lockable       \$30       \$30       \$30       \$30         L13 Fog lamp with cornering light function       \$223       \$223       \$223       \$223         L72 Pre-installation load compartment lighting       \$195       \$195       \$195       \$195         L76 Wire harness tail lamp w/ extended wiring       \$148       \$148       \$148       \$148         L77 Wiring for additional turn signals       \$98       \$98       \$98       \$98         L90 Tail lamp deletion, non-LED       -\$26       -\$26       -\$26       -\$26         not with L22       L91 Pre-wiring LED tail lights       \$55       \$55       \$55         not with L22/L90		Standard with C02/CA2/X11; not with LA3				
JW8         Attention Assist         \$55         \$55         \$55           KA3         Lateral exhaust pipe in front of rear axle, left         -         \$60         -         \$60           K51         Misfueling prevention for Diesel         \$55         \$55         \$55         \$55           K52         DEF fluid filler cap - lockable         \$30         \$30         \$30         \$30           L13         Fog lamp with cornering light function         \$223         \$223         \$223         \$223           L72         Pre-installation load compartment lighting         \$195         \$195         \$195         \$195           L76         Wire harness tail lamp w/ extended wiring         \$148         \$148         \$148         \$148           L77         Wiring for additional turn signals         \$98         \$98         \$98         \$98           L90         Tail lamp deletion, non-LED         -\$26         -\$26         -\$26         -\$26           not with L22         L91         Pre-wiring LED tail lights         \$55         \$55         \$55           not with L22/L90         \$25         \$55         \$55         \$55	JW0	Backup alarm	\$111	\$111	\$111	\$111
KA3       Lateral exhaust pipe in front of rear axle, left       -       \$60       -       \$60         K51       Misfueling prevention for Diesel       \$55       \$55       \$55       \$55         K52       DEF fluid filler cap - lockable       \$30       \$30       \$30       \$30         L13       Fog lamp with cornering light function       \$223       \$223       \$223       \$223         L72       Pre-installation load compartment lighting       \$195       \$195       \$195       \$195         L76       Wire harness tail lamp w/ extended wiring       \$148       \$148       \$148       \$148         L77       Wiring for additional turn signals       \$98       \$98       \$98       \$98         L90       Tail lamp deletion, non-LED       -\$26       -\$26       -\$26       -\$26         not with L22       L91       Pre-wiring LED tail lights       \$55       \$55       \$55         not with L22/L90       \$55       \$55       \$55       \$55		not wit Q72				
K51         Misfueling prevention for Diesel         \$55         \$55         \$55           K52         DEF fluid filler cap - lockable         \$30         \$30         \$30           L13         Fog lamp with cornering light function         \$223         \$223         \$223           L72         Pre-installation load compartment lighting         \$195         \$195         \$195           L76         Wire harness tail lamp w/ extended wiring         \$148         \$148         \$148           L77         Wiring for additional turn signals         \$98         \$98         \$98           L90         Tail lamp deletion, non-LED         -\$26         -\$26         -\$26           not with L22         L91         Pre-wiring LED tail lights         \$55         \$55         \$55           not with L22/L90         \$55         \$55         \$55         \$55	JW8		\$55	\$55	\$55	\$55
K52       DEF fluid filler cap - lockable       \$30       \$30       \$30         L13       Fog lamp with cornering light function       \$223       \$223       \$223         L72       Pre-installation load compartment lighting       \$195       \$195       \$195         L76       Wire harness tail lamp w/ extended wiring       \$148       \$148       \$148         L77       Wiring for additional turn signals       \$98       \$98       \$98         L90       Tail lamp deletion, non-LED       -\$26       -\$26       -\$26         not with L22       .91       Pre-wiring LED tail lights       \$55       \$55       \$55         not with L22/L90       .92       .93       .93       .93       .93       .93	KA3	Lateral exhaust pipe in front of rear axle, left	-	\$60	-	\$60
L13       Fog lamp with cornering light function       \$223       \$223       \$223         L72       Pre-installation load compartment lighting       \$195       \$195       \$195         L76       Wire harness tail lamp w/ extended wiring       \$148       \$148       \$148         L77       Wiring for additional turn signals       \$98       \$98       \$98         L90       Tail lamp deletion, non-LED       -\$26       -\$26       -\$26         not with L22       L91       Pre-wiring LED tail lights       \$55       \$55       \$55         not with L22/L90       \$55       \$55       \$55	K51		\$55	\$55	\$55	
L72       Pre-installation load compartment lighting       \$195       \$195       \$195         L76       Wire harness tail lamp w/ extended wiring       \$148       \$148       \$148         L77       Wiring for additional turn signals       \$98       \$98       \$98         L90       Tail lamp deletion, non-LED       -\$26       -\$26       -\$26         not with L22       -\$26       -\$55       \$55       \$55         not with L22/L90       \$55       \$55       \$55       \$55	K52			•	\$30	· · · · · · · · · · · · · · · · · · ·
L76       Wire harness tail lamp w/ extended wiring       \$148       \$148       \$148         L77       Wiring for additional turn signals       \$98       \$98       \$98         L90       Tail lamp deletion, non-LED       -\$26       -\$26       -\$26         not with L22       L91       Pre-wiring LED tail lights       \$55       \$55       \$55         not with L22/L90       \$55       \$55       \$55	L13		·			·
L77       Wiring for additional turn signals       \$98       \$98       \$98         L90       Tail lamp deletion, non-LED       -\$26       -\$26       -\$26         not with L22       L91       Pre-wiring LED tail lights       \$55       \$55       \$55         not with L22/L90       \$55       \$55       \$55	L72			\$195		· ·
L90     Tail lamp deletion, non-LED     -\$26     -\$26     -\$26       not with L22     -\$26     -\$26     -\$26       L91     Pre-wiring LED tail lights     \$55     \$55     \$55       not with L22/L90     \$55     \$55	L76			\$148	\$148	
not with L22           L91 Pre-wiring LED tail lights         \$55         \$55         \$55           not with L22/L90         \$55         \$55         \$55	L77	Wiring for additional turn signals		\$98	\$98	
L91 Pre-wiring LED tail lights \$55 \$55 \$55 not with L22/L90	L90		-\$26	-\$26	-\$26	-\$26
not with L22/L90		not with L22				
	L91	Pre-wiring LED tail lights	\$55	\$55	\$55	\$55
LB9   Illuminated front exits \$105 \$105 \$105		not with L22/L90				
	LB9	Illuminated front exits	\$105	\$105	\$105	\$105

		144" 4D High	144" AWD	170" 4D High	170" AWD
		мхсс4н	MXCC4A	мхсс7н	MXCC7A
		907.153	907.153	907.155	907.155
LC4	Comfort overhead control panel	\$105	\$105	\$105	\$105
LV6	Third brake light pre-wiring	\$36	\$36	\$36	\$36
	Speed limitation 65 mph	\$67	\$67	\$67	\$67
	not with MD3	7	75.	75.	7-1
M61	Alternator 14 V / 280 A	\$188	\$188	\$188	\$188
MD3	Top speed limitation 75 mph	\$71	\$71	\$71	\$71
	not with M20				
N62	Front engine bracket for additional alternator	\$523	\$523	\$523	\$523
	not with N63				
N63	Front engine bracket for auxiliary A/C compressor	\$523	\$523	\$523	\$523
200	not with N62		40	40	40
P08	Cover for transport	\$0	\$0	\$0	\$0
010	must have FW1/X69	¢72	672	672	\$73
	End cross member bolted Trailer cross member 7,500 lbs capacity	\$73 \$209	\$73 \$209	\$73 \$209	\$209
R65	Spare tire bracket below frame	\$209	\$209	\$209	\$0
KUJ	must have Q18; not with Q72/R60/R92	<b>3</b> 0	<b>30</b>	<b>30</b>	ŞÜ
R91	Spare tire deletion	-\$110	-\$110	-\$110	-\$110
1131	must have R92; not with R87/R60	7110	<b>7110</b>	Ţ110	Ų110
R92	Spare tire carrier deletion	\$0	\$0	\$0	\$0
	must have R91; not with R65/R60	7-	7-5	7-5	7-2
R98	Rims painted jet black	\$91	\$91	\$91	\$91
	not with RM2	·	,	,	
RF1	Tire brand Continental	\$0	\$0	\$0	\$0
	not with RD9	•			
RF8	Tire brand Michelin	\$0	\$0	\$0	\$0
	not with RD9/RF1/RM1				
RM1	M+S winter tires	\$190	\$190	\$190	\$190
	must have RD9/RF1; not with RF8/X31	_			
RM2	Rims painted arctic white	\$91	\$91	\$91	\$91
	not with X31/R98				
RM9	Specially requested tires	\$113	\$113	\$113	\$113
	must have RF1/RF8; not with RD9	4	4	4	4
S23	Twin front passenger seat	\$448	\$448	\$448	\$448
620	not with C00/X68/X01	ĆE0	ĆE0	ĆE0	¢50
	Armrest, driver and passenger door	\$58	\$58	\$58	\$58 \$36
S62	Seat belts orange, driver and front passenger not with S23	\$36	\$36	\$36	\$36
SB9	Driver's seat plus	\$267	\$267	\$267	\$267
363	must have FY7	\$207	\$267	\$267	\$267
SZ7	Storage net, driver's seat backrest	\$0	\$0	\$0	\$0
327	must have FW1/X69	Ģ0	70	ΨO	ÇÜ
SZ8	Storage net, passenger seat backrest	\$0	\$0	\$0	\$0
	must have FW1/X69; not with S23	· · · · · · · · · · · · · · · · · · ·			
T75	Door-mounted assist handles, driver & passenger	\$66	\$66	\$66	\$66
V07	Cab rear wall liner	\$403	\$403	\$403	\$403
	not with FW1				
V85	Cigarette lighter & ash cup, front	\$44	\$44	\$44	\$44
VV4	Additional Ground Weld Studs	\$50	\$50	\$50	\$50
	no restriction				
X2R	Conversion to RV requirement	-	-	\$0	\$0
	must have B01+E1X		·		
X93	Deletion of model badge, right rear door	\$0	\$0	\$0	\$0
XM4	Acoustic package	\$97	\$97	\$97	\$97
	standard with CO2/CO3	1 4	1		
	First-aid kit	\$30	\$30	\$30	\$30
Y26	Wheel chocks	\$43	\$43	\$43	\$43
Y45	Emergency flashlight	\$30	\$30	\$30	\$30
Y68	Paint preservative	\$98	\$98	\$98	\$98
Y69	Surface protection for stock vehicles	\$328	\$328	\$328	\$328

	144" 4D High	144" AWD	170" 4D High	170" AWD
	MXCC4H	MXCC4A	мхсс7н	МХСС7А
	907.153	907.153	907.155	907.155
C00   Comfort Package	\$307	\$307	\$307	\$307
.C4 Comfort overhead control panel	Х	Х	X	Х
E4 Lumbar support, co-driver's seat	Х	Х	X	Х
SE5 Lumbar support, driver's seat	Х	Х	Х	Х
SKO Comfort head restraint, driver	Х	Х	Х	Х
K1 Comfort head restraint, co-driver	Х	Х	Х	Х
nust have COS OR X68; not with S23				
COS   Comfort Package (Seat addition)	\$426	\$426	\$426	\$426
GB1 Comfort driver's seat	X	X	X	X
SB2 Comfort passenger seat	X	X	X	X
must have COO				
K68 Comfort Plus Package H15 Heated front passenger seat	\$1,898 X	\$ <b>1,898</b> X	\$1,898 X	\$ <b>1,898</b> X
<u> </u>				
F1 Driver's seat electrically adjustable	Х	Χ	X	Х
F2 Co-driver's seat electrically adjustable	Х	X	X	X
nust have C00 and VF4 OR VF6; not with S23				
CO1 Driver Convenience Package	\$362	\$362	\$362	\$362
12 V power outlet, driver seat base	X	X	X	Х
FJ1 Hinged lid for storage compartment	X	X	X	X
Z9 Keys, two additional masters	X	Χ	X	X
W8 Attention Assist	Х	X	X	Х
	1 400-	400-	400-	4007
	\$805	\$805	\$805	\$805
CO2 Premium Package				
MBUX Multimedia System with 7" touchscreen	X	X	X	X
MBUX Multimedia System with 7" touchscreen  Wet Wiper System	X	Х	Х	Х
3M MBUX Multimedia System with 7" touchscreen 5M3 Wet Wiper System 84 Active Lane Keeping Assist				
MBUX Multimedia System with 7" touchscreen  Wet Wiper System	X	Х	Х	Х
3M MBUX Multimedia System with 7" touchscreen 5M3 Wet Wiper System 84 Active Lane Keeping Assist	X	Х	Х	Х

CA2	C02 in combination with C03	\$547	\$547	\$547	\$547	
CL3	Leather steering wheel	X	Χ	Х	X	
FM3	Wet Wiper System	X	Х	Х	X	
JB4	Active Lane Keeping Assist	X	Х	Х	X	
must	must have CO3 + IF1					

144" 4D High	144" AWD	170" 4D High	170" AWD
МХСС4Н	MXCC4A	МХСС7Н	MXCC7A
907.153	907.153	907.155	907.155

C03	Premium Plus Package	\$2,008	\$2,008	\$2,008	\$2,008
E1B	Tray for smartphones incl. wireless charging	Х	Х	Х	Х
	Navigation	Х	Х	Х	Х
EY2	Intelligent navigation	Х	Х	Х	Х
E4M	MBUX Multimedia System with 10.25" touchscreen	Х	Х	Х	Х
EX9	Free map data updates for 3 years	Х	Х	Х	Х
H1I	Front-to-rear outlet in instrument panel	Х	Х	Х	Х
JA9	Traffic Sign Assist	Х	Х	Х	Х
XM4	Acoustic package	Х	Х	Х	Х
must	have CA2				

X67	Chrome Grille Package	\$325	\$325	\$325	\$325	
CN2	Radiator grille frame in vehicle color	X	Χ	Х	X	
FK3	Chrome plated radiator grille (MB only)	X	X	Х	X	
no re	no restrictions					

X13	Exterior Lighting Package	\$1,801	\$1,801	\$1,801	\$1,801
L13	Fog lamp with cornering light function	X	Χ	Х	X
L22	Partial LED tail lights	Х	Х	Х	X
LA1	High beam assist	X	Х	Х	X
LG7	LED high performance headlamps	X	Х	Х	X
no restrictions					

X69	Swivel Seat Package	\$657	\$657	\$657	\$657
SR8	Swivel base for driver's seat	Х	X	X	Χ
SR9	Swivel base for front passenger seat	Х	Х	Х	Х
S87	Driver's seat frame, low	X	Х	Х	Х
S88	Passenger seat frame, low	Х	Х	Х	Х
FW1	Rear wall deletion, chassis cab	Х	Х	Х	Х
BE2	Handbrake lever, folding	Х	Х	Х	Х
must	have (COO+COS) OR (COO+X68)	-			

		144" 4D High	170" 4D High
		М4СС4Н	М4СС7Н
		907.153	907.155
Engin	2		
_	High Output Engine/9-Speed Trans.	S	S
	AGM battery 12V 70AH	S	S
G43	Automatic transmission, 9G-tronic	S	S
M60	Alternator 14 V / 250 A	S	S
M71	Approval Bio-Diesel B20		
M5N	2.0L 4-cylinder diesel engine (208hp output)	S	S
MH8	SULEV emissions	S	S
Identi	fication Lights - choose while ordering		
V59	Identification Lamps Package	<i>\$</i> 0	\$0
L49	Identification lamps	0	0
	Clearance lights pre-wiring	0	0
For pr	e-wiring only (recommended for RV)	<i>\$</i> 0	\$0
LV7	Clearance lights pre-wiring	0	0
Equip	ment		
A50	Front axle reinforced	S	S
AR2	Axle ratio 3.923	S	S
	Active Brake Assist	S	S
	Hold Function	S	S
	Multifunction steering wheel	S	S
CB8	Stabilization Level II	S	S
CL1	Adjustable steering wheel (angle)	S	S
E07	Hill Start Assist	S	S
-	Standard radio	S	S
E1U	USB-C socket, 5 V	S	S
	Starter battery disconnect	S	S
E3J	Pre-installation for switch panel	S	S
	Trailer hitch prep. wiring	S	S
ED8 EE5	Preinstallation PSM	S	S
	Ultracapacitor discharge module Body Builder Connector	S	S S
ESO	Jump start terminal	S S	S
	Pre-installation for Mercedes me Remote Services	S	S
EY5	Emergency Call System	S	S
EY6	Breakdown management	S	S
F68	Heated & electrically adjustable exterior mirrors	S	S
FF5	Shelf above windshield	S	S
FG8	Cupholder front	S	S
FI1	Remote key (315 mhz) w/central locking	S	S
FJ4	Storage compartment underneath cockpit	S	S
FS2	Exterior mirror extended (for up to 96" box width)	S	S
H16	Heated driver's seat	S	S
H21	Windshield with filter band	S	S
HH2	Heater, auxiliary electric hot air	S	S
нн9	Air Condition, Front	S	S
IH7	Headunit	S	S
J11	Speedometer, miles and km/h	S	S
J55	Seat belt warning for co-driver seat	S	S
J58	Seat belt reminder driver	S	S
J65	Outside temperature gauge	S	S
JA8	Crosswind Assist	S	S
JH3	Communication module (LTE) for dig. services	S	S
JI9	Service interval 20.000 miles	S	S
JK5	Instrument cluster with color display	S	S

		144" 4D High	170" 4D High
		M4CC4H	М4СС7Н
		907.153	907.155
JW2	Deactivation lamp monitoring failure	S	S
JVVZ	. ,	S	S
K60	Black diesel filler cap	S	S
	Exhaust straight to rear		
	24.5 gallon fuel tank	S	S
KL1	Aux fuel sending unit w/ fuel tap	S	S
	Fuel/water seprarator & lubrication package	S	S
KP7	4rd generation SCR emission control system	S	S
L94	Parking lights deletion	S	S
LA2	Headlight assistant	S	S
	Cruise control	S	S
	Front mudflaps	S	S
Q11	Longitudinal member reinforcement	S	S
Q72	Deletion of end cross member	S	S
R60	Provisional spare wheel bracket frame mounted	S	S
R87	Spare tire	S	S
RD9	Unspecified tire brand	S	S
RH7	Tires LT 215/85 R16- DRW	S	S
RM0	All-season tires	S	S
RS6	5.5 J x 16 steel wheels	S	S
S02	Standard driver seat	S	S
S04	Standard front passenger seat	S	S
S22	Armrest for driver's seat	S	S
S25	Armrest for front passenger seat	S	S
SA5	Front airbag, driver	S	S
SA6	Front airbag, passenger	S	S
SH1	Thorax-pelvis sidebag, driver	S	S
SH2	Thorax-pelvis sidebag, co-driver	S	S
SH9	Airbag, driver/passenger window	S	S
SK2	Seat occupancy sensor, driver's seat	S	S
XL4	GVWR 12,125 lbs. / 5.500 Kg	S	S
X64	Plates/booklets in English (US)	S	S
X99	Manufacturer Mercedes-Benz AG	S	S
XC8	VIN visible from outside	S	S
XI2	Change Year G2-I	S	S
XY4	Model Year 2024	S	S
	Jack, hydraulic	S	S
	Vehicle class, incomplete vehicle (49 CFR 571.3)	S	S
ZU8	USA country version	S	S
ZZ4	Brand content Mercedes-Benz North America	S	S

		144" 4D High	170" 4D High
		М4СС4Н	М4СС7Н
		907.153	907.155
1		307.133	
B01	ESP for increased Center of Gravity above 39.4"	-	\$0
	must have CB4/CB8; not with RF8	1 4	4
BE2	Handbrake lever, folding	\$62	\$62
C72	Bumpers front/rear primed	\$158	\$158
	must have CN2 (part of X67), not with CM2		4
CB2	Comfort suspension, air suspension	-	\$3,294
	Must have ED5+A50+KA3+B01. Not with CB8/CE8/A4M		4
CB4	Stabilization Level III	\$209	\$209
	not with CB8		4.50
CE8	Raised rear body mounts	-	\$458
CM2	Bumpers/detachable body parts painted body colour	\$483	\$483
	must have CN2/X67 + (7755/9147/9197/9775)	4	4
CM9	Primed side moldings	\$408	\$408
	must have C72, not with CM2	4	4
E1B	Tray for smartphones incl. wireless charging	\$175	\$175
	must have CO2/E3M + H1I		40:-
E1E	Navigation	\$815	\$815
	must have CO2/E3M, not with CO3	<u> </u>	
E1S	Sirius XM, satellite radio	\$285	\$285
	must have CO2/E3M/CO3		
E1X	MBUX multimedia 6-hour runtime	-	\$0
	must have X2R + (C02+E1E/E1S)/C03/(E3M+E1E/E1S)		
E1R	Additional Fuses (40/80/150/100 Ampere)	-	\$57
	must have X2R/ not with E1Y		
E1Y	Additional Fuses (40/80/80/100 Ampere)	-	\$57
	must have X2R / not with E1R		
E2A	Access point for BB special signals in cockpit	\$32	\$32
E2I	Additional battery, co-driver seat base	\$277	\$277
	Must have E36; not with E2M	<u> </u>	
E2M	,	\$277	\$277
	must have X01+E36; not with E2I/X69	<u> </u>	
E3M	MBUX Multimedia System with 7" touchscreen	\$531	\$531
	not with CO2/CO3; must have JK5	4	4
E36	Cutoff relay for additional battery	\$124	\$124
	standard with E2I/E2M	<u> </u>	
E46	12 V power outlet, driver seat base	\$103	\$103
E5M	Extension of PSM standard contact	\$65	\$65
EA5	Pre-wiring central locking (upfitter doors rear)	\$44	\$44
ED4	AGM battery 12V 92 AH 850 A	\$113	\$113
	not with ED1	40-4	40=4
ED5	Parametric special module (PSM)	\$354	\$354
	not with ED8	4	4
EE3	115 V socket	\$140	\$140
EP7	Basic electric fitting for rear loudspeakers	\$76	\$76
ES5	Charging package, dashboard	\$92	\$92
ET4	Active Distance Assist DISTRONIC	\$294	\$294
	must have CO3	4	44.0
F35	Window in cab rear wall	\$149	\$149
	must have F61/FV1; not with FW1	4	40
F49	Electrically heated windshield	\$244	\$244
=c:	must have ED4; not with LA3		***
F61	Interior rear view mirror	\$41	\$41
	must have CO2/CO3/E3M		
F85	Pre-Installation Digital Rearview Mirror	\$736	\$736
	must have LA2/LA3 - not with F61		
FE9	Additional DIN-slot	\$91	\$91
FF8	Overhead storage slot, front center	\$117	\$117

		144" 4D High	170" 4D High
		M4CC4H	М4СС7Н
		907.153	907.155
FJ1	Hinged lid for storage compartment	\$105	\$105
FJ5	Hinged Lid for Storage Compartments left and right	\$108	\$108
	must have FJ1/C01	Ÿ200	Ψ200
FR7	Pre-wiring rear view camera (head unit display)	\$73	\$73
	must have CO2/CO3; not with FV1	ψ.3	ψ
FV1	Pre-wiring rear view camera (mirror display)	\$273	\$273
	not with F61/FR7/LA3	Ψ270	Ψ2.0
FW1	Rear wall deletion, chassis cab	\$0	\$0
	must have P08; not with FY1	7.5	7.0
FY1	Security alarm w. interior motion sensor	\$654	\$654
	must have LC4/C00; not with FW1/X2R	700.	700
FY7	Optional 3-button keys	\$41	\$41
FZ9	Keys, two additional masters	\$136	\$136
H04	Heat insulation, front compartment	\$209	\$209
	must have FW1/V07	7=00	7=00
H12	Fuel-fired pre-heater/booster (17K BTU)	\$925	\$925
	must have ED4; not with HZ9	70.00	70.00
H15	Heated front passenger seat	\$318	\$318
25	must have H16; not with X68	ψ010	<b>4010</b>
H88	Rear heater prep	\$453	\$453
	must have ED4+(H12/HZ9)	ψ 133	ψ 155
H1I	Front-to-rear outlet in instrument panel	\$0	\$0
	must have FJ1/C01	7.5	7.0
HH4	Thermotronic automatic climate control	\$378	\$378
	must have JF1	φσ, σ	ψ37.0
HZ9	Fuel-fired heater booster (18,000 BTU)	\$756	\$756
	not with H12	ψ.30	ψ.30
J1V	Pre-installation Blind Spot Assist	\$504	\$504
J51	Fuel gauge, optimized for aux. fuel tap	\$80	\$80
	not with HZ9/H12	755	700
J52	Engine oil level display at cold start	\$0	\$0
JB1	360 Degree Camera For Cluster A Body	\$1,133	\$1,133
-	Not with JB2/JB3	Ų1)100	Ψ1)100
JB2	360 Degree Camera For Cluster B Body	\$1,133	\$1,133
	Not with JB1/JB3	7-7-55	+ = / = 0
JB3	360 Degree Camera For Cluster C Body	\$1,133	\$1,133
	Not with JB1/JB2	, , ,	, ,
JB4	Active Lane Keeping Assist	\$322	\$322
	not with CO2/CA2	, -	, -
JF1	Rain sensor	\$118	\$118
	Standard with CO2/CA2/X11; not with LA3	,	
JW0	Backup alarm	\$111	\$111
	not wit Q72	,	,
JW8	Attention Assist	\$55	\$55
KA3	Lateral exhaust pipe in front of rear axle, left	-	\$60
K51	Misfueling prevention for Diesel	\$55	\$55
K52	DEF fluid filler cap - lockable	\$30	\$30
L13	Fog lamp with cornering light function	\$223	\$223
L72	Pre-installation load compartment lighting	\$195	\$195
L76	Wire harness tail lamp w/ extended wiring	\$148	\$148
L77	Wiring for additional turn signals	\$98	\$98
L90	Tail lamp deletion, non-LED	-\$26	-\$26
	not with L22	,	
L91	Pre-wiring LED tail lights	\$55	\$55
	not with L22/L90	7	,,,,
LB9	Illuminated front exits	\$105	\$105
	!	,	1

		144" 4D High	170" 4D High
		M4CC4H	м4СС7Н
		907.153	907.155
LC4	Comfort overhead control panel	\$105	\$105
LV6	Third brake light pre-wiring	\$36	\$36
M20	Speed limitation 65 mph	\$67	\$67
	not with MD3	•	
M61	Alternator 14 V / 280 A	\$188	\$188
MD3	Top speed limitation 75 mph	\$71	\$71
	not with M20		
N62	Front engine bracket for additional alternator	\$523	\$523
	not with N63		
N63	Front engine bracket for auxiliary A/C compressor	\$523	\$523
	not with N62		
P08	Cover for transport	\$0	\$0
	must have FW1/X69	1 4 1	4
Q18	End cross member bolted	\$73	\$73
	Trailer cross member 7,500 lbs capacity	\$209	\$209
R65	Spare tire bracket below frame	\$0	\$0
DO4	must have Q18; not with Q72/R60/R92	6440	6110
R91	Spare tire deletion	-\$110	-\$110
DO3	must have R92; not with R87/R60	ćo	ćo
R92	Spare tire carrier deletion must have R91; not with R65/R60	\$0	\$0
R98	Rims painted jet black	\$91	\$91
1130	not with RM2	751	791
RF1	Tire brand Continental	\$0	\$0
	not with RD9	ΨO	ŢŪ.
RF8	Tire brand Michelin	\$0	\$0
	not with RD9/RF1/RM1	7.0	7-
RM1	M+S winter tires	\$190	\$190
	must have RD9/RF1; not with RF8/X31	,	·
RM2	Rims painted arctic white	\$91	\$91
	not with X31/R98	·	·
RM9	Specially requested tires	\$113	\$113
	must have RF1/RF8; not with RD9	·	·
S23	Twin front passenger seat	\$448	\$448
	not with C00/X68/X01	,	·
S28	Armrest, driver and passenger door	\$58	\$58
S62	Seat belts orange, driver and front passenger	\$36	\$36
	not with S23		·
SB9	Driver's seat plus	\$267	\$267
	must have FY7		
SZ7	Storage net, driver's seat backrest	\$0	\$0
	must have FW1/X69	•	
SZ8	Storage net, passenger seat backrest	\$0	\$0
	must have FW1/X69; not with S23		
T75	Door-mounted assist handles, driver & passenger	\$66	\$66
V07	Cab rear wall liner	\$403	\$403
	not with FW1	,	
V85	Cigarette lighter & ash cup, front	\$44	\$44
VV4	Additional Ground Weld Studs	\$50	\$50
	no restriction	<b>400</b>	+30
X2R	Conversion to RV requirement	-	\$0
	must have B01+E1X		Ψ.
X93	Deletion of model badge, right rear door	\$0	\$0
XM4	Acoustic package	\$97	\$97
AIV14		١٤ڔ	751
V10	standard with CO2/CO3	ć20	620
Y10	First-aid kit	\$30	\$30
Y26	Wheel chocks	\$43	\$43
Y45	Emergency flashlight	\$30	\$30
Y68	Paint preservative	\$98	\$98
Y69	Surface protection for stock vehicles	\$328	\$328

144" 4D High	170" 4D High
М4СС4Н	М4СС7Н
907.153	907.155

C00	Comfort Package	\$307	\$307
LC4	Comfort overhead control panel	Х	Х
SE4	Lumbar support, co-driver's seat	Х	X
SE5	Lumbar support, driver's seat	Х	X
SK0	Comfort head restraint, driver	Х	Х
SK1	Comfort head restraint, co-driver	Х	Х
must	have COS OR X68: not with S23		

COS	Comfort Package (Seat addition)	\$426	\$426
SB1	Comfort driver's seat	X	X
SB2	Comfort passenger seat	Х	X
must	have COO	_	

X68	Comfort Plus Package	\$1,898	\$1,898	
H15	Heated front passenger seat	Х	X	
SF1	Driver's seat electrically adjustable	Х	X	
SF2	Co-driver's seat electrically adjustable	Х	Х	
must	must have COO and VF4 OR VF6; not with S23			

C01	Driver Convenience Package	\$362	\$362
E46	12 V power outlet, driver seat base	X	X
FJ1	Hinged lid for storage compartment	X	X
FZ9	Keys, two additional masters	X	Х
JW8	Attention Assist	X	Х

C02	Premium Package	\$805	\$805
E3M	MBUX Multimedia System with 7" touchscreen	X	Х
FM3	Wet Wiper System	X	Х
JB4	Active Lane Keeping Assist	Х	X
must	have JF1 + XM4		

CA2	C02 in combination with C03	\$547	\$547
CL3	Leather steering wheel	Х	Х
FM3	Wet Wiper System	Х	Х
JB4	Active Lane Keeping Assist	Х	Х
must have CO3 + JF1			

144" 4D High	170" 4D High
М4СС4Н	М4СС7Н
907.153	907.155

C03	Premium Plus Package	\$2,008	\$2,008
E1B	Tray for smartphones incl. wireless charging	Х	X
	Navigation	Х	X
EY2	Intelligent navigation	Х	X
E4M	MBUX Multimedia System with 10.25" touchscreen	Х	X
EX9	Free map data updates for 3 years	Х	X
H1I	Front-to-rear outlet in instrument panel	Х	X
JA9	Traffic Sign Assist	Х	X
XM4	Acoustic package	Х	X
must	have CA2	_	

X67	Chrome Grille Package	\$325	\$325									
CN2	Radiator grille frame in vehicle color	Х	X									
FK3	Chrome plated radiator grille (MB only)	Х	Х									
no re	no restrictions											

X13	Exterior Lighting Package	\$1,801	\$1,801							
L13	Fog lamp with cornering light function	X	Х							
L22	Partial LED tail lights	X	Х							
LA1	High beam assist	X	Х							
LG7	LG7 LED high performance headlamps X X									
no re	no restrictions									

X69	Swivel Seat Package	\$657	\$657
SR8	Swivel base for driver's seat	Х	Х
SR9	Swivel base for front passenger seat	Х	Х
S87	Driver's seat frame, low	Х	Х
S88	Passenger seat frame, low	Х	Х
FW1	Rear wall deletion, chassis cab	X	Х
BE2	Handbrake lever, folding	X	Х
must	have (C00+C0S) OR (C00+X68)		

# "Incomplete Vehicle" Packages - Fleet Only

If any of the below packages are ordered, vehicle will become an "incomplete vehicle"! In this case an upfitter will become the final stage manufacturer.

Please note that the involvement of an upfitter is required to register the vehicle. We recommend working with one of our ExpertSolutions Partners.

For questions or further assistance please reach out to: vaninfo@mbusa.com

## Cargo Models- Only 4cyl standard & 4cyl high Diesel engines

			2500	1		2500			2500//D	1			
			2500			3500			3500XD			4500	
		144"	170"	170"EXT									
		4x2/AWD	4x2/AWD	4x2/AWD	4x2	4x2	4x2	4x2/AWD	4x2/AWD	4x2/AWD	4x2	4x2	4x2
F02	Windows All Around Package	\$2,714	\$3,429	\$3,429	\$2,714	\$3,429	\$3,429	\$2,714	\$3,429	\$3,429	\$2,714	\$3,429	\$3,429
F43	Laminated glass rear	Х	Χ	Χ	Х	Χ	Х	Х	Χ	Х	Χ	Х	Х
H22	Rear window defroster	Х	Χ	Χ	Х	Χ	Х	Х	Χ	Х	Χ	Х	Х
VA7	Storage compart. w/ net in rear doors	Х	Χ	Χ	Х	Χ	Х	Х	Χ	Х	Χ	Х	Х
W02	Panel van w/windows all round	Х	Х	Х	X	Х	Х	X	Х	Х	X	Х	Х
W17	2nd row, fixed window, passenger side	Х	Х	Х	X	X	Х	X	Χ	Х	X	Х	Х
W22	Fixed window, center left	-	Χ	Χ	-	Χ	Х	-	Χ	Х	-	Х	Х
W23	Fixed window, center right	-	Χ	Χ	-	Χ	Х	-	Χ	Х	-	Х	Х
W27	Fixed window, rear left	Х	Χ	Χ	Х	Χ	Х	Х	Χ	Х	Χ	Х	Х
W28	Fixed window, rear right	Х	Х	X	X	Х	Х	Х	Χ	X	Х	Х	X

Choose while ordering: 1. W61/W78 2. W16/W33 W22 and W23 only available for 170" and 170"170"EXT. WB If ordered with standard roof CHS production required

			2500			3500			3500XD			4500	
		144"	170"	170"EXT	144"	170"	170"EXT	144"	170"	170"EXT	144"	170"	170"EXT
		4x2/AWD	4x2/AWD	4x2/AWD	4x2	4x2	4x2	4x2/AWD	4x2/AWD	4x2/AWD	4x2	4x2	4x2
F03	Window Prep Package I (knockouts for window installation)	\$674	\$674	\$674	\$674	\$674	\$674	\$674	\$674	\$674	\$674	\$674	\$674
H22	Rear window defroster	Х	Х	Х	Х	Х	Х	Х	Х	Х	Х	Х	Х
P08	Cover for transport	Х	Х	Х	Х	Х	Х	Х	Х	Х	Х	Х	Х
VA7	Storage compart. w/ net in rear doors	X	Х	Х	Χ	Х	Х	Х	Х	Х	Х	Х	X
W02	Panel van w/windows all round	X	Х	Х	Χ	X	X	Х	X	Х	Х	X	Х
W16	2nd row, fixed window, driver side	X	Х	Х	Χ	X	X	Х	X	Х	Х	X	Х
W17	2nd row, fixed window, passenger side	X	Х	Х	Χ	X	X	Х	X	Х	Х	X	Х
W22	Fixed window, center left	-	Х	Х	-	Х	Х	-	Х	Х	-	Х	X
W23	Fixed window, center right	-	Х	Χ	-	X	Х	-	X	Х	-	Х	X
W27	Fixed window, rear left	X	Х	Χ	Χ	X	Х	Х	X	Х	Χ	Х	X
W28	Fixed window, rear right	X	Х	Х	Χ	X	X	Х	X	Х	Х	X	Х
W61	Windows in rear doors	X	Х	Х	Χ	X	X	X	X	X	Χ	X	X
W94	Window openings w/o glass - side and rear	Х	Х	Х	X	Х	Х	Х	Х	Х	X	Х	Х

W22 and W23 only available for 170" and 170"170"EXT. WB.

			2500			3500			3500XD			4500	
		144"	170"	170"EXT	144"	170"	170"EXT	144"	170"	170"EXT	144"	170"	170"EXT
		4x2/AWD	4x2/AWD	4x2/AWD	4x2	4x2	4x2	4x2/AWD	4x2/AWD	4x2/AWD	4x2	4x2	4x2
F07	Window Prep Package II (knockouts for window installation with windows in rear door)	\$751	\$751	\$751	\$751	\$751	\$751	\$751	\$751	\$751	\$751	\$751	\$751
H22	Rear window defroster	Х	Х	Х	Х	X	X	Х	X	Х	X	X	Χ
P08	Cover for transport	X	Х	Χ	Х	X	Х	Х	X	Х	Χ	Х	Х
VA7	Storage compart. w/ net in rear doors	X	Х	Χ	Х	Х	Х	Х	Х	Х	Χ	Х	Х
W02	Panel van w/windows all round	X	Х	Χ	Х	Х	Х	Х	Х	Х	Χ	Х	Х
	2nd row, fixed window, driver side	X	Х	Χ	X	Х	Χ	X	Х	X	Χ	Х	Χ
W17	2nd row, fixed window, passenger side	X	Х	Χ	Х	Х	Х	Х	Х	Х	Χ	Х	Х
W22	Fixed window, center left	-	Х	Χ	-	Х	X	-	X	X	-	X	Х
W23	Fixed window, center right	-	Х	Х	-	X	X	-	X	Х	-	X	X
W27	Fixed window, rear left	Х	Х	Х	Х	X	X	Х	X	Х	X	X	X
W28	Fixed window, rear right	Х	Х	Х	Х	X	X	Х	X	Х	Χ	X	Χ
W93	Window openings w/o glass - side	X	Х	Χ	Х	X	Х	Х	X	Х	Χ	Х	X

Choose while ordering: W61/W78

W22 and W23 only available for 170" and 170"170"EXT. WB.

### "RV Bundles" for Cargo and Cab Chassis Models

RVO and RV1 are bundling essential product features specifically for RV upfits. MBUSA Product Management suggests that these bundles are added to any vehicle that will receive an RV-type upfit in order to allow an easier upfit process, enhanced technical usability as well as an improved driving performance tailored to RV vehicle characteristics.

### Cargo Models- Only 4cyl high output Diesel engines

			2500			3500			3500XD		4500		
		144"	170"	170"EXT	144"	170"	170"EXT	144"	170"	170"EXT	144"	170"	170"EXT
		4x2/AWD	4x2/AWD	4x2/AWD	4x2	4x2	4x2	4x2/AWD	4x2/AWD	4x2/AWD	4x2	4x2	4x2
RV0	RV Technical Bundle	\$957	\$957	\$957	\$957	\$957	\$957	\$957	\$957	\$957	\$957	\$957	\$957
E1X	MBUX 6-hour runtime	Х	X	Х	-	Х	Х	-	X	X	-	Х	Х
J51	Fuel gauge, optimized for aux. fuel tap	Х	X	Х	Х	Х	Х	Х	X	X	Х	Х	Х
N62	Front engine bracket for additional alternator	X	Х	Х	X	Х	Х	X	Х	X	X	Х	Х
KL1	Aux fuel sending unit w/ fuel tap	S	S	S	S	S	S	S	S	S	S	S	S
ED5	Parametric special module (PSM)	Х	X	Х	Х	Х	Х	X	Х	Х	Х	Х	Х

Not with H12/HZ9/HK4/N63

Must have X69 + (E3M/C02/C03) + must have X2R+B01/RV1
On 3500/3500XD/4500 144"WB models, X2R+B01/RV1 from the above rule is not required.

		_															
				2500				3500				3500XD				4500	
		144"	17	0"	170	"EXT	144"	170"	170"EXT	144"	17	'0"	170	"EXT	144"	170"	170"EXT
		4x2	4x2	AWD	4x2	AWD	4x2	4x2	4x2	4x2	4x2	AWD	4x2	AWD	4x2	4x2	4x2
RV1	RV Suspension Bundle	\$1,701	\$1,701	\$0	\$1,701	\$0	\$879	\$879	\$879	\$879	\$879	\$0	\$879	\$0	\$491	\$491	\$491
A50	Front axle reinforced	X	Х	-	Х	-	Х	Х	Х	Χ	Х	-	Χ	-	S	S	S
B01	Vehicle version for high load	X	Х	Х	Х	Х	-	Х	Х	-	Х	Χ	Χ	Χ	-	Х	Х
CB4	Stabilization Level III	Х	Х	-	Х	-	Х	Х	Х	Х	Х	-	Х	-	Х	Х	Х
CE8	Raised rear body mounts	Х	Х	-	Х	-	Х	Х	Х	X	Х	-	X	-	X	Х	X
X2R	Bodybuilder requirement: conversion to motorhome	Х	Х	X	Х	Х	-	Х	Х	-	Х	Х	Х	Х	-	Х	Х

Must have RV0 + D93; 3500XD must have X34

not with CB1/CB2/CB7/CB8/S23/RH0; 144"" WB not with K60

# Cab Chassis Models- Only 4cyl high output Diesel engines

				3500XD			45	500	
			144"	17	0"		144"	170"	
			4x2	4x2	AWD		4x2	4x2	
RV0	RV Technical Bundle		\$1,105	\$1,105	\$1,105		\$1,105	\$1,105	1
J51	Fuel gauge, optimized for aux. fuel tap		Χ	Х	Χ		X	Х	
LV7	Clearance lights pre-wiring		X	Х	X		Х	X	
L76	Wire harness tail lamp w/ extended wiring	N/A	X	X	X	N/A	X	X	N/A
E1X	MBUX 6-hour runtime	IN/A	-	Х	Х	IN/A	-	Х	IN/A
N62	Front engine bracket for additional alternator		X	X	X		X	X	
KL1	Aux fuel sending unit w/ fuel tap		S	S	S		S	S	
ED5	Parametric special module (PSM)		Х	X	Х		Х	Х	1

Not with V59/H12/HZ9/N63

Must have X69 + (E3M/C02/C03) + FR7/FV1 + must have X2R+B01/RV1 on 170"WB models only.

On 3500XD/4500 144"WB models, X2R+B01/RV1 from the above rule is not required.

			3500XD			45	00	
		144"	17	'0"		144"	170"	
		4x2	4x2	AWD		4x2	4x2	
RV Suspension Bundle		\$596	\$1,054	\$0		\$209	\$667	
Front axle reinforced		Х	Х	-		S	S	
Vehicle version for high load	NI/A	-	Х	Х	NI/A	-	Х	N/A
Stabilization Level III	N/A	Х	Х	-	N/A	Х	Х	IN/A
Raised rear body mounts		-	X	-		-	Χ	
Bodybuilder requirement: conversion to motorhome		-	Χ	х		-	Х	
	Front axle reinforced Vehicle version for high load stabilization Level III Valsed rear body mounts	AV Suspension Bundle Front axie reinforced //ehicle version for high load Stabilization Level III Raised rear body mounts	AV Suspension Bundle Special S	144"   17	144"   170"	144"   170"	144"   170"   144"   4x2   4x2   AWD	144"   170"

Must have RVO; 3500XD must have X34 not with CB2/CB8; 144" WB not with K60

	Retail Orders													
	ExpertSolutions™ Ship-Thru Partners													
Price	Upfitter	U-Code	Descripton of U-Code	CA	lodels /	Accepto	ed PV	Shipping Contact	Shipping Email Address	Shipping phone number	Shipping address			
\$125	Driverge	US1	Driverge Ship-Thru	Х	-	-	-	Stephen Fink	stephen.fink@driverge.com	330 247 5246	9004 Sightline Drive, Suite 5, Ladson, SC 29456			
\$125		I UK1	Knapheide Van Equipment Ship-Thru	Х	-	-	-							
\$125	Knapheide	I HK2	Gruau/ThermoKing by Knapheide Ship-Thru	х	- 1	1	1	Karl Braun	expertsolutions@knapheide.com	854 529 4923	2486 US Highway 52, Moncks Corner, SC 29461			
\$125		UK3	Knapheide Bodies Ship-Thru	1	х	1	1							
\$125	Holman	UA1	Holman Ship-Thru	х	-	х	-	Tana Drake	Tana.Keuck@holman.com	866 428 8267	211 Farmington RD, Summerville,			
\$125	noiman	UA2	Holman Mobile Service Van Ship-Thru	х	-	х	х	Tana Drake	Talla.Neuck@flolfflafl.com	000 428 8207	SC 29483			
	*US1, UK1, UK2, UK3, UA1, UA2 are to be used when ordering the corresponding ExpertSOLUTIONS™ upfits as shown on upfitterportal.com or mbvans.com													

	Other Charleston, SC Ship-Thru Partners														
Price	Facility	U-Code	Description of U-Code	CA CA	lodels /	Accepte	ed PV	Shipping Contact	Shipping Email Address	Shipping phone number	Shipping address				
			Innovative Vehicle Solutions	CA	CC	CV	PV			number	3241 Benchmark Drive, Ladson,				
\$125	IVS	LII1		Х	Х	Х	Х	Sam Kuhn	sam.k@innovativevehicle.com	843 376 3822					
·			Ship-Thru								SC 29456				
6425	A 41-4		Midway Specialty Vehicles	.,	.,	.,	v	David Cillada		F74 220 4400	3285 Benchmark Drive, Ladson,				
\$125	Midway	UM1	Ship-Thru	Х	Х	Х	Х	Russ Gilpin	rgilpin@mymidway.com	574-320-4188	SC 29456				
\$125	Thomas Vina	LIES	Thousand King of Charleston	х	~			Trouge Claud	TELevid @fleeteevineese eeee	042 744 5040	180 Strathmore RD, Summerville,				
\$125	Thermo King	U52	Thermo King of Charleston	Х	Х	-	•	Trevor Floyd	TFloyd@fleetsourcesc.com	843 744 5040	SC 29486				

#### **Small/Medium Fleet Upfitter Orders** All Charleston, SC Ship-Thru Partners Models Accepted Shipping phone U-Code **Shipping Email Address** Price Facility Descripton of U-Code **Shipping Contact** Shipping address CA CV PV CC 9004 Sightline Drive, Suite 5, Х 330 247 5246 \$125 Driverge US5 Driverge Fleet Ship-Thru Stephen Fink stephen.fink@driverge.com Ladson, SC 29456 2486 US Highway 52, Moncks \$125 Knapheide Knapheide Fleet Ship-Thru Χ Karl Braun 854 529 4923 Х Х expertsolutions@knapheide.com Corner, SC 29461 211 Farmington RD, Summerville \$125 Holman UA5 Holman Fleet Ship-Thru Х Χ Х Tana Drake Tana.Keuck@holman.com 866 428 8267 SC 29483 Innovative Vehicle Innovative Vehicle Solutions 3241 Benchmark Drive, Ladson, \$125 UI5 Х Х Χ 843 376 3822 Sam Kuhn sam.k@innovativevehicle.com Solutions Ship-Thru (Fleet) SC 29456 Midway Specialty Vehicles 3285 Benchmark Drive, Ladson, Х х 574-320-4188 \$125 Midway UM1 Х Russ Gilpin rgilpin@mymidway.com Ship-Thru SC 29456 180 Strathmore RD, Summerville Thermo King Thermo King of Charleston Trevor Floyd TFloyd@fleetsourcesc.com 843 744 5040 SC 29486

## **Ordering Information**

U-Codes can be added to the Purchase Order via the VII screen in NetStar OR by emailing the request to MBUSA Van Distribution (vandistribution@mbusa.com)

\*Don't forget to place your upfit order with the upfitter after you add the U-Code\* U-Codes can be added/changed through D40 status. No changes permitted after D41 status

U-Codes will carry over for dealer traded vehicles

Any requests to remove a U-Code must be approved by the Van Distribution & Upfitter Management Departments

For more information on U-codes, please reach out to the Upfitter Management team: upfitterinfo@mbusa.com

All information contained in this Reference Guide is based on the latest product information available at the time of publication. Mercedes-Benz USA, LLC reserve the right to make changes at any time, without notice, in colors, materials, equipment, specifications and models.

Prices are manufacturer suggested retail prices and are subject to change.