Version 1.0

# MY22

# SPRINTER

# Dealer Ordering Guide




Publish date: 8/11/2021



# **MY22 - Changes & Model Overview**

	MY22 Changes					
Engines	Carry-over from MY21					
Models	arry-over from MY21					
Now Standard	d ED4 standard for all CA CV PV (change implemented in MY21 already) EW6 Pre-installation for Mercedes me remote services					
	X05 Package discontinued (S23 available as option, Y2A discontinued)					
Packages	C02/CA2 - ordering might be partially restricted due to semi-conductor shortage					
RV Bundles	2 RV Bundles are now available for Cargo and CC 6cyl Diesel models					
	Suspension Offerings updated (see suspension matrix for comprehensive overview)					
	S23 now available as standalone option (X05 package discontinued)					
	E3M JK5 JB4 now available outside of C02/CA2 - ordering might be partially restricted due to					
	semi-conductor shortage					
	E1G replaced with EY2 - same functionality (available in package only)					
	X2R available for all diesel CA/CC; not available for 3500/3500XD/4500 144" wheelbase					
	B01 available for all engines on CA/CV/CC; not available for 3500/3500XD/4500 144" wheelbase					
Ontional Foatures	CB4 available for all 6cyl diesel CA/CC models					
Optional Features	New options shown in DOG but SOP pending:					
	E1X MBUX 6-hour runtime					
	E1R Additional Fuses (40/80/150/100 Ampere)					
	E1Y Additional Fuses (40/80/80/100 Ampere)					
	J1V Pre-installation Blind Spot Assist					
	JB8 360 Degree Camera					
	VV4 Additional Ground Weld Studs					
	W5F 90 Degree fixation point- Rear Doors					
Others	Updated Suspension Matrix and product detail					
Others	RV Bundles					

# **Sprinter Models**



# **MY22 MSRP Overview**

Model	GVWR	Wheelbase	Engine	Roof	MB Model	MSRP*
	1500 (8,550 GVW)	144" WB	Gas	SR	M1CA4G	\$37,000
			Gas	SR	M2CA4G	\$38,250
		144'' WB	4 Cyl	SR	M2CA44	\$41,450
		144 VVB	6 Cyl	SR	M2CA46	\$43,400
			4x4	SR	M2CA4X	\$51,600
	2500		Gas	HR	M2CA7G	\$43,800
	2500 (9,050 GVW)	170'' WB	4 Cyl	HR	M2CA74	\$47,000
	(3,030 G V VV)	170 WB	6 Cyl	HR	M2CA76	\$48,950
			4x4	HR	M2CA7X	\$57,150
			4 Cyl	HR	M2CAE4	\$48,950
		170EXT WB	6 Cyl	HR	M2CAE6	\$50,900
			4x4	HR	M2CAEX	\$59,100
	3500 (9,990 GVW)	144" WB	4 Cyl	SR	M3CA44	\$43,900
		144 VVB	6 Cyl	SR	M3CA46	\$45,850
		170" WB	4 Cyl	HR	M3CA74	\$49,450
			6 Cyl	HR	M3CA76	\$51,400
Cargo Vans		170EXT WB	4 Cyl	HR	M3CAE4	\$51,400
			6 Cyl	HR	M3CAE6	\$53,350
	252040	144" WB	4 Cyl	SR	MXCA44	\$46,300
			6 Cyl	SR	MXCA46	\$48,250
			4x4	SR	MXCA4X	\$56,450
			4 Cyl	HR	MXCA74	\$51,850
	3500XD (11,030 GVW)	170" WB	6 Cyl	HR	MXCA76	\$53,800
	(11,030 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0		4x4	HR	MXCA7X	\$62,000
			4 Cyl	HR	MXCAE4	\$53,800
		170EXT WB	6 Cyl	HR	MXCAE6	\$55,750
			4x4	HR	MXCAEX	\$63,950
		144" WB	4 Cyl	SR	M4CA44	\$48,400
		744 AAD	6 Cyl	SR	M4CA46	\$50,350
	4500	170" WB	4 Cyl	HR	M4CA74	\$53,950
	(12,125)	170 000	6 Cyl	HR	M4CA76	\$55,900
		170EXT WB	4 Cyl	HR	M4CAE4	\$55,900
		I/OLAT WD	6 Cyl	HR	M4CAE6	\$57,850

<sup>\*</sup>MSRP excludes destination and delivery \$1,695.

<sup>4</sup>x4 MSRP shown above include upcharge of X30 package

Model	GVWR	Wheelbase	Engine	Roof	MB Model	MSRP*
			Gas	SR	M2CV4G	\$42,000
		144'' WB	4 Cyl	SR	M2CV44	\$45,200
		144 VVB	6 Cyl	SR	M2CV46	\$47,150
	2500		4x4	SR	M2CV4X	\$55,350
	(9,050 GVW)		Gas	HR	M2CV7G	\$48,100
		170'' WB	4 Cyl	HR	M2CV74	\$51,300
		170 WB	6 Cyl	HR	M2CV76	\$53,250
			4x4	HR	M2CV7X	\$61,450
		144" WB	4 Cyl	SR	M3CV44	\$47,650
	3500	144 VVB	6 Cyl	SR	M3CV46	\$49,600
Cuana Vana	(9,990 GVW)	170" WB	4 Cyl	HR	M3CV74	\$53,750
Crew Vans		170 WB	6 Cyl	HR	M3CV76	\$55,700
			4 Cyl	SR	MXCV44	\$50,050
		144" WB	6 Cyl	SR	MXCV46	\$52,000
	3500XD (11,030 GVW)		4x4	SR	MXCV4X	\$60,200
		170" WB	4 Cyl	HR	MXCV74	\$56,150
			6 Cyl	HR	MXCV76	\$58,100
			4x4	HR	MXCV7X	\$66,300
	4500 (12,125)	144" WB	4 Cyl	SR	M4CV44	\$52,150
			6 Cyl	SR	M4CV46	\$54,100
		170" WB	4 Cyl	HR	M4CV74	\$58,250
			6 Cyl	HR	M4CV76	\$60,200
	1500 (8,550 GVW)	144" WB	Gas	SR	M1PV4G	\$43,800
			Gas	SR	M2PV4G	\$45,050
		144'' WB	4 Cyl	SR	M2PV44	\$48,250
Passenger Vans	2500	12-seater	6 Cyl	SR	M2PV46	\$50,200
	(9,050/9,480)		4x4	SR	M2PV4X	\$58,400
	, , , , ,	170" WB	4 Cyl	HR	M2PV74	\$56,020
		15-seater	6 Cyl	HR	M2PV76	\$57,970
		144" WB	4 Cyl	n/a	MXCC44	\$41,300
	3500XD	144 VVB	6 Cyl	n/a	MXCC46	\$43,250
	(11,030 GVW)	170" \\	4 Cyl	n/a	MXCC74	\$42,100
Cab Chassis		170" WB	6 Cyl	n/a	MXCC76	\$44,050
Cab Chassis		144" W/D	4 Cyl	n/a	M4CC44	\$43,430
	4500	144" WB	6 Cyl	n/a	M4CC46	\$45,380
	(12,125 GVW)	170" \\/D	4 Cyl	n/a	M4CC74	\$44,230
		170" WB	6 Cyl	n/a	M4CC76	\$46,180

<sup>\*</sup>MSRP excludes destination and delivery \$1,695.

<sup>4</sup>x4 MSRP shown above include upcharge of X30 package

# **Exterior Paint Overview**

Code	Description	Price	Paint	Code	Description	Price	Paint
1243	Calcite yellow	\$675		7701	Pebble grey	\$0	
3432	Sunset red	\$675		7224	Graphite grey	\$675	
3583	Velvet red	\$0		7708	Silver grey	\$675	
3589	Jupiter red	\$0		7709	Blue grey	\$0	
5362	Brilliant blue	\$675		7755	Tenorite grey metallic	\$1,070	
5389	Steel blue	\$0		7992	Selenite grey metallic	\$1,070	
5524	Black blue	\$1,070		9040	Jet black	\$1,070	
5890	Cavansite blue metallic	\$1,070		9136	Grey white	\$675	
5957	Vanda blue	\$675		9147	Arctic white	\$0	
6830	Aqua green	\$0		9197	Obsidian black metallic	\$1,070	
7160	Stone grey	\$675		9775	Iridiumsilver	\$1,070	

Please see NetStar for latest paint availability information.

# **Upholstery**

#### Standard

VF7

Fabric

Maturin Black Upholstery



#### **Optional**

VF4

Fabric

Caluma Black Upholstery

Upcharge					
Cargo	\$	60			
Cab Chassis	\$	60			
Crew Van	\$	205			
Passenger Van	\$	430			



#### **Optional**

VF6

Leatherette

Black

Upcharge			
Cargo	\$	60	
Cab Chassis	\$	60	
Crew Van	\$	205	
Passenger Van	\$	430	



#### **Seat restrictions**

			Fabrics	
Code	Seat	VF7	VF4	VF6
	Standard Seats Front	S	0	0
	Standard Seats Rear	S	n/a	0
SF1/SF2	Power Seats	n/a	0	0
SB1/SB2	Comfort Seats Front	S	0	0
	Comfort Seats Rear	n/a	0	0

Front and rear fabric always have to match.





# **Suspension Matrix**

Cargo Van / Crew Van								
Standard	1500	2500	3500	3500XD	4500			
Standard	Base Sus	spension		CB8	CB8 + A50			
Options		Д	·50		-			
	CB1 (add to standard)		-					
	CB7 (moved to option)		-					
Options	CB8 (replacing	B8 (replacing standard)		S				
	-	CB4 (R	4 (Recommended for RV) - only 6cyl Diesel					
	CT1 -							
Specialized	CE8 (not with 4x4 models)							
Options	B01 (not with 3500/3500XD/4500 144"WB)							
Options		X2R (not wit	th 3500/3500	X2R (not with 3500/3500XD/4500 144"WB)				

Passenger			
	1500	2500	
Standard	144" WB	144" WB	170" WB
	Base Suspe	ension + CB1 + CT1	Base Suspension + CB1 + CT1 + A50

Cab Chassis						
Standard	3500XD	4500				
	CB8	CB8 + A50				
Options	CB4					
	A50	-				
	CE8 (not on :	144"WB models)				
Specialized Options	B01 (not with 3500XD/4500 144"WB)					
	X2R (not with 3500XD/4	500 144"WB)				

# **Suspension Details**

	Standard Suspensions and Options					
Code	Title	Details Details				
A50	Front axle reinforced		Includes an increased load capacity of the front axle, where heavier bodies and equipment can be fitted. The higher capacity front axle caters to heavier cabs and heavier special equipment (e.g. for fire-fighting vehicles and ambulances).			
		Description	Ride comfort due to reduced roll stabilization.			
No Factory Code	Base Standard Factory Suspension	Benefit	The Base Standard Factory suspension, has an adapted front suspension for a lower and more comfortable entry.  With the removal of the rear stabilization bar it allows for an overall comfortable ride with reduced roll.			
		Description	Roll Stabilization with height body damping			
СВ7	CB7 Stabilization Level I	Benefit	CB7 compensates for rolling behavior due to higher center of gravity of loads or bodies. Torsion bars with an increased diameter are added to the front and rear axels. Furthermore, shock absorbers with an adapted characteristic are installed.			
		Description	Enhanced roll stabilization with higher body damping compared to CB7			
CB8	Stabilization Level II	Benefit	Additional roll stabilization and body damping compared to CB7. Increases torsion bar diameters at the front and rear axles and provides an adapted shock absorber characteristic. Furthermore, rear axle springs with increased rigidity are installed.			
CD4	Stabilization Lavel III	Description	Designed for vans with a intense rolling behavior due to a much heavier load and higher center of gravity. (i.e. recreational vehicles)			
CB4	Stabilization Level III	Benefit	CB4 comes with larger diameter stabilizers, shock absorbers and with charateristics that are adapted for an increased rebound and compression curve. Furthermore, the leaf springs are increased in rigidity.			
CB1	Suspension for comfort and load protection	Enhanced com	ofort due to adapted damper characteristics and the use of progressive spring characteristics.			
CT1	Rear spring vibration absorbers	Includes vibration absorbers fitted on the left and right rear spring and lowers the resonant vibrations of the rear springs, thus hindering noise development.				

	Specialized Suspension Options					
Code	Title		Explanation			
CE8	Raised rear body mounts	Raised body o	Raised body on rear axle (35mm/1.4")			
		Description	Adjusted braking and handling characteristics for vehicles with increased center of gravity.			
B01	ESP for increased Center of Gravity	Benefit	With code B01, the ESP® is optimized to reduce the vehicles tilt tendency with a total center of gravity of <a href="mailto:more">more</a> than 1000 mm (39,4 inches). It is essential to ensure that the vehicle is equipped with the right suspension and tires. With B01 it is required to also add CB8 or CB4.			
X2R	X2R Conversion to RV requirement MBUX Timed Switch-off extended to 6 hours and B01 is automatically added to this code.					

# Rear view camera/head unit plausibility

CA/PV/CV					
	Standard	Option A	Option A + JB7	Option A + JB6	Option A + JB8
Radio/HU	E10	E3M/E4M	E3M/E4M	E3M/E4M	E3M/E4M
	FR3	FR8	integrated camera	integrated 360	integrated 360
Camera	FKS	FKO	integrated camera	degree camera	degree camera
Pre-wiring Camera	n/a	n/a	n/a	n/a	n/a
Camera Display	Interior rear view	7/10.25" Screen	7/10.25" Screen	7/10.25" Screen	7/10.25" Screen
	mirror	7/10.23 Screen	7/10.23 Screen	7/10.23 Screen	7/10.23 Screen

Options shown above lead to an upcharge.

CC			
	Standard	Option A	Option B
Radio/HU	E10	E10	E3M/E4M
After-Sales Camera	-	Any analog* Camera	Mercedes-Benz Camera** (digital)
Pre-wiring	-	FV1	FR7
Rear-View Display		Interior rear view	
	-	mirror	7/10.25" Screen

Options shown above lead to an upcharge.

# **Cargo Van Floor Variations**

Standard	V93	Without factory installed flooring
Ontions	V43	Wood floor with 6 D-rings
Options	VK8	Floor covering, plastic

Note: see restrictions in combination with metallic paint

#### Special Rule for cargo vans with metallic paint

Paint Code	5890/7755/7992/9197/9775		
	V43	Wood floor with 6 D-rings	
	VK8	Floor covering, plastic	
		No floor covering; requires customer	
Must have one of		floor installation	
	779	Package contains:	
		V93 - No factory installed flooring	
		VL4 - Metallic painted floor	

Note: Fleet only

#### Additional comments ZZ9 Package

While applying the required clear coat layer to the metallic painted cargo floor, imperfections could occur. Therefore, we strongly recommend to install flooring in the cargo area for vehicles with a metallic paint.

Please be aware that potential paint appearance, contamination or imperfections of the uncovered cargo floor are not considered a defect and are therefore not reimbursable for repairs.

<sup>\*</sup>only cameras with analog signal works

 $<sup>{</sup>m **}$  only the Mercedes-Benz rear view camera works (digital signal)

## **Tire & Wheel Overview**

		1500/2500 Models		
		Standard Tire	RH8	
		Standard Wheel	RS3	
		Optional Wheel	RL5	
		Brand Options		
_		RM0 All-season tires	RM1 M+S tires	
RD9	Tire brand, unspecified	S	0	
RF8	Michelin	0	n/a	
RF1	Continental	n/a	0	
RH0	Kumho	0	n/a	

To order any of the tire brands above code RM9 has to be added to order.

			3500/3500XD Mode	ls
		Standard: Du	al Rear Wheel	
		Standard Tire	RH7	Standa
		Standard Wheel	RS6	Standa
		Brand (	Options	
		RM0 All-season tires	RM1 M+S tires	RM0
RD9	Tire brand, unspecified	0	0	
RF8	Michelin	0	n/a	
RF1	Continental	0	0	,
RH0	Kumho	n/a	n/a	

S	5		
	Optional: Supe	er Single	
St	tandard Tire	R9A	
St	tandard Wheel	RS5	
Brand Options		ions	
R	MO All-season tires	RM1 M+S tires	
	S	n/a	
	n/a	n/a	
	0	n/a	
	n/a	n/a	

To order any of the tire brands above code RM9 has to be added to order.

Standard is DRW, Option is Super Single

		4500 Models		
		Standard Tire	RH7	
		Standard Wheel	RS6	
		Brand Options		
		RM0 All-season tires	RM1 M+S tires	
RD9	Tire brand, unspecified	S	0	
RF8	Michelin	0	n/a	
RF1	Continental	0	0	
RH0	Kumho	n/a	n/a	

To order any of the tire brands above code RM9 has to be added to order.

Dual Rear Wheel Steel

Single tire Steel Alloy

#### **Hermes Module for Government contracts**

Note: municipal and county business is still

Please note that all Sprinter vehicles with the code **JH3** (*communications module LTE – standard equipment for all Sprinter*) are no longer eligible for tenders, sales, and lease or rental contracts with U.S. federal institutions, such as U.S. governmental bodies, U.S. authorities, U.S. embassies and diplomatic missions as well as U.S. armed forces worldwide.

The background is a new U.S. provision that prohibits the U.S. federal government from entering into, extending, or renewing contracts with any entity that uses any equipment, system, or service that uses telecommunication equipment incorporating certain Chinese technology (Interim rule to Section 889(a)(1)(B) of the John S. McCain National Defense Authorization Act for Fiscal Year 2019, published in the U.S. Federal Register on July 14, 2020).

Since Mercedes-Benz Vans vehicles currently do incorporate such covered technology (code JH3), business with U.S. federal contractor is no longer possible. The new rule applies to contracts entered into after **August 13, 2020** or contracts entered into before **August 13, 2020** of which the supply of vehicles takes place after that date.

#### **Ordering**

If you are planning to supply a customer out of the above listed groups with Sprinter vans, please be aware that JH3 is standard for all Sprinter models. Therefore, a special ordering process is required. For details, please reach out to your responsible RSM.

#### Removal of JH3 from stock vehicles

The Hermes Module can be removed from vehicles. Please contact Service & Parts for details.

#### **1500 CARGO VAN - GAS** Standard Equipment

144" G
M1CA4G
907.643

Figure   F	
ED4 AGM battery 12V 92 AH 850 A  G43 Automatic transmission, 9G-tronic  M60 Alternator 14 V / 250 A  MH8 SULEV emisinder turbo gasoline engine  Equipment  AR3 Axle ratio 4.182  BR3 Active Brake Assist  BH1 Hold Function  G6L Multifunction steering wheel  C1.1 Adjustable steering wheel (angle)  S7 Hill Start Assist  S8 Hill Stard Assist  S9 Hill Stard Assist  S1 Sandard radio  S1 USB-C socket, 5 V  S2 Sarter battery disconnect  S2 Sarter battery disconnect  S3 Pre-installation for switch panel  S4 Trailler hitch prep. wiring  S5 Perinstallation PSM  S6 Perinstallation PSM  S7 EB5 Jurny start terminal  S8 Pre-installation for Mercedes me Remote Services  S8 Sery Emergency Call System  S9 Breakdown management  S9 Breakdown management  S9 Shelf above windshield  S9 Surder compector  S1 Remote key (315 mhz) w/central locking  S8 Surder compector  S9 Surder description of Services  S9 Services of Services  S9 Serv	
G43       Automatic transmission, 9G-tronic       S         M60       Alternator 14 V / 250 A       S         MH8       SULEV emissions       S         MM3       2.0L 4-cylinder turbo gasoline engine       S         Equipment       S         AR3       Axle ratio 4.182       S         BA3       Active Brake Assist       S         BH1       Hold Function       S         C6L       Multifunction steering wheel       S         C1.1       Adjustable steering wheel (angle)       S         D93       Omission bulkhead       S         E07       Hill Start Assist       S         E10       Standard radio       S         E10       USB-C socket, 5 V       S         E30       Starter battery disconnect       S         E31       Pre-installation for switch panel       S         E40       Trailer hitch prep. wiring       S         E40       Trailer hitch prep. wiring       S         E53       Pre-installation PSM       S         E54       Ultracapacitor discharge module       S         EK1       Body Builder Connector       S         E50       Jump start terminal       S </td <td></td>	
M60       Alternator 14 V / 250 A       S         MH8       SULEV emissions       S         MM3       2.0L 4-cylinder turbo gasoline engine       S         Equipment         AR3       Axle ratio 4.182       S         BA3       Active Brake Assist       S         BH1       Hold Function       S         C6L       Multifunction steering wheel       S         C11       Adjustable steering wheel (angle)       S         D93       Omission bulkhead       S         E07       Hill Start Assist       S         E10       Standard radio       S         E10       Standard radio       S         E10       Starter battery disconnect       S         E30       Starter battery disconnect       S         E31       Pre-installation for switch panel       S         E40       Trailer hitch prep. wiring       S         E83       Pre-installation PSM       S         EE5       Ultracapacitor discharge module       S         EK1       Body Builder Connector       S         E50       Jump start terminal       S         EW6       Pre-installation for Mercedes me Remote Services       S	
MH8       SULEV emissions       S         MM3       2.0L 4-cylinder turbo gasoline engine       S         Equipment         AR3       Axle ratio 4.182       S         BA3       Active Brake Assist       S         BH1       Hold Function       S         C6L       Multifunction steering wheel       S         C11       Adjustable steering wheel (angle)       S         D93       Omission bulkhead       S         E07       Hill Start Assist       S         E10       Standard radio       S         E10       USB-C socket, 5 V       S         E30       Starter battery disconnect       S         E31       Pre-installation for switch panel       S         E40       Trailer hitch prep. wiring       S         E40       Trailer hitch prep. wiring       S         E83       Pre-installation PSM       S         EE5       Ultracapacitor discharge module       S         EK1       Body Builder Connector       S         E50       Jump start terminal       S         EW6       Pre-installation for Mercedes me Remote Services       S         EY5       Emergency Call System       S	
MM3 2.0L 4-cylinder turbo gasoline engine       S         Equipment         AR3 Axle ratio 4.182       S         BA3 Active Brake Assist       S         BH1 Hold Function       S         C6L Multifunction steering wheel       S         C1.1 Adjustable steering wheel (angle)       S         D93 Omission bulkhead       S         E07 Hill Start Assist       S         E07 Hill Start Assist       S         E10 Standard radio       S         E10 USB-C socket, 5 V       S         30 Starter battery disconnect       S         E30 Starter battery disconnect       S         E31 Pre-installation for switch panel       S         E40 Trailer hitch prep. wiring       S         E52 Ultracapacitor discharge module       S         EK1 Body Builder Connector       S         ES0 Jump start terminal       S         EK1 Body Builder Connector       S         EV5 Emergency Call System       S         EY6 Breakdown management       S         F68 Heated & electrically adjustable exterior mirrors       S         FF5 Shelf above windshield       S         F68 Cupholder front       S         FR3 Rear view camera (rear-view mirror disp	
Equipment         AR3       Axle ratio 4.182       S         BA3       Active Brake Assist       S         BH1       Hold Function       S         C6L       Multifunction steering wheel (angle)       S         CL1       Adjustable steering wheel (angle)       S         D93       Omission bulkhead       S         E07       Hill Start Assist       S         E10       Standard radio       S         E11       USB-C socket, 5 V       S         E30       Starter battery disconnect       S         E31       Pre-installation for switch panel       S         E40       Trailer hitch prep. wiring       S         E53       Preinstallation PSM       S         E54       Ultracapacitor discharge module       S         EK1       Body Builder Connector       S         E50       Jump start terminal       S         EK4       Body Builder Connector       S         E50       Jump start terminal       S         EW6       Pre-installation for Mercedes me Remote Services       S         EY5       Emergency Call System       S         EY6       Breakdown management       S	
AR3 Axle ratio 4.182 S BA3 Active Brake Assist S BH1 Hold Function S C6L Multifunction steering wheel S CL1 Adjustable steering wheel (angle) S D93 Omission bulkhead S E07 Hill Start Assist S E10 Standard radio S E1U USB-C socket, 5 V S E30 Starter battery disconnect S E31 Pre-installation for switch panel S E40 Trailer hitch prep. wiring S EB8 Preinstallation PSM S EE5 Ultracapacitor discharge module S EK1 Body Builder Connector S ES0 Jump start terminal S EW6 Pre-installation for Mercedes me Remote Services S EY5 Emergency Call System S EY6 Breakdown management S EF68 Leetrically adjustable exterior mirrors S EFF5 Shelf above windshield S EFF3 Rear view camera (rear-view mirror display) S EFF3 Headunit S EH64 Air Condition, Front S EH75 Speedometer, miles and km/h S EV9 Service Interval 1 year S EV9 Service Interval 1 year S EV9 Service Interval 1 year S	
BA3 Active Brake Assist  BH1 Hold Function  C6L Multifunction steering wheel  CL1 Adjustable steering wheel (angle)  D93 Omission bulkhead  S6O7 Hill Start Assist  E1O Standard radio  S1U USB-C socket, 5 V  S2O Starter battery disconnect  S2I Pre-installation for switch panel  S2HO Trailer hitch prep. wiring  S2HO Trailer hitch prep. wiring  S2HO Trailer hitch prep. wiring  S6ES Ultracapacitor discharge module  S7EKT Body Builder Connector  S8O Jump start terminal  S8O Pre-installation for Mercedes me Remote Services  S8O Fre-installation for Mercedes me Remote Services  S8O Service All System  S8O Fre-installation for Mercedes me Remote Services  S8O Fre-installation for Mercedes me Rem	
BH1       Hold Function       \$         C6L       Multifunction steering wheel       \$         C1.1       Adjustable steering wheel (angle)       \$         D93       Omission bulkhead       \$         E07       Hill Start Assist       \$         E10       Standard radio       \$         E10       USB-C socket, 5 V       \$         E30       Starter battery disconnect       \$         E31       Pre-installation for switch panel       \$         E40       Trailer hitch prep. wiring       \$         EB8       Preinstallation PSM       \$         EE5       Ultracapacitor discharge module       \$         EK1       Body Builder Connector       \$         ES0       Jump start terminal       \$         EW6       Pre-installation for Mercedes me Remote Services       \$         EY5       Emergency Call System       \$         EY6       Breakdown management       \$         F68       Heated & electrically adjustable exterior mirrors       \$         FF5       Shelf above windshield       \$         F68       Cupholder front       \$         F71       Remote key (315 mhz) w/central locking       \$	
C6L       Multifunction steering wheel       S         CL1       Adjustable steering wheel (angle)       S         D93       Omission bulkhead       S         E07       Hill Start Assist       S         E10       Standard radio       S         E10       USB-C socket, 5 V       S         E30       Starter battery disconnect       S         E31       Pre-installation for switch panel       S         E40       Trailer hitch prep. wiring       S         ED8       Preinstallation PSM       S         EE5       Ultracapacitor discharge module       S         EK1       Body Builder Connector       S         ES0       Jump start terminal       S         EW6       Pre-installation for Mercedes me Remote Services       S         EY5       Emergency Call System       S         EY6       Breakdown management       S         F68       Heated & electrically adjustable exterior mirrors       S         FF5       Shelf above windshield       S         F68       Cupholder front       S         F11       Remote key (315 mhz) w/central locking       S         F74       Storage compartment underneath cockpit       S	
CL1 Adjustable steering wheel (angle)  D93 Omission bulkhead  E07 Hill Start Assist  E10 Standard radio  E110 USB-C socket, 5 V  E30 Starter battery disconnect  E31 Pre-installation for switch panel  E40 Trailer hitch prep. wiring  E540 Preinstallation PSM  E55 Ultracapacitor discharge module  EK1 Body Builder Connector  S0 Jump start terminal  EW6 Pre-installation for Mercedes me Remote Services  E75 Emergency Call System  S18 Feakdown management  E76 Breakdown management  S2 Shelf above windshield  S3 Ferson Shelf above windshield  S4 Storage compartment underneath cockpit  S5 Storage compartment underneath cockpit  S6 Rear view camera (rear-view mirror display)  S6 Heater, auxiliary electric hot air  S8 Headomit  S9 Shelf Air Condition, Front  S1 Speedometer, miles and km/h  S1 Speedometer, miles and km/h  S6 Service Interval 1 year	
D93 Omission bulkhead S E07 Hill Start Assist S E10 Standard radio S E110 USB-C socket, 5 V S E30 Starter battery disconnect S E3J Pre-installation for switch panel S E40 Trailer hitch prep. wiring S ED8 Preinstallation PSM S EE5 Ultracapacitor discharge module S EK1 Body Builder Connector S ES0 Jump start terminal S EW6 Pre-installation for Mercedes me Remote Services S EY5 Emergency Call System S EY6 Breakdown management S EY6 Breakdown management S EY6 Heated & electrically adjustable exterior mirrors S EF5 Shelf above windshield S EG8 Cupholder front S EF6 Storage compartment underneath cockpit S EF7 Remote key (315 mhz) w/central locking S EF7 Shelf above windshield S EF7 Storage compartment underneath cockpit S EF7 SHelf above windshield S EF7 Storage compartment underneath cockpit S EF7 SHelf above windshield S EF7 Storage compartment underneath cockpit S EF7 SHelf above windshield S EF7 Storage compartment underneath cockpit S EF7 SHelf above windshield S EF7 Storage compartment underneath cockpit S EF8 Rear view camera (rear-view mirror display) S EF8 Rear view camera (rear-view mirror display) S EF8 Rear view camera (rear-view mirror display) S EF8 Heater, auxiliary electric hot air S EF7 Headunit S EF7 Speedometer, miles and km/h S EF7 Service Interval 1 year S	
E07 Hill Start Assist  E10 Standard radio  E10 USB-C socket, 5 V  E30 Starter battery disconnect  E31 Pre-installation for switch panel  E40 Trailer hitch prep. wiring  ED8 Preinstallation PSM  E55 Ultracapacitor discharge module  EK1 Body Builder Connector  ES0 Jump start terminal  Sew Pre-installation for Mercedes me Remote Services  EY5 Emergency Call System  EY6 Breakdown management  Sew Breakdown management  Sew Breakdown management  F68 Heated & electrically adjustable exterior mirrors  F75 Shelf above windshield  Sew Cupholder front  F11 Remote key (315 mhz) w/central locking  F14 Storage compartment underneath cockpit  Sew Rear view camera (rear-view mirror display)  Sew Heater, auxiliary electric hot air  HH2 Heater, auxiliary electric hot air  HH9 Air Condition, Front  Seworce Interval 1 year  Sevice Interval 1 year	
E10 Standard radio S E1U USB-C socket, 5 V S E30 Starter battery disconnect S E3J Pre-installation for switch panel S E40 Trailer hitch prep. wiring S EB8 Preinstallation PSM S EE5 Ultracapacitor discharge module S EK1 Body Builder Connector S ES0 Jump start terminal S EW6 Pre-installation for Mercedes me Remote Services S EY5 Emergency Call System S EY6 Breakdown management S EY6 Breakdown management S EW6 Reated & electrically adjustable exterior mirrors S EF5 Shelf above windshield S EF68 Cupholder front S EF11 Remote key (315 mhz) w/central locking S EF14 Storage compartment underneath cockpit S EF83 Rear view camera (rear-view mirror display) S EF83 Rear view camera (rear-view mirror display) S EF84 Heater, auxiliary electric hot air S EF95 Headounit S EF96 Seedometer, miles and km/h S EF97 Speedometer, miles and km/h	
E1U USB-C socket, 5 V E30 Starter battery disconnect S31 Pre-installation for switch panel E40 Trailer hitch prep. wiring S40 E58 Preinstallation PSM S5 E59 Ultracapacitor discharge module S60 Ultracapacitor discharge module S70 Jump start terminal S80 Pre-installation for Mercedes me Remote Services S81 E75 Emergency Call System S81 Breakdown management S81 Breakdown management S82 F76 Breakdown management S83 F768 Heated & electrically adjustable exterior mirrors S94 F75 Shelf above windshield S95 F75 Shelf above windshield S96 Cupholder front S97 Storage compartment underneath cockpit S97 Storage compartment underneath cockpit S97 Rear view camera (rear-view mirror display) S97 Shelf above windshield S98 Rear view camera (rear-view mirror display) S99 Shelf Pidanti S99 S99 S99 S99 S99 S99 S99 S99 S99 S9	
E30 Starter battery disconnect S E3J Pre-installation for switch panel S E40 Trailer hitch prep. wiring S ED8 Preinstallation PSM S EE5 Ultracapacitor discharge module S EK1 Body Builder Connector S ES0 Jump start terminal S EW6 Pre-installation for Mercedes me Remote Services S EY5 Emergency Call System S EY6 Breakdown management S EW6 Heated & electrically adjustable exterior mirrors S EF5 Shelf above windshield S EF68 Cupholder front S EF11 Remote key (315 mhz) w/central locking S EF3 Rear view camera (rear-view mirror display) S EF3 Rear view camera (rear-view mirror display) S EF1 Windshield with filter band S EF1 Headunit S EF1 Speedometer, miles and km/h S EF1 Speedometer	
E30 Starter battery disconnect S E3J Pre-installation for switch panel S E40 Trailer hitch prep. wiring S ED8 Preinstallation PSM S EE5 Ultracapacitor discharge module S EK1 Body Builder Connector S ES0 Jump start terminal S EW6 Pre-installation for Mercedes me Remote Services S EY5 Emergency Call System S EY6 Breakdown management S EW6 Heated & electrically adjustable exterior mirrors S EF5 Shelf above windshield S EF68 Cupholder front S EF11 Remote key (315 mhz) w/central locking S EF3 Rear view camera (rear-view mirror display) S EF3 Rear view camera (rear-view mirror display) S EF1 Windshield with filter band S EF1 Headunit S EF1 Speedometer, miles and km/h S EF1 Speedometer	
E3J Pre-installation for switch panel E40 Trailer hitch prep. wiring ED8 Preinstallation PSM EE5 Ultracapacitor discharge module EK1 Body Builder Connector ES0 Jump start terminal SEW6 Pre-installation for Mercedes me Remote Services EY5 Emergency Call System SEY6 Breakdown management SEY6 Breakdown management SEY6 Breakdown windshield SEW6 Cupholder front SEW6 Cu	
E40 Trailer hitch prep. wiring ED8 Preinstallation PSM EE5 Ultracapacitor discharge module EK1 Body Builder Connector ES0 Jump start terminal EW6 Pre-installation for Mercedes me Remote Services EY5 Emergency Call System EY6 Breakdown management Services EY7 Shelf above windshield Services EF7 Shelf above windshield Services EF8 Cupholder front EF8 Cupholder front EF9 Storage compartment underneath cockpit EF9 Storage compartment underneath cockpit EF9 Rear view camera (rear-view mirror display) EF9 Shelf above windshield EF9 Storage compartment underneath Cockpit EF9 Storage Cockpit Coc	
ED8 Preinstallation PSM S EE5 Ultracapacitor discharge module S EK1 Body Builder Connector S ES0 Jump start terminal S EW6 Pre-installation for Mercedes me Remote Services S EY5 Emergency Call System S EY6 Breakdown management S EY6 Breakdown management S EY6 Breakdown management S EY7 Shelf above windshield S EY8 Cupholder front S EY9 Shelf above windshield S EY9 Shelf above S EY9 S EY9 Shelf above S EY9 Shelf above S EY9 Shelf above S EY9 S EY9 Shelf above	
EE5 Ultracapacitor discharge module  EK1 Body Builder Connector  S  ES0 Jump start terminal  S  EW6 Pre-installation for Mercedes me Remote Services  EY5 Emergency Call System  S  EY6 Breakdown management  S  F68 Heated & electrically adjustable exterior mirrors  S  FF5 Shelf above windshield  S  FG8 Cupholder front  FI1 Remote key (315 mhz) w/central locking  FJ4 Storage compartment underneath cockpit  S  FR3 Rear view camera (rear-view mirror display)  S  H21 Windshield with filter band  S  HH2 Heater, auxiliary electric hot air  S  HH9 Air Condition, Front  S  J11 Speedometer, miles and km/h  S  S  S  S  S  S  S  S  S  S  S  S  S	
EK1 Body Builder Connector  ES0 Jump start terminal  EW6 Pre-installation for Mercedes me Remote Services  EY5 Emergency Call System  EY6 Breakdown management  S F68 Heated & electrically adjustable exterior mirrors  FF5 Shelf above windshield  S FG8 Cupholder front  S Remote key (315 mhz) w/central locking  FJ4 Storage compartment underneath cockpit  S FR3 Rear view camera (rear-view mirror display)  S H21 Windshield with filter band  HH2 Heater, auxiliary electric hot air  S HH9 Air Condition, Front  S H11 Speedometer, miles and km/h  S SPI1 Service Interval 1 year  S SPI1 Service Interval 1 year	
ESO Jump start terminal S EW6 Pre-installation for Mercedes me Remote Services S EY5 Emergency Call System S EY6 Breakdown management S F68 Heated & electrically adjustable exterior mirrors S FF5 Shelf above windshield S FG8 Cupholder front S FI1 Remote key (315 mhz) w/central locking S FJ4 Storage compartment underneath cockpit S FR3 Rear view camera (rear-view mirror display) S H21 Windshield with filter band S HH2 Heater, auxiliary electric hot air S HH9 Air Condition, Front S IH7 Headunit S J11 Speedometer, miles and km/h S J1W Service Interval 1 year S	
EW6 Pre-installation for Mercedes me Remote Services  EY5 Emergency Call System  S EY6 Breakdown management  S Heated & electrically adjustable exterior mirrors  FS Shelf above windshield  S GEY6 Cupholder front  S GEY6 Cu	
EY5 Emergency Call System S EY6 Breakdown management S F68 Heated & electrically adjustable exterior mirrors S FF5 Shelf above windshield S FG8 Cupholder front S FI1 Remote key (315 mhz) w/central locking S FJ4 Storage compartment underneath cockpit S FR3 Rear view camera (rear-view mirror display) S H21 Windshield with filter band S HH2 Heater, auxiliary electric hot air S HH9 Air Condition, Front S H7 Headunit S J11 Speedometer, miles and km/h S J1W Service Interval 1 year S	
EY6 Breakdown management S F68 Heated & electrically adjustable exterior mirrors S FF5 Shelf above windshield S FG8 Cupholder front S FI1 Remote key (315 mhz) w/central locking S FJ4 Storage compartment underneath cockpit S FR3 Rear view camera (rear-view mirror display) S H21 Windshield with filter band S HH2 Heater, auxiliary electric hot air S HH9 Air Condition, Front S H7 Headunit S J11 Speedometer, miles and km/h S J1W Service Interval 1 year S	
F68 Heated & electrically adjustable exterior mirrors  FF5 Shelf above windshield  FG8 Cupholder front  FI1 Remote key (315 mhz) w/central locking  FJ4 Storage compartment underneath cockpit  FR3 Rear view camera (rear-view mirror display)  FJ1 Windshield with filter band  SHH2 Heater, auxiliary electric hot air  SHH9 Air Condition, Front  SH7 Headunit  Speedometer, miles and km/h  Service Interval 1 year  S	
FF5 Shelf above windshield S FG8 Cupholder front S FI1 Remote key (315 mhz) w/central locking S FJ4 Storage compartment underneath cockpit S FR3 Rear view camera (rear-view mirror display) S H21 Windshield with filter band S HH2 Heater, auxiliary electric hot air S HH9 Air Condition, Front S H7 Headunit S J11 Speedometer, miles and km/h S J1W Service Interval 1 year S	
FG8 Cupholder front S FI1 Remote key (315 mhz) w/central locking S FJ4 Storage compartment underneath cockpit S FR3 Rear view camera (rear-view mirror display) S H21 Windshield with filter band S HH2 Heater, auxiliary electric hot air S HH9 Air Condition, Front S IH7 Headunit S J11 Speedometer, miles and km/h S J1W Service Interval 1 year S	
FI1 Remote key (315 mhz) w/central locking  FJ4 Storage compartment underneath cockpit  FR3 Rear view camera (rear-view mirror display)  KH21 Windshield with filter band  KH22 Heater, auxiliary electric hot air  KH49 Air Condition, Front  KH7 Headunit  S S S S S S S S S S S S S S S S S S S	
FJ4 Storage compartment underneath cockpit  FR3 Rear view camera (rear-view mirror display)  H21 Windshield with filter band  S HH2 Heater, auxiliary electric hot air  S HH9 Air Condition, Front  S IH7 Headunit  S Speedometer, miles and km/h  S Service Interval 1 year	
FR3 Rear view camera (rear-view mirror display)  H21 Windshield with filter band  S HH2 Heater, auxiliary electric hot air  S HH9 Air Condition, Front  S H7 Headunit  S J11 Speedometer, miles and km/h  S Service Interval 1 year	
H21 Windshield with filter band S HH2 Heater, auxiliary electric hot air S HH9 Air Condition, Front S HH7 Headunit S J11 Speedometer, miles and km/h S J1W Service Interval 1 year S	
HH2 Heater, auxiliary electric hot air  S HH9 Air Condition, Front S IH7 Headunit Speedometer, miles and km/h Service Interval 1 year S S	
HH9 Air Condition, Front  S  IH7 Headunit  S  J11 Speedometer, miles and km/h  S  Service Interval 1 year  S	
IH7 Headunit S J11 Speedometer, miles and km/h S J1W Service Interval 1 year S	
J11Speedometer, miles and km/hSJ1WService Interval 1 yearS	
J1W Service Interval 1 year S	
J58 Seat belt reminder driver S	
J65 Outside temperature gauge S	
JA8 Crosswind Assist S	
JH3 Communication module (LTE) for dig. services	
JI8 Service interval 15.000 miles S	
K14 22 gallon fuel tank S	
K60 Exhaust straight to rear S	
L65 Interior lights, cargo compartment S	
L94 Parking lights deletion S	
LA2 Headlight assistant S	
LB5 3rd brake light S	

Standard Equipment

		144" G
		M1CA4G
		907.643
MS1	Cruise control	S
P47	Front mudflaps	S
P48	Rear mudflaps	S
Q11	Longitudinal member reinforcement	S
R65	Spare tire bracket below frame	S
R87	Spare tire	S
RD9	Unspecified tire brand	S
RH8	Tires LT 245/75 R16	S
RM0	All-season tires	S
RS3	6.5 J x 16 steel wheels	S
RY2	Tire pressure monitoring sensors	S
S02	Standard driver seat	S
S04	Standard front passenger seat	S
S22	Armrest for driver's seat	S
S25	Armrest for front passenger seat	S
SA5	Front airbag, driver	S
SA6	Front airbag, passenger	S
SH1	Thorax-pelvis sidebag, driver	S
SH2	Thorax-pelvis sidebag, co-driver	S
SH9	Airbag, driver/passenger window	S
SK2	Seat occupancy sensor, driver's seat	S
T16	Sliding door, passenger side	S
V93	Without factory installed flooring	S
V94	Cable duct - side wall	S
V95	Cable duct - rear portal	S
XL8	GVWR 8,550 lbs. / 3,880 Kg	S
Y43	Jack, hydraulic	S

		144" G
		M1CA4G
		907.643
A50	Front axle reinforced	\$346
AP2	Addtl. bar for driveshaft & exhaust extension	\$69
B01	ESP for increased Center of Gravity above 39.4"	\$0
	must have CB4/CB8/X30; not with RH0/CB7	•
B25	Electric parking brake	\$279
	not with BE2; X69 choose B25/BE2	•
BE2	Handbrake lever, folding	\$55
	not with B25; X69 choose B25/BE2	•
C72	Bumpers front/rear primed	\$268
	must have CN2 (part of X67), not with CM0	·
CB1	Suspension for comfort and load protection	\$241
CB7	Stabilization Level I	\$307
	not with CB4/CB8/X30	700
CB8	Stabilization Level II	\$723
	not with CB1/CB4/CB7/X30	Ų, <u>2</u> 3
CE8	Raised rear body mounts	\$252
CL3	Leather steering wheel	\$187
020	must have (C02/E3M)/C03 + (ET4/MS1)	Ş107
CM0	Painted metallic front & rear bumper	\$587
OIVIO	must have (CN2/X67) + (JA7/C01) + (JB6/JB7) + (7755/9197/9775)	Ş387
CM9	Primed side moldings	\$364
CT1	-	
	Rear spring vibration absorbers	\$138
D03	High roof	\$2,900
D13	Mounting rails for roof rack	\$300
DZZ	Fixed sunroof (rear roof section)	\$336
D.C.O.	not with H08/HK4/H72/V36/ZK4	¢200
D50	Cargo partition	\$288
D.E.4	not with D51/D93/H08/HK4/T74/V36; must have one of T93/T77	4000
D51	Cargo partition with 1 window	\$335
	not with D50/D93/H08/HK4/T74/V37/D17; must have one of T93/T77	4
E1B	Tray for smartphones incl. wireless charging	\$156
	must have CO2/E3M + H1I	
E1E	Navigation	\$728
	must have CO2/E3M, not with CO3	
E1S	Sirius XM, satellite radio	\$255
	must have CO2/E3M/CO3	
E1R	Additional Fuses (40/80/150/100 Ampere)	\$50
	SoP and Plausibility TBD	
E1Y	Additional Fuses (40/80/80/100 Ampere)	\$50
	SoP and Plausibility TBD	
E2A	Access point for BB special signals in cockpit	\$29
E2I	Additional battery, co-driver seat base	\$248
	must have E36/C06; not with E2M/F09; CHS production only	
E2M	Additional battery, engine compartment	\$248
	must have X01+ (E36/C06); not with E2I/X69/F09	
ЕЗМ	MBUX Multimedia System with 7" touchscreen	\$474
	not with CO2/CO3; must have JK5+(JB7/JB6/JB8/FR8)	
E36	Cutoff relay for additional battery	\$110
E46	12 V power outlet, driver seat base	\$92
E5M	Extension of PSM standard contact	\$58

		144" G	
		M1CA4G	
		907.643	
ED5	Parametric special module (PSM)	\$317	
	not with ED8		
EE3	115 V socket	\$125	
EP7	Basic electric fitting for rear loudspeakers	\$68	
ES2	12 V power outlet, rear compartment	\$92	
ES5	Charging package, dashboard	\$82	
ET4	Active Distance Assist DISTRONIC	\$263	
	must have CO2/CO3/E3M; not with ZH4		
F1K	Coat hooks in driver cabin	\$14	
	must have D50/D51		
F49	Electrically heated windshield	\$218	
	no restriction		
F61	Interior rear view mirror	\$36	
	not with D50; must have C02/E3M/C03	_	
F64	Electrically folding exterior mirrors	\$49	
FE9	Additional DIN-slot	\$81	
FF8	Overhead storage slot, front center	\$105	
FJ1	Hinged lid for storage compartment	\$93	
FR8	Rear view camera (head unit display)	\$336	
	must have CO2/E3M; not with FR3/JB7/JB6/JB8		
FY1	Security alarm w. interior motion sensor	\$584	
	must have LC4/C00	_	
FY7	Optional 3-button keys	\$36	
FZ9	Keys, two additional masters	\$121	
H00	Warm/cool air duct to rear compartment	\$59	
	not with D50/D51/Y2A		
H01	Heat insulation, rear compartment	\$156	
	must have V21/V25/VA3/VA1/C07/X66	_	
H04	Heat insulation, front compartment	\$187	
	if + D50/D51 must have V07	_	
H08	Air conditioning rear, roof-mounted	\$2,872	
	must have D93 +V36; not with HK4/C06/X66/C07	_	
H13	Rear cabin heater and vents	\$786	
	must have H12/HZ9		
H15	Heated front passenger seat	\$284	
	must have H16; not with X68		
H16	Heated driver's seat	\$284	
	must have H15; not with X68		
H22	Rear window defroster	\$253	
	must have W61/W78; standard for W61+W70		
H72	Roof fan, electric	\$400	
1100	not with D22/V36		
H88	Rear heater prep	\$405	
1141	must have H12/HZ9; not with H13/T19	40	
H1I	Front-to-rear outlet in instrument panel	\$0	
11114	must have FJ1/C01	4227	
HH4	Thermotronic automatic climate control	\$337	
1 4 7	must have JF1; if +H13 must have H08/HK4	4.55	
JA7	Blind Spot Assist	\$450	
ID 4	must have F64; not with C01	4225	
JB4	Active Lane Keeping Assist	\$288	
ID /	standard with CO2/CA2	6775	
JB6	Parking Package with 360 degree camera	\$775	
	must have CO2/CO3/E3M; not with W75/W76/JB7		

	Options	
		144" G
		M1CA4G
		907.643
JB7	Parking Package	\$615
,0,	must have CO2/CO3/E3M; not with W75/W76/JB6	<b>7013</b>
JB8	360 Degree Camera	\$685
,,,,,	SoP and Plausibility TBD	<b>\$003</b>
JF1	Rain sensor	\$106
JK5	Instrument cluster with color display	\$144
-	standard with CO2/CA2	7-11
JW0	Backup alarm	\$99
JW2	Deactivation lamp monitoring failure	\$27
JW8	Attention Assist	\$49
L13	Fog lamp with cornering light function	\$199
L71	Light/motion sensor in rear compartment	\$54
	not with V36	
LB9	Illuminated front exits	\$151
LC2	LED light strip in load compartment	\$263
	not with H08/HK4/V36/C06	
LC4	Comfort overhead control panel	\$93
M20	Speed limitation 65 mph	\$60
	not with MD3	700
MD3	Top speed limitation 75 mph	\$60
	not with M20	700
P93	Omission of D-rings	-\$15
	not with D93/V43/VK8	
Q24	Trailer hitch, 5,000 lbs	\$147
	not with W73/W75/W76	
QA9	Half-sided step rear (for trailer hitch)	\$101
	must have Q24/QA2; not with W73/W75/W76	· · · · · ·
R91	Spare tire deletion	-\$110
	must have R92; not with R87	
R92	Spare tire carrier deletion	\$0
	must have R91; not with R65	
R98	Rims painted jet black	\$81
	not with RL5/RM2	
RF1	Tire brand Continental	\$0
	must have RM1 + RM9	
RF8	Tire brand Michelin	\$0
	must have RM9; not with RM1	
RH0	Tire brand Kumho	\$0
	must have RM9; not with RM1	
RL5	Light-alloy wheels 6.5 J x 16	\$906
	not with RS3/RM2/R98	
RM1	M+S winter tires	\$169
	must have RF1/RD9; not with RF8/RH0/X31	
RM2	Rims painted arctic white	\$81
	not with R98/RL5	
S23	Twin front passenger seat	\$400
	not with C00/X68/X01	
RM9	Specially requested tires	\$101
	must have RF1/RF8/RH0; not with RD9	
S28	Armrest, driver and passenger door	\$51
S62	Seat belts orange, driver and front passenger	\$32
	not with S23	
SB9	Driver's seat plus	\$238
	must have VF7; not with C00/X68/X69	

		144" G
		M1CA4G
		907.643
SZ7	Storage net, driver's seat backrest	\$64
SZ8	Storage net, passenger seat backrest	\$64
T12	Sliding door two stage opening	\$82
	not with T55	
T19	Sliding door, driver's side	\$935
	not with H13/H88/VC5/ZE6/F43/W16/F02; if +V36 must have D03	
T50	Electric closing assist right sliding door	\$335
	must have D03; not with T55/T93	
T51	Electric closing assist left sliding door	\$335
	must have T19 + D03	
T55	Electric sliding door right	\$831
	must have D03 + (FY7+T16); not with T12/T50	•
T57	Electric sliding step	\$1,071
	must have ED5; not with T93	. ,
T60	Opening limiter electrically operated sliding door	\$120
	must have T55	,
T74	Assist handle, B-pillar	\$32
	must have D93; not with T77	, -
T75	Door-mounted assist handles, driver & passenger	\$59
T77	Assist handle w/ partition	\$32
	must have D50/D51/D64	Ψ0=
T85	Assist handle, left rear door	\$32
T86	Assist handles, right rear door	\$32
T93	Sliding door right side deletion	\$0
	not with T16/T50/T57/VK8/VC5	ΨO
V07	Cab rear wall liner	\$360
,	must have (D50/D51)+F1K; standard with H04	Ψ300
V21	Luxury interior Trim	\$661
12.	must have VA5/VA7; not with V52/VA1/VA3	7001
V24	Pallet support in sliding door step	\$96
	must have (V43/X66)+(D50/D51); not with VK8/V93/C07	ψ30
V25	Half height load compartment trim	\$201
	not with VA1/VA3/VA5/V52/X66	Ψ201
V31	Window pillar trim	\$513
<b>V</b> O 1	must have V36 + (V21/VA1) + (F02/F03/F07); not with V42	7313
V35	Wheel house covering	\$105
<b>V</b> 00	if +V43 must have V25/VA1/VA3; not with V52	7103
V36	Roof trim	\$876
V 3 0	must have D93; not with D17/D22/H72/L65/L71/LC2/VA3/V42/ZE6/(T93+-D03)/X66/C06/C07	
V42		\$277
V + Z	Lashing rails, waist level not with V36/ZE6	<b>3411</b>
1//2		¢422
V43	Wood floor with 6 D-rings	\$422
\/4^	not with P93/V93/VL4/VK8/C07; standard with D93/H13/V24/V52/VC5/VV2	
V4A	Full paneling, right sliding door	\$109
\//0	must have D03+T16+V21+VA5+W17; not with T19	\$27
V48	Floor cover behind seat box	<b>\$</b> 21
V85	must have D93; not with D50/D51/D56/D62/D64/V43/VK5	¢20
	Cigarette lighter & ash cup, front	\$39
VA1	Side wall paneling waist height PVC	\$319
\/^2	must have VA5/VA7; not with V52	6446
VA3	Side wall paneling full hardboard	\$444
VA5	Full paneling, hinged rear doors	\$38
\/^7	must have D03+VA7+(W61/W78); not with V25	6427
VA7	Storage compart. w/ net in rear doors	\$127
	must have W61/W78; not with V52	

# **1500 CARGO VAN - GAS**Options

		144" G
		M1CA4G
		907.643
VC4	Cargo lashing rails, head height	\$415
	must have V42/C07/X66; not with ZE6	, -
VC5	Door sill - protective edge	\$71
	must have V43/X66; not with T19/T93/VK8/VV2/V93/C07	Ψ.=
VK8	Floor covering, plastic	\$370
	not with V43/P93/T19/T93/V52/VC5/X66	ψ373
VV2	Lashing rails, floor level (plus 4 anchors)	\$270
	must have V43; not with V93/VC5/ZE6	Ψ2.0
W16	2nd row, fixed window, driver side	\$145
W 10	if D93 must have F43+W70; if D93 & standard roof CHS production required	
W17	2nd row, fixed window, passenger side	\$145
VV 17	if D93 must have F43+W70; if D93 & standard roof CHS production required	·
W33		
WSS	FMVSS 217 emergency exit  must have V31; not with D50/T19/W16	\$379
VALE 4		¢260
W54	Rear doors, opening to side wall	\$360
W5F	90 Degree fixation point- Rear Doors	\$80
14/64	SoP and Plausibility TBD	400
W61	Windows in rear doors	\$93
14/70	must have VA7/ if D51 must have F61; not with W78/(W70+-(H22/F02))	4
W70	Black tinting (90%) for rear windows	\$138
	not with W94; must have W16/W17/F02/((W61/W78)+H22); standard with	F/13/W/33/F07
W73	Bumper step, rear, grey	\$187
***	not with Q24/W75/W76	7107
W75	Step, wide, at rear end	\$308
***	not with JB6/JB7/Q24/QA9; must have R91+R92	\$500
W76	Bumper step, rear, spring-loaded	\$601
VV / O		\$601
\4/70	must have R91+R92; not with JB6/JB7/X30/Q24	ćaar
W78	Heated rear window(s) w/ washers/wipers	\$335
V00	Must have H22+VA7 / if D51 must have F61; not with W61	40
X90	Deletion of Sprinter badge, left rear door	\$0
X93	Deletion of model badge, right rear door	\$0
XM4	Acoustic package	\$87
\(\(\frac{1}{2}\)	standard with C02/C03	4
Y10	First-aid kit	\$27
Y26	Wheel chocks	\$38
Y45	Emergency flashlight	\$27
Y68	Paint preservative	\$187
11// (		
Y69	Surface protection for stock vehicles	\$315
YK3	Cargo straps, D-rings	\$81
	Cargo straps, D-rings Cargo straps, lashing rails	
YK3 YK4	Cargo straps, D-rings	\$81 \$104
YK3	Cargo straps, D-rings Cargo straps, lashing rails	\$81

1500 CARGO VAN - GAS Packages

144" G
M1CA4G
907.643

C00	Comfort Package	\$300
LC4	Comfort overhead control panel	Х
SE4	Lumbar support, co-driver's seat	X
SE5	Lumbar support, driver's seat	Х
SK0	Comfort head restraint, driver	Х
SK1	Comfort head restraint, co-driver	X
S28	Armrest, driver and passenger door	Х
must have COS OR X68; CA/CC only: not with S23		

COS	Comfort Package (Seat addition)	\$381
SB1	Comfort driver's seat	X
SB2	Comfort passenger seat	Х
must have COO		

X68	Comfort Plus Package	\$1,923
H15	Heated front passenger seat	Χ
H16	Heated driver's seat	Х
SF1	Driver's seat electrically adjustable	X
SF2	Co-driver's seat electrically adjustable	Х
must have COO and VF4 OR VF6, CA/CC only: not with S23		

C01	Driver Convenience Package	\$760
E46	12 V power outlet, driver seat base	X
F64	Electrically folding exterior mirrors	X
FJ1	Hinged lid for storage compartment	X
FJ5	Hinged Lid for Storage Compartments left and right	X
FZ9	Keys, two additional masters	X
JA7	Blind Spot Assist	X
JW8	Attention Assist	X

Premium Package	\$983
Leather steering wheel	Х
MBUX Multimedia System with 7" touchscreen	Х
Wet Wiper System	Х
Active Lane Keeping Assist	Х
Instrument cluster with color display	Х
	Leather steering wheel  MBUX Multimedia System with 7" touchscreen  Wet Wiper System  Active Lane Keeping Assist

Ordering availability restricted, see NetStar for availability and restrictions|must have JF1 + XM4; must choose FR8/JB7/JB6

CA2	C02 in combination with C03	\$604
CL3	Leather steering wheel	X
FM3	Wet Wiper System	X
JB4	Active Lane Keeping Assist	Х
JK5	Instrument cluster with color display	Х

Ordering availability restricted, see NetStar for availability and restrctions|must have CO3 + JF1

Packages

144" G
M1CA4G
907.643

C03	Premium Plus Package	\$1,793	
E1B	Tray for smartphones incl. wireless charging	X	
	Navigation	Χ	
EY2	Intelligent navigation	X	
E4M	MBUX Multimedia System with 10.25" touchscreen	Χ	
EX9	Free map data updates for 3 years	Х	
H1I	Front-to-rear outlet in instrument panel	X	
JA9	Traffic Sign Assist	X	
XM4	Acoustic package	X	
must have (CA2+(JB7/JB6/JB8)) OR (JB4+JK5+FM3+(JB7/JB6/JB8)); not with FR8 and CO2			

X67	Chrome Grille Package	\$290
CN2	Radiator grille frame in vehicle color	X
FK3	Chrome plated radiator grille (MB only)	X
no restrictions		

X13	Exterior Lighting Package	\$1,608
L13	Fog lamp with cornering light function	Х
L22	Partial LED tail lights	Х
LA1	High beam assist	Х
LG7	LED high performance headlamps	Х
no restrictions		

C06	Cargo Convenience Package	\$658	
E36	Cutoff relay for additional battery	X	
ES2	12 V power outlet, rear compartment	X	
LC2	LED light strip in load compartment	X	
T12	Sliding door two stage opening	X	
T85	Assist handle, left rear door	X	
T86	Assist handles, right rear door	X	
W54	Rear doors, opening to side wall	X	
must l	must have T74 OR (T77+D50) OR (T77+D51)		

C07	Cargo Protection Package	\$1,117	
V25	Half height load compartment trim	X	
V42	Lashing rails, waist level	X	
VC4	Cargo lashing rails, head height	X	
VK8	Floor covering, plastic	X	
YK3	Cargo straps, D-rings	X	
not wi	not with X66		

Packages

X66	Heavy-Duty-Cargo Protection Package	\$2,043
V43	Wood floor with 6 D-rings	Х
V42	Lashing rails, waist level	Х
V52	Loadable wheel arch	Х
VA3	Side wall paneling full hardboard	Х
VC4	Cargo lashing rails, head height	Х
VV2	Lashing rails, floor level (plus 4 anchors)	Х
YK3	Cargo straps, D-rings	Х
YK4	Cargo straps, lashing rails	Х
not with CO7		

X69	Swivel Seat Package	\$532
SR8	Swivel base for driver's seat	Х
SR9	Swivel base for front passenger seat	Х
S87	Driver's seat frame, low	Х
S88	Passenger seat frame, low	Х
must have (C00+C0S) OR (C00+X68), choose BE2 or B25 (1500/2500 only)		

X01	Suspension Seating Package	\$940
SB3	Driver suspension seat, comfort version	Х
SB4	Passenger suspension seat, comfort version	Х
S87	Driver's seat frame, low	Х
S88	Passenger seat frame, low	Х
not with C00/C0S/E2I/X68/S23		

Standard Equipment

144" G	170" G
M2CA4G	M2CA7G
907.643	907.645

Engine	1		
Gas Engine/ 9-Speed Trans.			
ED4	AGM battery 12V 92 AH 850 A	<b>S</b>	S
G43	Automatic transmission, 9G-tronic	S	S
	·	S	
M60	Alternator 14 V / 250 A		S
MM3	2.0L 4-cylinder turbo gasoline engine	S	S
MH8	SULEV emissions	S	S
Equip			6
AR3	Axle ratio 4.182	S	S
BA3	Active Brake Assist	S	S
BH1	Hold Function	S	S
C6L	Multifunction steering wheel	S	S
CL1	Adjustable steering wheel (angle)	S	S
D03	High roof	-	S
D93	Omission bulkhead	S	S
E07	Hill Start Assist	S	S
E10	Standard radio	S	S
E1U	USB-C socket, 5 V	S	S
E30	Starter battery disconnect	S	S
E3J	Pre-installation for switch panel	S	S
E40	Trailer hitch prep. wiring	S	S
ED8	Preinstallation PSM	S	S
EE5	Ultracapacitor discharge module	S	S
EK1	Body Builder Connector	S	S
ES0	Jump start terminal	S	S
EW6	Pre-installation for Mercedes me Remote Services	S	S
EY5	Emergency Call System	S	S
EY6	Breakdown management	S	S
F68	Heated & electrically adjustable exterior mirrors	S	S
FF5	Shelf above windshield	S	S
FG8	Cupholder front	S	S
FI1	Remote key (315 mhz) w/central locking	S	S
FJ4	Storage compartment underneath cockpit	S	S
FR3	Rear view camera (rear-view mirror display)	S	S
H21	Windshield with filter band	S	S
HH2	Heater, auxiliary electric hot air	S	S
нн9	Air Condition, Front	S	S
IH7	Head Unit, North America	S	S
J11	Speedometer, miles and km/h	S	S
J1W	Service Interval 1 year	S	S
J55	Seat belt warning for co-driver seat	S	S
J58	Seat belt reminder driver	S	S
J65	Outside temperature gauge	S	S
JA8	Crosswind Assist	S	S
JH3	Communication module (LTE) for dig. services	S	S
JI8	Service interval 15.000 miles	S	S
K14	22 gallon fuel tank	S	S
K60	Exhaust straight to rear	S	S
L65	Interior lights, cargo compartment	S	S
L94	Parking lights deletion	S	S
LA2	Headlight assistant	S	S
LB5	3rd brake light	S	S
MS1	Cruise control	S	S
P47	Front mudflaps	S	S
F4/	i ront maanaps	3	3

#### **2500 CARGO VAN - GAS** Standard Equipment

		144" G	170'' G
		M2CA4G	M2CA7G
		907.643	907.645
P48	Rear mudflaps	S	S
Q11	Longitudinal member reinforcement	S	S
R65	Spare tire bracket below frame	S	S
R87	Spare tire	S	S
RH8	Tires LT 245/75 R16	S	S
RM0	All-season tires	S	S
RD9	Unspecified tire brand	S	S
RS3	6.5 J x 16 steel wheels	S	S
RY2	Tire pressure monitoring sensors	S	S
S02	Standard driver seat	S	S
S04	Standard front passenger seat	S	S
S22	Armrest for driver's seat	S	S
S25	Armrest for front passenger seat	S	S
SA5	Front airbag, driver	S	S
SA6	Front airbag, passenger	S	S
SH1	Thorax-pelvis sidebag, driver	S	S
SH2	Thorax-pelvis sidebag, co-driver	S	S
SH9	Airbag, driver/passenger window	S	S
SK2	Seat occupancy sensor, driver's seat	S	S
T16	Sliding door, passenger side	S	S
V93	Without factory installed flooring	S	S
V94	Cable duct - side wall	S	S
V95	Cable duct - rear portal	S	S
XL2	GVWR 9,050 lbs. / 4.100 Kg	S	S
Y43	Jack, hydraulic	S	S

		144" G	170" G
		M2CA4G	M2CA7G
		907.643	907.645
A50	Front axle reinforced	\$346	\$346
AP2	Addtl. bar for driveshaft & exhaust extension	\$69	\$69
B01	ESP for increased Center of Gravity above 39.4"	\$0	\$0
	must have CB4/CB8/X30; not with RH0/CB7		
B25	Electric parking brake	\$279	\$279
	not with BE2; X69 choose B25/BE2	1	
BE2	Handbrake lever, folding	\$55	\$55
	not with B25; X69 choose B25/BE2	4	40.00
C72	Bumpers front/rear primed	\$268	\$268
	must have CN2 (part of X67), not with CM0	4	40
CB1	Suspension for comfort and load protection	\$241	\$241
CB7	Stabilization Level I	\$307	\$307
	not with CB4/CB8/X30	4700	4700
CB8	Stabilization Level II	\$723	\$723
650	not with CB1/CB4/CB7/X30	4252	<b>\$252</b>
CE8	Raised rear body mounts	\$252	\$252
CL3	Leather steering wheel	\$187	\$187
C1 40	must have (CO2/E3M)/CO3 + (ET4/MS1)	<b>4507</b>	<b>4507</b>
CM0	Painted metallic front & rear bumper	\$587	\$587
	must have (CN2/X67) + (JA7/C01) + (JB6/JB7) + (7755/9197/9775)	4001	4001
CM9	Primed side moldings	\$364	\$364
CT1	Rear spring vibration absorbers	\$138	\$138
D03	High roof	\$2,900	S
D13	Mounting rails for roof rack	\$300	\$300
D22	Fixed sunroof (rear roof section)	\$336	\$336
550	not with H08/HK4/H72/V36/ZK4	4000	4222
D50	Cargo partition	\$288	\$288
554	not with D51/D93/H08/HK4/T74/V36; must have one of T93/T77	4005	4225
D51	Cargo partition with 1 window	\$335	\$335
545	not with D50/D93/H08/HK4/T74/V37/D17; must have one of T93/T77		<b>6456</b>
E1B	Tray for smartphones incl. wireless charging	\$156	\$156
<b>545</b>	must have CO2/E3M + H1I	6720	ć720
E1E	Navigation	\$728	\$728
F1C	must have CO2/E3M, not with CO3	ĆOFF	ĆOFF
E1S	Sirius XM, satellite radio	\$255	\$255
T1D	must have C02/E3M/C03	¢ro.	ĊΓΩ
E1R	Additional Fuses (40/80/150/100 Ampere)	\$50	\$50
F1V	SoP and Plausibility TBD Additional Fuses (40/80/80/100 Ampere)	\$50	\$50
E1Y		<b>Ş</b> 50	\$30
E2A	SoP and Plausibility TBD  Access point for BB special signals in cockpit	\$29	\$29
E2I	Additional battery, co-driver seat base	\$248	\$248
EZI	must have E36/C06; not with E2M/F09; CHS production only	Ş24 <b>0</b>	Ş2 <del>4</del> 0
E2M	Additional battery, engine compartment	\$248	\$248
CZIVI		Ş24 <b>0</b>	Ş2 <del>4</del> 6
E3M	must have X01+ (E36/C06); not with E2I/X69/F09  MBUX Multimedia System with 7" touchscreen	\$474	\$474
LJIVI	not with CO2/CO3; must have JK5+(JB7/JB6/JB8/FR8)	<b>→</b> +7+	74/4
E36	Cutoff relay for additional battery	\$110	\$110
_50	standard with E2I/E2M	Ϋ́TTU	2110
E46	12 V power outlet, driver seat base	\$92	\$92
E5M	Extension of PSM standard contact	\$92 \$58	\$58
ED5	Parametric special module (PSM)	\$317	\$317
בחט	not with ED8	321/	321/
EE3	115 V socket	\$125	\$125
LEJ	TTO A SOCKEL	<b>Σ1</b> ΖΣ	Ş1Z3

		144" G	170" G
		M2CA4G	M2CA7G
		907.643	907.645
EP7	Pacie electric fitting for roar loudeneakers		
ES2	Basic electric fitting for rear loudspeakers	\$68 \$92	\$68 \$92
	12 V power outlet, rear compartment	·	•
ES5	Charging package, dashboard	\$82	\$82
ET4	Active Distance Assist DISTRONIC	\$263	\$263
	must have CO2/CO3/E3M; not with ZH4	4	4
F1K	Coat hooks in driver cabin	\$14	\$14
	must have D50/D51	4	4
F49	Electrically heated windshield	\$218	\$218
	no restriction		
F61	Interior rear view mirror	\$36	\$36
	not with D50; must have C02/E3M/C03		
F64	Electrically folding exterior mirrors	\$49	\$49
FE9	Additional DIN-slot	\$81	\$81
FF8	Overhead storage slot, front center	\$105	\$105
FJ1	Hinged lid for storage compartment	\$93	\$93
FR8	Rear view camera (head unit display)	\$336	\$336
	must have CO2/E3M; not with FR3/JB7/JB6/JB8		
FY1	Security alarm w. interior motion sensor	\$584	\$584
	must have LC4/C00		
FY7	Optional 3-button keys	\$36	\$36
FZ9	Keys, two additional masters	\$121	\$121
H00	Warm/cool air duct to rear compartment	\$59	\$59
	not with D50/D51/Y2A		
H01	Heat insulation, rear compartment	\$156	\$156
	must have V21/V25/VA3/VA1/C07/X66		
H04	Heat insulation, front compartment	\$187	\$187
	if + D50/D51 must have V07		
H08	Air conditioning rear, roof-mounted	\$2,872	\$2,872
	must have D93 +V36; not with HK4/C06/X66/C07	•	
H13	Rear cabin heater and vents	\$786	\$786
	must have H12/HZ9	,	·
H15	Heated front passenger seat	\$284	\$284
	must have H16; not with X68	,	
H16	Heated driver's seat	\$284	\$284
	must have H15; not with X68	, -	, -
H22	Rear window defroster	\$253	\$253
	must have W61/W78; standard for W61+W70	7-00	7-55
H72	Roof fan, electric	\$400	\$400
	not with D22/V36	φ	φ.00
H88	Rear heater prep	\$405	\$405
1100	must have H12/HZ9; not with H13/T19	Ų 103	Ų 103
H1I	Front-to-rear outlet in instrument panel	\$0	\$0
1111	must have FJ1/C01	γo	γo
HH4	Thermotronic automatic climate control	\$337	\$337
пп4		Ş33 <i>1</i>	<b>3337</b>
147	must have JF1; if +H13 must have H08/HK4	¢450	Ć4FO
JA7	Blind Spot Assist	\$450	\$450
ID 4	must have F64; not with C01	6200	ć200
JB4	Active Lane Keeping Assist	\$288	\$288
IDC	standard with CO2/CA2	A-3-	A335
JB6	Parking Package with 360 degree camera	\$775	\$775
	must have CO2/CO3/E3M; not with W75/W76/JB7		4.
JB7	Parking Package	\$615	\$615
	must have C02/C03/E3M; not with W75/W76/JB6		
JB8	360 Degree Camera	\$685	\$685
-			
JF1	SoP and Plausibility TBD Rain sensor	\$106	\$106

		M2CA4G M2C	170" G
			M2CA7G 907.645
JK5	Landau and all address the color display		\$144
JVO	Instrument cluster with color display standard with CO2/CA2	\$144	Ş144
JW0	Backup alarm	\$99	\$99
JW2	Deactivation lamp monitoring failure	\$27	\$27
JW8	Attention Assist	\$49	\$49
L13	Fog lamp with cornering light function	\$49 \$199	\$199
L71		\$199 \$54	\$199 \$54
L/I	Light/motion sensor in rear compartment  not with V36	<b>Ş</b> 54	Ş5 <del>4</del>
LB9	Illuminated front exits	\$151	\$151
LC2		\$263	\$263
LCZ	LED light strip in load compartment	Ş203	Ş205
1.04	not with H08/HK4/V36/C06	\$93	ćoa
LC4	Comfort overhead control panel	·	\$93
M20	Speed limitation 65 mph	\$60	\$60
1402	not with MD3	¢co.	¢co.
IVID3	Top speed limitation 75 mph	\$60	\$60
D02	not with M20	645	645
P93	Omission of D-rings	-\$15	-\$15
	not with D93/V43/VK8	4447	A 4 4 7
Q24	Trailer hitch, 5,000 lbs	\$147	\$147
0.4.0	not with W73/W75/W76	4101	4404
QA9	Half-sided step rear (for trailer hitch)	\$101	\$101
	must have Q24/QA2; not with W73/W75/W76	4	4
R91	Spare tire deletion	-\$110	-\$110
	must have R92; not with R87	4 -	1 4-
R92	Spare tire carrier deletion	\$0	\$0
	must have R91; not with R65		
R98	Rims painted jet black	\$81	\$81
	not with RL5/RM2		
RF1	Tire brand Continental	\$0	\$0
	must have RM1 + RM9		
RF8	Tire brand Michelin	\$0	\$0
	must have RM9; not with RM1		T
RH0	Tire brand Kumho	\$0	\$0
	must have RM9; not with RM1		
RL5	Light-alloy wheels 6.5 J x 16	\$906	\$906
	not with RS3/RM2/R98		
RM1	M+S winter tires	\$169	\$169
	must have RF1/RD9; not with RF8/RH0/X31		
RM2	Rims painted arctic white	\$81	\$81
	not with R98/RL5		
RM9	Specially requested tires	\$101	\$101
	must have RF1/RF8/RH0; not with RD9		
S23	Twin front passenger seat	\$400	\$400
	not with C00/X68/X01		
S28	Armrest, driver and passenger door	\$51	\$51
S62	Seat belts orange, driver and front passenger	\$32	\$32
	not with S23		
SB9	Driver's seat plus	\$238	\$238
	must have VF7; not with C00/X68/X69		
SZ7	Storage net, driver's seat backrest	\$64	\$64
SZ8	Storage net, passenger seat backrest	\$64	\$64
T12	Sliding door two stage opening	\$82	\$82
	not with T55		
T19	Sliding door, driver's side	\$935	\$935
	not with H13/H88/VC5/ZE6/F43/W16/F02; if +V36 must have D03		

		144" G	170" G
		M2CA4G	M2CA7G
		907.643	907.645
T50	Electric closing assist right sliding door	\$335	\$335
130	must have D03; not with T55/T93	<b>\$333</b>	<del>-</del>
T51	Electric closing assist left sliding door	\$335	\$335
131	must have T19 + D03	<b>\$333</b>	<del> </del>
T55	Electric sliding door right	\$831	\$831
133	must have D03 + (FY7+T16); not with T12/T50	<del>7</del> 031	7031
T57	Electric sliding step	\$1,071	\$1,071
137	must have ED5; not with T93	71,071	71,071
T60	Opening limiter electrically operated sliding door	\$120	\$120
100	must have T55	<b>Ş120</b>	Ş120
T74	Assist handle, B-pillar	\$32	\$32
174	must have D93; not with T77	732	732
T75	Door-mounted assist handles, driver & passenger	\$59	\$59
T77	Assist handle w/ partition	\$32	\$32
177	must have D50/D51/D64	732	732
T85	Assist handle, left rear door	\$32	\$32
T86	Assist handles, right rear door	\$32	\$32
T93	Sliding door right side deletion	\$32 \$0	\$32 \$0
193	not with T16/T50/T57/VK8/VC5	ŞÜ	<b>3</b> 0
V07	Cab rear wall liner	\$360	\$360
V07	must have (D50/D51)+F1K; standard with H04	<del>3</del> 300	<del>3300</del>
V21	Luxury interior Trim	\$661	\$661
VZI	must have VA5/VA7; not with V52/VA1/VA3	3001	3001
V24	Pallet support in sliding door step	\$96	\$96
V 2-4	must have (V43/X66)+(D50/D51); not with VK8/V93/C07	<del>\$</del> 50	200
V25	Half height load compartment trim	\$201	\$201
V 2.5	not with VA1/VA3/VA5/V52/X66	<b>\$201</b>	<b>J201</b>
V31	Window pillar trim	\$513	\$513
V 3 I	must have V36 + (V21/VA1) + (F02/F03/F07); not with V42	7515	7313
V35	Wheel house covering	\$105	\$105
<b>V</b> 33	if +V43 must have V25/VA1/VA3; not with V52	Ş103	<b>Ş103</b>
V36	Roof trim	\$876	\$876
<b>V</b> 30	must have D93; not with D17/D22/H72/L65/L71/LC2/VA3/V42/ZE6/(T93+-D	,	3070
V42	Lashing rails, waist level	\$277	\$277
V 42	not with V36/ZE6	7211	ĄZ11
V43	Wood floor with 6 D-rings	\$422	\$422
V +3	not with P93/V93/VL4/VK8/C07; standard with D93/H13/V24/V52/V		7422
V48	Floor cover behind seat box	\$27	\$27
V +0	must have D93; not with D50/D51/D56/D62/D64/V43/VK5	<i>γ</i> 21	721
V4A	Full paneling, right sliding door	\$109	\$109
V -17 (	must have D03+T16+V21+VA5+W17; not with T19	<b>\$103</b>	<b>Ģ103</b>
V52	Loadable wheel arch	\$375	\$375
VJZ	must have V43/X66; not with EL9/V21/V25/V35/VA1/C07	<b>4373</b>	7373
V85	Cigarette lighter & ash cup, front	\$39	\$39
VA1	Side wall paneling waist height PVC	\$319	\$319
VAI	must have VA5/VA7; not with V52	\$313	7313
VA3	Side wall paneling full hardboard	\$444	\$444
*713	not with V36/F02; if T93 must have (D50/D51)	Ψ	Ψ
VA5	Full paneling, hinged rear doors	\$38	\$38
.,,5	must have D03+VA7+(W61/W78); not with V25	<b>750</b>	750
VA7	Storage compart. w/ net in rear doors	\$127	\$127
VA/	must have W61/W78; not with V52	7121	7121
	Cargo lashing rails, head height	\$415	\$415
V(Z	Tour Do radining rains, richar licigite	7413	γTJ
VC4	must have V42/C07/X66: not with 7F6		
VC4 VC5	must have V42/C07/X66; not with ZE6  Door sill - protective edge	\$71	\$71

		144" G M2CA4G	170" G M2CA7G
		907.643	907.645
VK8	Floor covering, plastic	\$370	\$370
	not with V43/P93/T19/T93/V52/VC5/X66	,	
VV2	Lashing rails, floor level (plus 4 anchors)	\$270	\$345
	must have V43; not with V93/VC5/ZE6	,	
W16	2nd row, fixed window, driver side	\$145	\$145
	if D93 must have F43+W70; if D93 & standard roof CHS production red		·
W17	2nd row, fixed window, passenger side	\$145	\$145
	if D93 must have F43+W70; if D93 & standard roof CHS production red	guired	•
W33	FMVSS 217 emergency exit	\$379	\$379
	must have V31; not with D50/T19/W16	·	·
W54	Rear doors, opening to side wall	\$360	\$360
W5F	90 Degree fixation point- Rear Doors	\$80	\$80
	SoP and Plausibility TBD	•	· · · · · · · · · · · · · · · · · · ·
W61	Windows in rear doors	\$93	\$93
	must have VA7/ if D51 must have F61; not with W78/(W70+-(H22/F02	2))	· · · · · · · · · · · · · · · · · · ·
W70	Black tinting (90%) for rear windows	\$138	\$138
	not with W94; must have W16/W17/F02/((W61/W78)+H22); standar	d with F43/W33/F	07
W73	Bumper step, rear, grey	\$187	\$187
	not with Q24/W75/W76	·	·
W75	Step, wide, at rear end	\$308	\$308
	not with JB6/JB7/Q24/QA9; must have R91+R92	· · · · · · · · · · · · · · · · · · ·	·
W76	Bumper step, rear, spring-loaded	\$601	\$601
	must have R91+R92; not with JB6/JB7/X30/Q24		
W78	Heated rear window(s) w/ washers/wipers	\$335	\$335
	Must have H22+VA7 / if D51 must have F61; not with W61	•	
X90	Deletion of Sprinter badge, left rear door	\$0	\$0
X93	Deletion of model badge, right rear door	\$0	\$0
XM4	Acoustic package	\$87	\$87
	standard with CO2/CO3		
Y10	First-aid kit	\$27	\$27
Y26	Wheel chocks	\$38	\$38
Y45	Emergency flashlight	\$27	\$27
Y68	Paint preservative	\$187	\$212
Y69	Surface protection for stock vehicles	\$315	\$315
YK3	Cargo straps, D-rings	\$81	\$81
YK4	Cargo straps, lashing rails	\$104	\$104
	must have V42/VV2; not with ZE6		
ZE6	Shelving prep	\$640	\$640
	not with T93/H13/T19/V36/V42/VC4/VK8/VV2/YK4		

Packages

		144" G M2CA4G	170" G M2CA7G
		907.643	907.645
C00	Comfort Package	\$300	\$300
LC4	Comfort overhead control panel	Х	Х
SE4	Lumbar support, co-driver's seat	Х	Х
SE5	Lumbar support, driver's seat	Х	Х
SK0	Comfort head restraint, driver	Х	Х
SK1	Comfort head restraint, co-driver	Х	Х
S28	Armrest, driver and passenger door	Х	Х
must	have COS OR X68; CA/CC only: not with S23		

COS	Comfort Package (Seat addition)	\$381	\$381
SB1	Comfort driver's seat	X	X
SB2	Comfort passenger seat	Х	Х
must	have COO		

X68	Comfort Plus Package	\$1,923	\$1,923
H15	Heated front passenger seat	Х	Х
H16	Heated driver's seat	Х	Х
SF1	Driver's seat electrically adjustable	Х	Х
SF2	Co-driver's seat electrically adjustable	Х	Х
must h	must have COO and VF4 OR VF6, CA/CC only: not with S23		

C01	Driver Convenience Package	\$760	\$760
E46	12 V power outlet, driver seat base	Х	X
F64	Electrically folding exterior mirrors	Х	X
FJ1	Hinged lid for storage compartment	Х	X
FJ5	Hinged Lid for Storage Compartments left and right	Χ	X
FZ9	Keys, two additional masters	Х	X
JA7	Blind Spot Assist	Х	X
JW8	Attention Assist	Х	Х

C02	Premium Package	\$983	\$983
CL3	Leather steering wheel	Х	Х
E3M	MBUX Multimedia System with 7" touchscreen	Х	X
FM3	Wet Wiper System	Х	Х
JB4	Active Lane Keeping Assist	X	X
JK5	Instrument cluster with color display	Х	Х

Ordering availability restricted, see NetStar for availability and restrictions|must have JF1 + XM4; must choose FR8/JB7/JB6

CA2	C02 in combination with C03	\$604	\$604
CL3	Leather steering wheel	Х	Х
FM3	Wet Wiper System	Х	Х
JB4	Active Lane Keeping Assist	Х	Х
JK5	Instrument cluster with color display	Х	Х
Orderi	ng availability restricted, see NetStar for availability and restrctions mus	t have CO3 + JF1	

Packages

144" G	170" G
M2CA4G	M2CA7G
907.643	907.645

C03	Premium Plus Package	\$1,793	\$1,793		
E1B	Tray for smartphones incl. wireless charging	Х	Х		
	Navigation	Х	Х		
EY2	Intelligent navigation	X	Х		
E4M	MBUX Multimedia System with 10.25" touchscreen	Χ	Х		
EX9	Free map data updates for 3 years	Χ	X		
H1I	Front-to-rear outlet in instrument panel	X	X		
JA9	Traffic Sign Assist	Χ	X		
XM4	Acoustic package	X	Х		
must have (CA2+(JB7/JB6/JB8)) OR (JB4+JK5+FM3+(JB7/JB6/JB8)); not with FR8 and CO2					

X67	Chrome Grille Package	\$290	\$290		
CN2	Radiator grille frame in vehicle color	Х	Х		
FK3	Chrome plated radiator grille (MB only)	Х	Х		
no res	no restrictions				

X13	Exterior Lighting Package	\$1,608	\$1,608
L13	Fog lamp with cornering light function	Х	Χ
L22	Partial LED tail lights	Х	X
LA1	High beam assist	Х	Х
LG7	LED high performance headlamps	Х	Х
no res			

C06	Cargo Convenience Package	\$658	\$658	
E36	Cutoff relay for additional battery	X	X	
ES2	12 V power outlet, rear compartment	X	X	
LC2	LED light strip in load compartment	Χ	X	
T12	Sliding door two stage opening	X	X	
T85	Assist handle, left rear door	Х	Х	
T86	Assist handles, right rear door	Х	Х	
W54	Rear doors, opening to side wall	Х	Х	
must l	must have T74 OR (T77+D50) OR (T77+D51)			

C07	Cargo Protection Package	\$1,117	\$1,117
V25	Half height load compartment trim	X	X
V42	Lashing rails, waist level	X	Х
VC4	Cargo lashing rails, head height	X	Х
VK8	Floor covering, plastic	X	X
YK3	Cargo straps, D-rings	X	Х
not wi			

Packages

144" G	170" G
M2CA4G	M2CA7G
907.643	907.645

X66	Heavy-Duty-Cargo Protection Package	\$2,043	\$2,043		
V43	Wood floor with 6 D-rings	Х	Х		
V42	Lashing rails, waist level	Х	Х		
V52	Loadable wheel arch	X	Х		
VA3	Side wall paneling full hardboard	Х	Х		
VC4	Cargo lashing rails, head height	Х	Х		
VV2	Lashing rails, floor level (plus 4 anchors)	X	Х		
YK3	Cargo straps, D-rings	Х	Х		
YK4	Cargo straps, lashing rails	Х	Х		
not with CO7					

X69	Swivel Seat Package	\$532	\$532		
SR8	Swivel base for driver's seat	X	X		
SR9	Swivel base for front passenger seat	X	X		
S87	Driver's seat frame, low	Х	Х		
S88	Passenger seat frame, low	Х	Х		
must	must have (C00+C0S) OR (C00+X68), choose BE2 or B25 (1500/2500 only)				

X01	Suspension Seating Package	\$940	\$940	
SB3	Driver suspension seat, comfort version	Х	X	
SB4	Passenger suspension seat, comfort version	X	Х	
S87	Driver's seat frame, low	X	X	
S88	Passenger seat frame, low	Х	Х	
not with C00/C0S/E2I/X68/S23				

Standard Equipment

144" 4C	170" 4C	170" E 4C
M2CA44	M2CA74	M2CAE4
907.643	907.645	907.647
	_	•

		907.643	907.045	907.647	
Engin	Engine				
4-Cyl	Engine/7-Speed Trans.	S	S	S	
	AGM battery 12V 92 AH 850 A	S	S	S	
G42	Automatic transmission, 7G-tronic	S	S	S	
-	Alternator 14 V / 200 A	S	S	S	
	2.0L 4-cylinder diesel engine	S	S	S	
	SULEV emissions	S	S	S	
Equip	I.	3	3	3	
	Axle ratio 3.923	C	C	C	
AR2		S	S	S	
BA3	Active Brake Assist	S	S	S	
BH1	Hold Function	S	S	S	
C6L	Multifunction steering wheel	S	S	S	
CL1	Adjustable steering wheel (angle)	S	S	S	
D03	High roof	-	S	S	
D93	Omission bulkhead	S	S	S	
E07	Hill Start Assist	S	S	S	
E10	Standard radio	S	S	S	
E1U	USB-C socket, 5 V	S	S	S	
E30	Starter battery disconnect	S	S	S	
E3J	Pre-installation for switch panel	S	S	S	
E40	Trailer hitch prep. wiring	S	S	S	
ED8	Preinstallation PSM	S	S	S	
EE5	Ultracapacitor discharge module	S	S	S	
EK1	Body Builder Connector	S	S	S	
ES0	Jump start terminal	S	S	S	
-	Pre-installation for Mercedes me Remote Services	S	S	S	
EY5	Emergency Call System	S	S	S	
EY6	Breakdown management	S	S	S	
F68	-		-	-	
	Heated & electrically adjustable exterior mirrors	S	S	S	
FF5	Shelf above windshield	S	S	S	
FG8	Cupholder front	S	S	S	
FI1	Remote key (315 mhz) w/central locking	S	S	S	
FJ4	Storage compartment underneath cockpit	S	S	S	
FR3	Rear view camera (rear-view mirror display)	S	S	S	
H21	Windshield with filter band	S	S	S	
HH2	Heater, auxiliary electric hot air	S	S	S	
HH9	Air Condition, Front	S	S	S	
IH7	Head Unit, North America	S	S	S	
J11	Speedometer, miles and km/h	S	S	S	
J55	Seat belt warning for co-driver seat	S	S	S	
J58	Seat belt reminder driver	S	S	S	
J65	Outside temperature gauge	S	S	S	
JA8	Crosswind Assist	S	S	S	
JH3	Communication module (LTE) for dig. services	S	S	S	
JI9	Service interval 20.000 miles	S	S	S	
K56	Red diesel filler cap	S	S	S	
K60	Exhaust straight to rear	S	S	S	
KB7	24.5 gallon fuel tank	S	S	S	
KL1	Aux fuel sending unit w/ fuel tap	S	S	S	
KL5	Fuel filter with water separator	S	S	S	
KP6	3rd generation SCR emission control system	S	S	S	
		S	S	S	
L65	Interior lights, cargo compartment	S			
L94	Parking lights deletion		S	S	
LA2	Headlight assistant	S	S	S	
LB5	3rd brake light	S	S	S	
MS1	Cruise control	S	S	S	

Standard Equipment

		144" 4C	170" 4C	170" E 4C
		M2CA44	M2CA74	M2CAE4
		907.643	907.645	907.647
P47	Front mudflaps	S	S	S
P48	Rear mudflaps	S	S	S
Q11	Longitudinal member reinforcement	S	S	S
R65	Spare tire bracket below frame	S	S	S
R87	Spare tire	S	S	S
RH8	Tires LT 245/75 R16	S	S	S
RM0	All-season tires	S	S	S
RD9	Unspecified tire brand	S	S	S
RS3	6.5 J x 16 steel wheels	S	S	S
RY2	Tire pressure monitoring sensors	S	S	S
S02	Standard driver seat	S	S	S
S04	Standard front passenger seat	S	S	S
S22	Armrest for driver's seat	S	S	S
S25	Armrest for front passenger seat	S	S	S
SA5	Front airbag, driver	S	S	S
SA6	Front airbag, passenger	S	S	S
SH1	Thorax-pelvis sidebag, driver	S	S	S
SH2	Thorax-pelvis sidebag, co-driver	S	S	S
SH9	Airbag, driver/passenger window	S	S	S
SK2	Seat occupancy sensor, driver's seat	S	S	S
T16	Sliding door, passenger side	S	S	S
V93	Without factory installed flooring	S	S	S
V94	Cable duct - side wall	S	S	S
V95	Cable duct - rear portal	S	S	S
W54	Rear doors, opening to side wall	0	0	S
XL2	GVWR 9,050 lbs. / 4.100 Kg	S	S	S
Y43	Jack, hydraulic	S	S	S

		144" 4C M2CA44	170" 4C	170" E 4C M2CAE4		
			M2CA74			
		907.643	907.645	907.647		
A50	Front axle reinforced	\$346	\$346	\$346		
AP2	Addtl. bar for driveshaft & exhaust extension	\$69	\$69	-		
AR3	Axle ratio 4.182	\$0	\$0	\$0		
B01	ESP for increased Center of Gravity above 39.4"	\$0	\$0	\$0		
	must have CB4/CB8/X30; not with RH0/CB7					
B25	Electric parking brake	\$279	\$279	\$279		
	not with BE2; X69 choose B25/BE2					
BE2	Handbrake lever, folding	\$55	\$55	\$55		
	not with B25; X69 choose B25/BE2					
C72	Bumpers front/rear primed	\$268	\$268	\$268		
	must have CN2 (part of X67), not with CM0					
CB1	Suspension for comfort and load protection	\$241	\$241	\$241		
CB7	Stabilization Level I	\$307	\$307	\$307		
	not with CB4/CB8/X30					
CB8	Stabilization Level II	\$723	\$723	\$723		
	not with CB1/CB4/CB7/X30					
CE8	Raised rear body mounts	\$252	\$252	\$252		
CL3	Leather steering wheel	\$187	\$187	\$187		
	must have (C02/E3M)/C03 + (ET4/MS1)					
CM0	Painted metallic front & rear bumper	\$587	\$587	\$587		
	must have (CN2/X67) + (JA7/C01) + (JB6/JB7) + (7755/9197/9775)					
CM9	Primed side moldings	\$364	\$364	\$364		
CT1	Rear spring vibration absorbers	\$138	\$138	\$138		
D03	High roof	\$2,900	S	S		
D13	Mounting rails for roof rack	\$300	\$300	\$300		
D22	Fixed sunroof (rear roof section)	\$336	\$336	\$336		
	not with H08/HK4/H72/V36/ZK4	•				
D50	Cargo partition	\$288	\$288	\$288		
	not with D51/D93/H08/HK4/T74/V36; must have one of T93/T77	•				
D51	Cargo partition with 1 window	\$335	\$335	\$335		
	not with D50/D93/H08/HK4/T74/V37/D17; must have one of T93/T	77				
E1B	Tray for smartphones incl. wireless charging	\$156	\$156	\$156		
	must have CO2/E3M + H1I	•				
E1E	Navigation	\$728	\$728	\$728		
	must have CO2/E3M, not with CO3	•				
E1S	Sirius XM, satellite radio	\$255	\$255	\$255		
	must have CO2/E3M/CO3	•				
E1R	Additional Fuses (40/80/150/100 Ampere)	\$50	\$50	\$50		
	SoP and Plausibility TBD					
E1Y	Additional Fuses (40/80/80/100 Ampere)	\$50	\$50	\$50		
	SoP and Plausibility TBD					
E1X	MBUX multimedia 6-hour runtime	\$0	\$0	\$0		
	must have X2R + (C02+E1E/E1S)/C03/(E3M+E1E/E1S)					
E2A	Access point for BB special signals in cockpit	\$29	\$29	\$29		
E2I	Additional battery, co-driver seat base	\$248	\$248	\$248		
	must have E36/C06; not with E2M/F09; CHS production only					
E2M	Additional battery, engine compartment	\$248	\$248	\$248		
•	must have X01+ (E36/C06); not with E2I/X69/F09					
E3M	MBUX Multimedia System with 7" touchscreen	\$474	\$474	\$474		
	not with CO2/CO3; must have JK5+(JB7/JB6/JB8/FR8)	Ψ 1, τ	717	7111		
E36	Cutoff relay for additional battery	\$110	\$110	\$110		
_55	standard with E2I/E2M	7110	7110	ŸII0		
F4C	12 V power outlet, driver seat base	\$92	\$92	\$92		
FAD	12 v power outlet, uriver seut buse	·				
E46 F5M	Extension of PSM standard contact	\$58	\$5X	\$5X		
E5M ED5	Extension of PSM standard contact Parametric special module (PSM)	\$58 \$317	\$58 \$317	\$58 \$317		

		144" 4C	170" 4C	170" E 4C
		M2CA44	M2CA74	M2CAE4
		907.643	907.645	907.647
EE3	115 V socket	\$125	\$125	\$125
EP7	Basic electric fitting for rear loudspeakers	\$68	\$68	\$68
ES2	12 V power outlet, rear compartment	\$92	\$92	\$92
ES5	Charging package, dashboard	\$82	\$82	\$82
ET4	Active Distance Assist DISTRONIC	\$263	\$263	\$263
- 14	must have CO2/CO3/E3M; not with ZH4	Ş203	<b>7203</b>	Ş203
F1K	Coat hooks in driver cabin	\$14	\$14	\$14
IIN	must have D50/D51	714	Ϋ́	Ϋ́
F49	Electrically heated windshield	\$218	\$218	\$218
143	no restriction	7210	7210	7210
F61	Interior rear view mirror	\$36	\$36	\$36
101	not with D50; must have C02/E3M/C03	730	730	730
F64	Electrically folding exterior mirrors	\$49	\$49	\$49
FE9	Additional DIN-slot	\$81	\$81	\$43
FF8	Overhead storage slot, front center	\$105	\$105	\$105
FJ1	Hinged lid for storage compartment	\$93	\$93	\$93
FR8	Rear view camera (head unit display)	\$336	\$336	\$336
1 1/0	must have CO2/E3M; not with FR3/JB7/JB6/JB8	,,,,,	2230	2230
FY1	Security alarm w. interior motion sensor	\$584	\$584	\$584
L11	must have LC4/C00	<b>3364</b>	<del>3</del> 364	<del>3</del> 364
FY7	Optional 3-button keys	\$36	\$36	\$36
FZ9	Keys, two additional masters	\$121	\$121	\$121
-		\$59		\$121
H00	Warm/cool air duct to rear compartment not with D50/D51/Y2A	\$28	\$59	\$59
H01	Heat insulation, rear compartment	\$156	\$156	\$156
пот	must have V21/V25/VA3/VA1/C07/X66	\$130	\$120	\$120
H04	Heat insulation, front compartment	\$187	\$187	\$187
1104	if + D50/D51 must have V07	\$107	\$107	\$107
H08	Air conditioning rear, roof-mounted	\$2,872	\$2,872	\$2,872
поо	must have D93 +V36; not with HK4/C06/X66/C07	\$2,072	\$2,072	\$2,072
H12	Fuel-fired pre-heater/booster (17K BTU)	\$1,116	\$1,116	\$1,116
П12	not with HZ9	\$1,110	\$1,110	\$1,110
H13	Rear cabin heater and vents	\$786	\$786	\$786
птэ	must have H12/HZ9	3780	\$780	\$760
H15	Heated front passenger seat	\$284	\$284	\$284
птэ	must have H16; not with X68	Ş20 <del>4</del>	<b>3204</b>	<i>3</i> 204
H16	Heated driver's seat	\$284	\$284	\$284
пто		\$2 <b>0</b> 4	\$ <b>2</b> 04	\$ <b>2</b> 04
H22	must have H15; not with X68  Rear window defroster	\$253	\$253	\$253
ПZZ		\$255	\$255	\$255
1172	must have W61/W78; standard for W61+W70	\$400	\$400	¢400
H72	Roof fan, electric	\$400	\$400	\$400
цоо	not with D22/V36	¢40F	¢405	Ć40F
H88	Rear heater prep	\$405	\$405	\$405
1141	must have H12/HZ9; not with H13/T19	ćo.	ćo	ćo
H1I	Front-to-rear outlet in instrument panel	\$0	\$0	\$0
ши	must have FJ1/C01  Thermetronic automatic climate central	6227	¢227	¢227
HH4	Thermotronic automatic climate control	\$337	\$337	\$337
шил	must have JF1; if +H13 must have H08/HK4	62.040	¢2.040	¢2.040
HK4	Rear air conditioner, heavyduty	\$3,940	\$3,940	\$3,940
1170	must have D03+V36+D93; not with H08/ZB6/ZE6/N62/N63	6070	¢c7c	¢c7c
HZ9	Fuel-fired heater booster (18,000 BTU)	\$676	\$676	\$676
154	not with H12	672	673	673
J51	Fuel gauge, optimized for aux. fuel tap	\$72	\$72	\$72
IES	not with HZ9/H12	<u> </u>	ćo	ĊO
J52	Engine oil level display at cold start	\$0	\$0	\$0

		144" 4C	170" 4C	170" E 4C M2CAE4	
		M2CA44	M2CA74		
		907.643	907.645	907.647	
JA7	Blind Spot Assist	\$450	\$450	\$450	
15.4	must have F64; not with C01		<b>6200</b>	<b>\$200</b>	
JB4	Active Lane Keeping Assist	\$288	\$288	\$288	
10.0	standard with CO2/CA2		6775	4775	
JB6	Parking Package with 360 degree camera	\$775	\$775	\$775	
107	must have CO2/CO3/E3M; not with W75/W76/JB7	¢645	¢C4F	¢645	
JB7	Parking Package	\$615	\$615	\$615	
IDO	must have CO2/CO3/E3M; not with W75/W76/JB6	¢cor	¢cor	¢cor	
JB8	360 Degree Camera	\$685	\$685	\$685	
JF1	SoP and Plausibility TBD Rain sensor	\$106	\$106	\$106	
1LT	not with CO2/X11	\$100	\$100	\$100	
JK5	·	\$144	\$144	\$144	
1//2	Instrument cluster with color display standard with CO2/CA2	Ş1 <del>44</del>	\$1 <del>44</del>	Ş144	
JW0	Backup alarm	\$99	\$99	\$99	
JW2	Deactivation lamp monitoring failure	\$27	\$27	\$27	
JW8	Attention Assist	\$49	\$49	\$49	
K51	Misfueling prevention for Diesel	\$49	\$49	\$49	
K51	DEF fluid filler cap - lockable	\$27	\$27	\$27	
L13	Fog lamp with cornering light function	\$199	\$199	\$199	
L71	Light/motion sensor in rear compartment	\$54	\$54	\$54	
	not with V36	ا ۶۵۰	754	<del>,</del>	
LB9	Illuminated front exits	\$151	\$151	\$151	
LC4	Comfort overhead control panel	\$93	\$93	\$93	
LC2	LED light strip in load compartment	\$263	\$263	\$263	
	not with H08/HK4/V36/C06	7200	<b>¥</b> 200	Ψ=00	
M20	Speed limitation 65 mph	\$60	\$60	\$60	
	not with MD3	, , , ,	1	,	
M60	Alternator 14 V / 250 A	\$704	\$704	\$704	
MD3	Top speed limitation 75 mph	\$60	\$60	\$60	
	not with M20		·		
N62	Front engine bracket for additional alternator	\$467	\$467	\$467	
	not with HK4/N63	•			
N63	Front engine bracket for auxiliary A/C compressor	\$467	\$467	\$467	
	not with HK4/N62	<del>,</del>			
P93	Omission of D-rings	-\$15	-\$15	-\$15	
	not with D93/V43/VK8				
Q24	Trailer hitch, 5,000 lbs	\$147	\$147	\$147	
	not with W73/W75/W76				
QA9	Half-sided step rear (for trailer hitch)	\$101	\$101	\$101	
	must have Q24/QA2; not with W73/W75/W76				
R91	Spare tire deletion	-\$110	-\$110	-\$110	
	must have R92; not with R87				
R92	Spare tire carrier deletion	\$0	\$0	\$0	
	must have R91; not with R65				
R98	Rims painted jet black	\$81	\$81	\$81	
	not with RL5/RM2				
RF1	Tire brand Continental	\$0	\$0	\$0	
	must have RM1 + RM9				
RF8	Tire brand Michelin	\$0	\$0	\$0	
	must have RM9; not with RM1				
RH0	Tire brand Kumho	\$0	\$0	\$0	
	must have RM9; not with RM1				
RL5	Light-alloy wheels 6.5 J x 16	\$906	\$906	\$906	
	not with RS3/RM2/R98				

		144" 4C	170" 4C	170" E 4C M2CAE4 907.647
		M2CA44	M2CA74 907.645	
		907.643		
RM1	M+S winter tires	\$169	\$169	\$169
	must have RF1/RD9; not with RF8/RH0/X31			
RM2	Rims painted arctic white	\$81	\$81	\$81
	not with R98/RL5			
RM9	Specially requested tires	\$101	\$101	\$101
	must have RF1/RF8/RH0; not with RD9			
S23	Twin front passenger seat	\$400	\$400	\$400
	not with C00/X68/X01			
S28	Armrest, driver and passenger door	\$51	\$51	\$51
S62	Seat belts orange, driver and front passenger	\$32	\$32	\$32
	not with S23			
SB9	Driver's seat plus	\$238	\$238	\$238
	must have VF7; not with C00/X68/X69			-
SZ7	Storage net, driver's seat backrest	\$64	\$64	\$64
SZ8	Storage net, passenger seat backrest	\$64	\$64	\$64
T12	Sliding door two stage opening	\$82	\$82	\$82
	not with T55			
T19	Sliding door, driver's side	\$935	\$935	\$935
	not with H13/H88/VC5/ZE6/F43/W16/F02; if +V36 must have D03			
T50	Electric closing assist right sliding door	\$335	\$335	\$335
	must have D03; not with T55/T93	•		
T51	Electric closing assist left sliding door	\$335	\$335	\$335
	must have T19 + D03	•		•
T55	Electric sliding door right	\$831	\$831	\$831
	must have D03 + (FY7+T16); not with T12/T50			
T57	Electric sliding step	\$1,071	\$1,071	\$1,071
	must have ED5; not with T93		<u> </u>	
T60	Opening limiter electrically operated sliding door	\$120	\$120	\$120
	must have T55		•	
T74	Assist handle, B-pillar	\$32	\$32	\$32
	must have D93; not with T77	752	7-2-	7-2-
T75	Door-mounted assist handles, driver & passenger	\$59	\$59	\$59
T77	Assist handle w/ partition	\$32	\$32	\$32
· · · ·	must have D50/D51/D64	, 432	Ψ32	<b>402</b>
T85	Assist handle, left rear door	\$32	\$32	\$32
T86	Assist handles, right rear door	\$32	\$32	\$32
T93	Sliding door right side deletion	\$0	\$0	\$0
133	not with T16/T50/T57/VK8/VC5	70	<b>30</b>	<b>30</b>
V07	Cab rear wall liner	\$360	\$360	\$360
V 07	must have (D50/D51)+F1K; standard with H04	\$300	7300	\$300
V21	Luxury interior Trim	\$661	\$661	\$661
VZI	must have VA5/VA7; not with V52/VA1/VA3	3001	3001	3001
V24	Pallet support in sliding door step	\$96	\$96	\$96
V 24		290	\$90	\$90
V2F	must have (V43/X66)+(D50/D51); not with VK8/V93/C07	¢201	¢201	¢201
V25	Half height load compartment trim	\$201	\$201	\$201
V21	not with VA1/VA3/VA5/V52/X66	¢512	ĆE12	ĆE12
V31	Window pillar trim	\$513	\$513	\$513
\/2F	must have V36 + (V21/VA1) + (F02/F03/F07); not with V42	6405	Ć40F	Ć40F
V35	Wheel house covering	\$105	\$105	\$105
\\\ \( \)	if +V43 must have V25/VA1/VA3; not with V52	40	4075	4075
V36	Roof trim	\$876	\$876	\$876
	must have D93; not with D17/D22/H72/L65/L71/LC2/VA3/V42/ZE			4 -
V42	Lashing rails, waist level	\$277	\$277	\$277
	not with V36/ZE6			
V43	Wood floor with 6 D-rings	\$422	\$422	\$422
	not with P93/V93/VL4/VK8/C07; standard with D93/H13/V24/V52			
V48	Floor cover behind seat box	\$27	\$27	\$27
	must have D93; not with D50/D51/D56/D62/D64/V43/VK5			

M2CA44   M2CA78   M3CA64   M3CA66   M			144" 4C	170" 4C	170" E 4C
Full paneling, right sliding door   S109					
must have D03+T16+V21+VA5+W17, not with T19  520 Loadable wheel arch must have V43/K66, not with EL9/V21/V25/V35/V41/C07  W55 Cigarette lighter, & sah cup, front M56 Side will paneling wish relight PVC M57 Side will paneling wish relight PVC M58 Side will paneling wish relight PVC M59 Side will paneling full hardboard M57 Side will paneling, linged rear doors M57 Side will paneling, linged rear doors M57 Side will paneling, hinged will pa			907.643	907.645	907.647
VS2         Loadable wheel arch         5375         5375         5375           W85         Cigarette lighter & ash cup, front         539         539         539           VA1         Side wall paneling waist height PVC         5319         5319         5319           VA1         Side wall paneling full hardboard         \$444         \$444         \$444           VA3         Side wall paneling, full hardboard         \$444         \$444         \$444           A3         Side wall paneling, full hardboard         \$444         \$444         \$444           A5         Full paneling, hinged rear doors         \$38         \$38         \$38           most hove D03+VA7-(W6L/W78); not with V25         V24         \$445         \$5415         \$415           MS4         Storage compart. Wy feet in rear doors         \$127         \$127         \$127           MS5         Storage compart. Wy feet in rear doors         \$127         \$127         \$127           MS5         Storage compart. Wy feet in rear doors         \$127         \$127         \$127           MS6         Storage compart. Wy feet in rear doors         \$127         \$127         \$127           VC4         Cargo lashing ralish         \$415         \$415         \$415      <	V4A	Full paneling, right sliding door	\$109	\$109	\$109
must have V43/X66; not with ELSP/V21/V25/V35/V41/C07		must have D03+T16+V21+VA5+W17; not with T19	_		
V35         Cgarette lighter & ash cup, front         \$39         \$39         \$318         \$319         \$319         \$319         \$319         \$319         \$318         \$319         \$319         \$319         \$319         \$319         \$319         \$319         \$319         \$319         \$319         \$319         \$319         \$319         \$319         \$319         \$319         \$312         \$312         \$412         \$412         \$444	V52		\$375	\$375	\$375
Side wall paneling waist height PVC   \$319		must have V43/X66; not with EL9/V21/V25/V35/VA1/C07	_		
			· ·	•	
VA3         Ide wall paneling full hardboard         \$444         \$445	VA1		\$319	\$319	\$319
VAS         Full paneling, linged rear doors         \$38         \$38         \$38           WAS         Full paneling, linged rear doors         \$127         \$127         \$127           VA7         Storage compart, w/ net in rear doors         \$127         \$127         \$127           VA7         Storage compart, w/ net in rear doors         \$127         \$127         \$127           VA7         Storage compart, w/ net in rear doors         \$127         \$127         \$127           VA7         Storage compart, w/ net in rear doors         \$127         \$127         \$127           vA8         Sas degree degree         \$71         \$71         \$71           vA8         For part of the with very degree degree         \$71         \$71         \$71           vCD         Door sall protective edge         \$71         \$71         \$71           vV2         Lashing rails, floor level (plus 4 anchors)         \$320         \$320         \$320         \$320         \$320		must have VA5/VA7; not with V52	_		
VAS Full paneling, hinged rear doors  was hove DATA**(HVE)/W78); not with V25  VA7 Storage compart. W) net in rear doors  stage compart. W) net in rear doors  was thowe W61/W78, not with V52  VC4 Cargo lashing ralls, head helpht  must hove W42/C07/X66, not with ZE6  VC5 Door sill - protective edge  must hove W43/X66, not with T19/T93/VX8/VV2/V93/C07  VK8 Floor covering, plastic  not with W43/P93/T19/T93/V52/VC5/X66  VC2 Lashing ralls, floor level (plus 4 anchors)  was thave V43/X67, not with V93/VC5/ZE6  VC3 Door sill - protective edge  not with W43/P93/T19/T93/V52/VC5/X66  VC4 Cargo strains, floor level (plus 4 anchors)  must have V43/X67, not with V93/VC5/ZE6  VC5 Door sill - protective edge  do not with W43/P93/T19/T93/V52/VC5/X66  VC5 Door sill - protective edge  not with W43/P93/T19/T93/V52/VC5/X66  VC6 Lashing ralls, floor level (plus 4 anchors)  must have V43/2; not with V93/VC5/ZE6  VC6 Lashing ralls, floor level (plus 4 anchors)  must have V43/2; not with V93/VC5/ZE6  VC7 Lashing ralls, floor level (plus 4 anchors)  pust have V43/2; not with V93/VC5/ZE6  VC7 Lashing ralls, floor level (plus 4 anchors)  pust have V43/2; not with V93/VC5/ZE6  VC7 Lashing ralls, floor level (plus 4 anchors)  pust have V43/2; not with V93/VC5/ZE6  VC7 Lashing ralls, floor level (plus 4 anchors)  pust have V43/4; not with V93/VC5/ZE6  VC7 Lashing ralls, floor level (plus 4 anchors)  pust have V43/4; not with V93/VC5/ZE6  VC7 Lashing ralls, floor level (plus 4 anchors)  pust have V43/4; not with D50/T19/V16  VC8 Lashing ralls have F43+W70; floor Sa standard roof CHS production required  VC9 Lashing ralls have F43+W70; floor Sa standard roof CHS production required  VC9 Lashing ralls have F41-W71/V16  VC9 Lashing ralls have F61 ralls have F61; not with W75/W76  VC9 Lashing ralls have F61 ralls have F61; not with W61  Dale late of Sa	VA3		\$444	\$444	\$444
Was brown both both both both both both both both			_		
VA7         Storage compart. w/ net in rear doors         \$127	VA5		\$38	\$38	\$38
must have W61/W78; not with V52         \$415         \$415         \$415           VC4         Cargo lashing rails, head height         \$415         \$415         \$415           must have V42/C07/86; not with Z66         VC5         Door sill - protective edge         \$71         \$71         \$71           W8         Floor covering, plastic         \$370         \$370         \$370         \$370           K8         Floor covering, plastic         \$370         \$337         \$370         \$370           VV2         Lashing rails, floor level (plus 4 anchors)         \$270         \$345         \$377           must have V43; not with V93/VC5/XE6         \$145         \$145         \$145         \$145         \$145           W12         Lashing rails, floor level (plus 4 anchors)         \$270         \$345         \$377         must have V43; not with V93/VC5/XE6           W12         Lard row, fixed window, driver side         \$145			_		
VC4         Cargo lashing rails, head height         \$415         \$415         \$415           must have V42/CO7/X66; not with ZE6         \$71         \$71         \$71           VC5         Dors Sill- protective edge         \$71         \$71         \$71           WK8         Floor covering, plastic         \$370         \$370         \$370           not with V43/P93/T19/T93/V52/VC5/X66         \$370         \$345         \$377           wst have V43, not with V93/VC5/ZE6         \$345         \$345         \$347           wst floar paint, fised window, griver side         \$145         \$145         \$145         \$145           v16         2nd row, fixed window, passenger side         \$145         \$145         \$145         \$145           w17         2nd row, fixed window, passenger side         \$145         \$145         \$145         \$145           w17         2nd row, fixed window, passenger side         \$145         \$145         \$145         \$145           w17         2nd row, fixed window, passenger side         \$145         \$145         \$145         \$145           w17         2nd row, fixed window, passenger side         \$145         \$145         \$145         \$145           w17         2nd row, fixed window, passenger side         \$145	VA7		\$127	\$127	\$127
Wish have V42/C07/X66; not with 12E6         \$71         \$71         \$71           VCS Door sill - protective edge must have V43/X66; not with T19/793/VK8/VV2/V93/C07         \$71         \$71         \$71           VK8         Floor covering, plastic not with T19/793/VK8/VV2/V93/C07         \$370         \$370         \$370         \$370           VK8         Floor covering, plastic not with V43/P93/V52/VC5/X66         \$270         \$345         \$377           VL2         Lashing ralis, floor level (plus 4 anchors)         \$270         \$345         \$377           W12         Lashing ralis, floor level (plus 4 anchors)         \$270         \$345         \$377           w12         Ladd row, fixed window, driver side if y103 & standard roof CHS production required         \$145			_	Ī	
VCS         Door sill – protective edge         \$71         \$71         \$71           must have V43/X66; not with T19/T93/VK8/VV2/V93/C07         \$370         \$370         \$370         \$370           VK8         Floor covering, plastic         \$370         \$370         \$370           VK8         Floor covering, plastic         \$370         \$345         \$377           must have V43/70 twith V93/VC5/Z66         \$345         \$377         must have V43/10 twith V93/VC5/ZE6           W16         2nd row, fixed window, driver side         \$145 <td< td=""><td>VC4</td><td></td><td>\$415</td><td>\$415</td><td>\$415</td></td<>	VC4		\$415	\$415	\$415
must have V43/X66; not with T19/T93/VK8/VV2/V93/C07           VK8         Floor covering, plastic         \$370         \$370           not with V43/P93/T19/T33/V52/VC5/X66           VV2         Lashing ralls, floor level (plus 4 anchors)         \$270         \$345         \$377           must have V43; not with V93/VC5/ZE6         W12         \$345         \$145         \$145         \$145           W16         2nd row, fixed window, driver side         \$145         \$145         \$145         \$145           W17         2nd row, fixed window, passenger side         \$145         \$145         \$145         \$145           W17         2nd row, fixed window, passenger side         \$145         \$145         \$145         \$145           W17         2nd row, fixed window, passenger side         \$145         \$145         \$145         \$145           W17         2nd row, fixed window, passenger side         \$145         \$145         \$145         \$145         \$145           W17         2nd row, fixed window, passenger side         \$150         \$145         \$145         \$145         \$145         \$145         \$145         \$145         \$145         \$145         \$145         \$145         \$145         \$145         \$145         \$145         \$145         \$145<			_		
VK8         Floor covering, plastic         \$370         \$370         \$370           not with V43/P33/T19/T93/V52/VC5/X66         \$270         \$345         \$377           VV2         Lashing rails, floor level (plus 4 anchors)         \$270         \$345         \$377           must have V43; not with V93/VC5/ZE6         \$145         \$145         \$145         \$145           W16         2nd row, fixed window, driver side         \$145	VC5	Door sill - protective edge	\$71	\$71	\$71
not with V43/P93/T19/T93/V52/VC5/X66         \$270         \$345         \$377           wus have V43; not with V93/VC5/Z66         \$270         \$345         \$377           must have V43; not with V93/VC5/Z66         \$145         \$145         \$145           W16         2nd row, fixed window, driver side         \$145         \$145         \$145           If D93 must have F43+W70; if D93 & standard roof CHS production required         \$145         \$145         \$145           W17         2nd row, fixed window, passenger side         \$145         \$145         \$145           if D93 must have F43+W70; if D93 & standard roof CHS production required         \$145         \$145         \$145           W33         FMVSS 217 emergency exit         \$379         \$379         \$379         \$379         \$379           W34         Rear doors, opening to side wall         \$360         \$360         \$         \$80 </td <td></td> <td></td> <td>_</td> <td></td> <td></td>			_		
VV2         Lashing rails, floor level (plus 4 anchors)         \$270         \$345         \$377           must have V43; not with V93/VCS/ZE6         \$145 <td< td=""><td>VK8</td><td>Floor covering, plastic</td><td>\$370</td><td>\$370</td><td>\$370</td></td<>	VK8	Floor covering, plastic	\$370	\$370	\$370
must have V43; not with V93/VC5/ZE6         \$145         \$145         \$145           W16 2nd row, fixed window, driver side         \$145         \$145         \$145         \$145           If D93 must have F43+W70; if D93 & standard roof CHS production required         \$145         \$145         \$145           W17 2nd row, fixed window, passenger side         \$145         \$145         \$145           If D93 must have F43+W70; if D93 & standard roof CHS production required         \$379         \$379         \$379           W33 FMVSS 217 emergency exit         \$379         \$379         \$379         \$379           must have V31; not with D50/T19/W16         \$360         \$360         \$360         \$5           W5F 90 Degree fixation point- Rear Doors         \$80         \$80         \$80         \$80           S5P 91 Quasibility TBD         \$93         \$93         \$93         \$93         \$93           W70 Black tinting (90%) for rear windows         \$138 </td <td></td> <td></td> <td></td> <td></td> <td></td>					
W16	VV2	Lashing rails, floor level (plus 4 anchors)	\$270	\$345	\$377
If D93 must have F43+W70; if D93 & standard roof CHS production required   S145   \$145   \$145   \$15		must have V43; not with V93/VC5/ZE6			
W17	W16	2nd row, fixed window, driver side	\$145	\$145	\$145
If D93 must have F43+W70; if D93 & standard roof CHS production required   \$379   \$379   \$379   must have V31, not with D50/T19/W16   \$360   \$360   \$5   \$80   \$80   \$80   \$80   \$80   \$80   \$50   \$90   \$		if D93 must have F43+W70; if D93 & standard roof CHS production re	equired		-
W33 FMVSS 217 emergency exit         \$379         \$379         \$379           must have V31, not with D50/T19/W16         \$360         \$360         \$           W54 Rear doors, opening to side wall         \$360         \$360         \$           W5F 90 Degree fixation point- Rear Doors         \$80         \$80         \$80           SoP and Plausibility TBD         \$93         \$93         \$93           W61 Windows in rear doors         \$93         \$93         \$93           must have V47/i JD51 must have F61; not with W78/(W70+-(H22/F02))         \$93         \$93           W70 Black tinting (90%) for rear windows not with W94; must have W16/W17/F02/((W61/W78)+H22); standard with F43/W33/F07         \$187         \$187           W73 Bumper step, rear, grey not with W64/W75/W76         \$187         \$187         \$187           W75 Step, wide, at rear end not with 186/187/Q24/QA9; must have R91+R92         \$308         \$308         \$308           W75 Bumper step, rear, spring-loaded \$601         \$601         \$601         \$601           must have R91+R92; not with 186/187/X30/Q24         \$335         \$335         \$335           W78 Heated rear window(s) w/ washers/wipers         \$335         \$335         \$335           Must have H22+VA7 / if D51 must have F61; not with W61         \$30         \$0         \$0 </td <td>W17</td> <td>2nd row, fixed window, passenger side</td> <td>\$145</td> <td>\$145</td> <td>\$145</td>	W17	2nd row, fixed window, passenger side	\$145	\$145	\$145
must have V31; not with D50/T19/W16           W54         Rear doors, opening to side wall         \$360         \$360         \$80           W5F         90 Degree fixation point- Rear Doors         \$80         \$80         \$80           SoP and Plausibility TBD         \$93         \$93         \$93         \$93           W61         Windows in rear doors         \$93         \$93         \$93           must have VA7/ if D51 must have F61; not with W78/(W70+(H22/F02))         W70         Black tinting (90%) for rear windows         \$138         \$138         \$138           M70         Black tinting (90%) for rear windows         \$138         \$138         \$138           M71         Statinting (90%) for rear windows         \$187         \$187           W72         Black tinting (90%) for rear windows         \$138         \$138           M73         Bumper step, rear, grey         \$187         \$187           not with W94; must have W16/W17/F02/((W61/W78)+H22); standard with F43/W33/F07         \$187         \$187           W75         Step, wide, at rear end         \$308         \$308         \$308           W75         Step, wide, at rear end         \$308         \$308         \$308           W76         Bumper step, rear, spring-loaded         \$601         \$601<		if D93 must have F43+W70; if D93 & standard roof CHS production re	equired		-
W54         Rear doors, opening to side wall         \$360         \$360         \$           W5F         90 Degree fixation point- Rear Doors         \$80         \$80         \$80           SoP and Plausibility TBD         Windows in rear doors         \$93         \$93         \$93           W01         Windows in rear doors         \$93         \$93         \$93           must have VA7/if DS1 must have F61; not with W78/(W70+-(H22/F02))         \$93         \$93           W70         Black tinting (90%) for rear windows         \$138         \$138         \$138           not with W94; must have W16/W17/F02/([W61/W78]+H22]; standard with F43/W33/F07         \$187         \$187         \$187           w73         Bumper step, rear, grey         \$187         \$187         \$187           not with U36/JB7/204/W75/W76         \$308         \$308         \$308           W75         Step, wide at rear end         \$308         \$308         \$308           W75         Step, wide at rear end         \$308         \$308         \$308           W75         Step, wide at rear end         \$308         \$308         \$308           W75         Step, wide at rear end         \$308         \$308         \$308           W75         Step, wide at rear end	W33	FMVSS 217 emergency exit	\$379	\$379	\$379
WSF         90 Degree fixation point- Rear Doors         \$80         \$80           SoP and Plausibility TBD         \$93         \$93         \$93           W61         Windows in rear doors         \$93         \$93         \$93           must have VA7/ if D51 must have F61; not with W78/(W70+-(H22/F02))         with W74/if possible for rear windows         \$138         \$138         \$138         \$138           not with W94; must have W16/W17/F02/((W61/W78)+H22); standard with F43/W33/F07         with R74/W33/F07         \$187		must have V31; not with D50/T19/W16			
SoP and Plausibility TBD	W54	Rear doors, opening to side wall	\$360	\$360	S
W61         Windows in rear doors         \$93         \$93         \$93           must have VA7/ if D51 must have F61; not with W78/(W70+-(H22/F02))           W70         Black tinting (90%) for rear windows         \$138         \$138         \$138           not with W94; must have W16/W17/F02/((W61/W78)+H22); standard with F43/W33/F07         \$187         \$187         \$187           W73         Bumper step, rear, grey         \$187         \$187         \$187           not with Q24/W75/W76         \$308         \$308         \$308           W75         Step, wide, at rear end         \$308         \$308         \$308           not with JB6/JB7/Q24/QA9; must have R91+R92         \$601         \$601         \$601           W76         Bumper step, rear, spring-loaded         \$601         \$601         \$601           must have R91+R92; not with JB6/JB7/X30/Q24         W78         Heated rear window(s) w/ washers/wipers         \$335         \$335         \$335           X90         Deletion of Sprinter badge, left rear door         \$0         \$0         \$0           X91         Deletion of model badge, right rear door         \$0         \$0         \$0           X22         Conversion to RV requirement         \$0         \$0         \$0           X22         S27	W5F	90 Degree fixation point- Rear Doors	\$80	\$80	\$80
must have VA7/ if D51 must have F61; not with W78/(W70+-(H22/F02))           W70         Black tinting (90%) for rear windows         \$138         \$138         \$138           not with W94; must have W16/W17/F02/((W61/W78)+H22); standard with F43/W33/F07           W73         Bumper step, rear, grey         \$187         \$187         \$187           w75         Step, wide, at rear end         \$308         \$308         \$308           not with JB6/JB7/Q24/QA9; must have R91+R92         w76         Bumper step, rear, spring-loaded         \$601         \$601         \$601           must have R91+R92; not with JB6/JB7/X30/Q24         w78         Heated rear window(s) w/ washers/wipers         \$335         \$335         \$335           Must have H22+VA7 / if D51 must have F61; not with W61         w70         \$0         \$0         \$0           X90         Deletion of Sprinter badge, left rear door         \$0         \$0         \$0           X93         Deletion of Psprinter badge, left rear door         \$0         \$0         \$0           X92         Deletion of RV requirement         \$0         \$0         \$0           X22         Conversion to RV requirement         \$0         \$0         \$0           XM4         Acoustic package         \$87         \$87         \$87		SoP and Plausibility TBD			
Black tinting (90%) for rear windows	W61	Windows in rear doors	\$93	\$93	\$93
not with W94; must have W16/W17/F02/((W61/W78)+H22); standard with F43/W33/F07           W73         Bumper step, rear, grey         \$187         \$187         \$187           not with Q24/W75/W76         \$308         \$308         \$308         \$308         \$308           W75         Step, wide, at rear end         \$308         \$308         \$308         \$308           not with JB6/JB7/Q24/QA9; must have R91+R92         word of the property		must have VA7/ if D51 must have F61; not with W78/(W70+-(H22/F0	12))		
W73       Bumper step, rear, grey       \$187       \$187       \$187         not with Q24/W75/W76       \$308       \$308       \$308         W75       Step, wide, at rear end       \$308       \$308       \$308         not with JB6/JB7/Q24/QA9; must have R91+R92       \$601       \$601       \$601         W76       Bumper step, rear, spring-loaded       \$601       \$601       \$601         must have R91+R92; not with JB6/JB7/X30/Q24       \$335       \$335       \$335         W78       Heated rear window(s) w/ washers/wipers       \$335       \$335       \$335         Must have H22+VA7 / if D51 must have F61; not with W61       \$0       \$0       \$0         X90       Deletion of Sprinter badge, left rear door       \$0       \$0       \$0         X93       Deletion of model badge, right rear door       \$0       \$0       \$0         X28       Conversion to RV requirement       \$0       \$0       \$0         must have B01+D93+E1X       XXM4       Acoustic package       \$87       \$87       \$87         X10       First-aid kit       \$27       \$27       \$27         Y26       Wheel chocks       \$38       \$38       \$38         Y45       Emergency flashlight       \$27 <td>W70</td> <td>Black tinting (90%) for rear windows</td> <td>\$138</td> <td>\$138</td> <td>\$138</td>	W70	Black tinting (90%) for rear windows	\$138	\$138	\$138
not with Q24/W75/W76           W75         Step, wide, at rear end         \$308         \$308           not with JB6/JB7/Q24/QA9; must have R91+R92           W76         Bumper step, rear, spring-loaded         \$601         \$601           must have R91+R92; not with JB6/JB7/X30/Q24           W78         Heated rear window(s) w/ washers/wipers         \$335         \$335           Must have H22+VA7 / if D51 must have F61; not with W61           X90         Deletion of Sprinter badge, left rear door         \$0         \$0         \$0           X93         Deletion of model badge, right rear door         \$0         \$0         \$0           X2R         Conversion to RV requirement         \$0         \$0         \$0           x2R         Value have B01+D93+E1X         \$27         \$27         \$27           x2D         Y2D         Y2D         Y2D         Y2D         Y2D <t< td=""><td></td><td>not with W94; must have W16/W17/F02/((W61/W78)+H22); standa</td><td>rd with F43/W</td><td>33/F07</td><td></td></t<>		not with W94; must have W16/W17/F02/((W61/W78)+H22); standa	rd with F43/W	33/F07	
W75       Step, wide, at rear end       \$308       \$308       \$308         not with JB6/JB7/Q24/QA9; must have R91+R92         W76       Bumper step, rear, spring-loaded       \$601       \$601       \$601         must have R91+R92; not with JB6/JB7/X30/Q24       \$335       \$335       \$335         W78       Heated rear window(s) w/ washers/wipers       \$335       \$335       \$335         Must have H22+VA7 / if D51 must have F61; not with W61       \$0       \$0       \$0         X90       Deletion of Sprinter badge, left rear door       \$0       \$0       \$0         X93       Deletion of model badge, right rear door       \$0       \$0       \$0         X2R       Conversion to RV requirement       \$0       \$0       \$0         must have B01+D93+E1X       \$30       \$0       \$0         XM4       Acoustic package       \$87       \$87       \$87         \$10       First-aid kit       \$27       \$27       \$27         Y26       Wheel chocks       \$38       \$38       \$38         Y45       Emergency flashlight       \$27       \$27       \$27         Y68       Paint preservative       \$187       \$212       \$225         Y69       Surface protection	W73	Bumper step, rear, grey	\$187	\$187	\$187
not with JB6/JB7/Q24/QA9; must have R91+R92           W76 Bumper step, rear, spring-loaded         \$601         \$601           must have R91+R92; not with JB6/JB7/X30/Q24           W78 Heated rear window(s) w/ washers/wipers         \$335         \$335           Must have H22+VA7 / if D51 must have F61; not with W61           X90 Deletion of Sprinter badge, left rear door         \$0         \$0         \$0           X93 Deletion of model badge, right rear door         \$0         \$0         \$0           X2R Conversion to RV requirement         \$0         \$0         \$0           must have B01+D93+E1X         XM4         Acoustic package         \$87         \$87         \$87           XM4 Acoustic package         \$87         \$87         \$87         \$87           Y10 First-aid kit         \$27         \$27         \$27           Y26 Wheel chocks         \$38         \$38         \$38           Y45 Emergency flashlight         \$27         \$27         \$27           Y68 Paint preservative         \$187         \$212         \$225           Y69 Surface protection for stock vehicles         \$315         \$315         \$315           YK3 Cargo straps, D-rings         \$81         \$81         \$81           YK4 Cargo straps, lashing rails         \$		not with Q24/W75/W76			
W76       Bumper step, rear, spring-loaded       \$601       \$601       \$601         must have R91+R92; not with JB6/JB7/X30/Q24         W78       Heated rear window(s) w/ washers/wipers       \$335       \$335       \$335         X90       Deletion of Sprinter badge, left rear door       \$0       \$0       \$0         X93       Deletion of model badge, right rear door       \$0       \$0       \$0         X2R       Conversion to RV requirement       \$0       \$0       \$0         must have B01+D93+E1X       XM4       Acoustic package       \$87       \$87       \$87         XM4       Acoustic package       \$87       \$87       \$87         Y10       First-aid kit       \$27       \$27       \$27         Y26       Wheel chocks       \$38       \$38       \$38         Y45       Emergency flashlight       \$27       \$27       \$27         Y68       Paint preservative       \$187       \$212       \$225         Y69       Surface protection for stock vehicles       \$315       \$315       \$315         YK3       Cargo straps, D-rings       \$81       \$81       \$81         YK4       Cargo straps, lashing rails       \$104       \$104       \$104 <td>W75</td> <td>Step, wide, at rear end</td> <td>\$308</td> <td>\$308</td> <td>\$308</td>	W75	Step, wide, at rear end	\$308	\$308	\$308
must have R91+R92; not with JB6/JB7/X30/Q24           W78 Heated rear window(s) w/ washers/wipers         \$335         \$335         \$335           Must have H22+VA7 / if D51 must have F61; not with W61         \$0         \$0         \$0           X90 Deletion of Sprinter badge, left rear door         \$0         \$0         \$0           X93 Deletion of model badge, right rear door         \$0         \$0         \$0           X2R Conversion to RV requirement         \$0         \$0         \$0           Must have B01+D93+E1X         XM4         Acoustic package         \$87         \$87           XM4 Acoustic package         \$87         \$87         \$87           Y10 First-aid kit         \$27         \$27         \$27           Y26 Wheel chocks         \$38         \$38         \$38           Y45 Emergency flashlight         \$27         \$27         \$27           Y68 Paint preservative         \$187         \$212         \$225           Y69 Surface protection for stock vehicles         \$315         \$315         \$315           YK3 Cargo straps, D-rings         \$81         \$81         \$81           YK4 Cargo straps, lashing rails         \$104         \$104         \$104           must have V42/VV2; not with ZE6         \$640         \$6		not with JB6/JB7/Q24/QA9; must have R91+R92			
W78       Heated rear window(s) w/ washers/wipers       \$335       \$335       \$335         Must have H22+VA7 / if D51 must have F61; not with W61         X90       Deletion of Sprinter badge, left rear door       \$0       \$0       \$0         X93       Deletion of model badge, right rear door       \$0       \$0       \$0         X2R       Conversion to RV requirement       \$0       \$0       \$0         must have B01+D93+E1X       XM4       Acoustic package       \$87       \$87       \$87         standard with C02/C03       \$1       \$27 <td< td=""><td>W76</td><td>Bumper step, rear, spring-loaded</td><td>\$601</td><td>\$601</td><td>\$601</td></td<>	W76	Bumper step, rear, spring-loaded	\$601	\$601	\$601
Must have H22+VA7 / if D51 must have F61; not with W61         X90       Deletion of Sprinter badge, left rear door       \$0       \$0       \$0         X93       Deletion of model badge, right rear door       \$0       \$0       \$0         X2R       Conversion to RV requirement       \$0       \$0       \$0         x2R       Conversion to RV requirement       \$0       \$0       \$0         must have B01+D93+E1X       XMM4       Acoustic package       \$87       \$87       \$87         x44       Acoustic package       \$87       \$27       \$27       \$27       \$27       \$27       \$27		must have R91+R92; not with JB6/JB7/X30/Q24			
X90         Deletion of Sprinter badge, left rear door         \$0         \$0         \$0           X93         Deletion of model badge, right rear door         \$0         \$0         \$0           X2R         Conversion to RV requirement         \$0         \$0         \$0           must have B01+D93+E1X         XM4         Acoustic package         \$87         \$87         \$87           XM4         Acoustic package         \$87         \$87         \$87           \$10         First-aid kit         \$27         \$27         \$27           Y26         Wheel chocks         \$38         \$38         \$38           Y45         Emergency flashlight         \$27         \$27         \$27           Y68         Paint preservative         \$187         \$212         \$225           Y69         Surface protection for stock vehicles         \$315         \$315         \$315           YK3         Cargo straps, D-rings         \$81         \$81         \$81           YK4         Cargo straps, lashing rails         \$104         \$104         \$104           must have V42/VV2; not with ZE6         \$640         \$640         \$640	W78	Heated rear window(s) w/ washers/wipers	\$335	\$335	\$335
X93       Deletion of model badge, right rear door       \$0       \$0       \$0         X2R       Conversion to RV requirement       \$0       \$0       \$0         must have B01+D93+E1X       XM4       Acoustic package       \$87       \$87       \$87         standard with C02/C03       Y10       First-aid kit       \$27       \$27       \$27         Y26       Wheel chocks       \$38       \$38       \$38         Y45       Emergency flashlight       \$27       \$27       \$27         Y68       Paint preservative       \$187       \$212       \$225         Y69       Surface protection for stock vehicles       \$315       \$315       \$315         YK3       Cargo straps, D-rings       \$81       \$81       \$81         YK4       Cargo straps, lashing rails       \$104       \$104       \$104         must have V42/VV2; not with ZE6         ZE6       Shelving prep       \$640       \$640       \$640		<del>_</del>			
X2R       Conversion to RV requirement       \$0       \$0         must have B01+D93+E1X         XM4       Acoustic package       \$87       \$87         standard with C02/C03         Y10       First-aid kit       \$27       \$27         Y26       Wheel chocks       \$38       \$38         Y45       Emergency flashlight       \$27       \$27         Y68       Paint preservative       \$187       \$212       \$225         Y69       Surface protection for stock vehicles       \$315       \$315       \$315         YK3       Cargo straps, D-rings       \$81       \$81       \$81         YK4       Cargo straps, lashing rails       \$104       \$104       \$104         must have V42/VV2; not with ZE6         ZE6       Shelving prep       \$640       \$640       \$640	X90	Deletion of Sprinter badge, left rear door	\$0	\$0	\$0
must have B01+D93+E1X         XM4 Acoustic package       \$87       \$87       \$87         standard with C02/C03       \$27       \$27       \$27         Y10 First-aid kit       \$27       \$27       \$27         Y26 Wheel chocks       \$38       \$38       \$38         Y45 Emergency flashlight       \$27       \$27       \$27         Y68 Paint preservative       \$187       \$212       \$225         Y69 Surface protection for stock vehicles       \$315       \$315       \$315         YK3 Cargo straps, D-rings       \$81       \$81       \$81         YK4 Cargo straps, lashing rails       \$104       \$104       \$104         must have V42/VV2; not with ZE6         ZE6 Shelving prep       \$640       \$640       \$640	X93	Deletion of model badge, right rear door	\$0	\$0	\$0
XM4       Acoustic package       \$87       \$87       \$87         standard with CO2/CO3       \$10       \$10       \$27	X2R	Conversion to RV requirement	\$0	\$0	\$0
standard with C02/C03         Y10       First-aid kit       \$27       \$27       \$27         Y26       Wheel chocks       \$38       \$38       \$38         Y45       Emergency flashlight       \$27       \$27       \$27         Y68       Paint preservative       \$187       \$212       \$225         Y69       Surface protection for stock vehicles       \$315       \$315       \$315         YK3       Cargo straps, D-rings       \$81       \$81       \$81         YK4       Cargo straps, lashing rails       \$104       \$104       \$104         must have V42/VV2; not with ZE6         ZE6       Shelving prep       \$640       \$640       \$640		must have B01+D93+E1X			
Y10       First-aid kit       \$27       \$27       \$27         Y26       Wheel chocks       \$38       \$38       \$38         Y45       Emergency flashlight       \$27       \$27       \$27         Y68       Paint preservative       \$187       \$212       \$225         Y69       Surface protection for stock vehicles       \$315       \$315       \$315         YK3       Cargo straps, D-rings       \$81       \$81       \$81         YK4       Cargo straps, lashing rails       \$104       \$104       \$104         must have V42/VV2; not with ZE6         ZE6       Shelving prep       \$640       \$640       \$640	XM4	Acoustic package	\$87	\$87	\$87
Y26       Wheel chocks       \$38       \$38         Y45       Emergency flashlight       \$27       \$27         Y68       Paint preservative       \$187       \$212       \$225         Y69       Surface protection for stock vehicles       \$315       \$315       \$315         YK3       Cargo straps, D-rings       \$81       \$81       \$81         YK4       Cargo straps, lashing rails       \$104       \$104       \$104         must have V42/VV2; not with ZE6         ZE6       Shelving prep       \$640       \$640       \$640		standard with CO2/CO3			
Y45       Emergency flashlight       \$27       \$27       \$27         Y68       Paint preservative       \$187       \$212       \$225         Y69       Surface protection for stock vehicles       \$315       \$315       \$315         YK3       Cargo straps, D-rings       \$81       \$81       \$81         YK4       Cargo straps, lashing rails       \$104       \$104       \$104         must have V42/VV2; not with ZE6         ZE6       Shelving prep       \$640       \$640       \$640	Y10		•	•	
Y68         Paint preservative         \$187         \$212         \$225           Y69         Surface protection for stock vehicles         \$315         \$315         \$315           YK3         Cargo straps, D-rings         \$81         \$81         \$81           YK4         Cargo straps, lashing rails         \$104         \$104         \$104           must have V42/VV2; not with ZE6           ZE6         Shelving prep         \$640         \$640         \$640	Y26				
Y69       Surface protection for stock vehicles       \$315       \$315         YK3       Cargo straps, D-rings       \$81       \$81         YK4       Cargo straps, lashing rails       \$104       \$104         must have V42/VV2; not with ZE6         ZE6       Shelving prep       \$640       \$640	Y45	Emergency flashlight	\$27	\$27	-
YK3       Cargo straps, D-rings       \$81       \$81         YK4       Cargo straps, lashing rails       \$104       \$104         must have V42/VV2; not with ZE6         ZE6       Shelving prep       \$640       \$640	Y68	Paint preservative	\$187	\$212	\$225
YK4       Cargo straps, lashing rails       \$104       \$104         must have V42/VV2; not with ZE6         ZE6       Shelving prep       \$640       \$640	Y69	Surface protection for stock vehicles	\$315	\$315	\$315
must have V42/VV2; not with ZE6           ZE6         Shelving prep         \$640         \$640	YK3	Cargo straps, D-rings	\$81	\$81	\$81
ZE6         Shelving prep         \$640         \$640	YK4	Cargo straps, lashing rails	\$104	\$104	\$104
		must have V42/VV2; not with ZE6			
not with T93/H13/T19/V36/V42/VC4/VK8/VV2/YK4	ZE6	Shelving prep	\$640	\$640	\$640
		not with T93/H13/T19/V36/V42/VC4/VK8/VV2/YK4			

2500 CARGO VAN - 4cyl Diesel Packages

		144" 4C	170" 4C	170" E 4C	
		M2CA44	M2CA74	M2CAE4	
		907.643	907.645	907.647	
C00	Comfort Package	\$300	\$300	\$300	
LC4	Comfort overhead control panel	Х	Х	X	
SE4	Lumbar support, co-driver's seat	Х	Х	X	
SE5	Lumbar support, driver's seat	Х	Х	Х	
SK0	Comfort head restraint, driver	Х	Х	Х	
SK1	Comfort head restraint, co-driver	Х	Х	Х	
S28	Armrest, driver and passenger door	Х	X	X	
must	must have COS OR X68; CA/CC only: not with S23				

COS	Comfort Package (Seat addition)	\$381	\$381	\$381
SB1	Comfort driver's seat	Х	Х	Х
SB2	Comfort passenger seat	Х	Х	Х
must	have COO			

X68	Comfort Plus Package	\$1,923	\$1,923	\$1,923
H15	Heated front passenger seat	X	X	Х
H16	Heated driver's seat	Х	Х	Х
SF1	Driver's seat electrically adjustable	Х	Х	Х
SF2	Co-driver's seat electrically adjustable	Х	Х	Х
must	must have COO and VF4 OR VF6, CA/CC only: not with S23			

C01	Driver Convenience Package	\$760	\$760	\$760
E46	12 V power outlet, driver seat base	X	X	X
F64	Electrically folding exterior mirrors	Х	X	Х
FJ1	Hinged lid for storage compartment	Х	Х	Х
FJ5	Hinged Lid for Storage Compartments left and right	Х	X	Х
FZ9	Keys, two additional masters	Х	Χ	X
JA7	Blind Spot Assist	Х	X	X
JW8	Attention Assist	Х	X	X

C02	Premium Package	\$983	\$983	\$983
CL3	Leather steering wheel	X	X	X
E3M	MBUX Multimedia System with 7" touchscreen	Х	Х	X
FM3	Wet Wiper System	Х	Х	X
JB4	Active Lane Keeping Assist	Х	Х	X
JK5	Instrument cluster with color display	X	X	X

Ordering availability restricted, see NetStar for availability and restrictions|must have JF1 + XM4; must choose FR8/JB7/JB6

CA2	C02 in combination with C03	\$604	\$604	\$604
CL3	Leather steering wheel	Х	X	X
FM3	Wet Wiper System	Х	X	X
JB4	Active Lane Keeping Assist	Х	Х	X
JK5	Instrument cluster with color display	Х	Х	X
Orde	Ordering availability restricted, see NetStar for availability and restrctions must have CO3 + JF1			

2500 CARGO VAN - 4cyl Diesel Packages

144" 4C	170" 4C	170" E 4C
M2CA44	M2CA74	M2CAE4
907.643	907.645	907.647

C03	Premium Plus Package	\$1,793	\$1,793	\$1,793
E1B	Tray for smartphones incl. wireless charging	Х	Х	Х
	Navigation	X	X	Х
EY2	Intelligent navigation	Х	X	Х
E4M	MBUX Multimedia System with 10.25" touchscreen	Χ	Χ	Х
EX9	Free map data updates for 3 years	Χ	X	Х
H1I	Front-to-rear outlet in instrument panel	Χ	X	Х
JA9	Traffic Sign Assist	Χ	X	Х
XM4	Acoustic package	X	X	Х
must	have (CA2+(JB7/JB6/JB8)) OR (JB4+JK5+FM3+(JB7/JB6/JB8)); no	t with FR8 and	C02	

X67	Chrome Grille Package	\$290	\$290	\$290
CN2	Radiator grille frame in vehicle color	Х	X	X
FK3	Chrome plated radiator grille (MB only)	Х	Х	X
no re	no restrictions			

X13	Exterior Lighting Package	\$1,608	\$1,608	\$1,608
L13	Fog lamp with cornering light function	X	Х	Х
L22	Partial LED tail lights	Х	Χ	Х
LA1	High beam assist	Х	Х	Х
LG7	LED high performance headlamps	Х	Х	Х
no re	strictions			

C06	Cargo Convenience Package	\$658	\$658	\$658
E36	Cutoff relay for additional battery	Х	Х	Х
ES2	12 V power outlet, rear compartment	Х	Х	Х
LC2	LED light strip in load compartment	Х	Х	X
T12	Sliding door two stage opening	Х	Х	Х
T85	Assist handle, left rear door	Х	Х	Х
T86	Assist handles, right rear door	Х	Х	Х
W54	Rear doors, opening to side wall	Х	Х	S
must	have T74 OR (T77+D50) OR (T77+D51)	_	_	

C07	Cargo Protection Package	\$1,117	\$1,117	\$1,117				
V25	Half height load compartment trim	Х	X	Х				
V42	Lashing rails, waist level	X	X	Х				
VC4	Cargo lashing rails, head height	X	X	Х				
VK8	Floor covering, plastic	X	X	Х				
YK3	Cargo straps, D-rings	X	X	X				
not v	not with X66							

X66	Heavy-Duty-Cargo Protection Package	\$2,043	\$2,043	\$2,043				
V43	Wood floor with 6 D-rings	X	X	X				
V42	Lashing rails, waist level	X	X	X				
V52	Loadable wheel arch	Х	X	X				
VA3	Side wall paneling full hardboard	Х	X	X				
VC4	Cargo lashing rails, head height	Х	X	X				
VV2	Lashing rails, floor level (plus 4 anchors)	X	X	X				
YK3	Cargo straps, D-rings	Х	X	X				
YK4	Cargo straps, lashing rails	X	X	X				
not v	not with CO7							

Packages

144" 4C	170" 4C	170" E 4C
M2CA44	M2CA74	M2CAE4
907.643	907.645	907.647

X69	(69 Swivel Seat Package \$532 \$532 \$532									
SR8 Swivel base for driver's seat X X X										
SR9	Swivel base for front passenger seat	Х	Х	X						
S87 Driver's seat frame, low X X X										
S88 Passenger seat frame, low X X X										
must	must have (C00+C0S) OR (C00+X68), choose BE2 or B25 (1500/2500 only)									

X01	Suspension Seating Package	\$940	\$940	\$940				
SB3	Driver suspension seat, comfort version	Х	Х	X				
SB4	Passenger suspension seat, comfort version	Х	Х	X				
S87	Driver's seat frame, low	Х	Х	X				
S88	Passenger seat frame, low X X X							
not v	not with C00/C0S/E2I/X68/S23							

170" E 4x4

#### 2500 CARGO VAN - 6cyl Diesel

144" 6C

Standard Equipment

144" 4x4

170" 6C

170" 4x4

170" E 6C

	M2CA46	M2CA4X	M2CA76	M2CA7X	M2CAE6	M2CAEX
	907.643	907.643	907.645	907.645	907.647	907.647
Engine		•				
6-Cyl Engine/7-Speed Trans.	S	S	S	S	S	S
ED4 AGM battery 12V 92 AH 850 A	S	S	S	S	S	S
G42 Automatic transmission, 7G-tronic	S	S	S	S	S	S
MIO ULEV emission	S	S	S	S	S	S
MG5 3.0L V6 turbo diesel engine	S	S	S	S	S	S
M46 Alternator 14 V/220 A	S	S	S	S	S	S
X30 4x4 Package	-	\$8,200	-	\$8,200	-	\$8,200
T75 Door-mounted assist handles, driver & passenger	-	S S	-	S S	_	S
ZG3 4x4 - High range transfer case w/ low gear	-	S	-	S	-	S
Equipment						
AR2 Axle ratio 3.923	S	S	S	S	S	S
BA3 Active Brake Assist	S	S	S	S	S	S
BH1 Hold Function	S	S	S	S	S	S
C6L Multifunction steering wheel	S	S	S	S	S	S
CL1 Adjustable steering wheel (angle)	S	S	S	S	S	S
D03 High roof	-	-	S	S	S	S
D93 Omission bulkhead	S	S	S	S	S	S
E07 Hill Start Assist	S	S	S	S	S	S
E10 Standard radio	S	S	S	S	S	S
E1U USB-C socket, 5 V	S	S	S	S	S	S
E30 Starter battery disconnect	S	S	S	S	S	S
E3J Pre-installation for switch panel	S	-	S	-	S	-
E40 Trailer hitch prep. wiring	S	S	S	S	S	S
ED8 Preinstallation PSM	S	S	S	S	S	S
EE5 Ultracapacitor discharge module	S	S	S	S	S	S
EK1 Body Builder Connector	S	S	S	S	S	S
ESO Jump start terminal	S	S	S	S	S	S
EW6 Pre-installation for Mercedes me Remote Services	S	S	S	S	S	S
EY5 Emergency Call System	S	S	S	S	S	S
EY6 Breakdown management	S	S	S	S	S	S
FF5 Shelf above windshield	S	S	S	S	S	S
FG8 Cupholder front	S	S	S	S	S	S
F68 Heated & electrically adjustable exterior mirrors	S	S	S	S	S	S
FI1 Remote key (315 mhz) w/central locking	S	S	S	S	S	S
FJ4 Storage compartment underneath cockpit	S	S	S	S	S	S
FR3 Rear view camera (rear-view mirror display)	S	S	S	S	S	S
H21 Windshield with filter band	S	S	S	S	S	S
HH2 Heater, auxiliary electric hot air	S	S	S	S	S	S
HH9 Air Condition, Front	S	S	S	S	S	S
IH7 Head Unit, North America	S	S	S	S	S	S
J11 Speedometer, miles and km/h	S	S	S	S	S	S
J55 Seat belt warning for co-driver seat	S	S	S	S	S	S
J58 Seat belt reminder driver	S	S	S	S	S	S
J65 Outside temperature gauge	S	S	S	S	S	S
JA8 Crosswind Assist	S	S	S	S	S	S
JH3 Communication module (LTE) for dig. services	S	S	S	S	S	S
JI9 Service interval 20.000 miles	S	S	S	S	S	S
K56 Red diesel filler cap	S	S	S	S	S	S
K60 Exhaust straight to rear	S	S	S	S	S	S
KB7 24.5 gallon fuel tank	S	S	S	S	S	S
KL1 Aux fuel sending unit w/ fuel tap	S	S	S	S	S	S
KL5 Fuel filter with water separator	S	S	S	S	S	S
KP6 3rd generation SCR emission control system	S	S	S	S	S	S

Standard Equipment

		144" 6C	144'' 4x4	170" 6C	170" 4x4	170" E 6C	170" E 4x4
		M2CA46	M2CA4X	M2CA76	M2CA7X	M2CAE6	M2CAEX
		907.643	907.643	907.645	907.645	907.647	907.647
L65	Interior lights, cargo compartment	S	S	S	S	S	S
L94	Parking lights deletion	S	S	S	S	S	S
LA2	Headlight assistant	S	S	S	S	S	S
LB5	3rd brake light	S	S	S	S	S	S
MS1	Cruise control	S	S	S	S	S	S
P47	Front mudflaps	S	S	S	S	S	S
P48	Rear mudflaps	S	S	S	S	S	S
Q11	Longitudinal member reinforcement	S	S	S	S	S	S
R65	Spare tire bracket below frame	S	S	S	S	S	S
R87	Spare tire	S	S	S	S	S	S
RH8	Tires LT 245/75 R16	S	S	S	S	S	S
RM0	All-season tires	S	S	S	S	S	S
RD9	Unspecified tire brand	S	S	S	S	S	S
RS3	6.5 J x 16 steel wheels	S	S	S	S	S	S
RY2	Tire pressure monitoring sensors	S	S	S	S	S	S
S02	Standard driver seat	S	S	S	S	S	S
S04	Standard front passenger seat	S	S	S	S	S	S
S22	Armrest for driver's seat	S	S	S	S	S	S
S25	Armrest for front passenger seat	S	S	S	S	S	S
SA5	Front airbag, driver	S	S	S	S	S	S
SA6	Front airbag, passenger	S	S	S	S	S	S
SH1	Thorax-pelvis sidebag, driver	S	S	S	S	S	S
SH2	Thorax-pelvis sidebag, co-driver	S	S	S	S	S	S
SH9	Airbag, driver/passenger window	S	S	S	S	S	S
SK2	Seat occupancy sensor, driver's seat	S	S	S	S	S	S
T16	Sliding door, passenger side	S	S	S	S	S	S
V93	Without factory installed flooring	S	S	S	S	S	S
V94	Cable duct - side wall	S	S	S	S	S	S
V95	Cable duct - rear portal	S	S	S	S	S	S
W54	Rear doors, opening to side wall	0	0	0	0	S	S
XL2	GVWR 9,050 lbs. / 4.100 Kg	S	S	S	S	S	S
Y43	Jack, hydraulic	S	S	S	S	S	S

AP2 A		144" 6C M2CA46	144" 4x4 M2CA4X	170" 6C M2CA76	170" 4x4	170" E 6C	170" E 4x4
AP2 A				I IVIZCA/b	M2CA7X	M2CAE6	M2CAEX
AP2 A		907.643	907.643	907.645	907.645	907.647	907.647
AP2 A	Front axle reinforced	\$346		\$346		\$346	
AR3 A	Addtl. bar for driveshaft & exhaust extension	\$69	\$69	\$69	\$69	Ş340 ————————————————————————————————————	-
	Axle ratio 4.182	\$69 \$0	\$09	·	\$09	÷0	-
	ESP for increased Center of Gravity above 39.4"	\$0 \$0	\$0	\$0 \$0	\$0	\$0 \$0	\$0
-	nust have CB4/CB8/X30; not with RH0/CB7	ŞU	<b>\$</b> 0	ŞU	<b>\$</b> 0	ŞU	ŞU
-	Electric parking brake	\$279	\$279	\$279	\$279	\$279	\$279
-	not with BE2; X69 choose B25/BE2	327 <i>3</i>	Ş27 <del>3</del>	3213	3213	Ş27 <del>3</del>	327 <i>9</i>
-	Handbrake lever, folding	\$55	\$55	\$55	\$55	\$55	\$55
-	not with B25; X69 choose B25/BE2	<b>پر</b> ې	<b>پر</b> ې	کردچ	<b>پر</b> ې	کری	<b>پر</b>
	Bumpers front/rear primed	\$268	\$268	\$268	\$268	\$268	\$268
$\vdash$	nust have CN2 (part of X67), not with CM0	\$200	\$200	\$20 <b>0</b>	\$20 <b>6</b>	\$20 <b>6</b>	\$20 <b>6</b>
$\vdash$	Suspension for comfort and load protection	\$241		\$241		\$241	
$\vdash$	Stabilization Level III	\$921	-	\$241	-	\$921	-
	not with CB1/CB7/CB8/X30	3921	-	\$921	-	\$921	
-	Stabilization Level I	\$307	_	\$307		\$307	
-	not with CB4/CB8/X30	\$507	-	\$3U7	-	Ş3U/	-
	Stabilization Level II	\$723	_	\$723	-	\$723	
	not with CB1/CB4/CB7/X30	\$725	-	\$725	-	\$725	-
-		\$252		\$252		\$252	
-	Raised rear body mounts	-	- 6107		- ć107	-	- ć107
-	Leather steering wheel	\$187 \$587	\$187	\$187	\$187	\$187	\$187
-	Painted metallic front & rear bumper	\$587	\$587	\$587	\$587	\$587	\$587
	must have (CN2/X67) + (JA7/C01) + (JB6/JB7) + (7755/9197/9775)	4254	6264	6264	6264	<b>\$254</b>	6264
-	Primed side moldings	\$364	\$364	\$364	\$364	\$364	\$364
$\vdash$	Rear spring vibration absorbers	\$138	\$138	\$138	\$138	\$138	\$138
	High roof	\$2,900	\$2,900	\$	\$	S	S
-	Mounting rails for roof rack	\$300	\$300	\$300	\$300	\$300	\$300
	Fixed sunroof (rear roof section)	\$336	\$336	\$336	\$336	\$336	\$336
-	not with H08/HK4/H72/V36/ZK4	1 4000	1 4000	4000	4222	4000	4000
	Cargo partition	\$288	\$288	\$288	\$288	\$288	\$288
-	not with D51/D93/H08/HK4/T74/V36; must have one of T93/T77	4005	1 4005	4005	4225	4225	4005
	Cargo partition with 1 window	\$335	\$335	\$335	\$335	\$335	\$335
	not with D50/D93/H08/HK4/T74/V37/D17; must have one of T93/T77			4	4	4.75	4.55
	Tray for smartphones incl. wireless charging	\$156	\$156	\$156	\$156	\$156	\$156
-	must have CO2/E3M + H1I	1 4	1 4	4	4	4	4
	Navigation	\$728	\$728	\$728	\$728	\$728	\$728
-	must have CO2/E3M, not with CO3	4	1 4	4	4	4	4
-	Sirius XM, satellite radio	\$255	\$255	\$255	\$255	\$255	\$255
-	must have CO2/E3M/CO3	1 4	1 4	4	4	4	4
-	Additional Fuses (40/80/150/100 Ampere)	\$50	\$50	\$50	\$50	\$50	\$50
	SoP and Plausibility TBD			,			
	Additional Fuses (40/80/80/100 Ampere)	\$50	\$50	\$50	\$50	\$50	\$50
$\vdash$	SoP and Plausibility TBD	1 4-	1 4-	4 -	1-		4 -
-	MBUX multimedia 6-hour runtime	\$0	\$0	\$0	\$0	\$0	\$0
	must have X2R + (C02+E1E/E1S)/C03/(E3M+E1E/E1S)						
	Access point for BB special signals in cockpit	\$29	\$29	\$29	\$29	\$29	\$29
-	Additional battery, co-driver seat base	\$248	\$248	\$248	\$248	\$248	\$248
	nust have E36/C06; not with E2M/F09; CHS production only						
-	Additional battery, engine compartment	\$248	\$248	\$248	\$248	\$248	\$248
	nust have X01+ (E36/C06); not with E2I/X69/F09						
E3M N	MBUX Multimedia System with 7" touchscreen	\$474	\$474	\$474	\$474	\$474	\$474
n	not with C02/C03; must have JK5+(JB7/JB6/JB8/FR8)						
E36 C	Cutoff relay for additional battery	\$110	\$110	\$110	\$110	\$110	\$110
S	tandard with E2I/E2M						
E46 1	12 V power outlet, driver seat base	\$92	\$92	\$92	\$92	\$92	\$92
E5M E	extension of PSM standard contact	\$58	\$58	\$58	\$58	\$58	\$58

MOCAGE   M			144" 6C	144" 4x4	170" 6C	170'' 4x4	170" E 6C	170" E 4x4
Fig.   Parametric special module (PSM)   S317   S								M2CAEX
Description								907.647
Book with EDB	ED5	Parametric special module (PSM)	\$317	\$317	\$317	\$317	\$317	\$317
FEB   15.5   Socket			ψ317	<b>401</b> 7	ψ317	ψ317	ψ31,	ψ31,
Sept	EE3		\$125	\$125	\$125	\$125	\$125	\$125
Security			-		•	•	·	
SSE			_					
E14  Active Distance Assist DISTRONIC   \$263   \$2						·		\$82
This   The Coat Policy   This   Thi				-	·	\$263		\$263
must have DSQ/DSL		must have CO2/CO3/E3M; not with ZH4	· ·		·	·	,	
East   Exertically heated windshield   \$318   \$31	F1K	Coat hooks in driver cabin	\$14	\$14	\$14	\$14	\$14	\$14
Description		must have D50/D51	•					
Food   State	F49	Electrically heated windshield	\$218	\$218	\$218	\$218	\$218	\$218
F64   Electrically folding exterior mirrors   \$49		no restriction	•					
Electrically folding exterior mirrors   \$49   \$49   \$49   \$49   \$49   \$49   \$49   \$49   \$49   \$49   \$49   \$49   \$49   \$49   \$40	F61	Interior rear view mirror	\$36	\$36	\$36	\$36	\$36	\$36
FEP   Additional DIN-stot   S81		not with D50; must have C02/E3M/C03						
FEB	F64	Electrically folding exterior mirrors	\$49	\$49	\$49	\$49	\$49	\$49
FEB		no restriction						
Hinged lid for storage compartment	FE9	Additional DIN-slot	\$81	\$81	\$81	\$81	\$81	\$81
### Rear view camera (head unit display)  ### Security alarm w. interior motion sensor  ### Security alarm w. inte	FF8	Overhead storage slot, front center	\$105	\$105	\$105	\$105	\$105	\$105
Must have CO2/E3M; not with FR3/B3/JB6/JB8	FJ1	Hinged lid for storage compartment	\$93	\$93	\$93	\$93	\$93	\$93
FY1 Security alarm w. interior motion sensor  must have LC4/C00  FY7 Optional "abutton keys	FR8	Rear view camera (head unit display)	\$336	\$336	\$336	\$336	\$336	\$336
must have LC4/C00		must have CO2/E3M; not with FR3/JB7/JB6/JB8						
PT   Optional 3-button keys   \$36	FY1	Security alarm w. interior motion sensor	\$584	\$584	\$584	\$584	\$584	\$584
FZ9   Keys, two additional masters   \$121		must have LC4/C00						
HOO   Warm/cool air duct to rear compartment   S59   S59   S59   S59   S59   S59   S59   Not with DSD/DSJ/PZA	FY7	Optional 3-button keys	\$36	\$36	\$36	\$36	\$36	\$36
Not with D50/D51/Y2A	FZ9	Keys, two additional masters	\$121	\$121	\$121	\$121	\$121	\$121
Heat insulation, rear compartment	H00	Warm/cool air duct to rear compartment	\$59	\$59	\$59	\$59	\$59	\$59
must have V21/V25/VA3/VA1/C07/X66   S187		not with D50/D51/Y2A						
Hotel   Heat insulation, front compartment   \$187	H01	Heat insulation, rear compartment	\$156	\$156	\$156	\$156	\$156	\$156
F D50/D51 must have V07		must have V21/V25/VA3/VA1/C07/X66						
H08   Air conditioning rear, roof-mounted   \$2,872   \$2	H04	Heat insulation, front compartment	\$187	\$187	\$187	\$187	\$187	\$187
must have D93 + V36; not with HK4/C06/X66/C07		if + D50/D51 must have V07						
H12   Fuel-fired pre-heater/booster (17K BTU)   \$1,116	H08	Air conditioning rear, roof-mounted	\$2,872	\$2,872	\$2,872	\$2,872	\$2,872	\$2,872
not with HZ9		must have D93 +V36; not with HK4/C06/X66/C07						
H13   Rear cabin heater and vents   \$786	H12	Fuel-fired pre-heater/booster (17K BTU)	\$1,116	\$1,116	\$1,116	\$1,116	\$1,116	\$1,116
must have H12/H29		not with HZ9						
Heated front passenger seat   \$284	H13	Rear cabin heater and vents	\$786	\$786	\$786	\$786	\$786	\$786
must have H16; not with X68         \$284         \$285         \$253         \$253         \$253         \$253         \$253 <t< td=""><td></td><td>must have H12/HZ9</td><td></td><td></td><td></td><td></td><td></td><td></td></t<>		must have H12/HZ9						
Heated driver's seat	H15	· -	\$284	\$284	\$284	\$284	\$284	\$284
must have H15; not with X68         \$253 <t< td=""><td></td><td>must have H16; not with X68</td><td></td><td></td><td></td><td></td><td></td><td></td></t<>		must have H16; not with X68						
H22   Rear window defroster   \$253	H16	Heated driver's seat	\$284	\$284	\$284	\$284	\$284	\$284
must have W61/W78; standard for W61+W70           H72         Roof fan, electric         \$400 <t< td=""><td></td><td>·</td><td></td><td></td><td></td><td></td><td></td><td></td></t<>		·						
H72   Roof fan, electric   \$400   \$	H22		\$253	\$253	\$253	\$253	\$253	\$253
Not with D22/V36   H88   Rear heater prep   \$405								
H88   Rear heater prep   \$405   \$40	H72		\$400	\$400	\$400	\$400	\$400	\$400
must have H12/HZ9; not with H13/T19         H1I       Front-to-rear outlet in instrument panel       \$0       \$0       \$0       \$0         must have FJ1/C01       HH4       Thermotronic automatic climate control       \$337       \$337       \$337       \$337       \$337         must have JF1; if +H13 must have H08/HK4       HK4       Rear air conditioner, heavyduty       \$3,940								
H11   Front-to-rear outlet in instrument panel   \$0			\$405	\$405	\$405	\$405	\$405	\$405
must have FJ1/C01         HH4       Thermotronic automatic climate control       \$337	-			1				
HH4   Thermotronic automatic climate control   \$337   \$3	H1I	·	\$0	\$0	\$0	\$0	\$0	\$0
must have JF1; if +H13 must have H08/HK4         HK4       Rear air conditioner, heavyduty       \$3,940		-		1				
HK4 Rear air conditioner, heavyduty \$3,940 \$	HH4		\$337	\$337	\$337	\$337	\$337	\$337
must have D03+V36+D93; not with H08/ZB6/ZE6/N62/N63         HZ9       Fuel-fired heater booster (18,000 BTU)       \$676								
HZ9       Fuel-fired heater booster (18,000 BTU)       \$676       \$6	HK4		\$3,940	\$3,940	\$3,940	\$3,940	\$3,940	\$3,940
not with H12         J51       Fuel gauge, optimized for aux. fuel tap       \$72       \$	ļ							
J51 Fuel gauge, optimized for aux. fuel tap \$72 \$72 \$72 \$72 \$72 \$72 \$72 \$72 \$72	HZ9	, , ,	\$676	\$676	\$676	\$676	\$676	\$676
not with HZ9/H12								
			\$72	\$72	\$72	\$72	\$72	\$72
IJ52   Engine oil level display at cold start   \$0   \$0   \$0   \$0   \$0		·		1				
70	J52	Engine oil level display at cold start	\$0	\$0	\$0	\$0	\$0	\$0

MACAGE   MICCAN   M			144" 6C	144" 4x4	170" 6C	170" 4x4	170" E 6C	170" E 4x4
Section   Sect			-					M2CAEX
APT   Blind Spot Assist								907.647
Part								
Math   Active Lane Keeping Assist   \$288	JA/	·	\$450	\$450	\$450	\$450	\$450	\$450
Standard with CDP/CAZ	ID 4	·	¢200	6200	¢200	¢200	¢200	¢200
166	JB4		\$288	\$288	\$288	\$288	\$288	\$288
Parking Face   Self   Parking Face   Self	IDG		¢775	¢775	¢775	¢775	¢775	¢775
	JRP		\$//5	\$775	\$//5	\$775	\$775	\$//5
must have CO2/CO3/CO3/CO3/M, not with WTS/WT6/86   S085	10.7		¢C15	¢C15	ĆC1E	¢C1E	¢C15	ĆC15
188   30 Degree Camera	JB/		\$012	\$012	\$012	\$012	\$012	\$012
Space   Spac	IDO		¢60E	\$60E	¢60E	¢60E	¢695	¢60E
If a min sensor	JDO		\$005	2005	\$005	\$005	\$005	\$005
Note   National Control   State   St	151		\$106	\$106	\$106	\$106	\$106	\$106
ISS   Instrument cluster with color display   \$144   \$14	)LI		\$100	\$100	\$100	\$100	\$100	\$100
Standard with COZ/CA2	IK5		\$144	\$1//	\$1//	\$1 <i>111</i>	\$111	\$144
SP   SP   SP   SP   SP   SP   SP   SP	3//2	. ,	Ş144	<b>Ş144</b>	<b>Ş144</b>	<b>3144</b>	\$1 <del>44</del>	Ş144
SVZ   Deactivation lamp monitoring failure   S27   S	1///0	-	\$99	\$99	\$99	\$99	\$99	\$99
Section   Sect		·						
SET   Misfueling prevention for Diesel   \$49			· ·			· ·	· ·	
S22   DEF fluid filter cap - lockable   \$27						-		
13   Fog lamp with cornering light function			-		-	-	-	-
171   Light/motion sensor in rear compartment   \$54   \$54   \$54   \$54   \$54   \$55	_	·				-		
						-		
B9	L/1		754	754	754	754	754	<del>9</del> 54
CA   Comfort overhead control panel   S93   S94   S9	I R9		\$151	\$151	\$151	\$151	\$151	\$151
CC2   LED light strip in load compartment   \$263			-			-		
			· ·					
M20   Speed limitation 65 mph   S60   S6			7203	7203	<b>7203</b>	7203	7203	7203
NOT	M20	····	\$60	\$60	\$60	\$60	\$60	\$60
MD3   Top speed limitation 75 mph   \$60	11120		Ψ00	\$00	<b>400</b>	700	700	700
Note	MD3		\$60	\$60	\$60	\$60	\$60	\$60
N62   Front engine bracket for additional alternator   S467   S			ΨOO	ΨOO	ψoo	φoo	ΨOO	ψoo
	N62		\$467	\$467	\$467	\$467	\$467	\$467
N63   Front engine bracket for auxiliary A/C compressor   \$467			φ.σ.	ψ	ψ 101	<b>4 107</b>	φ.σ.	<b>¥</b> 107
	N63		\$467	\$467	\$467	\$467	\$467	\$467
P93   Omission of D-rings			7	7 101	¥ 151	7 151	Ţ	¥ 101
not with D93/V43/VK8	P93	·	-\$15	-\$15	-\$15	-\$15	-\$15	-\$15
Q24   Trailer hitch, 5,000 lbs   \$147   \$1				, -	, -	, -	, -	, -
not with W73/W75/W76   \$101	Q24		\$147	\$147	\$147	\$147	\$147	\$147
must have Q24/QA2; not with W73/W75/W76           R91 Spare tire deletion         -\$110         \$100 <t< td=""><td></td><td>not with W73/W75/W76</td><td>•</td><td></td><td>·</td><td>·</td><td></td><td></td></t<>		not with W73/W75/W76	•		·	·		
must have Q24/QA2; not with W73/W75/W76           R91 Spare tire deletion         -\$110         \$100 <t< td=""><td>QA9</td><td>Half-sided step rear (for trailer hitch)</td><td>\$101</td><td>\$101</td><td>\$101</td><td>\$101</td><td>\$101</td><td>\$101</td></t<>	QA9	Half-sided step rear (for trailer hitch)	\$101	\$101	\$101	\$101	\$101	\$101
must have R92; not with R87           R92         Spare tire carrier deletion         \$0         \$0         \$0         \$0           must have R91; not with R65         R98         Rims painted jet black         \$81         \$81         \$81         \$81         \$81           not with RL5/RM2         RF1         Tire brand Continental         \$0         \$0         \$0         \$0         \$0           must have RM1 + RM9         RF8         Tire brand Michellin         \$0         \$0         \$0         \$0         \$0           must have RM9; not with RM1         RH0         Tire brand Kumho         \$0         \$0         \$0         \$0         \$0           RL5         Light-alloy wheels 6.5 J x 16         \$906 <td></td> <td></td> <td></td> <td></td> <td>·</td> <td>·</td> <td></td> <td></td>					·	·		
R92         Spare tire carrier deletion         \$0         \$0         \$0         \$0         \$0           must have R91; not with R65         R88         Rims painted jet black         \$81 <t< td=""><td>R91</td><td>Spare tire deletion</td><td>-\$110</td><td>-\$110</td><td>-\$110</td><td>-\$110</td><td>-\$110</td><td>-\$110</td></t<>	R91	Spare tire deletion	-\$110	-\$110	-\$110	-\$110	-\$110	-\$110
must have R91; not with R65           R98 Rims painted jet black         \$81         \$81         \$81         \$81           not with RL5/RM2         \$0         \$0         \$0         \$0         \$0         \$0           RF1 Tire brand Continental         \$0         \$0         \$0         \$0         \$0         \$0           must have RM1 + RM9         \$0         \$0         \$0         \$0         \$0         \$0         \$0           RF8 Tire brand Michelin         \$0 <td< td=""><td></td><td>must have R92; not with R87</td><td>•</td><td></td><td></td><td></td><td>•</td><td></td></td<>		must have R92; not with R87	•				•	
R98   Rims painted jet black   \$81	R92	Spare tire carrier deletion	\$0	\$0	\$0	\$0	\$0	\$0
not with RL5/RM2           RF1 Tire brand Continental         \$0         \$0         \$0         \$0         \$0           must have RM1 + RM9         \$0         \$0         \$0         \$0         \$0         \$0           RF8 Tire brand Michelin         \$0         \$0         \$0         \$0         \$0         \$0           must have RM9; not with RM1         \$0         \$0         \$0         \$0         \$0         \$0           RL5 Light-alloy wheels 6.5 J x 16         \$906 </td <td></td> <td>must have R91; not with R65</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>		must have R91; not with R65						
RF1       Tire brand Continental       \$0	R98	Rims painted jet black	\$81	\$81	\$81	\$81	\$81	\$81
must have RM1 + RM9         \$0 <td></td> <td>not with RL5/RM2</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>		not with RL5/RM2						
RF8         Tire brand Michelin         \$0         \$0         \$0         \$0         \$0           must have RM9; not with RM1         RH0         Tire brand Kumho         \$0         \$0         \$0         \$0         \$0           must have RM9; not with RM1         RL5         Light-alloy wheels 6.5 J x 16         \$906	RF1	Tire brand Continental	\$0	\$0	\$0	\$0	\$0	\$0
must have RM9; not with RM1         \$0 <t< td=""><td></td><td>must have RM1 + RM9</td><td>·</td><td>· ————</td><td></td><td></td><td></td><td></td></t<>		must have RM1 + RM9	·	· ————				
RHO         Tire brand Kumho         \$0         \$0         \$0         \$0           must have RM9; not with RM1         RL5 Light-alloy wheels 6.5 J x 16         \$906	RF8	Tire brand Michelin	\$0	\$0	\$0	\$0	\$0	\$0
must have RM9; not with RM1         RL5       Light-alloy wheels 6.5 J x 16       \$906       <		must have RM9; not with RM1						
RL5       Light-alloy wheels 6.5 J x 16       \$906	RH0	Tire brand Kumho	\$0	\$0	\$0	\$0	\$0	\$0
not with RS3/RM2/R98         RM1 M+S winter tires       \$169		must have RM9; not with RM1						
RM1       M+S winter tires       \$169	RL5		\$906	\$906	\$906	\$906	\$906	\$906
must have RF1/RD9; not with RF8/RH0/X31           RM2 Rims painted arctic white         \$81         \$81         \$81         \$81         \$81		not with RS3/RM2/R98						
RM2 Rims painted arctic white \$81 \$81 \$81 \$81 \$81 \$81	RM1	M+S winter tires	\$169	\$169	\$169	\$169	\$169	\$169
		must have RF1/RD9; not with RF8/RH0/X31						
not with R98/RL5	RM2	Rims painted arctic white	\$81	\$81	\$81	\$81	\$81	\$81
		not with R98/RL5						

M2CA46   M2CA4X   M2CA76   M2CA7X   M2CAE6   M2CAEX   907.643   907.645   907.645   907.647   907.647   907.647			144" 6C	1.0.011.00	17011.66	470!! 44	170U F CC	470!! 5 44
				144" 4x4	170" 6C	170" 4x4	170" E 6C	170" E 4x4
IMMO   Specially requested tires   S101								
must have RELIFISERATION out with RDP			907.643	907.643	907.645	907.645	907.647	907.647
\$2.21 Imm front passenger seat \$4.00	RM9	• • •	\$101	\$101	\$101	\$101	\$101	\$101
Section   Sect		must have RF1/RF8/RH0; not with RD9		_			_	
S28	S23	·	\$400	\$400	\$400	\$400	\$400	\$400
\$22 Sat betts crange, driver and front passenger		not with C00/X68/X01		_			_	
## STATE   STA	S28	· -	· ·	\$51	\$51	\$51	\$51	\$51
Separate	S62	Seat belts orange, driver and front passenger	\$32	\$32	\$32	\$32	\$32	\$32
must hove WT, not with COQ/TABLASS			_					
\$277 Storage net, driver's seart backrest \$64 \$64 \$64 \$64 \$64 \$64 \$64 \$64 \$64 \$64	SB9	·	\$238	\$238	\$238	\$238	\$238	\$238
S28   Storage nett, passenger seal backvest   S64   S66			_					
Stating about two stage opening			·		· ·	·		
	SZ8		·					
119   Siding door, driver's side	T12		\$82	\$82	\$82	\$82	\$82	\$82
not with H13/H88/NCS/TE6/H32/W16/F02; if V436 must have D03			T					
TSD   Electric closing assist right sliding door   \$335	T19		\$935	\$935	\$935	\$935	\$935	\$935
must hove D03; not with Ts5/T93   S335   S			•					
Electric closing assist telt silding door   \$335	T50		\$335	\$335	\$335	\$335	\$335	\$335
must have T19 + D03   S831   S332   S320   S320   S322			_					
Section   Sect	T51		\$335	\$335	\$335	\$335	\$335	\$335
First Force   First First   First First First   First Fi			•					
Electric sliding step	T55		\$831	\$831	\$831	\$831	\$831	\$831
Popening limiter electrically operated silding door   \$120   \$1			•					
Teol	T57		\$1,071	\$1,071	\$1,071	\$1,071	\$1,071	\$1,071
must have TSS         \$32         <			•					
T74	T60		\$120	\$120	\$120	\$120	\$120	\$120
must have D93; not with T77         Sopormounted assist handles, driver & passenger         \$59         \$599         \$599         \$599         \$599         \$599         \$599         \$599         \$599         \$599         \$599         \$599         \$599         \$599         \$599         \$599         \$599         \$599         \$599         \$599         \$500         \$502         \$32         \$322         \$322         \$322         \$322         \$322         \$			•					
T75	T74	•	\$32	\$32	\$32	\$32	\$32	\$32
T77         Assist handle w/ partition         \$32 </td <td></td> <td>,</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>		,						
must have D50/D51/D64         \$32								
785         Assist handle, left rear door         \$32         \$3	T77	·	\$32	\$32	\$32	\$32	\$32	\$32
786         Assist handles, right rear door         \$32         \$36         \$360         \$360 <t< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></t<>								
T93         Sliding door right side deletion         \$0         \$0         \$0         \$0         \$0           not with T16/T50/T57/VK8/VCS         VOT Cab rear wall liner         \$360			·		•			
not with T16/T50/T57/VK8/VC5           VOT         Cab rear wall liner         \$360 <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>								
V07         Cab rear wall liner         \$360 <td>T93</td> <td></td> <td>\$0</td> <td>\$0</td> <td><b>\$</b>0</td> <td><b>\$</b>0</td> <td>\$0</td> <td>\$0</td>	T93		\$0	\$0	<b>\$</b> 0	<b>\$</b> 0	\$0	\$0
must have (D50/D51)+F1K; standard with H04         \$661         \$602         \$602         \$602<								
\text{V21} Luxury interior Trim	V07		\$360	\$360	\$360	\$360	\$360	\$360
must have VA5/VA7; not with V52/VA1/VA3         V24       Pallet support in sliding door step       \$96								
V24       Pallet support in sliding door step       \$96 <td>V21</td> <td>·</td> <td>\$661</td> <td>\$661</td> <td>\$661</td> <td>\$661</td> <td>\$661</td> <td>\$661</td>	V21	·	\$661	\$661	\$661	\$661	\$661	\$661
must have (V43/X66)+(D50/D51); not with VK8/V93/C07       V25     Half height load compartment trim     \$201     \$201     \$201     \$201       not with VA1/VA3/VA5/V52/X66       V31     Window pillar trim     \$513     \$513     \$513     \$513       must have V36 + (V21/VA1) + (F02/F03/F07); not with V42       V35     Wheel house covering     \$105     \$105     \$105     \$105       if +V43 must have V25/VA1/VA3; not with V52       V36     Roof trim     \$876     \$876     \$876     \$876     \$876       must have D93; not with D17/D22/H72/L65/L71/LC2/VA3/V42/ZE6/(T93+-D03)/X66/C06/C07       V42     Lashing rails, waist level     \$277     \$277     \$277     \$277     \$277       not with V36/ZE6       V43     Wood floor with 6 D-rings     \$422     \$422     \$422     \$422     \$422       v43     Wood floor with P93/V93/VL4/VK8/C07; standard with D93/H13/V24/V52/VC5/VV2/ZE6       V48     Floor cover behind seat box     \$27     \$27     \$27     \$27     \$27     \$27       must have D93; not with D50/D51/D56/D62/D64/V43/VK5       V4A     Full paneling, right sliding door     \$109     \$109     \$109     \$109     \$109       v4A     Full paneling, right sliding door     \$375     \$375     \$375     \$375     \$37			4	4	4	4	4	4
V25       Half height load compartment trim       \$201 <td>V24</td> <td></td> <td>\$96</td> <td>\$96</td> <td>\$96</td> <td>\$96</td> <td>\$96</td> <td>\$96</td>	V24		\$96	\$96	\$96	\$96	\$96	\$96
not with VA1/VA3/VA5/V52/X66           V31         Window pillar trim         \$513         \$513         \$513         \$513         \$513           must have V36 + (V21/VA1) + (F02/F03/F07); not with V42         V35         Wheel house covering         \$105			4004	4004	4004	4204	4204	4224
V31         Window pillar trim         \$513         \$5105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105         \$105 <td>V25</td> <td></td> <td>\$201</td> <td>\$201</td> <td>\$201</td> <td>\$201</td> <td>\$201</td> <td>\$201</td>	V25		\$201	\$201	\$201	\$201	\$201	\$201
must have V36 + (V21/VA1) + (F02/F03/F07); not with V42         V35       Wheel house covering       \$105       \$105       \$105       \$105         if +V43 must have V25/VA1/VA3; not with V52       \$876	1/24		4542	<b>6542</b>	<b>AF43</b>	<b>6542</b>	<b>6542</b>	<b>6542</b>
V35         Wheel house covering         \$105         \$107         \$107         \$107         \$107         \$107 </td <td>V31</td> <td></td> <td>\$513</td> <td>\$513</td> <td>\$513</td> <td>\$513</td> <td>\$513</td> <td>\$513</td>	V31		\$513	\$513	\$513	\$513	\$513	\$513
if +V43 must have V25/VA1/VA3; not with V52   \$876			4405	4405	4405	4105	44.05	4405
V36         Roof trim         \$876         \$877         \$277         \$277         \$277         \$277         \$277         \$277         \$277         \$277         \$277         \$27         \$27         \$27         \$27         \$27         \$27         \$27         \$27         \$27         \$27         \$27         \$27         \$27 <td>V35</td> <td></td> <td>\$105</td> <td>\$105</td> <td>\$105</td> <td>\$105</td> <td>\$105</td> <td>\$105</td>	V35		\$105	\$105	\$105	\$105	\$105	\$105
must have D93; not with D17/D22/H72/L65/L71/LC2/VA3/V42/ZE6/(T93+-D03)/X66/C06/C07       V42     Lashing rails, waist level     \$277     \$277     \$277     \$277     \$277       not with V36/ZE6     \$422     \$422     \$422     \$422     \$422     \$422       V43     Wood floor with 6 D-rings     \$422     \$422     \$422     \$422     \$422       not with P93/V93/VL4/VK8/C07; standard with D93/H13/V24/V52/VC5/VV2/ZE6       V48     Floor cover behind seat box     \$27     \$27     \$27     \$27     \$27       must have D93; not with D50/D51/D56/D62/D64/V43/VK5       V4A     Full paneling, right sliding door     \$109     \$109     \$109     \$109     \$109       must have D03+T16+V21+VA5+W17; not with T19       V52     Loadable wheel arch     \$375     \$375     \$375     \$375     \$375	V/2.6		4076	4076	4076	4076	4076	4076
V42       Lashing rails, waist level       \$277       \$272       \$422	V36		•	·	\$876	\$876	\$876	\$876
not with V36/ZE6         V43       Wood floor with 6 D-rings       \$422	1//2		_		6277	6277	6077	6277
V43       Wood floor with 6 D-rings       \$422	V42		\$2//	\$277	\$277	\$277	\$277	\$277
not with P93/V93/VL4/VK8/C07; standard with D93/H13/V24/V52/VC5/VV2/ZE6         V48 Floor cover behind seat box       \$27       \$27       \$27       \$27       \$27         must have D93; not with D50/D51/D56/D62/D64/V43/VK5         V4A Full paneling, right sliding door       \$109       \$109       \$109       \$109       \$109         must have D03+T16+V21+VA5+W17; not with T19         V52 Loadable wheel arch       \$375       \$375       \$375       \$375       \$375	1/42	·	6433	¢433	Ć422	Ć422	6422	¢433
V48       Floor cover behind seat box       \$27	V43		·	\$422	\$422	\$422	\$422	\$422
must have D93; not with D50/D51/D56/D62/D64/V43/VK5         V4A       Full paneling, right sliding door       \$109	146			427	407	60-	407	407
V4A       Full paneling, right sliding door       \$109       \$109       \$109       \$109       \$109         must have D03+T16+V21+VA5+W17; not with T19         V52       Loadable wheel arch       \$375       \$375       \$375       \$375       \$375	V48		\$27	\$27	\$27	\$27	\$27	\$27
must have D03+T16+V21+VA5+W17; not with T19         V52       Loadable wheel arch       \$375       \$375       \$375       \$375	1/11		4405	4100	Å4.0C	4.00	4405	4100
V52         Loadable wheel arch         \$375         \$375         \$375         \$375         \$375	V4A		\$109	\$109	\$109	\$109	\$109	\$109
			4	4	A	4	4	42-5
must nave v43/хьь; not witn EL9/v21/v25/v35/vA1/СU/	V52		\$375	\$375	\$375	\$375	\$375	\$375
	<u> </u>	must nave V43/X66; not with EL9/V21/V25/V35/VA1/CU/						

		144" 6C	144" 4x4	170" 6C	170'' 4x4	170" E 6C	170" E 4x4
		M2CA46	M2CA4X	M2CA76	M2CA7X	M2CAE6	M2CAEX
		907.643	907.643	907.645	907.645	907.647	907.647
V85	Cigarette lighter & ash cup, front	\$39	\$39	\$39	\$39	\$39	\$39
	Side wall paneling waist height PVC	\$319	\$319	\$319	\$319	\$319	\$319
	must have VA5/VA7; not with V52	<del>40</del> 20	Ψ020	<del>40</del> 20	<del>40</del> 20	φ010	Ţ0 <u>-</u> 0
VA3	Side wall paneling full hardboard	\$444	\$444	\$444	\$444	\$444	\$444
17.0	not with V36/F02; if T93 must have (D50/D51)	Ψ	Ψ	Ψιιι	Ψιιι	ψ····	Ψιιι
VA5	Full paneling, hinged rear doors	\$38	\$38	\$38	\$38	\$38	\$38
17.5	must have D03+VA7+(W61/W78); not with V25	400	ΨOO	400	<del>-</del>	φοσ	φσσ
VA7	Storage compart. w/ net in rear doors	\$127	\$127	\$127	\$127	\$127	\$127
17.0	must have W61/W78; not with V52	Ψ127	, V12,	Ψ127	Ψ127	Ų12,	<b>γ12</b> ,
VC4	Cargo lashing rails, head height	\$415	\$415	\$415	\$415	\$415	\$415
10.	must have V42/C07/X66; not with ZE6	ψ.123	Ų 113	ψ 123	ψ123	Ų 113	Ų 123
VC5	Door sill - protective edge	\$71	\$71	\$71	\$71	\$71	\$71
100	must have V43/X66; not with T19/T93/VK8/VV2/V93/C07	7/1	J 7/-	Ψ, Ξ	Ψ/ ±	Ψ/1	Ψ/±
VK8	Floor covering, plastic	\$370	\$370	\$370	\$370	\$370	\$370
VICO	not with V43/P93/T19/T93/V52/VC5/X66	<b>4370</b>	ļ <del>2370</del>	<del>4</del> 370	<del>4</del> 370	<del>-</del>	1 2370
VV2	Lashing rails, floor level (plus 4 anchors)	\$270	\$270	\$345	\$345	\$377	\$377
100	must have V43; not with V93/VC5/ZE6	<b>\$270</b>	7270	<del>9</del> 5-5	<del>7</del> 5-75	<i></i>	<b>4377</b>
W16	2nd row, fixed window, driver side	\$145	\$145	\$145	\$145	\$145	\$145
**10	if D93 must have F43+W70; if D93 & standard roof CHS production re		7143	2143	7143	7143	7143
W17	2nd row, fixed window, passenger side	\$145	\$145	\$145	\$145	\$145	\$145
VV 17	if D93 must have F43+W70; if D93 & standard roof CHS production re		7140	\$145	\$145	<b>\$143</b>	7143
W33	FMVSS 217 emergency exit	\$379	\$379	\$379	\$379	\$379	\$379
VV 33	must have V31; not with D50/T19/W16	Ş379 -	\$3/9	Ş3/ <del>3</del>	Ş5/ <del>3</del>	Ş3/9	Ş3/ <del>3</del>
W54	Rear doors, opening to side wall	\$360	\$360	\$360	\$360	S	S
	90 Degree fixation point- Rear Doors	\$80	\$80	\$80	\$80	\$80	\$80
WSF	SoP and Plausibility TBD	300	\$60	\$60	\$60	\$60	\$60
W61	Windows in rear doors	\$93	\$93	\$93	\$93	\$93	L 602
WOI	must have VA7/ if D51 must have F61; not with W78/(W70+-(H22/F0		\$93	\$93	\$93	\$93	\$93
W/70	Black tinting (90%) for rear windows	\$138	\$138	\$138	\$138	\$138	\$138
VV / U				\$120	\$120	\$120	\$120
14/72	not with W94; must have W16/W17/F02/((W61/W78)+H22); standar	\$187	\$187	\$187	\$187	\$187	¢107
W/3	Bumper step, rear, grey not with Q24/W75/W76	\$107	\$107	\$101	\$107	\$107	\$187
\A/7E	Step, wide, at rear end	\$308	¢200	\$308	\$308	\$308	¢200
VV / 3	not with JB6/JB7/Q24/QA9; must have R91+R92	\$300	\$308	\$306	\$306	\$306	\$308
\A/76	Bumper step, rear, spring-loaded	\$601		¢601		¢601	
VV / 6	must have R91+R92; not with JB6/JB7/X30/Q24	\$601	-	\$601	-	\$601	-
14/70	Heated rear window(s) w/ washers/wipers	ćaar	<b>622</b> 5	ćaar	ćaar	ćaar	<b>622</b> 5
VV 78	Must have H22+VA7 / if D51 must have F61; not with W61	\$335	\$335	\$335	\$335	\$335	\$335
X2R	Conversion to RV requirement	ćo	l ćo	ćo	ćo	ćo	¢0
ΛZK	must have B01+D93+E1X	\$0	\$0	\$0	\$0	\$0	\$0
X90	Deletion of Sprinter badge, left rear door	\$0	l ćo	\$0	¢0	\$0	<u>د</u> د ا
-	·	\$0 \$0	\$0 \$0		\$0 \$0		\$0 \$0
X93	Deletion of model badge, right rear door		\$0	\$0	\$0	\$0 \$07	\$0
XM4	Acoustic package	\$87	\$87	\$87	\$87	\$87	\$87
V10	standard with CO2/CO3 First-aid kit	627	¢27	627	627	627	627
Y10		\$27	\$27	\$27	\$27	\$27	\$27
Y26	Wheel chocks	\$38	\$38	\$38	\$38	\$38	\$38
Y45	Emergency flashlight	\$27	\$27	\$27	\$27	\$27	\$27
Y68	Paint preservative	\$187	\$187	\$212	\$212	\$225	\$225
Y69	Surface protection for stock vehicles	\$315	\$315	\$315	\$315	\$315	\$315
YK3	Cargo straps, D-rings	\$81	\$81	\$81	\$81	\$81	\$81
YK4	Cargo straps, lashing rails	\$104	\$104	\$104	\$104	\$104	\$104
	must have V42/VV2; not with ZE6	4045	4645	45.5	40.0	40.45	40.45
ZE6	Shelving prep	\$640	\$640	\$640	\$640	\$640	\$640
	not with T93/H13/T19/V36/V42/VC4/VK8/VV2/YK4						
ZH4	Downhill speed regulation for 4x4	-	\$58	-	\$58	-	\$58
	must have ED5; not with ET4						

#### 2500 CARGO VAN - 6cyl Diesel Packages

		144" 6C	144" 4x4	170" 6C	170'' 4x4	170" E 6C	170" E 4x4
		M2CA46	M2CA4X	M2CA76	M2CA7X	M2CAE6	M2CAEX
		907.643	907.643	907.645	907.645	907.647	907.647
C00	Comfort Package	\$300	\$300	\$300	\$300	\$300	\$300
LC4	Comfort overhead control panel	Х	Х	Х	Х	Х	Х
SE4	Lumbar support, co-driver's seat	Х	Х	Х	Х	Х	Х
SE5	Lumbar support, driver's seat	Х	Х	Х	Х	Х	Х
SK0	Comfort head restraint, driver	Х	Х	Х	Х	Х	Х
SK1	Comfort head restraint, co-driver	Х	Х	Х	Х	Х	Х
S28	Armrest, driver and passenger door	Х	Х	Х	Х	Х	Х
must	have COS OR X68; CA/CC only: not with S23						

COS	Comfort Package (Seat addition)	\$381	\$381	\$381	\$381	\$381	\$381
SB1	Comfort driver's seat	Х	Х	Х	X	Х	Х
SB2	Comfort passenger seat	Х	X	X	X	Х	X
must	have COO						

X68	Comfort Plus Package	\$1,923	\$1,923	\$1,923	\$1,923	\$1,923	\$1,923		
H15	Heated front passenger seat	Х	X	Х	Х	X	X		
H16	Heated driver's seat	Х	Х	Х	X	Х	X		
SF1	Driver's seat electrically adjustable	Х	Х	Х	Х	X	X		
SF2	Co-driver's seat electrically adjustable	Х	Х	X	Х	Х	X		
must	nust have C00 and VF4 OR VF6, CA/CC only: not with S23								

C01	Driver Convenience Package	\$760	\$760	\$760	\$760	\$760	\$760
E46	12 V power outlet, driver seat base	Х	X	Х	Х	X	X
F64	Electrically folding exterior mirrors	Х	X	Х	Х	X	X
FJ1	Hinged lid for storage compartment	Х	X	Х	Х	X	X
FJ5	Hinged Lid for Storage Compartments left and right	Х	X	Х	Х	X	X
FZ9	Keys, two additional masters	Х	X	Х	X	X	X
JA7	Blind Spot Assist	Х	X	Х	X	X	X
JW8	Attention Assist	Х	Х	Х	X	X	X

C02	Premium Package	\$983	\$983	\$983	\$983	\$983	\$983			
CL3	Leather steering wheel	Х	Х	Х	Х	Х	Х			
E3M	MBUX Multimedia System with 7" touchscreen	Х	Х	Х	Х	Х	Х			
FM3	Wet Wiper System	Х	Х	Х	Х	Х	Х			
JB4	Active Lane Keeping Assist	Х	Х	Х	Х	Х	Х			
JK5	Instrument cluster with color display	Х	Х	Х	Х	Х	Х			
Orde	Ordering availability restricted, see NetStar for availability and restrictions   must have JF1 + XM4; must choose FR8/JB7/JB6									

CA2	C02 in combination with C03	\$604	\$604	\$604	\$604	\$604	\$604			
CL3	Leather steering wheel	Х	X	Х	X	X	Х			
FM3	Wet Wiper System	Х	Х	Х	Х	Х	Х			
JB4	Active Lane Keeping Assist	Х	Х	Х	Х	Х	Х			
JK5	Instrument cluster with color display	Х	Х	Х	Х	Х	Х			
Orde	Ordering availability restricted, see NetStar for availability and restrctions   must have CO3 + JF1									

#### 2500 CARGO VAN - 6cyl Diesel Packages

144" 6C	144" 4x4	170" 6C	170'' 4x4	170" E 6C	170" E 4x4
M2CA46	M2CA4X	M2CA76	M2CA7X	M2CAE6	M2CAEX
907.643	907.643	907.645	907.645	907.647	907.647

C03	Premium Plus Package	\$1,793	\$1,793	\$1,793	\$1,793	\$1,793	\$1,793
E1B	Tray for smartphones incl. wireless charging	X	X	Х	Х	Х	X
	Navigation	X	X	Х	Х	Х	X
EY2	Intelligent navigation	Х	Х	Х	Х	Х	Х
E4M	MBUX Multimedia System with 10.25" touchscreen	Х	Х	Х	Х	Х	Х
EX9	Free map data updates for 3 years	Х	Х	Х	Х	Х	Х
H1I	Front-to-rear outlet in instrument panel	Х	Х	Х	Х	Х	X
JA9	Traffic Sign Assist	Х	Х	Х	Х	Х	Х
XM4	Acoustic package	Х	Х	Х	Х	Х	Х
must	have (CA2+(JB7/JB6/JB8)) OR (JB4+JK5+FM3+(JB7/JB6/JB8)); no	ot with FR8 ar	d C02	-		-	

X67	Chrome Grille Package	\$290	\$290	\$290	\$290	\$290	\$290
CN2	Radiator grille frame in vehicle color	Х	X	Х	Х	Х	Х
FK3	Chrome plated radiator grille (MB only)	Х	Х	Х	X	X	Х
no re	strictions						

X13	Exterior Lighting Package	\$1,608	\$1,608	\$1,608	\$1,608	\$1,608	\$1,608		
L13	Fog lamp with cornering light function	Х	X	X	Х	X	Х		
L22	Partial LED tail lights	Х	X	X	Х	X	Х		
LA1	High beam assist	Х	Х	Х	Х	Х	Х		
LG7	LED high performance headlamps	Х	Х	Х	Х	Х	Х		
no re	no restrictions								

C06	Cargo Convenience Package	\$658	\$658	\$658	\$658	\$658	\$658
E36	Cutoff relay for additional battery	Х	Х	Х	Х	Х	Х
ES2	12 V power outlet, rear compartment	Х	X	Х	Х	Х	Х
LC2	LED light strip in load compartment	Х	Х	Х	Х	Х	Х
T12	Sliding door two stage opening	Х	Х	Х	Х	Х	Х
T85	Assist handle, left rear door	Х	Х	Х	Х	Х	Х
T86	Assist handles, right rear door	Х	Х	Х	Х	Х	Х
W54	Rear doors, opening to side wall	Х	Х	Х	Х	S	S
must	have T74 OR (T77+D50) OR (T77+D51)			_	_		

C07	Cargo Protection Package	\$1,117	\$1,117	\$1,117	\$1,117	\$1,117	\$1,117			
V25	Half height load compartment trim	Х	X	X	Х	X	Х			
V42	Lashing rails, waist level	Х	X	X	X	Х	Х			
VC4	Cargo lashing rails, head height	Х	X	X	Χ	Х	X			
VK8	Floor covering, plastic	Х	X	X	X	X	X			
YK3	Cargo straps, D-rings	Х	X	X	X	X	X			
not v	ot with X66									

X66	Heavy-Duty-Cargo Protection Package	\$2,043	\$2,043	\$2,043	\$2,043	\$2,043	\$2,043
V43	Wood floor with 6 D-rings	Х	Х	Х	Х	Х	Х
V42	Lashing rails, waist level	Х	Х	Х	Х	Х	Х
V52	Loadable wheel arch	Х	Х	Х	Х	Х	Х
VA3	Side wall paneling full hardboard	Х	Х	Х	Х	Х	Х
VC4	Cargo lashing rails, head height	X	Х	Х	Х	Х	Х
VV2	Lashing rails, floor level (plus 4 anchors)	Х	Х	Х	Х	Х	Х
YK3	Cargo straps, D-rings	Х	Х	Х	Х	Х	Х
YK4	Cargo straps, lashing rails	Х	Х	Х	Х	Х	Х
not with CO7							

Packages

144" 6C	144" 4x4	170" 6C	170" 4x4	170" E 6C	170" E 4x4
M2CA46	M2CA4X	M2CA76	M2CA7X	M2CAE6	M2CAEX
907.643	907.643	907.645	907.645	907.647	907.647

X69	Swivel Seat Package	\$532	\$532	\$532	\$532	\$532	\$532	
SR8	Swivel base for driver's seat	Х	Х	Х	Х	Х	Х	
SR9	Swivel base for front passenger seat	Х	Х	Х	Х	Х	Х	
S87	Driver's seat frame, low	Х	Х	Х	Х	Х	Х	
S88	Passenger seat frame, low	Х	Х	Х	Х	Х	Х	
must	must have (COO+COS) OR (COO+X68), choose BE2 or B25 (1500/2500 only)							

X01	Suspension Seating Package	\$940	\$940	\$940	\$940	\$940	\$940		
SB3	Driver suspension seat, comfort version	Х	Х	Х	Х	Х	Х		
SB4	Passenger suspension seat, comfort version	Х	Х	Х	Х	Х	Х		
S87	Driver's seat frame, low	Х	Х	Х	Х	Х	Х		
S88	Passenger seat frame, low	Х	Х	Х	Х	Х	Х		
not v	not with C00/C0S/E2I/X68/S23								

Standard Equipment

144" 4C M3CA44 170" 4C

M3CA74

170" E 4C

M3CAE4

		M3CA44	W3CA74	IVI3CAE4
		907.653	907.655	907.657
Engin	•			
	e Engine/7-Speed Trans.	C	C	C
	AGM battery 12V 92 AH 850 A	<b>S</b>	<b>S</b>	<b>S</b>
	Automatic transmission, 7G-tronic	S	S	S
	Alternator 14 V / 200 A	S	S	S
	2.0L 4-cylinder diesel engine	S	S	S
	SULEV emissions	S	S	S
	- choose while ordering	3	3	3
X34	Dual Rear Wheel	<i>\$</i> 0	<i>\$</i> 0	<i>\$</i> 0
	Tires LT 215/85 R16	S	S	S
-	5.5 J x 16 steel wheels	S	S	S
	Unspecified tire brand	S	S	S
	Super Single Tire	\$385	\$385	\$385
	285/65 R 16 C super single tires	,3363 O	<b>9303</b>	,3363 O
			0	
	Steel wheels: 8.5Jx16 Rr; 6.5Jx16 Fr	0		0
	Unspecified tire brand	0	0	0
	Tire pressure monitoring sensors	0	0	0
Equip			<u> </u>	C
AR3	Axle ratio 4.182	S	S	S
BA3	Active Brake Assist	S	S	S
	Hold Function	S	S	S
	Multifunction steering wheel	S	S	S
	Stabilization Level II	S	S	S
CL1	Adjustable steering wheel (angle)	S	S	S
D03	High roof	0	S	S
D93	Omission bulkhead	S	S	S
E07	Hill Start Assist	S	S	S
E10	Standard radio	S	S	S
E1U	USB-C socket, 5 V	S	S	S
	Starter battery disconnect	S	S	S
E3J	Pre-installation for switch panel	S	S	S
	Trailer hitch prep. wiring	S	S	S
ED8	Preinstallation PSM	S	S	S
EE5	Ultracapacitor discharge module	S	S	S
EK1	Body Builder Connector	S	S	S
-	Jump start terminal	S	S	S
EW6	Pre-installation for Mercedes me Remote Services	S	S	S
EY5	Emergency Call System	S	S	S
EY6	Breakdown management	S	S	S
F68	Heated & electrically adjustable exterior mirrors	S	S	S
FF5	Shelf above windshield	S	S	S
FG8	Cupholder front	S	S	S
FI1	Remote key (315 mhz) w/central locking	S	S	S
FJ4	Storage compartment underneath cockpit	S	S	S
FR3	Rear view camera (rear-view mirror display)	S	S	S
H21	Windshield with filter band	S	S	S
HH2	Heater, auxiliary electric hot air	S	S	S
HH9	Air Condition, Front	S	S	S
IH7	Head Unit, North America	S	S	S
J11	Speedometer, miles and km/h	S	S	S
J55	Seat belt warning for co-driver seat	S	S	S
J58	Seat belt reminder driver	S	S	S
J65	Outside temperature gauge	S	S	S
JA8	Crosswind Assist	S	S	S
JH3	Communication module (LTE) for dig. services	S	S	S
JI9	Service interval 20.000 miles	S	S	S
K56	Red diesel filler cap	S	S	S
K60	Exhaust straight to rear	S	S	S

Standard Equipment

		144" 4C	170" 4C	170" E 4C
		M3CA44	M3CA74	M3CAE4
		907.653	907.655	907.657
KB7	24.5 gallon fuel tank	S	S	S
KL1	Aux fuel sending unit w/ fuel tap	S	S	S
KL5	Fuel filter with water separator	S	S	S
KP6	3rd generation SCR emission control system	S	S	S
L65	Interior lights, cargo compartment	S	S	S
L94	Parking lights deletion	S	S	S
LA2	Headlight assistant	S	S	S
LB5	3rd brake light	S	S	S
MS1	Cruise control	S	S	S
P47	Front mudflaps	S	S	S
P48	Rear mudflaps	S	S	S
Q11	Longitudinal member reinforcement	S	S	S
R65	Spare tire bracket below frame	S	S	S
R87	Spare tire	S	S	S
RM0	All-season tires	S	S	S
S02	Standard driver seat	S	S	S
S04	Standard front passenger seat	S	S	S
S22	Armrest for driver's seat	S	S	S
S25	Armrest for front passenger seat	S	S	S
SA5	Front airbag, driver	S	S	S
SA6	Front airbag, passenger	S	S	S
SH1	Thorax-pelvis sidebag, driver	S	S	S
SH2	Thorax-pelvis sidebag, co-driver	S	S	S
SH9	Airbag, driver/passenger window	S	S	S
SK2	Seat occupancy sensor, driver's seat	S	S	S
T16	Sliding door, passenger side	S	S	S
V93	Without factory installed flooring	S	S	S
V94	Cable duct - side wall	S	S	S
V95	Cable duct - rear portal	S	S	S
W54	Rear doors, opening to side wall	0	0	S
XB3	GVWR 9,990 lbs. / 4,531 kg	S	S	S
Y43	Jack, hydraulic	S	S	S

	Γ	144" 4C	170" 4C	170" E 4C
		M3CA44	M3CA74	M3CAE4
		907.653	907.655	907.657
	Front axle reinforced	\$346	\$346	\$346
AP2	Addtl. bar for driveshaft & exhaust extension	\$69	\$69	-
AR2	Axle ratio 3.923	\$0	\$0	\$0
DO1	not with AR3		ćo	ćo
B01	ESP for increased Center of Gravity above 39.4"  must have CB4/CB8/X30; not with RH0/CB7	-	\$0	\$0
BE2	Handbrake lever, folding	\$55	\$55	\$55
BLZ	not with B25; X69 choose B25/BE2	<del>, , , , , , , , , , , , , , , , , , , </del>	<b>333</b>	<b>پ</b> رې
C72	Bumpers front/rear primed	\$268	\$268	\$268
C/Z	must have CN2 (part of X67), not with CM0	7200	7200	<b>3200</b>
C72	Bumpers front/rear primed	\$268	\$268	\$268
C/ Z	must have CN2 (part of X67), not with CM0	<b>7200</b>	<b>7200</b>	<b>\$200</b>
CE8	Raised rear body mounts	\$252	\$252	\$252
	Leather steering wheel	\$187	\$187	\$187
0_0	must have (C02/E3M)/C03 + (ET4/MS1)	Ψ=0:	φ=0;	<b>¥</b> 20;
CM0	Painted metallic front & rear bumper	\$587	\$587	\$587
	must have (CN2/X67) + (JA7/C01) + (JB6/JB7) + (7755/9197/9775)	700.	700	700.
CM9	Primed side moldings	\$364	\$364	\$364
	High roof	\$2,900	S	S
	Mounting rails for roof rack	\$300	\$300	\$300
	Fixed sunroof (rear roof section)	\$336	\$336	\$336
	not with H08/HK4/H72/V36/ZK4	,	,	,
D50	Cargo partition	\$288	\$288	\$288
	not with D51/D93/H08/HK4/T74/V36; must have one of T93/T77		· ·	,
D51	Cargo partition with 1 window	\$335	\$335	\$335
	not with D50/D93/H08/HK4/T74/V37/D17; must have one of T93/T77			•
E1B	Tray for smartphones incl. wireless charging	\$156	\$156	\$156
	must have CO2/E3M + H1I		•	
E1E	Navigation	\$728	\$728	\$728
	must have CO2/E3M, not with CO3		•	
E1S	Sirius XM, satellite radio	\$255	\$255	\$255
	must have CO2/E3M/CO3			
E1R	Additional Fuses (40/80/150/100 Ampere)	\$50	\$50	\$50
	SoP and Plausibility TBD		•	
E1Y	Additional Fuses (40/80/80/100 Ampere)	\$50	\$50	\$50
	SoP and Plausibility TBD			
E1X	MBUX multimedia 6-hour runtime	-	\$0	\$0
	must have X2R + (C02+E1E/E1S)/C03/(E3M+E1E/E1S)			
E2A	Access point for BB special signals in cockpit	\$29	\$29	\$29
E2I	Additional battery, co-driver seat base	\$248	\$248	\$248
	must have E36/C06; not with E2M/F09; CHS production only			
E2M	Additional battery, engine compartment	\$248	\$248	\$248
	must have X01+ (E36/C06); not with E2I/X69/F09			
E3M	MBUX Multimedia System with 7" touchscreen	\$474	\$474	\$474
	not with C02/C03; must have JK5+(JB7/JB6/JB8/FR8)			
E36	Cutoff relay for additional battery	\$110	\$110	\$110
ļ	standard with E2I/E2M			
		\$92	\$92	\$92
	12 V power outlet, driver seat base			
E5M	Extension of PSM standard contact	\$58	\$58	\$58
E5M	Extension of PSM standard contact Parametric special module (PSM)	\$58 \$317	\$58 \$317	\$58 \$317
E5M ED5	Extension of PSM standard contact Parametric special module (PSM) not with ED8	\$317	\$317	\$317
E5M ED5 EE3	Extension of PSM standard contact  Parametric special module (PSM)  not with ED8  115 V socket	\$317 \$125	\$317 \$125	\$317 \$125
E5M ED5 EE3 EP7	Extension of PSM standard contact Parametric special module (PSM) not with ED8  115 V socket Basic electric fitting for rear loudspeakers	\$317 \$125 \$68	\$317 \$125 \$68	\$317 \$125 \$68
E5M ED5 EE3 EP7 ES2	Extension of PSM standard contact  Parametric special module (PSM)  not with ED8  115 V socket  Basic electric fitting for rear loudspeakers  12 V power outlet, rear compartment	\$317 \$125 \$68 \$92	\$317 \$125 \$68 \$92	\$317 \$125 \$68 \$92
E5M ED5	Extension of PSM standard contact Parametric special module (PSM) not with ED8  115 V socket Basic electric fitting for rear loudspeakers	\$317 \$125 \$68	\$317 \$125 \$68	\$317 \$125 \$68

		144" 4C	170" 4C	170" E 4C
		M3CA44	M3CA74	M3CAE4
		907.653	907.655	907.657
	<u></u>			
F1K	Coat hooks in driver cabin	\$14	\$14	\$14
	must have D50/D51			
F49	Electrically heated windshield	\$218	\$218	\$218
	no restriction			
F61	Interior rear view mirror	\$36	\$36	\$36
	not with D50; must have C02/E3M/C03			
FE9	Additional DIN-slot	\$81	\$81	\$81
FF8	Overhead storage slot, front center	\$105	\$105	\$105
FJ1	Hinged lid for storage compartment	\$93	\$93	\$93
FR8	Rear view camera (head unit display)	\$336	\$336	\$336
	must have CO2/E3M; not with FR3/JB7/JB6/JB8			
FY1	Security alarm w. interior motion sensor	\$584	\$584	\$584
	must have LC4/C00			
FY7	Optional 3-button keys	\$36	\$36	\$36
FZ9	Keys, two additional masters	\$121	\$121	\$121
H00	Warm/cool air duct to rear compartment	\$59	\$59	\$59
	not with D50/D51/Y2A			
H01	Heat insulation, rear compartment	\$156	\$156	\$156
	must have V21/V25/VA3/VA1/C07/X66			
H04	Heat insulation, front compartment	\$187	\$187	\$187
	if + D50/D51 must have V07			
H08	Air conditioning rear, roof-mounted	\$2,872	\$2,872	\$2,872
	must have D93 +V36; not with HK4/C06/X66/C07	<del>,</del>		
H12	Fuel-fired pre-heater/booster (17K BTU)	\$1,116	\$1,116	\$1,116
	not with HZ9	•		•
H13	Rear cabin heater and vents	\$786	\$786	\$786
	must have H12/HZ9	•		•
H15	Heated front passenger seat	\$284	\$284	\$284
	must have H16; not with X68		· · · · · · · · · · · · · · · · · · ·	
H16	Heated driver's seat	\$284	\$284	\$284
	must have H15; not with X68		· · · · · · · · · · · · · · · · · · ·	
H22	Rear window defroster	\$253	\$253	\$253
	must have W61/W78; standard for W61+W70		,	
H72	Roof fan, electric	\$400	\$400	\$400
	not with D22/V36	,	·	
H88	Rear heater prep	\$405	\$405	\$405
	must have H12/HZ9; not with H13/T19	,	,	,
H1I	Front-to-rear outlet in instrument panel	\$0	\$0	\$0
	must have FJ1/C01	7.5	7 -	7.5
HH4	Thermotronic automatic climate control	\$337	\$337	\$337
	must have JF1; if +H13 must have H08/HK4	γ337	<b>433</b> 7	<b>4337</b>
НК4	Rear air conditioner, heavyduty	\$3,940	\$3,940	\$3,940
	must have D03+V36+D93; not with H08/ZB6/ZE6/N62/N63	73,340	73,340	\$3,540
HZ9	Fuel-fired heater booster (18,000 BTU)	\$676	\$676	\$676
1125	not with H12	Ş070	<del>\$</del> 070	\$070
J51	Fuel gauge, optimized for aux. fuel tap	\$72	\$72	\$72
131	not with HZ9/H12	<b>پ</b> // 2	<b>۷/</b> ۷	<i>γ</i> /2
J52	Engine oil level display at cold start	\$0	\$0	\$0
JA7	Blind Spot Assist	\$450	\$450	\$450
14/	must have F64; not with C01	<del>34</del> 30	Ş43U	Ş43U
JB4		\$288	\$288	\$288
104	Active Lane Keeping Assist	<b>\$</b> 288	<b>3</b> 200	320ŏ
IDC.	standard with CO2/CA2	6775	6775	A77F
JB6	Parking Package with 360 degree camera	\$775	\$775	\$775
<u> </u>	must have CO2/CO3/E3M; not with W75/W76/JB7	4	40	46.5
JB7	Parking Package	\$615	\$615	\$615
<u> </u>	must have CO2/CO3/E3M; not with W75/W76/JB6			
JB8	360 Degree Camera	\$685	\$685	\$685
	SoP and Plausibility TBD			

		144" 4C	170" 4C	170" E 4C
		M3CA44	M3CA74	M3CAE4
		907.653	907.655	907.657
JF1	Rain sensor	\$106	\$106	\$106
JK5	Instrument cluster with color display	\$144	\$144	\$144
3113	standard with CO2/CA2	9244	7277	7244
JW0	Backup alarm	\$99	\$99	\$99
JW2	Deactivation lamp monitoring failure	\$27	\$27	\$27
JW8	Attention Assist	\$49	\$49	\$49
K51	Misfueling prevention for Diesel	\$49	\$49	\$49
K52	DEF fluid filler cap - lockable	\$27	\$27	\$27
L13	Fog lamp with cornering light function	\$199	\$199	\$199
L71	Light/motion sensor in rear compartment	\$54	\$54	\$54
	not with V36	754	γυ <del>τ</del>	, <del>, , , , , , , , , , , , , , , , , , </del>
LB9	Illuminated front exits	\$151	\$151	\$151
LC2	LED light strip in load compartment	\$263	\$263	\$263
LC2	not with H08/HK4/V36/C06	<b>\$203</b>	7203	7203
LC4	Comfort overhead control panel	\$93	\$93	\$93
M20	Speed limitation 65 mph	\$60	\$60	\$60
14120	not with MD3	טטכָ	<b>900</b>	γoo
MDS	Top speed limitation 75 mph	\$60	\$60	\$60
צטועו	not with M20	\$60	\$60	\$60
N62	Front engine bracket for additional alternator	\$467	\$467	\$467
INOZ		\$467	\$407	\$467
NGO	not with HK4/N63	¢467	¢467	\$467
N63	Front engine bracket for auxiliary A/C compressor	\$467	\$467	\$467
D03	not with HK4/N62	Ć4F	Ć1F	Ć1F
P93	Omission of D-rings	-\$15	-\$15	-\$15
042	not with D93/V43/VK8	¢100	¢400	
QA2	Trailer cross member 7,500 lbs capacity	\$186	\$186	-
040	not with W73/W75/W76/Q24/Q67	¢404	¢101	¢101
QA9	Half-sided step rear (for trailer hitch)	\$101	\$101	\$101
024	must have Q24/QA2; not with W73/W75/W76			64.47
Q24	Trailer hitch, 5,000 lbs	-	-	\$147
D04	not with W73/W75/W76	4440	Ć440	6440
R91	Spare tire deletion	-\$110	-\$110	-\$110
	must have R92; not with R87	40	40	40
R92	Spare tire carrier deletion	\$0	\$0	\$0
	must have R91; not with R65	40.	4	40.
R98	Rims painted jet black	\$81	\$81	\$81
	not with RL5/RM2	4.5	4 -	1 4-
RF1	Tire brand Continental	\$0	\$0	\$0
	must have RM1 + RM9			
RF8	Tire brand Michelin	\$0	\$0	\$0
	must have RM9; not with RM1			
RH0	Tire brand Kumho	\$0	\$0	\$0
	must have RM9; not with RM1			
RM1	M+S winter tires	\$169	\$169	\$169
	must have RF1/RD9; not with RF8/RH0/X31			
RM2	Rims painted arctic white	\$81	\$81	\$81
	not with R98/RL5			
RM9	Specially requested tires	\$101	\$101	\$101
	must have RF1/RF8/RH0; not with RD9			
S23	Twin front passenger seat	\$400	\$400	\$400
	not with C00/X68/X01			
S28	Armrest, driver and passenger door	\$51	\$51	\$51
S62	Seat belts orange, driver and front passenger	\$32	\$32	\$32
	not with S23			
SB9	Driver's seat plus	\$238	\$238	\$238
	must have VF7; not with C00/X68/X69			
SZ7	Storage net, driver's seat backrest	\$64	\$64	\$64
SZ8	Storage net, passenger seat backrest	\$64	\$64	\$64

		144" 4C	170" 4C	170" E 4C
		M3CA44	M3CA74	M3CAE4
		907.653	907.655	907.657
T12	Sliding door two stage opening	\$82	\$82	\$82
	not with T55	4	4	4
T19	Sliding door, driver's side	\$935	\$935	\$935
	not with H13/H88/VC5/ZE6/F43/W16/F02; if +V36 must have D03	1	4	4
T50	Electric closing assist right sliding door	\$335	\$335	\$335
	must have D03; not with T55/T93			
T51	Electric closing assist left sliding door	\$335	\$335	\$335
	must have T19 + D03	4	4	4
T55	Electric sliding door right	\$831	\$831	\$831
	must have D03 + (FY7+T16); not with T12/T50			
T57	Electric sliding step	\$1,071	\$1,071	\$1,071
	must have ED5; not with T93			
T60	Opening limiter electrically operated sliding door	\$120	\$120	\$120
	must have T55			
T74	Assist handle, B-pillar	\$32	\$32	\$32
	must have D93; not with T77			
T75	Door-mounted assist handles, driver & passenger	\$59	\$59	\$59
T77	Assist handle w/ partition	\$32	\$32	\$32
	must have D50/D51/D64			
T85	Assist handle, left rear door	\$32	\$32	\$32
T86	Assist handles, right rear door	\$32	\$32	\$32
T93	Sliding door right side deletion	\$0	\$0	\$0
	not with T16/T50/T57/VK8/VC5			
V07	Cab rear wall liner	\$360	\$360	\$360
	must have (D50/D51)+F1K; standard with H04			
V21	Luxury interior Trim	\$661	\$661	\$661
	must have VA5/VA7; not with V52/VA1/VA3			
V24	Pallet support in sliding door step	\$96	\$96	\$96
	must have (V43/X66)+(D50/D51); not with VK8/V93/C07			
V25	Half height load compartment trim	\$201	\$201	\$201
	not with VA1/VA3/VA5/V52/X66			
V31	Window pillar trim	\$513	\$513	\$513
	must have V36 + (V21/VA1) + (F02/F03/F07); not with V42			
V35	Wheel house covering	\$105	\$105	\$105
	if +V43 must have V25/VA1/VA3; not with V52			
V36	Roof trim	\$876	\$876	\$876
	must have D93; not with D17/D22/H72/L65/L71/LC2/VA3/V42/ZE6/(7	793+-D03)/X66/0	C06/C07	
V42	Lashing rails, waist level	\$277	\$277	\$277
	not with V36/ZE6			
V43	Wood floor with 6 D-rings	\$422	\$422	\$422
	not with P93/V93/VL4/VK8/C07; standard with D93/H13/V24/V52/VC	-	·	
V48	Floor cover behind seat box	\$27	\$27	\$27
	must have D93; not with D50/D51/D56/D62/D64/V43/VK5	·		
V4A	Full paneling, right sliding door	\$109	\$109	\$109
-	not with P93/V93/VL4/VK8/C07; standard with D93/H13/V24/V52/VC		, , ,	
V85	Cigarette lighter & ash cup, front	\$39	\$39	\$39
VA1	Side wall paneling waist height PVC	\$319	\$319	\$319
	must have VA5/VA7; not with V52	70-3	70-3	70-0
VA3	Side wall paneling full hardboard	\$444	\$444	\$444
•,,,	not with V36/F02; if T93 must have (D50/D51)	<b>∀</b> -7-1	Y 111	¥ 1717
VA5	Full paneling, hinged rear doors	\$38	\$38	\$38
۷۸5	must have D03+VA7+(W61/W78); not with V25	730	730	730
VA7	Storage compart. w/ net in rear doors	\$127	\$127	\$127
VA/	must have W61/W78; not with V52	۱۷۲۲	7۲۲/	<b>Ϋ1</b> Ζ /
VC4	Cargo lashing rails, head height	\$415	\$415	\$415
v C+	must have V42/C07/X66; not with ZE6	ጎተፗጋ	ኃላ፤ጋ	ጎተተጋ
VC5	Door sill - protective edge	\$71	\$71	\$71
v CJ	יווכ זווו - או טובענועב בעצב	λ/1	٦/ <u>٦</u>	λ/T
	must have V43/X66; not with T19/T93/VK8/VV2/V93/C07			

		144" 4C	170" 4C	170" E 4C
		M3CA44	M3CA74	M3CAE4
		907.653	907.655	907.657
V// O	Floor covering placking			
VK8	Floor covering, plastic	\$370	\$370	\$370
V / / 2	not with V43/P93/T19/T93/V52/VC5/X66	6270	6245	6277
VV2	Lashing rails, floor level (plus 4 anchors)	\$270	\$345	\$377
	must have V43; not with V93/VC5/ZE6		4	4
W16	2nd row, fixed window, driver side	\$145	\$145	\$145
	if D93 must have F43+W70; if D93 & standard roof CHS production re		4	4
W17	2nd row, fixed window, passenger side	\$145	\$145	\$145
	if D93 must have F43+W70; if D93 & standard roof CHS production re			
W33	FMVSS 217 emergency exit	\$379	\$379	\$379
	must have V31; not with D50/T19/W16	1	1	
	Rear doors, opening to side wall	\$360	\$360	S
W5F	90 Degree fixation point- Rear Doors	\$80	\$80	\$80
	SoP and Plausibility TBD			_
W61	Windows in rear doors	\$93	\$93	\$93
	must have VA7/ if D51 must have F61; not with W78/(W70+-(H22/F02	2))		
W70	Black tinting (90%) for rear windows	\$138	\$138	\$138
	not with W94; must have W16/W17/F02/((W61/W78)+H22); standar	d with F43/W33	P/F07	
W73	Bumper step, rear, grey	\$187	\$187	\$187
	not with Q24/W75/W76			
W75	Step, wide, at rear end	\$308	\$308	\$308
	not with JB6/JB7/Q24/QA9; must have R91+R92			
W76	Bumper step, rear, spring-loaded	-	\$601	\$601
	must have R91+R92; not with JB6/JB7/X30/Q24			
W78	Heated rear window(s) w/ washers/wipers	\$335	\$335	\$335
	Must have H22+VA7 / if D51 must have F61; not with W61			,
X90	Deletion of Sprinter badge, left rear door	\$0	\$0	\$0
X93	Deletion of model badge, right rear door	\$0	\$0	\$0
X2R	Conversion to RV requirement	-	\$0	\$0
	must have B01+D93+E1X	•		•
XM4	Acoustic package	\$87	\$87	\$87
	standard with CO2/CO3			
Y10	First-aid kit	\$27	\$27	\$27
Y26	Wheel chocks	\$38	\$38	\$38
Y45	Emergency flashlight	\$27	\$27	\$27
Y68	Paint preservative	\$187	\$212	\$225
Y69	Surface protection for stock vehicles	\$315	\$315	\$315
YK3	Cargo straps, D-rings	\$81	\$81	\$81
YK4	Cargo straps, lashing rails	\$104	\$104	\$104
	must have V42/VV2; not with ZE6			
ZE6	Shelving prep	\$640	\$640	\$640
<del></del>	not with T93/H13/T19/V36/V42/VC4/VK8/VV2/YK4	<b>+3.0</b>	73.0	73.0
	110 C WIGH 199/1129/129/ V 30/ V 72/ V C4/ V NO/ V V Z/ 1 N4			

Packages

		144" 4C	170" 4C	170" E 4C				
		M3CA44	M3CA74	M3CAE4				
		907.653	907.655	907.657				
C00	Comfort Package	\$300	\$300	\$300				
LC4	Comfort overhead control panel	Х	Х	Х				
SE4	Lumbar support, co-driver's seat	X	X	Х				
SE5	Lumbar support, driver's seat	X	X	X				
SK0	Comfort head restraint, driver	Х	X	X				
SK1	Comfort head restraint, co-driver	Х	X	Х				
S28	Armrest, driver and passenger door	X	X	Х				
must	must have COS OR X68; CA/CC only: not with S23							

COS	Comfort Package (Seat addition)	\$381	\$381	\$381
SB1	Comfort driver's seat	Х	Х	X
SB2	Comfort passenger seat	Х	Х	Х
must	must have COO			

X68	Comfort Plus Package	\$1,923	\$1,923	\$1,923
H15	Heated front passenger seat	X	X	X
H16	Heated driver's seat	Х	Х	X
SF1	Driver's seat electrically adjustable	Х	X	X
SF2	Co-driver's seat electrically adjustable	Х	X	Х
must	must have C00 and VF4 OR VF6, CA/CC only: not with S23			

C01	Driver Convenience Package	\$760	\$760	\$760
E46	12 V power outlet, driver seat base	X	X	X
F64	Electrically folding exterior mirrors	X	X	X
FJ1	Hinged lid for storage compartment	X	X	X
FJ5	Hinged Lid for Storage Compartments left and right	X	X	X
FZ9	Keys, two additional masters	X	X	X
JA7	Blind Spot Assist	X	X	X
JW8	Attention Assist	X	X	X

Premium Package	\$983	\$983	\$983
Leather steering wheel	Х	Х	Х
MBUX Multimedia System with 7" touchscreen	Х	Х	Х
Wet Wiper System	Х	Х	Х
Active Lane Keeping Assist	Х	X	Х
Instrument cluster with color display	Х	X	X
	Leather steering wheel  MBUX Multimedia System with 7" touchscreen  Wet Wiper System  Active Lane Keeping Assist	Leather steering wheel X  MBUX Multimedia System with 7" touchscreen X  Wet Wiper System X  Active Lane Keeping Assist X	Leather steering wheel X X X  MBUX Multimedia System with 7" touchscreen X X X  Wet Wiper System X X X  Active Lane Keeping Assist X X

Ordering availability restricted, see NetStar for availability and restrictions | must have JF1 + XM4; must choose FR8/JB7/JB6

CA2	C02 in combination with C03	\$604	\$604	\$604
CL3	Leather steering wheel	X	X	X
FM3	Wet Wiper System	X	X	Х
JB4	Active Lane Keeping Assist	X	X	X
JK5	Instrument cluster with color display	X	X	X
Orde	Ordering availability restricted, see NetStar for availability and restrctions   must have CO3 + JF1			

Packages

144" 4C	170" 4C	170" E 4C
M3CA44	M3CA74	M3CAE4
907.653	907.655	907.657

C03	Premium Plus Package	\$1,793	\$1,793	\$1,793
E1B	Tray for smartphones incl. wireless charging	X	X	X
	Navigation	X	X	X
EY2	Intelligent navigation	X	X	X
E4M	MBUX Multimedia System with 10.25" touchscreen	X	X	X
EX9	Free map data updates for 3 years	X	Х	X
H1I	Front-to-rear outlet in instrument panel	Х	Х	Х
JA9	Traffic Sign Assist	Х	X	Х
XM4	Acoustic package	X	X	X
must	have (CA2+(JB7/JB6/JB8)) OR (JB4+JK5+FM3+(JB7/JB6/JB8)); no	ot with FR8 and	C02	

X67	Chrome Grille Package	\$290	\$290	\$290	
CN2	Radiator grille frame in vehicle color	X	X	X	
FK3	Chrome plated radiator grille (MB only)	X	X	X	
no re	no restrictions				

X13	Exterior Lighting Package	\$1,608	\$1,608	\$1,608
L13	Fog lamp with cornering light function	X	X	X
L22	Partial LED tail lights	Х	X	X
LA1	High beam assist	Х	Х	X
LG7	LED high performance headlamps	Х	Х	Х
no re	no restrictions			

C06	Cargo Convenience Package	\$658	\$658	\$658
E36	Cutoff relay for additional battery	Х	X	Х
ES2	12 V power outlet, rear compartment	Х	X	Х
LC2	LED light strip in load compartment	Х	X	Х
T12	Sliding door two stage opening	Х	X	Х
T85	Assist handle, left rear door	Х	X	Х
T86	Assist handles, right rear door	Х	X	Х
W54	Rear doors, opening to side wall	Х	X	S
must	have T74 OR (T77+D50) OR (T77+D51)			

C07	Cargo Protection Package	\$1,117	\$1,117	\$1,117
V25	Half height load compartment trim	X	X	Х
V42	Lashing rails, waist level	Х	X	Х
VC4	Cargo lashing rails, head height	Х	X	X
VK8	Floor covering, plastic	X	X	X
YK3	Cargo straps, D-rings	X	X	Х
not w	not with X66			

Packages

144" 4C	170" 4C	170" E 4C
M3CA44	M3CA74	M3CAE4
907.653	907.655	907.657

X66	Heavy-Duty-Cargo Protection Package	\$2,043	\$2,043	\$2,043		
V43	Wood floor with 6 D-rings	Х	Х	Х		
V42	Lashing rails, waist level	Х	Х	Х		
VA3	Side wall paneling full hardboard	Х	Х	Х		
VC4	Cargo lashing rails, head height	Х	Х	Х		
VV2 Lashing rails, floor level (plus 4 anchors) X X X						
YK3 Cargo straps, D-rings X X X						
YK4	/K4 Cargo straps, lashing rails X X X					
not v	vith CO7					

X69	Swivel Seat Package	\$532	\$532	\$532
SR8	Swivel base for driver's seat	X	X	X
SR9	Swivel base for front passenger seat	Х	Х	Х
S87	Driver's seat frame, low	Х	Х	Х
S88 Passenger seat frame, low X X X				
must	must have (C00+C0S) OR (C00+X68), choose BE2 or B25 (1500/2500 only)			

X01	Suspension Seating Package	\$940	\$940	\$940
SB3	Driver suspension seat, comfort version	Х	X	X
SB4	Passenger suspension seat, comfort version	Х	Х	X
S87	Driver's seat frame, low	Х	Х	Х
S88 Passenger seat frame, low X X		Х		
not v	ot with C00/C0S/E2I/X68/S23			

Standard Equipment

144" 6C	170" 6C	170" E 6C
M3CA46	M3CA76	M3CAE6
907.653	907.655	907.657

Engin	e e			
_	Engine/7-Speed Trans.	S	S	S
	AGM battery 12V 92 AH 850 A	S	S	S
	Automatic transmission, 7G-tronic	S	S	S
MI0	ULEV emission	S	S	S
_	3.0L V6 turbo diesel engine	S	S	S
	Alternator 14 V/220 A	S	S	S
	choose while ordering	3	3	3
X34	Dual Rear Wheel	<i>\$0</i>	<i>\$</i> 0	ćo
	Tires LT 215/85 R16			<b>\$0</b>
	5.5 J x 16 steel wheels	S	S	S
		S S	S S	S S
RD9	Unspecified tire brand	_		
X31	Super Single Tire	\$385	\$385	\$385
R9A	285/65 R 16 C super single tires	0	0	0
	Steel wheels: 8.5Jx16 Rr; 6.5Jx16 Fr	0	0	0
RD9	Unspecified tire brand	0	0	0
RY2	Tire pressure monitoring sensors	0	0	0
Equip				
	Axle ratio 4.182	S	S	S
BA3	Active Brake Assist	S	S	S
	Hold Function	S	S	S
C6L	Multifunction steering wheel	S	S	S
	Stabilization Level II	S	S	S
CL1	Adjustable steering wheel (angle)	S	S	S
	High roof	0	S	S
D93	Omission bulkhead	S	S	S
E07	Hill Start Assist	S	S	S
E10	Standard radio	S	S	S
E1U	USB-C socket, 5 V	S	S	S
E30	Starter battery disconnect	S	S	S
E3J	Pre-installation for switch panel	S	S	S
E40	Trailer hitch prep. wiring	S	S	S
ED8	Preinstallation PSM	S	S	S
EE5	Ultracapacitor discharge module	S	S	S
EK1	Body Builder Connector	S	S	S
ES0	Jump start terminal	S	S	S
EW6	Pre-installation for Mercedes me Remote Services	S	S	S
EY5	Emergency Call System	S	S	S
EY6	Breakdown management	S	S	S
FF5	Shelf above windshield	S	S	S
F68	Heated & electrically adjustable exterior mirrors	S	S	S
FG8	Cupholder front	S	S	S
FI1	Remote key (315 mhz) w/central locking	S	S	S
FJ4	Storage compartment underneath cockpit	S	S	S
FR3	Rear view camera (rear-view mirror display)	S	S	S
H21	Windshield with filter band	S	S	S
HH2	Heater, auxiliary electric hot air	S	S	S
HH9	Air Condition, Front	S	S	S
IH7	Head Unit, North America	S	S	S
J11	Speedometer, miles and km/h	S	S	S
J55	Seat belt warning for co-driver seat	S	S	S
J58	Seat belt reminder driver	S	S	S
J65	Outside temperature gauge	S	S	S
JA8	Crosswind Assist	S	S	S
JH3	Communication module (LTE) for dig. services	S	S	S
JI9	Service interval 20.000 miles	S	S	S
K56	Red diesel filler cap	S	S	S
K60	Exhaust straight to rear	S	S	S

#### **3500 CARGO VAN - 6cyl Diesel** Standard Equipment

		144" 6C	170" 6C	170" E 6C
		M3CA46	M3CA76	M3CAE6
		907.653	907.655	907.657
KB7	24.5 gallon fuel tank	S	S	S
KL1	Aux fuel sending unit w/ fuel tap	S	S	S
KL5	Fuel filter with water separator	S	S	S
KP6	3rd generation SCR emission control system	S	S	S
L65	Interior lights, cargo compartment	S	S	S
L94	Parking lights deletion	S	S	S
LA2	Headlight assistant	S	S	S
LB5	3rd brake light	S	S	S
MS1	Cruise control	S	S	S
P47	Front mudflaps	S	S	S
P48	Rear mudflaps	S	S	S
Q11	Longitudinal member reinforcement	S	S	S
R65	Spare tire bracket below frame	S	S	S
R87	Spare tire	S	S	S
RM0	All-season tires	S	S	S
S02	Standard driver seat	S	S	S
S04	Standard front passenger seat	S	S	S
S22	Armrest for driver's seat	S	S	S
S25	Armrest for front passenger seat	S	S	S
SA5	Front airbag, driver	S	S	S
SA6	Front airbag, passenger	S	S	S
SH1	Thorax-pelvis sidebag, driver	S	S	S
SH2	Thorax-pelvis sidebag, co-driver	S	S	S
SH9	Airbag, driver/passenger window	S	S	S
SK2	Seat occupancy sensor, driver's seat	S	S	S
T16	Sliding door, passenger side	S	S	S
V93	Without factory installed flooring	S	S	S
V94	Cable duct - side wall	S	S	S
V95	Cable duct - rear portal	S	S	S
W54	Rear doors, opening to side wall	0	0	S
XB3	GVWR 9,990 lbs. / 4,531 kg	S	S	S
Y43	Jack, hydraulic	S	S	S

		144" 6C	170" 6C	170" Ext.6C
		M3CA46	M3CA76	M3CAE6
		907.653	907.655	907.657
A50	Front axle reinforced	\$346	\$346	\$346
AP2	Addtl. bar for driveshaft & exhaust extension	\$69	\$69	-
AR2	Axle ratio 3.923	\$03	\$0	\$0
AILE	not with AR3	70	ŲΨ	ŲΨ
B01	ESP for increased Center of Gravity above 39.4"	-	\$0	\$0
	must have CB4/CB8/X30; not with RH0/CB7		ΨS	Ψū
BE2	Handbrake lever, folding	\$55	\$55	\$55
	not with B25; X69 choose B25/BE2	,	,	,
C72	Bumpers front/rear primed	\$268	\$268	\$268
	must have CN2 (part of X67), not with CM0	·		
CB4	Stabilization Level III	\$187	\$187	\$187
	not with CB1/CB7/CB8/X30		•	•
CE8	Raised rear body mounts	\$252	\$252	\$252
CL3	Leather steering wheel	\$187	\$187	\$187
	must have (C02/E3M)/C03 + (ET4/MS1)			
CM0	Painted metallic front & rear bumper	\$587	\$587	\$587
	must have (CN2/X67) + (JA7/C01) + (JB6/JB7) + (7755/9197/9775)			
CM9	Primed side moldings	\$364	\$364	\$364
D03	High roof	\$2,900	S	S
D13	Mounting rails for roof rack	\$300	\$300	\$300
D22	Fixed sunroof (rear roof section)	\$336	\$336	\$336
<u> </u>	not with H08/HK4/H72/V36/ZK4		•	
D50	Cargo partition	\$288	\$288	\$288
	not with D51/D93/H08/HK4/T74/V36; must have one of T93/T77			
D51	Cargo partition with 1 window	\$335	\$335	\$335
	not with D50/D93/H08/HK4/T74/V37/D17; must have one of T93/T77			
E1B	Tray for smartphones incl. wireless charging	\$156	\$156	\$156
-1-	must have CO2/E3M + H1I	4700	4700	4700
E1E	Navigation	\$728	\$728	\$728
F1C	must have CO2/E3M, not with CO3	ĆOFF	ĆOFF	ćarr
E1S	Sirius XM, satellite radio	\$255	\$255	\$255
E1X	must have CO2/E3M/CO3  MBUX multimedia 6-hour runtime	-	\$0	\$0
ETY	must have X2R + (C02+E1E/E1S)/C03/(E3M+E1E/E1S)	-	ŞU	ŞU
E1R	Additional Fuses (40/80/150/100 Ampere)	\$50	\$50	\$50
LIN	SoP and Plausibility TBD	<del>-</del> 550	٥٥ڔ	٥٥ڔ
E1Y	Additional Fuses (40/80/80/100 Ampere)	\$50	\$50	\$50
	SoP and Plausibility TBD	750	750	750
E2A	Access point for BB special signals in cockpit	\$29	\$29	\$29
E2I	Additional battery, co-driver seat base	\$248	\$248	\$248
	must have E36/C06; not with E2M/F09; CHS production only	Ψ <u>2</u> 10	Ψ <u>2</u> 10	Ų2 10
E2M	Additional battery, engine compartment	\$248	\$248	\$248
	must have X01+ (E36/C06); not with E2I/X69/F09	φ= .0	ΨΞ.0	φ= .5
E3M	MBUX Multimedia System with 7" touchscreen	\$474	\$474	\$474
	not with CO2/CO3; must have JK5+(JB7/JB6/JB8/FR8)	, .	,	
E36	Cutoff relay for additional battery	\$110	\$110	\$110
	standard with E2I/E2M	•	, -	, -
E46	12 V power outlet, driver seat base	\$92	\$92	\$92
E5M	Extension of PSM standard contact	\$58	\$58	\$58
ED5	Parametric special module (PSM)	\$317	\$317	\$317
	not with ED8			
EE3	115 V socket	\$125	\$125	\$125
EP7	Basic electric fitting for rear loudspeakers	\$68	\$68	\$68
ES2	12 V power outlet, rear compartment	\$92	\$92	\$92
ES5	Charging package, dashboard	\$82	\$82	\$82
ET4	Active Distance Assist DISTRONIC	\$263	\$263	\$263

F1K   Coat hooks in driver cabin			144" 6C	170" 6C	170" Ext.6C
F1K   Cost hooks in driver cabin					
Fix   Coat hooks in driver cabin					
F49   Electrically heated windshield   S218   S218   S218   No restriction	F41/	Cook has due to dub on sold in			
Executive   Exec	FIK		\$14	\$14	\$14
F61   Interior rear view mirror   \$36	E/10		\$219	\$219	\$218
Interior rear view mirror	F43		Ş216	Ş216	Ş216
FE9   Additional DIN-slot   S81   S83   S33	F61		\$36	\$36	\$36
FE9	101		750	<del>-</del> <del>-</del> <del>-</del> <del>-</del> <del>-</del> <del>-</del> <del>-</del> - <del>-</del> <del>-</del> <del>-</del>	730
FEB   Overhead storage slot, front center   \$105	FE9		\$81	\$81	\$81
F11   Hinged lid for storage compartment				•	·
FR8   Rear view camera (head unit display)   \$336			·		
FYT         Security alarm w. Interior motion sensor         \$584         \$584         \$584           fr7         Optional 3-button keys         \$36         \$36         \$36           F79         Optional 3-button keys         \$36         \$36         \$36           F29         Keys, two additional masters         \$121	FR8		\$336	\$336	\$336
must have LC4/C00		must have CO2/E3M; not with FR3/JB7/JB6/JB8			
F77   Optional 3-button keys   \$36   \$36   \$36   \$36   \$729   \$keys, two additional masters   \$121	FY1	Security alarm w. interior motion sensor	\$584	\$584	\$584
FZ9		must have LC4/C00			
Hoto  Warm/cool air duct to rear compartment	FY7	Optional 3-button keys	\$36	\$36	\$36
	FZ9	Keys, two additional masters	\$121	\$121	\$121
Heat insulation, rear compartment	H00	Warm/cool air duct to rear compartment	\$59	\$59	\$59
		not with D50/D51/Y2A			
Heat insulation, front compartment   \$187	H01		\$156	\$156	\$156
if + D50/D51 must have V07					
### HOS Air conditioning rear, roof-mounted ### S2,872 \$2,872 \$2,872 ### must have D93 *V36; not with HK4/C06/X66/C07 ### H12 Fuel-fired pre-heater/booster (17K BTU) \$1,116 \$1,116 \$1,116 \$1,116 \$1,116 not with H29 ### h13 Rear cabin heater and vents \$786 \$786 \$786 \$786 ### \$284 \$284 \$284 ### \$284 ##	H04		\$187	\$187	\$187
must have D93+V36; not with HK4/C06/X66/C07           H12 Fuel-fired pre-heater/booster (17K BTU)         \$1,116         \$1,116         \$1,116           not with HZ9         \$786         \$786         \$786         \$786           H13 Rear cabin heater and vents         \$786         \$786         \$786         \$786           must have H12/HZ9         \$284         \$284         \$284         \$284           must have H12/HZ9         \$284         \$284         \$284         \$284           must have H12/HZ9         \$284         \$284         \$284         \$284           must have H16; not with X68         \$284         \$284         \$284         \$284         \$284           must have H15; not with X68         \$253         \$253         \$253         \$253         \$253           must have M12/HX9; not with X68         \$284         \$284         \$284         \$284         \$284           H22 Rear window defroster         \$253         <					
H12   Fuel-fired pre-heater/booster (17K BTU)   \$1,116   \$1,116   not with H29	H08		\$2,872	\$2,872	\$2,872
H13   Rear cabin heater and vents   \$786	1140			4	4
H13   Rear cabin heater and vents   \$786   \$786   \$786   must hove H12/H29   must have H16; not with X68   Heated front passenger seat   \$284   \$284   \$284   must have H16; not with X68   H16   Heated driver's seat   \$284   \$284   \$284   must have H15; not with X68   H22   Rear window defroster   \$253   \$253   \$253   Must have W61/W78; standard for W61+W70   H72   Roof fan, electric   \$400   \$400   \$400   not with D22/V36   Must have H12/H29; not with H13/T19   H11   Front-to-rear outlet in instrument panel   \$0   \$0   \$0   \$0   must have F11/C01   H14   Thermotronic automatic climate control   \$337   \$337   \$337   must have F11/F11   Front-to-rear outlet in instrument panel   \$3,940	H12		\$1,116	\$1,116	\$1,116
must have H12/H29	1112		¢700	ć70 <i>c</i>	¢706
H15   Heated front passenger seat	H13		\$786	\$786	\$786
must have H16; not with X68   \$284   \$284   \$284   \$284   must have H15; not with X68   \$284   \$284   must have H15; not with X68   \$283   \$253   \$	U1E		¢204	¢204	¢204
H16   Heated driver's seat	птэ		\$284	\$284	\$284
must have H15; not with X68         \$253         \$253         \$253           must have W61/W78; standard for W61+W70         \$400         \$400         \$400           H72         Roof fan, electric         \$400         \$400         \$400           not with D22/V36         \$405         \$405         \$405         \$405           H88         Rear heater prep         \$405         \$405         \$405           must have H12/H29; not with H13/T19         \$0         \$0         \$0           H11         Front-to-rear outled in instrument panel         \$0         \$0         \$0           must have F11/C01         \$337         \$337         \$337         \$337           HH4         Thermoric automatic climate control         \$337         \$337         \$337           must have F11/C01         \$337         \$337         \$337         \$337           HK4         Rear air conditioner, heavyduty         \$3,940         \$3,940         \$3,940           must have D03+V36+D93; not with H08/ZB6/ZE6/N62/N63         H29         Fuel-fired heater booster (18,000 BTU)         \$676         \$676         \$676           not with H12         Fuel gauge, optimized for aux. fuel tap         \$72         \$72         \$72           152         Fugine oil le	H16		\$284	\$29/	\$29/
H22   Rear window defroster   \$253	1110		<b>γ204</b>	J204	Ş20 <del>4</del>
must have W61/W78; standard for W61+W70           H72         Roof fan, electric         \$400         \$400         \$400           not with D22/V36         \$405         \$405         \$405         \$405           H88         Rear heater prep         \$405         \$405         \$405           must have H12/H29; not with H13/T19         \$405         \$405         \$405           H11         Front-to-rear outlet in instrument panel         \$0         \$0         \$0           must have F11/C01         \$337         \$337         \$337         \$337           HH44         Thermotronic automatic climate control         \$337         \$337         \$337           must have F1; if +H13 must have H08/HK4         \$3,940         \$3,940         \$3,940         \$3,940           HK4         Rear air conditioner, heavyduty         \$3,940         \$3,940         \$3,940           must have D03+V36+D93; not with H08/ZB6/ZE6/N62/N63         \$676         \$676         \$676           HK4         Rear air conditioner, heavyduty         \$3,940         \$3,940         \$3,940           HK4         Rear air conditioner, heavyduty         \$3,940         \$3,940         \$3,940           HK4         Rear air conditioner, heavyduty         \$3,940         \$3,940	H22		\$253	\$253	\$253
H72   Roof fan, electric   \$400   \$			Ų233	Ų233	Ų233
Not with D22/V36   S405   S405   S405   S405   S405   Must have H12/HZ9; not with H13/T19   S405   S405   S405   Must have H12/HZ9; not with H13/T19   S405   S405   S405   Must have H12/HZ9; not with H13/T19   S405   S405   S405   Must have F11/C01   S437   S437   S437   S437   S437   S437   S437   S437   Must have JF1; if +H13 must have H08/HK4   S405	H72		\$400	\$400	\$400
must have H12/HZ9; not with H13/T19           H11         Front-to-rear outlet in instrument panel         \$0         \$0           must have F11/C01         \$337         \$337         \$337           HH4         Thermotronic automatic climate control         \$337         \$337         \$337           must have JF1; if +H13 must have H08/HK4         HK4         Rear air conditioner, heavyduty         \$3,940         \$3,940         \$3,940           HK4         Rear air conditioner, heavyduty         \$3,940         \$3,940         \$3,940           must have D03+V36+D93; not with H08/ZB6/ZE6/N62/N63         \$676         \$676         \$676           HK2         Fuel-fired heater booster (18,000 BTU)         \$676         \$676         \$676           not with H12         \$72         \$72         \$72         \$72           J51         Fuel gauge, optimized for aux. fuel tap         \$72         \$72         \$72           not with H29/H12         \$9         \$0         \$0         \$0           J52         Engine oil level display at cold start         \$0         \$0         \$0           JA7         Blind Spot Assist         \$450         \$450         \$450           JB4         Active Lane Keeping Assist         \$288         \$288         \$28				,	, , , , ,
must have H12/HZ9; not with H13/T19           H11         Front-to-rear outlet in instrument panel         \$0         \$0           must have FJ1/C01         \$337         \$337         \$337           HH4         Thermotronic automatic climate control         \$337         \$337         \$337           must have JF1; if +H13 must have H08/HK4         HK4         Rear air conditioner, heavyduty         \$3,940         \$3,940         \$3,940           HK4         Rear air conditioner, heavyduty         \$3,940         \$3,940         \$3,940           must have D03+V36+D93; not with H08/ZB6/ZE6/N62/N63         \$676         \$676         \$676           HZ9         Fuel-fired heater booster (18,000 BTU)         \$676         \$676         \$676           not with H12         151         Fuel gauge, optimized for aux. fuel tap         \$72         \$72         \$72           J52         Engine oil level display at cold start         \$0         \$0         \$0         \$0           JA7         Blind Spot Assist         \$450         \$450         \$450         \$450           must have F64; not with C01         3450         \$288         \$288         \$288           JB4         Active Lane Keeping Assist         \$288         \$288         \$288           stan	H88		\$405	\$405	\$405
must have FJI/C01           HH4 Thermotronic automatic climate control         \$337         \$337         \$337           must have JF1; if +H13 must have H08/HK4         \$3,940         \$3,940         \$3,940           HK4 Rear air conditioner, heavyduty         \$3,940         \$3,940         \$3,940           must have D03+V36+D93; not with H08/ZB6/ZE6/N62/N63         \$676         \$676         \$676           HZ9 Fuel-fired heater booster (18,000 BTU)         \$676         \$676         \$676           not with H12         \$72         \$72         \$72         \$72           Individual supplies on the model of supplies of supplie		must have H12/HZ9; not with H13/T19	•		•
HH4   Thermotronic automatic climate control   \$337   \$3	H1I	Front-to-rear outlet in instrument panel	\$0	\$0	\$0
must have JF1; if +H13 must have H08/HK4         HK4 Rear air conditioner, heavyduty       \$3,940       \$3,940       \$3,940         must have D03+V36+D93; not with H08/ZB6/ZE6/N62/N63         HZ9 Fuel-fired heater booster (18,000 BTU)       \$676       \$676       \$676         not with H12       \$72       \$72       \$72         J51 Fuel gauge, optimized for aux. fuel tap       \$72       \$72       \$72         not with HZ9/H12       \$0       \$0       \$0         JA7 Blind Spot Assist       \$450       \$450       \$450         must have F64; not with C01       \$288       \$288       \$288         standard with C02/CA2       \$775       \$775       \$775         must have C02/C03/E3M; not with W75/W76/JB7       \$615       \$615       \$615         JB7 Parking Package       \$615       \$685       \$685       \$685		must have FJ1/C01			
HK4       Rear air conditioner, heavyduty       \$3,940       \$3,940       \$3,940         must have D03+V36+D93; not with H08/ZB6/ZE6/N62/N63         HZ9       Fuel-fired heater booster (18,000 BTU)       \$676       \$676       \$676         not with H12       \$72       \$72       \$72       \$72         Inctive Ligange, optimized for aux. fuel tap       \$72 <td< td=""><td>HH4</td><td>Thermotronic automatic climate control</td><td>\$337</td><td>\$337</td><td>\$337</td></td<>	HH4	Thermotronic automatic climate control	\$337	\$337	\$337
must have D03+V36+D93; not with H08/ZB6/ZE6/N62/N63         HZ9 Fuel-fired heater booster (18,000 BTU)       \$676       \$676       \$676         not with H12       \$72       \$72       \$72         J51 Fuel gauge, optimized for aux. fuel tap       \$72       \$72       \$72         not with HZ9/H12       \$0       \$0       \$0       \$0         JA7 Blind Spot Assist       \$450       \$450       \$450         must have F64; not with C01       \$288       \$288       \$288         standard with C02/CA2       \$775       \$775       \$775         must have C02/C03/E3M; not with W75/W76/JB7       \$615       \$615       \$615         JB7 Parking Package       \$615       \$615       \$615         must have C02/C03/E3M; not with W75/W76/JB6       \$685       \$685       \$685		must have JF1; if +H13 must have H08/HK4			
HZ9   Fuel-fired heater booster (18,000 BTU)   \$676   \$6	HK4	Rear air conditioner, heavyduty	\$3,940	\$3,940	\$3,940
Institute					
J51   Fuel gauge, optimized for aux. fuel tap   \$72   \$73   \$73   \$74	HZ9	Fuel-fired heater booster (18,000 BTU)	\$676	\$676	\$676
not with HZ9/H12   J52   Engine oil level display at cold start   \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0					
J52   Engine oil level display at cold start   \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	J51		\$72	\$72	\$72
JA7       Blind Spot Assist       \$450       \$450         must have F64; not with C01  JB4       Active Lane Keeping Assist       \$288       \$288         standard with C02/CA2  JB6       Parking Package with 360 degree camera       \$775       \$775         must have C02/C03/E3M; not with W75/W76/JB7  JB7       Parking Package       \$615       \$615         must have C02/C03/E3M; not with W75/W76/JB6  JB8       360 Degree Camera       \$685       \$685					
must have F64; not with C01         JB4       Active Lane Keeping Assist       \$288       \$288         standard with C02/CA2         JB6       Parking Package with 360 degree camera       \$775       \$775         must have C02/C03/E3M; not with W75/W76/JB7         JB7       Parking Package       \$615       \$615         must have C02/C03/E3M; not with W75/W76/JB6         JB8       360 Degree Camera       \$685       \$685				•	
JB4         Active Lane Keeping Assist         \$288         \$288           standard with CO2/CA2         \$775         \$775           JB6         Parking Package with 360 degree camera         \$775         \$775           must have CO2/CO3/E3M; not with W75/W76/JB7         \$615         \$615           JB7         Parking Package         \$615         \$615           must have CO2/CO3/E3M; not with W75/W76/JB6         \$685         \$685           JB8         360 Degree Camera         \$685         \$685	JA7	·	\$450	\$450	\$450
standard with C02/CA2         JB6       Parking Package with 360 degree camera       \$775       \$775         must have C02/C03/E3M; not with W75/W76/JB7         JB7       Parking Package       \$615       \$615         must have C02/C03/E3M; not with W75/W76/JB6         JB8       360 Degree Camera       \$685       \$685	ID 4		6300	ć200	6200
JB6       Parking Package with 360 degree camera       \$775       \$775         must have C02/C03/E3M; not with W75/W76/JB7         JB7       Parking Package       \$615       \$615         must have C02/C03/E3M; not with W75/W76/JB6         JB8       360 Degree Camera       \$685       \$685	JB4		\$288	\$288	\$288
must have C02/C03/E3M; not with W75/W76/JB7         JB7 Parking Package       \$615       \$615         must have C02/C03/E3M; not with W75/W76/JB6         JB8 360 Degree Camera       \$685       \$685	ID <i>E</i>	*	6775	לחדר	ĆZZE
JB7       Parking Package       \$615       \$615         must have C02/C03/E3M; not with W75/W76/JB6         JB8       360 Degree Camera       \$685       \$685	סמנ		\$//5	\$//5	\$//5
must have C02/C03/E3M; not with W75/W76/JB6         JB8       360 Degree Camera       \$685       \$685	IR7		\$61E	¢61E	\$615
JB8 360 Degree Camera \$685 \$685 \$685	10/		3013	2012	<u> </u>
	IRR		\$685	\$685	\$685
I ISOP and Plausihility TBD	750	SoP and Plausibility TBD	7003	7005	7005

		4.4.511.00	47011.00	47011 5 7 60
		144" 6C		170" Ext.6C
		M3CA46		M3CAE6
		907.653	907.655	907.657
JF1	Rain sensor	\$106	\$106	\$106
JK5	Instrument cluster with color display	\$144	\$144	\$144
	standard with CO2/CA2			
JW0	Backup alarm	\$99	\$99	\$99
JW2	Deactivation lamp monitoring failure	\$27	\$27	\$27
JW8	Attention Assist	\$49	\$49	\$49
K51	Misfueling prevention for Diesel	\$49	\$49	\$49
K52	DEF fluid filler cap - lockable	\$27	\$27	\$27
L13	Fog lamp with cornering light function	\$199	\$199	\$199
L71	Light/motion sensor in rear compartment	\$54	\$54	\$54
	not with V36		\$144 \$99 \$27 \$49 \$49 \$27 \$199 \$54 \$151 \$263 \$93 \$60 \$60 \$467 \$467 -\$15 \$186 \$101 - -\$110 \$0 \$81 \$0 \$169 \$81 \$101	
	Illuminated front exits	\$151		\$151
LC2	LED light strip in load compartment	\$263	\$263	\$263
	not with H08/HK4/V36/C06			
	Comfort overhead control panel	\$93		\$93
M20	Speed limitation 65 mph	\$60	\$60	\$60
	not with MD3			
MD3	Top speed limitation 75 mph	\$60	\$60	\$60
	not with M20			
N62	Front engine bracket for additional alternator	\$467	\$467	\$467
	not with HK4/N63			
N63	Front engine bracket for auxiliary A/C compressor	\$467	\$467	\$467
	not with HK4/N62		,	
P93	Omission of D-rings	-\$15	-\$15	-\$15
	not with D93/V43/VK8		4	
QA2	Trailer cross member 7,500 lbs capacity	\$186	\$186	-
0.40	not with W73/W75/W76/Q24/Q67	4.0.	4.0.	4.5.
QA9	Half-sided step rear (for trailer hitch)	\$101	\$101	\$101
024	must have Q24/QA2; not with W73/W75/W76			64.47
Q24	Trailer hitch, 5,000 lbs	-	-	\$147
DO1	not with W73/W75/W76	¢440	Ć110	Ć110
R91	Spare tire deletion	-\$110	-\$110	-\$110
R92	must have R92; not with R87	ćo	ćo	ćo
K92	Spare tire carrier deletion  must have R91; not with R65	\$0	<b>Ş</b> U	\$0
R98	Rims painted jet black	\$81	Ć01	\$81
1136	not with RL5/RM2	301	201	201
RF1	Tire brand Continental	\$0	¢۸	\$0
IVI T	must have RM1 + RM9	, JO	<b>90</b>	<b>30</b>
RF8	Tire brand Michelin	\$0	ŚŊ	\$0
1410	must have RM9; not with RM1	70	ΨO	70
RH0	Tire brand Kumho	\$0	\$0	\$0
1110	must have RM9; not with RM1	70	ΨO	70
RM1	M+S winter tires	\$169	\$169	\$169
111111	must have RF1/RD9; not with RF8/RH0/X31	7103	7103	\$103
RM2	Rims painted arctic white	\$81	\$81	\$81
	not with R98/RL5	, , , , , , , , , , , , , , , , , , ,	Ψ01	<b>401</b>
RM9	Specially requested tires	\$101	\$101	\$101
	must have RF1/RF8/RH0; not with RD9	¥-0-	<b>4-0-</b>	7-0-
S23	Twin front passenger seat	\$400	\$400	\$400
<del>-</del> -	not with C00/X68/X01	Ţ . <b>00</b>	,	7
S28	Armrest, driver and passenger door	\$51	\$51	\$51
S62	Seat belts orange, driver and front passenger	\$32		\$32
	not with \$23	,		
SB9	Driver's seat plus	\$238	\$238	\$238
	must have VF7; not with C00/X68/X69	, , , , , ,		
SZ7	Storage net, driver's seat backrest	\$64	\$64	\$64
	Storage net, passenger seat backrest	\$64	\$64	\$64

`	:	
,	ptions	
•	Pulling	

		144" 6C	170" 6C	170" Ext.6C
		M3CA46	M3CA76	M3CAE6
		907.653	907.655	907.657
T12	Sliding door two stage opening	\$82	\$82	\$82
112	not with T55	<del>3</del> 62	<b>302</b>	<b>302</b>
T19	Sliding door, driver's side	\$935	\$935	\$935
113	not with H13/H88/VC5/ZE6/F43/W16/F02; if +V36 must have D03	7933	ردود	ردود
T50	Electric closing assist right sliding door	\$335	\$335	\$335
130	must have D03; not with T55/T93	7555	7333	7555
T51	Electric closing assist left sliding door	\$335	\$335	\$335
131	must have T19 + D03	<b>4333</b>	<del>-</del>	<b>†</b> \$333
T55	Electric sliding door right	\$831	\$831	\$831
	must have D03 + (FY7+T16); not with T12/T50	7001	<del>7031</del>	7031
T57	Electric sliding step	\$1,071	\$1,071	\$1,071
137	must have ED5; not with T93	71,071	71,071	71,071
T60	Opening limiter electrically operated sliding door	\$120	\$120	\$120
	must have T55	Ψ120	Ų120	Ų120
T74	Assist handle, B-pillar	\$32	\$32	\$32
	must have D93; not with T77	Ψ32	ΨOL	ΨOL
T75	Door-mounted assist handles, driver & passenger	\$59	\$59	\$59
T77	Assist handle w/ partition	\$32	\$32	\$32
	must have D50/D51/D64	Ψ <b>0</b> 2	ΨOL	<b>732</b>
T85	Assist handle, left rear door	\$32	\$32	\$32
T86	Assist handles, right rear door	\$32	\$32	\$32
T93	Sliding door right side deletion	\$0	\$0	\$0
.55	not with T16/T50/T57/VK8/VC5	Ψ0	ΨO	ΨO
V07	Cab rear wall liner	\$360	\$360	\$360
	must have (D50/D51)+F1K; standard with H04	4000	φουσ	φοσο
V21	Luxury interior Trim	\$661	\$661	\$661
	must have VA5/VA7; not with V52/VA1/VA3	<del>7</del> 00=	φ332	Ψ002
V24	Pallet support in sliding door step	\$96	\$96	\$96
	must have (V43/X66)+(D50/D51); not with VK8/V93/C07	400	φσσ	φσσ
V25	Half height load compartment trim	\$201	\$201	\$201
	not with VA1/VA3/VA5/V52/X66	¥=0=	Ψ=0=	Ψ=0=
V31	Window pillar trim	\$513	\$513	\$513
	must have V36 + (V21/VA1) + (F02/F03/F07); not with V42	,	,	,
V35	Wheel house covering	\$105	\$105	\$105
	if +V43 must have V25/VA1/VA3; not with V52	,	,	,
V36	Roof trim	\$876	\$876	\$876
	must have D93; not with D17/D22/H72/L65/L71/LC2/VA3/V42/ZE6/(1	•		·
V42	Lashing rails, waist level	\$277	\$277	\$277
	not with V36/ZE6		,	·
V43	Wood floor with 6 D-rings	\$422	\$422	\$422
	not with P93/V93/VL4/VK8/C07; standard with D93/H13/V24/V52/VC			·
V48	Floor cover behind seat box	\$27	\$27	\$27
	must have D93; not with D50/D51/D56/D62/D64/V43/VK5	•		•
V4A	Full paneling, right sliding door	\$109	\$109	\$109
	not with P93/V93/VL4/VK8/C07; standard with D93/H13/V24/V52/VC	.5/VV2/ZE6		
V85	Cigarette lighter & ash cup, front	\$39	\$39	\$39
VA1	Side wall paneling waist height PVC	\$319	\$319	\$319
	must have VA5/VA7; not with V52			
VA3	Side wall paneling full hardboard	\$444	\$444	\$444
	not with V36/F02; if T93 must have (D50/D51)			
VA5	Full paneling, hinged rear doors	\$38	\$38	\$38
	must have D03+VA7+(W61/W78); not with V25			
VA7	Storage compart. w/ net in rear doors	\$127	\$127	\$127
	must have W61/W78; not with V52			
		\$415	\$415	\$415
VC4	Cargo lashing rails, head height	3413	Y 1-3	
VC4	Cargo lashing rails, head height  must have V42/C07/X66; not with ZE6	Ş413	Ų 120	¥ 1.23
VC4 VC5		\$71	\$71	\$71

# **3500 CARGO VAN - 6cyl Diesel** Options

		144" 6C	170" 6C	170" Ext.6C
		M3CA46	M3CA76	M3CAE6
		907.653	907.655	907.657
VK8	Floor covering, plastic	\$370	\$370	\$370
TILO	not with V43/P93/T19/T93/V52/VC5/X66	ψ373	ψ370	ψ370
VV2	Lashing rails, floor level (plus 4 anchors)	\$270	\$345	\$377
* * * =	must have V43; not with V93/VC5/ZE6	Ψ270	ψ3 13	ψο,,
W16	2nd row, fixed window, driver side	\$145	\$145	\$145
	if D93 must have F43+W70; if D93 & standard roof CHS production red	•	Ψ2.0	Ψ=.0
W17	2nd row, fixed window, passenger side	\$145	\$145	\$145
	if D93 must have F43+W70; if D93 & standard roof CHS production red	·	7 - 10	7-10
W33	FMVSS 217 emergency exit	\$379	\$379	\$379
	must have V31; not with D50/T19/W16	70.0	70.0	40.0
W54	Rear doors, opening to side wall	\$360	\$360	S
	90 Degree fixation point- Rear Doors	\$80	\$80	\$80
	SoP and Plausibility TBD	,	·	
W61	Windows in rear doors	\$93	\$93	\$93
	must have VA7/ if D51 must have F61; not with W78/(W70+-(H22/F02		·	
W70	Black tinting (90%) for rear windows	\$138	\$138	\$138
	not with W94; must have W16/W17/F02/((W61/W78)+H22); standar	d with F43/W33	P/F07	
W73	Bumper step, rear, grey	\$187	\$187	\$187
	not with Q24/W75/W76			•
W75	Step, wide, at rear end	\$308	\$308	\$308
	not with JB6/JB7/Q24/QA9; must have R91+R92			•
W76	Bumper step, rear, spring-loaded	-	\$601	\$601
	must have R91+R92; not with JB6/JB7/X30/Q24			
W78	Heated rear window(s) w/ washers/wipers	\$335	\$335	\$335
	Must have H22+VA7 / if D51 must have F61; not with W61			
X90	Deletion of Sprinter badge, left rear door	\$0	\$0	\$0
X93	Deletion of model badge, right rear door	\$0	\$0	\$0
X2R	Conversion to RV requirement	-	\$0	\$0
	must have B01+D93+E1X			
XM4	Acoustic package	\$87	\$87	\$87
	standard with CO2/CO3			
Y10	First-aid kit	\$27	\$27	\$27
Y26	Wheel chocks	\$38	\$38	\$38
Y45	Emergency flashlight	\$27	\$27	\$27
Y68	Paint preservative	\$187	\$212	\$225
Y69	Surface protection for stock vehicles	\$315	\$315	\$315
YK3	Cargo straps, D-rings	\$81	\$81	\$81
YK4	Cargo straps, lashing rails	\$104	\$104	\$104
	must have V42/VV2; not with ZE6			
ZE6	Shelving prep	\$640	\$640	\$640
	not with T93/H13/T19/V36/V42/VC4/VK8/VV2/YK4			

Packages

		144" 6C	170" 6C	170" E 6C
		M3CA46	M3CA76	M3CAE6
		907.653	907.655	907.657
C00	Comfort Package	\$300	\$300	\$300
LC4	Comfort overhead control panel	Х	X	X
SE4	Lumbar support, co-driver's seat	Х	Х	Х
SE5	Lumbar support, driver's seat	Х	Х	Х
SK0	Comfort head restraint, driver	Х	Х	Х
SK1	Comfort head restraint, co-driver	Х	X	Х
S28	Armrest, driver and passenger door	Х	X	X
must	have COS OR X68; CA/CC only: not with S23			

COS	Comfort Package (Seat addition)	\$381	\$381	\$381	
SB1	Comfort driver's seat	Х	Х	Х	
SB2	Comfort passenger seat	Х	Х	Х	
must	must have COO				

X68	Comfort Plus Package	\$1,923	\$1,923	\$1,923
H15	Heated front passenger seat	X	X	X
H16	Heated driver's seat	Х	X	X
SF1	Driver's seat electrically adjustable	Х	X	X
SF2	Co-driver's seat electrically adjustable	Х	Х	X
must	must have COO and VF4 OR VF6, CA/CC only: not with S23			

C01	Driver Convenience Package	\$760	\$760	\$760
E46	12 V power outlet, driver seat base	X	X	X
F64	Electrically folding exterior mirrors	Х	Х	X
FJ1	Hinged lid for storage compartment	Х	X	X
FJ5	Hinged Lid for Storage Compartments left and right	Х	X	Χ
FZ9	Keys, two additional masters	Х	X	X
JA7	Blind Spot Assist	X	X	X
JW8	Attention Assist	X	X	X

C02	Premium Package	\$983	\$983	\$983
CL3	Leather steering wheel	X	Х	X
E3M	MBUX Multimedia System with 7" touchscreen	X	Х	Х
FM3	Wet Wiper System	Х	Х	Х
JB4	Active Lane Keeping Assist	Х	Х	X
JK5	Instrument cluster with color display	X	X	X

Ordering availability restricted, see NetStar for availability and restrictions|must have JF1 + XM4; must choose FR8/JB7/JB6

CA2	CO2 in combination with CO3	\$604	\$604	\$604	
CL3	Leather steering wheel	Х	Х	X	
FM3	Wet Wiper System	Х	Х	X	
JB4	Active Lane Keeping Assist	Х	Х	Х	
JK5	Instrument cluster with color display	Х	Х	X	
Orde	Ordering availability restricted, see NetStar for availability and restrctions   must have CO3 + JF1				

Packages

144" 6C	170" 6C	170" E 6C
M3CA46	M3CA76	M3CAE6
907.653	907.655	907.657

C03	Premium Plus Package	\$1,793	\$1,793	\$1,793
E1B	Tray for smartphones incl. wireless charging	Х	Х	Х
	Navigation	Х	Х	Х
EY2	Intelligent navigation	Х	Х	Х
E4M	MBUX Multimedia System with 10.25" touchscreen	Х	Χ	Х
EX9	Free map data updates for 3 years	Х	Х	Х
H1I	Front-to-rear outlet in instrument panel	Х	Χ	Х
JA9	Traffic Sign Assist	Х	Χ	Х
XM4	Acoustic package	Х	Х	Х
must	have (CA2+(JB7/JB6/JB8)) OR (JB4+JK5+FM3+(JB7/JB6/JB8)); no	ot with FR8 and	d CO2	

X67	Chrome Grille Package	\$290	\$290	\$290	
CN2	Radiator grille frame in vehicle color	Χ	X	Х	
FK3	Chrome plated radiator grille (MB only)	X	X	Х	
no re	no restrictions				

X13	Exterior Lighting Package	\$1,608	\$1,608	\$1,608
L13	Fog lamp with cornering light function	Х	Х	Х
L22	Partial LED tail lights	Х	Х	Х
LA1	High beam assist	X	Х	Х
LG7	LED high performance headlamps	Х	Х	Х
no re	strictions			

C06	Cargo Convenience Package	\$658	\$658	\$658
E36	Cutoff relay for additional battery	Х	X	X
ES2	12 V power outlet, rear compartment	Х	Х	X
LC2	LED light strip in load compartment	Х	Х	X
T12	Sliding door two stage opening	Х	Х	X
T85	Assist handle, left rear door	Х	Х	X
T86	Assist handles, right rear door	Х	Χ	X
W54	Rear doors, opening to side wall	Х	Х	Х
must	have T74 OR (T77+D50) OR (T77+D51)			

C07	Cargo Protection Package	\$1,117	\$1,117	\$1,117
V25	Half height load compartment trim	Х	X	Х
V42	Lashing rails, waist level	Х	Х	Х
VC4	Cargo lashing rails, head height	Х	X	Х
VK8	Floor covering, plastic	Х	X	Х
YK3	Cargo straps, D-rings	Х	Х	Х
not with X66				

Packages

144" 6C	170" 6C	170" E 6C
M3CA46	M3CA76	M3CAE6
907.653	907.655	907.657

X66	Heavy-Duty-Cargo Protection Package	\$2,043	\$2,043	\$2,043	
V43	Wood floor with 6 D-rings	Х	Х	Х	
V42	Lashing rails, waist level	Х	Х	Х	
V52	Loadable wheel arch	X	Х	Х	
VA3	Side wall paneling full hardboard	Х	Х	Х	
VC4	Cargo lashing rails, head height	Х	Х	Х	
VV2	Lashing rails, floor level (plus 4 anchors)	Х	Х	Х	
YK3	Cargo straps, D-rings	Х	Х	Х	
YK4	Cargo straps, lashing rails	Х	Х	Х	
not v	not with CO7				

X69	Swivel Seat Package	\$532	\$532	\$532
SR8	Swivel base for driver's seat	Х	Х	Х
SR9	Swivel base for front passenger seat	Х	Х	Х
S87	Driver's seat frame, low	Х	Х	Х
S88	Passenger seat frame, low	Х	Х	Х
must	must have (C00+C0S) OR (C00+X68), choose BE2 or B25 (1500/2500 only)			

X01	Suspension Seating Package	\$940	\$940	\$940
SB3	Driver suspension seat, comfort version	Х	Х	Х
SB4	Passenger suspension seat, comfort version	Х	Х	X
S87	Driver's seat frame, low	Х	Х	Х
S88	Passenger seat frame, low	Х	Х	Х
not v	not with C00/C0S/E2I/X68/S23			

#### 3500XD CARGO VAN - 4cyl Diesel Standard Equipment

144'' 4C	170" 4C	170" E 4C
MXCA44	MXCA74	MXCAE4
907.653	907.655	907.657

Page	\$\frac{S}{S}\$ \$\
4-Cyl Engine/7-Speed Trans.         S         S           ED4         AGM battery 12V 92 AH 850 A         S         S           G42         Automatic transmission, 7G-tronic         S         S           M40         Alternator 14 V / 200 A         S         S           MG3         2.0L 4-cylinder diesel engine         S         S           MG3         2.0L 4-cylinder diesel engine         S         S           MH8         SULEV emissions         S         S           MH8         SULEV emissions         S         S           Tires - choose while ordering         S         S         S           X34         Dual Rear Wheel         \$0         \$0           RH7         Tires LT 215/85 R16         S         S           RS6         5.5 J x 16 steel wheels         S         S           RD9         Unspecified tire brand         S         S           X31         Super Single Tire         \$385         \$385           R9A         285/65 R 16 C super single tires         O         O           R9A         285/65 R 16 C super single tires         O         O           R9D         Unspecified tire brand         O         O	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$
ED4         AGM battery 12V 92 AH 850 A         S         S           G42         Automatic transmission, 7G-tronic         S         S           M40         Alternator 14 V / 200 A         S         S           M63         2.0L 4-cylinder diesel engine         S         S           MH8         SULEV emissions         S         S           Tires - choose while ordering           X34         Dual Rear Wheel         \$0         \$0           RH7         Tires LT 215/85 R16         S         S           RS6         5.5 J x 16 steel wheels         S         S           RS9         Unspecified tire brand         S         S           R90         Unspecified tire brand         O         O           R91         Unspecified tire brand         O         O           R92         Unspecified tire brand         O         O           R93         Unspecified tire brand         O         O           R94         285/65 R 16 C super single tires         O         O           R95         Steel wheels: 8.5Jx16 Rr; 6.5Jx16 Fr         O         O           R92         Unspecified tire brand         O         O           R93         Ax	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$
G42         Automatic transmission, 7G-tronic         S         S           M40         Alternator 14 V / 200 A         S         S           MG3         2.0L 4-cylinder diesel engine         S         S           MH8         SULEV emissions         S         S           Tires - choose while ordering           X34         Dual Rear Wheel         \$0         \$0           RH7         Tires LT 215/85 R16         S         S           RS6         5.5 J x 16 steel wheels         S         S           RS6         5.5 J x 16 steel wheels         S         S           RD9         Unspecified tire brand         S         S           R94         285/65 R 16 C super single tires         O         O           R94         285/65 R 16 C super single tires         O         O           R95         Steel wheels: 8.5Jx16 Rr; 6.5Jx16 Fr         O         O           R99         Unspecified tire brand         O         O           R99         Unspecified tire brand         O         O           R92         Tire pressure monitoring sensors         O         O           Equipment         AR3         Axle ratio 4.182         S         S     <	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$
M40         Alternator 14 V / 200 A         S         S           MG3         2.0L 4-cylinder diesel engine         S         S           MH8         SULEV emissions         S         S           Tires - choose while ordering           X34         Dual Rear Wheel         \$0         \$0           RH7         Tires LT 215/85 R16         S         S           RS6         5.5 J x 16 steel wheels         S         S           RS9         Unspecified tire brand         S         S           R99         Unspecified tire brand         O         O           RS5         Steel wheels: 8.5Jx16 Rr; 6.5Jx16 Fr         O         O           RS9         Unspecified tire brand         O         O           RY2         Tire pressure monitoring sensors         O         O           Equipment         A         Axle ratio 4.182         S         S           BA3         Active Brake Assist         S         S         S           BH1         Hold Function         S         S         S           C6L         Multifunction steering wheel         S         S         S           CB8         Stabilization Level II         S<	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$
MG3         2.0L 4-cylinder diesel engine         S         S           MH8         SULEV emissions         S         S           Tires - choose while ordering           X34         Dual Rear Wheel         \$0         \$0           RH7         Tires LT 215/85 R16         S         S           RS6         5.5 J x 16 steel wheels         S         S           RD9         Unspecified tire brand         S         S           R90         Unspecified tire brand         O         O           R91         Unspecified tire brand         O         O           R92         Unspecified tire brand         O         O           R93         Unspecified tire brand         O         O           R94         Unspecified tire brand         O         O           R95         Steel wheels: 8.5Jx16 Rr; 6.5Jx16 Fr         O         O           R97         Unspecified tire brand         O         O           R92         Tire pressure monitoring sensors         O         O           Equipment         S         S         S           AR3         Axler ratio 4.182         S         S           BA3         Active Brake Assist         S<	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$
MH8         SULEV emissions         S         S           Tires - choose while ordering         X34         Dual Rear Wheel         \$0         \$0           RH7         Tires LT 215/85 R16         S         S           RS6         5.5 J x 16 steel wheels         S         S           RD9         Unspecified tire brand         S         S           R9A         285/65 R 16 C super single tires         O         O           R9A         285/65 R 16 C super single tires         O         O           R9D         Unspecified tire brand         O         O           R99         Unspecified tire brand         O         O           RY2         Tire pressure monitoring sensors         O         O           Equipment         S         S           AR3         Axle ratio 4.182         S         S           BA3         Active Brake Assist         S         S           BH1         Hold Function         S         S           C6L         Multifunction steering wheel         S         S           C7         S         S         S           C8         S tabilization Level II         S         S           C8         S<	\$0 \$0 \$ \$ \$ \$ \$ \$385 O
Tires - choose while ordering         \$0         \$0           X34	\$0 S S S \$385 O
X34         Dual Rear Wheel         \$0         \$0           RH7         Tires LT 215/85 R16         S         S           RS6         5.5 J x 16 steel wheels         S         S           RD9         Unspecified tire brand         S         S           RP9         Unspecified Tire         \$385         \$385           RP9A         285/65 R 16 C super single tires         O         O           RP9A         285/65 R 16 C super single tires         O         O           RP9A         285/65 R 16 C super single tires         O         O           RP9A         285/65 R 16 C super single tires         O         O           RP9A         285/65 R 16 C super single tires         O         O           RP9A         285/65 R 16 C super single tires         O         O           RP9A         285/65 R 16 C super single tires         O         O           RP9A         285/65 R 16 C super single tires         O         O           RP9A         285/65 R 16 C super single tires         O         O           RP9A         285/65 R 16 C super single tires         O         O           RP9A         285/65 R 16 C super single tires         O         O           RP9A <td< td=""><td>\$ \$ \$ <b>\$385</b> O</td></td<>	\$ \$ \$ <b>\$385</b> O
RH7       Tires LT 215/85 R16       S       S         RS6       5.5 J x 16 steel wheels       S       S         RD9       Unspecified tire brand       S       S         X31       Super Single Tire       \$385       \$385         R9A       285/65 R 16 C super single tires       O       O         R9A       285/65 R 16 C super single tires       O       O         R9D       Unspecified tire brand       O       O         R09       Unspecified tire brand       O       O         R72       Tire pressure monitoring sensors       O       O         Equipment       S       S         AR3       Axle ratio 4.182       S       S         BA3       Active Brake Assist       S       S         BH1       Hold Function       S       S         C6L       Multifunction steering wheel       S       S         CB8       Stabilization Level II       S       S         CL1       Adjustable steering wheel (angle)       S       S         D03       High roof       O       S         D93       Omission bulkhead       S       S         E07       Hill Start Assist       S <td>\$ \$ \$ <b>\$385</b> O</td>	\$ \$ \$ <b>\$385</b> O
RS6         5.5 J x 16 steel wheels         S         S           RD9         Unspecified tire brand         S         S           X31         Super Single Tire         \$385         \$385           R9A         285/65 R 16 C super single tires         O         O           R9A         285/65 R 16 C super single tires         O         O           R9A         285/65 R 16 C super single tires         O         O           R9A         285/65 R 16 C super single tires         O         O           R9A         285/65 R 16 C super single tires         O         O           R9A         285/65 R 16 C super single tires         O         O           R9A         285/65 R 16 C super single tires         O         O           R9B         Unspecified tire brand         O         O           R9D         Unspecified tire brand         O         O           R9D         O         O         O           R9D         Male ratio 4.182         S         S           S         S         S         S           BA3         Active Brake Assist         S         S           BH1         Hold Function         S         S           CB	\$ \$ <b>\$385</b> O
RD9         Unspecified tire brand         S         S           X31         Super Single Tire         \$385         \$385           R9A         285/65 R 16 C super single tires         O         O           R9A         285/65 R 16 C super single tires         O         O           R9A         285/65 R 16 C super single tires         O         O           R9A         285/65 R 16 C super single tires         O         O           R9D         Unspecified tire brand         O         O           RD9         Unspecified tire brand         O         O           RP9         Tire pressure monitoring sensors         O         O           E93         Active Brake Assist         S         S           S         S         S         S           BA3         Active Brake Assist         S         S           BH1         Hold Function         S         S           CB </td <td>\$ <b>\$385</b> O</td>	\$ <b>\$385</b> O
X31Super Single Tire\$385\$385R9A285/65 R 16 C super single tiresOORS5Steel wheels: 8.5Jx16 Rr; 6.5Jx16 FrOORD9Unspecified tire brandOORY2Tire pressure monitoring sensorsOOEquipmentAR3Axle ratio 4.182SSBA3Active Brake AssistSSBH1Hold FunctionSSC6LMultifunction steering wheelSSCB8Stabilization Level IISSCL1Adjustable steering wheel (angle)SSD03High roofOSD93Omission bulkheadSSE07Hill Start AssistSS	\$385 0 0
R9A 285/65 R 16 C super single tires  R55 Steel wheels: 8.5Jx16 Rr; 6.5Jx16 Fr  R09 Unspecified tire brand  R72 Tire pressure monitoring sensors  R73 Axle ratio 4.182  R74 Sample Sampl	0
RS5 Steel wheels: 8.5Jx16 Rr; 6.5Jx16 Fr  RD9 Unspecified tire brand  O O  RY2 Tire pressure monitoring sensors  O O  Equipment  AR3 Axle ratio 4.182  S S  BA3 Active Brake Assist  S S  BH1 Hold Function  S S  C6L Multifunction steering wheel  CB8 Stabilization Level II  S S  C11 Adjustable steering wheel (angle)  D03 High roof  O S  S  S  S  S  S  S  S  S  S  S  S  S	0
RD9 Unspecified tire brand OOOO RY2 Tire pressure monitoring sensors OOOO  Equipment  AR3 Axle ratio 4.182 SSSSSSSSSSSSSSSSSSSSSSSSSSSSSSSSSSSS	
RY2 Tire pressure monitoring sensors  Equipment  AR3 Axle ratio 4.182 S S  BA3 Active Brake Assist S S  BH1 Hold Function S S  C6L Multifunction steering wheel S S  CB8 Stabilization Level II S S  CL1 Adjustable steering wheel (angle) S S  D03 High roof O S  D93 Omission bulkhead S S  E07 Hill Start Assist S	0
Equipment           AR3         Axle ratio 4.182         S         S           BA3         Active Brake Assist         S         S           BH1         Hold Function         S         S           C6L         Multifunction steering wheel         S         S           CB8         Stabilization Level II         S         S           CL1         Adjustable steering wheel (angle)         S         S           D03         High roof         O         S           D93         Omission bulkhead         S         S           E07         Hill Start Assist         S         S	
AR3 Axle ratio 4.182 S S BA3 Active Brake Assist S S BH1 Hold Function S S S C6L Multifunction steering wheel S S CB8 Stabilization Level II S S S CL1 Adjustable steering wheel (angle) S S D03 High roof O S D93 Omission bulkhead S S E07 Hill Start Assist S S	0
BA3 Active Brake Assist  BH1 Hold Function  C6L Multifunction steering wheel  CB8 Stabilization Level II  CL1 Adjustable steering wheel (angle)  D03 High roof  O  S  D93 Omission bulkhead  E07 Hill Start Assist  S  S  S  S  S  S  S  S  S  S  S  S  S	
BA3 Active Brake Assist  BH1 Hold Function  C6L Multifunction steering wheel  CB8 Stabilization Level II  CL1 Adjustable steering wheel (angle)  D03 High roof  D93 Omission bulkhead  E07 Hill Start Assist  S  S  S  S  S  S  S  S  S  S  S  S  S	S
BH1 Hold Function S S C6L Multifunction steering wheel S S CB8 Stabilization Level II S S CL1 Adjustable steering wheel (angle) S S D03 High roof O S D93 Omission bulkhead S S E07 Hill Start Assist S S	S
CB8 Stabilization Level II S S CL1 Adjustable steering wheel (angle) S D03 High roof O S D93 Omission bulkhead S S S E07 Hill Start Assist S S S	S
CB8 Stabilization Level II S S CL1 Adjustable steering wheel (angle) S D03 High roof O S D93 Omission bulkhead S S S E07 Hill Start Assist S S S	S
D03High roofOSD93Omission bulkheadSSE07Hill Start AssistSS	S
D03High roofOSD93Omission bulkheadSSE07Hill Start AssistSS	S
D93 Omission bulkhead S S E07 Hill Start Assist S S	S
E07 Hill Start Assist S S	S
	S
1F 17 13(d)10d10 1d010	S
E1U USB-C socket, 5 V S S	S
E30 Starter battery disconnect S S	S
E3J Pre-installation for switch panel S S	S
E40 Trailer hitch prep. wiring S S	S
ED8 Preinstallation PSM S S	S
EES Ultracapacitor discharge module S S	S
EK1 Body Builder Connector S S	S
ESO Jump start terminal S S	S
EW6 Pre-installation for Mercedes me Remote Services S S	S
EY5 Emergency Call System S S	S
EY6 Breakdown management S S	S
F68 Heated & electrically adjustable exterior mirrors S S	S
FF5 Shelf above windshield S S	S
FG8 Cupholder front S S FI1 Remote key (315 mhz) w/central locking S S	S S
, , , , ,	
FJ4 Storage compartment underneath cockpit S S	S
FR3 Rear view camera (rear-view mirror display)  S S S U31 Windshield with filter hand	S
H21 Windshield with filter band S S	S
HH2 Heater, auxiliary electric hot air S S	S
HH9 Air Condition, Front S S	S
IH7 Head Unit, North America S S	S
J11 Speedometer, miles and km/h S S	S
J55 Seat belt warning for co-driver seat S S	S
J58 Seat belt reminder driver S S	S
J65 Outside temperature gauge S S	S
JA8 Crosswind Assist S S	S
JH3 Communication module (LTE) for dig. services S S	
JI9 Service interval 20.000 miles S	S
K56 Red diesel filler cap S S	S S
K60 Exhaust straight to rear S S	S

Standard Equipment

		144" 4C	170" 4C	170" E 4C
		MXCA44	MXCA74	MXCAE4
		907.653	907.655	907.657
KB7	24.5 gallon fuel tank	S	S	S
KL1	Aux fuel sending unit w/ fuel tap	S	S	S
KL5	Fuel filter with water separator	S	S	S
KP6	3rd generation SCR emission control system	S	S	S
L65	Interior lights, cargo compartment	S	S	S
L94	Parking lights deletion	S	S	S
LA2	Headlight assistant	S	S	S
LB5	3rd brake light	S	S	S
MS1	Cruise control	S	S	S
P47	Front mudflaps	S	S	S
P48	Rear mudflaps	S	S	S
Q11	Longitudinal member reinforcement	S	S	S
R65	Spare tire bracket below frame	S	S	S
R87	Spare tire	S	S	S
RM0	All-season tires	S	S	S
S02	Standard driver seat	S	S	S
S04	Standard front passenger seat	S	S	S
S22	Armrest for driver's seat	S	S	S
S25	Armrest for front passenger seat	S	S	S
SA5	Front airbag, driver	S	S	S
SA6	Front airbag, passenger	S	S	S
SH1	Thorax-pelvis sidebag, driver	S	S	S
SH2	Thorax-pelvis sidebag, co-driver	S	S	S
SH9	Airbag, driver/passenger window	S	S	S
SK2	Seat occupancy sensor, driver's seat	S	S	S
T16	Sliding door, passenger side	S	S	S
V93	Without factory installed flooring	S	S	S
V94	Cable duct - side wall	S	S	S
V95	Cable duct - rear portal	S	S	S
W54	Rear doors, opening to side wall	0	0	S
X5G	Witout load uprating/derating 5,000 kg	S	S	S
Y43	Jack, hydraulic	S	S	S

		144" 4C	170" 4C	170" E 4C
		MXCA44	MXCA74	MXCAE4
		907.653	907.655	907.657
A50	Front axle reinforced	\$346	\$346	\$346
ASU AP2	Addtl. bar for driveshaft & exhaust extension	\$69	\$69	\$340
AR2	Axle ratio 3.923	\$09 \$0	\$0	\$0
AKZ	not with AR3	ŞU	ŞU	ŞÜ
B01	ESP for increased Center of Gravity above 39.4"	_	\$0	\$0
B01	must have CB4/CB8/X30; not with RHO/CB7		ŞŪ	70
BE2	Handbrake lever, folding	\$55	\$55	\$55
	X69 must have BE2	φσσ	φoo	<b>400</b>
C72	Bumpers front/rear primed	\$268	\$268	\$268
	must have CN2 (part of X67), not with CM0	,	,	,
CE8	Raised rear body mounts	\$252	\$252	\$252
CL3	Leather steering wheel	\$187	\$187	\$187
	must have (C02/E3M)/C03 + (ET4/MS1)	, -	, -	, -
СМО	Painted metallic front & rear bumper	\$587	\$587	\$587
	must have (CN2/X67) + (JA7/C01) + JB7 + (7755/9197/9775)	,	,	,
СМ9	Primed side moldings	\$364	\$364	\$364
D03	High roof	\$2,900	S	S
D13	Mounting rails for roof rack	\$300	\$300	\$300
D22	Fixed sunroof (rear roof section)	\$336	\$336	\$336
	not with H08/HK4/H72/V36/ZK4	7000	7000	7000
D50	Cargo partition	\$288	\$288	\$288
	not with D51/D93/H08/HK4/T74/V36; must have one of T93/T77	7-00	7-55	7-55
D51	Cargo partition with 1 window	\$335	\$335	\$335
	not with D50/D93/H08/HK4/T74/V37/D17; must have one of T93/T77		7000	7000
E1B	Tray for smartphones incl. wireless charging	\$156	\$156	\$156
	must have CO2/E3M + H1I	,	,	,
E1E	Navigation	\$728	\$728	\$728
	must have CO2/E3M, not with CO3	,	·	·
E1S	Sirius XM, satellite radio	\$255	\$255	\$255
	must have CO2/E3M/CO3	·	·	·
E1X	MBUX multimedia 6-hour runtime	-	\$0	\$0
	must have X2R + (C02+E1E/E1S)/C03/(E3M+E1E/E1S)			·
E1R	Additional Fuses (40/80/150/100 Ampere)	\$50	\$50	\$50
	SoP and Plausibility TBD	,	,	,
E1Y	Additional Fuses (40/80/80/100 Ampere)	\$50	\$50	\$50
	SoP and Plausibility TBD	·	·	·
E2A	Access point for BB special signals in cockpit	\$29	\$29	\$29
E2I	Additional battery, co-driver seat base	\$248	\$248	\$248
	must have E36/C06; not with E2M/F09; CHS production only	, -	, -	, -
E2M	Additional battery, engine compartment	\$248	\$248	\$248
	must have X01+ (E36/C06); not with E2I/X69/F09	7-10	7-10	7-10
E3M	MBUX Multimedia System with 7" touchscreen	\$474	\$474	\$474
	not with CO2/CO3; must have JK5+(JB7/FR8)	,	,	7
E36	Cutoff relay for additional battery	\$110	\$110	\$110
	standard with E2I/E2M	,	7	7
E46	12 V power outlet, driver seat base	\$92	\$92	\$92
E5M	Extension of PSM standard contact	\$58	\$58	\$58
ED5	Parametric special module (PSM)	\$317	\$317	\$317
	not with ED8			
EE3	115 V socket	\$125	\$125	\$125
EP7	Basic electric fitting for rear loudspeakers	\$68	\$68	\$68
ES2	12 V power outlet, rear compartment	\$92	\$92	\$92
ES5	Charging package, dashboard	\$82	\$82	\$82
ET4	Active Distance Assist DISTRONIC	\$263	\$263	\$263
<u> </u>	must have CO2/CO3/E3M; not with ZH4	,		
F1K	Coat hooks in driver cabin	\$14	\$14	\$14

		144" 4C	170" 4C	170" E 4C
		MXCA44	MXCA74	MXCAE4
		907.653	907.655	907.657
F49	Electrically heated windshield	\$218	\$218	\$218
	no restriction			
F61	Interior rear view mirror	\$36	\$36	\$36
	not with D50; must have C02/E3M/C03			
FE9	Additional DIN-slot	\$81	\$81	\$81
FF4	Storage compartment above cabin	\$186	\$186	\$186
	must have D03, not with D17/D64/H08/HK4			
FF8	Overhead storage slot, front center	\$105	\$105	\$105
FJ1	Hinged lid for storage compartment	\$93	\$93	\$93
FR8	Rear view camera (head unit display)	\$336	\$336	\$336
	must have CO2/E3M; not with FR3/JB7; 3500XD not with JB8			
FY1	Security alarm w. interior motion sensor	\$584	\$584	\$584
	must have LC4/C00		<u>.</u>	
FY7	Optional 3-button keys	\$36	\$36	\$36
FZ9	Keys, two additional masters	\$121	\$121	\$121
H00	Warm/cool air duct to rear compartment	\$59	\$59	\$59
	not with D50/D51/Y2A	700	700	700
H01	Heat insulation, rear compartment	\$156	\$156	\$156
	must have V21/V25/VA3/VA1/C07/X66	<b>V</b> 130	<b></b>	<b>Ÿ</b> 130
H04	Heat insulation, front compartment	\$187	\$187	\$187
1104	if + D50/D51 must have V07	7107	<b>\$107</b>	7107
H08	Air conditioning rear, roof-mounted	\$2,872	\$2,872	\$2,872
1108	must have D93 +V36; not with HK4/C06/X66/C07	72,672	<b>ΫΖ,</b> 67Ζ	72,072
H12	Fuel-fired pre-heater/booster (17K BTU)	\$1,116	\$1,116	\$1,116
1112	not with HZ9	71,110	71,110	71,110
H13	Rear cabin heater and vents	\$786	\$786	\$786
птэ	must have H12/HZ9	\$760	\$760	376U
1115		6204	¢204	¢204
H15	Heated front passenger seat	\$284	\$284	\$284
114.6	must have H16; not with X68	6204	¢204	6204
H10	Heated driver's seat	\$284	\$284	\$284
	must have H15; not with X68	4252	4050	4252
H22	Rear window defroster	\$253	\$253	\$253
	must have W61/W78; standard for W61+W70	4.00	1	4.00
H72	Roof fan, electric	\$400	\$400	\$400
	not with D22/V36			
H88	Rear heater prep	\$405	\$405	\$405
	must have H12/HZ9; not with H13/T19			
H1I	Front-to-rear outlet in instrument panel	\$0	\$0	\$0
	must have FJ1/C01		•	
HH4	Thermotronic automatic climate control	\$337	\$337	\$337
	must have JF1; if +H13 must have H08/HK4			_
HK4	Rear air conditioner, heavyduty	\$3,940	\$3,940	\$3,940
	must have D03+V36+D93; not with H08/ZB6/ZE6/N62/N63			
HZ9	Fuel-fired heater booster (18,000 BTU)	\$676	\$676	\$676
	not with H12			
J51	Fuel gauge, optimized for aux. fuel tap	\$72	\$72	\$72
	not with HZ9/H12			
J52	Engine oil level display at cold start	\$0	\$0	\$0
JA7	Blind Spot Assist	\$450	\$450	\$450
	not with CO1			
JB4	Active Lane Keeping Assist	\$288	\$288	\$288
	standard with CO2/CA2	•		
JB7	Parking Package	\$615	\$615	\$615
	must have CO2/CO3/E3M; not with W75/W76/JB6			
JF1	Rain sensor	\$106	\$106	\$106
JK5	Instrument cluster with color display	\$144	\$144	\$144
	standard with CO2/CA2	+-''	, , , , , , , , , , , , , , , , , , ,	7
JW0	Backup alarm	\$99	\$99	\$99
		400	733	<b>-</b>

		144" 4C	170" 4C	170" E 4C
		MXCA44	MXCA74	MXCAE4
		907.653	907.655	907.657
JW2	Deactivation lamp monitoring failure	\$27	\$27	\$27
JW8	Attention Assist	\$49	\$49	\$49
K51	Misfueling prevention for Diesel	\$49	\$49	\$49
K52	DEF fluid filler cap - lockable	\$27	\$27	\$27
L13	Fog lamp with cornering light function	\$199	\$199	\$199
L71	Light/motion sensor in rear compartment	\$54	\$54	\$54
	not with V36	•	•	
LB9	Illuminated front exits	\$151	\$151	\$151
LC2	LED light strip in load compartment	\$263	\$263	\$263
	not with H08/HK4/V36/C06	•		
LC4	Comfort overhead control panel	\$93	\$93	\$93
M20	Speed limitation 65 mph	\$60	\$60	\$60
	not with MD3			!
MD3	Top speed limitation 75 mph	\$60	\$60	\$60
	not with M20	·	<u>.                                      </u>	· · · · · · · · · · · · · · · · · · ·
N62	Front engine bracket for additional alternator	\$467	\$467	\$467
	not with HK4/N63	·		·
N63	Front engine bracket for auxiliary A/C compressor	\$467	\$467	\$467
	not with HK4/N62	, -	, -	, ,
P93	Omission of D-rings	-\$15	-\$15	-\$15
-	not with D93/V43/VK8	7-0	7-0	7-0
QA2	Trailer cross member 7,500 lbs capacity	\$186	\$186	-
<u>~</u>	not with W73/W75/W76/Q24/Q67	Ψ <b>200</b>	<b>¥200</b>	
QA9	Half-sided step rear (for trailer hitch)	\$101	\$101	\$101
۵, ۱۶	must have QA2; not with W73/W75/W76	Ų101	<b>V</b> 101	<b>Ÿ101</b>
Q24	Trailer hitch, 5,000 lbs	-	_	\$147
	not with W73/W75/W76			Ψ=
R91	Spare tire deletion	-\$110	-\$110	-\$110
1131	must have R92; not with R87	7110	7110	<b>Ψ110</b>
R92	Spare tire carrier deletion	\$0	\$0	\$0
1132	must have R91; not with R65	ŲΟ	ŞÜ	ŞÜ
R98	Rims painted jet black	\$81	\$81	\$81
11.50	not with RL5/RM2	701	201	701
RF1	Tire brand Continental	\$0	\$0	\$0
KLI	must have RM1 + RM9	ŞU	<b>3</b> 0	ŞÜ
RF8	Tire brand Michelin	\$0	\$0	\$0
КГО	must have RM9; not with RM1	ŞU	ŞÜ	ŞÜ
RH0	Tire brand Kumho	\$0	\$0	\$0
КПО	must have RM9; not with RM1	ŞU	ŞÜ	ŞÜ
D 1 / 1		\$169	¢160	¢160
KIVII	M+S winter tires	\$109	\$169	\$169
D 1 4 2	must have RF1/RD9; not with RF8/RH0/X31	Ć01	Ć01	Ć01
KIVIZ	Rims painted arctic white	\$81	\$81	\$81
D 1 4 0	not with R98/RL5	¢101	Ć404	¢101
KIVI9	Specially requested tires	\$101	\$101	\$101
622	must have RF1/RF8/RH0; not with RD9	Ć400	Ć400	Ć400
S23	Twin front passenger seat	\$400	\$400	\$400
cac	not with C00/X68/X01	454	ĊE4	ČE4
S28	Armrest, driver and passenger door	\$51	\$51	\$51
S62	Seat belts orange, driver and front passenger	\$32	\$32	\$32
05.7	not with S23	4	400-	4
SB9	Driver's seat plus	\$238	\$238	\$238
	must have VF7; not with C00/X68/X69	1		
SZ7	Storage net, driver's seat backrest	\$64	\$64	\$64
SZ8	Storage net, passenger seat backrest	\$64	\$64	\$64
T12	Sliding door two stage opening	\$82	\$82	\$82
	not with T55			
T19	Sliding door, driver's side	\$935	\$935	\$935
	not with H13/H88/VC5/ZE6/F43/W16/F02; if +V36 must have D03			

		144" 4C	170" 4C	170" E 4C
		MXCA44	MXCA74	MXCAE4
		907.653	907.655	907.657
T50	Electric closing assist right sliding door	\$335	\$335	\$335
	must have D03; not with T55/T93	,	,	,
T51	Electric closing assist left sliding door	\$335	\$335	\$335
	must have T19 + D03	7000	7000	7000
T55	Electric sliding door right	\$831	\$831	\$831
133	must have D03 + (FY7+T16); not with T12/T50	, , , , , , , , , , , , , , , , , , ,	<b>7031</b>	, , , , , , , , , , , , , , , , , , ,
T57	Electric sliding step	\$1,071	\$1,071	\$1,071
	must have ED5; not with T93	Ψ=/07=	Ψ=/07=	<del>+ -/</del>
T60	Opening limiter electrically operated sliding door	\$120	\$120	\$120
100	must have T55	<b>Ÿ120</b>	<b>V120</b>	Ų120
T74	Assist handle, B-pillar	\$32	\$32	\$32
.,.	must have D93; not with T77	<b>732</b>	<b>432</b>	<b>702</b>
T75	Door-mounted assist handles, driver & passenger	\$59	\$59	\$59
T77	Assist handle w/ partition	\$32	\$32	\$32
177	must have D50/D51/D64	732	<del>-</del>	<b>732</b>
T85	Assist handle, left rear door	\$32	\$32	\$32
T86	Assist handles, right rear door	\$32	\$32	\$32
T93	Sliding door right side deletion	\$0	\$0	\$0
193	not with T16/T50/T57/VK8/VC5	ŞÜ	ŞÜ	Şυ
V07	Cab rear wall liner	\$360	\$360	\$360
V07	must have (D50/D51)+F1K; standard with H04	\$300	\$300	<b>3300</b>
V21	Luxury interior Trim	\$661	\$661	\$661
VZI	must have VA5/VA7; not with V52/VA1/VA3	3001	3001	\$001
V24	Pallet support in sliding door step	\$96	\$96	\$96
V 24	must have (V43/X66)+(D50/D51); not with VK8/V93/C07	\$30	390	Ş <del>3</del> 0
V25	Half height load compartment trim	\$201	\$201	\$201
V25		\$201	\$201	\$201
V31	not with VA1/VA3/VA5/V52/X66 Window pillar trim	¢512	¢512	¢E12
V31	must have V36 + (V21/VA1) + (F02/F03/F07); not with V42	\$513	\$513	\$513
\/2F		¢10F	¢10F	¢10F
V35	Wheel house covering	\$105	\$105	\$105
Vac	if +V43 must have V25/VA1/VA3; not with V52	¢076	¢076	¢076
V36	Roof trim	\$876	\$876	\$876
	must have D93; not with D17/D22/H72/L65/L71/LC2/VA3/V42/ZE6/(1			6277
V42	Lashing rails, waist level	\$277	\$277	\$277
1/42	not with V36/ZE6	<b>4422</b>	<b>.</b>	<b>6422</b>
V43	Wood floor with 6 D-rings	\$422	\$422	\$422
1440	not with P93/V93/VL4/VK8/C07; standard with D93/H13/V24/V52/VC		427	<b>427</b>
V48	Floor cover behind seat box	\$27	\$27	\$27
	must have D93; not with D50/D51/D56/D62/D64/V43/VK5	4400	4400	4400
V4A	Full paneling, right sliding door	\$109	\$109	\$109
	must have D03+T16+V21+VA5+W17; not with T19	1 400	100	400
V85	Cigarette lighter & ash cup, front	\$39	\$39	\$39
VA1	Side wall paneling waist height PVC	\$319	\$319	\$319
	must have VA5/VA7; not with V52			
VA3	Side wall paneling full hardboard	\$444	\$444	\$444
	not with V36/F02; if T93 must have (D50/D51)			
VA5	Full paneling, hinged rear doors	\$38	\$38	\$38
	must have D03+VA7+(W61/W78); not with V25			
VA7	Storage compart. w/ net in rear doors	\$127	\$127	\$127
	must have W61/W78; not with V52	1		
VC4	Cargo lashing rails, head height	\$415	\$415	\$415
	must have V42/C07/X66; not with ZE6			
VC5	Door sill - protective edge	\$71	\$71	\$71
	must have V43/X66; not with T19/T93/VK8/VV2/V93/C07			
VK8	Floor covering, plastic	\$370	\$370	\$370
	not with V43/P93/T19/T93/V52/VC5/X66			
VV2	Lashing rails, floor level (plus 4 anchors)	\$270	\$345	\$377
	must have V43; not with V93/VC5/ZE6			

		144" 4C	170" 4C	170" E 4C
		MXCA44	MXCA74	MXCAE4
		907.653	907.655	907.657
W16	2nd row, fixed window, driver side	\$145	\$145	\$145
	if D93 must have F43+W70; if D93 & standard roof CHS production	required	·	·
W17	2nd row, fixed window, passenger side	\$145	\$145	\$145
	if D93 must have F43+W70; if D93 & standard roof CHS production	required	•	
W33	FMVSS 217 emergency exit	\$379	\$379	\$379
	must have V31; not with D50/T19/W16	•	•	
W54	Rear doors, opening to side wall	\$360	\$360	S
W5F	90 Degree fixation point- Rear Doors	\$80	\$80	\$80
	SoP and Plausibility TBD	•		
W61	Windows in rear doors	\$93	\$93	\$93
	must have VA7/ if D51 must have F61; not with W78/(W70+-(H22/	F02))	•	•
W70	Black tinting (90%) for rear windows	\$138	\$138	\$138
	not with W94; must have W16/W17/F02/((W61/W78)+H22); stand	lard with F43/W33/	F07	•
W73	Bumper step, rear, grey	\$187	\$187	\$187
	not with QA2/W75/W76	•	•	•
W75	Step, wide, at rear end	\$308	\$308	\$308
	not with JB6/JB7/Q24/QA9; must have R91+R92	•		
W76	Bumper step, rear, spring-loaded	-	\$601	\$601
	must have R91+R92; not with JB6/JB7/X30/Q24			
W78	Heated rear window(s) w/ washers/wipers	\$335	\$335	\$335
	Must have H22+VA7 / if D51 must have F61; not with W61			
X90	Deletion of Sprinter badge, left rear door	\$0	\$0	\$0
X93	Deletion of model badge, right rear door	\$0	\$0	\$0
X2R	Conversion to RV requirement	-	\$0	\$0
	must have B01+D93+E1X			
XM4	Acoustic package	\$87	\$87	\$87
	standard with CO2/CO3			
Y10	First-aid kit	\$27	\$27	\$27
Y26	Wheel chocks	\$38	\$38	\$38
Y45	Emergency flashlight	\$27	\$27	\$27
Y68	Paint preservative	\$187	\$212	\$225
Y69	Surface protection for stock vehicles	\$315	\$315	\$315
YK3	Cargo straps, D-rings	\$81	\$81	\$81
YK4	Cargo straps, lashing rails	\$104	\$104	\$104
	must have V42/VV2; not with ZE6			
ZE6	Shelving prep	\$640	\$640	\$640
	not with T93/H13/T19/V36/V42/VC4/VK8/VV2/YK4			

## 3500XD CARGO VAN - 4cyl Diesel

Packages

144" 4C

170" 4C

170" E 4C

		MXCA44	MXCA74	MXCAE4
		907.653	907.655	907.657
C00	Comfort Package	\$300	\$300	\$300
LC4	Comfort overhead control panel	Х	Х	X
SE4	Lumbar support, co-driver's seat	Х	Х	X
SE5	Lumbar support, driver's seat	Х	Х	X
SK0	Comfort head restraint, driver	Х	X	X
SK1	Comfort head restraint, co-driver	Х	Х	X
S28	Armrest, driver and passenger door	Х	Х	X
must	have COS OR X68; CA/CC only: not with S23			

COS	Comfort Package (Seat addition)	\$381	\$381	\$381
SB1	Comfort driver's seat	Х	X	X
SB2	Comfort passenger seat	Х	Х	Х
must	must have COO			

X68	Comfort Plus Package	\$1,923	\$1,923	\$1,923
H15	Heated front passenger seat	X	Х	X
H16	Heated driver's seat	Х	Х	Х
SF1	Driver's seat electrically adjustable	Х	Х	Х
SF2	Co-driver's seat electrically adjustable	Х	Х	Х
must	must have COO and VF4 OR VF6, CA/CC only: not with S23			

C01	Driver Convenience Package	\$760	\$760	\$760
E46	12 V power outlet, driver seat base	X	X	Х
F64	Electrically folding exterior mirrors	X	X	Х
FJ1	Hinged lid for storage compartment	X	X	Х
FJ5	Hinged Lid for Storage Compartments left and right	X	X	Х
FZ9	Keys, two additional masters	X	X	X
JA7	Blind Spot Assist	X	X	X
JW8	Attention Assist	Х	Х	Х

C02	Premium Package	\$983	\$983	\$983
CL3	Leather steering wheel	X	X	X
E3M	MBUX Multimedia System with 7" touchscreen	Х	Х	Х
FM3	Wet Wiper System	X	Х	X
JB4	Active Lane Keeping Assist	X	Х	X
JK5	Instrument cluster with color display	Х	Х	X

Ordering availability restricted, see NetStar for availability and restrctions|must have JF1 + XM4; must choose FR8/JB7

CA2	C02 in combination with C03	\$604	\$604	\$604
CL3	Leather steering wheel	X	X	X
FM3	Wet Wiper System	Х	Х	Х
JB4	Active Lane Keeping Assist	Х	Х	X
JK5	Instrument cluster with color display	Х	Х	Х
Orde	Ordering availability restricted, see NetStar for availability and restrctions   must have CO3 + JF1			

### 3500XD CARGO VAN - 4cyl Diesel

Packages

144" 4C	170" 4C	170" E 4C
MXCA44	MXCA74	MXCAE4
907.653	907.655	907.657

C03	Premium Plus Package	\$1,793	\$1,793	\$1,793				
E1B	Tray for smartphones incl. wireless charging	X	Х	Х				
	Navigation	Х	X	Х				
EY2	Intelligent navigation	X	X	Х				
E4M	MBUX Multimedia System with 10.25" touchscreen	X	Х	Х				
EX9	Free map data updates for 3 years	Х	X	X				
H1I	Front-to-rear outlet in instrument panel	X	Х	Х				
JA9	Traffic Sign Assist	Х	Х	Х				
XM4	Acoustic package	X	Х	Х				
must	must have (CA2+JB7) OR (JB4+JK5+FM3+JB7); not with FR8 and CO2							

X67	Chrome Grille Package	\$290	\$290	\$290		
CN2	Radiator grille frame in vehicle color	X	X	X		
FK3	Chrome plated radiator grille (MB only)	X	X	X		
no restrictions						

X13	Exterior Lighting Package	\$1,608	\$1,608	\$1,608		
L13	Fog lamp with cornering light function	X	X	X		
L22	Partial LED tail lights	X	Х	Х		
LA1	High beam assist	X	Х	Х		
LG7	LED high performance headlamps	Х	Х	Χ		
no restrictions						

C06	Cargo Convenience Package	\$658	\$658	\$658				
E36	Cutoff relay for additional battery	X	Х	Х				
ES2	12 V power outlet, rear compartment	X	Х	Х				
LC2	LED light strip in load compartment	X	Х	X				
T12	Sliding door two stage opening	Х	Х	Х				
T85	Assist handle, left rear door	Х	Х	Х				
T86	Assist handles, right rear door	Х	Х	Х				
W54	Rear doors, opening to side wall	Х	Х	S				
must	must have T74 OR (T77+D50) OR (T77+D51)							

C07	Cargo Protection Package	\$1,117	\$1,117	\$1,117		
V25	Half height load compartment trim	X	X	Х		
V42	Lashing rails, waist level	X	X	X		
VC4	Cargo lashing rails, head height	Х	X	X		
VK8	Floor covering, plastic	X	Х	Х		
YK3	Cargo straps, D-rings	Х	Х	Х		
not with X66						

Packages

144" 4C	170" 4C	170" E 4C
MXCA44	MXCA74	MXCAE4
907.653	907.655	907.657

X66	Heavy-Duty-Cargo Protection Package	\$2,043	\$2,043	\$2,043			
V43	Wood floor with 6 D-rings	X	Х	Х			
V42	Lashing rails, waist level	X	Х	Х			
VA3	Side wall paneling full hardboard	Х	Х	Х			
VC4	Cargo lashing rails, head height	X	Х	Х			
VV2	Lashing rails, floor level (plus 4 anchors)	X	Х	Х			
YK3	Cargo straps, D-rings	X	Х	Х			
YK4	Cargo straps, lashing rails	Х	Х	Х			
not with CO7							

X69	Swivel Seat Package	\$532	\$532	\$532			
SR8	Swivel base for driver's seat	Х	Х	Х			
SR9	Swivel base for front passenger seat	Х	Х	Х			
S87	Driver's seat frame, low	Х	Х	Х			
S88	Passenger seat frame, low	Х	Х	Х			
must	must have (C00+C0S) OR (C00+X68)						

F09	SHUTTLE DOOR PREP PACKAGE	\$0	\$0	\$0
SW1	Seat belt deletion, passenger	Х	Х	X
S91	Passener seat, deleted	Х	Х	X
S99	Passenger seat pedestal - deletion	Х	Х	Х

Package deletes standard options: SH2 Thorax-Pelvis sidebag, co-driver; To add/delete from order must call distirbution team

X01	Suspension Seating Package	\$940	\$940	\$940			
SB3	Driver suspension seat, comfort version	X	Х	X			
SB4	Passenger suspension seat, comfort version	Х	Х	Х			
S87	Driver's seat frame, low	Х	Х	Х			
S88	Passenger seat frame, low	Х	Х	Х			
not v	not with C00/C0S/E2I/X68/S23						

170" E 4x4

### 3500XD CARGO VAN - 6cyl Diesel

Standard Equipment

144" 6C

144" 4x4

170" 6C

170" 4x4

170" E 6C

		MXCA46	MXCA4X	MXCA76	MXCA7X	MXCAE6	MXCAEX
		907.653	907.653	907.655	907.655	907.657	907.657
Engin	е						
6-Cyl	Engine/7-Speed Trans.	S	S	S	S	S	5
ED4	AGM battery 12V 92 AH 850 A	S	S	S	S	S	S
G42	Automatic transmission, 7G-tronic	S	S	S	S	S	S
	Alternator 14 V/220 A	S	S	S	S	S	S
MG5	3.0L V6 turbo diesel engine	S	S	S	S	S	S
	SULEV emissions	S	S	S	S	S	S
X30	4x4 Package	-	\$8,200	-	\$8,200	-	\$8,200
_	Door-mounted assist handles, driver & passenger	-	S	-	S	-	S
	4x4 - High range transfer case w/ low gear	-	S	-	S	-	S
	- choose while ordering	4 -	4-	4-	4-	4 -	4-
X34	Dual Rear Wheel	\$0	\$0	\$0	\$0	\$0	<i>\$0</i>
	Tires LT 215/85 R16	S	S	S	S	S	S
	5.5 J x 16 steel wheels	S	S	S	S	S	S
_	Unspecified tire brand	S	S	S	S	S	S
	Super Single Tire	\$385	-	\$385	-	\$385	-
	285/65 R 16 C super single tires Steel wheels: 8.5Jx16 Rr; 6.5Jx16 Fr	0	-	0	-	0	-
	Unspecified tire brand	0	-	0	-	0	-
RD9 RY2	-	0	-	0	-	0	-
Equip	Tire pressure monitoring sensors	0	-	0	-	0	-
	Axle ratio 3.923	0	S	0	S	0	S
_	Axle ratio 3.925 Axle ratio 4.182	S	-	O S	-	O S	5
	Active Brake Assist	S	S	S	S	S	S
-	Hold Function	S	S	S	S	S	S
	Multifunction steering wheel	S	S	S	S	S	S
	Stabilization Level II	S	-	S	_	S	-
CL1	Adjustable steering wheel (angle)	S	S	S	S	S	S
	High roof	0	0	S	S	S	S
	Omission bulkhead	S	S	S	S	S	S
	Hill Start Assist	S	S	S	S	S	S
-	Standard radio	S	S	S	S	S	S
	USB-C socket, 5 V	S	S	S	S	S	S
	Starter battery disconnect	S	S	S	S	S	S
_	Pre-installation for switch panel	S	-	S	-	S	-
_	Trailer hitch prep. wiring	S	S	S	S	S	S
ED8	Preinstallation PSM	S	S	S	S	S	S
EE5	Ultracapacitor discharge module	S	S	S	S	S	S
EK1	Body Builder Connector	S	S	S	S	S	S
ES0	Jump start terminal	S	S	S	S	S	S
EW6	Pre-installation for Mercedes me Remote Services	S	S	S	S	S	S
EY5	Emergency Call System	S	S	S	S	S	S
EY6	Breakdown management	S	S	S	S	S	S
F68	Heated & electrically adjustable exterior mirrors	S	S	S	S	S	S
FF5	Shelf above windshield	S	S	S	S	S	S
FG8	Cupholder front	S	S	S	S	S	S
FI1	Remote key (315 mhz) w/central locking	S	S	S	S	S	S
	Storage compartment underneath cockpit	S	S	S	S	S	S
FR3	Rear view camera (rear-view mirror display)	S	S	S	S	S	S
H21	Windshield with filter band	S	S	S	S	S	S
	Heater, auxiliary electric hot air	S	S	S	S	S	S
	Air Condition, Front	S	S	S	S	S	S
	Head Unit, North America	S	S	S	S	S	S
J11	Speedometer, miles and km/h	S	S	S	S	S	S
	Seat belt warning for co-driver seat	S	S	S	S	S	S
_	Seat belt reminder driver	S	S	S	S	S	S
J65	Outside temperature gauge	S	S	S	S	S	S
JA8	Crosswind Assist	S	S	S	S	S	S

### 3500XD CARGO VAN - 6cyl Diesel

Standard Equipment

		144" 6C	144" 4x4	170" 6C	170" 4x4	170" E 6C	170" E 4x4
		MXCA46	MXCA4X	MXCA76	MXCA7X	MXCAE6	MXCAEX
		907.653	907.653	907.655	907.655	907.657	907.657
JH3	Communication module (LTE) for dig. services	S	S	S	S	S	S
JI9	Service interval 20.000 miles	S	S	S	S	S	S
K56	Red diesel filler cap	S	S	S	S	S	S
K60	Exhaust straight to rear	S	S	S	S	S	S
KB7	24.5 gallon fuel tank	S	S	S	S	S	S
KL1	Aux fuel sending unit w/ fuel tap	S	S	S	S	S	S
KL5	Fuel filter with water separator	S	S	S	S	S	S
KP6	3rd generation SCR emission control system	S	S	S	S	S	S
L65	Interior lights, cargo compartment	S	S	S	S	S	S
L94	Parking lights deletion	S	S	S	S	S	S
LA2	Headlight assistant	S	S	S	S	S	S
LB5	3rd brake light	S	S	S	S	S	S
MS1	Cruise control	S	S	S	S	S	S
P47	Front mudflaps	S	S	S	S	S	S
P48	Rear mudflaps	S	S	S	S	S	S
Q11	Longitudinal member reinforcement	S	S	S	S	S	S
R65	Spare tire bracket below frame	S	S	S	S	S	S
R87	Spare tire	S	S	S	S	S	S
RM0	All-season tires	S	S	S	S	S	S
S02	Standard driver seat	S	S	S	S	S	S
S04	Standard front passenger seat	S	S	S	S	S	S
S22	Armrest for driver's seat	S	S	S	S	S	S
S25	Armrest for front passenger seat	S	S	S	S	S	S
SA5	Front airbag, driver	S	S	S	S	S	S
SA6	Front airbag, passenger	S	S	S	S	S	S
SH1	Thorax-pelvis sidebag, driver	S	S	S	S	S	S
SH2	Thorax-pelvis sidebag, co-driver	S	S	S	S	S	S
SH9	Airbag, driver/passenger window	S	S	S	S	S	S
SK2	Seat occupancy sensor, driver's seat	S	S	S	S	S	S
T16	Sliding door, passenger side	S	S	S	S	S	S
V93	Without factory installed flooring	S	S	S	S	S	S
V94	Cable duct - side wall	S	S	S	S	S	S
V95	Cable duct - rear portal	S	S	S	S	S	S
W54	Rear doors, opening to side wall	0	0	0	0	S	S
X5G	Witout load uprating/derating 5,000 kg	S	S	S	S	S	S
Y43	Jack, hydraulic	S	S	S	S	S	S

		144" 6C	144" 4x4	170" 6C	170" 4x4	170" E 6C	170" E 4x4
		MXCA46	MXCA4X	MXCA76	MXCA7X	MXCAE6	MXCAEX
		907.653	907.653	907.655	907.655	907.657	907.657
A50	Front axle reinforced	\$346	-	\$346	-	\$346	-
AP2	Addtl. bar for driveshaft & exhaust extension	\$69	\$69	\$69	\$69	-	-
-	Axle ratio 3.923	\$0	S	\$0	S	\$0	S
	not with AR3	, -	_	, -		, -	-
B01	ESP for increased Center of Gravity above 39.4"	-	-	\$0	\$0	\$0	\$0
	must have CB4/CB8/X30; not with RH0/CB7			, -	, -	, -	, -
BE2	Handbrake lever, folding	\$55	\$55	\$55	\$55	\$55	\$55
	X69 must have BE2	•		•			
CB4	Stabilization Level III	\$187	-	\$187	-	\$187	-
	not with CB7/CB8/X30						
C72	Bumpers front/rear primed	\$268	\$268	\$268	\$268	\$268	\$268
	must have CN2 (part of X67), not with CM0	·		·	·		
CE8	Raised rear body mounts	\$252	-	\$252	-	\$252	-
CL3	Leather steering wheel	\$187	\$187	\$187	\$187	\$187	\$187
	must have (C02/E3M)/C03 + (ET4/MS1)		·				·
CM0	Painted metallic front & rear bumper	\$587	\$587	\$587	\$587	\$587	\$587
	must have (CN2/X67) + (JA7/C01) + JB7 + (7755/9197/9775)		·				·
CM9	Primed side moldings	\$364	\$364	\$364	\$364	\$364	\$364
_	High roof	\$2,900	\$2,900	S	S	S	S
D13	Mounting rails for roof rack	\$300	\$300	\$300	\$300	\$300	\$300
D22	Fixed sunroof (rear roof section)	\$336	\$336	\$336	\$336	\$336	\$336
	not with H08/HK4/H72/V36/ZK4						
D50	Cargo partition	\$288	\$288	\$288	\$288	\$288	\$288
	not with D51/D93/H08/HK4/T74/V36; must have one of T93/T77		<u>.                                      </u>				
D51	Cargo partition with 1 window	\$335	\$335	\$335	\$335	\$335	\$335
	not with D50/D93/H08/HK4/T74/V37/D17; must have one of T93/T77		·				·
E1B	Tray for smartphones incl. wireless charging	\$156	\$156	\$156	\$156	\$156	\$156
	must have CO2/E3M + H1I						
E1E	Navigation	\$728	\$728	\$728	\$728	\$728	\$728
	must have CO2/E3M, not with CO3						
E1S	Sirius XM, satellite radio	\$255	\$255	\$255	\$255	\$255	\$255
	must have CO2/E3M/CO3						
E1X	MBUX multimedia 6-hour runtime	-	-	\$0	\$0	\$0	\$0
	must have X2R + (C02+E1E/E1S)/C03/(E3M+E1E/E1S)						
E1R	Additional Fuses (40/80/150/100 Ampere)	\$50	\$50	\$50	\$50	\$50	\$50
	SoP and Plausibility TBD						
E1Y	Additional Fuses (40/80/80/100 Ampere)	\$50	\$50	\$50	\$50	\$50	\$50
	SoP and Plausibility TBD						
E2A	Access point for BB special signals in cockpit	\$29	\$29	\$29	\$29	\$29	\$29
E2I	Additional battery, co-driver seat base	\$248	\$248	\$248	\$248	\$248	\$248
	must have E36/C06; not with E2M/F09; CHS production only						
E2M	Additional battery, engine compartment	\$248	\$248	\$248	\$248	\$248	\$248
	must have X01+ (E36/C06); not with E2I/X69/F09						
E3M	MBUX Multimedia System with 7" touchscreen	\$474	\$474	\$474	\$474	\$474	\$474
	not with CO2/CO3; must have JK5+(JB7/FR8)						
E36	Cutoff relay for additional battery	\$110	\$110	\$110	\$110	\$110	\$110
	standard with E2I/E2M						
E46	12 V power outlet, driver seat base	\$92	\$92	\$92	\$92	\$92	\$92
E5M	Extension of PSM standard contact	\$58	\$58	\$58	\$58	\$58	\$58
ED5	Parametric special module (PSM)	\$317	\$317	\$317	\$317	\$317	\$317
	not with ED8						
EE3	115 V socket	\$125	\$125	\$125	\$125	\$125	\$125
EP7	Basic electric fitting for rear loudspeakers	\$68	\$68	\$68	\$68	\$68	\$68
ES2	12 V power outlet, rear compartment	\$92	\$92	\$92	\$92	\$92	\$92
ES5	Charging package, dashboard	\$82	\$82	\$82	\$82	\$82	\$82
ET4	Active Distance Assist DISTRONIC	\$263	\$263	\$263	\$263	\$263	\$263
	must have CO2/CO3/E3M; not with ZH4						

			I				
		144" 6C	144" 4x4	170" 6C	170" 4x4	170" E 6C	170" E 4x4
		MXCA46	MXCA4X	MXCA76	MXCA7X	MXCAE6	MXCAEX
		907.653	907.653	907.655	907.655	907.657	907.657
F1K	Coat hooks in driver cabin	\$14	\$14	\$14	\$14	\$14	\$14
111	must have D50/D51	717	7=-	717	Y = -	717	㱬
F49	Electrically heated windshield	\$218	\$218	\$218	\$218	\$218	\$218
149	no restriction	<b>7218</b>	<b>7210</b>	7210	7210	7210	<b>Σ210</b>
F61	Interior rear view mirror	\$36	\$36	\$36	\$36	\$36	\$36
L01		\$30	<b>330</b>	<b>330</b>	Ş30 ————————————————————————————————————	<b>330</b>	<b>330</b>
	not with D50; must have C02/E3M/C03	C01	Ć01	Ć01	Ć01	¢01	Ć01
FE9	Additional DIN-slot	\$81	\$81	\$81	\$81	\$81	\$81
FF4	Storage compartment above cabin	\$186	\$186	\$186	\$186	\$186	\$186
	must have D03, not with D17/D64/H08/HK4	4405	6405	6405	6405	6405	6405
FF8	Overhead storage slot, front center	\$105	\$105	\$105	\$105	\$105	\$105
FJ1	Hinged lid for storage compartment	\$93	\$93	\$93	\$93	\$93	\$93
FR8	Rear view camera (head unit display)	\$336	\$336	\$336	\$336	\$336	\$336
	must have CO2/E3M; not with FR3/JB7; 3500XD not with JB8			,		,	
FY1	Security alarm w. interior motion sensor	\$584	\$584	\$584	\$584	\$584	\$584
	must have LC4/C00						
FY7	Optional 3-button keys	\$36	\$36	\$36	\$36	\$36	\$36
FZ9	Keys, two additional masters	\$121	\$121	\$121	\$121	\$121	\$121
H00	Warm/cool air duct to rear compartment	\$59	\$59	\$59	\$59	\$59	\$59
	not with D50/D51/Y2A						
H01	Heat insulation, rear compartment	\$156	\$156	\$156	\$156	\$156	\$156
	must have V21/V25/VA3/VA1/C07/X66						
H04	Heat insulation, front compartment	\$187	\$187	\$187	\$187	\$187	\$187
	if + D50/D51 must have V07			,			
H08	Air conditioning rear, roof-mounted	\$2,872	\$2,872	\$2,872	\$2,872	\$2,872	\$2,872
	must have D93 +V36; not with HK4/C06/X66/C07		-		-		
H12	Fuel-fired pre-heater/booster (17K BTU)	\$1,116	\$1,116	\$1,116	\$1,116	\$1,116	\$1,116
	not with HZ9	•					
H13	Rear cabin heater and vents	\$786	\$786	\$786	\$786	\$786	\$786
	must have H12/HZ9						
H15	Heated front passenger seat	\$284	\$284	\$284	\$284	\$284	\$284
	must have H16; not with X68		,	,	,	,	
H16	Heated driver's seat	\$284	\$284	\$284	\$284	\$284	\$284
	must have H15; not with X68	7-0	7	7	7	7-5	7-0
H22	Rear window defroster	\$253	\$253	\$253	\$253	\$253	\$253
	must have W61/W78; standard for W61+W70	Ÿ233	<b>7233</b>	<b>Q233</b>	<b>V</b> 233	<b>Ç</b> 233	<b>Ψ233</b>
H72	Roof fan, electric	\$400	\$400	\$400	\$400	\$400	\$400
1172	not with D22/V36	Ş <del>-1</del> 00	) <del>7-00</del>	Ş <del>-1</del> 00	) <del></del>	Ş <del>-1</del> 00	<del>у 1</del> 00
H88	Rear heater prep	\$405	\$405	\$405	\$405	\$405	\$405
1100	must have H12/HZ9; not with H13/T19	3403	Ş <del>4</del> 03	Ş <del>4</del> 03	Ş <del>4</del> 03	Ş <del>4</del> 03	3 <del>4</del> 03
Ш11	Front-to-rear outlet in instrument panel	\$0	\$0	\$0	\$0	\$0	\$0
H1I	·	<b>Ş</b> U	ŞU	ŞU	ŞU	ŞU	ŞU
	must have FJ1/C01	6227	6227	6227	6227	6227	6227
HH4	Thermotronic automatic climate control	\$337	\$337	\$337	\$337	\$337	\$337
1117.5	must have JF1; if +H13 must have H08/HK4	62.010	62.010	62.040	62.040	62.010	62.040
HK4	Rear air conditioner, heavyduty	\$3,940	\$3,940	\$3,940	\$3,940	\$3,940	\$3,940
	must have D03+V36+D93; not with H08/ZB6/ZE6/N62/N63	1 4	1 4	1 4	1 4	4	4
HZ9	Fuel-fired heater booster (18,000 BTU)	\$676	\$676	\$676	\$676	\$676	\$676
<u></u>	not with H12						
J51	Fuel gauge, optimized for aux. fuel tap	\$72	\$72	\$72	\$72	\$72	\$72
	not with HZ9/H12		1				
J52	Engine oil level display at cold start	\$0	\$0	\$0	\$0	\$0	\$0
JA7	Blind Spot Assist	\$450	\$450	\$450	\$450	\$450	\$450
	not with CO1						
JB4	Active Lane Keeping Assist	\$288	\$288	\$288	\$288	\$288	\$288
	standard with CO2/CA2						
JB7	Parking Package	\$615	\$615	\$615	\$615	\$615	\$615
	must have CO2/CO3/E3M; not with W75/W76/JB6	_					
JF1	Rain sensor	\$106	\$106	\$106	\$106	\$106	\$106
	•	•					

			1				
		144" 6C	144" 4x4	170" 6C	170" 4x4	170" E 6C	170" E 4x4
		MXCA46	MXCA4X	MXCA76	MXCA7X	MXCAE6	MXCAEX
		907.653	907.653	907.655	907.655	907.657	907.657
JK5	Instrument cluster with color display	\$144	\$144	\$144	\$144	\$144	\$144
	standard with CO2/CA2						
JW0	Backup alarm	\$99	\$99	\$99	\$99	\$99	\$99
JW2	Deactivation lamp monitoring failure	\$27	\$27	\$27	\$27	\$27	\$27
JW8	Attention Assist	\$49	\$49	\$49	\$49	\$49	\$49
K51	Misfueling prevention for Diesel	\$49	\$49	\$49	\$49	\$49	\$49
K52	DEF fluid filler cap - lockable	\$27	\$27	\$27	\$27	\$27	\$27
L13	Fog lamp with cornering light function	\$199	\$199	\$199	\$199	\$199	\$199
L71	Light/motion sensor in rear compartment	\$54	\$54	\$54	\$54	\$54	\$54
	not with V36			1			
	Illuminated front exits	\$151	\$151	\$151	\$151	\$151	\$151
LC2	LED light strip in load compartment	\$263	\$263	\$263	\$263	\$263	\$263
	not with H08/HK4/V36/C06			1			
	Comfort overhead control panel	\$93	\$93	\$93	\$93	\$93	\$93
M20	Speed limitation 65 mph	\$60	\$60	\$60	\$60	\$60	\$60
	not with MD3	1	•	1	•		
MD3	Top speed limitation 75 mph	\$60	\$60	\$60	\$60	\$60	\$60
	not with M20	1	•	1	•		
N62	Front engine bracket for additional alternator	\$467	\$467	\$467	\$467	\$467	\$467
	not with HK4/N63	1	•	1	•		
N63	Front engine bracket for auxiliary A/C compressor	\$467	\$467	\$467	\$467	\$467	\$467
	not with HK4/N62	_	_	•			
P93	Omission of D-rings	-\$15	-\$15	-\$15	-\$15	-\$15	-\$15
	not with D93/V43/VK8	1	•	1	•		
QA2	Trailer cross member 7,500 lbs capacity	\$186	\$186	\$186	\$186	-	-
	not with W73/W75/W76/Q24/Q67	_					
QA9	Half-sided step rear (for trailer hitch)	\$101	\$101	\$101	\$101	\$101	\$101
	must have QA2; not with W73/W75/W76						
Q24	Trailer hitch, 5,000 lbs	-	-	-	-	\$147	\$147
	not with W73/W75/W76						
R91	Spare tire deletion	-\$110	-\$110	-\$110	-\$110	-\$110	-\$110
	must have R92; not with R87						
R92	Spare tire carrier deletion	\$0	\$0	\$0	\$0	\$0	\$0
	must have R91; not with R65					,	
R98	Rims painted jet black	\$81	\$81	\$81	\$81	\$81	\$81
	not with RL5/RM2						
RF1	Tire brand Continental	\$0	\$0	\$0	\$0	\$0	\$0
	must have RM1 + RM9						
RF8	Tire brand Michelin	\$0	\$0	\$0	\$0	\$0	\$0
	must have RM9; not with RM1	1 40	1 4-		1 40	4.0	4.5
RH0	Tire brand Kumho	\$0	\$0	\$0	\$0	\$0	\$0
	must have RM9; not with RM1	44.50	1 4460	44.50	44.50	44.50	44.50
RM1	M+S winter tires	\$169	\$169	\$169	\$169	\$169	\$169
	must have RF1/RD9; not with RF8/RH0/X31	1 40.	T 40.	40.	1 40.	40.	40.
RM2	Rims painted arctic white	\$81	\$81	\$81	\$81	\$81	\$81
	not with R98/RL5	1 4.5.	1 4.5.	4.5.	4.5.	4.5.	4.5.
RM9	Specially requested tires	\$101	\$101	\$101	\$101	\$101	\$101
	must have RF1/RF8/RH0; not with RD9	1 4	1 4.00	4.00	4.00	4.00	4.55
S23	Twin front passenger seat	\$400	\$400	\$400	\$400	\$400	\$400
622	not with C00/X68/X01	A-4	A=4	Å=4	Å=4	ÅF.	A.c.
	Armrest, driver and passenger door	\$51	\$51	\$51	\$51	\$51	\$51
S62	Seat belts orange, driver and front passenger	\$32	\$32	\$32	\$32	\$32	\$32
555	not with S23	40.55	4222	4222	4225	4222	<b>4005</b>
SB9	Driver's seat plus	\$238	\$238	\$238	\$238	\$238	\$238
	must have VF7; not with C00/X68/X69	4.0	1 40.	4.0	4.0	4.0.0	4.5.4
	Storage net, driver's seat backrest	\$64	\$64	\$64	\$64	\$64	\$64
SZ8	Storage net, passenger seat backrest	\$64	\$64	\$64	\$64	\$64	\$64

				ı			
		144" 6C	144" 4x4	170" 6C	170'' 4x4	170" E 6C	170" E 4x4
		MXCA46	MXCA4X	MXCA76	MXCA7X	MXCAE6	MXCAEX
		907.653	907.653	907.655	907.655	907.657	907.657
T12	Sliding door two stage opening	\$82	\$82	\$82	\$82	\$82	\$82
	not with T55		<u> </u>	·		<u>·</u>	
T19	Sliding door, driver's side	\$935	\$935	\$935	\$935	\$935	\$935
	not with H13/H88/VC5/ZE6/F43/W16/F02; if +V36 must have D03		•				
T50	Electric closing assist right sliding door	\$335	\$335	\$335	\$335	\$335	\$335
	must have D03; not with T55/T93						
T51	Electric closing assist left sliding door	\$335	\$335	\$335	\$335	\$335	\$335
	must have T19 + D03						
T55	Electric sliding door right	\$831	\$831	\$831	\$831	\$831	\$831
	must have D03 + (FY7+T16); not with T12/T50		1	1			
T57	Electric sliding step	\$1,071	\$1,071	\$1,071	\$1,071	\$1,071	\$1,071
	must have ED5; not with T93						
T60	Opening limiter electrically operated sliding door	\$120	\$120	\$120	\$120	\$120	\$120
	must have T55	100	1 400	455	400	4	400
T74	Assist handle, B-pillar	\$32	\$32	\$32	\$32	\$32	\$32
	must have D93; not with T77	450		ć.co	6	ĆE0	dE0
T75	Door-mounted assist handles, driver & passenger	\$59	S	\$59	Ś	\$59	\$59
T77	Assist handle w/ partition	\$32	\$32	\$32	\$32	\$32	\$32
тог	must have D50/D51/D64	\$32	\$32	\$32	\$32	\$32	\$32
T85	Assist handle, left rear door						-
T86 T93	Assist handles, right rear door Sliding door right side deletion	\$32 \$0	\$32 \$0	\$32 \$0	\$32 \$0	\$32 \$0	\$32 \$0
193	not with T16/T50/T57/VK8/VC5	ŞU	ŞU	ŞU	ŞU	ŞU	ŞU
V07	Cab rear wall liner	\$360	\$360	\$360	\$360	\$360	\$360
V07	must have (D50/D51)+F1K; standard with H04	3300	<b>3300</b>	<b>3300</b>	<b>3300</b>	<b>3300</b>	\$300
V21	Luxury interior Trim	\$661	\$661	\$661	\$661	\$661	\$661
VZI	must have VA5/VA7; not with V52/VA1/VA3	7001	7001	7001	7001	7001	7001
V24	Pallet support in sliding door step	\$96	\$96	\$96	\$96	\$96	\$96
V2-7	must have (V43/X66)+(D50/D51); not with VK8/V93/C07	750	750	750	750	750	730
V25	Half height load compartment trim	\$201	\$201	\$201	\$201	\$201	\$201
-	not with VA1/VA3/VA5/V52/X66	7	1 7	7-5-	7-0-	7-0-	7-0-
V31	Window pillar trim	\$513	\$513	\$513	\$513	\$513	\$513
	must have V36 + (V21/VA1) + (F02/F03/F07); not with V42		, , , , , , , , , , , , , , , , , , ,	,			·
V35	Wheel house covering	\$105	\$105	\$105	\$105	\$105	\$105
	if +V43 must have V25/VA1/VA3; not with V52	<u>.</u>			· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·	
V36	Roof trim	\$876	\$876	\$876	\$876	\$876	\$876
	must have D93; not with D17/D22/H72/L65/L71/LC2/VA3/V42/ZE6/(7	T93+-D03)/X	66/C06/C07				
V42	Lashing rails, waist level	\$277	\$277	\$277	\$277	\$277	\$277
	not with V36/ZE6						
V43	Wood floor with 6 D-rings	\$422	\$422	\$422	\$422	\$422	\$422
	not with P93/V93/VL4/VK8/C07; standard with D93/H13/V24/V52/V	C5/VV2/ZE6					
V48	Floor cover behind seat box	\$27	\$27	\$27	\$27	\$27	\$27
	must have D93; not with D50/D51/D56/D62/D64/V43/VK5	•					
V4A	Full paneling, right sliding door	\$109	\$109	\$109	\$109	\$109	\$109
	must have D03+T16+V21+VA5+W17; not with T19		1				
V85	Cigarette lighter & ash cup, front	\$39	\$39	\$39	\$39	\$39	\$39
VA1	Side wall paneling waist height PVC	\$319	\$319	\$319	\$319	\$319	\$319
	must have VA5/VA7; not with V52			,			
VA3	Side wall paneling full hardboard	\$444	\$444	\$444	\$444	\$444	\$444
	not with V36/F02; if T93 must have (D50/D51)	455	A	45.5	455	Aca	Acc
VA5	Full paneling, hinged rear doors	\$38	\$38	\$38	\$38	\$38	\$38
\	must have D03+VA7+(W61/W78); not with V25	A10-	A40-	A40-	640-	640=	Å10=
VA7	Storage compart. w/ net in rear doors	\$127	\$127	\$127	\$127	\$127	\$127
VC1	must have W61/W78; not with V52	Ć44=	¢445	¢445	Ć 44 F	¢ 44.5	¢445
VC4	Cargo lashing rails, head height	\$415	\$415	\$415	\$415	\$415	\$415
VCE	must have V42/C07/X66; not with ZE6	674	674	674	674	Ć74	Ċ74
VC5	Door sill - protective edge  must have V43/X66; not with T19/T93/VK8/VV2/V93/C07	\$71	\$71	\$71	\$71	\$71	\$71
<u></u>							

		144" 6C	144" 4x4	170" 6C	170" 4x4	170" E 6C	170'' E 4x4
		MXCA46	MXCA4X	MXCA76	MXCA7X	MXCAE6	MXCAEX
		907.653	907.653	907.655	907.655	907.657	907.657
	let						
VK8	Floor covering, plastic	\$370	\$370	\$370	\$370	\$370	\$370
	not with V43/P93/T19/T93/V52/VC5/X66	6270	6270	62.45	62.45	6277	6277
VV2	Lashing rails, floor level (plus 4 anchors)	\$270	\$270	\$345	\$345	\$377	\$377
1446	must have V43; not with V93/VC5/ZE6	A4.45	A 4 4 5	A4.45	A4.45	A4.45	A4.4=
W16	2nd row, fixed window, driver side	\$145	\$145	\$145	\$145	\$145	\$145
	if D93 must have F43+W70; if D93 & standard roof CHS production re	i		,	,	,	
W17	2nd row, fixed window, passenger side	\$145	\$145	\$145	\$145	\$145	\$145
	if D93 must have F43+W70; if D93 & standard roof CHS production re	i					
W33	FMVSS 217 emergency exit	\$379	\$379	\$379	\$379	\$379	\$379
	must have V31; not with D50/T19/W16						
	Rear doors, opening to side wall	\$360	\$360	\$360	\$360	S	S
W5F	90 Degree fixation point- Rear Doors	\$80	\$80	\$80	\$80	\$80	\$80
	SoP and Plausibility TBD						
W61	Windows in rear doors	\$93	\$93	\$93	\$93	\$93	\$93
	must have VA7/ if D51 must have F61; not with W78/(W70+-(H22/F0						
W70	Black tinting (90%) for rear windows	\$138	\$138	\$138	\$138	\$138	\$138
	not with W94; must have W16/W17/F02/((W61/W78)+H22); standar	d with F43/V	V33/F07				
W73	Bumper step, rear, grey	\$187	\$187	\$187	\$187	\$187	\$187
	not with QA2/W75/W76						
W75	Step, wide, at rear end	\$308	-	\$308	-	\$308	-
	not with JB6/JB7/Q24/QA9; must have R91+R92						
W76	Bumper step, rear, spring-loaded	-	-	\$601	-	\$601	-
	must have R91+R92; not with JB6/JB7/X30/Q24	•	•	•	•	•	
W78	Heated rear window(s) w/ washers/wipers	\$335	\$335	\$335	\$335	\$335	\$335
	Must have H22+VA7 / if D51 must have F61; not with W61						
X2R	Conversion to RV requirement	-	-	\$0	\$0	\$0	\$0
	must have B01+D93+E1X	•	-				
X90	Deletion of Sprinter badge, left rear door	\$0	\$0	\$0	\$0	\$0	\$0
X93	Deletion of model badge, right rear door	\$0	\$0	\$0	\$0	\$0	\$0
XM4	Acoustic package	\$87	\$87	\$87	\$87	\$87	\$87
	standard with CO2/CO3						
Y10	First-aid kit	\$27	\$27	\$27	\$27	\$27	\$27
Y26	Wheel chocks	\$38	\$38	\$38	\$38	\$38	\$38
Y45	Emergency flashlight	\$27	\$27	\$27	\$27	\$27	\$27
Y68	Paint preservative	\$187	\$187	\$212	\$212	\$225	\$225
Y69	Surface protection for stock vehicles	\$315	\$315	\$315	\$315	\$315	\$315
YK3	Cargo straps, D-rings	\$81	\$81	\$81	\$81	\$81	\$81
YK4	Cargo straps, lashing rails	\$104	\$104	\$104	\$104	\$104	\$104
	must have V42/VV2; not with ZE6	,					
ZE6	Shelving prep	\$640	\$640	\$640	\$640	\$640	\$640
<b>-</b>	not with T93/H13/T19/V36/V42/VC4/VK8/VV2/YK4	73.0	75.0	75.0	75.0	70.0	7
ZH4	Downhill speed regulation for 4x4	-	\$58	_	\$58	_	\$58
<u> </u>	must have ED5; not with ET4		<b>J 930</b>		930		730
	mast have EDS, not with E14						

Packages

		144" 6C	144" 4x4	170" 6C	170'' 4x4	170" E 6C	170" E 4x4
		MXCA46	MXCA4X	MXCA76	MXCA7X	MXCAE6	MXCAEX
		907.653	907.653	907.655	907.655	907.657	907.657
C00	Comfort Package	\$300	\$300	\$300	\$300	\$300	\$300
LC4	Comfort overhead control panel	Х	Х	Х	Х	Х	X
SE4	Lumbar support, co-driver's seat	Х	Х	Х	Х	Х	X
SE5	Lumbar support, driver's seat	Х	Х	Х	Х	Х	X
SK0	Comfort head restraint, driver	Х	Х	Х	Х	Х	X
SK1	Comfort head restraint, co-driver	Х	Х	Х	Х	Х	Х
S28	Armrest, driver and passenger door	Х	Х	Х	Х	Х	Х
must	have COS OR X68; CA/CC only: not with S23						

COS	Comfort Package (Seat addition)	\$381	\$381	\$381	\$381	\$381	\$381
SB1	Comfort driver's seat	Х	Х	Х	Х	Х	Х
SB2	Comfort passenger seat	Х	Х	Х	Х	Х	Х
must	have COO	_				_	

X68	Comfort Plus Package	\$1,923	\$1,923	\$1,923	\$1,923	\$1,923	\$1,923	
H15	Heated front passenger seat	Х	Х	Х	X	Х	X	
H16	Heated driver's seat	Х	Х	Х	Х	Х	Х	
SF1	Driver's seat electrically adjustable	Х	Х	Х	Х	Х	Х	
SF2	Co-driver's seat electrically adjustable	Х	Х	Х	Х	Х	Х	
must	must have C00 and VF4 OR VF6, CA/CC only: not with S23							

C01	Driver Convenience Package	\$760	\$760	\$760	\$760	\$760	\$760
E46	12 V power outlet, driver seat base	Х	Х	Х	Х	Х	Х
f64	Electrically folding exterior mirrors	Х	Х	Х	Х	Х	Х
FJ1	Hinged lid for storage compartment	Х	Х	Х	Х	Х	Х
FJ5	Hinged Lid for Storage Compartments left and right	Х	Х	Х	Х	Х	Х
FZ9	Keys, two additional masters	Х	Х	Х	Х	Х	Х
JA7	Blind Spot Assist	Х	Х	Х	Х	Х	Х
JW8	Attention Assist	Х	Х	Х	Х	Х	Х

C02	Premium Package	\$983	\$983	\$983	\$983	\$983	\$983		
CL3	Leather steering wheel	Х	Х	Х	Х	Х	Х		
E3M	MBUX Multimedia System with 7" touchscreen	Х	Х	Х	Х	Х	Х		
FM3	Wet Wiper System	Х	Х	Х	Х	Х	Х		
JB4	Active Lane Keeping Assist	Х	Х	Х	Х	Х	Х		
JK5	Instrument cluster with color display	Х	Х	Х	Х	Х	Х		
Orde	Ordering availability restricted, see NetStar for availability and restrctions   must have JF1 + XM4; must choose FR8/JB7								

CA2	C02 in combination with C03	\$604	\$604	\$604	\$604	\$604	\$604		
CL3	Leather steering wheel	Х	Х	Х	X	Х	Х		
FM3	Wet Wiper System	Х	Х	Х	Х	Х	Х		
JB4	Active Lane Keeping Assist	Х	Х	Х	Х	Х	Х		
JK5	Instrument cluster with color display	Х	Х	Х	Х	Х	Х		
Orde	Ordering availability restricted, see NetStar for availability and restrctions   must have CO3 + JF1								

#### 3500XD CARGO VAN - 6cyl Diesel Packages

144" 6C	144" 4x4	170" 6C	170'' 4x4	170" E 6C	170" E 4x4
MXCA46	MXCA4X	MXCA76	MXCA7X	MXCAE6	MXCAEX
907.653	907.653	907.655	907.655	907.657	907.657

C03	Premium Plus Package	\$1,793	\$1,793	\$1,793	\$1,793	\$1,793	\$1,793
E1B	Tray for smartphones incl. wireless charging	Х	Х	X	Х	Х	Х
	Navigation	Х	Х	Х	Х	Х	Х
EY2	Intelligent navigation	Х	Х	X	Х	X	Х
E4M	MBUX Multimedia System with 10.25" touchscreen	Х	Х	Х	X	Х	Х
EX9	Free map data updates for 3 years	Х	Х	Χ	Х	Х	X
H1I	Front-to-rear outlet in instrument panel	Х	Х	Χ	Х	Х	X
JA9	Traffic Sign Assist	Х	Х	X	Х	Х	X
XM4	Acoustic package	Х	Х	Х	Х	Х	X
must	: have (CA2+JB7) OR (JB4+JK5+FM3+JB7); not with F	R8 and C02	-	-		-	

X67	Chrome Grille Package	\$290	\$290	\$290	\$290	\$290	\$290	
CN2	Radiator grille frame in vehicle color	Х	X	X	X	X	X	
FK3	Chrome plated radiator grille (MB only)	Х	X	X	X	X	X	
no re	no restrictions							

X13	Exterior Lighting Package	\$1,608	\$1,608	\$1,608	\$1,608	\$1,608	\$1,608			
L13	Fog lamp with cornering light function	Х	Х	Х	Х	Х	Х			
L22	Partial LED tail lights	Х	Х	Х	Х	Х	Х			
LA1	High beam assist	Х	Х	Х	Х	Х	Х			
LG7	LED high performance headlamps	Х	Х	Х	Х	Х	Х			
no re	no restrictions									

C06	Cargo Convenience Package	\$658	\$658	\$658	\$658	\$658	\$658
E36	Cutoff relay for additional battery	Х	Х	Х	Χ	Х	Х
ES2	12 V power outlet, rear compartment	Х	Х	Х	Χ	Х	Х
LC2	LED light strip in load compartment	Х	Х	Х	Х	Х	Х
T12	Sliding door two stage opening	Х	Х	Х	Х	Х	Х
T85	Assist handle, left rear door	Х	Х	Х	Х	Х	Х
T86	Assist handles, right rear door	Х	Х	Х	Х	Х	Х
W54	Rear doors, opening to side wall	Х	Х	Х	Х	S	S
must	have T74 OR (T77+D50) OR (T77+D51)		,	,			

C07	Cargo Protection Package	\$1,117	\$1,117	\$1,117	\$1,117	\$1,117	\$1,117		
V25	Half height load compartment trim	Х	Χ	Х	X	X	X		
V42	Lashing rails, waist level	Х	X	Х	X	X	Х		
VC4	Cargo lashing rails, head height	Х	X	Х	X	X	X		
VK8	Floor covering, plastic	Х	X	Х	X	X	X		
YK3	Cargo straps, D-rings	Х	X	Х	X	X	X		
not v	not with X66								

X66	Heavy-Duty-Cargo Protection Package	\$2,043	\$2,043	\$2,043	\$2,043	\$2,043	\$2,043		
V43	Wood floor with 6 D-rings	Х	Х	Х	Х	Х	Х		
V42	Lashing rails, waist level	Х	Х	Х	Х	Х	Х		
V52	Loadable wheel arch	X	Х	Х	Х	Х	Х		
VA3	Side wall paneling full hardboard	X	Х	Х	Х	Х	Х		
VC4	Cargo lashing rails, head height	Х	Х	Х	Х	Х	Х		
VV2	Lashing rails, floor level (plus 4 anchors)	Х	Х	Х	Х	Х	Х		
YK3	Cargo straps, D-rings	Х	Х	Х	Х	Х	Х		
YK4	Cargo straps, lashing rails	Х	Х	Х	Х	Х	Х		
not v	not with CO7								

### 3500XD CARGO VAN - 6cyl Diesel

11,030 GVWR

Packages

144" 6C	144" 4x4	170" 6C	170" 4x4	170" E 6C	170" E 4x4
MXCA46	MXCA4X	MXCA76	MXCA7X	MXCAE6	MXCAEX
907.653	907.653	907.655	907.655	907.657	907.657

X69	Swivel Seat Package	\$532	\$532	\$532	\$532	\$532	\$532		
SR8	Swivel base for driver's seat	X	Х	X	X	X	Х		
SR9	Swivel base for front passenger seat	Х	Х	Х	Х	Х	Х		
S87	Driver's seat frame, low	Х	Х	Х	Х	Х	Х		
S88	Passenger seat frame, low	Х	Х	Х	Х	Х	Х		
must	must have (C00+C0S) OR (C00+X68)								

X01	Suspension Seating Package	\$940	\$940	\$940	\$940	\$940	\$940	
SB3	Driver suspension seat, comfort version	Х	Х	Х	Х	Х	Х	
SB4	Passenger suspension seat, comfort version	Х	Х	Х	Х	Х	X	
S87	Driver's seat frame, low	Х	Х	Х	Х	Х	Х	
S88	Passenger seat frame, low	Х	Х	Х	Х	Х	Х	
not v	not with C00/C0S/E2I/X68/S23							

Standard Equipment

144" 4C

170" 4C

170" E 4C

		2446444		
		M4CA44	M4CA74	M4CAE4
		907.653	907.655	907.657
En a:				
Engine			C	C
	Ingine/7-Speed Trans.	S	S	S
	AGM battery 12V 92 AH 850 A	S	S	S
	Automatic transmission, 7G-tronic	S	S	S
_	Alternator 14 V / 200 A	S	S	S
	2.0L 4-cylinder diesel engine	S	S	S
	SULEV emissions	S	S	S
Equipn				
-	Front axle reinforced	S	S	S
-	Axle ratio 4.182	S	S	S
	Active Brake Assist	S	S	S
	Hold Function	S	S	S
-	Multifunction steering wheel	S	S	S
	Stabilization Level II	S	S	S
	Adjustable steering wheel (angle)	S	S	S
-	High roof	-	S	S
	Omission bulkhead	S	S	S
E07 I	Hill Start Assist	S	S	S
	Standard radio	S	S	S
E1U	USB-C socket, 5 V	S	S	S
E30 S	Starter battery disconnect	S	S	S
E3J I	Pre-installation for switch panel	S	S	S
E40	Trailer hitch prep. wiring	S	S	S
ED8	Preinstallation PSM	S	S	S
EE5	Ultracapacitor discharge module	S	S	S
	Body Builder Connector	S	S	S
-	lump start terminal	S	S	S
EW6	Pre-installation for Mercedes me Remote Services	S	S	S
EY5	Emergency Call System	S	S	S
-	Breakdown management	S	S	S
	Heated & electrically adjustable exterior mirrors	S	S	S
	Shelf above windshield	S	S	S
	Cupholder front	S	S	S
-	Remote key (315 mhz) w/central locking	S	S	S
	Storage compartment underneath cockpit	S	S	S
	Rear view camera (rear-view mirror display)	S	S	S
	Windshield with filter band	S	S	S
	Heater, auxiliary electric hot air	S	S	S
	Air Condition, Front	S	S	S
	Head Unit, North America	S	S	S
	Speedometer, miles and km/h	S	S	S
	Seat belt warning for co-driver seat	S	S	S
	Seat belt warning for co-driver seat	S	S	S
	Outside temperature gauge	S	S	S
-	Crosswind Assist	S	S	S
-		S	S	S
	Communication module (LTE) for dig. services Service interval 20.000 miles			
		S	S	S
	Red diesel filler cap	S	S	S
	Exhaust straight to rear	S	S	S
	24.5 gallon fuel tank	S	S	S
	Aux fuel sending unit w/ fuel tap	S	S	S
	Fuel filter with water separator	S	S	S
-	Brd generation SCR emission control system	S	S	S
-	nterior lights, cargo compartment	S	S	S
	Parking lights deletion	S	S	S
	Headlight assistant	S	S	S
LB5	Brd brake light	S	S	S

Standard Equipment

		144'' 4C	170'' 4C	170" E 4C
		M4CA44	M4CA74	M4CAE4
		907.653	907.655	907.657
MS1	Cruise control	S	S	S
P47	Front mudflaps	S	S	S
P48	Rear mudflaps	S	S	S
Q11	Longitudinal member reinforcement	S	S	S
R65	Spare tire bracket below frame	S	S	S
R87	Spare tire	S	S	S
RH7	Tires LT 215/85 R16	S	S	S
RD9	Unspecified tire brand	S	S	S
RM0	All-season tires	S	S	S
RS6	5.5 J x 16 steel wheels	S	S	S
S02	Standard driver seat	S	S	S
S04	Standard front passenger seat	S	S	S
S22	Armrest for driver's seat	S	S	S
S25	Armrest for front passenger seat	S	S	S
SA5	Front airbag, driver	S	S	S
SA6	Front airbag, passenger	S	S	S
SH1	Thorax-pelvis sidebag, driver	S	S	S
SH2	Thorax-pelvis sidebag, co-driver	S	S	S
SH9	Airbag, driver/passenger window	S	S	S
SK2	Seat occupancy sensor, driver's seat	S	S	S
T16	Sliding door, passenger side	S	S	S
V93	Without factory installed flooring	S	S	S
V94	Cable duct - side wall	S	S	S
V95	Cable duct - rear portal	S	S	S
W54	Rear doors, opening to side wall	0	0	S
XL4	GVWR 12,125 lbs. / 5.500 Kg	S	S	S
Y43	Jack, hydraulic	S	S	S

	r			1
		144" 4C	170" 4C	170" E 4C
		M4CA44	M4CA74	M4CAE4
		907.653	907.655	907.657
AP2	Addtl. bar for driveshaft & exhaust extension	\$69	\$69	-
AR2	Axle ratio 3.923	\$0	\$0	\$0
	not with AR3		, -	, -
B01	ESP for increased Center of Gravity above 39.4"	-	\$0	\$0
	must have CB4/CB8/X30; not with RH0/CB7		·	
BE2	Handbrake lever, folding	\$55	\$55	\$55
	X69 must have BE2	· · · · · · · · · · · · · · · · · · ·	•	
C72	Bumpers front/rear primed	\$268	\$268	\$268
	must have CN2 (part of X67), not with CM0	· · · · · · · · · · · · · · · · · · ·	•	
CE8	Raised rear body mounts	\$252	\$252	\$252
CL3	Leather steering wheel	\$187	\$187	\$187
	must have (C02/E3M)/C03 + (ET4/MS1)			
CL3	Leather steering wheel	\$187	\$187	\$187
	must have (C02/E3M)/C03 + (ET4/MS1)			
CM0	Painted metallic front & rear bumper	\$587	\$587	\$587
	must have (CN2/X67) + (JA7/C01) + JB7 + (7755/9197/9775)			•
CM9	Primed side moldings	\$364	\$364	\$364
D03	High roof	\$2,900	S	S
D13	Mounting rails for roof rack	\$300	\$300	\$300
D22	Fixed sunroof (rear roof section)	\$336	\$336	\$336
	not with H08/HK4/H72/V36/ZK4			
D50	Cargo partition	\$288	\$288	\$288
	not with D51/D93/H08/HK4/T74/V36; must have one of T93/T77			
D51	Cargo partition with 1 window	\$335	\$335	\$335
	not with D50/D93/H08/HK4/T74/V37/D17; must have one of T93/T77			_
E1B	Tray for smartphones incl. wireless charging	\$156	\$156	\$156
	must have CO2/E3M + H1I			
E1E	Navigation	\$728	\$728	\$728
	must have CO2/E3M, not with CO3			
E1S	Sirius XM, satellite radio	\$255	\$255	\$255
	must have CO2/E3M/CO3			
E1X	MBUX multimedia 6-hour runtime	-	\$0	\$0
	must have X2R + (C02+E1E/E1S)/C03/(E3M+E1E/E1S)			
E1R	Additional Fuses (40/80/150/100 Ampere)	\$50	\$50	\$50
	SoP and Plausibility TBD			
E1Y	Additional Fuses (40/80/80/100 Ampere)	\$50	\$50	\$50
	SoP and Plausibility TBD			
E2A	Access point for BB special signals in cockpit	\$29	\$29	\$29
E2I	Additional battery, co-driver seat base	\$248	\$248	\$248
	must have E36/C06; not with E2M/F09; CHS production only		1	
E2M	Additional battery, engine compartment	\$248	\$248	\$248
	must have X01+ (E36/C06); not with E2I/X69/F09		1	
E3M	MBUX Multimedia System with 7" touchscreen	\$474	\$474	\$474
	not with C02/C03; must have JK5+(JB7/FR8)			
E36	Cutoff relay for additional battery	\$110	\$110	\$110
	standard with E2I/E2M		1	•
E46	12 V power outlet, driver seat base	\$92	\$92	\$92
E5M	Extension of PSM standard contact	\$58	\$58	\$58
ED5	Parametric special module (PSM)	\$317	\$317	\$317
	not with ED8			
EE3	115 V socket	\$125	\$125	\$125
EP7	Basic electric fitting for rear loudspeakers	\$68	\$68	\$68
ES2	12 V power outlet, rear compartment	\$92	\$92	\$92
ES5	Charging package, dashboard	\$82	\$82	\$82
ET4	Active Distance Assist DISTRONIC	\$263	\$263	\$263
<u> </u>	must have CO2/CO3/E3M; not with ZH4			
F1K	Coat hooks in driver cabin	\$14	\$14	\$14
	must have D50/D51			

		144" 4C	170" 4C	170" E 4C
		M4CA44	M4CA74	M4CAE4
		907.653	907.655	907.657
F49	Electrically heated windshield	\$218	\$218	\$218
- 10	no restriction	7	7	7-2-5
F61	Interior rear view mirror	\$36	\$36	\$36
	not with D50; must have C02/E3M/C03	,	,	122
FE9	Additional DIN-slot	\$81	\$81	\$81
FF4	Storage compartment above cabin	\$186	\$186	\$186
	must have D03, not with D17/D64/H08/HK4	·		
FF8	Overhead storage slot, front center	\$105	\$105	\$105
FJ1	Hinged lid for storage compartment	\$93	\$93	\$93
FR8	Rear view camera (head unit display)	\$336	\$336	\$336
	must have CO2/E3M; not with FR3/JB7; 3500XD not with JB8	•		
FY1	Security alarm w. interior motion sensor	\$584	\$584	\$584
	must have LC4/C00	•		•
FY7	Optional 3-button keys	\$36	\$36	\$36
FZ9	Keys, two additional masters	\$121	\$121	\$121
H00	Warm/cool air duct to rear compartment	\$59	\$59	\$59
	not with D50/D51/Y2A			
H01	Heat insulation, rear compartment	\$156	\$156	\$156
	must have V21/V25/VA3/VA1/C07/X66			
H04	Heat insulation, front compartment	\$187	\$187	\$187
	if + D50/D51 must have V07			
H08	Air conditioning rear, roof-mounted	\$2,872	\$2,872	\$2,872
	must have D93 +V36; not with HK4/C06/X66/C07			
H12	Fuel-fired pre-heater/booster (17K BTU)	\$1,116	\$1,116	\$1,116
	not with HZ9		_	
H13	Rear cabin heater and vents	\$786	\$786	\$786
	must have H12/HZ9			
H15	Heated front passenger seat	\$284	\$284	\$284
	must have H16; not with X68			
H16	Heated driver's seat	\$284	\$284	\$284
	must have H15; not with X68			
H22	Rear window defroster	\$253	\$253	\$253
	must have W61/W78; standard for W61+W70			
H72	Roof fan, electric	\$400	\$400	\$400
	not with D22/V36			
H88	Rear heater prep	\$405	\$405	\$405
	must have H12/HZ9; not with H13/T19	1 4-	1 4-	1 4-
H1I	Front-to-rear outlet in instrument panel	\$0	\$0	\$0
	must have FJ1/C01	400-	1000	4000
HH4	Thermotronic automatic climate control	\$337	\$337	\$337
	must have JF1; if +H13 must have H08/HK4	40.040	1 40.040	40.040
HK4	Rear air conditioner, heavyduty	\$3,940	\$3,940	\$3,940
1170	must have D03+V36+D93; not with H08/ZB6/ZE6/N62/N63	6676	4676	4676
HZ9	Fuel-fired heater booster (18,000 BTU)	\$676	\$676	\$676
154	not with H12	672	672	672
J51	Fuel gauge, optimized for aux. fuel tap	\$72	\$72	\$72
IE 2	not with HZ9/H12	\$0	\$0	ćo
J52	Engine oil level display at cold start  Blind Spot Assist	\$450	\$0 \$450	\$0 \$450
JA7	not with CO1	Ş <b>4</b> 5U	\$450	\$450
JB4	Active Lane Keeping Assist	\$288	\$288	\$288
104	standard with CO2/CA2	<i>⊋</i> ∠00	<b>3</b> 200	<b>3200</b>
JB7	Parking Package	\$615	\$615	\$615
10/	must have CO2/CO3/E3M; not with W75/W76/JB6	5010	Ϋ́OTO	לדוול
JF1	Rain sensor	\$106	\$106	\$106
JK5	Instrument cluster with color display	\$100	\$100	\$106
3,3	standard with CO2/CA2	7144	ŽIT <del>T</del>	- PTTT
JW0	Backup alarm	\$99	\$99	\$99
3,10	-secret arann	723	755	755

144" AC					
907.653   907.657   907.			144" 4C	170" 4C	170" E 4C
INV2   Deactivation lamp monitoring failure					
Section   Sect			907.653	907.655	907.657
Size	-		· ·	·	
SET   International   SET	<b>—</b>		· ·	·	
133   Food   F				·	
171   Light/motion sensor in rear compartment   \$54   \$54   \$54   \$54   \$54   \$54   \$55   \$65		·	· ·		
	-			·	· ·
189   Illuminated front exits	L71		\$54	\$54	\$54
ICC   ED light strip in load compartment   S263			1 4	4	1 4
			·	· ·	
LCA   Comfort overhead control panel   \$93   \$95   \$96   \$	LC2		\$263	\$263	\$263
M20   Speed limitation 65 mph   Se0   Se	1.64		602	ćoa	ćoa
MO3 Top speed limitation 75 mph	<b>—</b>	'			
MD3   Top speed limitation 75 mph   S60	IVIZU		\$60	\$60	\$60
	MD2		¢60	¢co	¢co
N62   Front engine bracket for additional alternator	IVID3		\$60	\$60	\$60
	NGO		\$467	\$467	\$467
N63   Front engine bracket for auxiliary A/C compressor	INOZ	-	\$407	Ş407	Ş407
	NES	·	\$167	\$467	\$467
P93 Omission of D-rings	1405		<b>γ</b> 407	Ş+07	Ş <del>4</del> 07
Not with D93/V43/VK8	P93	·	-\$15	-\$15	-\$15
QA2   Trailer cross member 7,500 lbs capacity	1 33	-	713	713	713
Not with W73/W75/W76/Q24/Q67	OA2		\$186	\$186	-
QA9   Half-sided step rear (for trailer hitch)   \$101		· · · · ·	7-55	7-55	
must have QA2; not with W73/W75/W76           Q24 Trailer hitch, 5,000 lbs         -         -         \$147           not with W73/W75/W76         -         -         \$147           R91 Spare tire deletion         -\$110         -\$110         -\$110           must have R92; not with R87         -         \$0         \$0         \$0           R92 Spare tire carrier deletion         \$0         \$0         \$0         \$0           must have R91; not with R65         881         \$81         \$81         \$81           R93 Rims painted jet black         \$81         \$81         \$81         \$81           not with RL5/RM2         \$0         \$0         \$0         \$0         \$0         \$0           RF1 Tire brand Continental         \$0         <	QA9		\$101	\$101	\$101
Q24         Trailer hitch, 5,000 lbs         -         -         \$147           not with W73/W75/W76         -         -         \$110         -\$110         -\$110           R91         Spare tire deletion         -         -         \$10         -\$110         -\$110           must have R92; not with R87         -         -         \$0         \$0         \$0           must have R91; not with R65         - <td< td=""><td></td><td></td><td></td><td><u> </u></td><td>·</td></td<>				<u> </u>	·
R91         Spare tire deletion         -\$110         -\$110         -\$110           must have R92; not with R87         \$0         \$0         \$0           R92         Spare tire carrier deletion         \$0         \$0         \$0           must have R91; not with R65         \$81         \$81         \$81           R98         Rims painted jet black         \$81         \$81         \$81           not with RL5/RM2         \$0         \$0         \$0         \$0           RF1         Tire brand Continental         \$0         \$0         \$0           must have RM1 + RM9         \$0         \$0         \$0         \$0           RF8         Tire brand Michelin         \$0         \$0         \$0           must have RM9; not with RM1         \$0         \$0         \$0           must have RM9; not with RM1         \$169         \$169         \$169           must have RF1/RD9; not with RF8/RH0/X31         \$169         \$169         \$169           must have RF1/RD9; not with RF8/RH0/X31         \$81         \$81         \$81           RM2         Rims painted arctic white         \$81         \$81         \$81           not with R98/RL5         \$81         \$81         \$81         \$81     <	Q24		-	-	\$147
must have R92; not with R87		not with W73/W75/W76	•		•
R92         Spare tire carrier deletion         \$0         \$0           must have R91; not with R65           R98         Rims painted jet black         \$81         \$81           not with RL5/RM2         \$0         \$0         \$0           RF1         Tire brand Continental         \$0         \$0         \$0           must have RM1 + RM9         \$0         \$0         \$0           RF8         Tire brand Michelin         \$0         \$0         \$0           must have RM9; not with RM1         \$0         \$0         \$0           RH0         Tire brand Michelin         \$0         \$0         \$0           must have RM9; not with RM1         \$0         \$0         \$0           must have RM9; not with RM1         \$169         \$169         \$169           must have RF1/RD9; not with RF8/RH0/X31         \$169         \$169         \$169           must have RF1/RD9; not with RF8/RH0/X31         \$101         \$101         \$101           must have RF1/RD9; not with RD9         \$101         \$101         \$101           \$23         Twin front passenger seat         \$400         \$400         \$400           not with C00/X68/X01         \$51         \$51         \$51         \$51	R91	Spare tire deletion	-\$110	-\$110	-\$110
must have R91; not with R65           R98 Rims painted jet black         \$81         \$81         \$81           not with RLS/RM2         \$0         \$0         \$0           RF1 Tire brand Continental         \$0         \$0         \$0           must have RM1 + RM9         \$0         \$0         \$0           RF8 Tire brand Michelin         \$0         \$0         \$0           must have RM9; not with RM1         \$0         \$0         \$0           RM1 M-S winter tires         \$169         \$169         \$169           must have RF1/RD9; not with RF8/RH0/X31         \$169         \$169         \$169           must have RF1/RD9; not with RF8/RH0/X31         \$81         \$81         \$81           RM2 Rims painted arctic white         \$81         \$81         \$81           not with R98/RL5         \$101         \$101         \$101           RM9 Specially requested tires         \$101         \$101         \$101           must have RF1/RB/RH0; not with RD9         \$23         \$101         \$101         \$101           \$23         Twin front passenger seat         \$400         \$400         \$400           \$28         Armrest, driver and passenger door         \$51         \$51         \$51		must have R92; not with R87			
R98         Rims painted jet black         \$81         \$81         \$81           not with RL5/RM2         \$0         \$0         \$0           RF1         Tire brand Continental         \$0         \$0         \$0           must have RM1 + RM9         Tire brand Michelin         \$0         \$0         \$0           must have RM9; not with RM1         \$0         \$0         \$0           must have RM9; not with RM1         \$169         \$169         \$169           must have RF1/RD9; not with RF8/RH0/X31         \$81         \$81         \$81           RM2         Rims painted arctic white         \$81         \$81         \$81           not with R98/RL5         \$81         \$81         \$81         \$81           RM9         Specially requested tires         \$101 <td>R92</td> <td>Spare tire carrier deletion</td> <td>\$0</td> <td>\$0</td> <td>\$0</td>	R92	Spare tire carrier deletion	\$0	\$0	\$0
		must have R91; not with R65			
RF1         Tire brand Continental         \$0         \$0           must have RM1 + RM9         \$0         \$0         \$0           RF8         Tire brand Michelin         \$0         \$0         \$0           must have RM9; not with RM1         \$0         \$0         \$0           RM1         M+5 winter tires         \$169         \$169         \$169           must have RF1/RD9; not with RF8/RH0/X31         \$169         \$169         \$169           RM2         Rims painted arctic white         \$81         \$81         \$81           not with R98/RL5         \$101         \$101         \$101         \$101           must have RF1/RF8/RH0; not with RD9         \$23         \$400         \$400         \$400           solution on with CO0/X68/X01         \$51         \$51         \$51         \$51           \$28         Armrest, driver and passenger door         \$51         \$51         \$51           \$62         Seat belts orange, driver and front passenger         \$32         \$32         \$32           \$89         Driver's seat plus         \$238         \$238         \$238         \$238           must have VF7; not with CO0/X68/X69         \$64         \$64         \$64         \$64           \$27	R98	Rims painted jet black	\$81	\$81	\$81
### ### ### ### ### ### ### ### ### ##		not with RL5/RM2			
RF8         Tire brand Michelin         \$0         \$0         \$0           must have RM9; not with RM1         \$0         \$0         \$0           RM1         Tire brand Kumho         \$0         \$0         \$0           must have RM9; not with RM1         \$169         \$169         \$169           RM1         M+5 winter tires         \$169         \$169         \$169           must have RF1/RD9; not with RF8/RH0/X31         \$169         \$169         \$169           RM2         Rims painted arctic white         \$81         \$81         \$81           RM2         Rims painted arctic white         \$81         \$81         \$81         \$81           RM3         Specially requested tires         \$101         \$101         \$101         \$101         \$101         \$101         \$101         \$101         \$101         \$101         \$101         \$101         \$101         \$101         \$101         \$101         \$101         \$101         \$101<	RF1		\$0	\$0	\$0
must have RM9; not with RM1   \$0		must have RM1 + RM9		_	
RHO   Tire brand Kumho   \$0   \$0   \$0   \$0   \$0   \$0   \$0   \$	RF8		\$0	\$0	\$0
must have RM9; not with RM1         \$169         \$169         \$169           RM1         M+S winter tires         \$169         \$169         \$169           must have RF1/RD9; not with RF8/RH0/X31         \$81         \$81         \$81           RM2         Rims painted arctic white         \$81         \$81         \$81           not with R98/RL5         \$101         \$101         \$101           RM9         Specially requested tires         \$101         \$101         \$101           must have RF1/RF8/RH0; not with RD9         \$23         \$400         \$400         \$400           not with C00/X68/X01         \$51         \$51         \$51         \$51           \$28         Armrest, driver and passenger door         \$51         \$51         \$51           \$62         Seat belts orange, driver and front passenger         \$32         \$32         \$32           \$89         Driver's seat plus         \$238         \$238         \$238           must have VF7; not with C00/X68/X69         \$27         \$50 rage net, driver's seat backrest         \$64         \$64         \$64           \$28         \$50 rage net, passenger seat backrest         \$64         \$64         \$64           \$28         \$52 seat backrest         \$64			_		
RM1         M+S winter tires         \$169         \$169         \$169           must have RF1/RD9; not with RF8/RH0/X31         RM2         Rims painted arctic white         \$81         \$81         \$81           RM2         Rims painted arctic white         \$81         \$81         \$81           not with R98/RL5         \$101         \$101         \$101           RM9         Specially requested tires         \$101         \$101           must have RF1/RF8/RH0; not with RD9         \$23         Twin front passenger seat         \$400         \$400           solution front passenger seat         \$400         \$400         \$400           not with COO/X68/X01         \$51         \$51         \$51           \$62         Seat belts orange, driver and front passenger         \$32         \$32         \$32           solution with S23         \$238         \$238         \$238         \$238           solution with S23         \$238         \$238         \$238           solution with Ave VF7; not with COO/X68/X69         \$64         \$64         \$64           \$27         Storage net, driver's seat backrest         \$64         \$64         \$64           \$28         Storage net, passenger seat backrest         \$64         \$64         \$64	RH0		\$0	\$0	\$0
must have RF1/RD9; not with RF8/RH0/X31           RM2 Rims painted arctic white         \$81         \$81         \$81           not with R98/RL5         \$101         \$101         \$101           RM9 Specially requested tires         \$101         \$101         \$101           must have RF1/RF8/RH0; not with RD9         \$23         Twin front passenger seat         \$400         \$400           \$23         Twin front passenger seat         \$400         \$400         \$400           \$28         Armrest, driver and passenger door         \$51         \$51         \$51           \$62         Seat belts orange, driver and front passenger         \$32         \$32         \$32           \$62         Seat belts orange, driver and front passenger         \$238         \$238         \$238           \$89         Driver's seat plus         \$238         \$238         \$238           \$89         Driver's seat plus         \$238         \$238         \$238           \$89         Driver's seat plus         \$64         \$64         \$64           \$27         Storage net, driver's seat backrest         \$64         \$64         \$64           \$28         Storage net, passenger seat backrest         \$64         \$64         \$64           \$28					
RM2       Rims painted arctic white       \$81       \$81       \$81         not with R98/RL5       \$101       \$101       \$101         RM9       Specially requested tires       \$101       \$101       \$101         must have RF1/RF8/RH0; not with RD9       \$23       \$400       \$400       \$400         S23       Twin front passenger seat       \$400       \$400       \$400         not with COO/X68/X01       \$51       \$51       \$51         \$62       Seat belts orange, driver and front passenger       \$32       \$32       \$32         not with S23       \$238       \$238       \$238       \$238         B9       Driver's seat plus       \$238       \$238       \$238         must have VF7; not with COO/X68/X69       \$64       \$64       \$64         \$27       Storage net, driver's seat backrest       \$64       \$64       \$64         \$28       Storage net, passenger seat backrest       \$64       \$64       \$64         \$12       Sliding door two stage opening       \$82       \$82       \$82         \$19       Sliding door, driver's side       \$935       \$935       \$935	RM1		\$169	\$169	\$169
not with R98/RL5           RM9 Specially requested tires         \$101         \$101         \$101           must have RF1/RF8/RH0; not with RD9         \$400         \$400         \$400           523 Twin front passenger seat         \$400         \$400         \$400           not with C00/X68/X01         \$51         \$51         \$51           562 Seat belts orange, driver and front passenger         \$32         \$32         \$32           not with S23         \$238         \$238         \$238           SB9 Driver's seat plus         \$238         \$238         \$238           must have VF7; not with C00/X68/X69         \$64         \$64         \$64           \$27         Storage net, driver's seat backrest         \$64         \$64         \$64           \$28         Storage net, passenger seat backrest         \$64         \$64         \$64           \$28         Storage net, passenger seat backrest         \$64         \$64         \$64           \$10			<u> </u>		
RM9       Specially requested tires       \$101       \$101         must have RF1/RF8/RH0; not with RD9       \$400       \$400         \$23       Twin front passenger seat       \$400       \$400         not with C00/X68/X01       \$51       \$51       \$51         \$62       Seat belts orange, driver and front passenger       \$32       \$32       \$32         not with S23       \$238       \$238       \$238         SB9       Driver's seat plus       \$238       \$238       \$238         must have VF7; not with C00/X68/X69       \$64       \$64       \$64         \$27       Storage net, driver's seat backrest       \$64       \$64       \$64         \$28       Storage net, passenger seat backrest       \$64       \$64       \$64         \$12       Sliding door two stage opening       \$82       \$82       \$82         not with T55       \$935       \$935       \$935	RM2	•	\$81	\$81	\$81
must have RF1/RF8/RH0; not with RD9         \$23       Twin front passenger seat       \$400       \$400         not with COO/X68/X01         \$28       Armrest, driver and passenger door       \$51       \$51         \$62       Seat belts orange, driver and front passenger       \$32       \$32         not with \$23         \$89       Driver's seat plus       \$238       \$238         must have VF7; not with COO/X68/X69         \$27       Storage net, driver's seat backrest       \$64       \$64         \$28       Storage net, passenger seat backrest       \$64       \$64         \$28       Storage net, passenger seat backrest       \$64       \$64         \$12       Sliding door two stage opening       \$82       \$82         not with T55         \$19       Sliding door, driver's side       \$935       \$935	D1 40		44.04	4404	<b>\$4.04</b>
\$23       Twin front passenger seat       \$400       \$400       \$400         not with C00/X68/X01       \$51       \$51       \$51         \$28       Armrest, driver and passenger door       \$51       \$51       \$51         \$62       Seat belts orange, driver and front passenger       \$32       \$32       \$32         not with \$23       \$238       \$238       \$238         \$89       Driver's seat plus       \$238       \$238       \$238         must have VF7; not with C00/X68/X69       \$64       \$64       \$64         \$27       Storage net, driver's seat backrest       \$64       \$64       \$64         \$28       Storage net, passenger seat backrest       \$64       \$64       \$64         \$12       Sliding door two stage opening       \$82       \$82       \$82         not with T55       \$935       \$935       \$935	RIVI9		\$101	\$101	\$101
not with COO/X68/X01           \$28 Armrest, driver and passenger door         \$51         \$51         \$51           \$62 Seat belts orange, driver and front passenger         \$32         \$32         \$32           not with \$23         \$238         \$238         \$238           SB9 Driver's seat plus         \$238         \$238         \$238           must have VF7; not with COO/X68/X69         \$64         \$64         \$64           \$28 Storage net, driver's seat backrest         \$64         \$64         \$64           \$28 Storage net, passenger seat backrest         \$64         \$64         \$64           \$12 Sliding door two stage opening         \$82         \$82         \$82           not with T55         \$935         \$935         \$935	622		Ć400	Ć400	Ć400
\$28         Armrest, driver and passenger door         \$51         \$51           \$62         Seat belts orange, driver and front passenger         \$32         \$32         \$32           \$82         \$38         \$38         \$38         \$38         \$38         \$38         \$38         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$44         \$	523		\$400	\$400	\$400
S62       Seat belts orange, driver and front passenger       \$32       \$32       \$32         not with S23       \$238       \$238       \$238       \$238         SB9       Driver's seat plus       \$238       \$238       \$238         must have VF7; not with C00/X68/X69       \$64       \$64       \$64         SZ7       Storage net, driver's seat backrest       \$64       \$64       \$64         SZ8       Storage net, passenger seat backrest       \$64       \$64       \$64         T12       Sliding door two stage opening       \$82       \$82       \$82         not with T55       \$935       \$935       \$935	C20		ĆF1	¢E1	ĆE1
not with S23         \$238         \$238         \$238           SB9 Driver's seat plus         \$238         \$238         \$238           must have VF7; not with C00/X68/X69         \$64         \$64         \$64           \$28 Storage net, driver's seat backrest         \$64         \$64         \$64           \$28 Storage net, passenger seat backrest         \$64         \$64         \$64           \$12 Sliding door two stage opening         \$82         \$82         \$82           \$19 Sliding door, driver's side         \$935         \$935         \$935	<b>—</b>				
SB9         Driver's seat plus         \$238         \$238           must have VF7; not with COO/X68/X69           SZ7         Storage net, driver's seat backrest         \$64         \$64           SZ8         Storage net, passenger seat backrest         \$64         \$64           T12         Sliding door two stage opening         \$82         \$82           not with T55           T19         Sliding door, driver's side         \$935         \$935	302		<b>33</b> 2	\$3Z	<b>33</b> 2
must have VF7; not with C00/X68/X69           SZ7         Storage net, driver's seat backrest         \$64         \$64         \$64           SZ8         Storage net, passenger seat backrest         \$64         \$64         \$64           T12         Sliding door two stage opening         \$82         \$82         \$82           not with T55         T19         Sliding door, driver's side         \$935         \$935         \$935	SRQ		\$238	\$238	\$238
SZ7       Storage net, driver's seat backrest       \$64       \$64       \$64         SZ8       Storage net, passenger seat backrest       \$64       \$64       \$64         T12       Sliding door two stage opening       \$82       \$82       \$82         not with T55       \$935       \$935       \$935	303	·	9230	<b>9230</b>	<b>9230</b>
SZ8         Storage net, passenger seat backrest         \$64         \$64           T12         Sliding door two stage opening         \$82         \$82           not with T55         \$100         \$100         \$100           T19         Sliding door, driver's side         \$100         \$100         \$100           T19         Sliding door, driver's side         \$100	577		\$6/	\$64	\$64
T12         Sliding door two stage opening         \$82         \$82           not with T55         \$10			·	·	·
not with T55         \$935         \$935           T19 Sliding door, driver's side         \$935         \$935			· ·	·	·
T19 Sliding door, driver's side \$935 \$935 \$935	1.12		702	702	702
	T19		\$935	\$935	\$935
	<u> </u>		<b>4533</b>	+555	7000

		144" 4C	170" 4C	170" E 4C
		M4CA44	M4CA74	M4CAE4
		907.653	907.655	907.657
T50	Electric closing assist right sliding door	\$335	\$335	\$335
130	must have D03; not with T55/T93	,5555	رددد	2222
T51	Electric closing assist left sliding door	\$335	\$335	\$335
131	must have T19 + D03	ļ <del>2</del> 333	ļ <del>2333</del>	ψ333
T55	Electric sliding door right	\$831	\$831	\$831
	must have D03 + (FY7+T16); not with T12/T50	Ψ00 <b>-</b>	<b>Ψ</b> 002	Ψ00=
T57	Electric sliding step	\$1,071	\$1,071	\$1,071
	must have ED5; not with T93	1 /-	1 /-	1 /-
T60	Opening limiter electrically operated sliding door	\$120	\$120	\$120
	must have T55	•		
T74	Assist handle, B-pillar	\$32	\$32	\$32
	must have D93; not with T77	•	•	•
T75	Door-mounted assist handles, driver & passenger	\$59	\$59	\$59
T77	Assist handle w/ partition	\$32	\$32	\$32
	must have D50/D51/D64			
T85	Assist handle, left rear door	\$32	\$32	\$32
T86	Assist handles, right rear door	\$32	\$32	\$32
T93	Sliding door right side deletion	\$0	\$0	\$0
	not with T16/T50/T57/VK8/VC5			
V07	Cab rear wall liner	\$360	\$360	\$360
	must have (D50/D51)+F1K; standard with H04			
V21	Luxury interior Trim	\$661	\$661	\$661
	must have VA5/VA7; not with V52/VA1/VA3			
V24	Pallet support in sliding door step	\$96	\$96	\$96
	must have (V43/X66)+(D50/D51); not with VK8/V93/C07			
V25	Half height load compartment trim	\$201	\$201	\$201
	not with VA1/VA3/VA5/V52/X66	1 4	4=.0	4=
V31	Window pillar trim	\$513	\$513	\$513
\ /2F	must have V36 + (V21/VA1) + (F02/F03/F07); not with V42	4405	4405	Ć4.05
V35	Wheel house covering	\$105	\$105	\$105
V26	if +V43 must have V25/VA1/VA3; not with V52	¢076	\$876	¢076
V36	Roof trim	\$876	·	\$876
V42	must have D93; not with D17/D22/H72/L65/L71/LC2/VA3/V42/ZE6/(Lashing rails, waist level	\$277	\$277	\$277
V4Z	not with V36/ZE6	<i>3211</i>	<i>Ş</i> 211	<i>Ş</i> 211
V43	Wood floor with 6 D-rings	\$422	\$422	\$422
V 3	not with P93/V93/VL4/VK8/C07; standard with D93/H13/V24/V52/V		J 422	ψ-7-2-
V48	Floor cover behind seat box	\$27	\$27	\$27
	must have D93; not with D50/D51/D56/D62/D64/V43/VK5	Ψ=:	γ=-	Ψ=/
V4A	Full paneling, right sliding door	\$109	\$109	\$109
	must have D03+T16+V21+VA5+W17; not with T19	,	,	,
V85	Cigarette lighter & ash cup, front	\$39	\$39	\$39
VA1	Side wall paneling waist height PVC	\$319	\$319	\$319
	must have VA5/VA7; not with V52			•
VA3	Side wall paneling full hardboard	\$444	\$444	\$444
	not with V36/F02; if T93 must have (D50/D51)	,		
VA5	Full paneling, hinged rear doors	\$38	\$38	\$38
	must have D03+VA7+(W61/W78); not with V25			
VA7	Storage compart. w/ net in rear doors	\$127	\$127	\$127
	must have W61/W78; not with V52			
VC4	Cargo lashing rails, head height	\$415	\$415	\$415
	must have V42/C07/X66; not with ZE6			
VC5	Door sill - protective edge	\$71	\$71	\$71
	must have V43/X66; not with T19/T93/VK8/VV2/V93/C07			
VK8	Floor covering, plastic	\$370	\$370	\$370
	not with V43/P93/T19/T93/V52/VC5/X66	1 45	45	1
VV2	Lashing rails, floor level (plus 4 anchors)	\$270	\$345	\$377
	must have V43; not with V93/VC5/ZE6			

# **4500 CARGO VAN - 4cyl Diesel** Options

		144" 4C	170" 4C	170" E 4C
		M4CA44	M4CA74	M4CAE4
		907.653	907.655	907.657
W16	2nd row, fixed window, driver side	\$145	\$145	\$145
	if D93 must have F43+W70; if D93 & standard roof CHS production rec	quired		
W17	2nd row, fixed window, passenger side	\$145	\$145	\$145
	if D93 must have F43+W70; if D93 & standard roof CHS production red	quired	•	•
W33	FMVSS 217 emergency exit	-	\$379	\$379
	must have V31; not with D50/T19/W16			
W54	Rear doors, opening to side wall	\$360	\$360	S
W5F	90 Degree fixation point- Rear Doors	\$80	\$80	\$80
	SoP and Plausibility TBD			
W61	Windows in rear doors	\$93	\$93	\$93
	must have VA7/ if D51 must have F61; not with W78/(W70+-(H22/F02	2))	•	•
W70	Black tinting (90%) for rear windows	\$138	\$138	\$138
	not with W94; must have W16/W17/F02/((W61/W78)+H22); standard	d with F43/W33/	F07	
W73	Bumper step, rear, grey	\$187	\$187	\$187
	not with QA2/W75/W76			
W75	Step, wide, at rear end	\$308	\$308	\$308
	not with JB6/JB7/Q24/QA9; must have R91+R92			
W76	Bumper step, rear, spring-loaded	-	\$601	\$601
	must have R91+R92; not with JB6/JB7/X30/Q24			
W78	Heated rear window(s) w/ washers/wipers	\$335	\$335	\$335
	Must have H22+VA7 / if D51 must have F61; not with W61			
X90	Deletion of Sprinter badge, left rear door	\$0	\$0	\$0
X93	Deletion of model badge, right rear door	\$0	\$0	\$0
X2R	Conversion to RV requirement	-	\$0	\$0
	must have B01+D93+E1X		7 -	7 -
XM4	Acoustic package	\$87	\$87	\$87
	standard with CO2/CO3		, -	, -
Y10	First-aid kit	\$27	\$27	\$27
Y26	Wheel chocks	\$38	\$38	\$38
Y45	Emergency flashlight	\$27	\$27	\$27
Y68	Paint preservative	\$187	\$212	\$225
Y69	Surface protection for stock vehicles	\$315	\$315	\$315
YK3	Cargo straps, D-rings	\$81	\$81	\$81
YK4	Cargo straps, 12 migs  Cargo straps, lashing rails	\$104	\$104	\$104
	must have V42/VV2; not with ZE6	<b>Υ±0</b> ¬	7101	7201
ZE6	Shelving prep	\$640	\$640	\$640
	not with T93/H13/T19/V36/V42/VC4/VK8/VV2/YK4	70 <del>4</del> 0	7040	- <del> </del>
	110C VVICIT 133/1113/113/V3U/V42/VC4/VNO/VV2/TN4			

# **4500 CARGO VAN - 4cyl Diesel** Packages

144" 4C	170" 4C	170" E 4C
M4CA44	M4CA74	M4CAE4
907.653	907.655	907.657

C00	Comfort Package	\$300	\$300	\$300
LC4	Comfort overhead control panel	X	X	X
SE4	Lumbar support, co-driver's seat	X	X	X
SE5	Lumbar support, driver's seat	X	X	X
SK0	Comfort head restraint, driver	X	X	X
SK1	Comfort head restraint, co-driver	Х	X	Х
S28	Armrest, driver and passenger door	X	X	X
must	have COS OR X68; CA/CC only: not with S23			

COS	Comfort Package (Seat addition)	\$381	\$381	\$381	
SB1	Comfort driver's seat	X	Х	Х	
SB2	Comfort passenger seat	Х	Х	X	
must	must have COO				

X68	Comfort Plus Package	\$1,923	\$1,923	\$1,923
H15	Heated front passenger seat	Х	X	X
H16	Heated driver's seat	Х	Х	Х
SF1	Driver's seat electrically adjustable	Х	Х	Х
SF2	Co-driver's seat electrically adjustable	Х	Х	Х
must	must have COO and VF4 OR VF6, CA/CC only: not with S23			

C01	Driver Convenience Package	\$760	\$760	\$760
E46	12 V power outlet, driver seat base	Х	Х	Х
F64	Electrically folding exterior mirrors	Х	X	X
FJ1	Hinged lid for storage compartment	Х	X	X
FJ5	Hinged Lid for Storage Compartments left and right	Х	X	Х
FZ9	Keys, two additional masters	Х	X	Х
JA7	Blind Spot Assist	Х	X	Х
JW8	Attention Assist	Х	X	Х

C02	Premium Package	\$983	\$983	\$983
CL3	Leather steering wheel	X	Х	X
E3M	MBUX Multimedia System with 7" touchscreen	Х	Х	X
FM3	Wet Wiper System	Х	Х	Х
JB4	Active Lane Keeping Assist	Х	Х	X
JK5	Instrument cluster with color display	Х	Х	X
Orde	ring availability restricted, see NetStar for availability and restro	ctions   must ha	ve JF1 + XM4; i	must choose

Ordering availability restricted, see NetStar for availability and restrctions | must have JF1 + XM4; must choose FR8/JB7

CA2	C02 in combination with C03	\$604	\$604	\$604
CL3	Leather steering wheel	X	X	X
FM3	Wet Wiper System	X	X	Х
JB4	Active Lane Keeping Assist	Χ	Χ	Х
JK5	Instrument cluster with color display	Х	X	X
Orde	Ordering availability restricted, see NetStar for availability and restrctions must have CO3 + JF1			

Packages

144" 4C	170" 4C	170" E 4C
M4CA44	M4CA74	M4CAE4
907.653	907.655	907.657

C03	Premium Plus Package	\$1,793	\$1,793	\$1,793
E1B	Tray for smartphones incl. wireless charging	X	X	Х
	Navigation	Х	Х	Х
EY2	Intelligent navigation	Х	Х	Х
E4M	MBUX Multimedia System with 10.25" touchscreen	Х	Х	Х
EX9	Free map data updates for 3 years	Х	Х	Х
H1I	Front-to-rear outlet in instrument panel	Х	Х	Х
JA9	Traffic Sign Assist	Х	Х	Х
XM4	Acoustic package	Х	Х	Х
must	nust have (CA2+JB7) OR (JB4+JK5+FM3+JB7); not with FR8 and CO2			

X67	Chrome Grille Package	\$290	\$290	\$290	
CN2	Radiator grille frame in vehicle color	X	X	X	
FK3	Chrome plated radiator grille (MB only)	X	X	X	
no re	no restrictions				

X13	Exterior Lighting Package	\$1,608	\$1,608	\$1,608	
L13	Fog lamp with cornering light function	Χ	X	X	
L22	Partial LED tail lights	Х	X	X	
LA1	High beam assist	Х	X	X	
LG7	LED high performance headlamps	Х	Х	X	
no re	no restrictions				

C06	Cargo Convenience Package	\$658	\$658	\$658	
E36	Cutoff relay for additional battery	Х	Х	Х	
ES2	12 V power outlet, rear compartment	Х	Х	X	
LC2	LED light strip in load compartment	Χ	X	X	
T12	Sliding door two stage opening	Χ	X	X	
T85	Assist handle, left rear door	Χ	Х	X	
T86	Assist handles, right rear door	Χ	X	X	
W54	Rear doors, opening to side wall	Χ	X	S	
must	must have T74 OR (T77+D50) OR (T77+D51)				

C07	Cargo Protection Package	\$1,117	\$1,117	\$1,117
V25	Half height load compartment trim	X	Х	X
V42	Lashing rails, waist level	X	Х	X
VC4	Cargo lashing rails, head height	X	Х	X
VK8	Floor covering, plastic	X	Х	X
YK3	Cargo straps, D-rings	Х	X	Х
not w	not with X66			

X66	Heavy-Duty-Cargo Protection Package	\$2,043	\$2,043	\$2,043	
V43	Wood floor with 6 D-rings	Х	X	X	
V42	Lashing rails, waist level	Х	X	X	
VA3	Side wall paneling full hardboard	Х	Х	X	
VC4	Cargo lashing rails, head height	Х	X	X	
VV2	Lashing rails, floor level (plus 4 anchors)	X	X	X	
YK3	Cargo straps, D-rings	X	Х	X	
YK4	Cargo straps, lashing rails	X	Х	X	
not v	not with CO7				

#### Packages

144" 4C	170" 4C	170" E 4C
M4CA44	M4CA74	M4CAE4
907.653	907.655	907.657

X69	Swivel Seat Package	\$532	\$532	\$532	
SR8	Swivel base for driver's seat	Х	Х	Х	
SR9	Swivel base for front passenger seat	Х	Х	Х	
S87	Driver's seat frame, low	Х	Х	Х	
S88	Passenger seat frame, low	Х	Х	Х	
must	must have (C00+C0S) OR (C00+X68)				

F09	SHUTTLE DOOR PREP PACKAGE	\$0	\$0	\$0
SW1	Seat belt deletion, passenger	Х	Х	Х
S91	Passener seat, deleted	Х	Х	Х
S99	Passenger seat pedestal - deletion	Х	Х	Х

Package deletes standard options: SH2 Thorax-Pelvis sidebag, co-driver; To add/delete from order must call distirbution team

X01	Suspension Seating Package	\$940	\$940	\$940	
SB3	Driver suspension seat, comfort version	Х	Х	X	
SB4	Passenger suspension seat, comfort version	Х	Х	X	
S87	Driver's seat frame, low	Х	Х	X	
S88	Passenger seat frame, low	Х	Х	Х	
not v	not with C00/C0S/E2I/X68/S23				

Standard Equipment

144" 6C

170" 6C

170" E 6C

Engine		907.653	907.655	907.657
10-LVI EN	ngine/7-Speed Trans.	S	S	S
	GM battery 12V 92 AH 850 A	S	S	S
	automatic transmission, 7G-tronic	S	S	S
	lternator 14 V/220 A	S	S	S
	.0L V6 turbo diesel engine	S	S	S
	ULEV emissions	S	S	S
Equipm	ent			
	ront axle reinforced	S	S	S
AR3 A	xle ratio 4.182	S	S	S
BA3 A	ctive Brake Assist	S	S	S
BH1 H	lold Function	S	S	S
C6L M	Aultifunction steering wheel	S	S	S
CB8 St	tabilization Level II	S	S	S
CL1 A	djustable steering wheel (angle)	S	S	S
D03 H	ligh roof	-	S	S
D93 O	Omission bulkhead	S	S	S
E07 H	Iill Start Assist	S	S	S
E1O St	tandard radio	S	S	S
E1U U	ISB-C socket, 5 V	S	S	S
E30 St	tarter battery disconnect	S	S	S
E3J Pr	re-installation for switch panel	S	S	S
E40 Tr	railer hitch prep. wiring	S	S	S
ED8 Pr	reinstallation PSM	S	S	S
EE5 U	Iltracapacitor discharge module	S	S	S
EK1 B	ody Builder Connector	S	S	S
ESO Ju	ump start terminal	S	S	S
EW6 Pr	re-installation for Mercedes me Remote Services	S	S	S
EY5 Er	mergency Call System	S	S	S
EY6 Bı	reakdown management	S	S	S
F68 H	leated & electrically adjustable exterior mirrors	S	S	S
	helf above windshield	S	S	S
FG8 Cu	upholder front	S	S	S
FI1 Re	emote key (315 mhz) w/central locking	S	S	S
FJ4 St	torage compartment underneath cockpit	S	S	S
FR3 Re	ear view camera (rear-view mirror display)	S	S	S
H21 W	Vindshield with filter band	S	S	S
HH2 H	leater, auxiliary electric hot air	S	S	S
HH9 Ai	ir Condition, Front	S	S	S
IH7 H	lead Unit, North America	S	S	S
J11 Sp	peedometer, miles and km/h	S	S	S
J55 Se	eat belt warning for co-driver seat	S	S	S
J58 Se	eat belt reminder driver	S	S	S
J65 O	Outside temperature gauge	S	S	S
JA8 Cı	rosswind Assist	S	S	S
JH3 Co	Communication module (LTE) for dig. services	S	S	S
JI9 Se	ervice interval 20.000 miles	S	S	S
K56 R	ed diesel filler cap	S	S	S
K60 Ex	xhaust straight to rear	S	S	S
	4.5 gallon fuel tank	S	S	S
KL1 A	ux fuel sending unit w/ fuel tap	S	S	S
KL5 Fu	uel filter with water separator	S	S	S
KP6 3r	rd generation SCR emission control system	S	S	S
L65 In	nterior lights, cargo compartment	S	S	S
L94 Pa	arking lights deletion	S	S	S
LA2 H	leadlight assistant	S	S	S
LB5 3r	rd brake light	S	S	S

#### **4500 CARGO VAN - 6cyl Diesel** Standard Equipment

		144" 6C	170" 6C	170" E 6C
		M4CA46	M4CA76	M4CAE6
		907.653	907.655	907.657
MS1	Cruise control	S	S	S
P47	Front mudflaps	S	S	S
P48	Rear mudflaps	S	S	S
Q11	Longitudinal member reinforcement	S	S	S
R65	Spare tire bracket below frame	S	S	S
R87	Spare tire	S	S	S
RH7	Tires LT 215/85 R16	S	S	S
RD9	Unspecified tire brand	S	S	S
RM0	All-season tires	S	S	S
RS6	5.5 J x 16 steel wheels	S	S	S
S02	Standard driver seat	S	S	S
S04	Standard front passenger seat	S	S	S
S22	Armrest for driver's seat	S	S	S
S25	Armrest for front passenger seat	S	S	S
SA5	Front airbag, driver	S	S	S
SA6	Front airbag, passenger	S	S	S
SH1	Thorax-pelvis sidebag, driver	S	S	S
SH2	Thorax-pelvis sidebag, co-driver	S	S	S
SH9	Airbag, driver/passenger window	S	S	S
SK2	Seat occupancy sensor, driver's seat	S	S	S
T16	Sliding door, passenger side	S	S	S
V93	Without factory installed flooring	S	S	S
V94	Cable duct - side wall	S	S	S
V95	Cable duct - rear portal	S	S	S
W54	Rear doors, opening to side wall	0	0	S
XL4	GVWR 12,125 lbs. / 5.500 Kg	S	S	S
Y43	Jack, hydraulic	S	S	S

### Aller Table 3-923   \$0   \$0   \$0   \$0   \$0   \$0   \$0   \$		r			
907.653   907.657   907.657   907.657   907.657   907.657   ARZ   Adder atio 3.923   50   \$0   \$0   \$0   \$0   \$0   \$0   \$0					
APZ   Addtl. bar for driveshaft & exhaust extension   S.69   S.69   S.0   Most have Collego (Collego (Col			M4CA46	M4CA76	M4CAE6
### AREA Male ratio 3.923 ### AREA MALE RATI			907.653	907.655	907.657
### AREA Male ratio 3.923 ### AREA MALE RATI	AP2	Addtl. bar for driveshaft & exhaust extension	\$69	\$69	-
SSP   SSP   SSS	AR2			·	\$0
Both		not with AR3	•	·	
Both	B01	ESP for increased Center of Gravity above 39.4"	-	\$0	\$0
BEZ         Handbrake lever, folding         555         \$55         \$55           X69 must have BEZ         208         \$268         \$268         \$268           C72         Bumpers front/rear primed         \$268         \$268         \$268         \$268           C82         Stabilization Level III         \$187         \$187         \$187         \$187           C82         Stabilization Level III         \$187         \$187         \$187         \$187           C13         Leather Steering wheel         \$187         \$187         \$187         \$187           C13         Leather Steering wheel         \$187         \$187         \$187         \$187           C13         Leather Steering wheel         \$187         \$187         \$187         \$187           C14         March Steer Level L		·		·	
March Name BE2   S268	BE2		\$55	\$55	\$55
### ### ### ### ### ### ### ### ### ##		-	·	·	,
### State CNZ (part of X67), not with CMO  ### CNZ (part of X67), not with CNZ (part of X67), not with CMO  ### CNZ (part of X67), not with	C72	Bumpers front/rear primed	\$268	\$268	\$268
Stabilization Level   II		·	•		
CEB   Raised rear body mounts   \$252   \$25	CB4		\$187	\$187	\$187
CL3		not with CB7/CB8/X30			
must have (CO2/E3M)/CO3 + (ETA/MS1)   S587   S587   S587   S587   must have (CN2/K97) + (A7/CO1) + J87 + (7755/9197/9775)	CE8		\$252	\$252	\$252
must have (CO2/E3M)/CO3 + (ETA/MS1)   S587   S587   S587   S587   must have (CN2/K97) + (A7/CO1) + J87 + (7755/9197/9775)	CL3	·		\$187	\$187
Similar Metallic front & rear bumper   Similar May (CN2/K67) + (JA7/C01) + JB7 + (7755/9197/9775)		must have (C02/E3M)/C03 + (ET4/MS1)	·		
Primed side moldings	СМО		\$587	\$587	\$587
DO3		must have (CN2/X67) + (JA7/C01) + JB7 + (7755/9197/9775)			
D13	СМ9	Primed side moldings	\$364	\$364	\$364
D13   Mounting rails for roof rack   \$300   \$300   \$300   \$300   \$200	D03	High roof	\$2,900	S	S
D22   Fixed sunroof (rear roof section)   S336   S336   S336   S336   Not with H08/Hk4/H72/V36/Zk4	D13	-	\$300	\$300	\$300
Section	D22			\$336	
Section		not with H08/HK4/H72/V36/ZK4	•		
not with D51/D93/H08/HK4/T74/V36; must have one of T93/T77         \$335         \$335         \$335           D51 Cargo partition with 1 window         \$335         \$335         \$335         \$335           not with D50/D93/H08/HK4/T74/V37/D17; must have one of T93/T77         \$156         \$156         \$156           E18 Tray for smartphones incl. wireless charging         \$156         \$156         \$156           must have C02/E3M, H11         \$728         \$728         \$728           E18 Mavigation         \$728         \$728         \$728           must have C02/E3M, not with C03         \$255         \$255         \$255           E18 Sirius XM, satellite radio         \$255         \$255         \$255           must have C02/E3M/C03         \$0         \$0         \$0           E1X MBUX multimedia 6-hour runtime         -         \$0         \$0           must have C02/E3M/C03         \$0         \$0         \$0           E1X Additional Fuses (40/80/150/100 Ampere)         \$50         \$50         \$50           SoP and Plausibility TBD         \$50         \$50         \$50         \$50           E2A Access point for BB special signals in cockpit         \$29         \$29         \$29         \$29         \$29         \$29         \$29         \$29	D50		\$288	\$288	\$288
DS1   Cargo partition with 1 window   S335   S335   S335   S335   Not with DS0/D93/H08/Hck4/T74/V37/D17; must have one of T93/T77					
E1B Tray for smartphones incl. wireless charging	D51	Cargo partition with 1 window	\$335	\$335	\$335
### ### ### ### ### ### ### ### ### ##		not with D50/D93/H08/HK4/T74/V37/D17; must have one of T93/T77			
S728	E1B	Tray for smartphones incl. wireless charging	\$156	\$156	\$156
### ### ### ### ### ### ### ### ### ##		must have CO2/E3M + H1I			
E1S   Sirius XM, satellite radio   \$255   \$2	E1E	Navigation	\$728	\$728	\$728
### ### ### ### ### ### ### ### ### ##		must have CO2/E3M, not with CO3			
### BUX multimedia 6-hour runtime	E1S	Sirius XM, satellite radio	\$255	\$255	\$255
### ### ### ### ### ### ### ### ### ##		must have CO2/E3M/CO3			
### EIR Additional Fuses (40/80/150/100 Ampere)	E1X	MBUX multimedia 6-hour runtime	-	\$0	\$0
SoP and Plausibility TBD		must have X2R + (C02+E1E/E1S)/C03/(E3M+E1E/E1S)			
Additional Fuses (40/80/80/100 Ampere)   \$50	E1R	Additional Fuses (40/80/150/100 Ampere)	\$50	\$50	\$50
SoP and Plausibility TBD		SoP and Plausibility TBD			
E2A         Access point for BB special signals in cockpit         \$29         \$29         \$29           E2I         Additional battery, co-driver seat base         \$248         \$248         \$248           must have E36/C06; not with E2M/F09; CHS production only         E2M         Additional battery, engine compartment         \$248         \$248         \$248           must have X01+ (E36/C06); not with E2I/X69/F09         E3M         MBUX Multimedia System with 7" touchscreen         \$474         \$474         \$474           not with C02/C03; must have JK5+(IB7/FR8)         E36         Cutoff relay for additional battery         \$110         \$110         \$110           standard with E2I/E2M         \$12 V power outlet, driver seat base         \$92         \$92         \$92           E5M         Extension of PSM standard contact         \$58         \$58         \$58           ED5         Parametric special module (PSM)         \$317         \$317         \$317           not with ED8         \$125         \$125         \$125         \$125           EE3         \$15 V socket         \$125         \$125         \$125           EP7         Basic electric fitting for rear loudspeakers         \$68         \$68         \$68           ES2         \$2 V power outlet, rear compartment         \$92	E1Y	Additional Fuses (40/80/80/100 Ampere)	\$50	\$50	\$50
### E21 Additional battery, co-driver seat base ### \$248 ### ### \$248 ### \$248 ### ### \$248 ### ### ### \$248 ### ### \$248 ### ### ### \$248 ### ### ### ### \$248 ### ### ### \$248 ### ### ### ### \$248 ### ### ### ### ### ### ### ### ### #		SoP and Plausibility TBD			•
must have E36/C06; not with E2M/F09; CHS production only           E2M Additional battery, engine compartment         \$248         \$248           must have X01+ (E36/C06); not with E2I/X69/F09           E3M MBUX Multimedia System with 7" touchscreen         \$474         \$474           not with C02/C03; must have JK5+(JB7/FR8)         \$110         \$110           E36 Cutoff relay for additional battery         \$110         \$110           \$tandard with E2I/E2M         \$92         \$92         \$92           E46 12 V power outlet, driver seat base         \$92         \$92         \$92           E5M Extension of PSM standard contact         \$58         \$58         \$58           ED5 Parametric special module (PSM)         \$317         \$317         \$317           not with ED8         \$125         \$125         \$125           EE7 Basic electric fitting for rear loudspeakers         \$68         \$68         \$68           E52 12 V power outlet, rear compartment         \$92         \$92         \$92           E55 Charging package, dashboard         \$82         \$82         \$82           E74 Active Distance Assist DISTRONIC         \$263         \$263         \$263           must have C02/C03/E3M; not with ZH4         \$14         \$14         \$14	E2A	Access point for BB special signals in cockpit	\$29	\$29	\$29
### Additional battery, engine compartment	E2I	Additional battery, co-driver seat base	\$248	\$248	\$248
must have X01+ (E36/C06); not with E2I/X69/F09           E3M MBUX Multimedia System with 7" touchscreen         \$474         \$474         \$474           not with C02/C03; must have JK5+(JB7/FR8)         \$110         \$110         \$110           E36 Cutoff relay for additional battery         \$110         \$110         \$110           standard with E2I/E2M         \$92         \$92         \$92           E46 12 V power outlet, driver seat base         \$92         \$92         \$92           E5M Extension of PSM standard contact         \$58         \$58         \$58           ED5 Parametric special module (PSM)         \$317         \$317         \$317           not with ED8         \$125         \$125         \$125           EE3 115 V socket         \$125         \$125         \$125           EP7 Basic electric fitting for rear loudspeakers         \$68         \$68         \$68           ES2 12 V power outlet, rear compartment         \$92         \$92         \$92           ES5 Charging package, dashboard         \$82         \$82         \$82           ET4 Active Distance Assist DISTRONIC         \$263         \$263         \$263           must have C02/C03/E3M; not with ZH4         \$14         \$14         \$14		must have E36/C06; not with E2M/F09; CHS production only			
### BUX Multimedia System with 7" touchscreen	E2M	Additional battery, engine compartment	\$248	\$248	\$248
not with CO2/CO3; must have JK5+(JB7/FR8)           E36 Cutoff relay for additional battery         \$110         \$110           standard with E2I/E2M         \$92         \$92         \$92           E46 12 V power outlet, driver seat base         \$92         \$92         \$92           E5M Extension of PSM standard contact         \$58         \$58         \$58           ED5 Parametric special module (PSM)         \$317         \$317         \$317           not with ED8         \$15 V socket         \$125         \$125         \$125           EF7 Basic electric fitting for rear loudspeakers         \$68         \$68         \$68           ES2 12 V power outlet, rear compartment         \$92         \$92         \$92           ES5 Charging package, dashboard         \$82         \$82         \$82           ET4 Active Distance Assist DISTRONIC         \$263         \$263         \$263           must have CO2/CO3/E3M; not with ZH4         \$14         \$14         \$14           F1K Coat hooks in driver cabin         \$14         \$14         \$14		must have X01+ (E36/C06); not with E2I/X69/F09			
\$110   \$110	E3M	MBUX Multimedia System with 7" touchscreen	\$474	\$474	\$474
standard with E2I/E2M         E46       12 V power outlet, driver seat base       \$92       \$92       \$92         E5M       Extension of PSM standard contact       \$58       \$58       \$58         ED5       Parametric special module (PSM)       \$317       \$317       \$317         not with ED8       \$125       \$125       \$125         EE3       115 V socket       \$125       \$125       \$125         EP7       Basic electric fitting for rear loudspeakers       \$68       \$68       \$68         ES2       12 V power outlet, rear compartment       \$92       \$92       \$92         ES5       Charging package, dashboard       \$82       \$82       \$82         ET4       Active Distance Assist DISTRONIC       \$263       \$263       \$263         must have C02/C03/E3M; not with ZH4       \$14       \$14       \$14       \$14         F1K       Coat hooks in driver cabin       \$14       \$14       \$14		not with CO2/CO3; must have JK5+(JB7/FR8)			
E46       12 V power outlet, driver seat base       \$92       \$92       \$92         E5M       Extension of PSM standard contact       \$58       \$58       \$58         ED5       Parametric special module (PSM)       \$317       \$317       \$317         not with ED8       EE3       \$15 V socket       \$125       \$125       \$125         EP7       Basic electric fitting for rear loudspeakers       \$68       \$68       \$68         ES2       12 V power outlet, rear compartment       \$92       \$92       \$92         ES5       Charging package, dashboard       \$82       \$82       \$82         ET4       Active Distance Assist DISTRONIC       \$263       \$263       \$263         must have C02/C03/E3M; not with ZH4       \$14       \$14       \$14       \$14	E36	Cutoff relay for additional battery	\$110	\$110	\$110
E5M   Extension of PSM standard contact   \$58   \$58   \$58   \$58   \$58   \$58   \$55   \$25   \$217   \$317   \$		standard with E2I/E2M			
ED5   Parametric special module (PSM)   \$317   \$3	E46	12 V power outlet, driver seat base	\$92	\$92	\$92
not with ED8           EE3         115 V socket         \$125         \$125           EP7         Basic electric fitting for rear loudspeakers         \$68         \$68           ES2         12 V power outlet, rear compartment         \$92         \$92           ES5         Charging package, dashboard         \$82         \$82           ET4         Active Distance Assist DISTRONIC         \$263         \$263           must have CO2/CO3/E3M; not with ZH4           F1K         Coat hooks in driver cabin         \$14         \$14	E5M	Extension of PSM standard contact			•
EE3       115 V socket       \$125       \$125         EP7       Basic electric fitting for rear loudspeakers       \$68       \$68         ES2       12 V power outlet, rear compartment       \$92       \$92         ES5       Charging package, dashboard       \$82       \$82         ET4       Active Distance Assist DISTRONIC       \$263       \$263         must have CO2/CO3/E3M; not with ZH4         F1K       Coat hooks in driver cabin       \$14       \$14	ED5	Parametric special module (PSM)	\$317	\$317	\$317
EP7 Basic electric fitting for rear loudspeakers \$68 \$68 \$68  ES2 12 V power outlet, rear compartment \$92 \$92 \$92  ES5 Charging package, dashboard \$82 \$82 \$82  ET4 Active Distance Assist DISTRONIC \$263 \$263 \$263  must have CO2/CO3/E3M; not with ZH4  F1K Coat hooks in driver cabin \$14 \$14 \$14					
ES2       12 V power outlet, rear compartment       \$92       \$92       \$92         ES5       Charging package, dashboard       \$82       \$82       \$82         ET4       Active Distance Assist DISTRONIC       \$263       \$263       \$263         must have C02/C03/E3M; not with ZH4       \$14       \$14       \$14         F1K       Coat hooks in driver cabin       \$14       \$14       \$14	EE3				
ES5 Charging package, dashboard \$82 \$82 \$82  ET4 Active Distance Assist DISTRONIC \$263 \$263 \$263  must have CO2/CO3/E3M; not with ZH4  F1K Coat hooks in driver cabin \$14 \$14 \$14	EP7	Basic electric fitting for rear loudspeakers			
ET4 Active Distance Assist DISTRONIC \$263 \$263 \$263 <i>must have C02/C03/E3M; not with ZH4</i> F1K Coat hooks in driver cabin \$14 \$14 \$14	ES2	12 V power outlet, rear compartment	\$92	\$92	
must have C02/C03/E3M; not with ZH4  F1K Coat hooks in driver cabin \$14 \$14 \$14	ES5		-		
F1K Coat hooks in driver cabin \$14 \$14 \$14	ET4	Active Distance Assist DISTRONIC	\$263	\$263	\$263
must have D50/D51	F1K		\$14	\$14	\$14
		must have D50/D51			

		144" 6C	170" 6C	170" E 6C
		M4CA46	M4CA76	M4CAE6
		907.653	907.655	907.657
F49	Electrically heated windshield	\$218	\$218	\$218
175	no restriction	7210	<b>7210</b>	7210
F61	Interior rear view mirror	\$36	\$36	\$36
L01		,550	<b>330</b>	<b>330</b>
FF0	not with D50; must have C02/E3M/C03	Ć01	ć01	Ć01
FE9	Additional DIN-slot	\$81	\$81	\$81
FF4	Storage compartment above cabin	\$186	\$186	\$186
	must have D03, not with D17/D64/H08/HK4	<b>640</b> 5	6405	6405
FF8	Overhead storage slot, front center	\$105	\$105	\$105
FJ1	Hinged lid for storage compartment	\$93	\$93	\$93
FR8	Rear view camera (head unit display)	\$336	\$336	\$336
	must have CO2/E3M; not with FR3/JB7; 3500XD not with JB8	1 .		
FY1	Security alarm w. interior motion sensor	\$584	\$584	\$584
	must have LC4/C00			
FY7	Optional 3-button keys	\$36	\$36	\$36
FZ9	Keys, two additional masters	\$121	\$121	\$121
H00	Warm/cool air duct to rear compartment	\$59	\$59	\$59
	not with D50/D51/Y2A			
H01	Heat insulation, rear compartment	\$156	\$156	\$156
	must have V21/V25/VA3/VA1/C07/X66			
H04	Heat insulation, front compartment	\$187	\$187	\$187
	if + D50/D51 must have V07			
H08	Air conditioning rear, roof-mounted	\$2,872	\$2,872	\$2,872
	must have D93 +V36; not with HK4/C06/X66/C07		. ,	
H12	Fuel-fired pre-heater/booster (17K BTU)	\$1,116	\$1,116	\$1,116
	not with HZ9	. ,	. ,	, ,
H13	Rear cabin heater and vents	\$786	\$786	\$786
	must have H12/HZ9	φ, σσ	φ/ σσ	φ. σσ
H15	Heated front passenger seat	\$284	\$284	\$284
1113	must have H16; not with X68	Ψ20 I	Ψ20 I	Ψ201
H16	Heated driver's seat	\$284	\$284	\$284
1110	must have H15; not with X68	Ş20 <del>4</del>	Ş20 <del>4</del>	Ş20 <del>4</del>
<b>⊔</b> 22	Rear window defroster	¢2E2	\$253	\$253
H22		\$253	\$255	\$255
1172	must have W61/W78; standard for W61+W70	¢400	ć400	ć 400
H72	Roof fan, electric	\$400	\$400	\$400
	not with D22/V36	4405	4.05	4405
H88	Rear heater prep	\$405	\$405	\$405
	must have H12/HZ9; not with H13/T19	4-	4-	4 -
H1I	Front-to-rear outlet in instrument panel	\$0	\$0	\$0
	must have FJ1/C01			
HH4	Thermotronic automatic climate control	\$337	\$337	\$337
	must have JF1; if +H13 must have H08/HK4			
HK4	Rear air conditioner, heavyduty	\$3,940	\$3,940	\$3,940
	must have D03+V36+D93; not with H08/ZB6/ZE6/N62/N63			
HZ9	Fuel-fired heater booster (18,000 BTU)	\$676	\$676	\$676
	not with H12			
J51	Fuel gauge, optimized for aux. fuel tap	\$72	\$72	\$72
	not with HZ9/H12			
J52	Engine oil level display at cold start	\$0	\$0	\$0
JA7	Blind Spot Assist	\$450	\$450	\$450
	not with CO1			
JB4	Active Lane Keeping Assist	\$288	\$288	\$288
<u> </u>	standard with CO2/CA2	,		
JB7	Parking Package	\$615	\$615	\$615
<del>                                     </del>	must have CO2/CO3/E3M; not with W75/W76/JB6	7013	7013	7013
JF1	Rain sensor	\$106	\$106	\$106
JK5	Instrument cluster with color display	\$100	\$100	\$100
71/2		7144	À144	<b>→144</b>
	standard with C02/CA2			

		144" 6C	170" 6C	170" E 6C
		M4CA46 907.653	M4CA76 907.655	M4CAE6
				907.657
JW0	Backup alarm	\$99	\$99	\$99
JW2	Deactivation lamp monitoring failure	\$27	\$27	\$27
JW8	Attention Assist	\$49	\$49	\$49
K51	Misfueling prevention for Diesel	\$49	\$49	\$49
K52	DEF fluid filler cap - lockable	\$27	\$27	\$27
L13	Fog lamp with cornering light function	\$199	\$199	\$199
L71	Light/motion sensor in rear compartment	\$54	\$54	\$54
	not with V36			
LB9	Illuminated front exits	\$151	\$151	\$151
LC2	LED light strip in load compartment	\$263	\$263	\$263
	not with H08/HK4/V36/C06			
LC4	Comfort overhead control panel	\$93	\$93	\$93
M20	Speed limitation 65 mph	\$60	\$60	\$60
	not with MD3			_
MD3	Top speed limitation 75 mph	\$60	\$60	\$60
	not with M20			
N62	Front engine bracket for additional alternator	\$467	\$467	\$467
	not with HK4/N63			
N63	Front engine bracket for auxiliary A/C compressor	\$467	\$467	\$467
	not with HK4/N62			
P93	Omission of D-rings	-\$15	-\$15	-\$15
	not with D93/V43/VK8			
QA2	Trailer cross member 7,500 lbs capacity	\$186	\$186	-
	not with W73/W75/W76/Q24/Q67			
QA9	Half-sided step rear (for trailer hitch)	\$101	\$101	\$101
	must have QA2; not with W73/W75/W76			
Q24	Trailer hitch, 5,000 lbs	-	-	\$147
	not with W73/W75/W76			
R91	Spare tire deletion	-\$110	-\$110	-\$110
	must have R92; not with R87			
R92	Spare tire carrier deletion	\$0	\$0	\$0
	must have R91; not with R65			
R98	Rims painted jet black	\$81	\$81	\$81
	not with RL5/RM2	<u>,                                      </u>		
RF1	Tire brand Continental	\$0	\$0	\$0
	must have RM1 + RM9			
RF8	Tire brand Michelin	\$0	\$0	\$0
	must have RM9; not with RM1			
RH0	Tire brand Kumho	\$0	\$0	\$0
	must have RM9; not with RM1	•		•
RM1	M+S winter tires	\$169	\$169	\$169
	must have RF1/RD9; not with RF8/RH0/X31	•		•
RM2	Rims painted arctic white	\$81	\$81	\$81
	not with R98/RL5	•		•
RM9	Specially requested tires	\$101	\$101	\$101
	must have RF1/RF8/RH0; not with RD9			
S23	Twin front passenger seat	\$400	\$400	\$400
	not with C00/X68/X01			
S28	Armrest, driver and passenger door	\$51	\$51	\$51
S62	Seat belts orange, driver and front passenger	\$32	\$32	\$32
	not with S23			
SB9	Driver's seat plus	\$238	\$238	\$238
Ť	must have VF7; not with C00/X68/X69	7-50		
SZ7	Storage net, driver's seat backrest	\$64	\$64	\$64
SZ8	Storage net, passenger seat backrest	\$64	\$64	\$64
T12	Sliding door two stage opening	\$82	\$82	\$82
	not with T55	, ,,,,	7-2	
<b></b>	ļ			

			1	
		144" 6C	170" 6C	170" E 6C
		M4CA46	M4CA76	M4CAE6
		907.653	907.655	907.657
T19	Sliding door, driver's side	\$935	\$935	\$935
	not with H13/H88/VC5/ZE6/F43/W16/F02; if +V36 must have D03	•		
T50	Electric closing assist right sliding door	\$335	\$335	\$335
	must have D03; not with T55/T93			
T51	Electric closing assist left sliding door	\$335	\$335	\$335
	must have T19 + D03			
T55	Electric sliding door right	\$831	\$831	\$831
	must have D03 + (FY7+T16); not with T12/T50			
T57	Electric sliding step	\$1,071	\$1,071	\$1,071
	must have ED5; not with T93			
T60	Opening limiter electrically operated sliding door	\$120	\$120	\$120
	must have T55	1 4	4	4
T74	Assist handle, B-pillar	\$32	\$32	\$32
<u></u>	must have D93; not with T77	450	ģ.	Ġ.F.O.
T75	Door-mounted assist handles, driver & passenger	\$59	\$59	\$59
T77	Assist handle w/ partition	\$32	\$32	\$32
T85	must have D50/D51/D64 Assist handle, left rear door	\$32	\$32	\$32
T86	Assist handles, right rear door	\$32	\$32	\$32
T93	Sliding door right side deletion	\$52 \$0	\$52 \$0	\$32 \$0
133	not with T16/T50/T57/VK8/VC5	ŞÜ	Ų	<b>30</b>
V07	Cab rear wall liner	\$360	\$360	\$360
107	must have (D50/D51)+F1K; standard with H04	7300	<b>\$300</b>	<b>\$300</b>
V21	Luxury interior Trim	\$661	\$661	\$661
	must have VA5/VA7; not with V52/VA1/VA3	700-	7000	7002
V24	Pallet support in sliding door step	\$96	\$96	\$96
	must have (V43/X66)+(D50/D51); not with VK8/V93/C07		,	·
V25	Half height load compartment trim	\$201	\$201	\$201
	not with VA1/VA3/VA5/V52/X66	•		
V31	Window pillar trim	\$513	\$513	\$513
	must have V36 + (V21/VA1) + (F02/F03/F07); not with V42			
V35	Wheel house covering	\$105	\$105	\$105
	if +V43 must have V25/VA1/VA3; not with V52			
V36	Roof trim	\$876	\$876	\$876
	must have D93; not with D17/D22/H72/L65/L71/LC2/VA3/V42/ZE6/(			
V42	Lashing rails, waist level	\$277	\$277	\$277
	not with V36/ZE6			
V43	Wood floor with 6 D-rings	\$422	\$422	\$422
	not with P93/V93/VL4/VK8/C07; standard with D93/H13/V24/V52/V		4	4
V48	Floor cover behind seat box	\$27	\$27	\$27
	must have D93; not with D50/D51/D56/D62/D64/V43/VK5	<b>4400</b>	<b>\$400</b>	64.00
V4A	Full paneling, right sliding door	\$109	\$109	\$109
1/05	must have D03+T16+V21+VA5+W17; not with T19	¢20	¢20	630
V85	Cigarette lighter & ash cup, front	\$39	\$39	\$39
VA1	Side wall paneling waist height PVC  must have VA5/VA7; not with V52	\$319	\$319	\$319
VA3	Side wall paneling full hardboard	\$444	\$444	\$444
VAS	not with V36/F02; if T93 must have (D50/D51)	<b>у444</b>	Ş <del>444</del>	<b>3444</b>
VA5	Full paneling, hinged rear doors	\$38	\$38	\$38
• 7.5	must have D03+VA7+(W61/W78); not with V25	733	755	750
VA7	Storage compart. w/ net in rear doors	\$127	\$127	\$127
	must have W61/W78; not with V52	τ <i>'</i>	,	7
VC4	Cargo lashing rails, head height	\$415	\$415	\$415
	must have V42/C07/X66; not with ZE6			
VC5	Door sill - protective edge	\$71	\$71	\$71
	must have V43/X66; not with T19/T93/VK8/VV2/V93/C07			
VK8	Floor covering, plastic	\$370	\$370	\$370
	not with V43/P93/T19/T93/V52/VC5/X66			

		144" 6C	170" 6C	170" E 6C
		M4CA46	M4CA76	M4CAE6
		907.653	907.655	907.657
VV2	Lashing rails, floor level (plus 4 anchors)	\$270	\$345	\$377
	must have V43; not with V93/VC5/ZE6	,	,	
W16	2nd row, fixed window, driver side	\$145	\$145	\$145
	if D93 must have F43+W70; if D93 & standard roof CHS production red		,	
W17	2nd row, fixed window, passenger side	\$145	\$145	\$145
	if D93 must have F43+W70; if D93 & standard roof CHS production red	quired		
W33	FMVSS 217 emergency exit	-	\$379	\$379
	must have V31; not with D50/T19/W16	•		
W54	Rear doors, opening to side wall	\$360	\$360	S
W5F	90 Degree fixation point- Rear Doors	\$80	\$80	\$80
	SoP and Plausibility TBD			
W61	Windows in rear doors	\$93	\$93	\$93
	must have VA7/ if D51 must have F61; not with W78/(W70+-(H22/F02	2))		
W70	Black tinting (90%) for rear windows	\$138	\$138	\$138
	not with W94; must have W16/W17/F02/((W61/W78)+H22); standar	d with F43/W33/	′F07	
W73	Bumper step, rear, grey	\$187	\$187	\$187
	not with QA2/W75/W76			
W75	Step, wide, at rear end	\$308	\$308	\$308
	not with JB6/JB7/Q24/QA9; must have R91+R92			
W76	Bumper step, rear, spring-loaded	-	\$601	\$601
	must have R91+R92; not with JB6/JB7/X30/Q24			
W78	Heated rear window(s) w/ washers/wipers	\$335	\$335	\$335
	Must have H22+VA7 / if D51 must have F61; not with W61	•	•	•
X90	Deletion of Sprinter badge, left rear door	\$0	\$0	\$0
X93	Deletion of model badge, right rear door	\$0	\$0	\$0
X2R	Conversion to RV requirement	-	\$0	\$0
	must have B01+D93+E1X	ı		
XM4	Acoustic package	\$87	\$87	\$87
	standard with CO2/CO3	,	,	
Y10	First-aid kit	\$27	\$27	\$27
Y26	Wheel chocks	\$38	\$38	\$38
Y45	Emergency flashlight	\$27	\$27	\$27
Y68	Paint preservative	\$187	\$212	\$225
Y69	Surface protection for stock vehicles	\$315	\$315	\$315
YK3	Cargo straps, D-rings	\$81	\$81	\$81
YK4	Cargo straps, lashing rails	\$104	\$104	\$104
	must have V42/VV2; not with ZE6	ٱ0 <del>1</del>	7104	Ş <u>1</u> 04
ZE6	Shelving prep	\$640	\$640	\$640
120	not with T93/H13/T19/V36/V42/VC4/VK8/VV2/YK4	ŞU40	Ş0 <del>4</del> 0	Ş0 <del>4</del> 0
	110L WILII 133/113/113/V30/V42/VC4/VK8/VV2/YK4			

# **4500 CARGO VAN - 6cyl Diesel** Packages

		144" 6C	170" 6C	170" E 6C	
		M4CA46	M4CA76	M4CAE6	
		907.653	907.655	907.657	
C00	Comfort Package	\$300	\$300	\$300	
LC4	Comfort overhead control panel	Х	X	X	
SE4	Lumbar support, co-driver's seat	Х	Х	X	
SE5	Lumbar support, driver's seat	Х	Х	X	
SK0	Comfort head restraint, driver	Х	Х	X	
SK1	Comfort head restraint, co-driver	Х	Х	X	
S28	Armrest, driver and passenger door	X	Х	X	
must	nust have COS OR X68; CA/CC only: not with S23				

COS	Comfort Package (Seat addition)	\$381	\$381	\$381
SB1	Comfort driver's seat	X	X	X
SB2	Comfort passenger seat	X	X	Х
must	nust have COO			

X68	Comfort Plus Package	\$1,923	\$1,923	\$1,923
H15	Heated front passenger seat	Х	X	X
H16	Heated driver's seat	Х	X	X
SF1	Driver's seat electrically adjustable	Х	X	X
SF2	Co-driver's seat electrically adjustable	Х	Х	Х
must	must have C00 and VF4 OR VF6, CA/CC only: not with S23			

C01	Driver Convenience Package	\$760	\$760	\$760
E46	12 V power outlet, driver seat base	X	X	X
F64	Electrically folding exterior mirrors	Х	X	X
FJ1	Hinged lid for storage compartment	Х	X	X
FJ5	Hinged Lid for Storage Compartments left and right	X	X	X
FZ9	Keys, two additional masters	X	X	X
JA7	Blind Spot Assist	Х	X	Х
JW8	Attention Assist	X	X	X

C02	Premium Package	\$983	\$983	\$983
CL3	Leather steering wheel	X	X	X
E3M	MBUX Multimedia System with 7" touchscreen	X	X	X
FM3	Wet Wiper System	X	X	X
JB4	Active Lane Keeping Assist	X	Х	X
JK5	Instrument cluster with color display	X	X	X

Ordering availability restricted, see NetStar for availability and restrctions|must have JF1 + XM4; must choose FR8/JB7

CA2	C02 in combination with C03	\$604	\$604	\$604	
CL3	Leather steering wheel	X	X	Х	
FM3	Wet Wiper System	Х	X	Х	
JB4	Active Lane Keeping Assist	X	X	Х	
JK5	Instrument cluster with color display	Х	X	Х	
Orde	Ordering availability restricted, see NetStar for availability and restrctions   must have CO3 + JF1				

# **4500 CARGO VAN - 6cyl Diesel** Packages

144" 6C	170" 6C	170" E 6C
M4CA46	M4CA76	M4CAE6
907.653	907.655	907.657

C03	Premium Plus Package	\$1,793	\$1,793	\$1,793
E1B	Tray for smartphones incl. wireless charging	X	X	X
	Navigation	Х	X	Х
EY2	Intelligent navigation	Х	Х	X
E4M	MBUX Multimedia System with 10.25" touchscreen	Х	X	X
EX9	Free map data updates for 3 years	X	X	X
H1I	Front-to-rear outlet in instrument panel	X	X	X
JA9	Traffic Sign Assist	X	X	X
XM4	Acoustic package	Х	Х	Х
must	have (CA2+JB7) OR (JB4+JK5+FM3+JB7); not with FR8 and CO2			-

X67	Chrome Grille Package	\$290	\$290	\$290
CN2	Radiator grille frame in vehicle color	X	X	X
FK3	Chrome plated radiator grille (MB only)	X	X	X
no re	no restrictions			

X13	Exterior Lighting Package	\$1,608	\$1,608	\$1,608
L13	Fog lamp with cornering light function	X	X	Х
L22	Partial LED tail lights	X	X	X
LA1	High beam assist	Х	Х	Х
LG7	LED high performance headlamps	X	X	Х
no re	no restrictions			

C06	Cargo Convenience Package	\$658	\$658	\$658
E36	Cutoff relay for additional battery	Х	Х	Х
ES2	12 V power outlet, rear compartment	Х	Х	Х
LC2	LED light strip in load compartment	Х	Х	Х
T12	Sliding door two stage opening	Х	Х	Х
T85	Assist handle, left rear door	Х	Х	Х
T86	Assist handles, right rear door	Х	X	Х
W54	Rear doors, opening to side wall	Х	X	Х
must	have T74 OR (T77+D50) OR (T77+D51)			

C07	Cargo Protection Package	\$1,117	\$1,117	\$1,117
V25	Half height load compartment trim	Х	X	X
V42	Lashing rails, waist level	Х	X	X
VC4	Cargo lashing rails, head height	Х	X	X
VK8	Floor covering, plastic	Х	X	X
YK3	Cargo straps, D-rings	Х	X	X
not v	not with X66			

X66	Heavy-Duty-Cargo Protection Package	\$2,043	\$2,043	\$2,043
V43	Wood floor with 6 D-rings	X	Х	X
V42	Lashing rails, waist level	Х	Х	X
V52	Loadable wheel arch	X	X	X
VA3	Side wall paneling full hardboard	Х	X	X
VC4	Cargo lashing rails, head height	Х	X	X
VV2	Lashing rails, floor level (plus 4 anchors)	Х	X	X
YK3	Cargo straps, D-rings	Х	Х	X
YK4	Cargo straps, lashing rails	X	X	X
not v	not with CO7			

## 4500 CARGO VAN - 6cyl Diesel

Packages

144" 6C	170" 6C	170" E 6C
M4CA46	M4CA76	M4CAE6
907.653	907.655	907.657

X69	Swivel Seat Package	\$532	\$532	\$532	
SR8	Swivel base for driver's seat	Х	X	X	
SR9	Swivel base for front passenger seat	Х	X	X	
S87	Driver's seat frame, low	Х	Х	Х	
S88	Passenger seat frame, low	Х	Х	Х	
must	nust have (C00+C0S) OR (C00+X68)				

X01	Suspension Seating Package	\$940	\$940	\$940
SB3	Driver suspension seat, comfort version	Х	X	X
SB4	Passenger suspension seat, comfort version	X	X	X
S87	Driver's seat frame, low	Х	Х	X
S88	Passenger seat frame, low	Х	Х	Х
not v	not with C00/C0S/E2I/X68/S23			

F09	SHUTTLE DOOR PREP PACKAGE	\$0	\$0	\$0
SW1	Seat belt deletion, passenger	X	X	X
S91	Passener seat, deleted	Х	Х	Х
S99	Passenger seat pedestal - deletion	Х	Х	Х

Package deletes standard options: SH2 Thorax-Pelvis sidebag, co-driver; To add/delete from order must call distirbution team

144" G

170" G

		M2CV4G	M2CV7G		
		907.643	907.645		
Engin	e				
	ngine/9-Speed Trans.	S	S		
_	AGM battery 12V 92 AH 850 A	S	S		
	Automatic transmission, 9G-tronic	S	S		
	SULEV emissions	S	S		
	2.0L 4-cylinder turbo gasoline engine	S	S		
_	Alternator 14 V / 250 A	S	S		
Seating and Trim Packages					
	Standard Rear Seats	S	S		
U62	3-seater bench rear, 1st row (narrow)	S	S		
	Wall-side armrest	S	S		
U75	Aisle-side armrest	S	S		
can h	ave VF7/VF6 only; with X68 must have VF6				
	Standard Trim Crew Van Package	S	S		
V25	Half height load compartment trim	S	S		
V35	Wheel house covering	S	S		
V43	Wood floor with 6 D-rings	S	S		
Equip					
	Axle ratio 4.182	S	S		
BA3	Active Brake Assist	S	S		
BH1	Hold Function	S	S		
C6L	Multifunction steering wheel	S	S		
CL1	Adjustable steering wheel (angle)	S	S		
D03	High roof	0	S		
D93	Omission bulkhead	S	S		
E07	Hill Start Assist	S	S		
_	Standard radio	S	S		
E1U	USB-C socket, 5 V	S	S		
E30	Starter battery disconnect	S	S		
E3J	Pre-installation for switch panel	S	S		
	Trailer hitch prep. wiring	S	S		
ED8	Preinstallation PSM	S	S		
		_			
EE5	Ultracapacitor discharge module	S S	S S		
EK1	Body Builder Connector		S S		
ESO	Jump start terminal	S			
EW6	Pre-installation for Mercedes me Remote Services	S	S		
EY5	Emergency Call System	S	S		
EY6	Breakdown management	S	S		
F68	Heated & electrically adjustable exterior mirrors	S	S		
F43	Laminated glass rear	S	S		
FF3	Cupholder rear compartment	S	S		
FF5	Shelf above windshield	S	S		
FG8	Cupholder front	S	S		
FI1	Remote key (315 mhz) w/central locking	S	S		
FJ4	Storage compartment underneath cockpit	S	S		
FR3	Rear view camera (rear-view mirror display)	S	S		
H00	Warm/cool air duct to rear compartment	S	S		
H21	Windshield with filter band	S	S		
H22	Rear window defroster	S	S		
HH2	Heater, auxiliary electric hot air	S	S		
HH9	Air Condition, Front	S	S		
IH7	Head Unit, North America	S	S		
J11	Speedometer, miles and km/h	S	S		
J1W	Service Interval 1 year	S	S		
J55	Seat belt warning for co-driver seat	S	S		
J58	Seat belt reminder driver	S	S		
J65	Outside temperature gauge	S	S		

**2500 CREW VAN - GAS**Standard Equipment

		144" G	170" G
		M2CV4G	M2CV7G
		907.643	907.645
JA8	Crosswind Assist	S	S
JH3	Communication module (LTE) for dig. services	S	S
J18	Service interval 15.000 miles	S	S
	22 gallon fuel tank	S	S
K60	Exhaust straight to rear	S	S
L94	Parking lights deletion	S	S
	Headlight assistant	S	S
	3rd brake light	S	S
MS1	Cruise control	S	S
P47		S	
-	Front mudflaps		S
-	Rear mudflaps	S	S
	Longitudinal member reinforcement	S	S
	Spare tire bracket below frame	S	S
_	Spare tire	S	S
-	Unspecified tire brand	S	S
_	Tires LT 245/75 R16	S	S
-	All-season tires	S	S
	6.5 J x 16 steel wheels	S	S
RY2	Tire pressure monitoring sensors	S	S
S02	Standard driver seat	S	S
S04	Standard front passenger seat	S	S
S22	Armrest for driver's seat	S	S
S25	Armrest for front passenger seat	S	S
SA5	Front airbag, driver	S	S
SA6	Front airbag, passenger	S	S
SH1	Thorax-pelvis sidebag, driver	S	S
SH2	Thorax-pelvis sidebag, co-driver	S	S
SH9	Airbag, driver/passenger window	S	S
SK2	Seat occupancy sensor, driver's seat	S	S
T16	Sliding door, passenger side	S	S
T74	Assist handle, B-pillar	S	S
U22	Pre-inst. for seating configuration Crew Van	S	S
V35	Wheel house covering	S	S
V36	Roof trim	S	S
V40	Floor anchors for rear seat bench	S	S
_	Storage compart. w/ net in rear doors	S	S
	2nd row, fixed window, driver side	S	S
W17	2nd row, fixed window, passenger side	S	S
W61	Windows in rear doors	S	S
_	Black tinting (90%) for rear windows	S	S
XL2	GVWR 9,050 lbs. / 4.100 Kg	S	S
Y43	Jack, hydraulic	S	S
		J	

M2CV76   M2CV76   907.643   907.645   907.643   907.645   907.643   907.645   907.64			144" G	170" G
### ### ### ### ### ### ### ### ### ##				
ASO   Front axia reinforced   \$346   \$346   \$346   \$326   \$AP2   Addtl. Bar for driveshaft & exhaust extension   \$59   \$50				
APZ         Addtl. Dar for driveshaft & exhaust extension         \$59         \$69           825         Electric parking brake         \$279         \$279           C72         Bumpers front/rear primed         \$268         \$268           must how CAV/X67, not with CMO         \$268         \$268           B01         ESP for increased Center of Gravity above 39.4"         \$0         \$0           must how CB4/CB8/X30, not with RHO/CB7         \$1         \$241         \$241           CB1         Suspension for comfort and load protection         \$241         \$241           CB7         Stabilization Level I         \$307         \$307           not with CB4/CB8/X30         \$2         \$2           CB8         Stabilization Level II         \$723         \$723           not with CB4/CB8/ZG3         \$187         \$187         \$187           CB0         Stabilization Level II         \$723         \$723           MD         Winter Backering Wheel         \$187         \$187           MD         Stabilization Level III         \$728         \$728           MD         Stabilization Level III         \$187         \$187           MD         Stabilization Level III         \$187         \$187           MD			907.643	907.645
Security	A50			
	AP2	Addtl. bar for driveshaft & exhaust extension	·	·
See	B25	Electric parking brake	\$279	\$279
### ### ### ### ### ### ### ### ### ##		no restrictions		
SP   For increased Center of Gravity above 39.4"   S0   \$0   \$0   S0   S0   S0   S0   S0	C72	Bumpers front/rear primed	\$268	\$268
must have CB4/CB8/X30, not with RH0/CB7   S241		must have CN2/X67, not with CM0		
Suspension for comfort and load protection   \$241   \$241   \$241   \$307   \$307   \$307   \$307   \$307   \$307   \$307   \$307   \$0	B01	ESP for increased Center of Gravity above 39.4"	\$0	\$0
Stabilization Level		must have CB4/CB8/X30; not with RH0/CB7		
Not with CB4/CB8/X30   S723   S723   S723   Not with CB4/CB8/X30   S723   S723   Not with CB4/CB8/ZG3   S723   S	CB1	Suspension for comfort and load protection	\$241	\$241
Stabilization Level	CB7	Stabilization Level I	\$307	\$307
		not with CB4/CB8/X30	<del>,</del>	
CL3	CB8	Stabilization Level II	\$723	\$723
must have (C02/E3M)/C03 + (ET4/MS1)         \$587         \$587           CMD Painted metallic front & rear bumper         \$587         \$587           must have (C02/E67) + (IAT/C01) + (IB6/IB7) + (7755/9197/9775)         \$364         \$364           CMP Primed side moldings         \$364         \$364         \$364           CT1         Rear spring vibration absorbers         \$138         \$138         \$138           D3         High roof         \$2,900         \$         \$2,900         \$           D03         Must have be added for Duesseldorf production         \$300         \$300         \$300         \$300           B13         Tray for smartphones incl. wireless charging must have C02/E3M + H1         \$156         \$156         \$156           E1B         Tray for smartphones incl. wireless charging must have C02/E3M, not with C03         \$728         \$728         \$728           E1E         Navigation         \$728         \$728         \$728         \$728           E1E         Navigation         \$728         \$728         \$728           must have C02/E3M, not with C03         \$50         \$50         \$50         \$50         \$50         \$50         \$50         \$50         \$50         \$50         \$50         \$50         \$50         \$50		not with CB4/CB8/ZG3		
must have (C02/E3M)/C03 + (ET4/MS1)         \$587         \$587           CMD Painted metallic front & rear bumper         \$587         \$587           must have (C02/E67) + (IAT/C01) + (IB6/IB7) + (7755/9197/9775)         \$364         \$364           CMP Primed side moldings         \$364         \$364         \$364           CT1         Rear spring vibration absorbers         \$138         \$138         \$138           D3         High roof         \$2,900         \$         \$2,900         \$           D03         Must have be added for Duesseldorf production         \$300         \$300         \$300         \$300           B13         Tray for smartphones incl. wireless charging must have C02/E3M + H1         \$156         \$156         \$156           E1B         Tray for smartphones incl. wireless charging must have C02/E3M, not with C03         \$728         \$728         \$728           E1E         Navigation         \$728         \$728         \$728         \$728           E1E         Navigation         \$728         \$728         \$728           must have C02/E3M, not with C03         \$50         \$50         \$50         \$50         \$50         \$50         \$50         \$50         \$50         \$50         \$50         \$50         \$50         \$50	CL3	Leather steering wheel	\$187	\$187
Painted metallic front & rear bumper   \$587   \$587   \$587   must have (CNZ/K67) + (IA7/CO1) + (IB6/IB7) + (7755/9197/9775)   \$364   \$		<u> </u>	·	ļ
must have (CN2/X67) + (IA7/C01) + (IB6/IB7) + (7755/9197/9775)         \$364         \$364           CMP primed side moldings         \$138         \$138           D03 High roof         \$2,900         \$           D03 must be added for Duesseldorf production         \$300         \$300           D13 Mounting rails for roof rack         \$300         \$300           E1B Tray for smartphones incl. wireless charging         \$156         \$156           must have C02/E3M + H1I         \$728         \$728           E1E Navigation         \$728         \$728           must have C02/E3M, not with C03         \$255         \$255           E1S Sirius XM, satellite radio         \$255         \$255           must have C02/E3M/C03         \$800         \$800           E1R Additional Fuses (40/80/100 Ampere)         \$50         \$50           SOP and Plausibility TBD         \$80         \$50         \$50           E1Y Additional Fuses (40/80/80/100 Ampere)         \$50         \$50         \$50           SOP and Plausibility TBD         \$80         \$80         \$50         \$50           E2Y Additional Fuses (40/80/80/100 Ampere)         \$50         \$50         \$50         \$50         \$50         \$50         \$50         \$50         \$50         \$50	СМО		\$587	\$587
CM9         Primed side moldings         \$364         \$364           CT1         Rear spring vibration absorbers         \$138         \$138           D03         High roof         \$2,900         \$           D03         Mush for Consequence         \$300         \$300           E1B         Tray for smartphones incl. wireless charging         \$156         \$156           mush fave CO2/E3M + H1I         ***         ***         ***           E1E         Navigation         \$728         \$728         ***           mush fave CO2/E3M, not with CO3         ***		'	,	,
CT1         Rear spring vibration absorbers         \$138         \$138           D03         High roof         \$2,900         \$           D03         Must be added for Duesseldorf production           D13         Mounting rails for roof rack         \$300         \$300           E1B         Tray for smartphones incl. wireless charging         \$156         \$156           must have CO2/E3M + H11         ***         ***           E1E         Navigation         \$728         \$728           must have CO2/E3M, not with CO3         ***         ***           E1S         Sirius XM, satellite radio         \$255         \$255           must have CO2/E3M/CO3         ***         ***           E1A         Additional Fuses (40/80/100/100 Ampere)         \$50         \$50           SOP and Plausibility TBD         ***         ***         \$29         \$29           E1Y         Additional Fuses (40/80/80/100 Ampere)         \$50         \$50         \$50           SOP and Plausibility TBD         ***         \$29         \$29         \$29         \$29         \$29         \$29         \$29         \$29         \$29         \$29         \$29         \$29         \$29         \$29         \$29         \$29         \$29	CM9		\$364	\$364
D03				
D03 must be added for Duesseldorf production   S300   S3				
D13   Mounting rails for roof rack   \$300   \$300   \$300   \$156			Ψ2,300	J
### E1B Tray for smartphones incl. wireless charging ### \$156 ###	D13		\$300	\$300
### ### ### ### ### ### ### ### ### ##			· ·	· ·
### E1E Navigation			7130	7130
### ### ### ### ### ### ### ### ### ##	F1F		\$728	\$728
Sirius XM, satellite radio	LIL		Ş720	Ş720
### ### ##############################	E10		ĊZEE	¢255
E1R         Additional Fuses (40/80/150/100 Ampere)         \$50         \$50           SoP and Plausibility TBD         \$50         \$50           E2Y         Additional Fuses (40/80/80/100 Ampere)         \$50         \$50           SoP and Plausibility TBD         \$29         \$29           E2A         Access point for BB special signals in cockpit         \$29         \$29           E2I         Additional battery, co-driver seat base         \$248         \$248           Must have E36, not with E2M; CHS production only         \$110         \$110           E3G         Cutoff relay for additional battery         \$110         \$110           \$110         \$110         \$110         \$110           \$110         \$110         \$110         \$110           \$20         \$20/20         \$248         \$248           \$248         \$248         \$248           \$248         \$248         \$248           \$248         \$248         \$248           \$248         \$248         \$248           \$248         \$248         \$248           \$248         \$248         \$248           \$25         \$27         \$27         \$317           \$28         \$58         \$58	L13		<b>3233</b>	\$233
SoP and Plausibility TBD	E1D		¢E0	¢E0
E1Y         Additional Fuses (40/80/80/100 Ampere)         \$50         \$50           SoP and Plausibility TBD         \$29         \$29           E2A         Access point for BB special signals in cockpit         \$29         \$29           E2I         Additional battery, co-driver seat base         \$248         \$248           Must have E36; not with E2M; CHS production only         \$110         \$110           E36         Cutoff relay for additional battery         \$110         \$110           E37         Standard with E2I/E2M         \$110         \$110           E3M         MBUX Multimedia System with 7" touchscreen not with C02/C03; must have JK5+(JB7/JB6/JB8/FR8)         \$474         \$474           E5M         Extension of PSM standard contact         \$58         \$58           E5D         Parametric special module (PSM)         \$317         \$317           not with EDB         \$15         \$125         \$125         \$125	LIK		\$30	\$30
SoP and Plausibility TBD  E2A Access point for BB special signals in cockpit  E2A Additional battery, co-driver seat base  Must have E36; not with E2M; CHS production only  E36 Cutoff relay for additional battery  standard with E2I/E2M  E3M MBUX Multimedia System with 7" touchscreen  not with C02/C03; must have JK5+(JB7/JB6/JB8/FR8)  E5M Extension of PSM standard contact  \$58 \$58  EDS Parametric special module (PSM)  not with EDB  E63 115 V socket  \$115 V socket  \$125 \$125  E52 12 V power outlet, rear compartment  \$92 \$92  E55 Charging package, dashboard  \$82 \$82  ET4 Active Distance Assist DISTRONIC  must have C02/C03/E3M; not with ZH4  F49 Electrically heated windshield  no restrictions  F61 Interior rear view mirror  must have E3M/C02/C03  FE9 Additional DIN-slot  FF8 Overhead storage slot, front center  \$93 \$93  FR8 Rear view camera (head unit display)  must have C02/E3M; not with FR3/JB7/JB6/JB8  FY1 Security alarm w. interior motion sensor  \$584 \$584	E1V	,	¢E0	¢E0
E2A Access point for BB special signals in cockpit  E2I Additional battery, co-driver seat base  Must have E36; not with E2M; CHS production only  E36 Cutoff relay for additional battery  standard with E2I/E2M  E3M MBUX Multimedia System with 7" touchscreen  not with CO2/CO3; must have JK5+(JB7/JB6/JB8/FR8)  E5M Extension of PSM standard contact  E5M Parametric special module (PSM)  not with ED8  E53 115 V socket  E51 12 V power outlet, rear compartment  S20 \$92 \$92  E55 Charging package, dashboard  E74 Active Distance Assist DISTRONIC  must have CO2/CO3/E3M; not with ZH4  F49 Electrically heated windshield  no restrictions  F61 Interior rear view mirror  must have E3M/CO2/CO3  FF9 Additional DIN-slot  FF8 Overhead storage slot, front center  F11 Hinged lid for storage compartment  \$93 \$93  FF8 Rear view camera (head unit display)  \$336 \$336  must have CO2/E3M; not with FR3/JB7/JB6/JB8  FY1 Security alarm w. interior motion sensor  \$584 \$584	ETI		\$50	\$50
E2I Additional battery, co-driver seat base  Must have E36; not with E2M; CHS production only  E36 Cutoff relay for additional battery  standard with E2I/E2M  E3M MBUX Multimedia System with 7" touchscreen  not with C02/C03; must have JK5+(JB7/JB6/JB8/FR8)  E5M Extension of PSM standard contact  ED5 Parametric special module (PSM)  not with ED8  EE3 115 V socket  S125 \$125  E52 12 V power outlet, rear compartment  \$92 \$92  E55 Charging package, dashboard  E74 Active Distance Assist DISTRONIC  must have C02/C03/E3M; not with ZH4  F49 Electrically heated windshield  no restrictions  F61 Interior rear view mirror  must have E3M/C02/C03  FE9 Additional DIN-slot  \$81 \$81  FR8 Overhead storage slot, front center  \$93 \$93  FR8 Rear view camera (head unit display)  must have C02/E3M; not with FR3/JB7/JB6/JB8  FY1 Security alarm w. interior motion sensor  \$584 \$584	F2 A	·	¢20	¢20
Must have E36; not with E2M; CHS production only  E36 Cutoff relay for additional battery  \$110 \$110  \$tandard with E2I/E2M  E3M MBUX Multimedia System with 7" touchscreen  \$474 \$474  not with C02/C03; must have JK5+(JB7/JB6/JB8/FR8)  E5M Extension of PSM standard contact  \$58 \$58  ED5 Parametric special module (PSM)  **not with ED8  EE3 115 V socket  \$125 \$125  E52 12 V power outlet, rear compartment  \$92 \$92  E55 Charging package, dashboard  \$82 \$82  E74 Active Distance Assist DISTRONIC  **must have C02/C03/E3M; not with ZH4  F49 Electrically heated windshield  **no restrictions**  F61 Interior rear view mirror  **must have E3M/C02/C03  FE9 Additional DIN-slot  \$81 \$81  \$81  \$F8 Overhead storage slot, front center  \$105 \$105  FJ1 Hinged lid for storage compartment  \$93 \$93  FR8 Rear view camera (head unit display)  **must have C02/E3M; not with FR3/JB7/JB6/JB8  FY1 Security alarm w. interior motion sensor  \$584 \$584			·	·
E36 Cutoff relay for additional battery  standard with E2I/E2M  E3M MBUX Multimedia System with 7" touchscreen  not with C02/C03; must have JK5+(JB7/JB6/JB8/FR8)  E5M Extension of PSM standard contact  \$58 \$58  ED5 Parametric special module (PSM)  not with ED8  EE3 115 V socket  \$125 \$125  ES2 12 V power outlet, rear compartment  \$92 \$92  ES5 Charging package, dashboard  \$82 \$82  ET4 Active Distance Assist DISTRONIC  \$263 \$263  must have C02/C03/E3M; not with ZH4  F49 Electrically heated windshield  no restrictions  F61 Interior rear view mirror  \$36 \$36  must have E3M/C02/C03  FE9 Additional DIN-slot  \$81 \$81  \$81  \$FR Overhead storage slot, front center  \$105 \$105  FJ1 Hinged lid for storage compartment  \$93 \$93  FR8 Rear view camera (head unit display)  must have C02/E3M; not with FR3/JB7/JB6/JB8  FY1 Security alarm w. interior motion sensor  \$584 \$584	EZI	·	\$248	\$248
standard with E2I/E2M  E3M MBUX Multimedia System with 7" touchscreen \$474 \$474  not with C02/C03; must have JK5+(JB7/JB6/JB8/FR8)  E5M Extension of PSM standard contact \$58 \$58  ED5 Parametric special module (PSM) \$317 \$317  not with ED8  EE3 115 V socket \$125 \$125  ES2 12 V power outlet, rear compartment \$92 \$92  ES5 Charging package, dashboard \$82 \$82  ET4 Active Distance Assist DISTRONIC \$263 \$263  must have C02/C03/E3M; not with ZH4  F49 Electrically heated windshield \$218 \$218  no restrictions  F61 Interior rear view mirror \$36 \$36  must have E3M/C02/C03  FE9 Additional DIN-slot \$81 \$81  FF8 Overhead storage slot, front center \$105 \$105  FJ1 Hinged lid for storage compartment \$93 \$93  FR8 Rear view camera (head unit display) \$336 \$336  must have C02/E3M; not with FR3/JB7/JB6/JB8  FY1 Security alarm w. interior motion sensor \$584 \$584	F2.C		¢110	ć110
### E3M MBUX Multimedia System with 7" touchscreen	E36	•	\$110	\$110
not with CO2/CO3; must have JK5+(JB7/JB6/JB8/FR8)           E5M Extension of PSM standard contact         \$58         \$58           ED5 Parametric special module (PSM)         \$317         \$317           not with ED8         \$125         \$125           EE3 115 V socket         \$125         \$125           ES2 12 V power outlet, rear compartment         \$92         \$92           ES5 Charging package, dashboard         \$82         \$82           ET4 Active Distance Assist DISTRONIC         \$263         \$263           must have CO2/CO3/E3M; not with ZH4         \$218         \$218           F49 Electrically heated windshield         \$218         \$218           no restrictions         \$36         \$36           F61 Interior rear view mirror         \$36         \$36           must have E3M/CO2/CO3         \$81         \$81           FF9 Additional DIN-slot         \$81         \$81           F71 Hinged lid for storage compartment         \$93         \$93           FR8 Rear view camera (head unit display)         \$336         \$336           must have CO2/E3M; not with FR3/JB7/JB6/JB8         \$584         \$584	F2N4	·	Ć474	6474
E5M Extension of PSM standard contact \$58 \$58 ED5 Parametric special module (PSM) \$317 \$317  not with ED8 EE3 115 V socket \$125 \$125 ES2 12 V power outlet, rear compartment \$92 \$92 ES5 Charging package, dashboard \$82 \$82 ET4 Active Distance Assist DISTRONIC \$263 \$263  must have C02/C03/E3M; not with ZH4 F49 Electrically heated windshield \$218 \$218  no restrictions F61 Interior rear view mirror \$36 \$36  must have E3M/C02/C03 FE9 Additional DIN-slot \$81 \$81 FF8 Overhead storage slot, front center \$105 \$105 FJ1 Hinged lid for storage compartment \$93 \$93 FR8 Rear view camera (head unit display) \$336 \$336  must have C02/E3M; not with FR3/IB7/IB6/IB8 FY1 Security alarm w. interior motion sensor \$584 \$584	E3IVI	·	\$474	\$474
ED5 Parametric special module (PSM) \$317 \$317  not with ED8  EE3 115 V socket \$125 \$125  ES2 12 V power outlet, rear compartment \$92 \$92  ES5 Charging package, dashboard \$82 \$82  ET4 Active Distance Assist DISTRONIC \$263 \$263  must have CO2/CO3/E3M; not with ZH4  F49 Electrically heated windshield \$218 \$218  no restrictions  F61 Interior rear view mirror \$36 \$36  must have E3M/CO2/CO3  FE9 Additional DIN-slot \$81 \$81  FF8 Overhead storage slot, front center \$105 \$105  FJ1 Hinged lid for storage compartment \$93 \$93  FR8 Rear view camera (head unit display) \$336 \$336  must have CO2/E3M; not with FR3/JB7/JB6/JB8  FY1 Security alarm w. interior motion sensor \$584 \$584			450	450
not with ED8  EE3 115 V socket \$125 \$125  ES2 12 V power outlet, rear compartment \$92 \$92  ES5 Charging package, dashboard \$82 \$82  ET4 Active Distance Assist DISTRONIC \$263 \$263  must have CO2/CO3/E3M; not with ZH4  F49 Electrically heated windshield \$218 \$218  no restrictions  F61 Interior rear view mirror \$36 \$36  must have E3M/CO2/CO3  FE9 Additional DIN-slot \$81 \$81  FF8 Overhead storage slot, front center \$105 \$105  FJ1 Hinged lid for storage compartment \$93 \$93  FR8 Rear view camera (head unit display) \$336 \$336  must have CO2/E3M; not with FR3/JB7/JB6/JB8  FY1 Security alarm w. interior motion sensor \$584 \$584				
EE3       115 V socket       \$125       \$125         ES2       12 V power outlet, rear compartment       \$92       \$92         ES5       Charging package, dashboard       \$82       \$82         ET4       Active Distance Assist DISTRONIC       \$263       \$263         must have CO2/CO3/E3M; not with ZH4         F49       Electrically heated windshield       \$218       \$218         no restrictions         F61       Interior rear view mirror       \$36       \$36         must have E3M/CO2/CO3       \$81       \$81         FE9       Additional DIN-slot       \$81       \$81         F78       Overhead storage slot, front center       \$105       \$105         FJ1       Hinged lid for storage compartment       \$93       \$93         FR8       Rear view camera (head unit display)       \$336       \$336         must have CO2/E3M; not with FR3/IB7/IB6/IB8         FY1       Security alarm w. interior motion sensor       \$584       \$584	ED5		\$317	\$317
ES2 12 V power outlet, rear compartment \$92 \$92 ES5 Charging package, dashboard \$82 \$82 ET4 Active Distance Assist DISTRONIC \$263 \$263  **must have C02/C03/E3M; not with ZH4  F49 Electrically heated windshield \$218 \$218  **no restrictions*  F61 Interior rear view mirror \$36 \$36  **must have E3M/C02/C03  FE9 Additional DIN-slot \$81 \$81  FF8 Overhead storage slot, front center \$105 \$105  FJ1 Hinged lid for storage compartment \$93 \$93  FR8 Rear view camera (head unit display) \$336 \$336  **must have C02/E3M; not with FR3/JB7/JB6/JB8  FY1 Security alarm w. interior motion sensor \$584 \$584			4.55	4
ES5 Charging package, dashboard \$82 \$82 ET4 Active Distance Assist DISTRONIC \$263 \$263  must have CO2/CO3/E3M; not with ZH4  F49 Electrically heated windshield \$218 \$218  no restrictions  F61 Interior rear view mirror \$36 \$36  must have E3M/CO2/CO3  FE9 Additional DIN-slot \$81 \$81  FF8 Overhead storage slot, front center \$105 \$105  FJ1 Hinged lid for storage compartment \$93 \$93  FR8 Rear view camera (head unit display) \$336 \$336  must have CO2/E3M; not with FR3/JB7/JB6/JB8  FY1 Security alarm w. interior motion sensor \$584 \$584				
ET4 Active Distance Assist DISTRONIC  must have CO2/CO3/E3M; not with ZH4  F49 Electrically heated windshield  no restrictions  F61 Interior rear view mirror  s36 \$36  must have E3M/CO2/CO3  FE9 Additional DIN-slot  FF8 Overhead storage slot, front center  FJ1 Hinged lid for storage compartment  FR8 Rear view camera (head unit display)  must have CO2/E3M; not with FR3/JB7/JB6/JB8  FY1 Security alarm w. interior motion sensor  \$263  \$263  \$263  \$263  \$263  \$263  \$263  \$263  \$263  \$263  \$218  \$218  \$218  \$218  \$218  \$218  \$218  \$218  \$218  \$218  \$218  \$218  \$218  \$218  \$36  \$36  \$36  \$36  \$36  \$376  \$			·	
must have CO2/CO3/E3M; not with ZH4  F49 Electrically heated windshield \$218 \$218  no restrictions  F61 Interior rear view mirror \$36 \$36  must have E3M/CO2/CO3  FE9 Additional DIN-slot \$81 \$81  FF8 Overhead storage slot, front center \$105 \$105  FJ1 Hinged lid for storage compartment \$93 \$93  FR8 Rear view camera (head unit display) \$336 \$336  must have CO2/E3M; not with FR3/JB7/JB6/JB8  FY1 Security alarm w. interior motion sensor \$584 \$584				-
F49 Electrically heated windshield \$218 \$218  no restrictions  F61 Interior rear view mirror \$36 \$36  must have E3M/C02/C03  FE9 Additional DIN-slot \$81 \$81  FF8 Overhead storage slot, front center \$105 \$105  FJ1 Hinged lid for storage compartment \$93 \$93  FR8 Rear view camera (head unit display) \$336 \$336  must have C02/E3M; not with FR3/JB7/JB6/JB8  FY1 Security alarm w. interior motion sensor \$584 \$584	ET4		\$263	\$263
no restrictions  F61 Interior rear view mirror \$36 \$36  must have E3M/C02/C03  FE9 Additional DIN-slot \$81 \$81  FF8 Overhead storage slot, front center \$105 \$105  FJ1 Hinged lid for storage compartment \$93 \$93  FR8 Rear view camera (head unit display) \$336 \$336  must have C02/E3M; not with FR3/JB7/JB6/JB8  FY1 Security alarm w. interior motion sensor \$584 \$584				1
F61         Interior rear view mirror         \$36         \$36           must have E3M/C02/C03         \$81         \$81           FE9         Additional DIN-slot         \$81         \$81           FF8         Overhead storage slot, front center         \$105         \$105           FJ1         Hinged lid for storage compartment         \$93         \$93           FR8         Rear view camera (head unit display)         \$336         \$336           must have C02/E3M; not with FR3/JB7/JB6/JB8         \$584         \$584           FY1         Security alarm w. interior motion sensor         \$584         \$584	F49		\$218	\$218
must have E3M/C02/C03  FE9 Additional DIN-slot \$81 \$81  FF8 Overhead storage slot, front center \$105 \$105  FJ1 Hinged lid for storage compartment \$93 \$93  FR8 Rear view camera (head unit display) \$336 \$336  must have C02/E3M; not with FR3/JB7/JB6/JB8  FY1 Security alarm w. interior motion sensor \$584 \$584				
FE9 Additional DIN-slot \$81 \$81  FF8 Overhead storage slot, front center \$105 \$105  FJ1 Hinged lid for storage compartment \$93 \$93  FR8 Rear view camera (head unit display) \$336 \$336  must have CO2/E3M; not with FR3/JB7/JB6/JB8  FY1 Security alarm w. interior motion sensor \$584 \$584	F61	Interior rear view mirror	\$36	\$36
FF8 Overhead storage slot, front center \$105 \$105  FJ1 Hinged lid for storage compartment \$93 \$93  FR8 Rear view camera (head unit display) \$336 \$336  must have CO2/E3M; not with FR3/JB7/JB6/JB8  FY1 Security alarm w. interior motion sensor \$584 \$584				
FJ1 Hinged lid for storage compartment \$93 \$93  FR8 Rear view camera (head unit display) \$336 \$336  must have CO2/E3M; not with FR3/JB7/JB6/JB8  FY1 Security alarm w. interior motion sensor \$584 \$584	FE9	Additional DIN-slot	\$81	\$81
FR8 Rear view camera (head unit display) \$336 \$336  must have CO2/E3M; not with FR3/JB7/JB6/JB8  FY1 Security alarm w. interior motion sensor \$584 \$584	FF8	Overhead storage slot, front center	\$105	\$105
must have CO2/E3M; not with FR3/JB7/JB6/JB8  FY1 Security alarm w. interior motion sensor \$584 \$584	FJ1	Hinged lid for storage compartment	\$93	\$93
must have CO2/E3M; not with FR3/JB7/JB6/JB8  FY1 Security alarm w. interior motion sensor \$584 \$584	FR8	Rear view camera (head unit display)	\$336	\$336
FY1 Security alarm w. interior motion sensor \$584 \$584				
	FY1		\$584	\$584

		144" G	170" G
		M2CV4G	M2CV7G
		907.643	907.645
FY7	Optional 3-button keys	\$36	\$36
FZ9	Keys, two additional masters	\$121	\$121
H01	Heat insulation, rear compartment	\$156	\$156
	must have V25/VA3/VA1/C07/X66		·
H04	Heat insulation, front compartment	\$187	\$187
	if + D50/D51 must have V07	7-0:	7-0:
H13	Rear cabin heater and vents	\$786	\$786
1113	must have V43 + (H12/HZ9); not with VK8	γ, σσ	Ψ,00
H15	Heated front passenger seat	\$284	\$284
1113	must have H16; not with X68	<b>720</b> 4	<b>720</b> 4
H16	Heated driver's seat	\$284	\$284
1110	must have H15; not with X68	7204	7204
H88	Rear heater prep	\$405	\$405
1100	must have H12/HZ9; not with H13/T19	Ş <del>+</del> 03	Ş <del>4</del> 03
H1I	Front-to-rear outlet in instrument panel	\$0	\$0
1111		ŞU	ŞU
11114	must have FJ1/C01 Thermetranic submetic climate central	6227	6227
HH4	Thermotronic automatic climate control	\$337	\$337
107	must have JF1; if +H13 must have H08/HK4	Ć450	Ć450
JA7	Blind Spot Assist	\$450	\$450
15.4	must have F64; not with C01	4200	4200
JB4	Active Lane Keeping Assist	\$288	\$288
	standard with CO2/CA2	4	4
JB6	Parking Package with 360 degree camera	\$775	\$775
	must have E3M/C02/C03; not with W75/W76/JB7	4	4
JB7	Parking Package	\$615	\$615
	must have E3M/C02/C03; not with W75/W76/JB6	4	4
JB8	360 Degree Camera	\$685	\$685
	SoP and Plausibility TBD		
JF1	Rain sensor	\$106	\$106
JK5	Instrument cluster with color display	\$144	\$144
	not with CO3		
JW0	Backup alarm	\$99	\$99
JW2	Deactivation lamp monitoring failure	\$27	\$27
	Attention Assist	\$49	\$49
L13	Fog lamp with cornering light function	\$199	\$199
LB9	Illuminated front exits	\$151	\$151
LC4	Comfort overhead control panel	\$93	\$93
M20	Speed limitation 65 mph	\$60	\$60
	not with MD3		
MD3	Top speed limitation 75 mph	\$60	\$60
	not with M20		
Q24	Trailer hitch, 5,000 lbs	\$147	\$147
	not with W73/W75/W76		
QA9	Half-sided step rear (for trailer hitch)	\$101	\$101
	must have Q24/QA2; not with W73/W75/W76		
R91	Spare tire deletion	-\$110	-\$110
	must have R92; not with R87		
R92	Spare tire carrier deletion	\$0	\$0
	must have R91; not with R65		·
R98	Rims painted jet black	\$81	\$81
	not with RL5/RM2		
RF1	Tire brand Continental	\$0	\$0
	must have RM1 + RM9		
RF8	Tire brand Michelin	\$0	\$0
	must have RM9; not with RM1		
RH0	Tire brand Kumho	\$0	\$0
	must have RM9; not with RM1		

		144" G	170" G
		M2CV4G	M2CV7G
		907.643	907.645
RL5	Light-alloy wheels 6.5 J x 16	\$906	\$906
	not with RS3/RM2/R98		
RM1	M+S winter tires	\$169	\$169
	must have RF1/RD9; not with RF8/RH0/X31		
RM2	Rims painted arctic white	\$81	\$81
	not with R98/RL5		_
RM9	Specially requested tires	\$101	\$101
	must have RF1/RF8/RH0; not with RD9		
S28	Armrest, driver and passenger door	\$51	\$51
T12	Sliding door two stage opening	\$82	\$82
TE 0	not with T55	<b>\$225</b>	4225
T50	Electric closing assist right sliding door	\$335	\$335
<b>T</b> CC	must have D03; not with T55/T93	ć024	¢024
T55	Electric sliding door right	\$831	\$831
TF 7	must have D03 + (FY7+T16); not with T12/T50	¢4 074	64.074
T57	Electric sliding step	\$1,071	\$1,071
TC0	must have D03 + ED5; not with T93	<b>ć</b> 420	¢420
T60	Opening limiter electrically operated sliding door	\$120	\$120
T75	must have T55	ćro	ĆEQ.
T75	Door-mounted assist handles, driver & passenger	\$59	\$59
T85	Assist handle, left rear door	\$32	\$32
T86	Assist handles, right rear door	\$32	\$32
V43	Wood floor with 6 D-rings	\$422	\$422
\ (O.F.	not with P93/V93/VL4/VK8/C07; standard with D93/H13/V24/V52/VC		<b>†</b> 20
V85	Cigarette lighter & ash cup, front	\$39	\$39
VC5	Door sill - protective edge	\$71	\$71
) /// O	must have V43/X66; not with T19/T93/VK8/VV2/V93/C07	¢270	¢270
VK8	Floor covering, plastic	\$370	\$370
) A ( E 4	not with V43/P93/T19/T93/V52/VC5/X66	<b>\$250</b>	<b>†250</b>
	Rear doors, opening to side wall	\$360	\$360
W5F	90 Degree fixation point- Rear Doors	\$80	\$80
	SoP and Plausibility TBD	4407	4407
W73	Bumper step, rear, grey	\$187	\$187
	not with Q24/W75/W76	4222	4222
W/5	Step, wide, at rear end	\$308	\$308
	not with JB6/JB7/Q24/QA9; must have R91+R92	4001	1001
W76	Bumper step, rear, spring-loaded	\$601	\$601
	must have R91+R92; not with JB6/JB7/X30/Q24	4000	400-
W78	Heated rear window(s) w/ washers/wipers	\$335	\$335
	Must have H22+VA7 / if D51 must have F61; not with W61		
X90	Deletion of Sprinter badge, left rear door	\$0	\$0
X93	Deletion of model badge, right rear door	\$0	\$0
XM4	Acoustic package	\$87	\$87
	standard with CO2/CO3		
Y10	First-aid kit	\$27	\$27
Y26	Wheel chocks	\$38	\$38
Y45	Emergency flashlight	\$27	\$27
Y68	Paint preservative	\$187	\$212
Y69	Surface protection for stock vehicles	\$315	\$315
YK3	Cargo straps, D-rings	\$81	\$81

#### 2500 CREW VAN - GAS

Packages

		144" G	170" G
		M2CV4G	M2CV7G
		907.643	907.645
C00	Comfort Package	\$300	\$300
LC4	Comfort overhead control panel	Х	Х
SE4	Lumbar support, co-driver's seat	X	X
SE5	Lumbar support, driver's seat	X	X
SK0	Comfort head restraint, driver	X	X
SK1	Comfort head restraint, co-driver	X	X
S28	Armrest, driver and passenger door	X	X
must	have COS OR X68; CA/CC only: not with S23		

COS	Comfort Package (Seat addition)	\$381	\$381		
SB1	Comfort driver's seat	Х	Х		
SB2	Comfort passenger seat	Х	Х		
must	must have C00				

X68	Comfort Plus Package	\$1,923	\$1,923		
H15	Heated front passenger seat	X	X		
H16	Heated driver's seat	Х	X		
SF1	Driver's seat electrically adjustable	Х	X		
SF2	Co-driver's seat electrically adjustable	Х	Х		
must	must have COO and VF4 OR VF6, CA/CC only: not with S23				

C01	Driver Convenience Package	\$760	\$760
E46	12 V power outlet, driver seat base	X	X
F64	Electrically folding exterior mirrors	X	X
FJ1	Hinged lid for storage compartment	X	X
FJ5	Hinged Lid for Storage Compartments left and right	X	X
FZ9	Keys, two additional masters	X	Х
JA7	Blind Spot Assist	X	X
JW8	Attention Assist	Х	X

C02	Premium Package	\$983	\$983
CL3	Leather steering wheel	X	X
E3M	MBUX Multimedia System with 7" touchscreen	Х	Х
FM3	Wet Wiper System	X	X
JB4	Active Lane Keeping Assist	X	X
JK5	Instrument cluster with color display	X	Χ

Ordering availability restricted, see NetStar for availability and restrictions | must have JF1 + XM4; must choose FR8/JB7/JB6

CA2	C02 in combination with C03	\$604	\$604		
CL3	Leather steering wheel	X	X		
FM3	Wet Wiper System	X	X		
JB4	Active Lane Keeping Assist	X	X		
JK5	Instrument cluster with color display	X	X		
Order	Ordering availability restricted, see NetStar for availability and restrctions must have CO3 + JF1				

#### 2500 CREW VAN - GAS

144" G	170" G
M2CV4G	M2CV7G
907.643	907.645

C03	Premium Plus Package	\$1,793	\$1,793		
E1B	Tray for smartphones incl. wireless charging	X	X		
	Navigation	X	X		
EY2	Intelligent navigation	X	X		
E4M	MBUX Multimedia System with 10.25" touchscreen	X	X		
EX9	Free map data updates for 3 years	X	X		
H1I	Front-to-rear outlet in instrument panel	X	X		
JA9	Traffic Sign Assist	X	Х		
XM4	Acoustic package	X	Х		
must	must have (CA2+(JB7/JB6/JB8)) OR (JB4+JK5+FM3+(JB7/JB6/JB8)); not with FR8 and CO2				

X67	Chrome Grille Package	\$290	\$290
CN2	Radiator grille frame in vehicle color	X	X
FK3	Chrome plated radiator grille (MB only)	X	X
no restrictions			

X13	Exterior Lighting Package	\$1,608	\$1,608
L13	Fog lamp with cornering light function	X	X
L22	Partial LED tail lights	X	X
LA1	High beam assist	Х	Х
LG7	LED high performance headlamps	Х	Х
no restrictions			

X72	Crew Van Comfort Package	\$220	\$220
S31	Convenice head restraints for pass. compartment	X	X
UY1	3-seater comfort bench rear, 1st row (narrow)	X	Х
can have VF4/VF6 only			

X4Z	Interior Trim Upgrade Package	\$610	\$610	
VA1	Side wall paneling waist height PVC	X	X	
VA3	Side wall paneling full hardboard	X	X	
ZK4	Crew Van, produced in Germany	Х	X	
must have (V43+VC5) OR VK8				

144" 4C

170" 4C

		M2CV44	M2CV74
		907.643	907.645
Engin	0		
	Engine/7-Speed Trans.	S	S
ED4	AGM battery 12V 92 AH 850 A	S	S
	Automatic transmission, 7G-tronic	S	S
	Alternator 14 V / 200 A	S	S
	2.0L 4-cylinder diesel engine	S	S
	SULEV emissions	S	S
	ng and Trim Packages		J
	Standard Rear Seats	S	S
	3-seater bench rear, 1st row (narrow)	S	S
	Wall-side armrest	S	S
	Aisle-side armrest	S	S
	ave VF7/VF6 only; with X68 must have VF6	!	
X2V	Standard Trim Crew Van Package	S	S
V25	Half height load compartment trim	S	S
V35	Wheel house covering	S	S
V43	Wood floor with 6 D-rings	S	S
CHS p	production only	•	•
Equip	·		
AR2	Axle ratio 3.923	S	S
BA3	Active Brake Assist	S	S
BH1	Hold Function	S	S
C6L	Multifunction steering wheel	S	S
CL1	Adjustable steering wheel (angle)	S	S
D03	High roof	0	S
D93	Omission bulkhead	S	S
E07	Hill Start Assist	S	S
E10	Standard radio	S	S
E1U	USB-C socket, 5 V	S	S
E30	Starter battery disconnect	S	S
E3J	Pre-installation for switch panel	S	S
E40	Trailer hitch prep. wiring	S	S
ED8	Preinstallation PSM	S	S
EE5	Ultracapacitor discharge module	S	S
EK1	Body Builder Connector	S	S
ES0	Jump start terminal	S	S
EW6	Pre-installation for Mercedes me Remote Services	S	S
EY5	Emergency Call System	S	S
EY6	Breakdown management	S	S
F43	Laminated glass rear	S	S
F68	Heated & electrically adjustable exterior mirrors	S	S
FF3	Cupholder rear compartment	S	S
FF5	Shelf above windshield	S	S
FG8	Cupholder front	S	S
FI1	Remote key (315 mhz) w/central locking	S	S
FJ4	Storage compartment underneath cockpit	S	S
FR3	Rear view camera (rear-view mirror display)	S	S
H00	Warm/cool air duct to rear compartment	S	S
H21	Windshield with filter band	S	S
H22	Rear window defroster	S	S
HH2	Heater, auxiliary electric hot air	S	S
НН9	Air Condition, Front	S	S
IH7	Head Unit, North America	S	S
J11	Speedometer, miles and km/h	S	S
J55	Seat belt warning for co-driver seat	S	S
J58	Seat belt reminder driver	S	S
J65	Outside temperature gauge	S	S

#### 2500 CREW VAN - 4cyl Diesel Standard Equipment

144" 4C	170" 4C
M2CV44	M2CV74
907.643	907.645

JA8   Crosswind Assist   S   S   S   S   S   S   S   S   S
JH3 Communication module (LTE) for dig. services  Service interval 20,000 miles  Service interval 20,000 miles 20,000 milese 20,000 mile
JH3 Communication module (LTE) for dig. services  Service interval 20.000 miles  Service interval 20.000 miles Service interval 20.000 miles Service interval 20.000 miles Service interval 20.000 miles Service interval 20.000 miles Service interval 20.000 miles Service interval 20.000 miles Service interval 20.000 miles Service interval 20.000 miles Service interval 20.000 miles Service interval 20.000 miles Service interval 20.000 miles Service interval 20.000 miles Service interval 20.000 milese Service 20.000 milese Service 20.000 milese Service 20.000 milese Service 20.000 milese
JIP    Service interval 20.000 miles
K60       Exhaust straight to rear       S       S         KB7       24.5 gallon fuel tank       S       S         KL1       Aux fuel sending unit w/ fuel tap       S       S         KL5       Fuel filter with water separator       S       S         KP6       3rd generation SCR emission control system       S       S         L94       Parking lights deletion       S       S         LA2       Headlight assistant       S       S         LB3       3rd brake light       S       S         M51       Cruise control       S       S         M61       End mundifilance       S       S
KB7       24.5 gallon fuel tank       S       S         KL1       Aux fuel sending unit w/ fuel tap       S       S         KL5       Fuel filter with water separator       S       S         KP6       3rd generation SCR emission control system       S       S         L94       Parking lights deletion       S       S         LA2       Headlight assistant       S       S         LB5       3rd brake light       S       S         M51       Cruise control       S       S         P47       Front mudflaps       S       S         P48       Rear mudflaps       S       S         P48       Rear mudflaps       S       S         Q11       Longitudinal member reinforcement       S       S         R65       Spare tire bracket below frame       S       S         R87       Junspecified tire brand       S       S         R88       Spare tire       S       S         R99       Unspecified tire brand       S       S         R18       Tires LT 245/75 R16       S       S         R90       Unspecified tire brand       S       S         R83       6.5 J x 16 ste
KB7       24.5 gallon fuel tank       S       S         KL1       Aux fuel sending unit w/ fuel tap       S       S         KL5       Fuel filter with water separator       S       S         KK6       3rd generation SCR emission control system       S       S         L94       Parking lights deletion       S       S         LA2       Headlight assistant       S       S         LB5       3rd brake light       S       S         M51       Cruise control       S       S         P47       Front mudflaps       S       S         P48       Rear mudflaps       S       S         Q11       Longitudinal member reinforcement       S       S         R65       Spare tire bracket below frame       S       S         R87       Junspecified tire brand       S       S         R88       Spare tire       S       S         R99       Unspecified tire brand       S       S         R18       Tires LT 245/75 R16       S       S         R870       All-season tires       S       S         R53       6.5 J x 16 steel wheels       S       S         R92       Tire pres
KL1       Aux fuel sending unit w/ fuel tap       S       S         KL5       Fuel filter with water separator       S       S         KP6       3rd generation SCR emission control system       S       S         L94       Parking lights deletion       S       S         LA2       Headlight assistant       S       S         LB5       3rd brake light       S       S         MS1       Cruise control       S       S         MS2       Cruise control       S       S         P47       Front mudflaps       S       S         P48       Rear mudflaps       S       S         Q11       Longitudinal member reinforcement       S       S         R65       Spare tire bracket below frame       S       S         R7       Spare tire       S       S         R87       Spare tire       S       S         R90       Unspecified tire brand       S       S         R18       Tires LT 245/75 R16       S       S         R83       6.5 J x 16 steel wheels       S       S         R91       All-season tires       S       S         R92       X 16 steel wheels <t< td=""></t<>
KL5       Fuel filter with water separator       S       S         KP6       3rd generation SCR emission control system       S       S         L94       Parking lights deletion       S       S         LA2       Headlight assistant       S       S         LB5       3rd brake light       S       S         MS1       Cruise control       S       S         MS1       Cruise control       S       S         P47       Front mudflaps       S       S         P48       Rear mudflaps       S       S         Q11       Longitudinal member reinforcement       S       S         R65       Spare tire bracket below frame       S       S         R87       Spare tire bracket below frame       S       S         R87       Spare tire       S       S         R89       Unspecified tire brand       S       S         R89       Unspecified tire brand       S       S         R80       All-season tires       S       S         R80       All-season tires       S       S         R83       6.5 J x 16 steel wheels       S       S         R92       Tire pessure monitoring
L94       Parking lights deletion       \$       \$         LA2       Headlight assistant       \$       \$         LB5       3rd brake light       \$       \$         MS1       Cruise control       \$       \$         MS2       Front amodal       \$       \$         P47       Front airbag driver       \$       \$         P48       Rear mudflaps       \$       \$         Q11       Longitudinal member reinforcement       \$       \$         R65       Spare tire bracket below frame       \$       \$         R65       Spare tire bracket below frame       \$       \$         R87       Spare tire bracket below frame       \$       \$         R87       Spare tire bracket below frame       \$       \$         R87       Spare tire bracket below frame       \$       \$         S       \$       \$       \$     <
LA2Headlight assistantSSLB53rd brake lightSSMS1Cruise controlSSP47Front mudflapsSSP48Rear mudflapsSSQ11Longitudinal member reinforcementSSR65Spare tire bracket below frameSSR87Spare tireSSR89Unspecified tire brandSSR99Unspecified tire brandSSRM0All-season tiresSSR836.5 J x 16 steel wheelsSSR72Tire pressure monitoring sensorsSSS02Standard driver seatSSS04Standard front passenger seatSSS22Armrest for driver's seatSSS25Armrest for front passenger seatSSS46Front airbag, driverSSS46Front airbag, passengerSSSH1Thorax-pelvis sidebag, driverSSSH2Thorax-pelvis sidebag, co-driverSSSH2Thorax-pelvis sidebag, co-driverSSSH2Seat occupancy sensor, driver's seatSSSH2Siding door, passenger sideSST74Assist handle, B-pillarSSU22Pre-inst. for seating configuration Crew VanSSV40Floor anchors for rear seat benchSS
LA2Headlight assistantSSLB53rd brake lightSSMS1Cruise controlSSP47Front mudflapsSSP48Rear mudflapsSSQ11Longitudinal member reinforcementSSR65Spare tire bracket below frameSSR87Spare tireSSR89Unspecified tire brandSSR99Unspecified tire brandSSRM0All-season tiresSSR72Tire pressure monitoring sensorsSSS02Standard driver seatSSS04Standard front passenger seatSSS22Armrest for driver's seatSSS22Armrest for driver's seatSSS25Armrest for front passenger seatSSSA6Front airbag, driverSSSA7Front airbag, passengerSSSH1Thorax-pelvis sidebag, driverSSSH2Thorax-pelvis sidebag, co-driverSSSH2Thorax-pelvis sidebag, co-driverSSSH3Thorax-pelvis sidebag, co-driver's seatSSSH2Thorax-pelvis sidebag, driver's seatSSSH2Thorax-pelvis sidebag, co-driver's seatSSSH3Airbag, driver/passenger windowSSSK2Seat occupancy sensor, driver's seatSS
MS1Cruise controlSSP47Front mudflapsSSP48Rear mudflapsSSQ11Longitudinal member reinforcementSSR65Spare tire bracket below frameSSR87Spare tireSSR89Unspecified tire brandSSRH8Tires LT 245/75 R16SSRM0All-season tiresSSR836.5 J x 16 steel wheelsSSR72Tire pressure monitoring sensorsSSS02Standard driver seatSSS04Standard front passenger seatSSS22Armrest for driver's seatSSS25Armrest for front passenger seatSSS46Front airbag, driverSSSA6Front airbag, passengerSSSH1Thorax-pelvis sidebag, driverSSSH2Thorax-pelvis sidebag, co-driverSSSH3Airbag, driver/passenger windowSSSK2Seat occupancy sensor, driver's seatSST16Sliding door, passenger sideSST74Assist handle, B-pillarSSU22Pre-inst. for seating configuration Crew VanSSV40Floor anchors for rear seat benchSS
P47Front mudflapsSSP48Rear mudflapsSSQ11Longitudinal member reinforcementSSR65Spare tire bracket below frameSSR87Spare tireSSR89Unspecified tire brandSSRH8Tires LT 245/75 R16SSRM0All-season tiresSSR836.5 J x 16 steel wheelsSSR72Tire pressure monitoring sensorsSSS02Standard driver seatSSS04Standard front passenger seatSSS22Armrest for driver's seatSSS25Armrest for front passenger seatSSS26Front airbag, driverSSSA6Front airbag, passengerSSSH1Thorax-pelvis sidebag, driverSSSH2Thorax-pelvis sidebag, driverSSSH2Thorax-pelvis sidebag, co-driverSSSH2Seat occupancy sensor, driver's seatSSSK2Seat occupancy sensor, driver's seatSST16Sliding door, passenger sideSST74Assist handle, B-pillarSSU22Pre-inst. for seating configuration Crew VanSSV40Floor anchors for rear seat benchSS
P48Rear mudflapsSSQ11Longitudinal member reinforcementSSR65Spare tire bracket below frameSSR87Spare tireSSR89Unspecified tire brandSSRH8Tires LT 245/75 R16SSRM0All-season tiresSSR836.5 J x 16 steel wheelsSSR72Tire pressure monitoring sensorsSSS02Standard driver seatSSS04Standard front passenger seatSSS22Armrest for driver's seatSSS25Armrest for front passenger seatSSS25Armrest for front passenger seatSSS45Front airbag, driverSSSA6Front airbag, passengerSSSH1Thorax-pelvis sidebag, driverSSSH2Thorax-pelvis sidebag, co-driverSSSH2Airbag, driver/passenger windowSSSK2Seat occupancy sensor, driver's seatSST16Sliding door, passenger sideSST74Assist handle, B-pillarSSU22Pre-inst. for seating configuration Crew VanSSV40Floor anchors for rear seat benchSS
Q11Longitudinal member reinforcementSSR65Spare tire bracket below frameSSR87Spare tireSSRD9Unspecified tire brandSSRH8Tires LT 245/75 R16SSRM0All-season tiresSSRS36.5 J x 16 steel wheelsSSRY2Tire pressure monitoring sensorsSSS02Standard driver seatSSS04Standard front passenger seatSSS22Armrest for driver's seatSSS25Armrest for front passenger seatSSSA5Front airbag, driverSSSA6Front airbag, passengerSSSH1Thorax-pelvis sidebag, driverSSSH2Thorax-pelvis sidebag, co-driverSSSH3Airbag, driver/passenger windowSSSK2Seat occupancy sensor, driver's seatSST16Sliding door, passenger sideSST74Assist handle, B-pillarSSV36Roof trimSSV40Floor anchors for rear seat benchSS
R65Spare tire bracket below frameSSR87Spare tireSSRD9Unspecified tire brandSSRH8Tires LT 245/75 R16SSRM0All-season tiresSSRS36.5 J x 16 steel wheelsSSRY2Tire pressure monitoring sensorsSSS02Standard driver seatSSS04Standard front passenger seatSSS22Armrest for driver's seatSSS25Armrest for front passenger seatSSSA5Front airbag, driverSSSA6Front airbag, passengerSSSH1Thorax-pelvis sidebag, driverSSSH2Thorax-pelvis sidebag, co-driverSSSH2Thorax-pelvis sidebag, co-driverSSSH3Airbag, driver/passenger windowSSSK2Seat occupancy sensor, driver's seatSST16Sliding door, passenger sideSST74Assist handle, B-pillarSSU22Pre-inst. for seating configuration Crew VanSSV40Floor anchors for rear seat benchSS
R87 Spare tire S S S S S RD9 Unspecified tire brand S S S S S S S S S S S S S S S S S S S
RD9 Unspecified tire brand S S S S RH8 Tires LT 245/75 R16 S S S S S RM0 All-season tires S S S S S S S S S S S S S S S S S S S
RH8Tires LT 245/75 R16SSRM0All-season tiresSSRS36.5 J x 16 steel wheelsSSRY2Tire pressure monitoring sensorsSSS02Standard driver seatSSS04Standard front passenger seatSSS22Armrest for driver's seatSSS25Armrest for front passenger seatSSSA5Front airbag, driverSSSA6Front airbag, passengerSSSH1Thorax-pelvis sidebag, driverSSSH2Thorax-pelvis sidebag, co-driverSSSH2Airbag, driver/passenger windowSSSK2Seat occupancy sensor, driver's seatSST16Sliding door, passenger sideSST74Assist handle, B-pillarSSU22Pre-inst. for seating configuration Crew VanSSV36Roof trimSSV40Floor anchors for rear seat benchSS
RMOAll-season tiresSSRS36.5 J x 16 steel wheelsSSRY2Tire pressure monitoring sensorsSSS02Standard driver seatSSS04Standard front passenger seatSSS22Armrest for driver's seatSSS25Armrest for front passenger seatSSSA5Front airbag, driverSSSA6Front airbag, passengerSSSH1Thorax-pelvis sidebag, driverSSSH2Thorax-pelvis sidebag, co-driverSSSH9Airbag, driver/passenger windowSSSK2Seat occupancy sensor, driver's seatSST16Sliding door, passenger sideSST74Assist handle, B-pillarSSU22Pre-inst. for seating configuration Crew VanSSV36Roof trimSSV40Floor anchors for rear seat benchSS
RS3 6.5 J x 16 steel wheels  RY2 Tire pressure monitoring sensors  S S S  SO2 Standard driver seat  S S S  SO3 Standard front passenger seat  S S S S  SO4 Standard front passenger seat  S S S S  SO5 SA5 Front airbag, driver  S S S S S  SA6 Front airbag, passenger  S S S S S  SH1 Thorax-pelvis sidebag, driver  S S S S S  SH2 Thorax-pelvis sidebag, co-driver  S S S S  SH2 Seat occupancy sensor, driver's seat  S S S S  T16 Sliding door, passenger side  S S S S  T74 Assist handle, B-pillar  S S S  V40 Floor anchors for rear seat bench  S S S S
RY2Tire pressure monitoring sensorsSSS02Standard driver seatSSS04Standard front passenger seatSSS22Armrest for driver's seatSSS25Armrest for front passenger seatSSSA5Front airbag, driverSSSA6Front airbag, passengerSSSH1Thorax-pelvis sidebag, driverSSSH2Thorax-pelvis sidebag, co-driverSSSH9Airbag, driver/passenger windowSSSK2Seat occupancy sensor, driver's seatSST16Sliding door, passenger sideSST74Assist handle, B-pillarSSU22Pre-inst. for seating configuration Crew VanSSV36Roof trimSSV40Floor anchors for rear seat benchSS
SO2Standard driver seatSS04Standard front passenger seatSS22Armrest for driver's seatSS25Armrest for front passenger seatSSA5Front airbag, driverSSA6Front airbag, passengerSSH1Thorax-pelvis sidebag, driverSSH2Thorax-pelvis sidebag, co-driverSSH9Airbag, driver/passenger windowSSK2Seat occupancy sensor, driver's seatST16Sliding door, passenger sideST74Assist handle, B-pillarSU22Pre-inst. for seating configuration Crew VanSV36Roof trimSV40Floor anchors for rear seat benchS
SO4Standard front passenger seatSSS22Armrest for driver's seatSSS25Armrest for front passenger seatSSSA5Front airbag, driverSSSA6Front airbag, passengerSSSH1Thorax-pelvis sidebag, driverSSSH2Thorax-pelvis sidebag, co-driverSSSH9Airbag, driver/passenger windowSSSK2Seat occupancy sensor, driver's seatSST16Sliding door, passenger sideSST74Assist handle, B-pillarSSU22Pre-inst. for seating configuration Crew VanSSV36Roof trimSSV40Floor anchors for rear seat benchSS
S22Armrest for driver's seatSS25Armrest for front passenger seatSSA5Front airbag, driverSSA6Front airbag, passengerSSH1Thorax-pelvis sidebag, driverSSH2Thorax-pelvis sidebag, co-driverSSH9Airbag, driver/passenger windowSSK2Seat occupancy sensor, driver's seatST16Sliding door, passenger sideST74Assist handle, B-pillarSU22Pre-inst. for seating configuration Crew VanSV36Roof trimSV40Floor anchors for rear seat benchS
S25Armrest for front passenger seatSSSA5Front airbag, driverSSSA6Front airbag, passengerSSSH1Thorax-pelvis sidebag, driverSSSH2Thorax-pelvis sidebag, co-driverSSSH9Airbag, driver/passenger windowSSSK2Seat occupancy sensor, driver's seatSST16Sliding door, passenger sideSST74Assist handle, B-pillarSSU22Pre-inst. for seating configuration Crew VanSSV36Roof trimSSV40Floor anchors for rear seat benchSS
SA5 Front airbag, driver  SA6 Front airbag, passenger  SH1 Thorax-pelvis sidebag, driver  SH2 Thorax-pelvis sidebag, co-driver  SH3 Airbag, driver/passenger window  SH4 Seat occupancy sensor, driver's seat  SH5 SH5 Siding door, passenger side  SH6 Sliding door, passenger side  SH7 Assist handle, B-pillar  SH8
SA6 Front airbag, passenger  SH1 Thorax-pelvis sidebag, driver  SH2 Thorax-pelvis sidebag, co-driver  SH3 Airbag, driver/passenger window  SH4 Seat occupancy sensor, driver's seat  SH5 SK2 Seat occupancy sensor, driver's seat  SH6 Sliding door, passenger side  SH7 Assist handle, B-pillar  SH7 SH7
SH1Thorax-pelvis sidebag, driverSSSH2Thorax-pelvis sidebag, co-driverSSSH9Airbag, driver/passenger windowSSSK2Seat occupancy sensor, driver's seatSST16Sliding door, passenger sideSST74Assist handle, B-pillarSSU22Pre-inst. for seating configuration Crew VanSSV36Roof trimSSV40Floor anchors for rear seat benchSS
SH2Thorax-pelvis sidebag, co-driverSSSH9Airbag, driver/passenger windowSSSK2Seat occupancy sensor, driver's seatSST16Sliding door, passenger sideSST74Assist handle, B-pillarSSU22Pre-inst. for seating configuration Crew VanSSV36Roof trimSSV40Floor anchors for rear seat benchSS
SH9Airbag, driver/passenger windowSSSK2Seat occupancy sensor, driver's seatSST16Sliding door, passenger sideSST74Assist handle, B-pillarSSU22Pre-inst. for seating configuration Crew VanSSV36Roof trimSSV40Floor anchors for rear seat benchSS
SK2Seat occupancy sensor, driver's seatSST16Sliding door, passenger sideSST74Assist handle, B-pillarSSU22Pre-inst. for seating configuration Crew VanSSV36Roof trimSSV40Floor anchors for rear seat benchSS
T16Sliding door, passenger sideSST74Assist handle, B-pillarSSU22Pre-inst. for seating configuration Crew VanSSV36Roof trimSSV40Floor anchors for rear seat benchSS
T74Assist handle, B-pillarSSU22Pre-inst. for seating configuration Crew VanSSV36Roof trimSSV40Floor anchors for rear seat benchSS
U22       Pre-inst. for seating configuration Crew Van       S       S         V36       Roof trim       S       S         V40       Floor anchors for rear seat bench       S       S
V36 Roof trim S S S V40 Floor anchors for rear seat bench S S
V40 Floor anchors for rear seat bench S S
VA7 Storage compart. w/ net in rear doors S S
W16 2nd row, fixed window, driver side
W17 2nd row, fixed window, passenger side
W61 Windows in rear doors S S
W70 Black tinting (90%) for rear windows S S
XL2   GVWR 9,050 lbs. / 4.100 Kg
Y43 Jack, hydraulic S S

		144" 4C	170" 4C
		M2CV44	M2CV74
		_	
		907.643	907.645
A50	Front axle reinforced	\$346	\$346
AP2	Addtl. bar for driveshaft & exhaust extension	\$69	\$69
AR3	Axle ratio 4.182	\$0	\$0
B01	ESP for increased Center of Gravity above 39.4"	\$0	\$0
	must have CB4/CB8/X30; not with RH0/CB7	•	
B25	Electric parking brake	\$279	\$279
	no restrictions		
C72	Bumpers front/rear primed	\$268	\$268
	must have CN2/X67, not with CM0		
CB1	Suspension for comfort and load protection	\$241	\$241
CB7	Stabilization Level I	\$307	\$307
	not with CB1/CB7/CB8/ZG3		
CB8	Stabilization Level II	\$723	\$723
	not with CB4/CB8/ZG3		
CL3	Leather steering wheel	\$187	\$187
CM0	Painted metallic front & rear bumper	\$587	\$587
	must have (CN2/X67) + (JA7/C01) + (JB6/JB7) + (7755/9197/9775)		
CM9	Primed side moldings	\$364	\$364
CT1	Rear spring vibration absorbers	\$138	\$138
D03	High roof	\$2,900	S
	D03 must be added for Duesseldorf production		
D13	Mounting rails for roof rack	\$300	\$300
E1B	Tray for smartphones incl. wireless charging	\$156	\$156
	must have CO2/E3M + H1I		
E1E	Navigation	\$728	\$728
	must have CO2/E3M, not with CO3		
E1S	Sirius XM, satellite radio	\$255	\$255
	must have CO2/E3M/CO3		
E1R	Additional Fuses (40/80/150/100 Ampere)	\$50	\$50
	SoP and Plausibility TBD	1 4	4
E1Y	Additional Fuses (40/80/80/100 Ampere)	\$50	\$50
	SoP and Plausibility TBD	400	400
E2A	Access point for BB special signals in cockpit	\$29	\$29
E2I	Additional battery, co-driver seat base	\$248	\$248
526	Must have E36; not with E2M; CHS production only	6440	6440
E36	Cutoff relay for additional battery	\$110	\$110
E21.4	standard with E2I/E2M	¢474	6474
E3M	MBUX Multimedia System with 7" touchscreen  not with CO2/CO3; must have JK5+(JB7/JB6/JB8/FR8)	\$474	\$474
E5M	Extension of PSM standard contact	\$58	\$58
ED5		\$317	\$317
בט	Parametric special module (PSM)  not with ED8	321/	331/
EE3	115 V socket	\$125	\$125
ES2		\$125	\$125
ES5	12 V power outlet, rear compartment Charging package, dashboard	\$92	\$92
ET4	Active Distance Assist DISTRONIC	\$263	\$263
<u>-</u>  -	must have CO2/CO3/E3M; not with ZH4	7203	7203
F49	Electrically heated windshield	\$218	\$218
	no restrictions	Ų.10	Ψ <u>-1</u> 0
F61	Interior rear view mirror	\$36	\$36
- 51	must have E3M/C02/C03	750	750
F64	Electrically folding exterior mirrors	\$49	\$49
FE9	Additional DIN-slot	\$81	\$81
FF8	Overhead storage slot, front center	\$105	\$105
FJ1	Hinged lid for storage compartment	\$93	\$93
FR8	Rear view camera (head unit display)	\$336	\$336
·	must have CO2/E3M; not with FR3/JB7/JB6/JB8	<b>4333</b>	<b>4000</b>

		4.4-11	4800 50
		144" 4C	170" 4C
		M2CV44	M2CV74
		907.643	907.645
FY1	Security alarm w. interior motion sensor	\$584	\$584
	must have LC4/C00	700	700
FY7	Optional 3-button keys	\$36	\$36
FZ9	Keys, two additional masters	\$121	\$121
H01	Heat insulation, rear compartment	\$156	\$156
1101	must have V25/VA3/VA1/C07/X66	\$150	<b>Ş150</b>
H04	Heat insulation, front compartment	\$187	\$187
1104	if + D50/D51 must have V07	7107	7107
H12	Fuel-fired pre-heater/booster (17K BTU)	\$1,116	\$1,116
1112	not with HZ9	71,110	\$1,110
H13	Rear cabin heater and vents	\$786	\$786
птэ	must have V43 + (H12/HZ9); not with VK8	\$780	<i>\$76</i> 0
H15	Heated front passenger seat	\$284	\$284
птэ	must have H16; not with X68	\$ <b>2</b> 04	<b>\$204</b>
1116	Heated driver's seat	¢204	¢204
H16		\$284	\$284
1100	must have H15; not with X68	Ć40F	Ć40F
H88	Rear heater prep	\$405	\$405
	must have H12/HZ9; not with H13/T19	40	40
H1I	Front-to-rear outlet in instrument panel	\$0	\$0
	must have FJ1/C01	400-	400-
HH4	Thermotronic automatic climate control	\$337	\$337
	must have JF1; if +H13 must have H08/HK4		,
HZ9	Fuel-fired heater booster (18,000 BTU)	\$676	\$676
	not with H12		
J51	Fuel gauge, optimized for aux. fuel tap	\$72	\$72
	not with HZ9/H12		
J52	Engine oil level display at cold start	\$0	\$0
JA7	Blind Spot Assist	\$450	\$450
	must have F64; not with C01		
JB4	Active Lane Keeping Assist	\$288	\$288
	standard with CO2/CA2		
JB6	Parking Package with 360 degree camera	\$775	\$775
	must have E3M/C02/C03; not with W75/W76/JB7		
JB7	Parking Package	\$615	\$615
	must have E3M/C02/C03; not with W75/W76/JB6		
JB8	360 Degree Camera	\$685	\$685
	SoP and Plausibility TBD		
JF1	Rain sensor	\$106	\$106
	standard with CO2/X11		
JK5	Instrument cluster with color display	\$144	\$144
	not with CO3		
JW0	Backup alarm	\$99	\$99
JW2	Deactivation lamp monitoring failure	\$27	\$27
JW8	Attention Assist	\$49	\$49
K51	Misfueling prevention for Diesel	\$49	\$49
K52	DEF fluid filler cap - lockable	\$27	\$27
L13	Fog lamp with cornering light function	\$199	\$199
LB9	Illuminated front exits	\$151	\$151
LC4	Comfort overhead control panel	\$93	\$93
M20	Speed limitation 65 mph	\$60	\$60
	not with MD3	•	
MD3	Top speed limitation 75 mph	\$60	\$60
	not with M20	•	
N62	Front engine bracket for additional alternator	\$467	\$467
	not with HK4/N63	·	
N63	Front engine bracket for auxiliary A/C compressor	\$467	\$467
	not with HK4/N62	·	
	· · · · · · · · · · · · · · · · · · ·		

		144" 4C	170" 4C
		M2CV44	M2CV74
		907.643	907.645
Q24	Trailer hitch, 5,000 lbs	\$147	\$147
	not with W73/W75/W76	,	
QA9	Half-sided step rear (for trailer hitch)	\$101	\$101
	must have Q24/QA2; not with W73/W75/W76		
R91	Spare tire deletion	-\$110	-\$110
	must have R92; not with R87		
R92	Spare tire carrier deletion	\$0	\$0
	must have R91; not with R65		
R98	Rims painted jet black	\$81	\$81
	not with RL5/RM2		
RF1	Tire brand Continental	\$0	\$0
	must have RM1 + RM9		
RF8	Tire brand Michelin	\$0	\$0
	must have RM9; not with RM1	1 4-	4 -
RH0	Tire brand Kumho	\$0	\$0
51.5	must have RM9; not with RM1	4005	4006
RL5	Light-alloy wheels 6.5 J x 16	\$906	\$906
DN 44	not with RS3/RM2/R98	¢4.60	¢4.60
RM1	M+S winter tires	\$169	\$169
D142	must have RF1/RD9; not with RF8/RH0/X31	Ć01	Ć04
RIVIZ	Rims painted arctic white  not with R98/RL5	\$81	\$81
RM9	Specially requested tires	\$101	\$101
KIVIS	must have RF1/RF8/RH0; not with RD9	\$101	\$101
S28	Armrest, driver and passenger door	\$51	\$51
T12	Sliding door two stage opening	\$82	\$82
112	not with T55	702	<del>702</del>
T50	Electric closing assist right sliding door	\$335	\$335
130	must have D03; not with T55/T93	<b>γ</b> 555	<b>4333</b>
T55	Electric sliding door right	\$831	\$831
	must have D03 + (FY7+T16); not with T12/T50	φ001	<b>400</b>
T57	Electric sliding step	\$1,071	\$1,071
	must have D03 + ED5; not with T93	1 /-	, ,-
T60	Opening limiter electrically operated sliding door	\$120	\$120
	must have T55	·	,
T75	Door-mounted assist handles, driver & passenger	\$59	\$59
T85	Assist handle, left rear door	\$32	\$32
T86	Assist handles, right rear door	\$32	\$32
V43	Wood floor with 6 D-rings	\$422	\$422
	not with P93/V93/VL4/VK8/C07; standard with D93/H13/V24/V52/V0		·
V85	Cigarette lighter & ash cup, front	\$39	\$39
VC5	Door sill - protective edge	\$71	\$71
. 55	must have V43/X66; not with T19/T93/VK8/VV2/V93/C07	¥/-	Ψ.=
VK8	Floor covering, plastic	\$370	\$370
TIC	not with V43/P93/T19/T93/V52/VC5/X66	ψ373	<b>7370</b>
\ <i>\</i> /54	Rear doors, opening to side wall	\$360	\$360
	90 Degree fixation point- Rear Doors	\$80	\$80
	SoP and Plausibility TBD	700	<b>750</b>
W73	Bumper step, rear, grey	\$187	\$187
**/3	not with Q24/W75/W76	7107	9107
\ <b>\</b> /75	Step, wide, at rear end	\$308	\$308
**/3	not with JB6/JB7/Q24/QA9; must have R91+R92	7300	7300
\ <i>\\7</i>		\$601	\$601
VV / O	Bumper step, rear, spring-loaded	żουτ	ŻΟUI
14/70	must have R91+R92; not with JB6/JB7/X30/Q24	Ć	ĆOOF
W78	Heated rear window(s) w/ washers/wipers	\$335	\$335
V00	Must have H22+VA7 / if D51 must have F61; not with W61	40	¢0
X90	Deletion of Sprinter badge, left rear door	\$0	\$0

#### 2500 CREW VAN - 4cyl Diesel Options

		144" 4C	170" 4C
		M2CV44	M2CV74
		907.643	907.645
X93	Deletion of model badge, right rear door	\$0	\$0
XM4	Acoustic package	\$87	\$87
	standard with CO2/CO3		
Y10	First-aid kit	\$27	\$27
Y26	Wheel chocks	\$38	\$38
Y45	Emergency flashlight	\$27	\$27
Y68	Paint preservative	\$187	\$212
Y69	Surface protection for stock vehicles	\$315	\$315
YK3	Cargo straps, D-rings	\$81	\$81

SK1 Comfort head restraint, co-driver

choose FR8/JB7/JB6

S28 Armrest, driver and passenger door

must have COS OR X68; CA/CC only: not with S23

2500 CREW VAN - 4cyl Diesel Packages

144" 4C

Χ

170" 4C

Χ

		M2CV44	M2CV74
		907.643	907.645
C00	Comfort Package	\$300	\$300
LC4	Comfort overhead control panel	Х	Х
SE4	Lumbar support, co-driver's seat	Х	Х
SE5	Lumbar support, driver's seat	Х	Х
SK0	Comfort head restraint, driver	Х	Х

COS	Comfort Package (Seat addition)	\$381	\$381	
SB1	Comfort driver's seat	X	X	
SB2	Comfort passenger seat	Х	Х	
must have COO				

X68	Comfort Plus Package	\$1,923	\$1,923	
H15	Heated front passenger seat	Х	Х	
H16	Heated driver's seat	Х	Х	
SF1	Driver's seat electrically adjustable	Х	Х	
SF2	Co-driver's seat electrically adjustable	Х	Х	
must	must have COO and VF4 OR VF6, CA/CC only: not with S23			

C01	Driver Convenience Package	\$760	\$760
E46	12 V power outlet, driver seat base	X	Х
F64	Electrically folding exterior mirrors	Х	Х
FJ1	Hinged lid for storage compartment	Х	X
FJ5	Hinged Lid for Storage Compartments left and right	Х	X
FZ9	Keys, two additional masters	Х	X
JA7	Blind Spot Assist	Х	X
JW8	Attention Assist	Х	Х

C02	Premium Package	\$983	\$983	
CL3	Leather steering wheel	Х	Х	
E3M	MBUX Multimedia System with 7" touchscreen	Х	Х	
FM3	Wet Wiper System	Х	Х	
JB4	Active Lane Keeping Assist	Х	Х	
JK5	Instrument cluster with color display	Х	Х	
Ordering availability restricted, see NetStar for availability and restrictions must have IF1 + XM4: must				

CA2	C02 in combination with C03	\$604	\$604
CL3	Leather steering wheel	X	Х
FM3	Wet Wiper System	Х	Х
JB4	Active Lane Keeping Assist	Х	Х
JK5	Instrument cluster with color display	X	X

Ordering availability restricted, see NetStar for availability and restrctions|must have CO3 + JF1

#### 2500 CREW VAN - 4cyl Diesel

144" 4C	170" 4C
M2CV44	M2CV74
907.643	907.645

C03	Premium Plus Package	\$1,793	\$1,793		
E1B	Tray for smartphones incl. wireless charging	Х	Х		
	Navigation	Х	Х		
EY2	Intelligent navigation	Х	Х		
E4M	MBUX Multimedia System with 10.25" touchscreen	Х	Х		
EX9	Free map data updates for 3 years	Х	Х		
H1I	Front-to-rear outlet in instrument panel	Х	Х		
JA9	Traffic Sign Assist	Х	Х		
XM4	Acoustic package	Х	Х		
must	must have (CA2+(JB7/JB6/JB8)) OR (JB4+JK5+FM3+(JB7/JB6/JB8)); not with FR8 and CO2				

X67	Chrome Grille Package	\$290	\$290	
CN2	Radiator grille frame in vehicle color	X	Х	
FK3	Chrome plated radiator grille (MB only)	X	Х	
no restrictions				

X13	Exterior Lighting Package	\$1,608	\$1,608	
L13	Fog lamp with cornering light function	Х	Х	
L22	Partial LED tail lights	Х	Х	
LA1	High beam assist	Х	Х	
LG7	LED high performance headlamps	Х	Х	
no restrictions				

X72	Crew Van Comfort Package	\$220	\$220	
S31	Convenice head restraints for pass. compartment	X	Х	
UY1	3-seater comfort bench rear, 1st row (narrow)	Х	Х	
can have VF4/VF6 only				

X4Z	Interior Trim Upgrade Package	\$610	\$610	
VA1	Side wall paneling waist height PVC	X	X	
VA3	Side wall paneling full hardboard	Х	Х	
ZK4	Crew Van, produced in Germany	Х	X	
must have (V43+VC5) OR VK8				

2500 CREW VAN - 6cyl Diesel Standard Equipment

144" 6C

144" 6C 4x4

170'' 6C

170" 6C 4x4

		M2CV46	M2CV4X	M2CV76	M2CV7X
		907.643	907.643	907.645	907.645
Engin	е				
6-Cyl	Engine/7-Speed Trans.	S	s	S	S
	AGM battery 12V 92 AH 850 A	S	S	S	S
G42	Automatic transmission, 7G-tronic	S	S	S	S
-	ULEV emission	S	S	S	S
	3.0L V6 turbo diesel engine	S	S	S	S
	Alternator 14 V/220 A	S	S	S	S
X30		-	\$8,200	-	\$8,200
	Door-mounted assist handles, driver & passenger	_	\$ <b>5,200</b>	_	S S
	4x4 - High range transfer case w/ low gear	-	S	_	S
	ng and Trim Packages	_	3	_	3
	Standard Rear Seats	S	S	S	S
	3-seater bench rear, 1st row (narrow)	S	S	S	S
	Wall-side armrest	S	S	S	S
	Aisle-side armrest	S	S S	S	S
		3	3	3	3
	ave VF7/VF6 only; with X68 must have VF6		1 6		
	Standard Trim Crew Van Package	S	S	S	S
	Half height load compartment trim	S	S	S	S
	Wheel house covering	S	S	S	S
	Wood floor with 6 D-rings	S	S	S	S
	production only				
Equip					
AR2	Axle ratio 3.923	S	S	S	S
BA3	Active Brake Assist	S	S	S	S
BH1	Hold Function	S	S	S	S
C6L	Multifunction steering wheel	S	S	S	S
CL1	Adjustable steering wheel (angle)	S	S	S	S
D03	High roof	0	0	S	S
D93	Omission bulkhead	S	S	S	S
E07	Hill Start Assist	S	S	S	S
E10	Standard radio	S	S	S	S
E1U	USB-C socket, 5 V	S	S	S	S
E30	Starter battery disconnect	S	S	S	S
E3J	Pre-installation for switch panel	S	-	S	-
E40	Trailer hitch prep. wiring	S	S	S	S
	Preinstallation PSM	S	S	S	S
EE5	Ultracapacitor discharge module	S	S	S	S
EK1	Body Builder Connector	S	S	S	S
ES0	Jump start terminal	S	S	S	S
	Pre-installation for Mercedes me Remote Services	S	S	S	S
	Emergency Call System	S	S	S	S
EY6	Breakdown management	S	S	S	S
F43	Laminated glass rear	S	S	S	S
F68	Heated & electrically adjustable exterior mirrors	S	S	S	S
FF3		S	1		
-	Cupholder rear compartment Shelf above windshield		S	S	S
FF5		S	S	S	S
FG8	Cupholder front	S	S	S	S
FI1	Remote key (315 mhz) w/central locking	S	S	S	S
FJ4	Storage compartment underneath cockpit	S	S	S	S
FR3	Rear view camera (rear-view mirror display)	S	S	S	S
H00	Warm/cool air duct to rear compartment	S	S	S	S
H21	Windshield with filter band	S	S	S	S
H22	Rear window defroster	S	S	S	S
HH2	Heater, auxiliary electric hot air	S	S	S	S
HH9	Air Condition, Front	S	S	S	S
IH7	Head Unit, North America	S	S	S	S
J11	Speedometer, miles and km/h	S	S	S	S
			•		

#### 2500 CREW VAN - 6cyl Diesel

Standard Equipment

M3CV46   M3CV7x   M3CV7x   M3CV7x   M3CV7x   M3CV7x   907.643   907.643   907.643   907.643   907.645			144'' 6C	144" 6C 4x4	170'' 6C	170" 6C 4x4
Sear belt warning for co-driver seat						
158						
Dutside temperature gauge					_	
AB						_
JR3   Communication module (LTE) for dig. services   S   S   S   S   S   S   S   S   S						
K56         Red diesel filler cap         S         S         S           K50         Exhaust straight to rear         S         S         S         S           K67         24.5 gallon fuel tank         S         S         S         S         S           K1.1         Aux fuel sending unit W/ fuel tap         S	JH3	Communication module (LTE) for dig. services			S	S
K60         Exhaust straight to rear         S         S         S           K67         2.4 S gallon fuel tank         S         S         S           K1.1         Aux fuel sending unit w/ fuel tap         S         S         S           K1.5         Fuel filter with water separator         S         S         S           KP6         3rd generation SCR emission control system         S         S         S           L42         Headlight selection         S         S         S           L42         Headlight assistant         S         S         S           L85         3rd brake light         S         S         S           L87         4ront mudflaps         S         S         S <tr< td=""><td>JI9</td><td></td><td></td><td></td><td></td><td>S</td></tr<>	JI9					S
K87         24.5 gallon fuel tank         S         S         S           K11         Aux fuel sending unit w/ fuel tap         S         S         S         S           K15         Fuel filter with water separator         S         S         S         S           KP6         3rd generation SCR emission control system         S         S         S         S           L94         Parking lights deletion         S         S         S         S         S           L94         Parking lights deletion         S	K56	Red diesel filler cap		S	S	S
KL1         Aux fuel sending unit w/ fuel tap         S         S         S           KL5         Fuel filter with water separator         S         S         S         S           K66         3rd generation SCR emission control system         S         S         S         S           L94         Parking lights deletion         S         S         S         S         S           L85         3rd brake light         S         S         S         S         S         S           M51         Cruise control         S	K60					S
KLS         Fuel filter with water separator         S	KB7	24.5 gallon fuel tank	S	S	S	S
KP6         3rd generation SCR emission control system         S         S         S           L94         Parking lights deletion         S         S         S           L24         Headlight assistant         S         S         S         S           L85         3rd brake light         S         S         S         S         S           M51         Cruise control         S <td>KL1</td> <td>Aux fuel sending unit w/ fuel tap</td> <td>S</td> <td>S</td> <td>S</td> <td>S</td>	KL1	Aux fuel sending unit w/ fuel tap	S	S	S	S
194	KL5	·	S	S	S	S
LA2         Headlight assistant         S         S         S         S           LB5         3 rd brake light         S	KP6	3rd generation SCR emission control system	S	S	S	S
LB5         3rd brake light         S         S         S         S           MS1         Cruise control         S         S         S         S         S         S         S         PAP         Front mudflaps         S	L94	Parking lights deletion	S	S	S	S
MS1         Cruise control         S         S         S         S         PAP         Front mudflaps         S <t< td=""><td>LA2</td><td>Headlight assistant</td><td>S</td><td>S</td><td>S</td><td>S</td></t<>	LA2	Headlight assistant	S	S	S	S
P47         Front mudflaps         S         S         S         S         PAB         Rear mudflaps         S <td< td=""><td>LB5</td><td>3rd brake light</td><td>S</td><td>S</td><td>S</td><td>S</td></td<>	LB5	3rd brake light	S	S	S	S
P48         Rear mudflaps         S         S         S           Q11         Longitudinal member reinforcement         S         S         S         S           R65         Spare tire bracket below frame         S	MS1	Cruise control	S	S	S	S
Q11         Longitudinal member reinforcement         S         S         S           R65         Spare tire bracket below frame         S         S         S         S           R87         Spare tire         S         S         S         S         S           R89         Unspecified tire brand         S <td>P47</td> <td>Front mudflaps</td> <td>S</td> <td>S</td> <td>S</td> <td>S</td>	P47	Front mudflaps	S	S	S	S
R65         Spare tire bracket below frame         S         <	P48	Rear mudflaps	S	S	S	S
R87         Spare tire         S         S         S           RD9         Unspecified tire brand         S         S         S         S           RH8         Tires LT 245/75 R16         S         S         S         S         S           RM0         All-season tires         S         S         S         S         S           RS3         6.5 J x 16 steel wheels         S         S         S         S         S           R872         Tire pressure monitoring sensors         S         S         S         S         S           S02         Standard driver seat         S         S         S         S         S         S           S04         Standard front passenger seat         S	Q11	Longitudinal member reinforcement	S	S	S	S
RD9         Unspecified tire brand         S <td>R65</td> <td>Spare tire bracket below frame</td> <td>S</td> <td>S</td> <td>S</td> <td>S</td>	R65	Spare tire bracket below frame	S	S	S	S
RH8         Tires LT 245/75 R16         S	R87	Spare tire	S	S	S	S
RM0         All-season tires         S         S         S         S           RS3         6.5 J x 16 steel wheels         S         S         S         S           RY2         Tire pressure monitoring sensors         S         S         S         S           S02         Standard driver seat         S         S         S         S           S04         Standard front passenger seat         S         S         S         S           S02         Armrest for driver's seat         S         S         S         S           S22         Armrest for front passenger seat         S         S         S         S           S25         Armrest for front passenger seat         S         S         S         S           S45         Front airbag, driver         S         S         S         S         S           SA6         Front airbag, passenger         S	RD9	Unspecified tire brand	S	S	S	S
RS3         6.5 J x 16 steel wheels         S         S         S           RY2         Tire pressure monitoring sensors         S         S         S           S02         Standard driver seat         S         S         S           S04         Standard front passenger seat         S         S         S           S02         Armrest for driver's seat         S         S         S           S22         Armrest for front passenger seat         S         S         S         S           S25         Armrest for front passenger seat         S         S         S         S         S           S45         Front airbag, driver         S         <	RH8	Tires LT 245/75 R16	S	S	S	S
RY2         Tire pressure monitoring sensors         S         S         S           SO2         Standard driver seat         S         S         S           SO4         Standard front passenger seat         S         S         S           SO2         Armrest for driver's seat         S         S         S           SO2         Armrest for front passenger seat         S         S         S           SO3         Armrest for front passenger seat         S         S         S           SO3         Armrest for front passenger seat         S         S         S           SO4         Front airbag, driver         S         S         S           SA6         Front airbag, driver         S         S         S           SA6         Front airbag, driver         S         S         S           SA7         Thorax-pelvis sidebag, driver         S         S         S           SH1         Thorax-pelvis sidebag, driver         S         S         S           SH2         Thorax-pelvis sidebag, co-driver         S         S         S           SH2         Thorax-pelvis sidebag, co-driver         S         S         S           SH2         Airbag,	RM0	All-season tires	S	S	S	S
S02         Standard driver seat         S         S         S           S04         Standard front passenger seat         S         S         S           S22         Armrest for driver's seat         S         S         S           S25         Armrest for front passenger seat         S         S         S           S25         Armrest for front passenger seat         S         S         S           S45         Front airbag, driver         S         S         S           SA6         Front airbag, passenger         S         S         S           SA6         Front airbag, driver         S         S         S           SA6         Front airbag, driver         S         S         S           SA6         Front airbag, driver         S         S         S           SA7         Soldada, driver         S         S         S           SA7         Soldada, driver         S         S         S           SA7         Soldada, driver/passenger window         S         S         S         S           SK2         Seat occupancy sensor, driver's seat         S         S         S         S         S           SK2	RS3	6.5 J x 16 steel wheels	S	S	S	S
S04         Standard front passenger seat         S         S         S           S22         Armrest for driver's seat         S         S         S           S25         Armrest for front passenger seat         S         S         S           S25         Armrest for front passenger seat         S         S         S           S45         Front airbag, driver         S         S         S           SA6         Front airbag, passenger         S         S         S           SA7         Short passenger side passenger s	RY2	Tire pressure monitoring sensors	S	S	S	S
S22         Armrest for driver's seat         S         S         S           S25         Armrest for front passenger seat         S         S         S           SA5         Front airbag, driver         S         S         S           SA6         Front airbag, passenger         S         S         S           SA6         Front airbag, passenger         S         S         S           SA6         Front airbag, passenger         S         S         S           SA6         Front airbag, driver         S         S         S           SH1         Thorax-pelvis sidebag, driver         S         S         S           SH2         Thorax-pelvis sidebag, co-driver         S         S         S           SH2         Seat	S02	Standard driver seat	S	S	S	S
S25         Armrest for front passenger seat         S         S         S           SA5         Front airbag, driver         S         S         S         S           SA6         Front airbag, passenger         S         S         S         S         S           SH1         Thorax-pelvis sidebag, driver         S         S         S         S         S           SH2         Thorax-pelvis sidebag, co-driver         S         S         S         S         S           SH2         Thorax-pelvis sidebag, co-driver         S	S04	Standard front passenger seat	S	S	S	S
SA5         Front airbag, driver         S	S22	Armrest for driver's seat	S	S	S	S
SA6         Front airbag, passenger         S         S         S           SH1         Thorax-pelvis sidebag, driver         S         S         S           SH2         Thorax-pelvis sidebag, co-driver         S         S         S           SH9         Airbag, driver/passenger window         S         S         S         S           SH9         Airbag, driver/passenger window         S         S         S         S         S           SK2         Seat occupancy sensor, driver's seat         S	S25	Armrest for front passenger seat	S	S	S	S
SH1 Thorax-pelvis sidebag, driver         S         S         S           SH2 Thorax-pelvis sidebag, co-driver         S         S         S           SH9 Airbag, driver/passenger window         S         S         S           SK2 Seat occupancy sensor, driver's seat         S         S         S           SK2 Seat occupancy sensor, driver's seat         S         S         S           SK2 Seat occupancy sensor, driver's seat         S         S         S           SK2 Seat occupancy sensor, driver's seat         S         S         S           SK2 Seat occupancy sensor, driver's seat         S         S         S           SK2 Seat occupancy sensor, driver's seat         S         S         S           SK2 Seat occupancy sensor, driver's seat         S         S         S           SK2 Seat occupancy sensor, driver's seat         S         S         S           SK2 Seat occupancy sensor, driver's seat         S         S         S           SK2 Seat occupancy sensor, driver's seat         S         S         S           SK2 Seat occupancy sensor, driver's seat         S         S         S           SK2 Pre-inst. for seating configuration Crew Van         S         S         S           SK2 Seat occupancy se	SA5	Front airbag, driver	S	S	S	S
SH2         Thorax-pelvis sidebag, co-driver         S         S         S           SH9         Airbag, driver/passenger window         S         S         S         S           SK2         Seat occupancy sensor, driver's seat         S         S         S         S           T16         Sliding door, passenger side         S         S         S         S           T74         Assist handle, B-pillar         S         S         S         S           U22         Pre-inst. for seating configuration Crew Van         S         S         S         S           V36         Roof trim         S         S         S         S         S           V40         Floor anchors for rear seat bench         S         S         S         S           V47         Storage compart. w/ net in rear doors         S         S         S         S           W16         2nd row, fixed window, driver side         S         S         S         S           W17         2nd row, fixed window, passenger side         S         S         S         S           W61         Windows in rear doors         S         S         S         S           W70         Black tinting (90%) for rear	SA6	Front airbag, passenger	S	S	S	S
SH9Airbag, driver/passenger windowSSSSK2Seat occupancy sensor, driver's seatSSST16Sliding door, passenger sideSSST74Assist handle, B-pillarSSSU22Pre-inst. for seating configuration Crew VanSSSV36Roof trimSSSV40Floor anchors for rear seat benchSSSVA7Storage compart. w/ net in rear doorsSSSW162nd row, fixed window, driver sideSSSW172nd row, fixed window, passenger sideSSSW61Windows in rear doorsSSSW70Black tinting (90%) for rear windowsSSSXL2GVWR 9,050 lbs. / 4.100 KgSSS	SH1	Thorax-pelvis sidebag, driver	S	S	S	S
SK2       Seat occupancy sensor, driver's seat       S       S       S         T16       Sliding door, passenger side       S       S       S         T74       Assist handle, B-pillar       S       S       S         U22       Pre-inst. for seating configuration Crew Van       S       S       S         V36       Roof trim       S       S       S         V40       Floor anchors for rear seat bench       S       S       S         V47       Storage compart. w/ net in rear doors       S       S       S         W16       2nd row, fixed window, driver side       S       S       S         W17       2nd row, fixed window, passenger side       S       S       S         W61       Windows in rear doors       S       S       S         W70       Black tinting (90%) for rear windows       S       S       S         XL2       GVWR 9,050 lbs. / 4.100 Kg       S       S       S	SH2	Thorax-pelvis sidebag, co-driver	S	S	S	S
T16         Sliding door, passenger side         S         S         S           T74         Assist handle, B-pillar         S         S         S           U22         Pre-inst. for seating configuration Crew Van         S         S         S           V36         Roof trim         S         S         S           V40         Floor anchors for rear seat bench         S         S         S           V47         Storage compart. w/ net in rear doors         S         S         S           W16         2nd row, fixed window, driver side         S         S         S           W17         2nd row, fixed window, passenger side         S         S         S           W61         Windows in rear doors         S         S         S           W70         Black tinting (90%) for rear windows         S         S         S           XL2         GVWR 9,050 lbs. / 4.100 Kg         S         S         S	SH9	Airbag, driver/passenger window	S	S	S	S
T74         Assist handle, B-pillar         S         S         S           U22         Pre-inst. for seating configuration Crew Van         S         S         S           V36         Roof trim         S         S         S           V40         Floor anchors for rear seat bench         S         S         S           V47         Storage compart. w/ net in rear doors         S         S         S           W16         2nd row, fixed window, driver side         S         S         S           W17         2nd row, fixed window, passenger side         S         S         S           W61         Windows in rear doors         S         S         S           W70         Black tinting (90%) for rear windows         S         S         S           XL2         GVWR 9,050 lbs. / 4.100 Kg         S         S         S	SK2	Seat occupancy sensor, driver's seat	S	S	S	S
U22         Pre-inst. for seating configuration Crew Van         S         S         S           V36         Roof trim         S         S         S         S           V40         Floor anchors for rear seat bench         S         S         S         S           VA7         Storage compart. w/ net in rear doors         S         S         S         S           W16         2nd row, fixed window, driver side         S         S         S         S           W17         2nd row, fixed window, passenger side         S         S         S         S           W61         Windows in rear doors         S         S         S         S           W70         Black tinting (90%) for rear windows         S         S         S         S           XL2         GVWR 9,050 lbs. / 4.100 Kg         S         S         S         S	T16	Sliding door, passenger side	S	S	S	S
V36         Roof trim         S         S         S           V40         Floor anchors for rear seat bench         S         S         S           VA7         Storage compart. w/ net in rear doors         S         S         S           VA7         Storage compart. w/ net in rear doors         S         S         S           W16         2nd row, fixed window, driver side         S         S         S         S           W17         2nd row, fixed window, passenger side         S         S         S         S           W61         Windows in rear doors         S         S         S         S           W70         Black tinting (90%) for rear windows         S         S         S         S           XL2         GVWR 9,050 lbs. / 4.100 Kg         S         S         S         S	T74	Assist handle, B-pillar	S	S	S	S
V36         Roof trim         S         S         S           V40         Floor anchors for rear seat bench         S         S         S           VA7         Storage compart. w/ net in rear doors         S         S         S           VA7         Storage compart. w/ net in rear doors         S         S         S           W16         2nd row, fixed window, driver side         S         S         S         S           W17         2nd row, fixed window, passenger side         S         S         S         S           W61         Windows in rear doors         S         S         S         S           W70         Black tinting (90%) for rear windows         S         S         S         S           XL2         GVWR 9,050 lbs. / 4.100 Kg         S         S         S         S	U22	Pre-inst. for seating configuration Crew Van	S	S	S	S
V40         Floor anchors for rear seat bench         S         S         S           VA7         Storage compart. w/ net in rear doors         S         S         S         S           W16         2nd row, fixed window, driver side         S         S         S         S           W17         2nd row, fixed window, passenger side         S         S         S         S           W61         Windows in rear doors         S         S         S         S           W70         Black tinting (90%) for rear windows         S         S         S         S           XL2         GVWR 9,050 lbs. / 4.100 Kg         S         S         S         S	V36		S	S	S	S
VA7         Storage compart. w/ net in rear doors         S         S         S           W16         2nd row, fixed window, driver side         S         S         S           W17         2nd row, fixed window, passenger side         S         S         S           W61         Windows in rear doors         S         S         S           W70         Black tinting (90%) for rear windows         S         S         S           XL2         GVWR 9,050 lbs. / 4.100 Kg         S         S         S						
W16         2nd row, fixed window, driver side         S         S         S           W17         2nd row, fixed window, passenger side         S         S         S           W61         Windows in rear doors         S         S         S           W70         Black tinting (90%) for rear windows         S         S         S           XL2         GVWR 9,050 lbs. / 4.100 Kg         S         S         S						
W17         2nd row, fixed window, passenger side         S         S         S           W61         Windows in rear doors         S         S         S           W70         Black tinting (90%) for rear windows         S         S         S           XL2         GVWR 9,050 lbs. / 4.100 Kg         S         S         S						
W61         Windows in rear doors         S         S         S           W70         Black tinting (90%) for rear windows         S         S         S           XL2         GVWR 9,050 lbs. / 4.100 Kg         S         S         S						
W70         Black tinting (90%) for rear windows         S         S         S           XL2         GVWR 9,050 lbs. / 4.100 Kg         S         S         S						
XL2 GVWR 9,050 lbs. / 4.100 Kg S S S						
	-					

Options

144** 6C			44411.60	44411.60.4.4	47011.00	47011 60 4 4
S97.643   907.645   907.				<b>i</b>		
ASS						
A22 Adult bar for driveshaft & exhaust extension			907.643	907.643	907.645	907.645
A83         Ake ratio 4.182         \$0         -         \$0         -           B01         SFF for increased Center of Gravity above 39.4"         \$0         \$0         \$5         \$0         \$5           825         Electric parking brake         \$279         \$279         \$279         \$279         \$279           C72         Bumpers front/rear primed         \$268         \$268         \$268         \$268         \$268           C72         Bumpers front/rear primed         \$268         \$268         \$268         \$268           Must have CWJA67, not with CMO         \$307	A50	Front axle reinforced	\$346	-	\$346	-
Spr	AP2	Addtl. bar for driveshaft & exhaust extension	\$69	\$69	\$69	\$69
### ### ### ### ### ### ### ### ### ##	AR3	Axle ratio 4.182	\$0	-	\$0	-
Exercise parking brake	B01	ESP for increased Center of Gravity above 39.4"	\$0	\$0	\$0	\$0
C72   Bumpers front/rear primed   \$268   \$		must have CB4/CB8/X30; not with RH0/CB7				
C72	B25	Electric parking brake	\$279	\$279	\$279	\$279
Books		no restrictions				
Stabilization Level   Suppose	C72	Bumpers front/rear primed	\$268	\$268	\$268	\$268
Sample   S		must have CN2/X67, not with CM0				
Description	CB1	Suspension for comfort and load protection	\$241	-	\$241	-
Stabilization Level	CB7	Stabilization Level I	\$307	-	\$307	-
Clasther steering wheel		not with CB1/CB7/CB8/ZG3				
CL3   Leather steering wheel	CB8	Stabilization Level II	\$723	-	\$723	-
must have (CO2/E3M)/CO3 + (ET4/MS1)   S587   S587   S587   S587   Must have (CO2/E3M)/(Int/CO1) + (IB6/IB7) + (7755/9197/9775)   S364		not with CB4/CB8/ZG3				
CMO	CL3	Leather steering wheel	\$187	\$187	\$187	\$187
must have (CN2/X67) + (JA7/C01) + (J86/JB7) + (7755/9197/9775)		must have (C02/E3M)/C03 + (ET4/MS1)				
CM9   Primed side moldings   S364	CM0	Painted metallic front & rear bumper	\$587	\$587	\$587	\$587
CT1   Rear spring vibration absorbers   S138   S1		must have (CN2/X67) + (JA7/C01) + (JB6/JB7) + (7755/9197/9775)				
DO3	CM9	Primed side moldings	\$364	\$364	\$364	\$364
DO3 must be added for Duesseldorf production	CT1	Rear spring vibration absorbers	\$138	\$138	\$138	\$138
D13   Mounting rails for roof rack   \$300	D03	High roof	\$2,900	\$2,900	S	S
E1B Tray for smartphones incl. wireless charging		D03 must be added for Duesseldorf production				
### BILE Navigation   \$728   \$	D13	Mounting rails for roof rack	\$300	\$300	\$300	\$300
ST28	E1B	Tray for smartphones incl. wireless charging	\$156	\$156	\$156	\$156
### ### ### ### ### ### ### ### ### ##		must have CO2/E3M + H1I				·
E1S   Sirius XM, satellite radio   \$255   \$2	E1E	Navigation	\$728	\$728	\$728	\$728
### Big		must have CO2/E3M, not with CO3				
E1R Additional Fuses (40/80/150/100 Ampere) \$50 \$50 \$50 \$50 \$50 \$50 \$50 \$50 \$50 \$50	E1S	Sirius XM, satellite radio	\$255	\$255	\$255	\$255
SoP and Plausibility TBD		must have C02/E3M/C03				
E1Y Additional Fuses (40/80/80/100 Ampere) \$50 \$50 \$50 \$50 \$50 \$50 \$50 \$50 \$50 \$50	E1R	Additional Fuses (40/80/150/100 Ampere)	\$50	\$50	\$50	\$50
SoP and Plausibility TBD		SoP and Plausibility TBD				
E2A         Access point for BB special signals in cockpit         \$29         \$29         \$29           E2I         Additional battery, co-driver seat base         \$248         \$248         \$248           Must have E36; not with E2M; CHS production only         \$110         \$110         \$110         \$110           E36         Cutoff relay for additional battery         \$110         \$110         \$110         \$110           E3M         MBUX Multimedia System with 7" touchscreen         \$474         \$474         \$474         \$474           and with C02/C03; must have IK5+(IB7/IB6/IB8/FR8)         \$58         \$58         \$58         \$58           E5M         Extension of PSM standard contact         \$58         \$58         \$58           E5M         Extension of PSM standard contact         \$58         \$58         \$58           ED5         Parametric special module (PSM)         \$317         \$317         \$317         \$317           not with ED8         \$25         \$125<	E1Y	Additional Fuses (40/80/80/100 Ampere)	\$50	\$50	\$50	\$50
E21 Additional battery, co-driver seat base \$248 \$248 \$248 \$248 \$248 \$248 \$248 \$248		SoP and Plausibility TBD				
Must have E36; not with E2M; CHS production only	E2A	Access point for BB special signals in cockpit	\$29	\$29	\$29	\$29
E36 Cutoff relay for additional battery  \$110 \$110 \$110 \$110  \$110 \$110 \$110 \$1	E2I	Additional battery, co-driver seat base	\$248	\$248	\$248	\$248
Standard with E2I/E2M   S474		Must have E36; not with E2M; CHS production only		<u></u>		
E3M MBUX Multimedia System with 7" touchscreen \$474 \$474 \$474 \$474 \$474 \$474 \$474 \$47	E36	Cutoff relay for additional battery	\$110	\$110	\$110	\$110
not with CO2/CO3; must have JK5+(JB7/JB6/JB8/FR8)		standard with E2I/E2M				
E5M         Extension of PSM standard contact         \$58         \$58         \$58           ED5         Parametric special module (PSM)         \$317         \$317         \$317         \$317           not with ED8         \$125	E3M	MBUX Multimedia System with 7" touchscreen	\$474	\$474	\$474	\$474
ED5   Parametric special module (PSM)   \$317   \$3		not with C02/C03; must have JK5+(JB7/JB6/JB8/FR8)	_			_
Not with ED8   \$125	E5M	Extension of PSM standard contact	\$58	\$58	\$58	\$58
\$125	ED5	Parametric special module (PSM)	\$317	\$317	\$317	\$317
ES2   12 V power outlet, rear compartment   \$92   \$92   \$92   \$92   \$92   \$92   \$92   \$92   \$95   \$9		not with ED8				
ESS   Charging package, dashboard   \$82	EE3	115 V socket	\$125	\$125	\$125	\$125
ET4 Active Distance Assist DISTRONIC \$263 \$263 \$263 \$263 \$263 \$263 \$263 \$263			· ·	-	-	
must have C02/C03/E3M; not with ZH4           F49 Electrically heated windshield         \$218         \$218         \$218           no restrictions         \$36         \$36         \$36         \$36           F61 Interior rear view mirror         \$36         \$36         \$36         \$36           must have E3M/C02/C03         \$49         \$49         \$49         \$49           F64 Electrically folding exterior mirrors         \$49         \$49         \$49         \$49           no restrictions         \$81         \$81         \$81         \$81           FF8 Overhead storage slot, front center         \$105         \$105         \$105         \$105	ES5					
F49         Electrically heated windshield         \$218         \$218         \$218           no restrictions         \$36         \$36         \$36         \$36           F61         Interior rear view mirror         \$36         \$36         \$36           must have E3M/C02/C03         \$49         \$49         \$49           F64         Electrically folding exterior mirrors         \$49         \$49         \$49           no restrictions         \$81         \$81         \$81         \$81           FF8         Overhead storage slot, front center         \$105         \$105         \$105         \$105	ET4		\$263	\$263	\$263	\$263
no restrictions           F61 Interior rear view mirror         \$36         \$36         \$36           must have E3M/C02/C03         \$49         \$49         \$49           F64 Electrically folding exterior mirrors         \$49         \$49         \$49           no restrictions         \$81         \$81         \$81           FF8 Overhead storage slot, front center         \$105         \$105         \$105		must have C02/C03/E3M; not with ZH4				
F61         Interior rear view mirror         \$36         \$36         \$36           must have E3M/C02/C03         F64         Electrically folding exterior mirrors         \$49         \$49         \$49           no restrictions         FE9         Additional DIN-slot         \$81         \$81         \$81           FF8         Overhead storage slot, front center         \$105         \$105         \$105	F49		\$218	\$218	\$218	\$218
must have E3M/C02/C03           F64 Electrically folding exterior mirrors         \$49         \$49         \$49           no restrictions         \$81         \$81         \$81           FF8 Overhead storage slot, front center         \$105         \$105         \$105						
F64         Electrically folding exterior mirrors         \$49         \$49         \$49           no restrictions         \$81         \$81         \$81           FE9         Additional DIN-slot         \$81         \$81         \$81           FF8         Overhead storage slot, front center         \$105         \$105         \$105	F61		\$36	\$36	\$36	\$36
no restrictions           FE9         Additional DIN-slot         \$81         \$81         \$81           FF8         Overhead storage slot, front center         \$105         \$105         \$105						
FE9         Additional DIN-slot         \$81         \$81         \$81           FF8         Overhead storage slot, front center         \$105         \$105         \$105	F64		\$49	\$49	\$49	\$49
FF8 Overhead storage slot, front center \$105 \$105 \$105						
				-	-	
FJ1   Hinged lid for storage compartment \$93 \$93 \$93 \$93	-					
	FJ1	Hinged lid for storage compartment	\$93	\$93	\$93	\$93

Options

		144" 6C	144" 6C 4x4	170" 6C	170" 6C 4x4
		M2CV46	M2CV4X	M2CV76	M2CV7X
		907.643	907.643	907.645	907.645
LD0	Dear view comore (head unit display)	¢226	¢226	¢226	
FR8	Rear view camera (head unit display)  must have CO2/E3M; not with FR3/JB7; 3500XD not with JB8	\$336	\$336	\$336	\$336
FY1	Security alarm w. interior motion sensor	\$584	\$584	\$584	\$584
111	must have LC4/C00	7504	7304	7304	7304
FY7	Optional 3-button keys	\$36	\$36	\$36	\$36
FZ9	Keys, two additional masters	\$121	\$121	\$121	\$121
H01	Heat insulation, rear compartment	\$156	\$156	\$156	\$156
	must have V25/VA3/VA1/C07/X66	Ψ200	Ψ200	Ψ = 0 0	Ψ200
H04	Heat insulation, front compartment	\$187	\$187	\$187	\$187
	if + D50/D51 must have V07	7-21	7-01	7 - 0 :	7-01
H12	Fuel-fired pre-heater/booster (17K BTU)	\$1,116	\$1,116	\$1,116	\$1,116
	not with HZ9	1 / -	1 / -	, , -	1 / -
H13	Rear cabin heater and vents	\$786	\$786	\$786	\$786
	must have V43 + (H12/HZ9); not with VK8				
H15	Heated front passenger seat	\$284	\$284	\$284	\$284
	must have H16; not with X68		•		•
H16	Heated driver's seat	\$284	\$284	\$284	\$284
	must have H15; not with X68				
H88	Rear heater prep	\$405	\$405	\$405	\$405
	must have H12/HZ9; not with H13/T19				
H1I	Front-to-rear outlet in instrument panel	\$0	\$0	\$0	\$0
	must have FJ1/C01				
HH4	Thermotronic automatic climate control	\$337	\$337	\$337	\$337
	must have JF1; if +H13 must have H08/HK4				
HZ9	Fuel-fired heater booster (18,000 BTU)	\$676	\$676	\$676	\$676
	not with H12				
J51	Fuel gauge, optimized for aux. fuel tap	\$72	\$72	\$72	\$72
	not with HZ9/H12				
J52	Engine oil level display at cold start	\$0	\$0	\$0	\$0
JA7	Blind Spot Assist	\$450	\$450	\$450	\$450
	must have F64; not with C01	4000	4200	4000	4200
JB4	Active Lane Keeping Assist	\$288	\$288	\$288	\$288
IDC	standard with CO2/CA2	6775	6775	¢275	<b>477</b> 5
JB6	Parking Package with 360 degree camera	\$775	\$775	\$775	\$775
107	must have E3M/C02/C03; not with W75/W76/JB7	¢C15	¢C15	ĆC1E	¢C15
JB7	Parking Package must have E3M/C02/C03; not with W75/W76/JB6	\$615	\$615	\$615	\$615
JB8	360 Degree Camera	\$685	\$685	\$685	\$685
JDO	SoP and Plausibility TBD	\$005	\$005	\$665	\$005
JF1	Rain sensor	\$106	\$106	\$106	\$106
)LT	standard with CO2/X11	\$100	\$100	\$100	\$100
JK5	Instrument cluster with color display	\$144	\$144	\$144	\$144
313	not with CO3	7144	7144	ŞIHH	ŽITT
JW0	Backup alarm	\$99	\$99	\$99	\$99
JW2	Deactivation lamp monitoring failure	\$27	\$27	\$27	\$27
JW8	Attention Assist	\$49	\$49	\$49	\$49
K51	Misfueling prevention for Diesel	\$49	\$49	\$49	\$49
K52	DEF fluid filler cap - lockable	\$27	\$27	\$27	\$27
L13	Fog lamp with cornering light function	\$199	\$199	\$199	\$199
LB9	Illuminated front exits	\$151	\$151	\$151	\$151
LC4	Comfort overhead control panel	\$93	\$93	\$93	\$93
M20	Speed limitation 65 mph	\$60	\$60	\$60	\$60
	not with MD3	•	-		-
MD3	Top speed limitation 75 mph	\$60	\$60	\$60	\$60
	not with M20				
N62	Front engine bracket for additional alternator	\$467	\$467	\$467	\$467
	not with HK4/N63				

Options

		144" 6C	144" 6C 4x4	170" 6C	170" 6C 4x4
		M2CV46	M2CV4X	M2CV76	M2CV7X
		907.643	907.643	907.645	907.645
N63	Front engine bracket for auxiliary A/C compressor	\$467	\$467	\$467	\$467
	not with HK4/N62	1 4	1 4	4	4
Q24	Trailer hitch, 5,000 lbs	\$147	\$147	\$147	\$147
	not with W73/W75/W76	4.5.		4.0.	4.0.
QA9	Half-sided step rear (for trailer hitch)	\$101	\$101	\$101	\$101
	must have Q24/QA2; not with W73/W75/W76	4	4	4	4
R91	Spare tire deletion	-\$110	-\$110	-\$110	-\$110
D02	must have R92; not with R87	40	40	<b></b>	40
R92	Spare tire carrier deletion	\$0	\$0	\$0	\$0
DOG	must have R91; not with R65	Ć01	Ć01	Ć01	Ć01
R98	Rims painted jet black not with RL5/RM2	\$81	\$81	\$81	\$81
RF1	Tire brand Continental	\$0	\$0	\$0	\$0
KLI	must have RM1 + RM9	ŞÜ	<b>3</b> 0	<b>3</b> 0	, ŞU
RF8	Tire brand Michelin	\$0	\$0	\$0	\$0
KFO	must have RM9; not with RM1	ŞÜ	<b>3</b> 0	<b>3</b> 0	<b>3</b> 0
RH0	Tire brand Kumho	\$0	\$0	\$0	\$0
1110	must have RM9; not with RM1	Şΰ	Şΰ	<del>, , , , , , , , , , , , , , , , , , , </del>	Şΰ
RL5	Light-alloy wheels 6.5 J x 16	\$906	\$906	\$906	\$906
INLO	not with RS3/RM2/R98	7500	7500	7,000	7500
RM1	M+S winter tires	\$169	\$169	\$169	\$169
I	must have RF1/RD9; not with RF8/RH0/X31	7103	7103	7103	<b>\$103</b>
RM2	Rims painted arctic white	\$81	\$81	\$81	\$81
	not with R98/RL5	702	Ψ	70-	Ψ0-
RM9	Specially requested tires	\$101	\$101	\$101	\$101
	must have RF1/RF8/RH0; not with RD9	, -	, -	, -	, -
S28	Armrest, driver and passenger door	\$51	\$51	\$51	\$51
T12	Sliding door two stage opening	\$82	\$82	\$82	\$82
	not with T55			· · · · · · · · · · · · · · · · · · ·	•
T50	Electric closing assist right sliding door	\$335	\$335	\$335	\$335
	must have D03; not with T55/T93	•			•
T55	Electric sliding door right	\$831	\$831	\$831	\$831
	must have D03 + (FY7+T16); not with T12/T50				•
T57	Electric sliding step	\$1,071	\$1,071	\$1,071	\$1,071
	must have D03 + ED5; not with T93	-	-		,
T60	Opening limiter electrically operated sliding door	\$120	\$120	\$120	\$120
	must have T55				
T75	Door-mounted assist handles, driver & passenger	\$59	S	\$59	S
T85	Assist handle, left rear door	\$32	\$32	\$32	\$32
T86	Assist handles, right rear door	\$32	\$32	\$32	\$32
V43	Wood floor with 6 D-rings	\$422	\$422	\$422	\$422
	not with P93/V93/VL4/VK8/C07; standard with D93/H13/V24/V52/V	/C5/VV2/ZE6			
V85	Cigarette lighter & ash cup, front	\$39	\$39	\$39	\$39
VC5	Door sill - protective edge	\$71	\$71	\$71	\$71
	must have V43/X66; not with T19/T93/VK8/VV2/V93/C07			· · · · · · · · · · · · · · · · · · ·	•
VK8	Floor covering, plastic	\$370	\$370	\$370	\$370
	not with V43/P93/T19/T93/V52/VC5/X66	,	,	,	, , , ,
W54	Rear doors, opening to side wall	\$360	\$360	\$360	\$360
	90 Degree fixation point- Rear Doors	\$80	\$80	\$80	\$80
1	SoP and Plausibility TBD	700	<del>,</del> 550	<b>430</b>	<b>700</b>
W73	Bumper step, rear, grey	\$187	\$187	\$187	\$187
**/3	not with Q24/W75/W76	710/	7107	2101	\$10 <i>1</i>
W75		\$308	¢200	\$308	\$308
VV /5	Step, wide, at rear end	<b>Ş</b> 508	\$308	<b>300δ</b>	<b>300</b> δ
14176	not with JB6/JB7/Q24/QA9; must have R91+R92	¢001		¢601	
VV / b	Bumper step, rear, spring-loaded	\$601	-	\$601	-
<u> </u>	must have R91+R92; not with JB6/JB7/X30/Q24				

#### 2500 CREW VAN - 6cyl Diesel Options

		144" 6C	144" 6C 4x4	170" 6C	170" 6C 4x4
		M2CV46	M2CV4X	M2CV76	M2CV7X
		907.643	907.643	907.645	907.645
W78	Heated rear window(s) w/ washers/wipers	\$335	\$335	\$335	\$335
	Must have H22+VA7 / if D51 must have F61; not with W61				
X90	Deletion of Sprinter badge, left rear door	\$0	\$0	\$0	\$0
X93	Deletion of model badge, right rear door	\$0	\$0	\$0	\$0
XM4	Acoustic package	\$87	\$87	\$87	\$87
	standard with CO2/CO3				
Y10	First-aid kit	\$27	\$27	\$27	\$27
Y26	Wheel chocks	\$38	\$38	\$38	\$38
Y45	Emergency flashlight	\$27	\$27	\$27	\$27
Y68	Paint preservative	\$187	\$187	\$212	\$212
Y69	Surface protection for stock vehicles	\$315	\$315	\$315	\$315
YK3	Cargo straps, D-rings	\$81	\$81	\$81	\$81
ZH4	Downhill speed regulation for 4x4	-	\$58	-	\$58
	must have ED5; not with ET4				

#### 2500 CREW VAN - 6cyl Diesel

		144" 6C	144" 6C 4x4	170" 6C	170" 6C 4x4		
		M2CV46	M2CV4X	M2CV76	M2CV7X		
		907.643	907.643	907.645	907.645		
C00	Comfort Package	\$300	\$300	\$300	\$300		
LC4	Comfort overhead control panel	Х	Х	Х	Х		
SE4	Lumbar support, co-driver's seat	X	Х	Х	X		
SE5	Lumbar support, driver's seat	X	X	X	X		
SK0	Comfort head restraint, driver	X	X	X	Х		
SK1	Comfort head restraint, co-driver	X	X	X	Х		
S28	Armrest, driver and passenger door	X	X	X	X		
must	must have COS OR X68; CA/CC only: not with S23						

COS	Comfort Package (Seat addition)	\$381	\$381	\$381	\$381
SB1	Comfort driver's seat	X	X	X	X
SB2	Comfort passenger seat	Х	Х	Х	X
must	have COO		_		

X68	Comfort Plus Package	\$1,923	\$1,923	\$1,923	\$1,923
H15	Heated front passenger seat	X	X	X	X
H16	Heated driver's seat	Х	Х	Х	X
SF1	Driver's seat electrically adjustable	Х	Х	Х	X
SF2	Co-driver's seat electrically adjustable	Х	Х	Х	X
must	must have COO and VF4 OR VF6, CA/CC only: not with S23				

C01	Driver Convenience Package	\$760	\$760	\$760	\$760
E46	12 V power outlet, driver seat base	X	X	X	X
F64	Electrically folding exterior mirrors	X	X	X	X
FJ1	Hinged lid for storage compartment	X	X	X	X
FJ5	Hinged Lid for Storage Compartments left and right	X	X	X	Х
FZ9	Keys, two additional masters	X	X	X	X
JA7	Blind Spot Assist	X	X	X	Х
JW8	Attention Assist	X	X	X	X

C02	Premium Package	\$983	\$983	\$983	\$983		
CL3	Leather steering wheel	Х	X	X	X		
E3M	MBUX Multimedia System with 7" touchscreen	Х	X	X	X		
FM3	Wet Wiper System	Х	Х	X	Х		
JB4	Active Lane Keeping Assist	Х	Х	X	Х		
JK5	Instrument cluster with color display X X X X						
Order	Ordering availability restricted, see NetStar for availability and restrictions must have JF1 + XM4; must choose FR8/JB7/JB6						

CA2	C02 in combination with C03	\$604	\$604	\$604	\$604	
CL3	Leather steering wheel	X	X	X	X	
FM3	Wet Wiper System	X	X	Х	X	
JB4	Active Lane Keeping Assist	Х	Х	Х	Х	
JK5	Instrument cluster with color display	Х	Х	Х	Х	
Order	Ordering availability restricted, see NetStar for availability and restrctions must have CO3 + JF1					

144" 6C	144" 6C 4x4	170" 6C	170" 6C 4x4
M2CV46	M2CV4X	M2CV76	M2CV7X
907.643	907.643	907.645	907.645

C03	Premium Plus Package	\$1,793	\$1,793	\$1,793	\$1,793
E1B	Tray for smartphones incl. wireless charging	Х	Х	Х	Х
	Navigation	Х	Х	Х	X
EY2	Intelligent navigation	X	Х	Х	X
E4M	MBUX Multimedia System with 10.25" touchscreen	X	Х	X	X
EX9	Free map data updates for 3 years	X	Х	X	X
H1I	Front-to-rear outlet in instrument panel	X	Х	X	Х
JA9	Traffic Sign Assist	X	Х	X	Х
XM4	Acoustic package	X	Х	Х	Х
H1I	Front-To-Rear Outlet In Instrument Panel	X	Х	X	X
must	have (CA2+(JB7/JB6/JB8)) OR (JB4+JK5+FM3+(JB7/JB6/JB8)); not with	FR8 and CO2		_	

X67	Chrome Grille Package	\$290	\$290	\$290	\$290	
CN2	Radiator grille frame in vehicle color	Х	X	X	X	
FK3	Chrome plated radiator grille (MB only)	Х	X	X	Х	
no res	no restrictions					

X13	Exterior Lighting Package	\$1,608	\$1,608	\$1,608	\$1,608	
L13	Fog lamp with cornering light function	Х	X	X	X	
L22	Partial LED tail lights	Х	Х	Х	Х	
LA1	High Beam Assist	Х	Х	Х	Х	
LG7	LED High Performance headlamps	Х	Х	Х	Х	
no res	no restrictions					

X72	Crew Van Comfort Package	\$220	\$220	\$220	\$220	
S31	Convenience Head Restraints For Pass. Comp.	X	Х	Х	Х	
T12	Sliding door two stage opening	X	Х	X	X	
T50	Electric closing assist right sliding door (soft close)	Х	Х	Х	Х	
UY1	Three-seater comfort bench in passenger compartment, first row (na	Х	Х	Х	Х	
can h	an have VF4/VF6 only					

X4Z	Interior Trim Upgrade Package	\$610	\$610	\$610	\$610	
VA1	Side wall paneling waist height PVC	Х	Х	Х	Х	
VA3	Side wall paneling full hardboard	Х	Х	Х	Х	
ZK4	Mixto	Х	Х	Х	Х	
must	must have (V43+VC5) OR VK8					

144" 4C

170" 4C

		144" 4C	170° 4C
		M3CV44	M3CV74
		907.643	907.645
		5071010	5071010
Engin	e		
4-Cyl	Engine/7-Speed Trans.	S	S
ED4	AGM battery 12V 92 AH 850 A	S	S
	Automatic transmission, 7G-tronic	S	S
	Alternator 14 V / 200 A	S	S
	2.0L 4-cylinder diesel engine	S	S
	SULEV emissions	S	S
		3	3
	- choose while ordering	40	40
X34	Dual Rear Wheel	<i>\$</i> 0	\$0
	Tires LT 215/85 R16	S	S
	5.5 J x 16 steel wheels	S	S
RD9	Unspecified tire brand	S	S
X31	Super Single Tire	\$385	\$385
R9A	285/65 R 16 C super single tires	0	0
RS5	Steel wheels: 8.5Jx16 Rr; 6.5Jx16 Fr	0	0
RD9	Unspecified tire brand	0	0
RY2	Tire pressure monitoring sensors	0	0
Seati	ng and Trim Packages		
	Standard Rear Seats	S	S
	3-seater bench rear, 1st row (narrow)	S	S
	Wall-side armrest	S	S
	Aisle-side armrest	S	S
		3	3
	nave VF7/VF6 only; with X68 must have VF6	_	_
X2V	Standard Trim Crew Van Package	S	S
	Half height load compartment trim	S	S
V35	Wheel house covering	S	S
	Wood floor with 6 D-rings	S	S
CHS p	production only		
Equip	ment		
AR3	Axle ratio 4.182	S	S
BA3	Active Brake Assist	S	S
BH1	Hold Function	S	S
CB8	Stabilization Level II	S	S
C6L	Multifunction steering wheel	S	S
CL1	Adjustable steering wheel (angle)	S	S
D03	High roof	0	S
D93	Omission bulkhead	S	S
E07	Hill Start Assist	S	S
		S S	S
E10	Standard radio		_
E1U	USB-C socket, 5 V	S	S
E30	Starter battery disconnect	S	S
E3J	Pre-installation for switch panel	S	S
E40	Trailer hitch prep. wiring	S	S
ED8	Preinstallation PSM	S	S
EE5	Ultracapacitor discharge module	S	S
EK1	Body Builder Connector	S	S
ES0	Jump start terminal	S	S
EW6	Pre-installation for Mercedes me Remote Services	S	S
EY5	Emergency Call System	S	S
EY6	Breakdown management	S	S
F43	Laminated glass rear	S	S
F68	Heated & electrically adjustable exterior mirrors	S	S
FF3		S	S
	Cupholder rear compartment		_
FF5	Shelf above windshield	S	S
FG8	Cupholder front	S	S
FI1	Remote key (315 mhz) w/central locking	S	S
FJ4	Storage compartment underneath cockpit	S	S

144" 4C 170" 4C

		144" 4C	170" 4C
		M3CV44	M3CV74
		907.643	907.645
FR3	Rear view camera (rear-view mirror display)	S	S
H00	Warm/cool air duct to rear compartment	S	S
H21	Windshield with filter band	S	S
H22	Rear window defroster	S	S
HH2	Heater, auxiliary electric hot air	S	S
HH9	Air Condition, Front	S	S
IH7	Head Unit, North America	S	S
J11	Speedometer, miles and km/h	S	S
J55	Seat belt warning for co-driver seat	S	S
J58	Seat belt reminder driver	S	S
J65			S
JA8	Outside temperature gauge Crosswind Assist	S S	S
$\vdash$			
JH3	Communication module (LTE) for dig. services	S	S
JI9	Service interval 20.000 miles	S	S
K56	Red diesel filler cap	S	S
K60	Exhaust straight to rear	S	S
KB7	24.5 gallon fuel tank	S	S
KL1	Aux fuel sending unit w/ fuel tap	S	S
KL5	Fuel filter with water separator	S	S
KP6	3rd generation SCR emission control system	S	S
L94	Parking lights deletion	S	S
LA2	Headlight assistant	S	S
LB5	3rd brake light	S	S
MS1	Cruise control	S	S
P47	Front mudflaps	S	S
P48	Rear mudflaps	S	S
Q11	Longitudinal member reinforcement	S	S
	Spare tire bracket below frame	S	S
R87	Spare tire	S	S
RM0	All-season tires	S	S
S02	Standard driver seat	S	S
S04	Standard front passenger seat	S	S
S22	Armrest for driver's seat	S	S
S25	Armrest for front passenger seat	S	S
SA5	Front airbag, driver	S	S
SA6	Front airbag, passenger	S	S
SH1	Thorax-pelvis sidebag, driver	S	S
SH2	Thorax-pelvis sidebag, co-driver	S	S
SH9	Airbag, driver/passenger window	S	S
SK2	Seat occupancy sensor, driver's seat	S	S
T16	Sliding door, passenger side	S	S
T74	Assist handle, B-pillar	S	S
U22	Pre-inst. for seating configuration Crew Van	S	S
V36	Roof trim	S	S
V40	Floor anchors for rear seat bench	S	S
VA7	Storage compart. w/ net in rear doors	S	S
	2nd row, fixed window, driver side	S	S
W17	2nd row, fixed window, passenger side	S	S
W61	Windows in rear doors	S	S
W70	Black tinting (90%) for rear windows	S	S
	I		_
XB3 Y43	GVWR 9,990 lbs. / 4,531 kg Jack, hydraulic	S	S S

		144" 4C	170" 4C
		M3CV44	M3CV74
		907.643	907.645
A50	Front axle reinforced	\$346	\$346
AP2	Addtl. bar for driveshaft & exhaust extension	\$69	\$69
AR2	Axle ratio 3.923	\$0	\$0
	not with AR3	•	·
B01	ESP for increased Center of Gravity above 39.4"	_	\$0
	must have CB4/CB8/X30; not with RH0/CB7		·
C72	Bumpers front/rear primed	\$268	\$268
	must have CN2/X67, not with CM0	•	·
CL3	Leather steering wheel	\$187	\$187
	must have (C02/E3M)/C03 + (ET4/MS1)	7-01	720
CM0	Painted metallic front & rear bumper	\$587	\$587
-	must have (CN2/X67) + (JA7/C01) + (JB6/JB7) + (7755/9197/9775)	<del>, , , , , , , , , , , , , , , , , , , </del>	<del>, , , , , , , , , , , , , , , , , , , </del>
CM9	Primed side moldings	\$364	\$364
D03	High roof	\$2,900	S
D13	Mounting rails for roof rack	\$300	\$300
E1B	Tray for smartphones incl. wireless charging	\$156	\$156
<del></del>	must have CO2/E3M + H1I	<b>\$133</b>	7230
E1E	Navigation	\$728	\$728
	must have CO2/E3M, not with CO3	7,20	<b>7720</b>
E1S	Sirius XM, satellite radio	\$255	\$255
	must have CO2/E3M/CO3	Ų233	<b>7233</b>
E1R	Additional Fuses (40/80/150/100 Ampere)	\$50	\$50
	SoP and Plausibility TBD	750	730
E1Y	Additional Fuses (40/80/80/100 Ampere)	\$50	\$50
	SoP and Plausibility TBD	730	<del>-</del> <del>-</del> <del>-</del> <del>-</del> <del>-</del> <del>-</del> <del>-</del> - <del>-</del> <del>-</del> - <del>-</del>
E2A	Access point for BB special signals in cockpit	\$29	\$29
E2I	Additional battery, co-driver seat base	\$248	\$248
	Must have E36; not with E2M; CHS production only	Ψ <u>2</u> 10	Ψ <u>2</u> 10
E36	Cutoff relay for additional battery	\$110	\$110
	standard with E2I/E2M	7110	Ţ110
E3M	MBUX Multimedia System with 7" touchscreen	\$474	\$474
	not with CO2/CO3; must have JK5+(JB7/JB6/JB8/FR8)	¥ .7 .	¥ 17 1
E5M	Extension of PSM standard contact	\$58	\$58
ED5	Parametric special module (PSM)	\$317	\$317
	not with ED8	702	702
EE3	115 V socket	\$125	\$125
ES2	12 V power outlet, rear compartment	\$92	\$92
ES5	Charging package, dashboard	\$82	\$82
ET4	Active Distance Assist DISTRONIC	\$263	\$263
	must have CO2/CO3/E3M; not with ZH4	<b>¥</b> 200	<b>¥</b> 200
F49	Electrically heated windshield	\$218	\$218
	no restrictions	¥==5	7
F61	Interior rear view mirror	\$36	\$36
	must have E3M/C02/C03		,
FE9	Additional DIN-slot	\$81	\$81
FF8	Overhead storage slot, front center	\$105	\$105
FJ1	Hinged lid for storage compartment	\$93	\$93
FR8	Rear view camera (head unit display)	\$336	\$336
	must have CO2/E3M; not with FR3/JB7/JB6/JB8		
FY1	Security alarm w. interior motion sensor	\$584	\$584
	must have LC4/C00	,	
FY7	Optional 3-button keys	\$36	\$36
FZ9	Keys, two additional masters	\$121	\$121
H01	Heat insulation, rear compartment	\$156	\$156
<u> </u>	must have V25/VA3/VA1/C07/X66	,	
H04	Heat insulation, front compartment	\$187	\$187
	if + D50/D51 must have V07	,	
	[7] = 2 -7 - 2		

Hall   Fuel-fired pre-heater/booster (17K BTU)   S.1,116   S.1,116   S.1,116   not with #29   S.786   S786   s78			144" 4C 170" 4C	
### ### ##############################				
### ### ### ### ### ### ### ### ### ##				
Hailang	H12	Fuel-fired pre-heater/booster (17K BTU)	\$1,116	\$1,116
must have V33 + (H12/H29); not with VK8           H15 Heated front passenger seat         \$284         \$284           must have H16; not with X68         \$284         \$284           H16 Heated driver's seat         \$284         \$284           must have H15; not with X68         \$405         \$405           H88 Rear heater prep         \$405         \$405           must have H12/H29; not with H13/T19         \$405         \$405           H17 Front-to-rear outlet in instrument panel         \$0         \$0           must have F12/C01         \$337         \$337           HH4 Thermotronic automatic climate control         \$337         \$337           must have F11; if +113 must have H08/HK4         \$666         \$676           H29 Fuel-fired heater booster (18,000 BTU)         \$676         \$676           not with H29/H12         \$51         \$616         \$676           52 Engine oil level display at cold start         \$0         \$0         \$0           JA7 Blind Spot Assist         \$450         \$450         \$450           must have F64; not with C01         \$288         \$288         \$288           standard with C02/C02         \$288         \$288         \$288           standard with C02/C03; not with W75/W76/J87         \$775			_	
### Hasted front passenger seat ### \$284   \$	H13	Rear cabin heater and vents	\$786	\$786
### ### ### ### ### ### ### ### ### ##				
### ### ##############################	H15	Heated front passenger seat	\$284	\$284
must hove H15; not with X68         \$405         \$405           H88 Rear heater prep         \$405         \$405           must hove H12/Hzg, not with H13/T19         \$50         \$0           H11 Front-to-rear outlet in instrument panel         \$0         \$0           must hove F11/C01         \$337         \$337         \$337           must hove F11/C01         \$337         \$337         \$337           must hove F11/C01         \$576         \$676         \$676           not with H12         \$572         \$572         \$72           151 Full gauge, optimized for aux. fuel tap         \$77         \$72         \$72           not with H12/F112         \$0         \$0         \$0         \$0           1A7 Blind Spot Assist         \$450         \$450         \$450           MA7 Blind Spot Assist         \$450         \$450         \$450           must hove F64; not with CO1         \$685         \$288         \$288           1A7 Blind Spot Assist         \$288         \$288         \$288           528 Bloof Spot Assist         \$288         \$288         \$288           528 Bloof Spot Assist         \$288         \$288         \$288           528 Bloof Spot Assist         \$288         \$288		must have H16; not with X68		
H88   Rear heater prep   S405   S405   S405   must have H12/H29; not with H13/T19   H11   Front-ro-ear outlet in instrument panel   \$0   \$0   \$0   must have F11/C01   H14   Thermotronic automatic climate control   \$337   \$337   must have F11/C01   H14   Thermotronic automatic climate control   \$337   \$337   must have F11/C01   H14   Thermotronic automatic climate control   \$337   \$337   must have F11/C01   H14   Thermotronic automatic climate control   \$337   \$337   must have F11/16   H14   H29/H14   H29/H14   H29/H12   H29/H14   H29/H12   H29/H14	H16	Heated driver's seat	\$284	\$284
must have H12/H29; not with H13/T19         \$0         \$0           H11 Front-to-rear outlet in instrument panel must have F11/C91         \$0         \$0           must have F11/C91         \$1337         \$3337         \$3337           must have F11/C91         \$676         \$676         \$676           HH4         Thermotronic automatic climate control         \$337         \$3337           must have F11/C91         \$676         \$676         \$676           Jack F16 from Control of the M12         \$72         \$72         \$72           John With H12         \$72         \$72         \$72         \$72           not with H12         \$72 <td></td> <td>must have H15; not with X68</td> <td></td> <td></td>		must have H15; not with X68		
H11   Front-to-rear outlet in instrument panel   \$0   \$0   must have F1J/COI   must have F1J/COI   H14   Thermotronic automatic climate control   \$337   \$337   \$337   must have F1J; if +H13 must have H08/HK4   H29   Fuel-fired heater booster (18,000 BTU)   \$676   \$676   \$676   not with H12   Fuel faired heater booster (18,000 BTU)   \$676   \$572   \$72   not with H29/H12   Fuel gauge, optimized for aux. Fuel tap   \$72   \$72   not with H29/H12   Fuel gauge, optimized for aux. Fuel tap   \$72   \$72   not with H29/H12   Fuel gauge, optimized for aux. Fuel tap   \$75   \$75   \$750   \$750   Must have F64; not with C01   Must have F64; not with C01   Must have F64; not with C01   Must have E3M/C02/C03; not with W75/W76/JB7   Must have E3M/C02/C03; not with W75/W76/JB7   Farking Package   \$615   \$615   Must have E3M/C02/C03; not with W75/W76/JB6   Must have E3M/C02/C03; not with W75/W76/JC03/C03/C03, not with W75/W76/W76/W76/W76/W76/W76/W76/W76/W76/W76	H88	Rear heater prep	\$405	\$405
must have FJI/C01         \$337         \$337           HH4 Thermotronic automatic climate control         \$337         \$337           must have JE; If +H13 must have H08/HK4         H29         Fuel-fired heater booster (18,000 BTU)         \$676         \$676           not with H12         572         \$72         \$72           15 Fuel gauge, optimized for aux. fuel tap         \$72         \$72           not with H29/H12         \$0         \$0           152 Fugine oil level display at cold start         \$0         \$0           17 Blind Spot Assist         \$450         \$450           M13 Flind Spot Assist         \$288         \$288           standard with C02/C02         \$288         \$288           184 Active Lane Keeping Assist         \$288         \$288           standard with C02/C02         \$288         \$288           186 Parking Package with 360 degree camera         \$775         \$775           must have E3M/C02/C03; not with W75/W76/JB7         \$615         \$615           187 Parking Package         \$615         \$615           must have E3M/C02/C03; not with W75/W76/JB6         \$685         \$685           188 360 Degree Camera         \$685         \$685           \$692 and Pluusibility TBD         \$685         \$685		must have H12/HZ9; not with H13/T19		
HH4   Thermotronic automatic climate control   must have IFI; if +H13 must have H08/HK4	H1I	Front-to-rear outlet in instrument panel	\$0	\$0
must have IF1; if +H13 must have H08/HK4           H29 Euel-fired heater booster (18,000 BTU)         \$676         \$676           not with H12         572         \$72           J51 Fuel gauge, optimized for aux. fuel tap not with H29/H12         \$72         \$72           J52 Engine oil level display at cold start         \$0         \$0           J87 Blind Spot Assist         \$450         \$450           must have F64, not with C01         ***         ***           J84 Active Lane Keeping Assist         \$288         \$288           standard with C02/CA2         ***         ***           J86 Parking Package with 360 degree camera         \$775         \$775           must have E3M/C02/C03; not with W75/W76/JB7         ***           J87 Parking Package         \$615         \$615           must have E3M/C02/C03; not with W75/W76/JB6         ***           J88 360 Degree Camera         \$685         \$685           \$68 \$         \$685         \$685           \$68 \$         \$685         \$685           \$68 \$         \$685         \$685           \$68 \$         \$685         \$685           \$68 \$         \$685         \$685           \$68 \$         \$685         \$685           \$68 \$		must have FJ1/C01		
HZ9   Fuel-fired heater booster (18,000 BTU)   \$676   \$676   \$676   \$151   Fuel gauge, optimized for aux. fuel tap   \$72   \$73   \$	HH4	Thermotronic automatic climate control	\$337	\$337
		must have JF1; if +H13 must have H08/HK4	•	
151   Fuel gauge, optimized for aux. fuel tap	HZ9	Fuel-fired heater booster (18,000 BTU)	\$676	\$676
	J51	Fuel gauge, optimized for aux. fuel tap	\$72	\$72
152   Engine oil level display at cold start   \$0 \$0 \$0 \$0 \$1A7 \$ \$18ind Spot Assist				
JA7   Blind Spot Assist   S450   \$450   must have F64; not with C01     JB4   Active Lane Keeping Assist   \$288   \$288     Standard with C02/CA2   S450   S450     JB6   Parking Package with 360 degree camera   \$775   \$775     must have E3M/C02/C03; not with W75/W76/JB7   S615   S615     JB7   Parking Package   \$615   \$615     JB8   360 Degree Camera   \$685   \$685     JB8   JB8   JB8   S60   S60     JF1   Rain sensor   \$106   \$106     JK5   Instrument cluster with color display   \$144   \$144     not with C03   S106   S106     JW0   Backup alarm   \$99   \$99     JW2   Deactivation lamp monitoring failure   \$27   \$27     JW8   Attention Assist   \$49   \$49     K51   Misfueling prevention for Diesel   \$49   \$49     K52   DEF fluid filler cap - lockable   \$27   \$27     L13   F0g lamp with cornering light function   \$199   \$199     LB9   Illuminated front exits   \$151   \$151     LC4   Comfort overhead control panel   \$93   \$93     M20   Speed limitation 65 mph   \$60   \$60     not with M03   MD3   Top speed limitation 75 mph   \$60   \$60     not with M100   MD3   Top speed limitation 75 mph   \$60   \$60     not with M20   Top speed limitation 75 mph   \$60   \$60     Nato M100   M100   M100   M100     MD3   Top speed limitation 75 mph   \$60   \$60     not with M400   \$467   \$467     not with M400   \$100   \$100   \$100     MD3   Top speed limitation 75 mph   \$60   \$60     Not with M400   \$100   \$100   \$100     MD3   Top speed limitation 75 mph   \$60   \$60     Not with M400   \$100   \$100   \$100     MD3   Top speed limitation 75 mph   \$60   \$60     NOT the negine bracket for additional alternator   \$467   \$467     Not with M400   \$100   \$100   \$100     MD3   Top speed limitation 75 mph   \$60   \$60     NOT the negine bracket for additional alternator   \$467   \$467     Not with M400   \$100   \$100     MD3   Top speed limitation 75 mph   \$60   \$60     NOT the negine bracket for additional alternator   \$467	J52	·	\$0	\$0
must have F64; not with C01           JB4         Active Lane Keeping Assist         \$288         \$288           standard with CO2/CA2         JB6         Parking Package with 360 degree camera         \$775         \$775           must have E3M/CO2/CO3; not with W75/W76/JB7         JB7         Parking Package         \$615         \$615           must have E3M/CO2/CO3; not with W75/W76/JB6         JB8         360 Degree Camera         \$685         \$685           SoP and Plausibility TBD         JIF1         Rain sensor         \$106         \$106         \$106           JK5         Instrument cluster with color display         \$144         \$145         \$145 </td <td></td> <td></td> <td></td> <td>·</td>				·
Section   Sect	-	·	7 .55	Ŧ 100
Standard with CO2/CA2     JB6   Parking Package with 360 degree camera   \$775   \$775     must have E3M/CO2/CO3; not with W75/W76/JB7     JB7   Parking Package   \$615   \$615     must have E3M/CO2/CO3; not with W75/W76/JB6     JB8   360 Degree Camera   \$685   \$685     SoP and Plausibility TBD     JF1   Rain sensor   \$106   \$106     JK5   Instrument cluster with color display   \$144   \$144     not with CO3     JW0   Backup alarm   \$99   \$99     W2   Deactivation lamp monitoring failure   \$27   \$27     JW8   Attention Assist   \$49   \$49     K51   DEF fluid filler cap - lockable   \$27   \$27     L13   Fog lamp with cornering light function   \$199   \$199     BIll lilluminated front exits   \$151   \$151     LC4   Comfort overhead control panel   \$93   \$93     M20   Speed limitation 65 mph   \$60   \$60     not with MD3   \$199   \$190     MD3   Top speed limitation 75 mph   \$60   \$60     not with MBO   \$60   \$60     not with HK4/N63   \$186   \$186     not with HK4/N63   \$186   \$186     not with W3/W75/W76(24/Q67     Alf-sided step rear (for trailer hitch)   \$101     must have Q24/QA2; not with W73/W75/W76     R91   Spare tire deletion   \$50   \$00     must have R91; not with R85   \$88   \$88   \$88     R98   Rims painted jet black   \$81   \$81	JB4		\$288	\$288
JB6	-		Ψ200	Ψ=00
must have E3M/C02/C03; not with W75/W76/JB7           JB7         Parking Package         \$615         \$615           must have E3M/C02/C03; not with W75/W76/JB6         \$685         \$685         \$685           JB8         360 Degree Camera         \$685         \$685         \$685           SoP and Plausibility TBD         JF1         Rain sensor         \$106         \$106           JK5         Instrument cluster with color display         \$144         \$144           JK5         Instrument cluster with color display         \$144         \$144           JK5         Instrument cluster with color display         \$144         \$144           JW0         Backup alarm         \$99         \$99           JW0         Backup alarm         \$99         \$99           JW2         Deactivation lamp monitoring failure         \$27         \$27           JW8         Attention Assist         \$49         \$49           K51         Misfueling prevention for Diesel         \$49         \$49           K52         DEF fluid filler cap - lockable         \$27         \$27           L52         LF fluid filler cap - lockable         \$27         \$27           L63         Fog lamp with cornering light function         \$199 <td< td=""><td>JB6</td><td></td><td>\$775</td><td>\$775</td></td<>	JB6		\$775	\$775
B87   Parking Package   \$615	300		7,73	ψ,,,3
must have E3M/C02/C03; not with W75/W76/JB6	IR7		\$615	\$615
JBB   360 Degree Camera   \$685   \$685   \$685   \$50P and Plausibility TBD   \$106   \$106   \$106   \$105   \$105   \$144   \$1	107		7013	<del>701</del> 5
SoP and Plausibility TBD	IRR		\$685	\$685
F1	100		2002	2002
JK5       Instrument cluster with color display       \$144       \$144         not with C03       \$99       \$99         JW0       Backup alarm       \$99       \$99         JW2       Deactivation lamp monitoring failure       \$27       \$27         JW8       Attention Assist       \$49       \$49         K51       Misfueling prevention for Diesel       \$49       \$49         K51       Misfueling prevention for Diesel       \$49       \$49         K52       DEF fluid filler cap - lockable       \$27       \$27         L13       Fog lamp with cornering light function       \$199       \$199         LB9       Illuminated front exits       \$151       \$151         LC4       Comfort overhead control panel       \$93       \$93         M20       Speed limitation 65 mph       \$60       \$60         not with MD3       \$60       \$60       \$60         not with MW20       \$60       \$60       \$60         N62       Front engine bracket for additional alternator       \$467       \$467         not with HK4/N63       \$186       \$186         N63       Front engine bracket for auxiliary A/C compressor       \$467       \$467         not with W73/W75/W7	IE1	,	\$106	\$106
JW0 Backup alarm       \$99       \$99         JW2 Deactivation lamp monitoring failure       \$27       \$27         JW8 Attention Assist       \$49       \$49         K51 Misfueling prevention for Diesel       \$49       \$49         K52 DEF fluid filler cap - lockable       \$27       \$27         L13 Fog lamp with cornering light function       \$199       \$199         LB9 Illuminated front exits       \$151       \$151         LC4 Comfort overhead control panel       \$93       \$93         M20 Speed limitation 65 mph       \$60       \$60         not with MD3       \$60       \$60         MD3 Top speed limitation 75 mph       \$60       \$60         not with M20       \$60       \$60         N62 Front engine bracket for additional alternator       \$467       \$467         not with HK4/N63       \$467       \$467         N63 Front engine bracket for auxiliary A/C compressor       \$467       \$467         not with HK4/N62       \$186       \$186         QA2 Trailer cross member 7,500 lbs capacity       \$186       \$186         not with W73/W75/W76/Q24/Q67       \$10       \$101         QA9 Half-sided step rear (for trailer hitch)       \$10       \$101         must have Q24/QA2; not with W7	1//2	· · ·	Ş1 <del>44</del>	Ş144
JW2       Deactivation lamp monitoring failure       \$27       \$27         JW8       Attention Assist       \$49       \$49         K51       Misfueling prevention for Diesel       \$49       \$49         K52       DEF fluid filler cap - lockable       \$27       \$27         L13       Fog lamp with cornering light function       \$199       \$199         LB9       Illuminated front exits       \$151       \$151         LC4       Comfort overhead control panel       \$93       \$93         M20       Speed limitation 65 mph       \$60       \$60         not with MD3       Speed limitation 75 mph       \$60       \$60         not with M20       \$60       \$60         N62       Front engine bracket for additional alternator       \$467       \$467         not with HK4/N63       \$467       \$467         N63       Front engine bracket for auxiliary A/C compressor       \$467       \$467         not with HK4/N62       \$186       \$186         QA2       Trailer cross member 7,500 lbs capacity       \$186       \$186         not with W73/W75/W76/Q24/Q67       \$10       \$101         QA9       Half-sided step rear (for trailer hitch)       \$101       \$101         mus	114/0		ćoo	ćoo
JW8 Attention Assist       \$49       \$49         K51 Misfueling prevention for Diesel       \$49       \$49         K52 DEF fluid filler cap - lockable       \$27       \$27         L13 Fog lamp with cornering light function       \$199       \$199         LB9 Illuminated front exits       \$151       \$151         LC4 Comfort overhead control panel       \$93       \$93         M20 Speed limitation 65 mph       \$60       \$60         not with MD3       \$60       \$60         MD3 Top speed limitation 75 mph       \$60       \$60         not with M20       \$467       \$467         N62 Front engine bracket for additional alternator       \$467       \$467         not with HK4/N63       \$467       \$467         N63 Front engine bracket for auxiliary A/C compressor       \$467       \$467         not with HK4/N62       \$186       \$186         QA2 Trailer cross member 7,500 lbs capacity       \$186       \$186         not with W73/W75/W76/Q24/Q67       \$101       \$101         QA9 Half-sided step rear (for trailer hitch)       \$101       \$101         must have Q24/QA2; not with W73/W75/W76       \$10       -\$110       -\$110         must have R92; not with R87       \$9       \$0       \$0 </td <td></td> <td>·</td> <td></td> <td></td>		·		
K51       Misfueling prevention for Diesel       \$49       \$49         K52       DEF fluid filler cap - lockable       \$27       \$27         L13       Fog lamp with cornering light function       \$199       \$199         LB9       Illuminated front exits       \$151       \$151         LC4       Comfort overhead control panel       \$93       \$93         M20       Speed limitation 65 mph       \$60       \$60         not with MD3       \$60       \$60         MD3       Top speed limitation 75 mph       \$60       \$60         not with M20       \$60       \$60         N62       Front engine bracket for additional alternator       \$467       \$467         not with HK4/N63       \$60       \$467       \$467         N63       Front engine bracket for auxiliary A/C compressor       \$467       \$467         not with HK4/N62       \$186       \$186         QA2       Trailer cross member 7,500 lbs capacity       \$186       \$186         not with W73/W75/W76/Q24/Q67       \$101       \$101         QA9       Half-sided step rear (for trailer hitch)       \$101       \$101         must have R92; not with R87       \$2       \$2       \$2         R92       Spar			· ·	
K52       DEF fluid filler cap - lockable       \$27       \$27         L13       Fog lamp with cornering light function       \$199       \$199         LB9       Illuminated front exits       \$151       \$151         LC4       Comfort overhead control panel       \$93       \$93         M20       Speed limitation 65 mph       \$60       \$60         not with MD3       \$60       \$60         MD3       Top speed limitation 75 mph       \$60       \$60         not with M20       \$467       \$467         N62       Front engine bracket for additional alternator       \$467       \$467         not with HK4/N63       \$70       \$467       \$467         N63       Front engine bracket for auxiliary A/C compressor       \$467       \$467         not with HK4/N62       \$186       \$186         QA2       Trailer cross member 7,500 lbs capacity       \$186       \$186         not with W73/W75/W76/Q24/Q67       \$101       \$101         QA9       Half-sided step rear (for trailer hitch)       \$101       \$101         must have R92; not with R87       \$2       \$2       \$2       \$2       \$2       \$3       \$3         R92       Spare tire carrier deletion       \$0			· ·	•
L13       Fog lamp with cornering light function       \$199       \$199         LB9       Illuminated front exits       \$151       \$151         LC4       Comfort overhead control panel       \$93       \$93         M20       Speed limitation 65 mph       \$60       \$60         not with MD3       \$60       \$60         MD3       Top speed limitation 75 mph       \$60       \$60         not with M20       \$60       \$467       \$467         N62       Front engine bracket for additional alternator       \$467       \$467         not with HK4/N63       \$70       \$467       \$467         N63       Front engine bracket for auxiliary A/C compressor       \$467       \$467         not with HK4/N62       \$186       \$186         QA2       Trailer cross member 7,500 lbs capacity       \$186       \$186         not with W73/W75/W76/Q24/Q67       \$101       \$101         QA9       Half-sided step rear (for trailer hitch)       \$101       \$101         must have R92; not with R87       \$2       \$2       \$2       \$2       \$2       \$2       \$3       \$3         R92       Spare tire carrier deletion       \$0       \$0       \$0       \$0       \$0 <tr< td=""><td></td><td></td><td>· ·</td><td></td></tr<>			· ·	
LB9       Illuminated front exits       \$151       \$151         LC4       Comfort overhead control panel       \$93       \$93         M20       Speed limitation 65 mph       \$60       \$60         not with MD3       \$60       \$60         MD3       Top speed limitation 75 mph       \$60       \$60         not with M20       \$60       \$60         N62       Front engine bracket for additional alternator       \$467       \$467         not with HK4/N63       \$186       \$467         N63       Front engine bracket for auxiliary A/C compressor       \$467       \$467         not with HK4/N62       \$186       \$186         QA2       Trailer cross member 7,500 lbs capacity       \$186       \$186         not with W73/W75/W76/Q24/Q67       \$101       \$101         QA9       Half-sided step rear (for trailer hitch)       \$101       \$101         must have Q24/QA2; not with W73/W75/W76       \$110       -\$110       -\$110         must have R92; not with R87       \$2       \$2       \$2       \$2       \$3       \$3         R92       Spare tire carrier deletion       \$0       \$0       \$0         must have R91; not with R65       \$81       \$81       \$81 </td <td></td> <td>·</td> <td>· ·</td> <td></td>		·	· ·	
LC4       Comfort overhead control panel       \$93       \$93         M20       Speed limitation 65 mph       \$60       \$60         MD3       Top speed limitation 75 mph       \$60       \$60         N62       Front engine bracket for additional alternator       \$467       \$467         N63       Front engine bracket for auxiliary A/C compressor       \$467       \$467         N63       Front engine bracket for auxiliary A/C compressor       \$467       \$467         N64       N64       \$186       \$186         N65       N60       \$186       \$186         N61       Front engine bracket for auxiliary A/C compressor       \$467       \$467         N62       Trailer cross member 7,500 lbs capacity       \$186       \$186         N63       Pront engine bracket for auxiliary A/C compressor       \$467       \$467         N64       \$186       \$186       \$186         N63       Front engine bracket for auxiliary A/C compressor       \$467       \$467         N64       \$186       \$186       \$186         N63       Front engine bracket for auxiliary A/C compressor       \$467       \$467         N64       Trailer cross member 7,500 lbs capacity       \$186       \$186         N63 </td <td></td> <td></td> <td>· ·</td> <td></td>			· ·	
M20 Speed limitation 65 mph       \$60       \$60         not with MD3       \$60       \$60         MD3 Top speed limitation 75 mph       \$60       \$60         not with M20       \$467       \$467         N62 Front engine bracket for additional alternator       \$467       \$467         not with HK4/N63       \$186       \$186         N63 Front engine bracket for auxiliary A/C compressor       \$467       \$467         not with HK4/N62       \$186       \$186         QA2 Trailer cross member 7,500 lbs capacity       \$186       \$186         not with W73/W75/W76/Q24/Q67       \$101       \$101         QA9 Half-sided step rear (for trailer hitch)       \$101       \$101         must have Q24/QA2; not with W73/W75/W76       \$10       -\$110         R91 Spare tire deletion       -\$110       -\$110         must have R92; not with R87       \$0       \$0         R92 Spare tire carrier deletion       \$0       \$0         must have R91; not with R65       \$81       \$81         R98 Rims painted jet black       \$81       \$81			· ·	
not with MD3         MD3 Top speed limitation 75 mph       \$60       \$60         not with M20         N62 Front engine bracket for additional alternator       \$467       \$467         not with HK4/N63       \$467       \$467         N63 Front engine bracket for auxiliary A/C compressor       \$467       \$467         not with HK4/N62       \$186       \$186         QA2 Trailer cross member 7,500 lbs capacity       \$186       \$186         not with W73/W75/W76/Q24/Q67       \$101       \$101         QA9 Half-sided step rear (for trailer hitch)       \$101       \$101         must have Q24/QA2; not with W73/W75/W76       \$101       \$110         R91 Spare tire deletion       -\$110       -\$110         must have R92; not with R87       \$0       \$0         R92 Spare tire carrier deletion       \$0       \$0         must have R91; not with R65       \$81       \$81         R98 Rims painted jet black       \$81       \$81		·		
MD3 Top speed limitation 75 mph  not with M20  N62 Front engine bracket for additional alternator  not with HK4/N63  N63 Front engine bracket for auxiliary A/C compressor  not with HK4/N62  QA2 Trailer cross member 7,500 lbs capacity  not with W73/W75/W76/Q24/Q67  QA9 Half-sided step rear (for trailer hitch)  must have Q24/QA2; not with W73/W75/W76  R91 Spare tire deletion  must have R92; not with R87  R92 Spare tire carrier deletion  must have R91; not with R65  R98 Rims painted jet black  \$ \$60 \$ \$60  \$ \$60  \$ \$60  \$ \$467  \$ \$	M20		\$60	\$60
not with M20  N62 Front engine bracket for additional alternator  not with HK4/N63  N63 Front engine bracket for auxiliary A/C compressor  not with HK4/N62  QA2 Trailer cross member 7,500 lbs capacity  not with W73/W75/W76/Q24/Q67  QA9 Half-sided step rear (for trailer hitch)  must have Q24/QA2; not with W73/W75/W76  R91 Spare tire deletion  must have R92; not with R87  R92 Spare tire carrier deletion  must have R91; not with R65  R98 Rims painted jet black  \$467				
N62 Front engine bracket for additional alternator  not with HK4/N63  N63 Front engine bracket for auxiliary A/C compressor  not with HK4/N62  QA2 Trailer cross member 7,500 lbs capacity  not with W73/W75/W76/Q24/Q67  QA9 Half-sided step rear (for trailer hitch)  must have Q24/QA2; not with W73/W75/W76  R91 Spare tire deletion  must have R92; not with R87  R92 Spare tire carrier deletion  must have R91; not with R65  R98 Rims painted jet black  \$467  \$	MD3		\$60	\$60
not with HK4/N63  N63 Front engine bracket for auxiliary A/C compressor \$467 \$467  not with HK4/N62  QA2 Trailer cross member 7,500 lbs capacity \$186 \$186  not with W73/W75/W76/Q24/Q67  QA9 Half-sided step rear (for trailer hitch) \$101 \$101  must have Q24/QA2; not with W73/W75/W76  R91 Spare tire deletion -\$110 -\$110  must have R92; not with R87  R92 Spare tire carrier deletion \$0 \$0  must have R91; not with R65  R98 Rims painted jet black \$81 \$81				
N63 Front engine bracket for auxiliary A/C compressor  not with HK4/N62  QA2 Trailer cross member 7,500 lbs capacity  not with W73/W75/W76/Q24/Q67  QA9 Half-sided step rear (for trailer hitch)  must have Q24/QA2; not with W73/W75/W76  R91 Spare tire deletion  must have R92; not with R87  R92 Spare tire carrier deletion  must have R91; not with R65  R98 Rims painted jet black  \$467  \$467  \$467  \$467  \$467  \$467  \$467  \$467  \$467  \$467  \$467  \$186  \$186  \$180  \$101  \$101  \$101  \$101  \$101  \$101  \$200  \$300  \$400	N62		\$467	\$467
not with HK4/N62       \$186       \$186         QA2 Trailer cross member 7,500 lbs capacity       \$186       \$186         not with W73/W75/W76/Q24/Q67       \$101       \$101         QA9 Half-sided step rear (for trailer hitch)       \$101       \$101         must have Q24/QA2; not with W73/W75/W76       \$10       -\$110         R91 Spare tire deletion       -\$110       -\$110         must have R92; not with R87       \$0       \$0         R92 Spare tire carrier deletion       \$0       \$0         must have R91; not with R65       \$81       \$81         R98 Rims painted jet black       \$81       \$81				
QA2       Trailer cross member 7,500 lbs capacity       \$186       \$186         not with W73/W75/W76/Q24/Q67       \$101       \$101         QA9       Half-sided step rear (for trailer hitch)       \$101       \$101         must have Q24/QA2; not with W73/W75/W76       -\$110       -\$110         R91       Spare tire deletion       -\$110       -\$110         must have R92; not with R87       \$0       \$0         R92       Spare tire carrier deletion       \$0       \$0         must have R91; not with R65       \$81       \$81         R98       Rims painted jet black       \$81       \$81	N63		\$467	\$467
not with W73/W75/W76/Q24/Q67         QA9 Half-sided step rear (for trailer hitch)       \$101       \$101         must have Q24/QA2; not with W73/W75/W76         R91 Spare tire deletion       -\$110       -\$110         must have R92; not with R87         R92 Spare tire carrier deletion       \$0       \$0         must have R91; not with R65         R98 Rims painted jet black       \$81       \$81		·		
QA9 Half-sided step rear (for trailer hitch) \$101 \$101  must have Q24/QA2; not with W73/W75/W76  R91 Spare tire deletion -\$110 -\$110  must have R92; not with R87  R92 Spare tire carrier deletion \$0 \$0  must have R91; not with R65  R98 Rims painted jet black \$81 \$81	QA2		\$186	\$186
must have Q24/QA2; not with W73/W75/W76           R91 Spare tire deletion         -\$110         -\$110           must have R92; not with R87           R92 Spare tire carrier deletion         \$0         \$0           must have R91; not with R65           R98 Rims painted jet black         \$81         \$81				
R91 Spare tire deletion -\$110 -\$110  must have R92; not with R87  R92 Spare tire carrier deletion \$0 \$0  must have R91; not with R65  R98 Rims painted jet black \$81	QA9		\$101	\$101
must have R92; not with R87  R92 Spare tire carrier deletion \$0 \$0  must have R91; not with R65  R98 Rims painted jet black \$81		must have Q24/QA2; not with W73/W75/W76		
R92 Spare tire carrier deletion \$0 \$0  must have R91; not with R65  R98 Rims painted jet black \$81 \$81	R91	Spare tire deletion	-\$110	-\$110
must have R91; not with R65  R98 Rims painted jet black \$81 \$81		must have R92; not with R87		
must have R91; not with R65  R98 Rims painted jet black \$81 \$81	R92	Spare tire carrier deletion	\$0	\$0
R98 Rims painted jet black \$81 \$81		·		
	R98		\$81	\$81

		144" 4C	170" 4C
		M3CV44	M3CV74
		907.643	907.645
RF1	Tire brand Continental	\$0	\$0
	must have RM1 + RM9	Ţ Ţ	ΨO
RF8	Tire brand Michelin	\$0	\$0
	must have RM9; not with RM1	Ţ.	ΨS
RH0	Tire brand Kumho	\$0	\$0
	must have RM9; not with RM1	Ţ.	Ψū
RM1	M+S winter tires	\$169	\$169
	must have RF1/RD9; not with RF8/RH0/X31	<b>7</b> 200	Ψ200
RM2	Rims painted arctic white	\$81	\$81
	not with R98/RL5	702	<del>7</del> 02
RM9	Specially requested tires	\$101	\$101
	must have RF1/RF8/RH0; not with RD9	<b>V101</b>	<b>V</b> 101
S28	Armrest, driver and passenger door	\$51	\$51
T12	Sliding door two stage opening	\$82	\$82
	not with T55	7-5-	702
T50	Electric closing assist right sliding door	\$335	\$335
	must have D03; not with T55/T93	7000	<del>, , , , , , , , , , , , , , , , , , , </del>
T55	Electric sliding door right	\$831	\$831
133	must have D03 + (FY7+T16); not with T12/T50	3031	, 7631
T57		¢1.071	¢1 071
137	Electric sliding step	\$1,071	\$1,071
TCO	must have D03 + ED5; not with T93	¢420	¢120
T60	Opening limiter electrically operated sliding door	\$120	\$120
	must have T55		
T75	Door-mounted assist handles, driver & passenger	\$59	\$59
T85	Assist handle, left rear door	\$32	\$32
T86	Assist handles, right rear door	\$32	\$32
V43	Wood floor with 6 D-rings	\$422	\$422
	not with P93/V93/VL4/VK8/C07; standard with D93/H13/V24/V52,	/VC5/VV2/ZE6	
V85	Cigarette lighter & ash cup, front	\$39	\$39
VC5	Door sill - protective edge	\$71	\$71
	must have V43/X66; not with T19/T93/VK8/VV2/V93/C07		
VK8	Floor covering, plastic	\$370	\$370
	not with V43/P93/T19/T93/V52/VC5/X66	·	· · · · · · · · · · · · · · · · · · ·
W54	Rear doors, opening to side wall	\$360	\$360
	90 Degree fixation point- Rear Doors	\$80	\$80
<del>                                     </del>	SoP and Plausibility TBD	φοσ	, , , , , , , , , , , , , , , , , , ,
\\\/73	Bumper step, rear, grey	\$187	\$187
VV / 3	not with Q24/W75/W76	Ş107	Ş107
\\/75	Step, wide, at rear end	¢200	¢200
VV / 5		\$308	\$308
14/76	not with JB6/JB7/Q24/QA9; must have R91+R92		4504
W /6	Bumper step, rear, spring-loaded	-	\$601
	must have R91+R92; not with JB6/JB7/X30/Q24		
W78	Heated rear window(s) w/ washers/wipers	\$335	\$335
	Must have H22+VA7 / if D51 must have F61; not with W61		•
X90	Deletion of Sprinter badge, left rear door	\$0	\$0
X93	Deletion of model badge, right rear door	\$0	\$0
XM4	Acoustic package	\$87	\$87
	standard with CO2/CO3		
Y10	First-aid kit	\$27	\$27
Y26	Wheel chocks	\$38	\$38
Y45	Emergency flashlight	\$27	\$27
Y68	Paint preservative	\$187	\$212
Y69	Surface protection for stock vehicles	\$315	\$315
YK3	Cargo straps, D-rings	\$81	\$81
	Ca. 20 20 40 2 11162	AO.T	Ų01

### 3500 CREW VAN - 4cyl Diesel

Packages

144" 4C	170" 4C
M3CV44	M3CV74
907.643	907.645

C00	Comfort Package	\$300	\$300		
LC4	Comfort overhead control panel	Х	Х		
SE4	Lumbar support, co-driver's seat	Х	Х		
SE5	Lumbar support, driver's seat	Х	X		
SK0	Comfort head restraint, driver	Х	X		
SK1	Comfort head restraint, co-driver	Х	Х		
S28	Armrest, driver and passenger door	Х	Х		
must	nust have COS OR X68; CA/CC only: not with S23				

COS	Comfort Package (Seat addition)	\$381	\$381
SB1	Comfort driver's seat	X	X
SB2	Comfort passenger seat	Х	Х
must	must have COO		

X68	Comfort Plus Package	\$1,923	\$1,923
H15	Heated front passenger seat	X	X
H16	Heated driver's seat	Х	Х
SF1	Driver's seat electrically adjustable	Х	Х
SF2	Co-driver's seat electrically adjustable	Х	Х
must	must have COO and VF4 OR VF6, CA/CC only: not with S23		

C01	Driver Convenience Package	\$760	\$760
E46	12 V power outlet, driver seat base	X	X
F64	Electrically folding exterior mirrors	X	X
FJ1	Hinged lid for storage compartment	Х	X
FJ5	Hinged Lid for Storage Compartments left and right	Х	X
FZ9	Keys, two additional masters	Х	X
JA7	Blind Spot Assist	X	X
JW8	Attention Assist	X	X

C02	Premium Package	\$983	\$983
CL3	Leather steering wheel	X	X
E3M	MBUX Multimedia System with 7" touchscreen	X	Х
FM3	Wet Wiper System	Х	Х
JB4	Active Lane Keeping Assist	X	X
JK5	Instrument cluster with color display	X	X
Ordering availability restricted, see NetStar for availability and restrictions   must have JF1 + XM4; must			

Ordering availability restricted, see NetStar for availability and restrictions | must have JF1 + XM4; must choose FR8/JB7/JB6

CA2	C02 in combination with C03	\$604	\$604
CL3	Leather steering wheel	X	Х
FM3	Wet Wiper System	X	Х
JB4	Active Lane Keeping Assist	X	Х
JK5	Instrument cluster with color display	X	X
Ordering availability restricted, see NetStar for availability and restrctions must have CO3 + JF1			

#### 3500 CREW VAN - 4cyl Diesel

144" 4C	170" 4C
M3CV44	M3CV74
907.643	907.645

C03	Premium Plus Package	\$1,793	\$1,793
E1B	Tray for smartphones incl. wireless charging	X	Х
	Navigation	Х	Х
EY2	Intelligent navigation	X	Х
E4M	MBUX Multimedia System with 10.25" touchscreen	Х	Х
EX9	Free map data updates for 3 years	Х	Х
H1I	Front-to-rear outlet in instrument panel	Х	Х
JA9	Traffic Sign Assist	X	X
XM4	Acoustic package	X	Х
must	must have (CA2+(JB7/JB6/JB8)) OR (JB4+JK5+FM3+(JB7/JB6/JB8)); not with FR8 and CO2		

X67	Chrome Grille Package	\$290	\$290
CN2	Radiator grille frame in vehicle color	Х	X
FK3	Chrome plated radiator grille (MB only)	Х	Х
no res	no restrictions		

X13	Exterior Lighting Package	\$1,608	\$1,608
L13	Fog lamp with cornering light function	X	X
L22	Partial LED tail lights	Х	Х
LA1	High beam assist	Х	Х
LG7	LED high performance headlamps	Х	Х
no res	no restrictions		

X72	Crew Van Comfort Package	\$220	\$220	
S31	Convenice head restraints for pass. compartment	Х	X	
UY1	3-seater comfort bench rear, 1st row (narrow)	Х	Х	
can h	can have VF4/VF6 only			

144" 6C	170" 6C
M3CV46	M3CV76
907.653	907.655

		507.000	567.666
Engin	e		
	Engine/7-Speed Trans.	S	S
ED4	AGM battery 12V 92 AH 850 A	S	S
_	Automatic transmission, 7G-tronic	S	S
-	ULEV emission	S	S
		ļ	
	3.0L V6 turbo diesel engine	S	S
	Alternator 14 V/220 A	S	S
	choose while ordering	4 -	4 -
_	Dual Rear Wheel	\$0	\$0
	Tires LT 215/85 R16	S	S
	5.5 J x 16 steel wheels	S	S
	Unspecified tire brand	S	S
X31	Super Single Tire	\$385	\$385
R9A	285/65 R 16 C super single tires	0	0
RS5	Steel wheels: 8.5Jx16 Rr; 6.5Jx16 Fr	0	0
RD9	Unspecified tire brand	0	0
RY2	Tire pressure monitoring sensors	0	0
Seatir	ng and Trim Packages		
X7S	Standard Rear Seats	S	S
	3-seater bench rear, 1st row (narrow)	S	S
	Wall-side armrest	S	S
U75	Aisle-side armrest	S	S
	ave VF7/VF6 only; with X68 must have VF6	<u> </u>	<u> </u>
X2V	Standard Trim Crew Van Package	S	S
	Half height load compartment trim	S	S
V25		S	
	Wheel house covering	<u> </u>	S
V43	Wood floor with 6 D-rings	S	S
	production only		
Equip		T	
-	Axle ratio 4.182	S	S
	Active Brake Assist	S	S
	Hold Function	S	S
C6L	Multifunction steering wheel	S	S
CB8	Stabilization Level II	S	S
CL1	Adjustable steering wheel (angle)	S	S
D03	High roof	0	S
D93	Omission bulkhead	S	S
E07	Hill Start Assist	S	S
E10	Standard radio	S	S
E1U	USB-C socket, 5 V	S	S
E30	Starter battery disconnect	S	S
E3J	Pre-installation for switch panel	S	S
E40	Trailer hitch prep. wiring	S	S
ED8	Preinstallation PSM	S	S
EE5	Ultracapacitor discharge module	S	S
EK1	Body Builder Connector	S	S
ESO	Jump start terminal	S	S
EW6	Pre-installation for Mercedes me Remote Services	S	S
EY5	Emergency Call System	S	S
EY6	Breakdown management	S	S
F43	Laminated glass rear	S	S
F68	Heated & electrically adjustable exterior mirrors	S	S
FF3	Cupholder rear compartment	S	S
FF5	Shelf above windshield	S	S
FC0	Cupholder front	S	S
FG8			
FG8 FI1	Remote key (315 mhz) w/central locking	S	S

		144" 6C	170" 6C	
		M3CV46	M3CV76	
		907.653	907.655	
ED2	Description and the second second second second			
FR3	Rear view camera (rear-view mirror display)	S	S	
H00	Warm/cool air duct to rear compartment	S	S	
H21	Windshield with filter band	S	S	
H22	Rear window defroster	S	S	
HH2	Heater, auxiliary electric hot air	S	S	
HH9	Air Condition, Front	S	S	
IH7	Head Unit, North America	S	S	
J11	Speedometer, miles and km/h	S	S	
J55	Seat belt warning for co-driver seat	S	S	
J58	Seat belt reminder driver	S	S	
J65 JA8	Outside temperature gauge Crosswind Assist	S	S	
	Communication module (LTE) for dig. services	S	S	
JH3 JH3	Service interval 20.000 miles	S	S S	
K56	Red diesel filler cap	S S	S	
K60		S	S	
KB7	Exhaust straight to rear  24.5 gallon fuel tank	S	S	
KL1	Aux fuel sending unit w/ fuel tap	S	S	
KL5	Fuel filter with water separator	S	S	
KP6	3rd generation SCR emission control system	S	S	
L94	Parking lights deletion	S	S	
LA2	Headlight assistant	S	S	
LB5	3rd brake light	S	S	
MS1	Cruise control	S	S	
P47	Front mudflaps	S	S	
P48	Rear mudflaps	S	S	
Q11	Longitudinal member reinforcement	S	S	
R65	Spare tire bracket below frame	S	S	
	Spare tire	S	S	
RM0	All-season tires	S	S	
S02	Standard driver seat	S	S	
S04	Standard front passenger seat	S	S	
S22	Armrest for driver's seat	S	S	
S25	Armrest for front passenger seat	S	S	
SA5	Front airbag, driver	S	S	
SA6	Front airbag, passenger	S	S	
SH1	Thorax-pelvis sidebag, driver	S	S	
SH2	Thorax-pelvis sidebag, co-driver	S	S	
SH9	Airbag, driver/passenger window	S	S	
SK2	Seat occupancy sensor, driver's seat	S	S	
T16	Sliding door, passenger side	S	S	
T74	Assist handle, B-pillar	S	S	
U22	Pre-inst. for seating configuration Crew Van	S	S	
V36	Roof trim	S	S	
V40	Floor anchors for rear seat bench	S	S	
VA7	Storage compart. w/ net in rear doors	S	S	
W16	2nd row, fixed window, driver side	S	S	
W17	2nd row, fixed window, passenger side	S	S	
W61	Windows in rear doors	S	S	
W70	Black tinting (90%) for rear windows	S	S	
XB3	GVWR 9,990 lbs. / 4,531 kg	S	S	
Y43	Jack, hydraulic	S	S	

ASO Front axile reinforced ASO Front axile reinforce			144" 6C	170" 6C
907.653   907.655				
ASO   Front axle reinforced   S346   S346   AP2   Addtl. bar for driveshaft & exhaust extension   S59   S69   S69   AP2   Axle ratio 3.923   S0   S0   S0   Not with AR3   Axle ratio 3.923   S0   S0   Not with AR3   S187   S187   Not with AR3   S187   S187   Not with AR3   S187				
AP2         Addtl. bar for driveshaft & exhaust extension         \$69         \$69           AR2         Akle ratio 3.923         \$0         \$0           AR2         Akle ratio 3.923         \$0         \$0           not with AR3         \$0         \$0           B01         ESP for increased Center of Gravity above 39.4"         \$0         \$0           C72         Bumpers front/rear primed         \$268         \$268         \$268           C72         Bumpers front/rear primed         \$268         \$268         \$268           Most for Gravity for the compartment         \$260         \$268         \$268           Mount for Collegal Archived for C			907.653	907.655
AR2 Axie ratio 3.923	A50	Front axle reinforced	\$346	\$346
	AP2	Addtl. bar for driveshaft & exhaust extension	\$69	\$69
SSP for increased Center of Gravity above 39.4"   SSP	AR2	Axle ratio 3.923	\$0	\$0
must have CB4/CB8/X30; not with RHO/CB7         \$268         \$268           C72         Bumpers front/rear primed         \$268         \$268           must have CR2/K26, not with CM0         \$187         \$187           C13         Leather steering wheel         \$187         \$187           must have (CO2/E3M)/CO3 + (ET4/MS1)         \$587         \$587           CMD         Primed indertallic front & rear bumper         \$586         \$586           Most fight roof         \$2,900         \$           D33         High roof         \$2,900         \$           D33         Mounting rails for roof rack         \$3300         \$3300           B18         Tray for smartphones incl. wireless charging         \$156         \$156           must have CO2/E3M + H11         \$181         \$187         \$728         \$728           E18         Tray for smartphones incl. wireless charging         \$156         \$156         \$156           must have CO2/E3M, H11         \$182         \$728         \$728         \$728           E18         Tray for smartphones incl. wirth C03         \$150         \$50         \$50         \$50           E18         Tray for said fill said fill said fill said fill said said said said said said said said		not with AR3		
C72         Bumpers front/rear primed must have CN2/K67, not with CM0         \$268         \$268         \$268           C13         Leather steering wheel         \$187         \$187           C13         Leather steering wheel         \$187         \$187           CMD         Painted metallic front & rear bumper must have (CO2/K67) (LAT/CO1) + (IB6/IB7) + (7755/9197/9775)         \$587         \$587           CMD         Primed side moldings         \$364         \$364         \$364         \$364           D33         Mounting rails for roof rack         \$300         \$300         \$300         \$300           E1B         Tray for smartphones incl. wireless charging must have CO2/E3M + H11         ***         ***         \$156         \$156         \$156           E1E         Navigation         \$728         \$728         \$728         \$728         \$728           must have CO2/E3M, H11         ***         ***         ***         \$55         \$255         \$255         \$255         \$255         \$228         \$728         \$728         \$728         \$728         \$728         \$728         \$728         \$728         \$728         \$728         \$728         \$728         \$728         \$728         \$728         \$728         \$728         \$728         \$728	B01	ESP for increased Center of Gravity above 39.4"	-	\$0
must have CN2/X67, not with CM0   \$187   \$187   \$187   must have (CO2/EMM/CO3+ (ET4/MS1)   \$180   \$187   \$188   \$18		must have CB4/CB8/X30; not with RH0/CB7	•	
CL3   Leather steering wheel	C72	Bumpers front/rear primed	\$268	\$268
CL3   Leather steering wheel				
must have (CO2/E3M)/CO3 + (ET4/MS1)         \$587         \$587           CMD         Painted metallic front & rear bumper         \$587         \$587           must have (CO2/EAS) + (IA/CO1) + (IB6/IB7) + (7755/9197/9775)         \$364         \$364           CMP         Primed side moldings         \$364         \$360           D33         Mounting rails for roof rack         \$300         \$300           E1B         Tray for smartphones incl. wireless charging         \$156         \$156           must have CO2/E3M + H11         ****         ****           E1E         Navigation         \$728         \$728           must have CO2/E3M, not with CO3         ****         ****           E1S         Sirius XM, satellite radio         \$255         \$255           must have CO2/E3M, not with CO3         ***         ***           E1S         Sirius XM, satellite radio         \$255         \$255           must have CO2/E3M, not with CO3         ***         ***           E1S         Additional Fuses (40/80/150/100 Ampere)         \$50         \$50           SoP and Plausibility TBD         ***         ***           E21         Additional Fuses (40/80/150/100 Ampere)         \$50         \$50           SoP and Plausibility TBD         **	CL3		\$187	\$187
CMO			,	
must have (CN2/X67) + (JA7/C01) + (JB6/JB7) + (7755/9197/9775)         \$364         \$364           CM9 Primed side moldings         \$364         \$364         \$364           D31 High roof         \$2,900         \$           D13 Mounting rails for roof rack         \$300         \$300         \$300           E1B Tray for smartphones incl. wireless charging         \$156         \$156         \$156           must hove CO2/E3M, not with C03         \$728         \$728         \$728           E1S Sirius XM, satellite radio         \$255         \$255         \$255           must hove C02/E3M, not with C03         \$50         \$50         \$50           E1R Additional Fuses (40/80/80/100 Ampere)         \$50         \$50         \$50           SP and Plausibility TBD         \$29         \$29         \$29           E2A Access point for BB special signals in cockpit         \$29         \$29           E2A Access point for BB special base         \$248         \$248           Must have E36; not with E2M; CHS production only         \$110         \$110           E36 Cutoff relay for additional battery         \$110         \$110         \$110           E37 Cutoff relay for additional battery         \$110         \$110         \$110           E38 E38 E38         \$248         \$	CM0		\$587	\$587
CM9         Primed side moldings         \$364         \$364           D03         High roof         \$2,900         \$           D13         Mounting rails for roof rack         \$300         \$300           E1B         Tray for smartphones incl. wireless charging must hove CO2/E3M + H11         ***           E1E         Navigation         \$728         \$728           must hove CO2/E3M, not with C03         ***         ***           E1S         Sirius XM, satellite radio         \$255         \$255           must hove C02/E3M/C03         ***         ***           E1R         Additional Fuses (40/80/150/100 Ampere)         \$50         \$50           SoP and Plausibility TBD         ***         ***           E1Y         Additional Fuses (40/80/80/100 Ampere)         \$50         \$50           SoP and Plausibility TBD         ***         ***         \$50         \$50           E2A         Access point for BB special signals in cockpit         \$29			700.	700
D03	CM9		\$364	\$364
D13         Mounting rails for roof rack         \$300         \$300           E1B         Tray for smartphones incl. wireless charging         \$156         \$156           must have C02/E3M, H1I         \$728         \$728           E1E         Navigation         \$728         \$728           must have C02/E3M, not with C03         \$255         \$255           E1S         Sirius XM, satellite radio         \$255         \$255           must have C02/E3M/C03         \$50         \$50           E1R         Additional Fuses (40/80/150/100 Ampere)         \$50         \$50           SoP and Plausibility TBD         \$50         \$50           E2A         Access point for BB special signals in cockpit         \$29         \$29           E2A         Access point for BB special signals in cockpit         \$29         \$29           E2I         Additional battery, co-driver seat base         \$248         \$248           Must have E36; not with E2M; CHS production only         \$310         \$110           E36         Cutoff relay for additional battery         \$110         \$110           Standard with E2M; CHS production only         \$310         \$110           E3M         MBUX MUX Multimedia system with 7" touchscreen         \$474         \$474      <				,
### E1B Tray for smartphones incl. wireless charging		~		_
### ### ### ### ### ### ### ### ### ##	-			•
### ST28   \$728   \$728   ### ST28   ### ST25			<b>Ÿ</b> 130	<b>\$130</b>
### Birling ### Bi	F1F		\$728	\$728
E1S         Sirius XM, satellite radio         \$255         \$255           must have COZ/E3M/CO3         \$50         \$50           E1R         Additional Fuses (40/80/150/100 Ampere)         \$50         \$50           SOP and Plausibility TBD         \$50         \$50           E1Y         Additional Fuses (40/80/80/100 Ampere)         \$50         \$50           SOP and Plausibility TBD         \$50         \$50           E2A         Access point for B8 special signals in cockpit         \$29         \$29           E2A         Access point for B8 special signals in cockpit         \$29         \$29           E2I         Additional battery, co-driver seat base         \$248         \$248           Must have E36, not with E2M; CHS production only         \$210         \$248         \$248           Must have E36, not with E2M; CHS production only         \$110         \$1			7/20	Ų, 20
### Bush ###	F1S		\$255	\$255
E1R         Additional Fuses (40/80/150/100 Ampere)         \$50         \$50           SOP and Plausibility TBD         \$50         \$50           E1Y         Additional Fuses (40/80/80/100 Ampere)         \$50         \$50           SOP and Plausibility TBD         \$50         \$50           E2A         Access point for BB special signals in cockpit         \$29         \$29           E2I         Additional battery, co-driver seat base         \$248         \$248           Must have E36; not with E2M; CHS production only         \$110         \$110           E36         Cutoff relay for additional battery         \$110         \$110           Standard with E2I/E2M         \$110         \$110         \$110           E3M         MBUX Multimedia System with 7" touchscreen         \$474         \$474           not with C02/C03; must have JK5+(JB7/JB6/JB8/FR8)         \$58         \$58           E5M         Extension of PSM standard contact         \$58         \$58           E5D         Parametric special module (PSM)         \$317         \$317           not with ED8         \$125         \$125         \$125           E63         15 V socket         \$125         \$125           E52         12 V power outlet, rear compartment         \$92         \$9	-13		7233	7233
SoP and Plausibility TBD	E1D		\$50	\$50
E1Y         Additional Fuses (40/80/80/100 Ampere)         \$50         \$50           SoP and Plausibility TBD         \$29         \$29           E2A         Access point for BB special signals in cockpit         \$29         \$29           E2I         Additional battery, co-driver seat base         \$248         \$248           Must have E36; not with E2M; CHS production only         \$110         \$110           E36         Cutoff relay for additional battery         \$110         \$110           \$170         \$110         \$110         \$110           \$180         WILL Multimedia System with 7" touchscreen         \$474         \$474           \$181         \$110         \$110         \$110         \$110           \$183         MBUX Multimedia System with 7" touchscreen         \$474         \$474         \$474           \$263         must Mot CO2/CO3, sust have JKS+(JB7/JB6/JB8/FR8)         \$58<	LIK		\$30	\$30
SoP and Plausibility TBD           E2A         Access point for BB special signals in cockpit         \$29         \$29           E2I         Additional battery, co-driver seat base         \$248         \$248           Must have E36; not with E2M; CHS production only         \$110         \$110           S6         Cutoff relay for additional battery         \$110         \$110           S6         Sandard with E2I/E2M         \$110         \$110           E3M         MBUX Multimedia System with 7" touchscreen not with C02/C03; must have JK5+(JB7/JB6/JB8/FR8)         \$474         \$474           E5M         Extension of PSM standard contact         \$58         \$58           E5D         Parametric special module (PSM) \$317         \$317           not with ED8         \$125         \$125           E6D         Parametric special module (PSM) \$317         \$317           not with ED8         \$125         \$125           E6D         Parametric special module (PSM) \$317         \$317           not with ED8         \$212         \$22           E6D         Parametric special module (PSM) \$317         \$317           parametric special module (PSM) \$317         \$317         \$317           parametric special module (PSM) \$317         \$325         \$22         \$22 <td>E1V</td> <td></td> <td>\$50</td> <td>\$50</td>	E1V		\$50	\$50
E2A         Access point for BB special signals in cockpit         \$29         \$29           E2I         Additional battery, co-driver seat base         \$248         \$248           Must have E36; not with E2M; CHS production only         \$110         \$110           E36         Cutoff relay for additional battery         \$110         \$110           E3M MBUX Multimedia System with 7" touchscreen         \$474         \$474           not with C02/C03; must have JK5+(JB7/JB6/JB8/FR8)         \$58         \$58           E5M Extension of PSM standard contact         \$58         \$58           E5D Parametric special module (PSM)         \$317         \$317           not with ED8         \$125         \$125           EE3         15 V socket         \$125         \$125           E52         12 V power outlet, rear compartment         \$92         \$92           E55         Charging package, dashboard         \$82         \$82           E74         Active Distance Assist DISTRONIC         \$263         \$263           must have C02/C03/E3M; not with ZH4         \$218         \$218         \$218           F61         Interior rear view mirror         \$36         \$36         \$36           F61         Interior rear view mirror         \$36         \$36	ETI		<b>\$30</b>	\$30
E21       Additional battery, co-driver seat base       \$248       \$248         Must have E36; not with E2M; CHS production only       \$110       \$110         E36       Cutoff relay for additional battery       \$110       \$110         standard with E2I/EZM       E3M MBUX Multimedia System with 7" touchscreen not with C02/C03; must have JK5+(JB7/JB6/JB8/FR8)         E5M Extension of PSM standard contact       \$58       \$58         ED5 Parametric special module (PSM)       \$317       \$317         not with ED8       \$15 V socket       \$125       \$125         E52       12 V power outlet, rear compartment       \$92       \$92         E55       Charging package, dashboard       \$82       \$82         E74       Active Distance Assist DISTRONIC       \$263       \$263         must have C02/C03/E3M; not with ZH4       F49       Electrically heated windshield       \$218       \$218         no restrictions       F61       Interior rear view mirror       \$36       \$36         must have E3M/C02/C03       FF7         FF8       Overhead storage slot, front center       \$105       \$105         F11       Hinged lid for storage compartment       \$93       \$93         FR8       Rear view camera (head unit display	E2 A	•	\$20	\$20
Must have E36; not with E2M; CHS production only				•
E36         Cutoff relay for additional battery         \$110         \$110           standard with E2I/E2M         \$474         \$474           E3M         MBUX Multimedia System with 7" touchscreen         \$474         \$474           not with CO2/C03; must have JK5+(JB7/JB6/JB8/FR8)         \$58         \$58           E5M         Extension of PSM standard contact         \$58         \$58           EDS         Parametric special module (PSM)         \$317         \$317           not with ED8         \$115 V socket         \$125         \$125           E52         12 V power outlet, rear compartment         \$92         \$92           E55         Charging package, dashboard         \$82         \$82           E74         Active Distance Assist DISTRONIC         \$263         \$263           must have C02/C03/E3M; not with ZH4         \$218         \$218           F49         Electrically heated windshield         \$218         \$218           no restrictions         \$36         \$36           F61         Interior rear view mirror         \$36         \$36           must have E3M/C02/C03         \$44         \$81         \$81           FF9         Additional DIN-slot         \$81         \$81           FF8 <t< td=""><td>EZI</td><td></td><td><u> </u></td><td>Ş246</td></t<>	EZI		<u> </u>	Ş246
standard with E2I/E2M           E3M         MBUX Multimedia System with 7" touchscreen         \$474         \$474           not with C02/C03; must have JK5+(JB7/JB6/JB8/FR8)           E5M         Extension of PSM standard contact         \$58         \$58           EDS         Parametric special module (PSM)         \$317         \$317           not with ED8         \$15                 \$125         \$125           EE3         115 V socket         \$125         \$125         \$125           E5S         12 V power outlet, rear compartment         \$92         \$92           E5S         Charging package, dashboard         \$82         \$82           E5S         Charging package, dashboard         \$82         \$82           E74         Active Distance Assist DISTRONIC         \$263         \$263           must have C02/C03/E3M; not with ZH4         \$218         \$218           F49         Electrically heated windshield         \$218         \$218           no restrictions         \$36         \$36         \$36           F61         Interior rear view mirror         \$36         \$36           must have E3M/C02/C03         \$41         \$81         \$81           F69         Additional Dil-slot         \$81	F26		¢110	ć110
E3M         MBUX Multimedia System with 7" touchscreen         \$474         \$474           not with C02/C03; must have JK5+(JB7/JB6/JB8/FR8)         \$58         \$58           E5M         Extension of PSM standard contact         \$58         \$58           ED5         Parametric special module (PSM)         \$317         \$317           not with ED8         EE3         115 V socket         \$125         \$125           ES2         12 V power outlet, rear compartment         \$92         \$92           ES5         Charging package, dashboard         \$82         \$82           ES5         Charging package, dashboard         \$263         \$263           ES4         Charging package, dashboard         \$82         \$82           ES5         Charging package, dashboard         \$82         \$82           ES5         Charging package, dashboard         \$82         \$82           ES5         Charging package, dashboard         \$82         \$82           E84         Active Distance Assist DISTRONIC         \$82         \$82           E85         Charging package, dashboard         \$263         \$263           E74         Electrically heated windshield         \$121         \$121           FF         Must have E3M/C02	E30		\$110	\$110
	E21/4	•	¢474	6474
E5M         Extension of PSM standard contact         \$58         \$58           ED5         Parametric special module (PSM)         \$317         \$317           not with ED8         \$125         \$125           EE3         115 V socket         \$125         \$125           ES2         12 V power outlet, rear compartment         \$92         \$92           ES5         Charging package, dashboard         \$82         \$82           ET4         Active Distance Assist DISTRONIC         \$263         \$263           must have CO2/C03/E3M; not with ZH4         F49         Electrically heated windshield         \$218         \$218           no restrictions         F61         Interior rear view mirror         \$36         \$36           must have E3M/C02/C03         FE9         Additional DIN-slot         \$81         \$81           FF8         Overhead storage slot, front center         \$105         \$105           FJ1         Hinged lid for storage compartment         \$93         \$93           FR8         Rear view camera (head unit display)         \$336         \$336           must have C02/E3M; not with FR3/IB7/IB6/IB8           FY1         Security alarm w. interior motion sensor         \$584         \$584     <	ESIVI	·	\$474	\$474
ED5       Parametric special module (PSM)       \$317       \$317         not with ED8       \$125       \$125         EE3       115 V socket       \$125       \$125         ES2       12 V power outlet, rear compartment       \$92       \$92         ES5       Charging package, dashboard       \$82       \$82         ET4       Active Distance Assist DISTRONIC       \$263       \$263         must have CO2/C03/E3M; not with ZH4         F49       Electrically heated windshield       \$218       \$218         no restrictions         F61       Interior rear view mirror       \$36       \$36         must have E3M/C02/C03         FE9       Additional DIN-slot       \$81       \$81         F7       Overhead storage slot, front center       \$105       \$105         FJ1       Hinged lid for storage compartment       \$93       \$93         FR8       Rear view camera (head unit display)       \$336       \$336         must have C02/E3M; not with FR3/JB7/JB6/JB8         FY1       Security alarm w. interior motion sensor       \$584       \$584         must have LC4/C00         FY7       Optional 3-button keys       \$36       \$36         FZ9       Keys, two additi			ćro.	ć r o
	-			
EE3       115 V socket       \$125       \$125         ES2       12 V power outlet, rear compartment       \$92       \$92         ES5       Charging package, dashboard       \$82       \$82         ET4       Active Distance Assist DISTRONIC       \$263       \$263         must have CO2/CO3/E3M; not with ZH4         F49       Electrically heated windshield       \$218       \$218         no restrictions         F61       Interior rear view mirror       \$36       \$36         must have E3M/C02/C03       \$81       \$81         FE9       Additional DIN-slot       \$81       \$81         F78       Overhead storage slot, front center       \$105       \$105         FJ1       Hinged lid for storage compartment       \$93       \$93         FR8       Rear view camera (head unit display)       \$336       \$336         must have C02/E3M; not with FR3/JB7/JB6/JB8         FY1       Security alarm w. interior motion sensor       \$584       \$584         must have LC4/C00       \$121       \$121       \$121         FY7       Optional 3-button keys       \$36       \$36         FZ9       Keys, two additional masters       \$121       \$121         H01       Heat in	בטס		\$317	\$317
ES2         12 V power outlet, rear compartment         \$92         \$92           ES5         Charging package, dashboard         \$82         \$82           ET4         Active Distance Assist DISTRONIC         \$263         \$263           must have CO2/CO3/E3M; not with ZH4         F49         Electrically heated windshield         \$218         \$218           F49         Electrically heated windshield         \$218         \$218           no restrictions         F61         Interior rear view mirror         \$36         \$36           must have E3M/CO2/CO3         FF99         Additional DIN-slot         \$81         \$81           F80         Overhead storage slot, front center         \$105         \$105           FJ1         Hinged lid for storage compartment         \$93         \$93           FR8         Rear view camera (head unit display)         \$336         \$336           must have C02/E3M; not with FR3/JB7/JB6/JB8         FY1         Security alarm w. interior motion sensor         \$584         \$584           must have LC4/C00         FY7         Optional 3-button keys         \$36         \$36           FZ9         Keys, two additional masters         \$121         \$121 <t< td=""><td>FF2</td><td></td><td>6425</td><td>¢425</td></t<>	FF2		6425	¢425
ESS Charging package, dashboard \$82 \$82 ET4 Active Distance Assist DISTRONIC \$263 \$263  must have CO2/CO3/E3M; not with ZH4 F49 Electrically heated windshield \$218 \$218  no restrictions F61 Interior rear view mirror \$36 \$36  must have E3M/CO2/CO3 FE9 Additional DIN-slot \$81 \$81  FF8 Overhead storage slot, front center \$105 \$105  FJ1 Hinged lid for storage compartment \$93 \$93  FR8 Rear view camera (head unit display) \$336 \$336  must have CO2/E3M; not with FR3/JB7/JB6/JB8 FY1 Security alarm w. interior motion sensor \$584 \$584  must have LC4/CO0 FY7 Optional 3-button keys \$36 \$36  F29 Keys, two additional masters \$121 \$121 Ho1 Heat insulation, rear compartment \$156 \$156  must have V25/VA3/VA1/CO7/X66 HO4 Heat insulation, front compartment \$187 \$187			1	-
ET4 Active Distance Assist DISTRONIC  must have CO2/CO3/E3M; not with ZH4  F49 Electrically heated windshield  no restrictions  F61 Interior rear view mirror  \$36 \$36  must have E3M/CO2/CO3  FE9 Additional DIN-slot  FF8 Overhead storage slot, front center  \$105 \$105  FJ1 Hinged lid for storage compartment  \$93 \$93  FR8 Rear view camera (head unit display)  must have CO2/E3M; not with FR3/JB7/JB6/JB8  FY1 Security alarm w. interior motion sensor  must have LC4/CO0  FY7 Optional 3-button keys  \$36 \$36  \$36  \$36  \$36  \$36  \$36  \$36			-	-
must have CO2/CO3/E3M; not with ZH4  F49 Electrically heated windshield \$218 \$218  no restrictions  F61 Interior rear view mirror \$36 \$36  must have E3M/CO2/CO3  FE9 Additional DIN-slot \$81 \$81  FF8 Overhead storage slot, front center \$105 \$105  FJ1 Hinged lid for storage compartment \$93 \$93  FR8 Rear view camera (head unit display) \$336 \$336  must have CO2/E3M; not with FR3/JB7/JB6/JB8  FY1 Security alarm w. interior motion sensor \$584 \$584  must have LC4/CO0  FY7 Optional 3-button keys \$36 \$36  FZ9 Keys, two additional masters \$121 \$121  Ho1 Heat insulation, rear compartment \$156 \$156  must have V25/VA3/VA1/CO7/X66  HO4 Heat insulation, front compartment \$187 \$187				
F49 Electrically heated windshield  no restrictions  F61 Interior rear view mirror  must have E3M/C02/C03  FE9 Additional DIN-slot  F78 Overhead storage slot, front center  F19 Hinged lid for storage compartment  F80 Rear view camera (head unit display)  must have C02/E3M; not with FR3/JB7/JB6/JB8  F71 Security alarm w. interior motion sensor  F77 Optional 3-button keys  F78 Keys, two additional masters  F79 Keys, two additional masters  F19 Heat insulation, rear compartment  F10 Heat insulation, front compartment  F11 \$121  F12 \$137	E14		\$263	\$263
no restrictions  F61 Interior rear view mirror \$36 \$36 \$36 \$36 \$36 \$36 \$36 \$36 \$36 \$36	F 4 5		6242	6346
F61         Interior rear view mirror         \$36         \$36           must have E3M/C02/C03         \$81         \$81           FE9         Additional DIN-slot         \$81         \$81           FF8         Overhead storage slot, front center         \$105         \$105           FJ1         Hinged lid for storage compartment         \$93         \$93           FR8         Rear view camera (head unit display)         \$336         \$336           must have C02/E3M; not with FR3/JB7/JB6/JB8         \$584         \$584           FY1         Security alarm w. interior motion sensor         \$584         \$584           must have LC4/C00         \$36         \$36         \$36           FY7         Optional 3-button keys         \$36         \$36           FZ9         Keys, two additional masters         \$121         \$121           H01         Heat insulation, rear compartment         \$156         \$156           must have V25/VA3/VA1/C07/X66         \$187         \$187	F49		\$218	\$218
must have E3M/C02/C03  FE9 Additional DIN-slot \$81 \$81  FF8 Overhead storage slot, front center \$105 \$105  FJ1 Hinged lid for storage compartment \$93 \$93  FR8 Rear view camera (head unit display) \$336 \$336  must have C02/E3M; not with FR3/JB7/JB6/JB8  FY1 Security alarm w. interior motion sensor \$584 \$584  must have LC4/C00  FY7 Optional 3-button keys \$36 \$36  FZ9 Keys, two additional masters \$121 \$121  H01 Heat insulation, rear compartment \$156 \$156  must have V25/VA3/VA1/C07/X66  H04 Heat insulation, front compartment \$187 \$187			45.5	4-7
FE9         Additional DIN-slot         \$81         \$81           FF8         Overhead storage slot, front center         \$105         \$105           FJ1         Hinged lid for storage compartment         \$93         \$93           FR8         Rear view camera (head unit display)         \$336         \$336           must have CO2/E3M; not with FR3/JB7/JB6/JB8         \$584         \$584           FY1         Security alarm w. interior motion sensor         \$584         \$584           must have LC4/C00         \$36         \$36           FY7         Optional 3-button keys         \$36         \$36           FZ9         Keys, two additional masters         \$121         \$121           H01         Heat insulation, rear compartment         \$156         \$156           must have V25/VA3/VA1/C07/X66         \$187         \$187	F61		\$36	\$36
FF8 Overhead storage slot, front center \$105 \$105  FJ1 Hinged lid for storage compartment \$93 \$93  FR8 Rear view camera (head unit display) \$336 \$336  must have CO2/E3M; not with FR3/JB7/JB6/JB8  FY1 Security alarm w. interior motion sensor \$584 \$584  must have LC4/C00  FY7 Optional 3-button keys \$36 \$36  FZ9 Keys, two additional masters \$121 \$121  HO1 Heat insulation, rear compartment \$156 \$156  must have V25/VA3/VA1/C07/X66  HO4 Heat insulation, front compartment \$187 \$187				
FJ1 Hinged lid for storage compartment \$93 \$93  FR8 Rear view camera (head unit display) \$336 \$336  must have CO2/E3M; not with FR3/JB7/JB6/JB8  FY1 Security alarm w. interior motion sensor \$584 \$584  must have LC4/C00  FY7 Optional 3-button keys \$36 \$36  FZ9 Keys, two additional masters \$121 \$121  HO1 Heat insulation, rear compartment \$156 \$156  must have V25/VA3/VA1/C07/X66  HO4 Heat insulation, front compartment \$187 \$187				·
FR8 Rear view camera (head unit display) \$336 \$336  must have CO2/E3M; not with FR3/JB7/JB6/JB8  FY1 Security alarm w. interior motion sensor \$584 \$584  must have LC4/C00  FY7 Optional 3-button keys \$36 \$36  FZ9 Keys, two additional masters \$121 \$121  H01 Heat insulation, rear compartment \$156 \$156  must have V25/VA3/VA1/C07/X66  H04 Heat insulation, front compartment \$187 \$187			1	-
must have C02/E3M; not with FR3/JB7/JB6/JB8           FY1         Security alarm w. interior motion sensor         \$584         \$584           must have LC4/C00         \$36         \$36           FY7         Optional 3-button keys         \$36         \$36           FZ9         Keys, two additional masters         \$121         \$121           H01         Heat insulation, rear compartment         \$156         \$156           must have V25/VA3/VA1/C07/X66         \$187         \$187           H04         Heat insulation, front compartment         \$187         \$187			· ·	
FY1 Security alarm w. interior motion sensor \$584 \$584  must have LC4/C00  FY7 Optional 3-button keys \$36 \$36  FZ9 Keys, two additional masters \$121 \$121  H01 Heat insulation, rear compartment \$156 \$156  must have V25/VA3/VA1/C07/X66  H04 Heat insulation, front compartment \$187 \$187	FR8		\$336	\$336
must have LC4/C00FY7 Optional 3-button keys\$36\$36FZ9 Keys, two additional masters\$121\$121H01 Heat insulation, rear compartment\$156\$156must have V25/VA3/VA1/C07/X66H04 Heat insulation, front compartment\$187\$187	<b>_</b>			
FY7         Optional 3-button keys         \$36         \$36           FZ9         Keys, two additional masters         \$121         \$121           HO1         Heat insulation, rear compartment         \$156         \$156           must have V25/VA3/VA1/C07/X66         \$187         \$187           HO4         Heat insulation, front compartment         \$187         \$187			\$584	\$584
FZ9 Keys, two additional masters \$121 \$121  HO1 Heat insulation, rear compartment \$156 \$156  must have V25/VA3/VA1/C07/X66  HO4 Heat insulation, front compartment \$187 \$187				· · · · · · · · · · · · · · · · · · ·
H01 Heat insulation, rear compartment \$156 \$156  must have V25/VA3/VA1/C07/X66  H04 Heat insulation, front compartment \$187 \$187				
must have V25/VA3/VA1/C07/X66  H04 Heat insulation, front compartment \$187 \$187				-
H04 Heat insulation, front compartment \$187 \$187	H01		\$156	\$156
		must have V25/VA3/VA1/C07/X66		
if + D50/D51 must have V07	H04	Heat insulation, front compartment	\$187	\$187
		if + D50/D51 must have V07		

H12   Fuel-fired pre-heater/booster (17K BTU)			144" 6C	170" 6C
### ### ### ### ### ### ### ### ### ##				
### H12   Fuel-fired pre-heater/booster (17K BTU)   \$1,116   \$1,11				
				907.033
H13   Rear cabin heater and vents	H12		\$1,116	\$1,116
H15   Heated front pasenger seat				
### H15 Heated front passenger seat	H13		\$786	\$786
must have H16; not with X68         \$284         \$286         \$286         \$286         \$286         \$286         \$286         \$286         \$286         \$286         \$286         \$286         \$286         \$286         \$288 <t< td=""><td></td><td></td><td></td><td></td></t<>				
Hate	H15		\$284	\$284
Must have H15; not with X68         \$405         \$405           H88 Rear heater prep must have H12/H29; not with H13/T19         \$405         \$405           H11 Front-to-rear outlet in instrument panel must have F13/C01         \$50         \$50           HH4 Thermotronic automatic climate control         \$337         \$337           must have JF1; JF +H13 must have H08/HK4         \$576         \$676           H29 Fuel-fired heater booster (18,000 BTU)         \$676         \$676           not with H21         \$572         \$72         \$72           J51 Fuel gauge, optimized for aux. fuel tap not with H29/H12         \$50         \$0         \$0           J47 Blind Spot Assist         \$450         \$450         \$450           M37 Blind Spot Assist         \$450         \$450         \$450           M38 Standard with C02/CA2         \$288         \$288         \$288         \$288         \$288           Standard with C02/CA2         \$657         \$775         \$775         \$775         \$775           M37 Parking Package with 360 degree camera         \$775         \$775         \$775         \$775           M37 Parking Package with 360 degree camera         \$651         \$615         \$615         \$615           M37 Parking Package with 360 degree camera         \$752			•	
H88   Rear heater prep	H16	Heated driver's seat	\$284	\$284
must have H12/H29; not with H13/T19         \$0         \$0           H11 Front-to-rear outlet in instrument panel must have F11/C01         \$0         \$0           HH4 Thermotronic automatic climate control must have F11/C01         \$337         \$337           HH4 Thermotronic automatic climate control must have F11/C01         \$576         \$676           HH4 Thermotronic automatic climate control must have F11/C01         \$676         \$676           HH4 Thermotronic automatic climate control must have F11/C01         \$72         \$72           151 Fuel gauge, optimized for aux. fuel tap not with H29/H12         \$0         \$0           152 Engine oil level display at cold start         \$0         \$0           1A7 Blind Spot Assist         \$450         \$450           must have F44/C01         \$450         \$450           Mast have E3M/C02/C03         \$288         \$288         \$288           standard with C02/CA2         \$775         \$775         \$775           Must have E3M/C02/C03; not with W75/W76/JB7         \$615         \$615         \$615           MB8 360 Degree Camera         \$685         \$685         \$685           SoP and Plausibility TBD         \$106         \$106           F1 Rain sensor         \$106         \$106           M15 Instruct cluster with color disp			•	
H1	H88		\$405	\$405
must have FJI/C01         \$337         \$337           HH4 Thermotronic automatic climate control         \$337         \$337           must have JF.; if +H13 must have H08/HK4         ***           HZ9         Fuel-fired heater booster (18,000 BTU)         \$676         \$676           not with H12         ***         ***         \$72         \$72           J51         Fuel gauge, optimized for aux. fuel tap not with H29/H12         ***         \$72         \$72           J52         Engine oil level display at cold start         \$0         \$0         \$450           JA7         Blind Spot Assist         \$450         \$450         \$450           JA7         Blind Spot Assist         \$450         \$450         \$450           JB4         Active Lane Keeping Assist         \$5288         \$288			•	
HH4   Thermotronic automatic climate control   must hove JF1; if H13 must hove H08/HK4	H1I		\$0	\$0
must have JF1; if +H13 must have H08/HK4           H29 Fuel-fired heater booster (18,000 BTU)         \$676         \$676           not with H12		,	•	
HZ9   Fuel-fired heater booster (18,000 BTU)   \$676   \$6	HH4		\$337	\$337
151   Fuel gauge, optimized for aux. fuel tap   572   572   572   572   572   572   572   572   572   572   572   573   574   575	HZ9	Fuel-fired heater booster (18,000 BTU)	\$676	\$676
		not with H12	_	
J52   Engine oil level display at cold start   \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	J51	Fuel gauge, optimized for aux. fuel tap	\$72	\$72
JA7   Blind Spot Assist   S450   S450   must have F64; not with C01		not with HZ9/H12	_	
must have F64; not with C01           JB4         Active Lane Keeping Assist         \$288         \$288           standard with CO2/CA2         JB4         Active Lane Keeping Assist         \$288         \$288           standard with CO2/CA2         JB6         Parking Package with 360 degree camera         \$775         \$775           must have E3M/CO2/CO3; not with W75/W76/JB6         JB8         360 Degree Camera         \$685         \$685           SOP and Plausibility TBD         JF1         Rain sensor         \$106         \$106           JK5         Instrument cluster with color display         \$144         \$144           not with CO3         JW0         Backup alarm         \$99         \$99           JW2         Deactivation lamp monitoring failure         \$27         \$27           JW3         Attention Assist         \$49         \$49         \$49           K51         Misfueling prevention for Diesel         \$49         \$49         \$49         \$49         \$49         \$49	J52	Engine oil level display at cold start	-	\$0
See	JA7	Blind Spot Assist	\$450	\$450
standard with CO2/CA2         JB6         Parking Package with 360 degree camera         \$775         \$775           must have E3M/CO2/CO3; not with W75/W76/JB7         JB7         Parking Package         \$615         \$615           JB7         Parking Package         \$615         \$615           must have E3M/CO2/CO3; not with W75/W76/JB6         JB8         360 Degree Camera         \$685         \$685           JB8         360 Degree Camera         \$685         \$685           JB8         360 Degree Camera         \$106         \$106           JB8         360 Degree Camera         \$685         \$685           JB9         \$194         \$144         \$144           JB1         361         \$166         \$166         \$166           JB1         361         \$184         \$144         \$144         \$144         \$144         \$144         \$144		must have F64; not with C01		
JB6	JB4	Active Lane Keeping Assist	\$288	\$288
must have E3M/C02/C03; not with W75/W76/JB7           JB7         Parking Package         \$615         \$615           must have E3M/C02/C03; not with W75/W76/JB6         \$685         \$685         \$685           JB8         360 Degree Camera         \$685         \$685         \$685           SOP and Plausibility TBD         JF1         Rain sensor         \$106         \$106         \$106           JK5         Instrument cluster with color display         \$144         \$149         \$49		standard with CO2/CA2	•	
JBT	JB6	Parking Package with 360 degree camera	\$775	\$775
must have E3M/C02/C03; not with W75/W76/JB6           JB8         360 Degree Camera         \$685         \$685           SoP and Plausibility TBD           JK1         Rain sensor         \$106         \$106           JK5         Instrument cluster with color display         \$144         \$144           not with C03		must have E3M/C02/C03; not with W75/W76/JB7		
Season	JB7	Parking Package	\$615	\$615
SoP and Plausibility TBD		must have E3M/C02/C03; not with W75/W76/JB6		
Section   Sect	JB8	360 Degree Camera	\$685	\$685
State   Stat		SoP and Plausibility TBD		
	JF1	Rain sensor	\$106	\$106
JWO         Backup alarm         \$99         \$99           JW2         Deactivation lamp monitoring failure         \$27         \$27           JW8         Attention Assist         \$49         \$49           K51         Misfueling prevention for Diesel         \$49         \$49           K52         DEF fluid filler cap - lockable         \$27         \$27           L13         Fog lamp with cornering light function         \$199         \$199           LB9         Illuminated front exits         \$151         \$151           LC4         Comfort overhead control panel         \$93         \$93           M20         Speed limitation 65 mph         \$60         \$60           not with MD3         Top speed limitation 75 mph         \$60         \$60           not with MX0         N62         Front engine bracket for additional alternator         \$467         \$467           not with HK4/N63         ***         ***         \$467         \$467           N63         Front engine bracket for auxiliary A/C compressor         \$467         \$467         \$467           not with HK4/N62         ***         ***         \$186         \$186           not with W3/W75/W76/Q24/Q67         ***         ***         **	JK5	Instrument cluster with color display	\$144	\$144
JW2       Deactivation lamp monitoring failure       \$27       \$27         JW8       Attention Assist       \$49       \$49         K51       Misfueling prevention for Diesel       \$49       \$49         K52       DEF fluid filler cap - lockable       \$27       \$27         L13       Fog lamp with cornering light function       \$199       \$199         LB9       Illuminated front exits       \$151       \$151         LC4       Comfort overhead control panel       \$93       \$93         M20       Speed limitation 65 mph       \$60       \$60         not with MD3       ***       ***         MD3       Top speed limitation 75 mph       \$60       \$60         not with M20       ***       ***         N62       Front engine bracket for additional alternator       \$467       \$467         not with HK4/N63       ***       ***         N63       Front engine bracket for auxiliary A/C compressor       \$467       \$467         not with HK4/N62       ***       ***         QA2       Trailer cross member 7,500 lbs capacity       \$186       \$186         not with W73/W75/W76/Q24/Q67       **         QA9       Half-sided step rear (for trailer hitch)       \$101 <td></td> <td>not with CO3</td> <td></td> <td></td>		not with CO3		
JW8 Attention Assist       \$49       \$49         K51 Misfueling prevention for Diesel       \$49       \$49         K52 DEF fluid filler cap - lockable       \$27       \$27         L13 Fog lamp with cornering light function       \$199       \$199         LB9 Illuminated front exits       \$151       \$151         LC4 Comfort overhead control panel       \$93       \$93         M20 Speed limitation 65 mph       \$60       \$60         not with MD3       \$60       \$60         MD3 Top speed limitation 75 mph       \$60       \$60         not with M20       \$467       \$467         N62 Front engine bracket for additional alternator       \$467       \$467         not with HK4/N63       \$467       \$467         N63 Front engine bracket for auxiliary A/C compressor       \$467       \$467         not with HK4/N62       \$186       \$186         QA2 Trailer cross member 7,500 lbs capacity       \$186       \$186         not with W73/W75/W76/Q24/Q67       \$101       \$101         R91 Spare tire deletion       -\$110       -\$110         must have R92; not with R87       \$2       \$2         R92 Spare tire carrier deletion       \$0       \$0         must have R91; not with R65       \$81<	JW0	Backup alarm	\$99	\$99
K51       Misfueling prevention for Diesel       \$49       \$49         K52       DEF fluid filler cap - lockable       \$27       \$27         L13       Fog lamp with cornering light function       \$199       \$199         LB9       Illuminated front exits       \$151       \$151         LC4       Comfort overhead control panel       \$93       \$93         M20       Speed limitation 65 mph       \$60       \$60         not with MD3       \$60       \$60         MD3       Top speed limitation 75 mph       \$60       \$60         not with M20       \$60       \$60         N62       Front engine bracket for additional alternator       \$467       \$467         not with HK4/N63       \$467       \$467       \$467         N63       Front engine bracket for auxiliary A/C compressor       \$467       \$467         not with HK4/N62       \$186       \$186         QA2       Trailer cross member 7,500 lbs capacity       \$186       \$186         not with W73/W75/W76/Q24/Q67       \$101       \$101         QA9       Half-sided step rear (for trailer hitch)       \$101       \$101         must have Q24/QA2; not with R87         R92       Spare tire carrier deletion       \$0	JW2	Deactivation lamp monitoring failure	\$27	\$27
K52       DEF fluid filler cap - lockable       \$27       \$27         L13       Fog lamp with cornering light function       \$199       \$199         LB9       Illuminated front exits       \$151       \$151         LC4       Comfort overhead control panel       \$93       \$93         M20       Speed limitation 65 mph       \$60       \$60         not with MD3       \$60       \$60         MD3       Top speed limitation 75 mph       \$60       \$60         not with M20       \$60       \$60         N62       Front engine bracket for additional alternator       \$467       \$467         not with HK4/N63       \$467       \$467       \$467         N63       Front engine bracket for auxiliary A/C compressor       \$467       \$467         not with HK4/N62       \$186       \$186       \$186         not with HK4/N62       \$186       \$186       \$186         not with W73/W75/W76/Q24/Q67       \$101       \$101       \$101         QA9       Half-sided step rear (for trailer hitch)       \$101       \$101         must have Q24/QA2; not with W73/W75/W76       \$10       -\$110       -\$110         R91       Spare tire carrier deletion       \$0       \$0	JW8	Attention Assist	\$49	\$49
L13       Fog lamp with cornering light function       \$199       \$199         LB9       Illuminated front exits       \$151       \$151         LC4       Comfort overhead control panel       \$93       \$93         M20       Speed limitation 65 mph       \$60       \$60         not with MD3       MD3 Top speed limitation 75 mph       \$60       \$60         N62       Front engine bracket for additional alternator       \$467       \$467         not with HK4/N63       Front engine bracket for auxiliary A/C compressor       \$467       \$467         not with HK4/N62       Trailer cross member 7,500 lbs capacity       \$186       \$186         not with W73/W75/W76/Q24/Q67       QA9 Half-sided step rear (for trailer hitch)       \$101       \$101         must have Q24/QA2; not with W73/W75/W76       R91       Spare tire deletion       -\$110       -\$110         must have R92; not with R87       R92       Spare tire carrier deletion       \$0       \$0         must have R91; not with R65       R98       Rims painted jet black       \$81       \$81	K51	Misfueling prevention for Diesel	\$49	\$49
LB9       Illuminated front exits       \$151       \$151         LC4       Comfort overhead control panel       \$93       \$93         M20       Speed limitation 65 mph       \$60       \$60         not with MD3       MD3 Top speed limitation 75 mph       \$60       \$60         not with M20       N62       Front engine bracket for additional alternator       \$467       \$467         not with HK4/N63       Front engine bracket for auxiliary A/C compressor       \$467       \$467         not with HK4/N62       QA2       Trailer cross member 7,500 lbs capacity       \$186       \$186         not with W73/W75/W76/Q24/Q67       QA9       Half-sided step rear (for trailer hitch)       \$101       \$101         must have Q24/QA2; not with W73/W75/W76       R91       Spare tire deletion       -\$110       -\$110         must have R92; not with R87       R92       Spare tire carrier deletion       \$0       \$0         must have R91; not with R65       R88       Rims painted jet black       \$81       \$81	K52	DEF fluid filler cap - lockable	\$27	\$27
LC4       Comfort overhead control panel       \$93       \$93         M20       Speed limitation 65 mph       \$60       \$60         not with MD3       \$60       \$60         MD3       Top speed limitation 75 mph       \$60       \$60         not with M20       \$467       \$467       \$467         N62       Front engine bracket for additional alternator       \$467       \$467         not with HK4/N63       \$186       \$186       \$186         N63       Front engine bracket for auxiliary A/C compressor       \$467       \$467         not with HK4/N62       \$186       \$186       \$186         QA2       Trailer cross member 7,500 lbs capacity       \$186       \$186         not with W73/W75/W76/Q24/Q67       \$101       \$101       \$101         QA9       Half-sided step rear (for trailer hitch)       \$101       \$101         must have Q24/QA2; not with W73/W75/W76       \$10       -\$110       -\$110         R91       Spare tire deletion       \$0       \$0         must have R92; not with R87       \$0       \$0         R92       Spare tire carrier deletion       \$0       \$0         must have R91; not with R65       \$81       \$81         R98	L13	Fog lamp with cornering light function	\$199	\$199
M20 Speed limitation 65 mph  not with MD3  MD3 Top speed limitation 75 mph  sequence with M20  N62 Front engine bracket for additional alternator  not with HK4/N63  N63 Front engine bracket for auxiliary A/C compressor  not with HK4/N62  QA2 Trailer cross member 7,500 lbs capacity  not with W73/W75/W76/Q24/Q67  QA9 Half-sided step rear (for trailer hitch)  must have Q24/QA2; not with W73/W75/W76  R91 Spare tire deletion  must have R92; not with R87  R92 Spare tire carrier deletion  must have R91; not with R65  R98 Rims painted jet black  \$81 \$81	LB9	Illuminated front exits	\$151	\$151
not with MD3  MD3 Top speed limitation 75 mph \$60 \$60  not with M20  N62 Front engine bracket for additional alternator \$467 \$467  not with HK4/N63  N63 Front engine bracket for auxiliary A/C compressor \$467 \$467  not with HK4/N62  QA2 Trailer cross member 7,500 lbs capacity \$186 \$186  not with W73/W75/W76/Q24/Q67  QA9 Half-sided step rear (for trailer hitch) \$101 \$101  must have Q24/QA2; not with W73/W75/W76  R91 Spare tire deletion \$50 \$50  must have R92; not with R87  R92 Spare tire carrier deletion \$0 \$0  must have R91; not with R65  R98 Rims painted jet black \$81 \$81	LC4	Comfort overhead control panel	\$93	\$93
MD3       Top speed limitation 75 mph       \$60       \$60         not with M20       N62       Front engine bracket for additional alternator       \$467       \$467         not with HK4/N63       N63       Front engine bracket for auxiliary A/C compressor       \$467       \$467         not with HK4/N62       QA2       Trailer cross member 7,500 lbs capacity       \$186       \$186         not with W73/W75/W76/Q24/Q67       QA9       Half-sided step rear (for trailer hitch)       \$101       \$101         must have Q24/QA2; not with W73/W75/W76       R91       Spare tire deletion       -\$110	M20	Speed limitation 65 mph	\$60	\$60
not with M20         N62 Front engine bracket for additional alternator       \$467       \$467         not with HK4/N63       \$467       \$467         N63 Front engine bracket for auxiliary A/C compressor       \$467       \$467         not with HK4/N62       \$186       \$186         QA2 Trailer cross member 7,500 lbs capacity       \$186       \$186         not with W73/W75/W76/Q24/Q67       \$101       \$101         QA9 Half-sided step rear (for trailer hitch)       \$101       \$101         must have Q24/QA2; not with W73/W75/W76       \$10       -\$110         R91 Spare tire deletion       -\$110       -\$110         must have R92; not with R87       \$0       \$0         R92 Spare tire carrier deletion       \$0       \$0         must have R91; not with R65       \$81       \$81         R98 Rims painted jet black       \$81       \$81				
not with M20         N62 Front engine bracket for additional alternator       \$467       \$467         not with HK4/N63       \$467       \$467         N63 Front engine bracket for auxiliary A/C compressor       \$467       \$467         not with HK4/N62       \$186       \$186         QA2 Trailer cross member 7,500 lbs capacity       \$186       \$186         not with W73/W75/W76/Q24/Q67       \$101       \$101         QA9 Half-sided step rear (for trailer hitch)       \$101       \$101         must have Q24/QA2; not with W73/W75/W76       \$10       -\$110         R91 Spare tire deletion       -\$110       -\$110         must have R92; not with R87       \$0       \$0         R92 Spare tire carrier deletion       \$0       \$0         must have R91; not with R65       \$81       \$81         R98 Rims painted jet black       \$81       \$81	MD3	Top speed limitation 75 mph	\$60	\$60
not with HK4/N63         N63 Front engine bracket for auxiliary A/C compressor       \$467       \$467         not with HK4/N62       \$186       \$186         QA2 Trailer cross member 7,500 lbs capacity       \$186       \$186         not with W73/W75/W76/Q24/Q67       \$101       \$101         QA9 Half-sided step rear (for trailer hitch)       \$101       \$101         must have Q24/QA2; not with W73/W75/W76       \$100       \$110         R91 Spare tire deletion       -\$110       -\$110         must have R92; not with R87       \$0       \$0         R92 Spare tire carrier deletion       \$0       \$0         must have R91; not with R65       \$81       \$81         R98 Rims painted jet black       \$81       \$81				
not with HK4/N63         N63 Front engine bracket for auxiliary A/C compressor       \$467       \$467         not with HK4/N62       \$186       \$186         QA2 Trailer cross member 7,500 lbs capacity       \$186       \$186         not with W73/W75/W76/Q24/Q67       \$101       \$101         QA9 Half-sided step rear (for trailer hitch)       \$101       \$101         must have Q24/QA2; not with W73/W75/W76       \$100       \$110         R91 Spare tire deletion       -\$110       -\$110         must have R92; not with R87       \$0       \$0         R92 Spare tire carrier deletion       \$0       \$0         must have R91; not with R65       \$81       \$81         R98 Rims painted jet black       \$81       \$81	N62		\$467	\$467
N63 Front engine bracket for auxiliary A/C compressor  not with HK4/N62  QA2 Trailer cross member 7,500 lbs capacity  not with W73/W75/W76/Q24/Q67  QA9 Half-sided step rear (for trailer hitch)  must have Q24/QA2; not with W73/W75/W76  R91 Spare tire deletion  must have R92; not with R87  R92 Spare tire carrier deletion  must have R91; not with R65  R98 Rims painted jet black  \$467 \$467 \$467 \$467 \$467 \$467 \$467 \$46			•	
not with HK4/N62         QA2 Trailer cross member 7,500 lbs capacity       \$186       \$186         not with W73/W75/W76/Q24/Q67       \$101       \$101         QA9 Half-sided step rear (for trailer hitch)       \$101       \$101         must have Q24/QA2; not with W73/W75/W76       \$10       -\$110         R91 Spare tire deletion       -\$110       -\$110         must have R92; not with R87       \$0       \$0         R92 Spare tire carrier deletion       \$0       \$0         must have R91; not with R65       \$81       \$81         R98 Rims painted jet black       \$81       \$81	N63	Front engine bracket for auxiliary A/C compressor	\$467	\$467
QA2       Trailer cross member 7,500 lbs capacity       \$186       \$186         not with W73/W75/W76/Q24/Q67       QA9 Half-sided step rear (for trailer hitch)       \$101       \$101         must have Q24/QA2; not with W73/W75/W76       R91       Spare tire deletion       -\$110       -\$110         must have R92; not with R87         R92       Spare tire carrier deletion       \$0       \$0         must have R91; not with R65         R98       Rims painted jet black       \$81       \$81				
not with W73/W75/W76/Q24/Q67         QA9 Half-sided step rear (for trailer hitch)       \$101       \$101         must have Q24/QA2; not with W73/W75/W76         R91 Spare tire deletion       -\$110       -\$110         must have R92; not with R87         R92 Spare tire carrier deletion       \$0       \$0         must have R91; not with R65         R98 Rims painted jet black       \$81       \$81	QA2	·	\$186	\$186
QA9       Half-sided step rear (for trailer hitch)       \$101       \$101         must have Q24/QA2; not with W73/W75/W76         R91       Spare tire deletion       -\$110       -\$110         must have R92; not with R87         R92       Spare tire carrier deletion       \$0       \$0         must have R91; not with R65         R98       Rims painted jet black       \$81       \$81				
must have Q24/QA2; not with W73/W75/W76         R91 Spare tire deletion       -\$110       -\$110         must have R92; not with R87         R92 Spare tire carrier deletion       \$0       \$0         must have R91; not with R65         R98 Rims painted jet black       \$81       \$81	QA9		\$101	\$101
R91 Spare tire deletion       -\$110       -\$110         must have R92; not with R87       \$0       \$0         R92 Spare tire carrier deletion       \$0       \$0         must have R91; not with R65       \$81       \$81				
must have R92; not with R87  R92 Spare tire carrier deletion \$0 \$0  must have R91; not with R65  R98 Rims painted jet black \$81 \$81	R91		-\$110	-\$110
R92 Spare tire carrier deletion \$0 \$0  must have R91; not with R65  R98 Rims painted jet black \$81 \$81				
must have R91; not with R65  R98 Rims painted jet black \$81 \$81	R92		\$0	\$0
R98 Rims painted jet black \$81 \$81		·	, +·	7
	R98		\$81	\$81
IIIOL WILLI NEJ/NIVIZ		not with RL5/RM2	, <del>,</del> , , ,	ΨUI

		144" 6C	170'' 6C
		M3CV46	M3CV76
		907.653	907.655
RF1	Tire brand Continental		
KLI	Tire brand Continental  must have RM1 + RM9	\$0	\$0
RF8	Tire brand Michelin	\$0	\$0
NFO	must have RM9; not with RM1	<b>3</b> 0	ŞÜ
RH0	Tire brand Kumho	\$0	\$0
KITO	must have RM9; not with RM1	30	ŞÜ
RM1	M+S winter tires	\$169	\$169
11111	must have RF1/RD9; not with RF8/RH0/X31	7103	<b>Ģ103</b>
RM2	Rims painted arctic white	\$81	\$81
	not with R98/RL5	702	<b>702</b>
RM9	Specially requested tires	\$101	\$101
	must have RF1/RF8/RH0; not with RD9		, -
S28	Armrest, driver and passenger door	\$51	\$51
T12	Sliding door two stage opening	\$82	\$82
	not with T55		
T50	Electric closing assist right sliding door	\$335	\$335
	must have D03; not with T55/T93	•	
T55	Electric sliding door right	\$831	\$831
	must have D03 + (FY7+T16); not with T12/T50		·
T57	Electric sliding step	\$1,071	\$1,071
	must have D03 + ED5; not with T93	<del>+ -/</del>	7-701-
T60	Opening limiter electrically operated sliding door	\$120	\$120
	must have T55	7-2-0	<b>7</b> 220
T75	Door-mounted assist handles, driver & passenger	\$59	\$59
T85	Assist handle, left rear door	\$32	\$32
T86	Assist handles, right rear door	\$32	\$32
V43	Wood floor with 6 D-rings	\$422	\$422
V43	not with P93/V93/VL4/VK8/C07; standard with D93/H13/V24/V52/VC		<b>3422</b>
V85	Cigarette lighter & ash cup, front		¢20
VC5		\$39	\$39
VCS	Door sill - protective edge	\$71	\$71
\/\/O	must have V43/X66; not with T19/T93/VK8/VV2/V93/C07	6270	¢270
VK8	Floor covering, plastic	\$370	\$370
\A/F 4	not with V43/P93/T19/T93/V52/VC5/X66	40.50	40.50
	Rear doors, opening to side wall	\$360	\$360
W5F	90 Degree fixation point- Rear Doors	\$80	\$80
	SoP and Plausibility TBD	4	4
W73	Bumper step, rear, grey	\$187	\$187
	not with Q24/W75/W76		
W75	Step, wide, at rear end	\$308	\$308
	not with JB6/JB7/Q24/QA9; must have R91+R92		
W76	Bumper step, rear, spring-loaded	-	\$601
	must have R91+R92; not with JB6/JB7/X30/Q24		
W78	Heated rear window(s) w/ washers/wipers	\$335	\$335
	Must have H22+VA7 / if D51 must have F61; not with W61		
X90	Deletion of Sprinter badge, left rear door	\$0	\$0
X93	Deletion of model badge, right rear door	\$0	\$0
XM4	Acoustic package	\$87	\$87
	standard with C02/C03		
Y10	First-aid kit	\$27	\$27
Y26	Wheel chocks	\$38	\$38
Y45	Emergency flashlight	\$27	\$27
Y68	Paint preservative	\$187	\$212
Y69	Surface protection for stock vehicles	\$315	\$315
YK3	Cargo straps, D-rings	\$81	\$81

### 3500 CREW VAN - 6cyl Diesel Packages

144" 6C

170" 6C

		IVI3CV46	IVI3CV/6	
		907.653	907.655	
C00	Comfort Package	\$300	\$300	
LC4	Comfort overhead control panel	Х	Х	
SE4	Lumbar support, co-driver's seat	Х	Х	
SE5	Lumbar support, driver's seat	Х	Х	
SK0	Comfort head restraint, driver	X	Х	
SK1	Comfort head restraint, co-driver	X	X	
S28	Armrest, driver and passenger door	Х	Х	
must have COS OR X68; CA/CC only: not with S23				

COS	Comfort Package (Seat addition)	\$381	\$381	
SB1	Comfort driver's seat	X	X	
SB2	Comfort passenger seat	X	Х	
must	must have COO			

X68	Comfort Plus Package	\$1,923	\$1,923	
H15	Heated front passenger seat	Х	X	
H16	Heated driver's seat	Х	Х	
SF1	Driver's seat electrically adjustable	Х	Х	
SF2	Co-driver's seat electrically adjustable	Х	Х	
must	must have COO and VF4 OR VF6, CA/CC only: not with S23			

C01	Driver Convenience Package	\$760	\$760
E46	12 V power outlet, driver seat base	X	X
F64	Electrically folding exterior mirrors	X	X
FJ1	Hinged lid for storage compartment	Х	X
FJ5	Hinged Lid for Storage Compartments left and right	Х	X
FZ9	Keys, two additional masters	Х	Х
JA7	Blind Spot Assist	Х	Х
JW8	Attention Assist	X	Х

C02	Premium Package	\$983	\$983
CL3	Leather steering wheel	X	X
E3M	MBUX Multimedia System with 7" touchscreen	X	X
FM3	Wet Wiper System	X	X
JB4	Active Lane Keeping Assist	X	Х
JK5	Instrument cluster with color display	Х	X
Oudou	in a survivability, anatorists of son NatChaufea and survivability, and anatoristic and		/A / /

Ordering availability restricted, see NetStar for availability and restrictions|must have JF1 + XM4; must choose FR8/JB7/JB6

CA2	C02 in combination with C03	\$604	\$604	
CL3	Leather steering wheel	X	X	
FM3	Wet Wiper System	Х	X	
JB4	Active Lane Keeping Assist	Х	X	
JK5	Instrument cluster with color display	Х	X	
Order	Ordering availability restricted, see NetStar for availability and restrctions must have CO3 + JF1			

### 3500 CREW VAN - 6cyl Diesel Packages

144" 6C	170" 6C
M3CV46	M3CV76
907.653	907.655

C03	Premium Plus Package	\$1,793	\$1,793
E1B	Tray for smartphones incl. wireless charging	Х	Х
	Navigation	Х	Х
EY2	Intelligent navigation	Х	Х
E4M	MBUX Multimedia System with 10.25" touchscreen	Х	Х
EX9	Free map data updates for 3 years	Х	Х
H1I	Front-to-rear outlet in instrument panel	Х	Х
JA9	Traffic Sign Assist	Х	Х
XM4	Acoustic package	Х	Х
must have (CA2+(JB7/JB6/JB8)) OR (JB4+JK5+FM3+(JB7/JB6/JB8)); not with FR8 and CO2			

X67	Chrome Grille Package	\$290	\$290
CN2	Radiator grille frame in vehicle color	X	X
FK3	Chrome plated radiator grille (MB only)	Х	Х
no restrictions			

X13	Exterior Lighting Package	\$1,608	\$1,608	
L13	Fog lamp with cornering light function	X	X	
L22	Partial LED tail lights	Х	Х	
LA1	High beam assist	Х	X	
LG7	LED high performance headlamps	Х	Х	
no res	no restrictions			

X72	Crew Van Comfort Package	\$220	\$220
S31	Convenice head restraints for pass. compartment	Х	X
T12	Sliding door two stage opening	Х	X
T50	Electric closing assist right sliding door	Х	X
UY1	3-seater comfort bench rear, 1st row (narrow)	Х	X
can have VF4/VF6 only			

### 3500XD CREW VAN - 4cyl Diesel Standard Equipment

144" 4C	170" 4C
MXCV44	MXCV74
907.653	907.655

		907.053	907.055
Engin	e		
	Engine/7-Speed Trans.	S	S
ED4	AGM battery 12V 92 AH 850 A	S	S
G42	Automatic transmission, 7G-tronic	S	S
M40	Alternator 14 V / 200 A	S	S
	·	S	S
	2.0L 4-cylinder diesel engine		
	SULEV emissions	S	S
	- choose while ordering	1-	4-5
X34	Dual Rear Wheel	\$0	\$0
RH7	Tires LT 215/85 R16	S	S
RS6	5.5 J x 16 steel wheels	S	S
RD9	Unspecified tire brand	S	S
X31	Super Single Tire	\$385	\$385
R9A	285/65 R 16 C super single tires	0	0
RS5	Steel wheels: 8.5Jx16 Rr; 6.5Jx16 Fr	0	0
RD9	Unspecified tire brand	0	0
RY2	Tire pressure monitoring sensors	0	0
Seatii	ng and Trim Packages		
X7S	Standard Rear Seats	S	S
U62	3-seater bench rear, 1st row (narrow)	S	S
	Wall-side armrest	S	S
	Aisle-side armrest	S	S
	nave VF7/VF6 only; with X68 must have VF6		3
X2V	Standard Trim Crew Van Package	S	S
V25	Half height load compartment trim	S	S
V25	Wheel house covering	S	S
V43	Wood floor with 6 D-rings	S	S
		3	3
	production only		
Equip		· ·	C .
AR3	Axle ratio 4.182	S	S
BA3	Active Brake Assist	S	S
BH1	Hold Function	S	S
CB8	Stabilization Level II	S	S
C6L	Multifunction steering wheel	S	S
CL1	Adjustable steering wheel (angle)	S	S
D03	High roof	0	S
D93	Omission bulkhead	S	S
E07	Hill Start Assist	S	S
E10	Standard radio	S	S
E1U	USB-C socket, 5 V	S	S
E30	Starter battery disconnect	S	S
E3J	Pre-installation for switch panel	S	S
E40	Trailer hitch prep. wiring	S	S
ED8	Preinstallation PSM	S	S
EE5	Ultracapacitor discharge module	S	S
EK1	Body Builder Connector	S	S
ES0	Jump start terminal	S	S
	Pre-installation for Mercedes me Remote Services	S	S
			3
EW6			C
EY5	Emergency Call System	S	S
EY5 EY6	Emergency Call System Breakdown management	S S	S
EY5 EY6 F43	Emergency Call System Breakdown management Laminated glass rear	S S S	S S
EY5 EY6 F43 FF3	Emergency Call System Breakdown management Laminated glass rear Cupholder rear compartment	\$ \$ \$ \$	S S S
EY5 EY6 F43 FF3 F68	Emergency Call System Breakdown management Laminated glass rear Cupholder rear compartment Heated & electrically adjustable exterior mirrors	S S S S S	S S S
EY5 EY6 F43 FF3 F68 FF5	Emergency Call System Breakdown management Laminated glass rear Cupholder rear compartment Heated & electrically adjustable exterior mirrors Shelf above windshield	S S S S S S	S S S S S
EY5 EY6 F43 FF3 F68	Emergency Call System Breakdown management Laminated glass rear Cupholder rear compartment Heated & electrically adjustable exterior mirrors	S S S S S	S S S
EY5 EY6 F43 FF3 F68 FF5	Emergency Call System Breakdown management Laminated glass rear Cupholder rear compartment Heated & electrically adjustable exterior mirrors Shelf above windshield	S S S S S S	S S S S S

### 3500XD CREW VAN - 4cyl Diesel Standard Equipment

H00 Warm H21 Winds H22 Rear w HH2 Heate HH9 Air Co IH7 Head U J11 Speed J55 Seat b J58 Seat b J65 Outsic JA8 Crossv JH3 Comm JI9 Service K56 Red di K60 Exhau: KB7 24.5 g KL1 Aux fu	iew camera (rear-view mirror display) /cool air duct to rear compartment hield with filter band vindow defroster r, auxiliary electric hot air ndition, Front Unit, North America ometer, miles and km/h elt warning for co-driver seat elt reminder driver le temperature gauge vind Assist unication module (LTE) for dig. services e interval 20.000 miles esel filler cap st straight to rear	MXCV44 907.653  S S S S S S S S S S S S S S S S S S	MXCV74 907.655  S S S S S S S S S S S S S S S S S S
H00 Warm H21 Winds H22 Rear v HH2 Heate HH9 Air Co IH7 Head I J11 Speed J55 Seat b J58 Seat b J65 Outsic JA8 Crossv JH3 Comm JI9 Service K56 Red di K60 Exhau: KB7 24.5 g KL1 Aux fu	/cool air duct to rear compartment hield with filter band vindow defroster r, auxiliary electric hot air ndition, Front Unit, North America ometer, miles and km/h elt warning for co-driver seat elt reminder driver le temperature gauge vind Assist unication module (LTE) for dig. services e interval 20.000 miles esel filler cap st straight to rear	S S S S S S S S S S S S S S S S S S S	S S S S S S S S S S S S S S S S S S S
H00 Warm H21 Winds H22 Rear v HH2 Heate HH9 Air Co IH7 Head I J11 Speed J55 Seat b J58 Seat b J65 Outsic JA8 Crossv JH3 Comm JI9 Service K56 Red di K60 Exhau: KB7 24.5 g KL1 Aux fu	/cool air duct to rear compartment hield with filter band vindow defroster r, auxiliary electric hot air ndition, Front Unit, North America ometer, miles and km/h elt warning for co-driver seat elt reminder driver le temperature gauge vind Assist unication module (LTE) for dig. services e interval 20.000 miles esel filler cap st straight to rear	S S S S S S S S S S S S S S S S S S S	S S S S S S S S S S S S S S S S S S S
H00 Warm H21 Winds H22 Rear w HH2 Heate HH9 Air Co IH7 Head U J11 Speed J55 Seat b J58 Seat b J65 Outsic JA8 Crossw JH3 Comm JI9 Service K56 Red di K60 Exhaus KB7 24.5 g KL1 Aux fu	/cool air duct to rear compartment hield with filter band vindow defroster r, auxiliary electric hot air ndition, Front Unit, North America ometer, miles and km/h elt warning for co-driver seat elt reminder driver le temperature gauge vind Assist unication module (LTE) for dig. services e interval 20.000 miles esel filler cap st straight to rear	S S S S S S S S S S S S S S S S S S S	S S S S S S S S S S S S S S S S S S S
H21 Winds H22 Rear w HH2 Heate HH9 Air Co IH7 Head U J11 Speed J55 Seat b J58 Seat b J65 Outsic JA8 Crossw JH3 Comm JI9 Service K56 Red di K60 Exhau: KB7 24.5 g KL1 Aux fu	hield with filter band vindow defroster r, auxiliary electric hot air ndition, Front Unit, North America ometer, miles and km/h elt warning for co-driver seat elt reminder driver le temperature gauge vind Assist unication module (LTE) for dig. services e interval 20.000 miles esel filler cap st straight to rear	S S S S S S S S S S S S S S S S S S S	S S S S S S S S S S S S S S S S S S S
H22 Rear w HH2 Heate HH9 Air Co IH7 Head I J11 Speed J55 Seat b J58 Seat b J65 Outsic JA8 Crossw JH3 Comm JI9 Service K56 Red di K60 Exhau: KB7 24.5 g KL1 Aux fu	vindow defroster r, auxiliary electric hot air ndition, Front Unit, North America ometer, miles and km/h elt warning for co-driver seat elt reminder driver le temperature gauge vind Assist unication module (LTE) for dig. services e interval 20.000 miles esel filler cap st straight to rear	S S S S S S S S S S S S S S S S S S S	S S S S S S S S S S S S S S S S S S S
HH2 Heate HH9 Air Co IH7 Head I J11 Speed J55 Seat b J58 Seat b J65 Outsic JA8 Crossy JH3 Comm JI9 Service K56 Red di K60 Exhau: KB7 24.5 g KL1 Aux fu	r, auxiliary electric hot air ndition, Front  Unit, North America ometer, miles and km/h elt warning for co-driver seat elt reminder driver le temperature gauge vind Assist unication module (LTE) for dig. services e interval 20.000 miles esel filler cap st straight to rear	S S S S S S S S S S S S S S S S S S S	S S S S S S S S S S S S S S S S S S S
HH9 Air Colling HH7 Head I J11 Speed J55 Seat b J58 Seat b J65 Outsic JA8 Crossy JH3 Comm JI9 Service K56 Red di K60 Exhaus KB7 24.5 g KL1 Aux fu	ndition, Front Unit, North America ometer, miles and km/h elt warning for co-driver seat elt reminder driver le temperature gauge vind Assist unication module (LTE) for dig. services e interval 20.000 miles esel filler cap st straight to rear	S S S S S S S S S S S S S S S S S S S	S S S S S S S S S S S S S S S S S S S
IH7 Head I J11 Speed J55 Seat b J58 Seat b J65 Outsid JA8 Crossy JH3 Comm JI9 Service K56 Red di K60 Exhau: KB7 24.5 g KL1 Aux fu	Unit, North America ometer, miles and km/h elt warning for co-driver seat elt reminder driver le temperature gauge vind Assist unication module (LTE) for dig. services e interval 20.000 miles esel filler cap st straight to rear	S S S S S S S S S S S	S S S S S S S S S S S S S S S S S S S
J11 Speed J55 Seat b J58 Seat b J65 Outsic JA8 Crossy JH3 Comm JI9 Service K56 Red di K60 Exhau: KB7 24.5 g KL1 Aux fu	ometer, miles and km/h elt warning for co-driver seat elt reminder driver le temperature gauge vind Assist unication module (LTE) for dig. services e interval 20.000 miles esel filler cap st straight to rear	S S S S S S S S S	S S S S S S S S S
J55 Seat b J58 Seat b J65 Outsid JA8 Crossy JH3 Comm JI9 Service K56 Red di K60 Exhau: KB7 24.5 g KL1 Aux fu	elt warning for co-driver seat elt reminder driver le temperature gauge vind Assist unication module (LTE) for dig. services e interval 20.000 miles esel filler cap st straight to rear	S S S S S S S	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$
J58 Seat b J65 Outsid JA8 Crossy JH3 Comm JI9 Service K56 Red di K60 Exhau: KB7 24.5 g KL1 Aux fu	elt reminder driver le temperature gauge vind Assist unication module (LTE) for dig. services e interval 20.000 miles esel filler cap st straight to rear	S S S S S	S S S S
J65 Outsic JA8 Crossy JH3 Comm JI9 Service K56 Red di K60 Exhau: KB7 24.5 g KL1 Aux fu	le temperature gauge vind Assist unication module (LTE) for dig. services e interval 20.000 miles esel filler cap st straight to rear	S S S S	\$ \$ \$ \$
JA8 Crossy JH3 Comm JI9 Service K56 Red di K60 Exhau: KB7 24.5 gi KL1 Aux fu	vind Assist unication module (LTE) for dig. services e interval 20.000 miles esel filler cap st straight to rear	\$ \$ \$ \$	\$ \$ \$
JH3 Comm JI9 Service K56 Red di K60 Exhau: KB7 24.5 g KL1 Aux fu	unication module (LTE) for dig. services e interval 20.000 miles esel filler cap st straight to rear	S S S	S S
JI9 Service K56 Red di K60 Exhau: KB7 24.5 g KL1 Aux fu	e interval 20.000 miles esel filler cap st straight to rear	S S	S
K56 Red di K60 Exhau: KB7 24.5 gi KL1 Aux fu	esel filler cap st straight to rear	S	
K60 Exhau: KB7 24.5 g KL1 Aux fu	st straight to rear		S
KB7 24.5 g KL1 Aux fu	-	S	S
KL1 Aux fu	allon fuel tank	S	S
	el sending unit w/ fuel tap	S	S
IKIS IHIIAITI	Iter with water separator	S	S
	neration SCR emission control system	S	S
<u> </u>	g lights deletion	S	S
	ght assistant	S	S
	ake light	S	S
	control	S	S
	mudflaps	S	S
	nudflaps	S	S
	udinal member reinforcement	S	S
	tire bracket below frame	S	S
R87 Spare	tire	S	S
	ison tires	S	S
	ard driver seat	S	S
S04 Standa	ard front passenger seat	S	S
	st for driver's seat	S	S
S25 Armre	st for front passenger seat	S	S
SA5 Front	airbag, driver	S	S
SA6 Front	airbag, passenger	S	S
SH1 Thorax	c-pelvis sidebag, driver	S	S
SH2 Thorax	c-pelvis sidebag, co-driver	S	S
SH9 Airbag	, driver/passenger window	S	S
SK2 Seat o	ccupancy sensor, driver's seat	S	S
T16 Sliding	door, passenger side	S	S
T74 Assist	handle, B-pillar	S	S
U22 Pre-in:	st. for seating configuration Crew Van	S	S
V36 Roof t	rim	S	S
V40 Floor a	anchors for rear seat bench	S	S
VA7 Storag	e compart. w/ net in rear doors	S	S
W16 2nd ro	w, fixed window, driver side	S	S
W17 2nd rd	w, fixed window, passenger side	S	S
W61 Windo	ws in rear doors	S	S
W70 Black t	inting (90%) for rear windows	S	S
X5G Witou	t load uprating/derating 5,000 kg	S	S
Y43 Jack, h	ydraulic	S	S

		144" 4C	170" 4C
		MXCV44	MXCV74
		907.653	907.655
A50	Front axle reinforced	\$346	\$346
-	Addtl. bar for driveshaft & exhaust extension	\$69	\$69
AP2		\$0	\$0
AR2	Axle ratio 3.923	ŞU	\$U
D04	not with AR3		do.
B01	ESP for increased Center of Gravity above 39.4"	-	\$0
	must have CB4/CB8/X30; not with RH0/CB7	42.52	40.00
C72	Bumpers front/rear primed	\$268	\$268
	must have CN2/X67, not with CM0	4	4
CL3	Leather steering wheel	\$187	\$187
	must have (C02/E3M)/C03 + (ET4/MS1)		1
CM0	Painted metallic front & rear bumper	\$587	\$587
	must have (CN2/X67) + (JA7/C01) + JB7 + (7755/9197/9775)		
CM9	Primed side moldings	\$364	\$364
D03	High roof	\$2,900	S
	D03 must be added for Duesseldorf production		
D13	Mounting rails for roof rack	\$300	\$300
E1B	Tray for smartphones incl. wireless charging	\$156	\$156
	must have CO2/E3M + H1I	•	
E1E	Navigation	\$728	\$728
	must have CO2/E3M, not with CO3		, -
E1S	Sirius XM, satellite radio	\$255	\$255
	must have CO2/E3M/CO3	Ψ=00	<b>¥</b> 200
E1R	Additional Fuses (40/80/150/100 Ampere)	\$50	\$50
LIK	SoP and Plausibility TBD	\$30	<b>\$30</b>
Γ1V		ćro	ćro
E1Y	Additional Fuses (40/80/80/100 Ampere)	\$50	\$50
	SoP and Plausibility TBD	400	420
E2A	Access point for BB special signals in cockpit	\$29	\$29
E2I	Additional battery, co-driver seat base	\$248	\$248
	Must have E36; not with E2M; CHS production only	4	4
E36	Cutoff relay for additional battery	\$110	\$110
	standard with E2I/E2M		
E3M	MBUX Multimedia System with 7" touchscreen	\$474	\$474
	not with C02/C03; must have JK5+(JB7/FR8)		
E5M	Extension of PSM standard contact	\$58	\$58
ED5	Parametric special module (PSM)	\$317	\$317
	not with ED8		
EE3	115 V socket	\$125	\$125
ES2	12 V power outlet, rear compartment	\$92	\$92
ES5	Charging package, dashboard	\$82	\$82
ET4	Active Distance Assist DISTRONIC	\$263	\$263
	must have CO2/CO3/E3M; not with ZH4		
F49	Electrically heated windshield	\$218	\$218
	no restrictions	·	
F61	Interior rear view mirror	\$36	\$36
	must have E3M/C02/C03		
FE9	Additional DIN-slot	\$81	\$81
FF8	Overhead storage slot, front center	\$105	\$105
FJ1	Hinged lid for storage compartment	\$93	\$93
FR8	Rear view camera (head unit display)	\$336	\$336
	must have CO2/E3M; not with FR3/JB7; 3500XD not with JB8		
FY1	Security alarm w. interior motion sensor	\$584	\$584
	must have LC4/C00		,
FY7	Optional 3-button keys	\$36	\$36
FZ9	Keys, two additional masters	\$121	\$121
H01	Heat insulation, rear compartment	\$156	\$156
	must have V25/VA3/VA1/C07/X66	Ų-130	<b>7130</b>
H04	Heat insulation, front compartment	\$187	\$187
1.04	if + D50/D51 must have V07	710/	710/
	ווו דרם לספה ו לון ווומצר ווומצר א לון		

		144" 4C	170" 4C
		MXCV44	MXCV74
		907.653	907.655
H12	Fuel-fired pre-heater/booster (17K BTU)	\$1,116	\$1,116
	not with HZ9	Ψ=)==0	<del>+-</del> /
H13	Rear cabin heater and vents	\$786	\$786
	must have V43 + (H12/HZ9); not with VK8	,	·
H15	Heated front passenger seat	\$284	\$284
	must have H16; not with X68		·
H16	Heated driver's seat	\$284	\$284
	must have H15; not with X68	•	
H88	Rear heater prep	\$405	\$405
	must have H12/HZ9; not with H13/T19		
H1I	Front-to-rear outlet in instrument panel	\$0	\$0
	must have FJ1/C01		
HH4	Thermotronic automatic climate control	\$337	\$337
	must have JF1; if +H13 must have H08/HK4		
HZ9	Fuel-fired heater booster (18,000 BTU)	\$676	\$676
	not with H12		
J51	Fuel gauge, optimized for aux. fuel tap	\$72	\$72
	not with HZ9/H12		
J52	Engine oil level display at cold start	\$0	\$0
JA7	Blind Spot Assist	\$450	\$450
	must have F68; not with C01		
JB4	Active Lane Keeping Assist	\$288	\$288
	standard with CO2/CA2		
JB7	Parking Package	\$615	\$615
	must have E3M/C02/C03; not with W75/W76/JB6		
JF1	Rain sensor	\$106	\$106
JK5	Instrument cluster with color display	\$144	\$144
	not with CO3		
JW0	Backup alarm	\$99	\$99
JW2	Deactivation lamp monitoring failure	\$27	\$27
JW8	Attention Assist	\$49	\$49
K51	Misfueling prevention for Diesel	\$49	\$49
K52	DEF fluid filler cap - lockable	\$27	\$27
L13	Fog lamp with cornering light function	\$199	\$199
LB9	Illuminated front exits	\$151	\$151
LC4	Comfort overhead control panel	\$93	\$93
M20	Speed limitation 65 mph	\$60	\$60
	not with MD3		
MD3		\$60	\$60
	not with M20		
N62	Front engine bracket for additional alternator	\$467	\$467
	not with HK4/N63	1 4	4
N63	Front engine bracket for auxiliary A/C compressor	\$467	\$467
	not with HK4/N62		4.00
QA2	Trailer cross member 7,500 lbs capacity	\$186	\$186
	not with W73/W75/W76/Q24/Q67	<b>44.04</b>	Ć4.04
QA9	Half-sided step rear (for trailer hitch)	\$101	\$101
DO1	must have QA2; not with W73/W75/W76	¢110	ć110
R91	Spare tire deletion	-\$110	-\$110
DO2	must have R92; not with R87	ć0	ćo
R92	Spare tire carrier deletion	\$0	\$0
DUG	must have R91; not with R65	Ć01	Ć01
R98	Rims painted jet black	\$81	\$81
DE1	not with RL5/RM2 Tire brand Continental	ćo	\$0
RF1	must have RM1 + RM9	\$0	ŞU
RF8	Tire brand Michelin	\$0	\$0
1110	must have RM9; not with RM1	∪ږ	UÇ
<u> </u>	mast nave mivis, not with mivit		

		144" 4C	170" 4C
		MXCV44	MXCV74
		907.653	907.655
RH0	Tire brand Kumho	\$0	\$0
	must have RM9; not with RM1		
RM1	M+S winter tires	\$169	\$169
	must have RF1/RD9; not with RF8/RH0/X31		
RM2	Rims painted arctic white	\$81	\$81
	not with R98/RL5		
RM9	Specially requested tires	\$101	\$101
	must have RF1/RF8/RH0; not with RD9		
S28	Armrest, driver and passenger door	\$51	\$51
T12	Sliding door two stage opening	\$82	\$82
	not with T55		
T50	Electric closing assist right sliding door	\$335	\$335
	must have D03; not with T55/T93		
T55	Electric sliding door right	\$831	\$831
	must have D03 + (FY7+T16); not with T12/T50		
T57	Electric sliding step	\$1,071	\$1,071
	must have D03 + ED5; not with T93		
T60	Opening limiter electrically operated sliding door	\$120	\$120
	must have T55		,
T75	Door-mounted assist handles, driver & passenger	\$59	\$59
T85	Assist handle, left rear door	\$32	\$32
T86	Assist handles, right rear door	\$32	\$32
V43	Wood floor with 6 D-rings	\$422	\$422
V43	not with P93/V93/VL4/VK8/C07; standard with D93/H13/V24/V52/VC	-	<b>3422</b>
V85	Cigarette lighter & ash cup, front	\$39	\$39
VC5		\$39 \$71	\$39 \$71
VC3	Door sill - protective edge	\$/1	\$/1
\/\/O	must have V43/X66; not with T19/T93/VK8/VV2/V93/C07	6270	6270
VK8	Floor covering, plastic	\$370	\$370
	not with V43/P93/T19/T93/V52/VC5/X66	42.50	42.52
W54	Rear doors, opening to side wall	\$360	\$360
W5F	90 Degree fixation point- Rear Doors	\$80	\$80
	SoP and Plausibility TBD		
W73	Bumper step, rear, grey	\$187	\$187
	not with QA2/W75/W76		
W75	Step, wide, at rear end	\$308	\$308
	not with JB6/JB7/Q24/QA9; must have R91+R92		
W76	Bumper step, rear, spring-loaded	-	\$601
	must have R91+R92; not with JB6/JB7/X30/Q24		
W78	Heated rear window(s) w/ washers/wipers	\$335	\$335
	Must have H22+VA7 / if D51 must have F61; not with W61		
X90	Deletion of Sprinter badge, left rear door	\$0	\$0
X93	Deletion of model badge, right rear door	\$0	\$0
XM4	Acoustic package	\$87	\$87
	standard with C02/C03		
Y10	First-aid kit	\$27	\$27
Y26	Wheel chocks	\$38	\$38
Y45	Emergency flashlight	\$27	\$27
Y68	Paint preservative	\$187	\$212
Y69	Surface protection for stock vehicles	\$315	\$315
YK3	Cargo straps, D-rings	\$81	\$81
	0   1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -	T ==	7

### 3500XD CREW VAN - 4cyl Diesel Packages

144" 4C	170" 4C
MXCV44	MXCV74
907.653	907.655

C00	Comfort Package	\$300	\$300
LC4	Comfort overhead control panel	Х	Х
SE4	Lumbar support, co-driver's seat	Х	Х
SE5	Lumbar support, driver's seat	Х	Х
SK0	Comfort head restraint, driver	Х	Х
SK1	Comfort head restraint, co-driver	Х	Х
S28	Armrest, driver and passenger door	Х	X
must	have COS OR X68; CA/CC only: not with S23		

COS	Comfort Package (Seat addition)	\$381	\$381	
SB1	Comfort driver's seat	X	X	
SB2	Comfort passenger seat	Х	X	
must	must have COO			

X68	Comfort Plus Package	\$1,923	\$1,923	
H15	Heated front passenger seat	X	X	
H16	Heated driver's seat	Х	X	
SF1	Driver's seat electrically adjustable	Х	Х	
SF2	Co-driver's seat electrically adjustable	Х	Х	
must	must have COO and VF4 OR VF6, CA/CC only: not with S23			

C01	Driver Convenience Package	\$760	\$760
E46	12 V power outlet, driver seat base	X	Х
F64	Electrically folding exterior mirrors	X	X
FJ1	Hinged lid for storage compartment	Х	Х
FJ5	Hinged Lid for Storage Compartments left and right	Х	Х
FZ9	Keys, two additional masters	X	X
JA7	Blind Spot Assist	X	X
JW8	Attention Assist	Х	Х

C02	Premium Package	\$983	\$983	
CL3	Leather steering wheel	X	X	
E3M	MBUX Multimedia System with 7" touchscreen	X	Х	
FM3	Wet Wiper System	Х	Х	
JB4	Active Lane Keeping Assist	Х	X	
JK5	Instrument cluster with color display	Х	Х	
Ordor	Ordering qualified restricted see Notice for qualified and restrictions I must be use IEL VMA must about			

Ordering availability restricted, see NetStar for availability and restrctions|must have JF1 + XM4; must choose FR8/JB7

CA2	C02 in combination with C03	\$604	\$604	
CL3	Leather steering wheel	X	Х	
FM3	Wet Wiper System	Х	X	
JB4	Active Lane Keeping Assist	Х	Х	
JK5	Instrument cluster with color display	Х	Х	
Order	Ordering availability restricted, see NetStar for availability and restrctions must have CO3 + JF1			

### 3500XD CREW VAN - 4cyl Diesel Packages

144" 4C	170" 4C
MXCV44	MXCV74
907.653	907.655

C03	Premium Plus Package	\$1,793	\$1,793
E1B	Tray for smartphones incl. wireless charging	X	X
	Navigation	X	X
EY2	Intelligent navigation	X	X
E4M	MBUX Multimedia System with 10.25" touchscreen	X	X
EX9	Free map data updates for 3 years	X	X
H1I	Front-to-rear outlet in instrument panel	X	X
JA9	Traffic Sign Assist	X	X
XM4	Acoustic package	X	X
must	have (CA2+JB7) OR (JB4+JK5+FM3+JB7); not with FR8 and CO2	•	

X67	Chrome Grille Package	\$290	\$290	
CN2	Radiator grille frame in vehicle color	X	X	
FK3	Chrome plated radiator grille (MB only)	Х	X	
no res	no restrictions			

X13	Exterior Lighting Package	\$1,608	\$1,608			
L13	Fog lamp with cornering light function	X	Х			
L22	Partial LED tail lights	Х	Х			
LA1	High beam assist	Х	Х			
LG7	LED high performance headlamps	Х	Х			
no res	no restrictions					

X72	Crew Van Comfort Package	\$220	\$220		
S31	Convenice head restraints for pass. compartment	X	Х		
UY1	3-seater comfort bench rear, 1st row (narrow)	X	Х		
can h	can have VF4/VF6 only				

### 3500XD CREW VAN - 6cyl Diesel

Standard Equipment

		144'' 6C	144" 6C 4x4	170" 6C	170" 6C 4x4
		MXCV46	MXCV4X	MXCV76	MXCV7X
		907.653	907.653	907.655	907.655
Francis				1	
Engin	e Engine/7-Speed Trans.	S	S	S	S
ED4	AGM battery 12V 92 AH 850 A	S S	S	S	S
G42	Automatic transmission, 7G-tronic	S	S	S	S
	SULEV emissions	S	S	S	S
	3.0L V6 turbo diesel engine	S	S	S	S
	Alternator 14 V/220 A	S	S	S	S
	4x4 Package	-	\$8,200	-	\$8,200
T75	Door-mounted assist handles, driver & passenger	-	\$ S	-	S S
$\vdash$	4x4 - High range transfer case w/ low gear	-	S	-	S
	- choose while ordering				
X34	Dual Rear Wheel	\$0	<i>\$0</i>	<i>\$0</i>	\$0
	Tires LT 215/85 R16	S	S	S	S
	5.5 J x 16 steel wheels	S	S	S	S
RD9	Unspecified tire brand	S	S	S	S
X31	Super Single Tire	\$385	-	\$385	-
R9A	285/65 R 16 C super single tires	0	-	0	-
RS5	Steel wheels: 8.5Jx16 Rr; 6.5Jx16 Fr	0	-	0	-
RD9	Unspecified tire brand	0	-	0	-
RY2	Tire pressure monitoring sensors	0	-	0	-
Seatii	ng and Trim Packages				
X7S	Standard Rear Seats	S	S	S	S
U62	3-seater bench rear, 1st row (narrow)	S	S	S	S
U74	Wall-side armrest	S	S	S	S
U75	Aisle-side armrest	S	S	S	S
can h	ave VF7/VF6 only; with X68 must have VF6				
X2V	Standard Trim Crew Van Package	S	S	S	S
V25	Half height load compartment trim	S	S	S	S
V35	Wheel house covering	S	S	S	S
	Wood floor with 6 D-rings	S	S	S	S
	production only				
Equip			_		
	Axle ratio 3.923	0	S	0	S
_	Axle ratio 4.182	S	-	S	-
	Active Brake Assist	S	S	S	S
BH1	Hold Function	S	S	S	S
	Stabilization Level II	S	-	S	-
	Multifunction steering wheel	S	S	S	S
CL1	Adjustable steering wheel (angle)	S	S	S	S
D03	High roof	0	0	S	S
D93	Omission bulkhead	S	S	S	S
E07	Hill Start Assist	S	S	S	S
E10	Standard radio	S S	S S	S S	S
E1U E30	USB-C socket, 5 V Starter battery disconnect	S S	S	S	S S
E3J	Pre-installation for switch panel	S	-	S	5
E40	Trailer hitch prep. wiring	S	S	S	S
ED8	Preinstallation PSM	S	S	S	S
EE5	Ultracapacitor discharge module	S	S	S	S
EK1	Body Builder Connector	S	S	S	S
ESO	Jump start terminal	S	S	S	S
EW6	Pre-installation for Mercedes me Remote Services	S	S	S	S
EY5	Emergency Call System	S	S	S	S
EY6	Breakdown management	S	S	S	S
F43	Laminated glass rear	S	S	S	S
F68	Heated & electrically adjustable exterior mirrors	S	S	S	S
FF3	Cupholder rear compartment	S	S	S	S
1.12	capholaci real compartificit	3	,	3	3

### 3500XD CREW VAN - 6cyl Diesel

Standard Equipment

	144" 6C 144" 6C 4x4 170" 6C 170" 6C 4x4				
		MXCV46	MXCV4X	MXCV76	MXCV7X
		907.653	907.653	907.655	907.655
FF5	Shelf above windshield	S	S	S	S
	Cupholder front	S	S	S	S
FI1	Remote key (315 mhz) w/central locking	S	S	S	S
FJ4	Storage compartment underneath cockpit	S	S	S	S
FR3	Rear view camera (rear-view mirror display)	S	S	S	S
H00	Warm/cool air duct to rear compartment	S	S	S	S
H21	Windshield with filter band	S	S	S	S
H22	Rear window defroster	S	S	S	S
HH2	Heater, auxiliary electric hot air	S	S	S	S
_	Air Condition, Front	S	S	S	S
IH7	Head Unit, North America	S	S	S	S
J11	Speedometer, miles and km/h	S	S	S	S
J55	Seat belt warning for co-driver seat	S	S	S	S
J58	Seat belt reminder driver	S	S	S	S
J65	Outside temperature gauge	S	S	S	S
JA8	Crosswind Assist	S	S	S	S
JH3	Communication module (LTE) for dig. services	S	S	S	S
JI9	Service interval 20.000 miles	S	S	S	S
	Red diesel filler cap	S	S	S	S
	Exhaust straight to rear	S	S	S	S
KB7	24.5 gallon fuel tank	S	S	S	S
KL1	Aux fuel sending unit w/ fuel tap	S	S	S	S
KL5	Fuel filter with water separator	S	S	S	S
KP6	3rd generation SCR emission control system	S	S	S	S
L94	Parking lights deletion	S	S	S	S
LA2	Headlight assistant	S	S	S	S
LB5	3rd brake light	S	S	S	S
	Cruise control	S	S	S	S
	Front mudflaps	S	S	S	S
	Rear mudflaps	S	S	S	S
Q11	Longitudinal member reinforcement	S	S	S	S
	Spare tire bracket below frame	S	S	S	S
R87	Spare tire	S	S	S	S
	All-season tires	S	S	S	S
	Standard driver seat	S	S	S	S
	Standard front passenger seat	S	S	S	S
S22	Armrest for driver's seat	S	S	S	S
S25	Armrest for front passenger seat	S	S	S	S
	Front airbag, driver	S	S	S	S
<b>I</b>	Front airbag, passenger	S	S	S	S
SH1	Thorax-pelvis sidebag, driver	S	S	S	S
SH2	Thorax-pelvis sidebag, co-driver	S	S	S	S
	Airbag, driver/passenger window	S	S	S	S
SK2	Seat occupancy sensor, driver's seat	S	S	S	S
_	Sliding door, passenger side	S	S	S	S
_	Assist handle, B-pillar	S	S	S	S
U22	Pre-inst. for seating configuration Crew Van	S	S	S	S
V36	Roof trim	S	S	S	S
	Floor anchors for rear seat bench	S	S	S	S
_	Storage compart. w/ net in rear doors	S	S S	S	S
	2nd row, fixed window, driver side	S	S S	S	S
_	2nd row, fixed window, driver side 2nd row, fixed window, passenger side		1	S	
_		S	S	_	S
	Windows in rear doors	S	S	S	S
	Black tinting (90%) for rear windows	S	S	S	S
	Witout load uprating/derating 5,000 kg	S	S	S	S
Y43	Jack, hydraulic	S	S	S	S

Options

		144" 6C	144" 6C 144" 6C 4x4	170" 6C	170" 6C 4x4 MXCV7X 907.655
		MXCV46	MXCV4X	MXCV76	
		907.653	907.653	907.655	
۸۲۵	Front axle reinforced	¢246		¢246	
A50 AP2	Addtl. bar for driveshaft & exhaust extension	\$346 \$69	\$69	\$346 \$69	\$69
APZ AR2	Axle ratio 3.923	\$0	\$69 S	\$09 \$0	\$69 \$
ANZ	not with AR3	γU	3	<b>90</b>	3
B01	ESP for increased Center of Gravity above 39.4"	-	_	\$0	\$0
501	must have CB4/CB8/X30; not with RH0/CB7			Ψ0	μ γο
C72	Bumpers front/rear primed	\$268	\$268	\$268	\$268
	must have CN2/X67, not with CM0	,	,	,	,
CL3	Leather steering wheel	\$187	\$187	\$187	\$187
	must have (C02/E3M)/C03 + (ET4/MS1)				•
CM0	Painted metallic front & rear bumper	\$587	\$587	\$587	\$587
	must have (CN2/X67) + (JA7/C01) + JB7 + (7755/9197/9775)	•	•		•
CM9	Primed side moldings	\$364	\$364	\$364	\$364
D03	High roof	\$2,900	\$2,900	S	S
	D03 must be added for Duesseldorf production	-			
D13	Mounting rails for roof rack	\$300	\$300	\$300	\$300
E1B	Tray for smartphones incl. wireless charging	\$156	\$156	\$156	\$156
	must have CO2/E3M + H1I				
E1E	Navigation	\$728	\$728	\$728	\$728
	must have C02/E3M, not with C03				
E1S	Sirius XM, satellite radio	\$255	\$255	\$255	\$255
	must have C02/E3M/C03		1		•
E1R	Additional Fuses (40/80/150/100 Ampere)	\$50	\$50	\$50	\$50
	SoP and Plausibility TBD				•
E1Y	Additional Fuses (40/80/80/100 Ampere)	\$50	\$50	\$50	\$50
	SoP and Plausibility TBD				_
E2A	Access point for BB special signals in cockpit	\$29	\$29	\$29	\$29
E2I	Additional battery, co-driver seat base	\$248	\$248	\$248	\$248
	Must have E36; not with E2M; CHS production only				
E36	Cutoff relay for additional battery	\$110	\$110	\$110	\$110
	standard with E2I/E2M	4	1 4	4	1 4
E3M	MBUX Multimedia System with 7" touchscreen	\$474	\$474	\$474	\$474
5534	not with CO2/CO3; must have JK5+(JB7/FR8)	ģ.	450	ģ.	450
E5M	Extension of PSM standard contact	\$58	\$58	\$58	\$58
ED5	Parametric special module (PSM) not with ED8	\$317	\$317	\$317	\$317
EE3	115 V socket	\$125	\$125	\$125	\$125
ES2	12 V power outlet, rear compartment	\$92	\$123	\$123	\$123
ES5	Charging package, dashboard	\$82	\$82	\$82	\$82
ET4	Active Distance Assist DISTRONIC	\$263	\$263	\$263	\$263
	must have CO2/CO3/E3M; not with ZH4	γ=00	Ψ200	Ψ=00	<b>7</b> 200
F49	Electrically heated windshield	\$218	\$218	\$218	\$218
	no restrictions			,	·
F61	Interior rear view mirror	\$36	\$36	\$36	\$36
	must have E3M/C02/C03	•	•	•	•
FE9	Additional DIN-slot	\$81	\$81	\$81	\$81
FF8	Overhead storage slot, front center	\$105	\$105	\$105	\$105
FJ1	Hinged lid for storage compartment	\$93	\$93	\$93	\$93
FR8	Rear view camera (head unit display)	\$336	\$336	\$336	\$336
	must have CO2/E3M; not with FR3/JB7; 3500XD not with JB8				
FY1	Security alarm w. interior motion sensor	\$584	\$584	\$584	\$584
	must have LC4/C00				
FY7	Optional 3-button keys	\$36	\$36	\$36	\$36
FZ9	Keys, two additional masters	\$121	\$121	\$121	\$121
H01	Heat insulation, rear compartment	\$156	\$156	\$156	\$156
	must have V25/VA3/VA1/C07/X66				
H04	Heat insulation, front compartment	\$187	\$187	\$187	\$187
	if + D50/D51 must have V07				

Options

		144" 6C	144" 6C 4x4	170" 6C	170" 6C 4x4
		MXCV46	MXCV4X	MXCV76	MXCV7X
		907.653	907.653	907.655	907.655
H12	Fuel-fired pre-heater/booster (17K BTU)	\$1,116	\$1,116	\$1,116	\$1,116
	not with HZ9	4	T 4	4	1
H13	Rear cabin heater and vents	\$786	\$786	\$786	\$786
	must have V43 + (H12/HZ9); not with VK8	4004	4004	4004	1 4004
H15	Heated front passenger seat	\$284	\$284	\$284	\$284
111.0	must have H16; not with X68	¢204	6204	ć204	6204
H16	Heated driver's seat  must have H15; not with X68	\$284	\$284	\$284	\$284
H88	Rear heater prep	\$405	\$405	\$405	\$405
1100	must have H12/HZ9; not with H13/T19	Ş <del>4</del> 03	Ş <del>4</del> 03	Ş <del>4</del> 05	Ş <del>4</del> 03
H1I	Front-to-rear outlet in instrument panel	\$0	\$0	\$0	\$0
1111	must have FJ1/C01	70	γo	γo	٥٦
HH4	Thermotronic automatic climate control	\$337	\$337	\$337	\$337
<del></del>	must have JF1; if +H13 must have H08/HK4	<b>,</b>	φου,	φου,	φουν
HZ9	Fuel-fired heater booster (18,000 BTU)	\$676	\$676	\$676	\$676
	not with H12	1			
J51	Fuel gauge, optimized for aux. fuel tap	\$72	\$72	\$72	\$72
	not with HZ9/H12				
J52	Engine oil level display at cold start	\$0	\$0	\$0	\$0
JA7	Blind Spot Assist	\$450	\$450	\$450	\$450
	must have F68; not with C01				
JB4	Active Lane Keeping Assist	\$288	\$288	\$288	\$288
	standard with C02/CA2	·			
JB7	Parking Package	\$615	\$615	\$615	\$615
	must have E3M/C02/C03; not with W75/W76/JB6				
JF1	Rain sensor	\$106	\$106	\$106	\$106
JK5	Instrument cluster with color display	\$144	\$144	\$144	\$144
	not with CO3		T 4	4	1 4
-	Backup alarm	\$99	\$99	\$99	\$99
	Deactivation lamp monitoring failure	\$27	\$27	\$27	\$27
	Attention Assist	\$49	\$49	\$49	\$49
	Misfueling prevention for Diesel  DEF fluid filler cap - lockable	\$49 \$27	\$49 \$27	\$49 \$27	\$49 \$27
L13	Fog lamp with cornering light function	\$199	\$27 \$199	\$27 \$199	\$27 \$199
LB9	Illuminated front exits	\$151	\$155	\$151	\$155
	Comfort overhead control panel	\$93	\$93	\$93	\$93
_	Speed limitation 65 mph	\$60	\$60	\$60	\$60
11120	not with MD3	Ŷ	γoo	ΨOO	γου
MD3	Top speed limitation 75 mph	\$60	\$60	\$60	\$60
	not with M20	, , , , , , , , , , , , , , , , , , ,	,	,	·
N62	Front engine bracket for additional alternator	\$467	\$467	\$467	\$467
	not with HK4/N63				
N63	Front engine bracket for auxiliary A/C compressor	\$467	\$467	\$467	\$467
	not with HK4/N62				
QA2	Trailer cross member 7,500 lbs capacity	\$186	\$186	\$186	\$186
	not with W73/W75/W76/Q24/Q67				
QA9	Half-sided step rear (for trailer hitch)	\$101	\$101	\$101	\$101
	must have QA2; not with W73/W75/W76				
R91	Spare tire deletion	-\$110	-\$110	-\$110	-\$110
	must have R92; not with R87				
R92	Spare tire carrier deletion	\$0	\$0	\$0	\$0
<u> </u>	must have R91; not with R65	<u> </u>			
R98	Rims painted jet black	\$81	\$81	\$81	\$81
	not with RL5/RM2		1		
RF1	Tire brand Continental	\$0	\$0	\$0	\$0
D50	must have RM1 + RM9	4.5	40	40	40
RF8	Tire brand Michelin	\$0	\$0	\$0	\$0
<u> </u>	must have RM9; not with RM1				

**3500XD CREW VAN - 6cyl Diesel**Options

	144" 6C			170" 6C 4x4
	MXCV46	MXCV4X	MXCV76	MXCV7X
	907.653	907.653	907.655	907.655
rand Kumho	\$0	\$0	\$0	\$0
have RM9; not with RM1	1 4:	1 4 1	4	1
winter tires	\$169	\$169	\$169	\$169
have RF1/RD9; not with RF8/RH0/X31	604	T 404 T	<b>604</b>	404
painted arctic white	\$81	\$81	\$81	\$81
vith R98/RL5	¢101	Ć101	¢101	¢101
ally requested tires	\$101	\$101	\$101	\$101
have RF1/RF8/RH0; not with RD9	\$51	\$51	\$51	\$51
est, driver and passenger door	\$82	\$82	\$82	\$82
g door two stage opening vith T55	Ş0Z	<b>ఫ</b> 02	<b>302</b>	Ş6Z
ric closing assist right sliding door	\$335	\$335	\$335	\$335
have DO3; not with T55/T93	2333	رددد	7333	7333
ric sliding door right	\$831	\$831	\$831	\$831
have D03 + (FY7+T16); not with T12/T50	\$631	\$831	\$831	\$831
	¢1.071	¢1 071	¢1 071	¢1 071
ric sliding step	\$1,071	\$1,071	\$1,071	\$1,071
have D03 + ED5; not with T93	ć120	ć120	Ć430	¢120
ing limiter electrically operated sliding door	\$120	\$120	\$120	\$120
have T55	Ġ.F.O.		ģ.	
mounted assist handles, driver & passenger	\$59	S	\$59	\$
handle, left rear door	\$32	\$32	\$32	\$32
handles, right rear door	\$32	\$32	\$32	\$32
d floor with 6 D-rings	\$422	\$422	\$422	\$422
rith P93/V93/VL4/VK8/C07; standard with D93/H13/V24/V5		1 4 1	4	100
ette lighter & ash cup, front	\$39	\$39	\$39	\$39
sill - protective edge	\$71	\$71	\$71	\$71
have V43/X66; not with T19/T93/VK8/VV2/V93/C07	40-0	1 4 1	4	1
covering, plastic	\$370	\$370	\$370	\$370
rith V43/P93/T19/T93/V52/VC5/X66	4	4	4	4
doors, opening to side wall	\$360	\$360	\$360	\$360
gree fixation point- Rear Doors	\$80	\$80	\$80	\$80
nd Plausibility TBD	1 .			
per step, rear, grey	\$187	\$187	\$187	\$187
ith QA2/W75/W76				
wide, at rear end	\$308	-	\$308	-
rith JB6/JB7/Q24/QA9; must have R91+R92				
per step, rear, spring-loaded	-	-	\$601	-
have R91+R92; not with JB6/JB7/X30/Q24				
ed rear window(s) w/ washers/wipers	\$335	\$335	\$335	\$335
have H22+VA7 / if D51 must have F61; not with W61				
ion of Sprinter badge, left rear door	\$0	\$0	\$0	\$0
ion of model badge, right rear door	\$0	\$0	\$0	\$0
stic package	\$87	\$87	\$87	\$87
ard with CO2/CO3				
aid kit	\$27	\$27	\$27	\$27
el chocks	\$38	\$38	\$38	\$38
gency flashlight	\$27	\$27	\$27	\$27
preservative	\$187	\$187	\$212	\$212
ce protection for stock vehicles	\$315	\$315	\$315	\$315
straps, D-rings	\$81	\$81	\$81	\$81
hill speed regulation for 4x4	-	\$58	-	\$58
preserv ce prote straps, hill spe	ative ection for stock vehicles D-rings	ative \$187 ection for stock vehicles \$315  D-rings \$81 ed regulation for 4x4 -	sative         \$187         \$187           ection for stock vehicles         \$315         \$315           D-rings         \$81         \$81           ed regulation for 4x4         -         \$58	sative         \$187         \$187         \$212           ection for stock vehicles         \$315         \$315         \$315           D-rings         \$81         \$81         \$81           ed regulation for 4x4         -         \$58         -

### 3500XD CREW VAN - 6cyl Diesel

Packages

		144" 6C	144" 6C 4x4	170" 6C	170" 6C 4x4
		MXCV46	MXCV4X	MXCV76	MXCV7X
		907.653	907.653	907.655	907.655
C00	Comfort Package	\$300	\$300	\$300	\$300
LC4	Comfort overhead control panel	Х	Х	Х	Х
SE4	Lumbar support, co-driver's seat	X	Х	Х	Х
SE5	Lumbar support, driver's seat	X	Х	Х	Х
SK0	Comfort head restraint, driver	X	Х	Х	Х
SK1	Comfort head restraint, co-driver	X	Х	Х	Х
S28	Armrest, driver and passenger door	X	Х	Х	Х
must	have COS OR X68; CA/CC only: not with S23				

COS	Comfort Package (Seat addition)	\$381	\$381	\$381	\$381	
SB1	Comfort driver's seat	Х	Х	Х	X	
SB2	Comfort passenger seat	Х	Х	Х	X	
must	must have COO					

X68	Comfort Plus Package	\$1,923	\$1,923	\$1,923	\$1,923
H15	Heated front passenger seat	X	X	X	X
H16	Heated driver's seat	Х	X	X	Х
SF1	Driver's seat electrically adjustable	Х	Х	Х	Х
SF2	Co-driver's seat electrically adjustable	Х	Х	Х	Х
must	must have C00 and VF4 OR VF6, CA/CC only: not with S23				

C01	Driver Convenience Package	\$760	\$760	\$760	\$760
E46	12 V power outlet, driver seat base	Х	Х	Х	Х
F64	Electrically folding exterior mirrors	Х	X	Х	X
FJ1	Hinged lid for storage compartment	Х	X	Х	Х
FJ5	Hinged Lid for Storage Compartments left and right	Х	X	Х	X
FZ9	Keys, two additional masters	Х	X	Х	X
JA7	Blind Spot Assist	X	Х	Х	Х
JW8	Attention Assist	X	X	Х	Х

C02	Premium Package	\$983	\$983	\$983	\$983	
CL3	Leather steering wheel	Х	Х	Х	X	
E3M	MBUX Multimedia System with 7" touchscreen	Х	Х	Х	Х	
FM3	Wet Wiper System	Х	Х	Х	Х	
JB4	Active Lane Keeping Assist	Х	Х	Х	Х	
JK5	Instrument cluster with color display	X	Х	Х	X	
Order	Ordering availability restricted, see NetStar for availability and restrctions must have JF1 + XM4; must choose FR8/JB7					

CA2	C02 in combination with C03	\$604	\$604	\$604	\$604	
CL3	Leather steering wheel	Х	Х	Х	Х	
FM3	Wet Wiper System	Х	Х	Х	Х	
JB4	Active Lane Keeping Assist	Х	Х	Х	Х	
JK5	Instrument cluster with color display	Х	Х	Х	Х	
Order	Ordering availability restricted, see NetStar for availability and restrctions must have CO3 + JF1					

### 3500XD CREW VAN - 6cyl Diesel Packages

 144" 6C
 144" 6C 4x4
 170" 6C
 170" 6C 4x4

 MXCV46
 MXCV4X
 MXCV76
 MXCV7X

 907.653
 907.655
 907.655

C03	Premium Plus Package	\$1,793	\$1,793	\$1,793	\$1,793
E1B	Tray for smartphones incl. wireless charging	X	Х	Х	X
	Navigation	Х	Х	Х	X
EY2	Intelligent navigation	Х	Х	Х	X
E4M	MBUX Multimedia System with 10.25" touchscreen	Х	Х	Х	X
EX9	Free map data updates for 3 years	Х	Х	Х	X
H1I	Front-to-rear outlet in instrument panel	Х	Х	Х	X
JA9	Traffic Sign Assist	Х	Х	Х	X
XM4	Acoustic package	Х	Х	Х	Х
must	have (CA2+JB7) OR (JB4+JK5+FM3+JB7); not with FR8 and CO2				

X67	Chrome Grille Package	\$290	\$290	\$290	\$290		
CN2	Radiator grille frame in vehicle color	X	X	X	Х		
FK3	Chrome plated radiator grille (MB only)	X	X	X	X		
no res	no restrictions						

X13	Exterior Lighting Package	\$1,608	\$1,608	\$1,608	\$1,608	
L13	Fog lamp with cornering light function	X	X	X	X	
L22	Partial LED tail lights	Х	Х	Х	X	
LA1	High beam assist	Х	Х	Х	Х	
LG7	LED high performance headlamps	Х	Х	Х	X	
no res	no restrictions					

X72	Crew Van Comfort Package	\$220	\$220	\$220	\$220	
S31	Convenice head restraints for pass. compartment	Х	Х	Х	X	
T12	Sliding door two stage opening	Х	Х	Х	X	
T50	Electric closing assist right sliding door	Х	Х	Х	X	
UY1	3-seater comfort bench rear, 1st row (narrow)	Х	Х	Х	Х	
can h	can have VF4/VF6 only					

Standard Equipment

144" 4C

170" 4C

		144 4C	170 4C
		M4CV44	M4CV74
		907.653	907.655
Engin			
4-Cyl	Engine/7-Speed Trans.	5	5
ED4	AGM battery 12V 92 AH 850 A	S	S
G42	Automatic transmission, 7G-tronic	S	S
M40	Alternator 14 V / 200 A	S	S
-	2.0L 4-cylinder diesel engine	S	S
	SULEV emissions	S	S
	ng and Trim Packages	_	
	Standard Rear Seats	S	5
		S	S
	3-seater bench rear, 1st row (narrow)		
_	Wall-side armrest	S	S
	Aisle-side armrest	S	S
	ave VF7/VF6 only; with X68 must have VF6	ī	
-	Standard Trim Crew Van Package	S	S
V25	Half height load compartment trim	S	S
V35	Wheel house covering	S	S
V43	Wood floor with 6 D-rings	S	S
CHS p	production only		
Equip	ment		
	Front axle reinforced	S	S
-	Axle ratio 4.182	S	S
	Active Brake Assist	S	S
$\vdash$	Hold Function	S	S
$\vdash$	Multifunction steering wheel	S	S
	Stabilization Level II	S	S
CL1	Adjustable steering wheel (angle)	S	S
-	High roof	0	S
D93	Omission bulkhead	S	S
E07	Hill Start Assist	S	S
E10	Standard radio	S	S
E1U	USB-C socket, 5 V	S	S
E30	Starter battery disconnect	S	S
E3J	Pre-installation for switch panel	S	S
E40	Trailer hitch prep. wiring	S	S
	Preinstallation PSM	S	S
EE5	Ultracapacitor discharge module	S	S
$\vdash$			S
EK1	Body Builder Connector	S	
ES0	Jump start terminal	S	S
$\overline{}$	Pre-installation for Mercedes me Remote Services	S	S
EY5	Emergency Call System	S	S
EY6	Breakdown management	S	S
F43	Laminated glass rear	S	S
F68	Heated & electrically adjustable exterior mirrors	S	S
FF3	Cupholder rear compartment	S	S
FF5	Shelf above windshield	S	S
FG8	Cupholder front	S	S
FI1	Remote key (315 mhz) w/central locking	S	S
FJ4	Storage compartment underneath cockpit	S	S
FR3	Rear view camera (rear-view mirror display)	S	S
$\vdash$			S
H00	Warm/cool air duct to rear compartment	S	
H21	Windshield with filter band	S	S
H22	Rear window defroster	S	S
HH2	Heater, auxiliary electric hot air	S	S
HH9	Air Condition, Front	S	S
-	the transfer of the transfer o		S
IH7	Head Unit, North America	S	3
	Speedometer, miles and km/h	S	<u> </u>

### Standard Equipment

		144" 4C	170" 4C
		M4CV44	M4CV74
		907.653	907.655
J58	Seat belt reminder driver	S	S
J65	Outside temperature gauge	S	S
JA8	Crosswind Assist	S	S
JH3	Communication module (LTE) for dig. services	S	S
JI9	Service interval 20.000 miles	S	S
K56	Red diesel filler cap	S	S
K60	Exhaust straight to rear	S	S
KB7	24.5 gallon fuel tank	S	S
KL1	Aux fuel sending unit w/ fuel tap	S	S
KL5	Fuel filter with water separator	S	S
KP6	3rd generation SCR emission control system	S	S
L94	Parking lights deletion	S	S
LA2	Headlight assistant	S	S
LB5	3rd brake light	S	S
MS1	Cruise control	S	S
P47	Front mudflaps	S	S
P48	Rear mudflaps	S	S
Q11	Longitudinal member reinforcement	S	S
R65	Spare tire bracket below frame	S	S
R87	Spare tire	S	S
RH7	Tires LT 215/85 R16	S	S
RD9	Unspecified tire brand	S	S
RM0	All-season tires	S	S
RS6	5.5 J x 16 steel wheels	S	S
S02	Standard driver seat	S	S
S04	Standard front passenger seat	S	S
S22	Armrest for driver's seat	S	S
S25	Armrest for front passenger seat	S	S
SA5	Front airbag, driver	S	S
SA6	Front airbag, passenger	S	S
SH1	Thorax-pelvis sidebag, driver	S	S
SH2	Thorax-pelvis sidebag, co-driver	S	S
SH9	Airbag, driver/passenger window	S	S
SK2	Seat occupancy sensor, driver's seat	S	S
T16	Sliding door, passenger side	S	S
T74	Assist handle, B-pillar	S	S
U22	Pre-inst. for seating configuration Crew Van	S	S
V36	Roof trim	S	S
V40	Floor anchors for rear seat bench	S	S
VA7	Storage compart. w/ net in rear doors	S	S
W16	2nd row, fixed window, driver side	S	S
W17	2nd row, fixed window, passenger side	S	S
W61	Windows in rear doors	S	S
W70	Black tinting (90%) for rear windows	S	S
XL4	GVWR 12,125 lbs. / 5.500 Kg	S	S
Y43	Jack, hydraulic	S	S

**V VAN - 4cy** Options

		144" 4C	170" 4C	
		M4CV44	M4CV74 907.655	
		907.653		
AP2	Addtl. bar for driveshaft & exhaust extension	\$69	\$69	
AR2	Axle ratio 3.923	\$0	\$0	
	not with AR3	·	· ·	
B01	ESP for increased Center of Gravity above 39.4"	-	\$0	
	must have CB4/CB8/X30; not with RH0/CB7			
C72	Bumpers front/rear primed	\$268	\$268	
	must have CN2/X67, not with CM0			
CL3	Leather steering wheel	\$187	\$187	
	must have (C02/E3M)/C03 + (ET4/MS1)			
CM0	Painted metallic front & rear bumper	\$587	\$587	
	must have (CN2/X67) + (JA7/C01) + JB7 + (7755/9197/9775)			
CM9	Primed side moldings	\$364	\$364	
D03	High roof	\$2,900	S	
	D03 must be added for Duesseldorf production			
D13	Mounting rails for roof rack	\$300	\$300	
E1B	Tray for smartphones incl. wireless charging	\$156	\$156	
	must have CO2/E3M + H1I			
E1E	Navigation	\$728	\$728	
	must have CO2/E3M, not with CO3			
E1S	Sirius XM, satellite radio	\$255	\$255	
	must have CO2/E3M/CO3			
E1R	Additional Fuses (40/80/150/100 Ampere)	\$50	\$50	
	SoP and Plausibility TBD			
E1Y	Additional Fuses (40/80/80/100 Ampere)	\$50	\$50	
	SoP and Plausibility TBD			
E2A	Access point for BB special signals in cockpit	\$29	\$29	
E2I	Additional battery, co-driver seat base	\$248	\$248	
	Must have E36; not with E2M; CHS production only			
E36	Cutoff relay for additional battery	\$110	\$110	
	standard with E2I/E2M			
E3M	MBUX Multimedia System with 7" touchscreen	\$474	\$474	
	not with CO2/CO3; must have JK5+(JB7/FR8)			
E5M	Extension of PSM standard contact	\$58	\$58	
ED5	Parametric special module (PSM)	\$317	\$317	
	not with ED8	4405	4405	
EE3	115 V socket	\$125	\$125	
ES2	12 V power outlet, rear compartment	\$92	\$92	
ES5	Charging package, dashboard	\$82	\$82	
ET4	Active Distance Assist DISTRONIC	\$263	\$263	
F40	must have CO2/CO3/E3M; not with ZH4	¢210	¢240	
F49	Electrically heated windshield	\$218	\$218	
F.C.1	no restrictions	\$36	626	
F61	Interior rear view mirror	\$30	\$36	
FE9	must have E3M/C02/C03 Additional DIN-slot	\$81	\$81	
FF8	Overhead storage slot, front center	\$105	\$105	
FJ1	Hinged lid for storage compartment	\$93	\$93	
FR8	Rear view camera (head unit display)	\$336	\$336	
1110	must have CO2/E3M; not with FR3/JB7; 3500XD not with JB8	\$330	<del>-</del>	
FY1	Security alarm w. interior motion sensor	\$584	\$584	
	must have LC4/C00	7504	7304	
FY7	Optional 3-button keys	\$36	\$36	
FZ9	Keys, two additional masters	\$121	\$121	
H01	Heat insulation, rear compartment	\$156	\$156	
. 101	must have V25/VA3/VA1/C07/X66	7130	7130	
H04	Heat insulation, front compartment	\$187	\$187	
		7107	7107	

not with RL5/RM2  RF1 Tire brand Continental \$0 \$0  must have RM1 + RM9					
### ### ### ### ### ### ### ### ### ##			144" 4C	170" 4C	
H12   Fuel-fired pre-heater/booster (17K BTU)			M4CV44	M4CV74	
			907.653	907.655	
13   Rear cabin heater and vents   must have W3 + (H12/H29); not with VK8   H15   Heated front passenger seat   must have W3 + (H12/H29); not with VK8   H16   Heated driver's seat   must have H16; not with K68   must have H16; not with K68   H16   Heated driver's seat   S284   S284   S284   must have H16; not with K68   H16   Heated driver's seat   S284   S284   S284   Must have H16; not with K68   H16   Heated driver's seat   S284   S284   S284   S284   Must have H16; not with K68   H16   H	H12	Fuel-fired pre-heater/booster (17K BTU)	\$1,116	\$1,116	
### ### ### ### ### ### ### ### ### ##			, , ,	. ,	
### ### ### ### ### ### ### ### ### ##	H13	Rear cabin heater and vents	\$786	\$786	
### ### ### ### ### ### ### ### ### ##		must have V43 + (H12/HZ9); not with VK8	•	•	
### ### ### ### ### ### ### ### ### ##	H15	Heated front passenger seat	\$284	\$284	
Must have H15; not with X68         \$405         \$405           H88 Rear heater prep must have H12/H29; not with H13/T19         \$405         \$50           H11 Front-to-rear outlet in instrument panel must have F11/C01         \$50         \$50           H14 Thermotronic automatic climate control must have F11/C01         \$337         \$337           H14 Thermotronic automatic climate control must have F11/C01         \$676         \$676           H14 Thermotronic automatic climate control must have F11/C01         \$676         \$676           H12 F12 F12         F12 F14/13 must have H08/HK4         \$676         \$676           H25 F14 F14 F13 must have H08/HK4         \$676         \$676         \$676           H25 F14 F14 F13 must have H08/HK4         \$676         \$676         \$676           H25 F14 F14 F14 M12         \$676 <t< td=""><td></td><td>must have H16; not with X68</td><td>•</td><td></td></t<>		must have H16; not with X68	•		
H88	H16	Heated driver's seat	\$284	\$284	
### ### ### ### ### ### ### ### ### ##		must have H15; not with X68			
H11   Front-to-rear outlet in instrument panel   \$0   \$0   mush have FIJ/COI	H88	Rear heater prep	\$405	\$405	
must have FJI/C01         \$337         \$337           HH4 Thermotronic automatic climate control must have #17; if +H13 must have #08/HK4         \$337         \$337           H29 Fuel-fired heater booster (18,000 BTU) not with H12         \$676         \$676           J51 Fuel gauge, optimized for aux. fuel tap not with H29/H12         \$72         \$72           J52 Engine oil level display at cold start         \$0         \$0           J47 Blind Spot Assist         \$450         \$450           J84 Active Lane Keeping Assist         \$288         \$288           stondard with C02/CA2         ***           J87 Parking Package must have E3M/C02/C03; not with W75/W76/JB6         \$615           J88 Insensor         \$106         \$106           J85 Instrument cluster with color display not with C03         \$144         \$144           JWO Backup alarm         \$99         \$99           JWO Backup alarm         \$99         \$99 </td <td></td> <td>must have H12/HZ9; not with H13/T19</td> <td></td> <td>_</td>		must have H12/HZ9; not with H13/T19		_	
HH4   Thermotronic automatic climate control	H1I	Front-to-rear outlet in instrument panel	\$0	\$0	
must have JF1; if +H13 must have H08/HK4         5676         \$676           H29 Fuel-fired heater booster (18,000 BTU)         \$676         \$676           not with H12		·			
H29   Fuel-fired heater booster (18,000 BTU)   S676   S676	HH4		\$337	\$337	
not with H12         571         Fuel gauge, optimized for aux. fuel tap not with H29/H12         \$72         \$72         not with H29/H12           152         Engine oil level display at cold start         \$0         \$0         \$10 <td></td> <td></td> <td></td> <td>1</td>				1	
151   Fuel gauge, optimized for aux. fuel tap	HZ9		\$676	\$676	
not with HZ9/H12         50         \$0           152         Engine oil level display at cold start         \$0         \$0           JA7         Blind Spot Assist         \$450         \$450           JB4         Active Lane Keeping Assist         \$288         \$288           standard with C02/CA2         \$288         \$288           JB7         Parking Package         \$615         \$615           must have E3M/CO2/CO3; not with W75/W76/JB6         \$106         \$106         \$106           JK5         Instrument cluster with color display         \$144         \$144           JK5         Instrument cluster with color display         \$144         \$144           JW0         Backup alarm         \$99         \$99           JW2         Deactivation lamp monitoring failure         \$27         \$27           JW0         Backup alarm         \$99         \$99           JW2         Deactivation lamp monitoring failure         \$27         \$27           JW0         Backup alarm         \$99         \$99           JW2         Deactivation lamp monitoring failure         \$27         \$27           JW1         Deactivation lamp monitoring failure         \$27         \$27           JW1         Sp6					
152   Engine oil level display at cold start   \$0 \$0 \$0 \$0	J51		\$72	\$72	
JA7   Blind Spot Assist		·			
JB4         Active Lane Keeping Assist         \$288         \$288           standard with CO2/CA2           JB7         Parking Package         \$615         \$615           must have E3M/CO2/CO3; not with W75/W76/JB6         \$106         \$106           JF1         Rain sensor         \$106         \$106           JK5         Instrument cluster with color display         \$144         \$144           not with CO3         not with CO3         \$99         \$99           JW0         Backup alarm         \$99         \$99           JW2         Deactivation lamp monitoring failure         \$27         \$27           JW2         Deactivation lamp monitoring failure         \$49         \$49           JW2         Deactivation lamp monitoring failure         \$27         \$27           JW8         Attention Assist         \$49         \$49           K51         Misfueling prevention for Diesel         \$49         \$49           K52         DEF fluid filler cap - lockable         \$27         \$27           L51         Misfueling prevention for Diesel         \$49         \$49           K52         DEF fluid filler cap - lockable         \$27         \$27           L13         Fog lamp with cornering light function </td <td></td> <td></td> <td></td> <td></td>					
Standard with CO2/CA2   Parking Package		·	·		
BF7   Parking Package   \$615   \$615	JB4		\$288	\$288	
must have E3M/Co2/Co3; not with W75/W76/IB6           JF1         Rain sensor         \$106         \$106           JKS         Instrument cluster with color display         \$144         \$144           JKS         Instrument cluster with color display         \$144         \$144           JKD         Instrument cluster with color display         \$144         \$144           JKD         Instrument cluster with color display         \$149         \$149           JW2         Deactivation lamp monitoring failure         \$27         \$27           JW2         Deactivation lamp monitoring failure         \$49         \$49           JW2         Deactivation lamp monitoring failure         \$49         \$49           JW2         Deactivation lamp monitoring failure         \$49         \$49           KS49         \$49         \$49         \$49           KS49         \$49         \$49         \$49           KS49         \$49         \$49         \$49         \$49           KS1         Misfuelling prevention for Diesel         \$27         \$27           LS2         Misfuelling prevention for Diesel         \$27         \$27           LS2         Eper fluid filler cap - lockable         \$319         \$199           <			4645	4645	
	JB/		\$615	\$615	
IKS   Instrument cluster with color display	154		¢100	¢100	
			· ·	· ·	
Section   Sect	JK2		\$144	\$144	
JW2         Deactivation lamp monitoring failure         \$27         \$27           JW8         Attention Assist         \$49         \$49           K51         Misfueling prevention for Diesel         \$49         \$49           K52         DEF fluid filler cap - lockable         \$27         \$27           L13         Fog lamp with cornering light function         \$199         \$199           L89         Illuminated front exits         \$151         \$151           LC4         Comfort overhead control panel         \$93         \$93           M20         Speed limitation 65 mph         \$60         \$60           not with MD3         NB3         Top speed limitation 75 mph         \$60         \$60           not with M20         NB467         \$467         \$467         \$467           N62         Front engine bracket for additional alternator         \$467         \$467         \$467           not with HK4/N63         ***         ***         \$467         \$467         \$467         \$467         ***         \$467         \$467         ***         \$467         ***         \$467         ***         \$467         ***         \$467         ***         \$467         ***         \$467         ***         \$467	114/0		¢00	¢00	
JW8       Attention Assist       \$49       \$49         K51       Misfueling prevention for Diesel       \$49       \$49         K52       DEF fluid filler cap - lockable       \$27       \$27         L33       Fog lamp with cornering light function       \$199       \$199         LB9       Illuminated front exits       \$151       \$151         COmfort overhead control panel       \$93       \$93         M20       Speed limitation 65 mph       \$60       \$60         not with MD3       \$93       \$93         MD3       Top speed limitation 75 mph       \$60       \$60         not with M20       \$60       \$60       \$60         N62       Front engine bracket for additional alternator       \$467       \$467         not with HK4/N63       \$467       \$467       \$467         N63       Front engine bracket for auxiliary A/C compressor       \$467       \$467         not with HK4/N62       \$186       \$186       \$186         QA2       Trailer cross member 7,500 lbs capacity       \$186       \$186         not with W73/W75/W76/Q24/Q67       \$10       \$101         QA3       Half-sided step rear (for trailer hitch)       \$101       \$101         must have R			· ·		
K51       Misfueling prevention for Diesel       \$49       \$49         K52       DEF fluid filler cap - lockable       \$27       \$27         L13       Fog lamp with cornering light function       \$199       \$199         LB9       Illuminated front exits       \$151       \$151         LC4       Comfort overhead control panel       \$93       \$93         M20       Speed limitation 65 mph       \$60       \$60         not with MD3       \$60       \$60         MD3       Top speed limitation 75 mph       \$60       \$60         not with M20       \$60       \$60         N62       Front engine bracket for additional alternator       \$467       \$467         not with HK4/N63       \$467       \$467       \$467         not with HK4/N63       \$186       \$186         N63       Front engine bracket for auxiliary A/C compressor       \$467       \$467         not with HK4/N63       \$186       \$186         N63       Front engine bracket for auxiliary A/C compressor       \$467       \$467         not with HK4/N63       \$186       \$186       \$186         not with W73/W75/W76/Q24/Q67       \$186       \$186       \$186         QA9       Half-sided step rear			· ·		
K52         DEF fluid filler cap - lockable         \$27         \$27           L13         Fog lamp with cornering light function         \$199         \$199           LB9         Illuminated front exits         \$151         \$151           LC4         Comfort overhead control panel         \$93         \$93           M20         Speed limitation 55 mph         \$60         \$60           not with MD3         Top speed limitation 75 mph         \$60         \$60           not with M20         ***         ***         \$467         \$467           N62         Front engine bracket for additional alternator         \$467         \$467         ***         ***           N63         Front engine bracket for auxiliary A/C compressor         \$467         \$467         ***         ***         ***         ***         ***         ***         ***         ***         ***         ***         ***         ***         ***         **         ***         ***         ** <td></td> <td></td> <td></td> <td></td>					
L13       Fog lamp with cornering light function       \$199       \$199         LB9       Illuminated front exits       \$151       \$151         LC4       Comfort overhead control panel       \$93       \$93         M20       Speed limitation 65 mph       \$60       \$60         not with MD3       MD3       Top speed limitation 75 mph       \$60       \$60         not with M20       N62       Front engine bracket for additional alternator       \$467       \$467         not with HK4/N63       N63       Front engine bracket for auxiliary A/C compressor       \$467       \$467         not with HK4/N62       N63       Front engine bracket for auxiliary A/C compressor       \$467       \$467         not with HK4/N62       N63       Front engine bracket for auxiliary A/C compressor       \$467       \$467         not with HK4/N62       N63       \$186       \$186         not with W73/W75/W76/Q24/Q67       N6467       N6467 <td colspan<="" td=""><td></td><td></td><td>·</td><td></td></td>	<td></td> <td></td> <td>·</td> <td></td>			·	
LB9       Illuminated front exits       \$151       \$151         LC4       Comfort overhead control panel       \$93       \$93         M20       Speed limitation 65 mph       \$60       \$60         not with MD3       ***Top speed limitation 75 mph       \$60       \$60         not with M20       ***Top speed limitation 75 mph       \$60       \$60         not with M20       ***Top speed limitation 75 mph       \$60       \$60         not with M20       ***Top speed limitation 75 mph       \$60       \$60         not with M20       ***Top speed limitation 75 mph       ***Speed limitation 75 mph       \$60       \$60         not with M20       ***Top speed limitation 75 mph       **\$\$ \$467         not with H20       ***Top speed limitation 75 mph       **\$\$ \$467         not with H24/N63       ***Top speed limitation 75 mph       **\$\$\$ \$186         not with H24/N63       ***Top speed limitation 75 mph       **\$\$\$\$\$\$ \$100       **\$		·	·	· ·	
LC4       Comfort overhead control panel       \$93       \$93         M20       Speed limitation 65 mph       \$60       \$60         not with MD3       MD3 Top speed limitation 75 mph       \$60       \$60         not with M20       N62       Front engine bracket for additional alternator       \$467       \$467         not with HK4/N63       N63       Front engine bracket for auxiliary A/C compressor       \$467       \$467         not with HK4/N62       N63       Panet with W73/W75/W76         QA2       Trailer cross member 7,500 lbs capacity       \$186       \$186         not with W73/W75/W76/Q24/Q67       QA9       Half-sided step rear (for trailer hitch)       \$101       \$101         must have QA2; not with W73/W75/W76       Spare tire deletion       -\$110       -\$110         must have R91; not with R65       R88       Rims painted jet black       \$81       \$81       \$81       \$81       \$81       \$81       \$81       \$81       \$81       \$81       \$81       \$81       \$81 <td colspa<="" td=""><td></td><td></td><td>· ·</td><td></td></td>	<td></td> <td></td> <td>· ·</td> <td></td>			· ·	
M20       Speed limitation 65 mph       \$60       \$60         not with MD3       \$60       \$60         MD3       Top speed limitation 75 mph       \$60       \$60         not with M20       \$467       \$467         N62       Front engine bracket for additional alternator       \$467       \$467         not with HK4/N63       \$467       \$467         N63       Front engine bracket for auxiliary A/C compressor       \$467       \$467         not with HK4/N62       \$186       \$186         QA2       Trailer cross member 7,500 lbs capacity       \$186       \$186         not with W73/W75/W76/Q24/Q67       \$101       \$101         QA9       Half-sided step rear (for trailer hitch)       \$101       \$101         must have QA2; not with W73/W75/W76       \$101       \$101         R91       Spare tire deletion       \$0       \$0         must have R92; not with R87       \$0       \$0         R92       Spare tire carrier deletion       \$0       \$0         must have R91; not with R65       \$81       \$81         R98       Rims painted jet black       \$81       \$81         not with RL5/RM2       \$0       \$0         must have RM1 + RM9       \$0 </td <td></td> <td></td> <td></td> <td></td>					
not with MD3         \$60         \$60           MD3         Top speed limitation 75 mph         \$60         \$60           not with M20         \$467         \$467           N62         Front engine bracket for additional alternator         \$467         \$467           not with HK4/N63         \$186         \$467           N63         Front engine bracket for auxiliary A/C compressor         \$467         \$467           not with HK4/N62         \$186         \$186           QA2         Trailer cross member 7,500 lbs capacity         \$186         \$186           not with W73/W75/W76/Q24/Q67         \$101         \$101         \$101           QA9         Half-sided step rear (for trailer hitch)         \$101         \$101         \$101           must have QA2; not with W73/W75/W76         \$101         \$101         \$101         \$101           R91         Spare tire deletion         \$0         \$0         \$0         \$0           must have R92; not with R87         \$10         \$0         \$0         \$0           must have R91; not with R65         \$81         \$81         \$81           R98         Rims painted jet black         \$0         \$0           must have RM1 + RM9         \$0         \$0					
MD3       Top speed limitation 75 mph       \$60       \$60         not with M20       N62       Front engine bracket for additional alternator       \$467       \$467         not with HK4/N63       N63       Front engine bracket for auxiliary A/C compressor       \$467       \$467         not with HK4/N62       QA2       Trailer cross member 7,500 lbs capacity       \$186       \$186         not with W73/W75/W76/Q24/Q67       QA9       Half-sided step rear (for trailer hitch)       \$101       \$101         must have QA2; not with W73/W75/W76       R91       Spare tire deletion       -\$110       -\$110         must have R92; not with R87         R92       Spare tire carrier deletion       \$0       \$0         must have R91; not with R65         R98       Rims painted jet black       \$81       \$81         not with RL5/RM2         RF1       Tire brand Continental       \$0       \$0         must have RM1 + RM9         RF8       Tire brand Michelin       \$0       \$0			700	700	
not with M20         N62       Front engine bracket for additional alternator       \$467       \$467         not with HK4/N63       \$186       \$467       \$467         N63       Front engine bracket for auxiliary A/C compressor       \$467       \$467         not with HK4/N62       \$186       \$186         QA2       Trailer cross member 7,500 lbs capacity       \$186       \$186         not with W73/W75/W76/Q24/Q67       \$101       \$101         QA9       Half-sided step rear (for trailer hitch)       \$101       \$101         must have QA2; not with W73/W75/W76       \$100       \$100         R91       Spare tire deletion       \$50       \$0         must have R92; not with R87       \$0       \$0         R92       Spare tire carrier deletion       \$0       \$0         must have R91; not with R65       \$81       \$81         R98       Rims painted jet black       \$81       \$81         not with RL5/RM2       \$0       \$0         RF1       Tire brand Continental       \$0       \$0         must have RM1 + RM9         RF8       Tire brand Michelin       \$0       \$0	MD3		\$60	\$60	
N62       Front engine bracket for additional alternator       \$467       \$467         not with HK4/N63       \$467       \$467         N63       Front engine bracket for auxiliary A/C compressor       \$467       \$467         not with HK4/N62       \$186       \$186         QA2       Trailer cross member 7,500 lbs capacity       \$186       \$186         not with W73/W75/W76/Q24/Q67       \$101       \$101         QA9       Half-sided step rear (for trailer hitch)       \$101       \$101         must have QA2; not with W73/W75/W76       \$100       \$110         R91       Spare tire deletion       -\$110       -\$110         must have R92; not with R87       \$0       \$0         R92       Spare tire carrier deletion       \$0       \$0         must have R91; not with R65       \$81       \$81         R98       Rims painted jet black       \$81       \$81         not with RL5/RM2       \$0       \$0         RF1       Tire brand Continental       \$0       \$0         must have RM1 + RM9       \$0       \$0         RF8       Tire brand Michelin       \$0       \$0			700	700	
not with HK4/N63         N63       Front engine bracket for auxiliary A/C compressor       \$467       \$467         not with HK4/N62       \$186       \$186         QA2       Trailer cross member 7,500 lbs capacity       \$186       \$186         not with W73/W75/W76/Q24/Q67       \$101       \$101         QA9       Half-sided step rear (for trailer hitch)       \$101       \$101         must have QA2; not with W73/W75/W76       \$110       -\$110         R91       Spare tire deletion       \$0       \$0         must have R92; not with R87         R92       Spare tire carrier deletion       \$0       \$0         must have R91; not with R65         R98       Rims painted jet black       \$81       \$81         not with RL5/RM2         RF1       Tire brand Continental       \$0       \$0         must have RM1 + RM9         RF8       Tire brand Michelin       \$0       \$0	N62		\$467	\$467	
not with HK4/N62         QA2 Trailer cross member 7,500 lbs capacity       \$186       \$186         not with W73/W75/W76/Q24/Q67       \$101       \$101         QA9 Half-sided step rear (for trailer hitch)       \$101       \$101         must have QA2; not with W73/W75/W76       \$100       -\$110         R91 Spare tire deletion       -\$110       -\$110         must have R92; not with R87       \$0       \$0         R92 Spare tire carrier deletion       \$0       \$0         must have R91; not with R65       \$81       \$81         R98 Rims painted jet black       \$81       \$81         not with RL5/RM2       \$0       \$0         RF1 Tire brand Continental       \$0       \$0         must have RM1 + RM9       \$0       \$0         RF8 Tire brand Michelin       \$0       \$0			· ·		
not with HK4/N62         QA2 Trailer cross member 7,500 lbs capacity       \$186       \$186         not with W73/W75/W76/Q24/Q67       \$101       \$101         QA9 Half-sided step rear (for trailer hitch)       \$101       \$101         must have QA2; not with W73/W75/W76       \$100       \$100         R91 Spare tire deletion       -\$110       -\$110         must have R92; not with R87       \$0       \$0         R92 Spare tire carrier deletion       \$0       \$0         must have R91; not with R65       \$81       \$81         R98 Rims painted jet black       \$81       \$81         not with RL5/RM2       \$0       \$0         RF1 Tire brand Continental       \$0       \$0         must have RM1 + RM9       \$0       \$0         RF8 Tire brand Michelin       \$0       \$0	N63	·	\$467	\$467	
not with W73/W75/W76/Q24/Q67           QA9 Half-sided step rear (for trailer hitch)         \$101         \$101           must have QA2; not with W73/W75/W76         -\$110         -\$110           R91 Spare tire deletion         -\$110         -\$110           must have R92; not with R87         \$0         \$0           R92 Spare tire carrier deletion         \$0         \$0           must have R91; not with R65         \$81         \$81           R98 Rims painted jet black         \$81         \$81           not with RL5/RM2         \$0         \$0           RF1 Tire brand Continental         \$0         \$0           must have RM1 + RM9         \$0         \$0           RF8 Tire brand Michelin         \$0         \$0		not with HK4/N62	•		
QA9       Half-sided step rear (for trailer hitch)       \$101       \$101         must have QA2; not with W73/W75/W76         R91       Spare tire deletion       -\$110       -\$110         must have R92; not with R87       \$0       \$0         R92       Spare tire carrier deletion       \$0       \$0         must have R91; not with R65       \$81       \$81         R98       Rims painted jet black       \$81       \$81         not with RL5/RM2       \$0       \$0         RF1       Tire brand Continental       \$0       \$0         must have RM1 + RM9         RF8       Tire brand Michelin       \$0       \$0	QA2	Trailer cross member 7,500 lbs capacity	\$186	\$186	
must have QA2; not with W73/W75/W76         R91       Spare tire deletion       -\$110       -\$110         must have R92; not with R87         R92       Spare tire carrier deletion       \$0       \$0         must have R91; not with R65         R98       Rims painted jet black       \$81       \$81         not with RL5/RM2       \$0       \$0         RF1       Tire brand Continental       \$0       \$0         must have RM1 + RM9       \$0       \$0         RF8       Tire brand Michelin       \$0       \$0		not with W73/W75/W76/Q24/Q67	•		
R91         Spare tire deletion         -\$110         -\$110           must have R92; not with R87         \$0         \$0           R92         Spare tire carrier deletion         \$0         \$0           must have R91; not with R65         \$1         \$81           R98         Rims painted jet black         \$81         \$81           not with RL5/RM2         \$0         \$0           RF1         Tire brand Continental         \$0         \$0           must have RM1 + RM9         \$0         \$0           RF8         Tire brand Michelin         \$0         \$0	QA9	Half-sided step rear (for trailer hitch)	\$101	\$101	
must have R92; not with R87           R92 Spare tire carrier deletion         \$0         \$0           must have R91; not with R65           R98 Rims painted jet black         \$81         \$81           not with RL5/RM2           RF1 Tire brand Continental         \$0         \$0           must have RM1 + RM9           RF8 Tire brand Michelin         \$0         \$0		must have QA2; not with W73/W75/W76			
R92         Spare tire carrier deletion         \$0         \$0           must have R91; not with R65         R98         Rims painted jet black         \$81         \$81           not with RL5/RM2         RF1         Tire brand Continental         \$0         \$0           must have RM1 + RM9         RF8         Tire brand Michelin         \$0         \$0	R91	Spare tire deletion	-\$110	-\$110	
must have R91; not with R65           R98         Rims painted jet black         \$81         \$81           not with RL5/RM2         FF1         Tire brand Continental         \$0         \$0           must have RM1 + RM9         FF8         Tire brand Michelin         \$0         \$0		must have R92; not with R87			
R98         Rims painted jet black         \$81         \$81           not with RL5/RM2         RF1         Tire brand Continental         \$0         \$0           must have RM1 + RM9         RF8         Tire brand Michelin         \$0         \$0	R92		\$0	\$0	
not with RL5/RM2           RF1 Tire brand Continental         \$0         \$0           must have RM1 + RM9           RF8 Tire brand Michelin         \$0         \$0					
RF1         Tire brand Continental         \$0         \$0           must have RM1 + RM9         \$0         \$0           RF8         Tire brand Michelin         \$0         \$0	R98		\$81	\$81	
must have RM1 + RM9         \$0         \$0           RF8         Tire brand Michelin         \$0         \$0					
RF8 Tire brand Michelin \$0 \$0	RF1		\$0	\$0	
must have RM9; not with RM1	RF8		\$0	\$0	
		must have RM9; not with RM1			

Options

			1
		144" 4C M4CV44	170" 4C M4CV74 907.655
		907.653	
RH0	Tire brand Kumho	\$0	\$0
	must have RM9; not with RM1		
RM1	M+S winter tires	\$169	\$169
	must have RF1/RD9; not with RF8/RH0/X31		
RM2	Rims painted arctic white	\$81	\$81
	not with R98/RL5		
RM9	Specially requested tires	\$101	\$101
	must have RF1/RF8/RH0; not with RD9	•	•
S28	Armrest, driver and passenger door	\$51	\$51
T12	Sliding door two stage opening	\$82	\$82
	not with T55		
T50	Electric closing assist right sliding door	\$335	\$335
	must have D03; not with T55/T93		
T55	Electric sliding door right	\$831	\$831
	must have D03 + (FY7+T16); not with T12/T50		
T57	Electric sliding step	\$1,071	\$1,071
	must have D03 + ED5; not with T93		
T60	Opening limiter electrically operated sliding door	\$120	\$120
	must have T55		
T75	Door-mounted assist handles, driver & passenger	\$59	\$59
T85	Assist handle, left rear door	\$32	\$32
T86	Assist handles, right rear door	\$32	\$32
V43	Wood floor with 6 D-rings	\$422	\$422
	not with P93/V93/VL4/VK8/C07; standard with D93/H13/V24/V52/V	/C5/VV2/ZE6	
V85	Cigarette lighter & ash cup, front	\$39	\$39
VC5	Door sill - protective edge	\$71	\$71
	must have V43/X66; not with T19/T93/VK8/VV2/V93/C07		
VK8	Floor covering, plastic	\$370	\$370
	not with V43/P93/T19/T93/V52/VC5/X66	•	
W54	Rear doors, opening to side wall	\$360	\$360
	90 Degree fixation point- Rear Doors	\$80	\$80
	SoP and Plausibility TBD		
W73	Bumper step, rear, grey	\$187	\$187
	not with QA2/W75/W76		
W75	Step, wide, at rear end	\$308	\$308
	not with JB6/JB7/Q24/QA9; must have R91+R92	·	·
W76	Bumper step, rear, spring-loaded	-	\$601
	must have R91+R92; not with JB6/JB7/X30/Q24		,
W78	Heated rear window(s) w/ washers/wipers	\$335	\$335
	Must have H22+VA7 / if D51 must have F61; not with W61	,	,
X90	Deletion of Sprinter badge, left rear door	\$0	\$0
X93	Deletion of model badge, right rear door	\$0	\$0
XM4	Acoustic package	\$87	\$87
	standard with CO2/CO3	7	7-
Y10	First-aid kit	\$27	\$27
Y26	Wheel chocks	\$38	\$38
	Emergency flashlight	\$27	\$27
Y45		747	7 <i>L</i> /
Y45 Y68		·	\$212
Y45 Y68 Y69	Paint preservative Surface protection for stock vehicles	\$187 \$315	\$212 \$315

# **4500 CREW VAN - 4cyl Diesel** Packages

		144" 4C	170" 4C
		M4CV44	M4CV74
		907.653	907.655
C00	Comfort Package	\$300	\$300
LC4	Comfort overhead control panel	X	X
SE4	Lumbar support, co-driver's seat	Х	X
SE5	Lumbar support, driver's seat	Х	X
SK0	Comfort head restraint, driver	Х	X
SK1	Comfort head restraint, co-driver	Х	X
S28	Armrest, driver and passenger door	Х	X
must	have COS OR X68; CA/CC only: not with S23		

COS	Comfort Package (Seat addition)	\$381	\$381		
SB1	Comfort driver's seat	X	X		
SB2	Comfort passenger seat	X	Х		
must	must have COO				

X68	Comfort Plus Package	\$1,923	\$1,923	
H15	Heated front passenger seat	X	X	
H16	Heated driver's seat	X	X	
SF1	Driver's seat electrically adjustable	X	X	
SF2	Co-driver's seat electrically adjustable	Х	Х	
must	must have COO and VF4 OR VF6, CA/CC only: not with S23			

C01	Driver Convenience Package	\$760	\$760
E46	12 V power outlet, driver seat base	X	X
F64	Electrically folding exterior mirrors	X	X
FJ1	Hinged lid for storage compartment	X	X
FJ5	Hinged Lid for Storage Compartments left and right	X	X
FZ9	Keys, two additional masters	X	X
JA7	Blind Spot Assist	X	X
JW8	Attention Assist	Х	X

C02	Premium Package	\$983	\$983
CL3	Leather steering wheel	X	X
E3M	MBUX Multimedia System with 7" touchscreen	Х	Х
FM3	Wet Wiper System	X	Х
JB4	Active Lane Keeping Assist	X	Х
JK5	Instrument cluster with color display	Х	Х

Ordering availability restricted, see NetStar for availability and restrctions|must have JF1 + XM4; must choose FR8/JB7

CA2	C02 in combination with C03	\$604	\$604
CL3	Leather steering wheel	X	X
FM3	Wet Wiper System	X	X
JB4	Active Lane Keeping Assist	Х	X
JK5	Instrument cluster with color display	Х	X
Order	ing availability restricted, see NetStar for availability and restrctions n	nust have CO3 + JF1	1

# **4500 CREW VAN - 4cyl Diesel** Packages

144" 4C	170" 4C
M4CV44	M4CV74
907.653	907.655

C03	Premium Plus Package	\$1,793	\$1,793
E1B	Tray for smartphones incl. wireless charging	X	X
	Navigation	X	X
EY2	Intelligent navigation	X	X
E4M	MBUX Multimedia System with 10.25" touchscreen	X	X
EX9	Free map data updates for 3 years	X	X
H1I	Front-to-rear outlet in instrument panel	X	X
JA9	Traffic Sign Assist	X	Х
XM4	Acoustic package	X	X
must	have (CA2+JB7) OR (JB4+JK5+FM3+JB7); not with FR8 and CO2		

X67	Chrome Grille Package	\$290	\$290	
CN2	Radiator grille frame in vehicle color	X	X	
FK3	Chrome plated radiator grille (MB only)	Х	X	
no res	no restrictions			

X13	Exterior Lighting Package	\$1,608	\$1,608	
L13	Fog lamp with cornering light function	Х	X	
L22	Partial LED tail lights	Х	Х	
LA1	High beam assist	Х	Х	
LG7	LED high performance headlamps	Х	Х	
no res	no restrictions			

X72	Crew Van Comfort Package	\$220	\$220
S31	Convenice head restraints for pass. compartment	X	X
UY1	3-seater comfort bench rear, 1st row (narrow)	Х	X
can have VF4/VF6 only			

### **4500 CREW VAN - 6cyl Diesel** Standard Equipment

144" 6C

170" 6C

		144" 6C	170" 6C
		M4CV46	M4CV76
		907.653	907.655
Engin		ı	
	Engine/7-Speed Trans.	S	S
	AGM battery 12V 92 AH 850 A	S	S
	Automatic transmission, 7G-tronic	S	S
MH8	SULEV emissions	S	S
MG5	3.0L V6 turbo diesel engine	S	S
M46	Alternator 14 V/220 A	S	S
Seatii	ng and Trim Packages		
X7S	Standard Rear Seats	S	S
U62	3-seater bench rear, 1st row (narrow)	S	S
	Wall-side armrest	S	S
	Aisle-side armrest	S	S
	ave VF7/VF6 only; with X68 must have VF6	_	-
X2V	Standard Trim Crew Van Package	S	S
V25	Half height load compartment trim	S	S
V35	Wheel house covering	S	S
V43	Wood floor with 6 D-rings	S	S
		3	3
	production only		
Equip		_	-
	Front axle reinforced	S	S
AR3	Axle ratio 4.182	S	S
BA3	Active Brake Assist	S	S
BH1	Hold Function	S	S
C6L	Multifunction steering wheel	S	S
CB8	Stabilization Level II	S	S
CL1	Adjustable steering wheel (angle)	S	S
D03	High roof	0	S
D93	Omission bulkhead	S	S
E07	Hill Start Assist	S	S
E10	Standard radio	S	S
E1U	USB-C socket, 5 V	S	S
E30	Starter battery disconnect	S	S
E3J	Pre-installation for switch panel	S	S
E40	Trailer hitch prep. wiring	S	S
ED8	Preinstallation PSM	S	S
EE5	Ultracapacitor discharge module	S	S
EK1	Body Builder Connector	S	S
ESO	Jump start terminal	S	S
EW6	Pre-installation for Mercedes me Remote Services	S	S
EY5	Emergency Call System	S	S
EY6	Breakdown management	S	S
F43	Laminated glass rear	S	S
F68	Heated & electrically adjustable exterior mirrors	S	S
FF3	Cupholder rear compartment	S	S
FF5	Shelf above windshield	S	S
FG8	Cupholder front	S	S
FI1	Remote key (315 mhz) w/central locking	S	S
FJ4	Storage compartment underneath cockpit	S	S
FR3	Rear view camera (rear-view mirror display)	S	S
H00	Warm/cool air duct to rear compartment	S	S
H21	Windshield with filter band	S	S
H22	Rear window defroster	S	S
HH2	Heater, auxiliary electric hot air	S	S
		S	S
HH9	Air Condition, Front		
IH7	Head Unit, North America	S	S
J11	Speedometer, miles and km/h	S	S
J55	Seat belt warning for co-driver seat	S	S

### **4500 CREW VAN - 6cyl Diesel** Standard Equipment

		144" 6C 170" 6C	
			M4CV76
		907.653	907.655
		907.653	907.055
J58	Seat belt reminder driver	S	S
J65	Outside temperature gauge	S	S
JA8	Crosswind Assist	S	S
JH3	Communication module (LTE) for dig. services	S	S
JI9	Service interval 20.000 miles	S	S
K56	Red diesel filler cap	S	S
K60	Exhaust straight to rear	S	S
KB7	24.5 gallon fuel tank	S	S
KL1	Aux fuel sending unit w/ fuel tap	S	S
KL5	Fuel filter with water separator	S	S
KP6	3rd generation SCR emission control system	S	S
L94	Parking lights deletion	S	S
LA2	Headlight assistant	S	S
LB5	3rd brake light	S	S
MS1	Cruise control	S	S
P47	Front mudflaps	S	S
P48	Rear mudflaps	S	S
Q11	Longitudinal member reinforcement	S	S
R65	Spare tire bracket below frame	S	S
R87	Spare tire	S	S
RH7	Tires LT 215/85 R16	S	S
RD9	Unspecified tire brand	S	S
RM0	All-season tires	S	S
RS6	5.5 J x 16 steel wheels	S	S
S02	Standard driver seat	S	S
S04	Standard front passenger seat	S	S
S22	Armrest for driver's seat	S	S
S25	Armrest for front passenger seat	S	S
SA5	Front airbag, driver	S	S
SA6	Front airbag, passenger	S	S
SH1	Thorax-pelvis sidebag, driver	S	S
SH2	Thorax-pelvis sidebag, co-driver	S	S
SH9	Airbag, driver/passenger window	S	S
SK2	Seat occupancy sensor, driver's seat	S	S
T16	Sliding door, passenger side	S	S
T74	Assist handle, B-pillar	S	S
U22	Pre-inst. for seating configuration Crew Van	S	S
V36	Roof trim	S	S
V40	Floor anchors for rear seat bench	S	S
VA7	Storage compart. w/ net in rear doors	S	S
W16	2nd row, fixed window, driver side	S	S
W17	2nd row, fixed window, passenger side	S	S
W61	Windows in rear doors	S	S
W70	Black tinting (90%) for rear windows	S	S
XL4	GVWR 12,125 lbs. / 5.500 Kg	S	S
Y43	Jack, hydraulic	S	S

		144" 6C	170" 6C
		M4CV46	M4CV76
		907.653	907.655
AP2	Addtl. bar for driveshaft & exhaust extension	\$69	\$69
AR2	Axle ratio 3.923	\$0	\$0
	not with AR3	•	
B01	ESP for increased Center of Gravity above 39.4"	-	\$0
	must have CB4/CB8/X30; not with RH0/CB7		
C72	Bumpers front/rear primed	\$268	\$268
	must have CN2/X67, not with CM0		
CL3	Leather steering wheel	\$187	\$187
	must have (C02/E3M)/C03 + (ET4/MS1)		
CM0	Painted metallic front & rear bumper	\$587	\$587
	must have (CN2/X67) + (JA7/C01) + JB7 + (7755/9197/9775)	·	•
CM9	Primed side moldings	\$364	\$364
D03	High roof	\$2,900	S
	D03 must be added for Duesseldorf production		
D13	Mounting rails for roof rack	\$300	\$300
E1B	Tray for smartphones incl. wireless charging	\$156	\$156
	must have CO2/E3M + H1I		
E1E	Navigation	\$728	\$728
	must have CO2/E3M, not with CO3		
E1S	Sirius XM, satellite radio	\$255	\$255
	must have CO2/E3M/CO3		
E1R	Additional Fuses (40/80/150/100 Ampere)	\$50	\$50
	SoP and Plausibility TBD		
E1Y	Additional Fuses (40/80/80/100 Ampere)	\$50	\$50
	SoP and Plausibility TBD		
E2A	Access point for BB special signals in cockpit	\$29	\$29
E2I	Additional battery, co-driver seat base	\$248	\$248
	Must have E36; not with E2M; CHS production only		
E36	Cutoff relay for additional battery	\$110	\$110
	standard with E2I/E2M		
E3M	MBUX Multimedia System with 7" touchscreen	\$474	\$474
	not with CO2/CO3; must have JK5+(JB7/FR8)		
E5M	Extension of PSM standard contact	\$58	\$58
ED5	Parametric special module (PSM)	\$317	\$317
	not with ED8		
EE3	115 V socket	\$125	\$125
ES2	12 V power outlet, rear compartment	\$92	\$92
ES5	Charging package, dashboard	\$82	\$82
ET4	Active Distance Assist DISTRONIC	\$263	\$263
	must have CO2/CO3/E3M; not with ZH4	45	4
F49	Electrically heated windshield	\$218	\$218
	no restrictions	400	400
F61	Interior rear view mirror	\$36	\$36
	must have E3M/C02/C03	45.	4
FE9	Additional DIN-slot	\$81	\$81
FF8	Overhead storage slot, front center	\$105	\$105
FJ1	Hinged lid for storage compartment	\$93	\$93
FR8	Rear view camera (head unit display)	\$336	\$336
F\/4	must have CO2/E3M; not with FR3/JB7; 3500XD not with JB8	ĆEO4	ĆE04
FY1	Security alarm w. interior motion sensor	\$584	\$584
רעיז	must have LC4/C00	626	ćac.
FY7	Optional 3-button keys	\$36	\$36
FZ9	Keys, two additional masters	\$121	\$121
H01	Heat insulation, rear compartment	\$156	\$156
1104	must have V25/VA3/VA1/C07/X66	6407	6407
H04	Heat insulation, front compartment	\$187	\$187
	if + D50/D51 must have V07		

		44411.00	
		144" 6C	170" 6C
		M4CV46	M4CV76
		907.653	907.655
H12	Fuel-fired pre-heater/booster (17K BTU)	\$1,116	\$1,116
	not with HZ9		
H13	Rear cabin heater and vents	\$786	\$786
	must have V43 + (H12/HZ9); not with VK8		
H15	Heated front passenger seat	\$284	\$284
	must have H16; not with X68		
H16	Heated driver's seat	\$284	\$284
	must have H15; not with X68		
H88	Rear heater prep	\$405	\$405
	must have H12/HZ9; not with H13/T19		
H1I	Front-to-rear outlet in instrument panel	\$0	\$0
	must have FJ1/C01		
HH4	Thermotronic automatic climate control	\$337	\$337
	must have JF1; if +H13 must have H08/HK4		
HZ9	Fuel-fired heater booster (18,000 BTU)	\$676	\$676
	not with H12		
J51	Fuel gauge, optimized for aux. fuel tap	\$72	\$72
	not with HZ9/H12		
J52	Engine oil level display at cold start	\$0	\$0
JA7	Blind Spot Assist	\$450	\$450
	must have F68; not with C01		
JB4	Active Lane Keeping Assist	\$288	\$288
	standard with CO2/CA2		
JB7	Parking Package	\$615	\$615
	must have E3M/C02/C03; not with W75/W76/JB6		
JF1	Rain sensor	\$106	\$106
JK5	Instrument cluster with color display	\$144	\$144
	not with CO3		
JW0	Backup alarm	\$99	\$99
JW2	Deactivation lamp monitoring failure	\$27	\$27
JW8	Attention Assist	\$49	\$49
K51	Misfueling prevention for Diesel	\$49	\$49
K52	DEF fluid filler cap - lockable	\$27	\$27
L13	Fog lamp with cornering light function	\$199	\$199
LB9	Illuminated front exits	\$151	\$151
LC4	Comfort overhead control panel	\$93	\$93
M20	Speed limitation 65 mph	\$60	\$60
	not with MD3		
MD3		\$60	\$60
	not with M20		
N62	Front engine bracket for additional alternator	\$467	\$467
	not with HK4/N63		
N63	Front engine bracket for auxiliary A/C compressor	\$467	\$467
<u> </u>	not with HK4/N62		
QA2	Trailer cross member 7,500 lbs capacity	\$186	\$186
_	not with W73/W75/W76/Q24/Q67	1	4
QA9	Half-sided step rear (for trailer hitch)	\$101	\$101
	must have QA2; not with W73/W75/W76	4	4
R91	Spare tire deletion	-\$110	-\$110
225	must have R92; not with R87		4
R92	Spare tire carrier deletion	\$0	\$0
	must have R91; not with R65		
R98	Rims painted jet black	\$81	\$81
<u> </u>	not with RL5/RM2		
RF1	Tire brand Continental	\$0	\$0
	must have RM1 + RM9		
RF8	Tire brand Michelin	\$0	\$0
	must have RM9; not with RM1		

		14411.00	47011.00
		144" 6C	170" 6C
		M4CV46	M4CV76
		907.653	907.655
RH0	Tire brand Kumho	\$0	\$0
	must have RM9; not with RM1		
RM1	M+S winter tires	\$169	\$169
	must have RF1/RD9; not with RF8/RH0/X31		
RM2	Rims painted arctic white	\$81	\$81
	not with R98/RL5		
RM9	Specially requested tires	\$101	\$101
	must have RF1/RF8/RH0; not with RD9		
S28	Armrest, driver and passenger door	\$51	\$51
T12	Sliding door two stage opening	\$82	\$82
	not with T55	•	
T50	Electric closing assist right sliding door	\$335	\$335
	must have D03; not with T55/T93		
T55	Electric sliding door right	\$831	\$831
	must have D03 + (FY7+T16); not with T12/T50	•	
T57	Electric sliding step	\$1,071	\$1,071
	must have D03 + ED5; not with T93	, ,	. ,
T60	Opening limiter electrically operated sliding door	\$120	\$120
	must have T55	, -	, -
T75	Door-mounted assist handles, driver & passenger	\$59	\$59
T85	Assist handle, left rear door	\$32	\$32
T86	Assist handles, right rear door	\$32	\$32
V43	Wood floor with 6 D-rings	\$422	\$422
V 43	not with P93/V93/VL4/VK8/C07; standard with D93/H13/V24/V52/V0	•	У <del>ч</del> ZZ
V85	Cigarette lighter & ash cup, front	\$39	\$39
VC5	Door sill - protective edge	\$71	\$71
VC3	must have V43/X66; not with T19/T93/VK8/VV2/V93/C07	<b>γ/1</b>	<b>γ/1</b>
VK8	Floor covering, plastic	\$370	\$370
VICO	not with V43/P93/T19/T93/V52/VC5/X66	7370	<del>-</del>
W54	Rear doors, opening to side wall	\$360	\$360
W5F	90 Degree fixation point- Rear Doors	\$80	\$80
WJF	SoP and Plausibility TBD	Ş6U	Ş6U
14/72		\$187	\$187
W73	Bumper step, rear, grey	\$187	\$187
\A/7F	not with QA2/W75/W76	¢200	¢200
W /5	Step, wide, at rear end	\$308	\$308
	not with JB6/JB7/Q24/QA9; must have R91+R92		4001
W76	Bumper step, rear, spring-loaded	-	\$601
	must have R91+R92; not with JB6/JB7/X30/Q24		
W78	Heated rear window(s) w/ washers/wipers	\$335	\$335
<u> </u>	Must have H22+VA7 / if D51 must have F61; not with W61		
X90	Deletion of Sprinter badge, left rear door	\$0	\$0
X93	Deletion of model badge, right rear door	\$0	\$0
XM4	Acoustic package	\$87	\$87
	standard with C02/C03	T	
Y10	First-aid kit	\$27	\$27
Y26	Wheel chocks	\$38	\$38
Y45	Emergency flashlight	\$27	\$27
Y68	Paint preservative	\$187	\$212
Y69	Surface protection for stock vehicles	\$315	\$315
YK3	Cargo straps, D-rings	\$81	\$81

# **4500 CREW VAN - 6cyl Diesel** Packages

		144" 6C	170" 6C
		M4CV46	M4CV76
		907.653	907.655
C00	Comfort Package	\$300	\$300
LC4	Comfort overhead control panel	Х	X
SE4	Lumbar support, co-driver's seat	Х	X
SE5	Lumbar support, driver's seat	X	X
SK0	Comfort head restraint, driver	X	X
SK1	Comfort head restraint, co-driver	X	X
S28	Armrest, driver and passenger door	X	X
must	have COS OR X68; CA/CC only: not with S23		

COS	Comfort Package (Seat addition)	\$381	\$381		
SB1	Comfort driver's seat	X	X		
SB2	Comfort passenger seat	Х	X		
must	must have COO				

X68	Comfort Plus Package	\$1,923	\$1,923	
H15	Heated front passenger seat	X	X	
H16	Heated driver's seat	Х	Х	
SF1	Driver's seat electrically adjustable	Х	Х	
SF2	Co-driver's seat electrically adjustable	Х	Х	
must	must have C00 and VF4 OR VF6, CA/CC only: not with S23			

C01	Driver Convenience Package	\$760	\$760
E46	12 V power outlet, driver seat base	X	X
F64	Electrically folding exterior mirrors	X	X
FJ1	Hinged lid for storage compartment	X	X
FJ5	Hinged Lid for Storage Compartments left and right	X	X
FZ9	Keys, two additional masters	X	X
JA7	Blind Spot Assist	X	X
JW8	Attention Assist	X	X

C02	Premium Package	\$983	\$983
CL3	Leather steering wheel	X	Х
E3M	MBUX Multimedia System with 7" touchscreen	X	X
FM3	Wet Wiper System	Х	Х
JB4	Active Lane Keeping Assist	Х	X
JK5	Instrument cluster with color display	Х	X

Ordering availability restricted, see NetStar for availability and restrctions|must have JF1 + XM4; must choose FR8/JB7

CA2	C02 in combination with C03	\$604	\$604	
CL3	Leather steering wheel	X	X	
FM3	Wet Wiper System	Х	X	
JB4	Active Lane Keeping Assist	Х	X	
JK5	Instrument cluster with color display	Х	X	
Order	Ordering availability restricted, see NetStar for availability and restrctions   must have CO3 + JF1			

# **4500 CREW VAN - 6cyl Diesel** Packages

144" 6C	170" 6C
M4CV46	M4CV76
907.653	907.655

C03	Premium Plus Package	\$1,793	\$1,793
E1B	Tray for smartphones incl. wireless charging	Х	Х
	Navigation	X	X
EY2	Intelligent navigation	X	X
E4M	MBUX Multimedia System with 10.25" touchscreen	Х	X
EX9	Free map data updates for 3 years	X	X
H1I	Front-to-rear outlet in instrument panel	Х	X
JA9	Traffic Sign Assist	Х	Х
XM4	Acoustic package	X	X
must have (CA2+JB7) OR (JB4+JK5+FM3+JB7); not with FR8 and CO2			

X67	Chrome Grille Package	\$290	\$290
CN2	Radiator grille frame in vehicle color	X	X
FK3	Chrome plated radiator grille (MB only)	X	X
no restrictions			

X13	Exterior Lighting Package	\$1,608	\$1,608
L13	Fog lamp with cornering light function	Х	Х
L22	Partial LED tail lights	Х	Х
LA1	High beam assist	Х	Х
LG7	LED high performance headlamps	Х	Х
no restrictions			

X72	Crew Van Comfort Package	\$220	\$220
S31	Convenice head restraints for pass. compartment	Х	X
T12	Sliding door two stage opening	Х	Х
T50	Electric closing assist right sliding door	Х	Х
UY1	3-seater comfort bench rear, 1st row (narrow)	Х	Х
can have VF4/VF6 only			

### **1500 PASSENGER VAN - GAS** Standard Equipment

144'' G
12 seats
M1PV4G
907.743

		907.743
Engin	e	
	ngine/9-Speed Trans.	S
ED4	AGM battery 12V 92 AH 850 A	S
G43	Automatic transmission, 9G-tronic	S
	Alternator 14 V / 250 A	S
	SULEV emissions	S
	2.0L 4-cylinder turbo gasoline engine	S
	Seating Configuration	3
X7S	Standard Rear Seats	S
U62	3-seater bench rear, 1st row (narrow)	S
UC3	3-seater bench rear, 2nd row (narrow)	S
UD6	4-seater bench in rear, 3rd row	S
Equip		3
AP2	Addtl. bar for driveshaft & exhaust extension	S
AR3	Axle ratio 4.182	S
BA3 BH1	Active Brake Assist Hold Function	S
		S
C6L CB1	Multifunction steering wheel Suspension for comfort and load protection	S
CL1	Adjustable steering wheel (angle)	S
CT1	Rear spring vibration absorbers	S
E07	Hill Start Assist	S
E10	Standard radio	S
E1U	USB-C socket, 5 V	S
E30	Starter battery disconnect	S
E3J	Pre-installation for switch panel	S
E40	Trailer hitch prep. wiring	S
ED8	Preinstallation PSM	S
EE5	Ultracapacitor discharge module	S
EK1	Body Builder Connector	S
EL9	Audio systems speakers, 5 front, 8 rear	S
ES0	Jump start terminal	S
ES2	12 V power outlet, rear compartment	S
EW6	Pre-installation for Mercedes me Remote Services	S
EY5	Emergency Call System	S
EY6	Breakdown management	S
F43	Laminated glass rear	S
F68	Heated & electrically adjustable exterior mirrors	S
FF0	Coat hooks	S
FF3	Cupholder rear compartment	S
FF5	Shelf above windshield	S
FG8	Cupholder front	S
FI1	Remote key (315 mhz) w/central locking	S
FJ1	Hinged lid for storage compartment	S
FJ4	Storage compartment underneath cockpit	S
FR3	Rear view camera (rear-view mirror display)	S
H00	Warm/cool air duct to rear compartment	S
H01	Heat insulation, rear compartment	S
H04	Heat insulation, front compartment	S
H08	Air conditioning rear, roof-mounted	S
H13	Rear cabin heater and vents	S
H1I	Front-to-rear outlet in instrument panel	S
H21	Windshield with filter band	S
H22	Rear window defroster	S

### **1500 PASSENGER VAN - GAS** Standard Equipment

		144" G
		12 seats
		M1PV4G
		907.743
HH2	Heater, auxiliary electric hot air	S
	Air Condition, Front	S
	Headunit	S
	Speedometer, miles and km/h	S
_	Service Interval 1 year	S
_	Seat belt warning for co-driver seat	S
1	Seat belt reminder driver	S
	Outside temperature gauge	S
	Crosswind Assist	S
	Communication module (LTE) for dig. services	S
-	Service interval 15.000 miles	S
	22 gallon fuel tank	S
	Exhaust straight to rear	S
_	Parking lights deletion	S
1	Headlight assistant	S
	3rd brake light	S
	Illuminated front exits	S
	Cruise control	S
	Front mudflaps	S
	Rear mudflaps	S
	Longitudinal member reinforcement	S
	Tow hook rear	S
	Spare tire bracket below frame	S
	Spare tire	S
	Unspecified tire brand	S
_	Tires LT 245/75 R16	S
_	All-season tires	S
-	6.5 J x 16 steel wheels	S
	Tire pressure monitoring sensors	S
	Standard driver seat	S
	Standard front passenger seat	S
	Armrest for driver's seat	S
	Armrest for front passenger seat	S
	Front airbag, driver	S
	Front airbag, passenger	S
_	Thorax-pelvis sidebag, driver	S
	Thorax-pelvis sidebag, co-driver	S
	Airbag, driver/passenger window	S
	Seat occupancy sensor, driver's seat	S
	Storage net, driver's seat backrest	S
	Storage net, passenger seat backrest	S
	Sliding door, passenger side	S
	Assist handle, B-pillar	S
	Pre-inst. for seating configuration 12-seater	S
	Wall-side armrest	S
	Aisle-side armrest	S
	Luxury interior Trim	S
V21	Window pillar trim	S
	Trinacti pinar trini	9
V31	Wheel house covering	ς
V31 V35	Wheel house covering Roof trim	S
V31 V35 V36	Roof trim	S
V31 V35 V36 V39	Roof trim Weight optimized plastic floor	\$ \$
V31 V35 V36 V39 V40	Roof trim	S

### 1500 PASSENGER VAN - GAS

### Standard Equipment

		144" G 12 seats M1PV4G 907.743
W17	2nd row, fixed window, passenger side	S
W27	Fixed window, rear left	S
W28	Fixed window, rear right	S
W33	FMVSS 217 emergency exit	S
W61	Windows in rear doors	S
W70	Black tinting (90%) for rear windows	S
XL8	GVWR 8,550 lbs. / 3,880 Kg	S
Y43	Jack, hydraulic	S

Options

		144" G
	-	12 seats
		M1PV4G
		907.743
		307.743
B25	Electric parking brake	\$279
C72	Bumpers front/rear primed	\$268
	must have CN2/X67, not with CM0	
CB7	Stabilization Level I	\$307
	not with ZG3	
CL3	Leather steering wheel	\$187
	must have (C02/E3M)/C03 + (ET4/MS1)	
CM0	Painted metallic front & rear bumper	\$587
	must have CN2 (part of X67) + (JA7/C01) + (JB6/JB7) + (7755/9197/9775)	
CM9	Primed side moldings	\$364
D03	High roof	\$2,900
D13	Mounting rails for roof rack	\$300
E1B	Tray for smartphones incl. wireless charging	\$156
	must have CO2/E3M	
E1E	Navigation	\$728
	must have CO2/E3M, not with CO3	
E1S	Sirius XM, satellite radio	\$255
	must have CO2/E3M/CO3	
E1R	Additional Fuses (40/80/150/100 Ampere)	\$50
	SoP and Plausibility TBD	
E1Y	Additional Fuses (40/80/80/100 Ampere)	\$50
	PV plausi 12 seater	
E2A	Access point for BB special signals in cockpit	\$29
E2I	Additional battery, co-driver seat base	\$248
	Must have E36; not with E2M	
E36	Cutoff relay for additional battery	\$110
	standard with E2I/E2M	
E3M	MBUX Multimedia System with 7" touchscreen	\$474
	not with CO2/CO3; must have JK5+(JB7/JB6/JB8/FR8)	
E5M	Extension of PSM standard contact	\$58
ED5	Parametric special module (PSM)	\$317
	not with ED8	
EE3	115 V socket	\$125
ES5	Charging package, dashboard	\$82
ET4	Active Distance Assist DISTRONIC	\$263
	must have CO2/CO3/E3M; not with ZH4	
F49	Electrically heated windshield	\$218
F61	Interior rear view mirror	\$0
	must have CO2/CO3/E3M	
FE9	Additional DIN-slot	\$81
FF8	Overhead storage slot, front center	\$105
FR8	Rear view camera (head unit display)	\$336
	must have CO2/E3M; not with FR3/JB7/JB6/JB8	
FY1	Security alarm w. interior motion sensor	\$584
	must have LC4/C00	
FY7	Optional 3-button keys	\$36
FZ9	Keys, two additional masters	\$121
H15	Heated front passenger seat	\$284
	must have H16; not with X68	
H16	Heated driver's seat	\$284
	must have H15; not with X68	
HH4	Thermotronic automatic climate control	\$337
	must have JF1	

Options

144" G

		12 seats
		M1PV4G
		907.743
JA7	Blind Spot Assist	\$450
	must have F64	
JB4	Active Lane Keeping Assist	\$288
	standard with CO2/CA2	
JB6	Parking Package with 360 degree camera	\$775
	must have CO2/CO3/E3M; not with JB7	
JB7	Parking Package	\$615
	must have CO2/CO3/E3M; not with JB6	
JB8	360 Degree Camera	\$685
	SoP and Plausibility TBD	
JF1	Rain sensor	\$106
	standard with CO2/X11	
JK5	Instrument cluster with color display	\$144
	standard with CO3	
JW0	Backup alarm	\$99
JW2	Deactivation lamp monitoring failure	\$34
JW8	Attention Assist	\$49
L13	Fog lamp with cornering light function	\$199
LC4	Comfort overhead control panel	\$93
M20	Speed limitation 65 mph	\$60
	not with MD3	-
MD3	Top speed limitation 75 mph	\$60
	not with M20	
Q24	Trailer hitch, 5,000 lbs	\$147
	not with W73	
QA9	Half-sided step rear (for trailer hitch)	\$101
	must have Q24, not with W73	
R91	Spare tire deletion	-\$110
	must have R92; not with R87	
R92	Spare tire carrier deletion	\$0
	must have R91; not with R65	
R98	Rims painted jet black	\$81
	not with RL5/RM2	
RF1	Tire brand Continental	\$0
	must have RM1 + RM9	
RF8	Tire brand Michelin	\$0
	must have RM9; not with RM1	
RH0	Tire brand Kumho	\$0
	must have RM9; not with RM1	
RL5	Light-alloy wheels 6.5 J x 16	\$906
	not with RS3/RM2/R98	
RM1	M+S winter tires	\$169
	must have RF1/RD9; not with RF8/RH0	
RM2	Rims painted arctic white	\$81
	not with R98/RL5	
RM9	Specially requested tires	\$101
	must have RF1/RF8/RH0; not with RD9	
S28	Armrest, driver and passenger door	\$51
T12	Sliding door two stage opening	\$82
	not with T55/X71	
T50	Electric closing assist right sliding door	\$335
	must have D03; not with T55	
T55	Electric sliding door right	\$831
	must have D03 + (FY7+T16); not with T12/T50	

# **1500 PASSENGER VAN - GAS**Options

144" G	
12 seats	
M1PV4G	
907.743	

T57	Electric sliding step	\$1,071
	must have ED5	
T60	Opening limiter electrically operated sliding door	\$120
	must have T55	
T75	Door-mounted assist handles, driver & passenger	\$59
T85	Assist handle, left rear door	\$32
T86	Assist handles, right rear door	\$32
V85	Cigarette lighter & ash cup, front	\$39
V4A	Full paneling, right sliding door	\$109
	must have D03+VA5	
VA5	Full paneling, hinged rear doors	\$38
must have D03		
W54	Rear doors, opening to side wall	\$360
W5F	90 Degree fixation point- Rear Doors	\$80
	SoP and Plausibility TBD	
W73	Bumper step, rear, grey	\$187
	not with Q24	
W78	Heated rear window(s) w/ washers/wipers	\$335
	not with W61	
X90	Deletion of Sprinter badge, left rear door	\$0
X93	Deletion of model badge, right rear door	\$0
XM4	Acoustic package	\$87
	standard with CO2/CO3	
Y10	First-aid kit	\$27
Y45	Emergency flashlight	\$27
Y68	Paint preservative	\$187
Y69	Surface protection for stock vehicles	\$315

# **1500 PASSENGER VAN - GAS** Packages

144" G
12 seats
M1PV4G
907.743

C00	Comfort Package	\$300	
LC4	Comfort overhead control panel	Х	
SE4	Lumbar support, co-driver's seat	Χ	
SE5	Lumbar support, driver's seat	Χ	
SK0	Comfort head restraint, driver	Χ	
SK1	Comfort head restraint, co-driver	X	
S28	Armrest, driver and passenger door	Χ	
must	must have S28 + (COS OR X68); not with S23		

COS	Comfort Package (Seat addition)	\$381	
SB1	Comfort driver's seat	X	
SB2	Comfort passenger seat	X	
must	must have COO		

X68	Comfort Plus Package	\$1,923
H15	Heated front passenger seat	X
H16	Heated driver's seat	Х
SF1	Driver's seat electrically adjustable	Х
SF2	Co-driver's seat electrically adjustable	Х
must	have COO and VF4 OR VF6, CA/CC only: not with S23	

C01	Driver Convenience Package	\$760
E46	12 V power outlet, driver seat base	X
F64	Electrically folding exterior mirrors	X
FJ1	Hinged lid for storage compartment	S
FJ5	Hinged Lid for Storage Compartments left and right	X
FZ9	Keys, two additional masters	X
JA7	Blind Spot Assist	X
JW8	Attention Assist	Х

C02	Premium Package	\$983
CL3	Leather steering wheel	X
E3M	MBUX Multimedia System with 7" touchscreen	X
FM3	Wet Wiper System	X
JB4	Active Lane Keeping Assist	X
JK5	Instrument cluster with color display	X
Ordering availability restricted, see NetStar for availability and restrictions must have		

CA2	C02 in combination with C03	\$604
CL3	Leather steering wheel	X
FM3	Wet Wiper System	X
JB4	Active Lane Keeping Assist	X
JK5	Instrument cluster with color display	Х
Ordering qualitability restricted see NotCtar for qualitability and restrational must baye		

Ordering availability restricted, see NetStar for availability and restrctions | must have CO3 + JF1

JF1 + XM4; must choose FR8/JB7/JB6

# **1500 PASSENGER VAN - GAS** Packages

144" G
12 seats
M1PV4G
907.743

C03	Premium Plus Package	\$1,793
E1B	Tray for smartphones incl. wireless charging	X
	Navigation	X
EY2	Intelligent navigation	X
E4M	MBUX Multimedia System with 10.25" touchscreen	Х
EX9	Free map data updates for 3 years	X
H1I	Front-to-rear outlet in instrument panel	Х
JA9	Traffic Sign Assist	X
XM4	Acoustic package	Х
must CO2	have (CA2+(JB7/JB6/JB8)) OR (JB4+JK5+FM3+(JB7/JB6/JB8)); no	ot with FR8 and

X67	Chrome Grille Package	\$290
CN2	Radiator grille frame in vehicle color	X
FK3	Chrome plated radiator grille (MB only)	X
no restrictions		

X13	Exterior Lighting Package	\$1,608
L13	Fog lamp with cornering light function	X
L22	Partial LED tail lights	X
LA1	High beam assist	X
LG7	LED high performance headlamps	X
no restrictions		

X70	Rear Comfort Package	\$1,521
S31	Convenice head restraints for pass. compartment	X
U3Y	3-seater comfort bench rear - 3rd row (narrow)	-
UY1	3-seater comfort bench rear, 1st row (narrow)	X
UY2	3-seater comfort bench rear, 2nd row (narrow)	X
UY3	4-seater comfort bench rear, 3rd row	X
UY6	4-seater comfort bench rear, 4th row	-
can h	ave VF4/VF6 only	

X71	Passenger Accessibility Package	\$1,504
T55	Electric sliding door right	X
ED5	Parametric special module (PSM)	X
T57	Electric sliding step	X
FY7	Optional 3-button keys	X

Opening limiter for electrically operated sliding door (T60) can be added in combination with the package

**2500 PASSENGER VAN - GAS** Standard Equipment

144" G
12 seats
M2PV4G
907.743

Engin	Engine			
Gas E	S			
ED4	AGM battery 12V 92 AH 850 A	S		
G43	Automatic transmission, 9G-tronic	S		
M60	Alternator 14 V / 250 A	S		
	2.0L 4-cylinder turbo gasoline engine	S		
	SULEV emissions	S		
	Seating Configuration			
X7S	Standard Rear Seats	S		
U62	3-seater bench rear, 1st row (narrow)	S		
	3-seater bench rear, 2nd row (narrow)	S		
UD6	4-seater bench in rear, 3rd row	S		
Equip	l ·	3		
AP2	Addtl. bar for driveshaft & exhaust extension	S		
AR3	Axle ratio 4.182	S		
BA3	Active Brake Assist	S		
BH1	Hold Function			
C6L	Multifunction steering wheel	S S		
CB1	Suspension for comfort and load protection	S		
CL1	Adjustable steering wheel (angle)	S		
CT1	Rear spring vibration absorbers	S		
E07	Hill Start Assist	S		
E10	Standard radio	S		
E1U	USB-C socket, 5 V	S		
E30	Starter battery disconnect	S		
E3J	Pre-installation for switch panel	S		
E40	Trailer hitch prep. wiring	S		
ED8	Preinstallation PSM	S		
EE5 EK1	Ultracapacitor discharge module	S S		
EL9	Body Builder Connector Audio systems speakers, 5 front, 8 rear	S		
ES0	Jump start terminal	S		
ES2				
EW6	12 V power outlet, rear compartment Pre-installation for Mercedes me Remote Services	S		
EY5	Emergency Call System	S		
EY6	Breakdown management	S		
F68	Heated & electrically adjustable exterior mirrors	S		
F43	Laminated glass rear	S		
FF0	Coat hooks	S		
	Cupholder rear compartment	S		
FF3 FF5	Shelf above windshield	S		
FG8	Cupholder front	S		
FI1	Remote key (315 mhz) w/central locking	S		
FJ1	Hinged lid for storage compartment	S		
FJ4	Storage compartment underneath cockpit	S		
FR3	Rear view camera (rear-view mirror display)	S		
H00	Warm/cool air duct to rear compartment	S		
H01	Heat insulation, rear compartment	S		
H04	Heat insulation, front compartment	S		
H04 H08	·	S S		
	Air conditioning rear, roof-mounted  Rear cabin heater and vents			
H13		S		
H1I	Front-to-rear outlet in instrument panel	S		
H21	Windshield with filter band	S		
H22	Rear window defroster	S		
HH2	Heater, auxiliary electric hot air	S		

#### **2500 PASSENGER VAN - GAS** Standard Equipment

144" G 12 seats

	M2PV4G
	907.743
	307.743
HH9 Air Condition, Front	S
IH7 Headunit	S
J11 Speedometer, miles and km/h	S
J1W Service Interval 1 year	S
J55 Seat belt warning for co-driver seat	S
J58 Seat belt reminder driver	S
J65 Outside temperature gauge	S
JA8 Crosswind Assist	S
JH3 Communication module (LTE) for dig. s	
JI8 Service interval 15.000 miles	S
K14 22 gallon fuel tank	S
K60 Exhaust straight to rear	S
L94 Parking lights deletion	S
LA2 Headlight assistant	S
LB5 3rd brake light	S
LB9 Illuminated front exits	S
MS1 Cruise control	S
P47 Front mudflaps	S
P48 Rear mudflaps	S
Q11 Longitudinal member reinforcement	S
Q67 Tow hook rear	S
R65 Spare tire bracket below frame	S
R87 Spare tire	S
RD9 Unspecified tire brand	S
RH8 Tires LT 245/75 R16	S
RMO All-season tires	S
RS3 6.5 J x 16 steel wheels	S
RY2 Tire pressure monitoring sensors	S
S02 Standard driver seat	S
S04 Standard front passenger seat	S
S22 Armrest for driver's seat	S
S25 Armrest for front passenger seat	S
SA5 Front airbag, driver	S
SA6 Front airbag, passenger	S
SH1 Thorax-pelvis sidebag, driver	S
SH2 Thorax-pelvis sidebag, co-driver	S
SH9 Airbag, driver/passenger window	S
SK2 Seat occupancy sensor, driver's seat	S
SZ7 Storage net, driver's seat backrest	S
SZ8 Storage net, passenger seat backrest	S
T16 Sliding door, passenger side	S
T74 Assist handle, B-pillar	S
U28 Pre-inst. for seating configuration 12-s	eater S
U74 Wall-side armrest	S
U75 Aisle-side armrest	S
V21 Luxury interior Trim	S
V31 Window pillar trim	S
V35 Wheel house covering	S
V36 Roof trim	S
V39 Weight optimized plastic floor	S
V40 Floor anchors for rear seat bench	S
VA7 Storage compart. w/ net in rear doors	S
W02 Panel van w/windows all round	S
W17 2nd row, fixed window, passenger side	S
W27 Fixed window, rear left	S
W28 Fixed window, rear right	S

#### 2500 PASSENGER VAN - GAS

		144" G
		12 seats
		M2PV4G
		907.743
\ <b>\</b> /33	FMVSS 217 emergency exit	ς
VV 33	TIVIVOS 217 CHICIBETICY CAIL	3
W61	Windows in rear doors	S
W70	Black tinting (90%) for rear windows	S
XL2	GVWR 9,050 lbs. / 4.100 Kg	S
Y43	Jack, hydraulic	S

144" G 12 seats

		12 seats
		M2PV4G
		907.743
B25	Electric parking brake	\$279
C72	Bumpers front/rear primed	\$268
	must have CN2/X67, not with CM0	
CB7	Stabilization Level I	\$307
	not with ZG3	
CL3	Leather steering wheel	\$187
	must have (C02/E3M)/C03 + (ET4/MS1)	
CM0	Painted metallic front & rear bumper	\$587
	must have CN2 (part of X67) + (JA7/C01) + (JB6/JB7) + (7755/9197/9775)	
CM9	Primed side moldings	\$364
D03	High roof	\$2,900
D13	Mounting rails for roof rack	\$300
E1B	Tray for smartphones incl. wireless charging	\$156
	must have CO2/E3M	•
E1E	Navigation	\$728
	must have CO2/E3M, not with CO3	·
E1S	Sirius XM, satellite radio	\$255
	must have CO2/E3M/CO3	·
E1R	Additional Fuses (40/80/150/100 Ampere)	\$50
	SoP and Plausibility TBD	,
E1Y	Additional Fuses (40/80/80/100 Ampere)	\$50
	PV plausi 12 seater	7-0
E2A	Access point for BB special signals in cockpit	\$29
E2I	Additional battery, co-driver seat base	\$248
	Must have E36; not with E2M	72.0
E36	Cutoff relay for additional battery	\$110
	standard with E2I/E2M	Ÿ==0
E3M	MBUX Multimedia System with 7" touchscreen	\$474
	not with CO2/CO3; must have JK5+(JB7/JB6/JB8/FR8)	Ψ., .
E5M	Extension of PSM standard contact	\$58
	Parametric special module (PSM)	\$317
	not with ED8	γο1,
EE3	115 V socket	\$125
ES5	Charging package, dashboard	\$82
ET4	Active Distance Assist DISTRONIC	\$263
	must have CO2/CO3/E3M; not with ZH4	Ψ203
F49	Electrically heated windshield	\$218
F61	Interior rear view mirror	\$0
101	must have CO2/CO3/E3M	Ψ.
FE9	Additional DIN-slot	\$81
FF8	Overhead storage slot, front center	\$105
FR8	Rear view camera (head unit display)	\$336
110	must have CO2/E3M; not with FR3/JB7/JB6/JB8	7550
FY1	Security alarm w. interior motion sensor	\$584
	must have LC4/C00	<del>у</del> 50-т
FY7	Optional 3-button keys	\$36
FZ9	Keys, two additional masters	\$121
H15	Heated front passenger seat	\$284
1110	must have H16; not with X68	7404
H16	Heated driver's seat	\$284
1110	must have H15; not with X68	<b>₹204</b>
		6227
шци	Thormotronic automatic climate control	
HH4	Thermotronic automatic climate control	\$337
HH4 JA7	Thermotronic automatic climate control  must have JF1  Blind Spot Assist	\$450

144" G

		12 coots
		12 seats
		M2PV4G
		907.743
JB4	Active Lane Keeping Assist	\$288
	standard with CO2/CA2	
JB6	Parking Package with 360 degree camera	\$775
	must have CO2/CO3/E3M; not with JB7	
JB7	Parking Package	\$615
	must have CO2/CO3/E3M; not with JB6	
JB8	360 Degree Camera	\$685
	SoP and Plausibility TBD	
JF1	Rain sensor	\$106
	standard with CO2/X11	•
JK5	Instrument cluster with color display	\$144
	standard with CO3	•
JW0	Backup alarm	\$99
JW2	Deactivation lamp monitoring failure	\$34
JW8	Attention Assist	\$49
L13	Fog lamp with cornering light function	\$199
LC4	Comfort overhead control panel	\$93
M20	Speed limitation 65 mph	\$60
	not with MD3	
MD3	Top speed limitation 75 mph	\$60
	not with M20	
Q24	Trailer hitch, 5,000 lbs	\$147
	not with W73	
QA9	Half-sided step rear (for trailer hitch)	\$101
	must have Q24, not with W73	,
R91	Spare tire deletion	-\$110
	must have R92; not with R87	·
R92	Spare tire carrier deletion	\$0
	must have R91; not with R65	·
R98	Rims painted jet black	\$81
	not with RL5/RM2	
RF1	Tire brand Continental	\$0
	must have RM1 + RM9	
RF8	Tire brand Michelin	\$0
	must have RM9; not with RM1	
RH0	Tire brand Kumho	\$0
	must have RM9; not with RM1	
RL5	Light-alloy wheels 6.5 J x 16	\$906
	not with RS3/RM2/R98	
RM1	M+S winter tires	\$169
	must have RF1/RD9; not with RF8/RH0	
RM2	Rims painted arctic white	\$81
	not with R98/RL5	
RM9	Specially requested tires	\$101
	must have RF1/RF8/RH0; not with RD9	
S28	Armrest, driver and passenger door	\$51
T12	Sliding door two stage opening	\$82
	not with T55/X71	
T50	Electric closing assist right sliding door	\$335
	must have D03; not with T55	
T55	Electric sliding door right	\$831
	must have D03 + (FY7+T16); not with T12/T50	
T57	Electric sliding step	\$1,071
	must have ED5	
T60	Opening limiter electrically operated sliding door	\$120
	must have T55	!
T75	Door-mounted assist handles, driver & passenger	\$59
	· · · · · ·	

		144" G
		12 seats
		M2PV4G
		907.743
T85	Assist handle, left rear door	\$32
T86	Assist handles, right rear door	\$32
V85	Cigarette lighter & ash cup, front	\$39
V4A	Full paneling, right sliding door	\$109
	must have D03+VA5	
VA5	Full paneling, hinged rear doors	\$38
	must have D03	
W54	Rear doors, opening to side wall	\$360
W5F	90 Degree fixation point- Rear Doors	\$80
	SoP and Plausibility TBD	
W73	Bumper step, rear, grey	\$187
	not with Q24	
W78	Heated rear window(s) w/ washers/wipers	\$335
	not with W61	
X90	Deletion of Sprinter badge, left rear door	\$0
X93	Deletion of model badge, right rear door	\$0
XM4	Acoustic package	\$87
	standard with C02/C03	
Y10	First-aid kit	\$27
Y45	Emergency flashlight	\$27
Y68	Paint preservative	\$187
Y69	Surface protection for stock vehicles	\$315

# **2500 PASSENGER VAN - GAS**Packages

144" G
12 seats
M2PV4G
907.743

C00	Comfort Package	\$300
LC4	Comfort overhead control panel	X
SE4	Lumbar support, co-driver's seat	X
SE5	Lumbar support, driver's seat	X
SK0	Comfort head restraint, driver	X
SK1	Comfort head restraint, co-driver	X
S28	Armrest, driver and passenger door	X
must have S28 + (COS OR X68); not with S23		

COS	Comfort Package (Seat addition)	\$381
SB1	Comfort driver's seat	X
SB2	Comfort passenger seat	X
must have COO		

X68	Comfort Plus Package	\$1,923
H15	Heated front passenger seat	X
H16	Heated driver's seat	X
SF1	Driver's seat electrically adjustable	Х
SF2	Co-driver's seat electrically adjustable	Х
must have C00 and VF4 OR VF6, CA/CC only: not with S23		

C01	Driver Convenience Package	\$760
E46	12 V power outlet, driver seat base	X
F64	Electrically folding exterior mirrors	X
FJ1	Hinged lid for storage compartment	S
FJ5	Hinged Lid for Storage Compartments left and right	X
FZ9	Keys, two additional masters	X
JA7	Blind Spot Assist	Х
JW8	Attention Assist	Х

C02	Premium Package	\$983
CL3	Leather steering wheel	X
E3M	MBUX Multimedia System with 7" touchscreen	X
FM3	Wet Wiper System	X
JB4	Active Lane Keeping Assist	X
JK5	Instrument cluster with color display	Х

Ordering availability restricted, see NetStar for availability and restrictions | must have JF1 + XM4; must choose FR8/JB7/JB6

CA2	C02 in combination with C03	\$604
CL3	Leather steering wheel	X
FM3	Wet Wiper System	X
JB4	Active Lane Keeping Assist	X
JK5	Instrument cluster with color display	X

Ordering availability restricted, see NetStar for availability and restrctions | must have CO3 + JF1

# **2500 PASSENGER VAN - GAS**Packages

144" G
12 seats
M2PV4G
907.743

C03	Premium Plus Package	\$1,793
E1B	Tray for smartphones incl. wireless charging	X
	Navigation	Х
EY2	Intelligent navigation	X
E4M	MBUX Multimedia System with 10.25" touchscreen	X
EX9	Free map data updates for 3 years	X
H1I	Front-to-rear outlet in instrument panel	X
JA9	Traffic Sign Assist	X
XM4	Acoustic package	X
must have (CA2+(JB7/JB6/JB8)) OR (JB4+JK5+FM3+(JB7/JB6/JB8)); not with FR8 and CO2		

X67	Chrome Grille Package	\$290
CN2	Radiator grille frame in vehicle color	X
FK3	Chrome plated radiator grille (MB only)	X
no restrictions		

X13	Exterior Lighting Package	\$1,608
L13	Fog lamp with cornering light function	X
L22	Partial LED tail lights	X
LA1	High beam assist	X
LG7	LED high performance headlamps	X
no restrictions		

X70	Rear Comfort Package	\$1,521
S31	Convenice head restraints for pass. compartment	X
UY1	3-seater comfort bench rear, 1st row (narrow)	X
UY2	3-seater comfort bench rear, 2nd row (narrow)	X
UY3	4-seater comfort bench rear, 3rd row	X
can have VF4/VF6 only		

X71	Passenger Accessibility Package	\$1,504
T55	Electric sliding door right	X
ED5	Parametric special module (PSM)	X
T57	Electric sliding step	X
FY7	Optional 3-button keys	X

Opening limiter for electrically operated sliding door (T60) can be added in combination with the package

144" 4C	170" 4C
12 seats	15 seats
M2PV44	M2PV74
907.743	907.745

		56711 16	00111110
Engin	e		
4-Cyl	Engine/7-Speed Trans.	S	S
ED4	AGM battery 12V 92 AH 850 A	S	S
	Automatic transmission, 7G-tronic	S	S
	Alternator 14 V / 250 A	S	S
	2.0L 4-cylinder diesel engine	S	S
	SULEV emissions	S	S
	Seating Configuration	3	3
		c	C
	Standard Rear Seats	S	S
	3-seater bench rear, 1st row (narrow)	S	S
	3-seater bench rear, 2nd row (narrow)	S	S
UD6	4-seater bench in rear, 3rd row	S	-
U3S	3-seater bench in rear, 3rd row (narrow)	-	S
UD7	4-seater bench in rear, 4th row	-	S
Equip	ment		
A50	Front axle reinforced	-	S
AP2	Addtl. bar for driveshaft & exhaust extension	S	S
AR2	Axle ratio 3.923	S	S
	Active Brake Assist	S	S
	Hold Function	S	S
	Multifunction steering wheel	S	S
	Suspension for comfort and load protection	S	S
CL1	Adjustable steering wheel (angle)	S	S
CT1		S	S
	Rear spring vibration absorbers		
	High roof	0	S
E07	Hill Start Assist	S	S
	Standard radio	S	S
E1U	USB-C socket, 5 V	S	S
E30	Starter battery disconnect	S	S
E3J	Pre-installation for switch panel	S	S
E40	Trailer hitch prep. wiring	S	-
ED8	Preinstallation PSM	S	S
EE5	Ultracapacitor discharge module	S	S
EK1	Body Builder Connector	S	S
EL9	Audio systems speakers, 5 front, 8 rear	S	S
ES0	Jump start terminal	S	S
ES2	12 V power outlet, rear compartment	S	S
EW6	Pre-installation for Mercedes me Remote Services	S	S
EY5	Emergency Call System	S	S
EY6	Breakdown management	S	S
F43	Laminated glass rear	S	S
F68	Heated & electrically adjustable exterior mirrors	S	S
FF0	Coat hooks	S	S
FF3	Cupholder rear compartment	S	S
FF5	Shelf above windshield		
		S	S
FG8	Cupholder front	S	S
FI1	Remote key (315 mhz) w/central locking	S	S
FJ1	Hinged lid for storage compartment	S	S
FJ4	Storage compartment underneath cockpit	S	S
FR3	Rear view camera (rear-view mirror display)	S	S
H00	Warm/cool air duct to rear compartment	S	S
H01	Heat insulation, rear compartment	S	S
H04	Heat insulation, front compartment	S	S
H08	Air conditioning rear, roof-mounted	S	S

Standard Equipment

144" 4C

170" 4C

		40	4
		12 seats	15 seats
		M2PV44	M2PV74
		907.743	907.745
H1I	Front-to-rear outlet in instrument panel	S	S
H21	Windshield with filter band	S	S
H22	Rear window defroster	S	S
HH2	Heater, auxiliary electric hot air	S	S
HH9	Air Condition, Front	S	S
HZ9	Fuel-fired heater booster (18,000 BTU)	S	S
IH7	Headunit North America	S	S
J11	Speedometer, miles and km/h	S	S
J55	Seat belt warning for co-driver seat	S	S
J58	Seat belt reminder driver	S	S
J65	Outside temperature gauge	S	S
JA8	Crosswind Assist	S	S
-			S
JH3	Communication module (LTE) for dig. services	S	
JI9	Service interval 20.000 miles	S	S
K56	Red diesel filler cap	S	S
K60	Exhaust straight to rear	S	S
KB7	24.5 gallon fuel tank	S	S
KL5	Fuel filter with water separator	S	S
KP6	3rd generation SCR emission control system	S	S
L94	Parking lights deletion	S	S
LA2	Headlight assistant	S	S
LB5	3rd brake light	S	S
LB9	Illuminated front exits	S	S
MS1	Cruise control	S	S
P47	Front mudflaps	S	S
P48	Rear mudflaps	S	S
Q00	Constrained towing capacity (0 lbs)	-	S
Q11	Longitudinal member reinforcement	S	S
Q67	Tow hook rear	S	S
R65	Spare tire bracket below frame	S	S
R87	Spare tire	S	S
RD9	Unspecified tire brand	S	S
RH8	Tires LT 245/75 R16	S	S
RM0	All-season tires	S	S
RS3	6.5 J x 16 steel wheels	S	S
RY2	Tire pressure monitoring sensors	S	S
S02	Standard driver seat	S	S
S04	Standard front passenger seat	S	S
S22	Armrest for driver's seat	S	S
S25	Armrest for front passenger seat	S	S
SA5	Front airbag, driver	S	S
SA6	Front airbag, passenger	S	S
SH1	Thorax-pelvis sidebag, driver	S	S
SH2	Thorax-pelvis sidebag, co-driver	S	S
SH9	Airbag, driver/passenger window	S	S
SK2	Seat occupancy sensor, driver's seat	S	S
SZ7	Storage net, driver's seat backrest	S	S
SZ8	Storage net, passenger seat backrest	S	S
T16	Sliding door, passenger side	S	S
T74	Assist handle, B-pillar	S	S
U1A	14+1-seater version	-	S
U28	Pre-inst. for seating configuration 12-seater	S	-
U29	Pre-inst. for seating configuration 15-seater	-	S
U74	Wall-side armrest	S	S
U75	Aisle-side armrest	S	S
V21	Luxury interior Trim	S	S
V31	Window pillar trim	S	S

#### 2500 PASSENGER VAN - 4cyl Diesel

	144" 4C	170" 4C
	12 seats	15 seats
	M2PV44	M2PV74
	907.743	907.745
V35 Wheel house covering	S	S
V36 Roof trim	S	S
V39 Weight optimized plastic floor	S	S
V40 Floor anchors for rear seat bench	S	S
VA7 Storage compart. w/ net in rear doors	S	S
W02 Panel van w/windows all round	S	S
W17 2nd row, fixed window, passenger side	S	S
W22 Fixed window, center left	-	S
W23 Fixed window, center right		S
W27 Fixed window, rear left	S	S
W28 Fixed window, rear right	S	S
W33 FMVSS 217 emergency exit	S	S
W61 Windows in rear doors	S	S
W70 Black tinting (90%) for rear windows	S	S
X2B GVWR 9,480 lbs. / 4,300 kg	-	S
XL2 GVWR 9,050 lbs. / 4.100 Kg	S	-
Y43 Jack, hydraulic	S	S

144" 4C

170" 4C

			-70 .0
		12 seats	15 seats
		M2PV44	M2PV74
		907.743	907.745
AR3	Axle ratio 4.182	\$0	\$0
	not with AR2	70	Ψ°
B25	Electric parking brake	\$279	\$279
C72	Bumpers front/rear primed	\$268	\$268
	must have CN2/X67, not with CM0		
CB7	Stabilization Level I	\$307	\$307
	not with ZG3	•	
CL3	Leather steering wheel	\$187	\$187
	must have (C02/E3M)/C03 + (ET4/MS1)		
CM0	Painted metallic front & rear bumper	\$587	\$587
	must have CN2 (part of X67) + (JA7/C01) + (JB6/JB7) + (7755/9197/97	775)	
CM9	Primed side moldings	\$364	\$364
D03	High roof	\$2,900	S
D13	Mounting rails for roof rack	\$300	\$300
E1B	Tray for smartphones incl. wireless charging	\$156	\$156
	must have CO2/E3M		
E1E	Navigation	\$728	\$728
	must have CO2/E3M, not with CO3		
E1S	Sirius XM, satellite radio	\$255	\$255
	must have CO2/E3M/CO3		
E1R	Additional Fuses (40/80/150/100 Ampere)	\$50	\$50
	SoP and Plausibility TBD		
E1Y	Additional Fuses (40/80/80/100 Ampere)	\$50	\$50
	PV plausi 12 seater		
E2A	Access point for BB special signals in cockpit	\$29	\$29
E2I	Additional battery, co-driver seat base	\$248	-
	Must have E36; not with E2M		
E36	Cutoff relay for additional battery	\$110	\$110
	standard with E2I/E2M		
E3M	MBUX Multimedia System with 7" touchscreen	\$474	\$474
	not with CO2/CO3; must have JK5+(JB7/JB6/JB8/FR8)		
E5M	Extension of PSM standard contact	\$58	\$58
ED5	Parametric special module (PSM)	\$317	\$317
	not with ED8		
EE3	115 V socket	\$125	\$125
ES5	Charging package, dashboard	\$82	\$82
ET4	Active Distance Assist DISTRONIC	\$263	\$263
	must have C02/C03/E3M; not with ZH4		
F49	Electrically heated windshield	\$218	\$218
F61	Interior rear view mirror	\$0	\$0
	must have CO2/CO3/E3M		
F64	Electrically folding exterior mirrors	\$49	\$49
FE9	Additional DIN-slot	\$81	\$81
FF8	Overhead storage slot, front center	\$105	\$105
FR8	Rear view camera (head unit display)	\$336	\$336
	must have CO2/E3M; not with FR3/JB7/JB6/JB8		
FY1	Security alarm w. interior motion sensor	\$584	\$584
	must have LC4/C00		
FY7	Optional 3-button keys	\$36	\$36
FZ9	Keys, two additional masters	\$121	\$121
H12	Fuel-fired pre-heater/booster (17K BTU)	\$826	\$826
	not with HZ9/J51/KL1	4	455
H15	Heated front passenger seat	\$284	\$284
1147	must have H16; not with X68	4004	4004
H16	Heated driver's seat	\$284	\$284
	must have H15; not with X68		

144" 4C

170" 4C

		144 4C	170 4C
		12 seats	15 seats
		M2PV44	M2PV74
		907.743	907.745
	L	4	4
HH4	Thermotronic automatic climate control	\$337	\$337
	must have JF1		
J51	Fuel gauge, optimized for aux. fuel tap	\$72	\$72
	not with HZ9/H12		
J52	Engine oil level display at cold start	\$0	\$0
JA7	Blind Spot Assist	\$450	\$450
	must have F64		
JB4	Active Lane Keeping Assist	\$288	\$288
	standard with CO2/CA2		
JB6	Parking Package with 360 degree camera	\$775	\$775
	must have CO2/CO3/E3M; not with JB7	,	
JB7	Parking Package	\$615	\$615
	must have CO2/CO3/E3M; not with JB6		
JB8	360 Degree Camera	\$685	\$685
	SoP and Plausibility TBD	•	
JF1	Rain sensor	\$106	\$106
	standard with CO2/X11		•
JK5	Instrument cluster with color display	\$144	\$144
,	standard with CO3	7	7-11
JW0	Backup alarm	\$99	\$99
JW2	Deactivation lamp monitoring failure	\$34	\$34
JW8	Attention Assist	\$49	\$49
K51	Misfueling prevention for Diesel	\$49	\$49
K52	DEF fluid filler cap - lockable	\$27	\$27
L13		\$199	
	Fog lamp with cornering light function  Comfort overhead control panel		\$199
LC4	'	\$93	\$93
M20	Speed limitation 65 mph	\$60	\$60
1400	not with MD3	450	450
MD3	Top speed limitation 75 mph	\$60	\$60
11/0	not with M20	4.5=	4
N62	Front engine bracket for additional alternator	\$467	\$467
	not with X11	4	
Q24	Trailer hitch, 5,000 lbs	\$147	-
	not with W73		
QA9	Half-sided step rear (for trailer hitch)	\$101	-
	must have Q24, not with W73		
R91	Spare tire deletion	-\$110	-\$110
	must have R92; not with R87		
R92	Spare tire carrier deletion	\$0	\$0
	must have R91; not with R65		
R98	Rims painted jet black	\$81	\$81
	not with RL5/RM2		
RF1	Tire brand Continental	\$0	\$0
	must have RM1 + RM9		
RF8	Tire brand Michelin	\$0	\$0
	must have RM9; not with RM1		· · · · · · · · · · · · · · · · · · ·
RH0	Tire brand Kumho	\$0	\$0
	must have RM9; not with RM1	'	
RL5	Light-alloy wheels 6.5 J x 16	\$906	\$906
	not with RS3/RM2/R98	4000	73
RM1	M+S winter tires	\$169	\$169
12141	must have RF1/RD9; not with RF8/RH0	7103	7103
RM2	Rims painted arctic white	\$81	\$81
MIVIZ		301	λοτ
RM9	not with R98/RL5	\$101	\$101
KIVIY	Specially requested tires  must have RF1/RF8/RH0; not with RD9	\$101	\$101
000		654	ĆE4
S28	Armrest, driver and passenger door	\$51	\$51

144" 4C	170" 4C	
12 seats	15 seats	
M2PV44	M2PV74	
907.743	907.745	

X93 Deletion of model badge, right rear door  XM4 Acoustic package  \$87  \$tandard with CO2/CO3			907.743	907.745
Electric closing assist right sliding door   \$335   \$335	T12	Sliding door two stage opening	\$82	\$82
must have D03; not with T55         Electric sliding door right         \$831         \$831           must have D03 + (FY7+T16); not with T12/T50         \$1,071         \$1,071           T67         Electric sliding step         \$1,071         \$1,071           must have ED5         "must have ED5         \$120         \$120           T75         Door-mounted assist handles, driver & passenger         \$59         \$59           T85         Assist handle, left rear door         \$32         \$32           T86         Assist handles, right rear door         \$32         \$32           V85         Cigarette lighter & ash cup, front         \$39         \$39           V4A         Full paneling, right sliding door         \$109         \$109           must have D03+VA5         ***         ***           VA5         Full paneling, hinged rear doors         \$38         \$38           must have D03         ***         ***           W54         Rear doors, opening to side wall         \$360         \$360           W57         90 Degree fixation point- Rear Doors         \$80         \$80           SOP and Plausibility TBD         ***         ***           W78         Heated rear window(s) w/ washers/wipers         \$335         \$335		not with T55/X71	•	•
T55         Electric sliding door right         \$831         \$831           must have D03 + (FY7+T16); not with T12/T50         \$1,071         \$1,071           T67         Electric sliding step         \$1,071         \$1,071           must have ED5         \$120         \$120           T60         Opening limiter electrically operated sliding door         \$120         \$120           must have T55         \$59         \$59           T75         Door-mounted assist handles, driver & passenger         \$59         \$59           R85         Assist handle, left rear door         \$32         \$32           R86         Assist handle, left rear door         \$32         \$32           V85         Cigarette lighter & ash cup, front         \$39         \$39           V86         Cigarette lighter & ash cup, front         \$39         \$39           V4A         Full paneling, right sliding door         \$109         \$109           must have D03+VA5         Full paneling, hinged rear doors         \$38         \$38           W54         Full paneling, hinged rear doors         \$360         \$360           W57         90 Degree flausibility TBD           W73         Bumper step, rear, grey         \$187         \$187           N90<	T50	Electric closing assist right sliding door	\$335	\$335
must have D03 + (FY7+T16); not with T12/T50           T57         Electric sliding step         \$1,071         \$1,071           must have ED5         \$120         \$120           T60         Opening limiter electrically operated sliding door         \$120         \$120           must have T55         \$59         \$59         \$59           T75         Door-mounted assist handles, driver & passenger         \$32         \$32         \$32           T86         Assist handles, left rear door         \$32         \$32         \$32         \$32           T86         Assist handles, right rear door         \$32         <		must have D03; not with T55		
T57         Electric sliding step         \$1,071         \$1,071           must have ED5	T55	Electric sliding door right	\$831	\$831
must have ED5         \$120         \$120           T60         Opening limiter electrically operated sliding door         \$120         \$120           must have T55         \$59         \$59         \$59           T75         Door-mounted assist handles, driver & passenger         \$32         \$32         \$32           T86         Assist handle, left rear door         \$32         \$32         \$32           T86         Assist handles, right rear door         \$32         \$32         \$32           V85         Cigarette lighter & ash cup, front         \$39         \$39         \$39         \$39           V4A         Full paneling, right sliding door         \$109         \$109         \$109         \$109           must have D03+VA5         W5         Full paneling, hinged rear doors         \$38         \$38         \$38           must have D03         \$360<		must have D03 + (FY7+T16); not with T12/T50		
T60         Opening limiter electrically operated sliding door         \$120         \$120           must have T55         T75         Door-mounted assist handles, driver & passenger         \$59         \$59           T85         Assist handle, left rear door         \$32         \$32           T86         Assist handles, right rear door         \$32         \$32           V85         Cigarette lighter & ash cup, front         \$39         \$39           V4A         Full paneling, right sliding door         \$109         \$109           must have D03+VA5         ***         ***           VA5         Full paneling, hinged rear doors         \$38         \$38           must have D03         ***         ***           W54         Rear doors, opening to side wall         \$360         \$360           W5F         90 Degree fixation point- Rear Doors         \$80         \$80           SOP and Plausibility TBD         ***         ***           W73         Bumper step, rear, grey         \$187         \$187           M78         Heated rear window(s) w/ washers/wipers         \$335         \$335           not with W61         ***         ***           X90         Deletion of Sprinter badge, left rear door         \$0         \$0     <	T57	Electric sliding step	\$1,071	\$1,071
must have T55           T75         Door-mounted assist handles, driver & passenger         \$59         \$59           T85         Assist handle, left rear door         \$32         \$32           T86         Assist handles, right rear door         \$32         \$32           V85         Cigarette lighter & ash cup, front         \$39         \$39           V4A         Full paneling, right sliding door         \$109         \$109           must have D03+VA5         W109         \$109         \$109           W54         Full paneling, hinged rear doors         \$38         \$38           must have D03         W54         Rear doors, opening to side wall         \$360         \$360           W55         90 Degree fixation point- Rear Doors         \$80         \$80           SOP and Plausibility TBD         S0         \$80           W73         Bumper step, rear, grey         \$187         \$187           M78         Heated rear window(s) w/ washers/wipers         \$335         \$335           not with W61         \$0         \$0           X90         Deletion of Sprinter badge, left rear door         \$0         \$0           X93         Deletion of model badge, right rear door         \$0         \$0           X94		must have ED5		
T75         Door-mounted assist handles, driver & passenger         \$59         \$59           T85         Assist handle, left rear door         \$32         \$32           T86         Assist handles, right rear door         \$32         \$32           V85         Cigarette lighter & ash cup, front         \$39         \$39           V4A         Full paneling, right sliding door         \$109         \$109           must have D03+VA5         VA5         Full paneling, hinged rear doors         \$38         \$38           must have D03         W54         Rear doors, opening to side wall         \$360         \$360           W57         90 Degree fixation point- Rear Doors         \$80         \$80           SOP and Plausibility TBD         W73         Bumper step, rear, grey         \$187         \$187           not with Q24         W78         Heated rear window(s) w/ washers/wipers         \$335         \$335           not with W61         X90         Deletion of Sprinter badge, left rear door         \$0         \$0           X93         Deletion of model badge, right rear door         \$0         \$0           X94         Acoustic package         \$87         \$87           x10         First-aid kit	T60	Opening limiter electrically operated sliding door	\$120	\$120
T85         Assist handle, left rear door         \$32         \$32           T86         Assist handles, right rear door         \$32         \$32           V85         Cigarette lighter & ash cup, front         \$39         \$39           V4A         Full paneling, right sliding door         \$109         \$109           Must have D03+VA5         VA5         Full paneling, hinged rear doors         \$38         \$38           Must have D03         W54         Rear doors, opening to side wall         \$360         \$360           W55         90 Degree fixation point- Rear Doors         \$80         \$80           SOP and Plausibility TBD         W73         Bumper step, rear, grey         \$187         \$187           not with Q24         W78         Heated rear window(s) w/ washers/wipers         \$335         \$335         \$335           N90         Deletion of Sprinter badge, left rear door         \$0         \$0           X93         Deletion of model badge, right rear door         \$0         \$0           X94         Acoustic package         \$87         \$87           X10         First-aid kit         \$27         \$27           Y45         Emergency flashlig		must have T55	•	
T86       Assist handles, right rear door       \$32       \$32         V85       Cigarette lighter & ash cup, front       \$39       \$39         V4A       Full paneling, right sliding door       \$109       \$109         wash have D03+VA5       \$38       \$38         VA5       Full paneling, hinged rear doors       \$38       \$38         wst have D03       \$360       \$360         W54       Rear doors, opening to side wall       \$360       \$360         W5F       90 Degree fixation point- Rear Doors       \$80       \$80         SOP and Plausibility TBD       \$187       \$187         W73       Bumper step, rear, grey       \$187       \$187         not with Q24       \$335       \$335       \$335         NO       with W61       \$360       \$0         X90       Deletion of Sprinter badge, left rear door       \$0       \$0         X93       Deletion of model badge, right rear door       \$0       \$0         XM4       Acoustic package       \$87       \$87         standard with C02/C03       \$27       \$27         Y45       Emergency flashlight       \$27       \$27         Y68       Paint preservative       \$187       \$212	T75	Door-mounted assist handles, driver & passenger	\$59	\$59
V85         Cigarette lighter & ash cup, front         \$39         \$39           V4A         Full paneling, right sliding door         \$109         \$109           must have D03+VA5         \$38         \$38           VA5         Full paneling, hinged rear doors         \$38         \$38           must have D03         \$360         \$360         \$360           W54         Rear doors, opening to side wall         \$360         \$360           W5F         90 Degree fixation point- Rear Doors         \$80         \$80           SoP and Plausibility TBD         \$80         \$80           W73         Bumper step, rear, grey         \$187         \$187           not with Q24         \$335         \$335         \$335           W78         Heated rear window(s) w/ washers/wipers         \$335         \$335           not with W61         \$20         \$0           X90         Deletion of Sprinter badge, left rear door         \$0         \$0           X93         Deletion of model badge, right rear door         \$0         \$0           XM4         Acoustic package         \$87         \$87           \$40         \$187         \$27         \$27           Y45         Emergency flashlight         \$27	T85	Assist handle, left rear door	\$32	\$32
V4A         Full paneling, right sliding door         \$109         \$109           must have D03+VA5         \$38         \$38           VA5         Full paneling, hinged rear doors         \$38         \$38           must have D03         \$360         \$360           W54         Rear doors, opening to side wall         \$360         \$360           W5F         90 Degree fixation point- Rear Doors         \$80         \$80           SoP and Plausibility TBD         \$187         \$187           W73         Bumper step, rear, grey         \$187         \$187           not with Q24         \$35         \$335         \$335           Not with W61         \$30         \$0           X90         Deletion of Sprinter badge, left rear door         \$0         \$0           X93         Deletion of model badge, right rear door         \$0         \$0           XM4         Acoustic package         \$87         \$87           standard with C02/C03         \$27         \$27           Y45         Emergency flashlight         \$27         \$27           Y68         Paint preservative         \$187         \$212	T86	Assist handles, right rear door	\$32	\$32
must have D03+VA5           VA5         Full paneling, hinged rear doors         \$38         \$38           must have D03         \$360         \$360         \$360           W54         Rear doors, opening to side wall         \$360         \$360           W5F         90 Degree fixation point- Rear Doors         \$80         \$80           SOP and Plausibility TBD         \$187         \$187           W73         Bumper step, rear, grey         \$187         \$187           not with Q24         \$335         \$335         \$335           Not with W61         \$0         \$0         \$0           X90         Deletion of Sprinter badge, left rear door         \$0         \$0           X93         Deletion of model badge, right rear door         \$0         \$0           XM4         Acoustic package         \$87         \$87           standard with C02/C03         \$27         \$27           Y45         Emergency flashlight         \$27         \$27           Y68         Paint preservative         \$187         \$212	V85	Cigarette lighter & ash cup, front	\$39	\$39
VA5         Full paneling, hinged rear doors         \$38         \$38           must have D03         \$360         \$360           W54         Rear doors, opening to side wall         \$360         \$360           W5F         90 Degree fixation point- Rear Doors         \$80         \$80           SoP and Plausibility TBD         \$187         \$187           W73         Bumper step, rear, grey         \$187         \$187           not with Q24         \$335         \$335         \$335           NO         W61         \$0         \$0         \$0         \$0           X90         Deletion of Sprinter badge, left rear door         \$0         \$0         \$0         \$0           X93         Deletion of model badge, right rear door         \$0         \$0         \$0           XM4         Acoustic package         \$87         \$87           \$10         First-aid kit         \$27         \$27           Y45         Emergency flashlight         \$27         \$27           Y68         Paint preservative         \$187         \$212	V4A	Full paneling, right sliding door	\$109	\$109
must have D03         \$360         \$360           W54         Rear doors, opening to side wall         \$360         \$360           W5F         90 Degree fixation point- Rear Doors         \$80         \$80           SoP and Plausibility TBD         \$187         \$187           W73         Bumper step, rear, grey         \$187         \$187           not with Q24         \$335         \$335         \$335           Not with W61         \$20         \$0         \$0           X90         Deletion of Sprinter badge, left rear door         \$0         \$0         \$0           X93         Deletion of model badge, right rear door         \$0         \$0         \$0           XM4         Acoustic package         \$87         \$87           \$tandard with C02/C03         \$27         \$27           Y10         First-aid kit         \$27         \$27           Y45         Emergency flashlight         \$27         \$27           Y68         Paint preservative         \$187         \$212		must have D03+VA5		
W54       Rear doors, opening to side wall       \$360       \$360         W5F       90 Degree fixation point- Rear Doors       \$80       \$80         SoP and Plausibility TBD         W73       Bumper step, rear, grey       \$187       \$187         not with Q24       \$335       \$335       \$335         Not with W61       \$0       \$0       \$0         X90       Deletion of Sprinter badge, left rear door       \$0       \$0         X93       Deletion of model badge, right rear door       \$0       \$0         XM4       Acoustic package       \$87       \$87         standard with C02/C03       \$27       \$27         Y10       First-aid kit       \$27       \$27         Y45       Emergency flashlight       \$27       \$27         Y68       Paint preservative       \$187       \$212	VA5	Full paneling, hinged rear doors	\$38	\$38
W5F 90 Degree fixation point- Rear Doors  SoP and Plausibility TBD  W73 Bumper step, rear, grey  not with Q24  W78 Heated rear window(s) w/ washers/wipers  not with W61  X90 Deletion of Sprinter badge, left rear door  X93 Deletion of model badge, right rear door  X94 Acoustic package  \$187 \$187  \$187  \$187  \$187  \$187  \$187  \$27  \$27  \$27  \$27  \$27  \$28  \$28  \$		must have D03		
SoP and Plausibility TBD  W73 Bumper step, rear, grey \$187 \$187  not with Q24  W78 Heated rear window(s) w/ washers/wipers \$335 \$335  not with W61  X90 Deletion of Sprinter badge, left rear door \$0 \$0  X93 Deletion of model badge, right rear door \$0 \$0  XM4 Acoustic package \$87 \$87  standard with CO2/CO3  Y10 First-aid kit \$27 \$27  Y45 Emergency flashlight \$27 \$27  Y68 Paint preservative \$187 \$212	W54	Rear doors, opening to side wall	\$360	\$360
W73       Bumper step, rear, grey       \$187       \$187         not with Q24       \$335       \$335         W78       Heated rear window(s) w/ washers/wipers       \$335       \$335         not with W61       \$0       \$0         X90       Deletion of Sprinter badge, left rear door       \$0       \$0         X93       Deletion of model badge, right rear door       \$0       \$0         XM4       Acoustic package       \$87       \$87         standard with C02/C03       \$27       \$27         Y10       First-aid kit       \$27       \$27         Y45       Emergency flashlight       \$27       \$27         Y68       Paint preservative       \$187       \$212	W5F	90 Degree fixation point- Rear Doors	\$80	\$80
not with Q24         W78 Heated rear window(s) w/ washers/wipers       \$335       \$335         not with W61         X90 Deletion of Sprinter badge, left rear door       \$0       \$0         X93 Deletion of model badge, right rear door       \$0       \$0         XM4 Acoustic package       \$87       \$87         standard with C02/C03       \$27       \$27         Y10 First-aid kit       \$27       \$27         Y45 Emergency flashlight       \$27       \$27         Y68 Paint preservative       \$187       \$212		SoP and Plausibility TBD	<del>,</del>	,
W78       Heated rear window(s) w/ washers/wipers       \$335       \$335         not with W61       \$0       \$0         X90       Deletion of Sprinter badge, left rear door       \$0       \$0         X93       Deletion of model badge, right rear door       \$0       \$0         XM4       Acoustic package       \$87       \$87         standard with C02/C03       \$27       \$27         Y10       First-aid kit       \$27       \$27         Y45       Emergency flashlight       \$27       \$27         Y68       Paint preservative       \$187       \$212	W73	Bumper step, rear, grey	\$187	\$187
not with W61         X90       Deletion of Sprinter badge, left rear door       \$0       \$0         X93       Deletion of model badge, right rear door       \$0       \$0         XM4       Acoustic package       \$87       \$87         standard with C02/C03       \$27       \$27         Y10       First-aid kit       \$27       \$27         Y45       Emergency flashlight       \$27       \$27         Y68       Paint preservative       \$187       \$212		not with Q24	·	,
X90       Deletion of Sprinter badge, left rear door       \$0       \$0         X93       Deletion of model badge, right rear door       \$0       \$0         XM4       Acoustic package       \$87       \$87         standard with C02/C03       \$27       \$27         Y10       First-aid kit       \$27       \$27         Y45       Emergency flashlight       \$27       \$27         Y68       Paint preservative       \$187       \$212	W78	Heated rear window(s) w/ washers/wipers	\$335	\$335
X93       Deletion of model badge, right rear door       \$0       \$0         XM4       Acoustic package       \$87       \$87         standard with C02/C03       \$27       \$27         Y10       First-aid kit       \$27       \$27         Y45       Emergency flashlight       \$27       \$27         Y68       Paint preservative       \$187       \$212		not with W61		
XM4       Acoustic package       \$87       \$87         standard with C02/C03       \$27       \$27         Y10       First-aid kit       \$27       \$27         Y45       Emergency flashlight       \$27       \$27         Y68       Paint preservative       \$187       \$212	X90	Deletion of Sprinter badge, left rear door	\$0	\$0
standard with C02/C03           Y10         First-aid kit         \$27         \$27           Y45         Emergency flashlight         \$27         \$27           Y68         Paint preservative         \$187         \$212	X93	Deletion of model badge, right rear door	\$0	\$0
Y10       First-aid kit       \$27       \$27         Y45       Emergency flashlight       \$27       \$27         Y68       Paint preservative       \$187       \$212	XM4	Acoustic package	\$87	\$87
Y45       Emergency flashlight       \$27       \$27         Y68       Paint preservative       \$187       \$212		standard with C02/C03	<u> </u>	
Y68 Paint preservative \$187 \$212	Y10	First-aid kit	\$27	\$27
· · · · · · · · · · · · · · · · · · ·	Y45	Emergency flashlight	\$27	\$27
Y69 Surface protection for stock vehicles \$315	Y68	Paint preservative	\$187	\$212
	Y69	Surface protection for stock vehicles	\$315	\$315

**Packages** 

144" 4C	170" 4C
12 seats	15 seats
M2PV44	M2PV74
907.743	907.745

C00	Comfort Package	\$300	\$300	
LC4	Comfort overhead control panel	X	X	
SE4	Lumbar support, co-driver's seat	X	X	
SE5	Lumbar support, driver's seat	X	X	
SK0	Comfort head restraint, driver	Х	X	
SK1	Comfort head restraint, co-driver	Х	X	
S28	Armrest, driver and passenger door	X	X	
must have S28 + (COS OR X68); not with S23				

COS	Comfort Package (Seat addition)	\$381	\$381	
SB1	Comfort driver's seat	X	X	
SB2	Comfort passenger seat	X	X	
must	must have COO			

X68	Comfort Plus Package	\$1,923	\$1,923	
H15	Heated front passenger seat	Х	X	
H16	Heated driver's seat	Х	X	
SF1	Driver's seat electrically adjustable	Х	X	
SF2	Co-driver's seat electrically adjustable	Х	X	
must	must have C00 and VF4 OR VF6, CA/CC only: not with S23			

C01	Driver Convenience Package	\$760	\$760
E46	12 V power outlet, driver seat base	X	X
F64	Electrically folding exterior mirrors	X	X
FJ1	Hinged lid for storage compartment	S	S
FJ5	Hinged Lid for Storage Compartments left and right	X	X
FZ9	Keys, two additional masters	X	X
JA7	Blind Spot Assist	X	X
JW8	Attention Assist	X	X
no re	strictions		

C02	Premium Package	\$983	\$983			
CL3	Leather steering wheel	X	X			
E3M	MBUX Multimedia System with 7" touchscreen	X	X			
FM3	Wet Wiper System	X	X			
JB4	Active Lane Keeping Assist	X	X			
JK5	Instrument cluster with color display	X	X			
Ordo	Ordering qualishility restricted, see NatStar for qualishility and restrictions must have IE1 + VMA+					

Ordering availability restricted, see NetStar for availability and restrictions | must have JF1 + XM4; must choose FR8/JB7/JB6

CA2	C02 in combination with C03	\$604	\$604	
CL3	Leather steering wheel	X	X	
FM3	Wet Wiper System	X	X	
JB4	Active Lane Keeping Assist	X	X	
JK5	Instrument cluster with color display	X	X	
Ordering qualibility restricted, see NotStar for qualibility and restrictions must have CO2 + JE1				

Ordering availability restricted, see NetStar for availability and restrctions | must have CO3 + JF1

Packages

144" 4C	170" 4C	
12 seats	15 seats	
M2PV44	M2PV74	
907.743	907.745	

C03	Premium Plus Package	\$1,793	\$1,793		
E1B	Tray for smartphones incl. wireless charging	X	Х		
	Navigation	Х	Х		
EY2	Intelligent navigation	X	Х		
E4M	MBUX Multimedia System with 10.25" touchscreen	X	Х		
EX9	Free map data updates for 3 years	Х	Х		
H1I	Front-to-rear outlet in instrument panel	X	Х		
JA9	Traffic Sign Assist	X	Х		
XM4	Acoustic package	X	Х		
must	must have (CA2+(JB7/JB6/JB8)) OR (JB4+JK5+FM3+(JB7/JB6/JB8)); not with FR8 and CO2				

X67	Chrome Grille Package	\$290	\$290	
CN2	Radiator grille frame in vehicle color	X	X	
FK3	Chrome plated radiator grille (MB only)	X	X	
no restrictions				

X13	Exterior Lighting Package	\$1,608	\$1,608		
L13	Fog lamp with cornering light function	Х	Х		
L22	Partial LED tail lights	Х	Х		
LA1	High beam assist	Х	Х		
LG7	LED high performance headlamps	Х	Х		
no re	no restrictions				

X70	Rear Comfort Package	\$1,521	\$1,521		
S31	Convenice head restraints for pass. compartment	Х	X		
U3Y	3-seater comfort bench rear - 3rd row (narrow)	-	X		
UY1	3-seater comfort bench rear, 1st row (narrow)	Х	X		
UY2	3-seater comfort bench rear, 2nd row (narrow)	Х	Х		
UY3	4-seater comfort bench rear, 3rd row	X	•		
UY6	4-seater comfort bench rear, 4th row	-	X		
can have VF4/VF6 only					

X71	Passenger Accessibility Package	\$1,504	\$1,504
T55	Electric sliding door right	X	X
ED5	Parametric special module (PSM)	X	X
T57	Electric sliding step	X	X
FY7	Optional 3-button keys	X	X

Opening limiter for electrically operated sliding door (T60) can be added in combination with the package

X11	High-Performance Rear Air Conditioning Package	\$1,123	\$1,123	
HK4	Rear air conditioner, heavyduty	X	X	
HH4	Thermotronic automatic climate control	X	X	
must have D03; HK4 n/a on gas models				

144" 6C	144" 6C 4x4	170" 6C
12 seats	12 seats	15 seats
M2PV46	M2PV4X	M2PV76
907.743	907.743	907.745

Engin	Engine				
	Engine/7-Speed Trans.	S	S	S	
ED4	AGM battery 12V 92 AH 850 A	S	S	S	
G42	Automatic transmission, 7G-tronic	S	S	S	
	Alternator 14 V/220 A	S	S	S	
-	3.0L V6 turbo diesel engine	S	S	S	
MI0	ULEV emission	S	S	S	
X30	4x4 Package	-	\$8,200	-	
T75	Door-mounted assist handles, driver & passenger	_	\$ <b>5,200</b>	_	
ZG3	4x4 - High range transfer case w/ low gear	_	S	_	
	Seating Configuration		3		
		•			
X7S	Standard Rear Seats	S	S	S	
	3-seater bench rear, 1st row (narrow)	S	S	S	
	3-seater bench rear, 2nd row (narrow)	S	S	S	
UD6	4-seater bench in rear, 3rd row	S	S	-	
U3S	3-seater bench in rear, 3rd row (narrow)	-	-	S	
UD7	4-seater bench in rear, 4th row	-	-	S	
Equip	ment				
A50	Front axle reinforced	-	-	S	
AP2	Addtl. bar for driveshaft & exhaust extension	S	S	S	
AR2	Axle ratio 3.923	S	S	S	
BA3	Active Brake Assist	S	S	S	
BH1	Hold Function	S	S	S	
C6L	Multifunction steering wheel	S	-	S	
CB1	Suspension for comfort and load protection	S	-	S	
CL1	Adjustable steering wheel (angle)	S	S	S	
CT1	Rear spring vibration absorbers	S	S	S	
D03	High roof	0	0	S	
E07	Hill Start Assist	S	S	S	
E10	Standard radio	S	S	S	
E1U	USB-C socket, 5 V	S	S	S	
E30	Starter battery disconnect	S	S	S	
E3J	Pre-installation for switch panel	S	-	S	
E40	Trailer hitch prep. wiring	S	S	-	
ED8	Preinstallation PSM	S	S	S	
EE5	Ultracapacitor discharge module	S	S	S	
EK1	Body Builder Connector	S	S	S	
EL9	Audio systems speakers, 5 front, 8 rear	S	S	S	
ES0	Jump start terminal	S	S	S	
ES2					
ESZ EW6	12 V power outlet, rear compartment Pre-installation for Mercedes me Remote Services	S	S S	S S	
		S		S	
EY5	Emergency Call System  Proakdown management		S		
EY6	Breakdown management	S	S	S	
F43	Laminated glass rear	S	S	S	
F68	Heated & electrically adjustable exterior mirrors	S	S	S	
FF0	Coat hooks	S	S	S	
FF3	Cupholder rear compartment	S	S	S	
FF5	Shelf above windshield	S	S	S	
FG8	Cupholder front	S	S	S	
FI1	Remote key (315 mhz) w/central locking	S	S	S	
FJ1	Hinged lid for storage compartment	S	S	S	
FJ4	Storage compartment underneath cockpit	S	S	S	
FR3	Rear view camera (rear-view mirror display)	S	S	S	
H00	Warm/cool air duct to rear compartment	S	S	S	
H01	Heat insulation, rear compartment	S	S	S	

MY 2022 Dealer Ordering Guide

#### 2500 PASSENGER VAN - 6cyl Diesel

		144" 6C	144" 6C 4x4	170" 6C
		12 seats	12 seats	15 seats
		M2PV46	M2PV4X	M2PV76
		907.743	907.743	907.745
H04	Heat insulation, front compartment	S	S	S
H08	Air conditioning rear, roof-mounted	S	S	S
H13	Rear cabin heater and vents	S	S	S
H1I	Front-to-rear outlet in instrument panel	S	S	S
H21	Windshield with filter band	S	S	S
H22	Rear window defroster	S	S	S
HH2	Heater, auxiliary electric hot air	S	S	S
HH9	Air Condition, Front	S	S	S
HZ9	Fuel-fired heater booster (18,000 BTU)	S	S	S
IH7	Headunit North America	S	S	S
J11	Speedometer, miles and km/h	S	S	S
J55	Seat belt warning for co-driver seat	S	S	S
J58	Seat belt reminder driver	S	S	S
J65	Outside temperature gauge	S	S	S
JA8	Crosswind Assist	S	S	S
JH3	Communication module (LTE) for dig. services	S	S	S
JI9	Service interval 20.000 miles	S	S	S
K56	Red diesel filler cap	S	S	S
K60	Exhaust straight to rear	S	S	S
KB7	24.5 gallon fuel tank	S	S	S
KL5	Fuel filter with water separator	S	S	S
KP6	3rd generation SCR emission control system	S	S	S
L94	Parking lights deletion	S	S	S
LA2	Headlight assistant	S	S	S
LB5	3rd brake light	S	S	S
LB9	Illuminated front exits	S	S	S
MS1 P47	Cruise control Front mudflaps	S	S S	S S
P47 P48	Rear mudflaps	S S	S	S S
Q00	Constrained towing capacity (0 lbs)	-	_	S
Q00 Q11	Longitudinal member reinforcement	S	S	S
Q11 Q67	Tow hook rear	S	S	S
R65	Spare tire bracket below frame	S	S	S
R87	Spare tire	S	S	S
RD9	Unspecified tire brand	S	S	S
RH8	Tires LT 245/75 R16	S	S	S
RM0	All-season tires	S	S	S
RS3	6.5 J x 16 steel wheels	S	S	S
RY2	Tire pressure monitoring sensors	S	S	S
S02	Standard driver seat	S	S	S
S04	Standard front passenger seat	S	S	S
S22	Armrest for driver's seat	S	S	S
S25	Armrest for front passenger seat	S	S	S
SA5	Front airbag, driver	S	S	S
SA6	Front airbag, passenger	S	S	S
SH1	Thorax-pelvis sidebag, driver	S	S	S
SH2	Thorax-pelvis sidebag, co-driver	S	S	S
SH9	Airbag, driver/passenger window	S	S	S
SK2	Seat occupancy sensor, driver's seat	S	S	S
SZ7	Storage net, driver's seat backrest	S	S	S
SZ8	Storage net, passenger seat backrest	S	S	S
T16	Sliding door, passenger side	S	S	S
T74	Assist handle, B-pillar	S	S	S
U1A	14+1-seater version	-	-	S
U28	Pre-inst. for seating configuration 12-seater	S	S	-
U29	Pre-inst. for seating configuration 15-seater	-	-	S
U74	Wall-side armrest	S	S	S

#### 2500 PASSENGER VAN - 6cyl Diesel

		144" 6C	144" 6C 4x4	170" 6C
		12 seats	12 seats	15 seats
		M2PV46	M2PV4X	M2PV76
		907.743	907.743	907.745
		907.743	907.743	907.745
U75	Aisle-side armrest	S	S	S
V21	Luxury interior Trim	S	S	S
V31	Window pillar trim	S	S	S
V35	Wheel house covering	S	S	S
V36	Roof trim	S	S	S
V39	Weight optimized plastic floor	S	S	S
V40	Floor anchors for rear seat bench	S	S	S
VA7	Storage compart. w/ net in rear doors	S	S	S
W02	Panel van w/windows all round	S	S	S
W17	2nd row, fixed window, passenger side	S	S	S
W22	Fixed window, center left	-	-	S
W23	Fixed window, center right	-	-	S
W27	Fixed window, rear left	S	S	S
W28	Fixed window, rear right	S	S	S
W33	FMVSS 217 emergency exit	S	S	S
W61	Windows in rear doors	S	S	S
W70	Black tinting (90%) for rear windows	S	S	S
X2B	GVWR 9,480 lbs. / 4,300 kg	-	-	S
XL2	GVWR 9,050 lbs. / 4.100 Kg	S	S	-
Y43	Jack, hydraulic	S	S	S

### 2500 PASSENGER VAN - 6cyl Diesel

Options

9,050 GVWR

12 seats   12 seats   12 seats   12 seats   15 seats   16 seats   16 seats   16 seats   16 seats   16 seats   17 seats			144" 6C	144" 6C 4x4	170" 6C
### 807.743   907.743   907.745   ### 807.745   80   -     80   ### 807.745   80   ### 807.745   80   -     80   ### 807.745			12 seats	12 seats	15 seats
AR3 Axie ratio 4.182			M2PV46	M2PV4X	
Description   Security   Securi			907.743	907.743	
Description   Security   Securi	AR3	Axle ratio 4.182	\$0	- 1	\$0
S279			70		7.5
Sample	B25		\$279	\$279	\$279
C72   Bumpers front/rear primed   \$268   \$268   \$268   \$268   \$268   must hove CN2/X67, not with CMO					
Must hove (CDZ/ESM)/CO3 + (ET4/MS1)		not with ZG3			·
CL3   eather steering wheel	C72	Bumpers front/rear primed	\$268	\$268	\$268
Most   Nave   CO2/E3M /CO3 + (ET4/MS1)   SS87   SS87   SS87   Most   Nave   CO2/E3M /CO3 + (ET4/MS1)   SS87   SS87   Most   Nave   Na		must have CN2/X67, not with CM0	•		
Sample   S	CL3	Leather steering wheel	\$187	\$187	\$187
must have CN2 (part of X67) + (JA7/C01) + (JB6/JB7) + (7755/9197/9775)   S364   S365   S2900   S2,900   S2,900   S2,900   S2,900   S2,900   S300		must have (C02/E3M)/C03 + (ET4/MS1)	•	,	
Frinced side moldings	CM0	Painted metallic front & rear bumper	\$587	\$587	\$587
Section   Sect		must have CN2 (part of X67) + (JA7/C01) + (JB6/JB7) + (7755/92	197/9775)		
1913   Mounting rails for roof rack	CM9	Primed side moldings	\$364	\$364	\$364
Tray for smartphones incl. wireless charging	D03	High roof	\$2,900	\$2,900	S
### ### ### ### ### ### ### ### ### ##	D13	Mounting rails for roof rack	\$300	\$300	\$300
Strius XM, satellite ratio   \$728	E1B	Tray for smartphones incl. wireless charging	\$156	\$156	\$156
### ### ### ### ### ### ### ### ### ##		must have CO2/E3M			
E1S Sirius XM, satellite radio  must have CO2/E3M/C03  must have CO2/E3M/C03  E1Y Additional Fuses (40/80/150/100 Ampere)  E1Y Additional Fuses (40/80/150/100 Ampere)  E1Y Additional Fuses (40/80/80/80/100 Ampere)  E1Y Additional Fuses (40/80/80/80/100 Ampere)  E2A Access point for BB special signals in cockpit  E2A Access point for BB special signals in cockpit  E3A Additional battery, co-driver seat base  E2A Additional battery, co-driver seat base  E3A E4A E3A E3A E3A E3A E3A E3A E3A E3A E3A E3	E1E	Navigation	\$728	\$728	\$728
### ### ### ### ### ### ### ### ### ##		must have CO2/E3M, not with CO3			
E1R Additional Fuses (40/80/150/100 Ampere) \$50 \$50 \$50 \$50 \$50 \$50 \$50 \$50 \$50 \$50	E1S	Sirius XM, satellite radio	\$255	\$255	\$255
SoP and Plausibility TBD		must have C02/E3M/C03			
E1Y Additional Fuses (40/80/80/100 Ampere) \$50 \$50 \$50 \$50 \$PV plausi 12 seater \$224 Access point for BB special signals in cockpit \$29 \$29 \$29 \$29 \$29 \$29 \$29 \$29 \$29 \$29	E1R	Additional Fuses (40/80/150/100 Ampere)	\$50	\$50	\$50
PV plausi 12 seater         \$29         \$29         \$29           EZA         Access point for BB special signals in cockpit         \$29         \$29         \$29           EZI         Additional battery, co-driver seat base         \$248         \$248         \$-           Must have E36; not with E2M         \$110         \$110         \$110         \$110           E36         Cutoff relay for additional battery         \$110         \$110         \$110         \$110           E36         Cutoff relay for additional battery         \$110         \$110         \$110         \$110           E37         Standard with E2/E2M         \$474         \$474         \$474         \$474           E38         MBUX Multimedia System with 7" touchscreen         \$474         \$474         \$474           and with C02/C03; must have XISF/IBF/IB6/IB8/IB8/IB8/IB8         \$58         \$58         \$58           E5M         Extension of PSM standard contact         \$58         \$58         \$58           E5D         Parametric special module (PSM)         \$317         \$317         \$317         \$317         \$317         \$317         \$317         \$317         \$317         \$317         \$317         \$317         \$317         \$317         \$317         \$317 <t< td=""><td></td><td>SoP and Plausibility TBD</td><td></td><td></td><td></td></t<>		SoP and Plausibility TBD			
E2A         Access point for BB special signals in cockpit         \$29         \$29         \$29           E2I         Additional battery, co-driver seat base         \$248         \$248         -           Mush have E36; not with E2M         \$110         \$110         \$110           E3A         Cutoff relay for additional battery         \$110         \$110         \$110           E3M         MBUX Multimedia System with 7" touchscreen         \$474         \$474         \$474           not with C02/C03; must have /K5+(/B7//B6//B8/FR8)         \$58         \$58         \$58           E5M         Extension of PSM standard contact         \$58         \$58         \$58           E5D         Parametric special module (PSM)         \$317         \$317         \$317           not with ED8         \$15 V socket         \$125         \$125         \$125           E63         115 V socket         \$125         \$125         \$125           E64         Active Distance Assist DISTRONIC         \$263         \$263         \$263           E74         Active Distance Assist DISTRONIC         \$263         \$263         \$263           E74         Active Distance Assist DISTRONIC         \$258         \$218         \$218           E74         Active Distan	E1Y	Additional Fuses (40/80/80/100 Ampere)	\$50	\$50	\$50
E21   Additional battery, co-driver seat base   \$248   \$		PV plausi 12 seater			
Must have E36; not with E2M         \$110         \$110         \$110           E36         Cutoff relay for additional battery         \$110         \$110         \$110           standard with E2/E2M         \$474         \$474         \$474           E3M         MBUX Multimedia System with 7" touchscreen not with C02/C03; must have JK5+(JB7/JB6/JB8/FR8)         \$474         \$474         \$474           E5M         Extension of PSM standard contact         \$58         \$58         \$58           ED5         Parametric special module (PSM)         \$317         \$317         \$317           not with ED8         \$125         \$125         \$125         \$125           EE3         115 V socket         \$125         \$125         \$125           Charging package, dashboard         \$82         \$82         \$82           E63         115 V socket         \$125         \$125         \$125           E14         Active Distance Assist DISTRONIC         \$263         \$263         \$263           must have C02/C03/E3M; not with ZH4         \$218         \$218         \$218           F49         Electrically heated windshield         \$218         \$218         \$218           F61         Interior rear view mirror         \$0         \$0 <t< td=""><td>E2A</td><td>Access point for BB special signals in cockpit</td><td>\$29</td><td>\$29</td><td>\$29</td></t<>	E2A	Access point for BB special signals in cockpit	\$29	\$29	\$29
E36         Cutoff relay for additional battery         \$110         \$110         \$110           standard with E2I/E2M         \$474         \$474         \$474           E3M         MBUX Multimedia System with 7" touchscreen         \$474         \$474         \$474           not with CO2/CO3; must have JKS+(JB7/JB6/JB8/FR8)         \$58         \$58         \$58           E5M         Extension of PSM standard contact         \$58         \$58         \$58           ED5         Parametric special module (PSM)         \$317         \$317         \$317           not with ED8         ***Extension of PSM standard contact         \$58         \$58         \$58           EB3         115 V socket         \$125         \$125         \$125           EB4         Active Distance Assist DISTRONIC         \$82         \$82         \$82           ES5         Charging package, dashboard         \$263         \$263         \$263         \$263           EB4         Active Distance Assist DISTRONIC         \$82         \$82         \$82           ES4         Active Distance Assist DISTRONIC         \$263         \$263         \$263         \$263           E10         Interior activitions         \$218         \$218         \$218	E2I	Additional battery, co-driver seat base	\$248	\$248	-
standard with E2I/E2M         \$474         \$474         \$474           B3M         MBUX Multimedia System with 7" touchscreen         \$474         \$474         \$474           not with C02/C03; must have JK5+(JBT/JB6/JB8/FR8)         \$58         \$58         \$58           E5M         Extension of PSM standard contact         \$58         \$58         \$58           ED5         Parametric special module (PSM)         \$317         \$317         \$317         \$317           not with ED8         \$58 </td <td></td> <td></td> <td></td> <td></td> <td></td>					
E3M         MBUX Multimedia System with 7" touchscreen not with CO2/CO3; must have JK5+(JB7/JB6/JB8/FR8)         \$474         \$474         \$474           E5M         Extension of PSM standard contact         \$58         \$58         \$58           ED5         Parametric special module (PSM)         \$317         \$317         \$317           not with ED8         \$125         \$125         \$125           E53         115 V socket         \$125         \$125         \$125           E55         Charging package, dashboard         \$82         \$82         \$82           E74         Active Distance Assist DISTRONIC         \$263         \$263         \$263           must have CO2/CO3/E3M; not with ZH4         \$218         \$218         \$218           F61         Interior rear view mirror         \$0         \$0         \$0           must have CO2/CO3/E3M         \$0         \$0         \$0           F64         Electrically folding exterior mirrors         \$49         \$49         \$49           no restrictions         \$81         \$81         \$81           FF8         Additional DIN-slot         \$81         \$81         \$81           FF8         Overhead storage slot, front center         \$105         \$105         \$105	E36	Cutoff relay for additional battery	\$110	\$110	\$110
E5M         Extension of PSM standard contact         \$58         \$58         \$58           ED5         Parametric special module (PSM)         \$317         \$317         \$317           not with ED8         EE3         \$115 V socket         \$125         \$125         \$125           ES5         Charging package, dashboard         \$82         \$82         \$82         \$82           ET4         Active Distance Assist DISTRONIC         \$263         \$263         \$263           must have CO2/CO3/E3M; not with ZH4         Electrically heated windshield         \$218         \$218         \$218           F61         Interior rear view mirror         \$0         \$0         \$0           must have CO2/CO3/E3M         F64         Electrically folding exterior mirrors         \$49         \$49         \$49           F64         Electrically folding exterior mirrors         \$81         \$81         \$81           F69         Additional DIN-slot         \$81         \$81         \$81           FF8         Overhead storage slot, front center         \$105         \$105         \$105           FR8         Rear view camera (head unit display)         \$336         \$336         \$336           FY1         Security alarm w. inte	E3M	·	\$474	\$474	\$474
ED5   Parametric special module (PSM)   \$317   \$3					
EE3       115 V socket       \$125       \$125       \$125         ES5       Charging package, dashboard       \$82       \$82       \$82         ET4       Active Distance Assist DISTRONIC       \$263       \$263       \$263         must have CO2/CO3/E3M; not with ZH4       F49       Electrically heated windshield       \$218       \$218       \$218         F61       Interior rear view mirror       \$0       \$0       \$0         must have CO2/CO3/E3M       F549       \$49       \$49       \$49         no restrictions       FF9       Additional DIN-slot       \$81       \$81       \$81         FF9       Additional DIN-slot       \$81       \$81       \$81         FR8       Overhead storage slot, front center       \$105       \$105       \$105         FR8       Rear view camera (head unit display)       \$336       \$336       \$336         must have CO2/E3M; not with FR3/JB7/JB6/JB8       FY1       Security alarm w. interior motion sensor       \$584       \$584       \$584         FY2       Optional 3-button keys       \$36       \$36       \$36         FY2       Keys, two additional masters       \$121       \$121       \$121         H12 <td>ED5</td> <td></td> <td>\$317</td> <td>\$317</td> <td>\$317</td>	ED5		\$317	\$317	\$317
S82					
ET4       Active Distance Assist DISTRONIC       \$263       \$263       \$263         must have CO2/C03/E3M; not with ZH4         F49       Electrically heated windshield       \$218       \$218         F61       Interior rear view mirror       \$0       \$0       \$0         must have CO2/C03/E3M       F64       Electrically folding exterior mirrors       \$49       \$49       \$49         no restrictions       FF9       Additional DIN-slot       \$81       \$81       \$81         F80       Overhead storage slot, front center       \$105       \$105       \$105         FR8       Rear view camera (head unit display)       \$336       \$336       \$336         must have CO2/E3M; not with FR3/JB7/JB6/JB8       FY1       Security alarm w. interior motion sensor       \$584       \$584       \$584         must have LC4/C00       FY7       Optional 3-button keys       \$36       \$36       \$36         FZ9       Keys, two additional masters       \$121       \$121       \$121         H12       Fuel-fired pre-heater/booster (17K BTU)       \$826       \$826       \$826         not with HZ9/J51/KL1       \$124       \$284       \$284       \$284	_				
must have CO2/CO3/E3M; not with ZH4           F49 Electrically heated windshield         \$218         \$218         \$218           F61 Interior rear view mirror         \$0         \$0         \$0           must have CO2/CO3/E3M         \$49         \$49         \$49           F64 Electrically folding exterior mirrors         \$49         \$49         \$49           no restrictions         \$81         \$81         \$81           FE9 Additional DIN-slot         \$81         \$81         \$81           F78 Overhead storage slot, front center         \$105         \$105         \$105           FR8 Rear view camera (head unit display)         \$336         \$336         \$336           must have CO2/E3M; not with FR3/JB7/JB6/JB8         \$584         \$584         \$584           FY1 Security alarm w. interior motion sensor         \$584         \$584         \$584           must have LC4/C00         \$36         \$36         \$36           FY7 Optional 3-button keys         \$36         \$36         \$36           FZ9 Keys, two additional masters         \$121         \$121         \$121           H12 Fuel-fired pre-heater/booster (17K BTU)         \$826         \$826         \$826           not with HZ9/J51/KL1         \$105         \$105         \$105			·		
F49         Electrically heated windshield         \$218         \$218           F61         Interior rear view mirror         \$0         \$0         \$0           must have CO2/CO3/E3M         F64         Electrically folding exterior mirrors         \$49         \$49         \$49           no restrictions         FF9         Additional DIN-slot         \$81         \$81         \$81           FF8         Overhead storage slot, front center         \$105         \$105         \$105           FR8         Rear view camera (head unit display)         \$336         \$336         \$336           must have C02/E3M; not with FR3/JB7/JB6/JB8           FY1         Security alarm w. interior motion sensor         \$584         \$584         \$584           Must have LC4/C00           FY7         Optional 3-button keys         \$36         \$36         \$36           FZ9         Keys, two additional masters         \$121         \$121         \$121           H12         Fuel-fired pre-heater/booster (17K BTU)         \$826         \$826         \$826           not with HZ9/J51/KL1         H15         Heated front passenger seat         \$284         \$284         \$284	ET4		\$263	\$263	\$263
F61         Interior rear view mirror         \$0         \$0         \$0           must have CO2/CO3/E3M         F64         Electrically folding exterior mirrors         \$49         \$49         \$49           F69         Additional DIN-slot         \$81         \$81         \$81           F78         Overhead storage slot, front center         \$105         \$105         \$105           FR8         Rear view camera (head unit display)         \$336         \$336         \$336           must have CO2/E3M; not with FR3/JB7/JB6/JB8         FY1         Security alarm w. interior motion sensor         \$584         \$584         \$584           must have LC4/C00         FY7         Optional 3-button keys         \$36         \$36         \$36           FZ9         Keys, two additional masters         \$121         \$121         \$121           H12         Fuel-fired pre-heater/booster (17K BTU)         \$826         \$826         \$826           not with HZ9/J51/KL1         H15         Heated front passenger seat         \$284         \$284         \$284			<b>4</b> c : -	1 4	4
must have CO2/CO3/E3M           F64         Electrically folding exterior mirrors         \$49         \$49         \$49           no restrictions         \$81         \$81         \$81           FE9         Additional DIN-slot         \$81         \$81         \$81           FF8         Overhead storage slot, front center         \$105         \$105         \$105           FR8         Rear view camera (head unit display)         \$336         \$336         \$336           must have CO2/E3M; not with FR3/JB7/JB6/JB8         \$584         \$584         \$584           FY1         Security alarm w. interior motion sensor         \$584         \$584         \$584           must have LC4/C00         \$36         \$36         \$36         \$36           FY7         Optional 3-button keys         \$36         \$36         \$36           FZ9         Keys, two additional masters         \$121         \$121         \$121           H12         Fuel-fired pre-heater/booster (17K BTU)         \$826         \$826         \$826           not with HZ9/J51/KL1         H15         Heated front passenger seat         \$284         \$284         \$284					
F64       Electrically folding exterior mirrors       \$49       \$49       \$49         no restrictions       FE9       Additional DIN-slot       \$81       \$81       \$81         FF8       Overhead storage slot, front center       \$105       \$105       \$105         FR8       Rear view camera (head unit display)       \$336       \$336       \$336         must have C02/E3M; not with FR3/JB7/JB6/JB8       FY1       Security alarm w. interior motion sensor       \$584       \$584       \$584         must have LC4/C00       FY7       Optional 3-button keys       \$36       \$36       \$36         FZ9       Keys, two additional masters       \$121       \$121       \$121         H12       Fuel-fired pre-heater/booster (17K BTU)       \$826       \$826       \$826         not with HZ9/J51/KL1       \$284       \$284       \$284       \$284	F61		<b>\$</b> 0	\$0	<b>\$</b> 0
no restrictions           FE9         Additional DIN-slot         \$81         \$81         \$81           FF8         Overhead storage slot, front center         \$105         \$105         \$105           FR8         Rear view camera (head unit display)         \$336         \$336         \$336           must have CO2/E3M; not with FR3/JB7/JB6/JB8         FY1         Security alarm w. interior motion sensor         \$584         \$584         \$584           must have LC4/C00         FY7         Optional 3-button keys         \$36         \$36         \$36           FZ9         Keys, two additional masters         \$121         \$121         \$121           H12         Fuel-fired pre-heater/booster (17K BTU)         \$826         \$826         \$826           not with HZ9/J51/KL1         H15         Heated front passenger seat         \$284         \$284         \$284         \$284	F / *		640	640	¢40
FE9       Additional DIN-slot       \$81       \$81       \$81         FF8       Overhead storage slot, front center       \$105       \$105       \$105         FR8       Rear view camera (head unit display)       \$336       \$336       \$336         must have CO2/E3M; not with FR3/JB7/JB6/JB8         FY1       Security alarm w. interior motion sensor       \$584       \$584       \$584         must have LC4/C00         FY7       Optional 3-button keys       \$36       \$36       \$36         FZ9       Keys, two additional masters       \$121       \$121       \$121         H12       Fuel-fired pre-heater/booster (17K BTU)       \$826       \$826       \$826         not with HZ9/J51/KL1       \$284       \$284       \$284       \$284	F64		\$49	\$ <b>4</b> 9	\$49
FF8         Overhead storage slot, front center         \$105         \$105           FR8         Rear view camera (head unit display)         \$336         \$336         \$336           must have CO2/E3M; not with FR3/JB7/JB6/JB8         FY1         Security alarm w. interior motion sensor         \$584         \$584         \$584           must have LC4/C00         FY7         Optional 3-button keys         \$36         \$36         \$36           FZ9         Keys, two additional masters         \$121         \$121         \$121           H12         Fuel-fired pre-heater/booster (17K BTU)         \$826         \$826         \$826           not with HZ9/J51/KL1         H15         Heated front passenger seat         \$284         \$284         \$284	FFO		604	604	Ć01
FR8       Rear view camera (head unit display)       \$336       \$336       \$336         must have CO2/E3M; not with FR3/JB7/JB6/JB8         FY1       Security alarm w. interior motion sensor       \$584       \$584         must have LC4/C00         FY7       Optional 3-button keys       \$36       \$36         FZ9       Keys, two additional masters       \$121       \$121         H12       Fuel-fired pre-heater/booster (17K BTU)       \$826       \$826       \$826         not with HZ9/J51/KL1       \$284       \$284       \$284	_		·		
must have C02/E3M; not with FR3/JB7/JB6/JB8         FY1       Security alarm w. interior motion sensor       \$584       \$584       \$584         must have LC4/C00       \$36       \$36       \$36         FY7       Optional 3-button keys       \$36       \$36       \$36         FZ9       Keys, two additional masters       \$121       \$121       \$121         H12       Fuel-fired pre-heater/booster (17K BTU)       \$826       \$826       \$826         not with HZ9/J51/KL1       \$284       \$284       \$284					
FY1       Security alarm w. interior motion sensor       \$584       \$584       \$584         must have LC4/C00       FY7       Optional 3-button keys       \$36       \$36       \$36         FZ9       Keys, two additional masters       \$121       \$121       \$121         H12       Fuel-fired pre-heater/booster (17K BTU)       \$826       \$826       \$826         not with HZ9/J51/KL1       H15       Heated front passenger seat       \$284       \$284       \$284	1 1/0		Ş330	3330 3330	<b>3330</b>
must have LC4/C00         FY7 Optional 3-button keys       \$36       \$36       \$36         FZ9 Keys, two additional masters       \$121       \$121       \$121         H12 Fuel-fired pre-heater/booster (17K BTU)       \$826       \$826       \$826         not with HZ9/J51/KL1       \$284       \$284       \$284	EV1		¢εοл	¢59/I	¢59 <i>1</i>
FY7         Optional 3-button keys         \$36         \$36         \$36           FZ9         Keys, two additional masters         \$121         \$121         \$121           H12         Fuel-fired pre-heater/booster (17K BTU)         \$826         \$826         \$826           not with HZ9/J51/KL1         H15         Heated front passenger seat         \$284         \$284         \$284	111		<i>\$</i> 304	320 <del>4</del>	\$30 <del>4</del>
FZ9       Keys, two additional masters       \$121       \$121         H12       Fuel-fired pre-heater/booster (17K BTU)       \$826       \$826         not with HZ9/J51/KL1         H15       Heated front passenger seat       \$284       \$284	EV7		\$26	\$26	\$26
H12       Fuel-fired pre-heater/booster (17K BTU)       \$826       \$826       \$826         not with HZ9/J51/KL1       H15       Heated front passenger seat       \$284       \$284       \$284					
not with HZ9/J51/KL1           H15 Heated front passenger seat         \$284         \$284					
H15 Heated front passenger seat \$284 \$284 \$284	1114		γο20	<b>γο</b> Ζυ	9020
	H15		\$284	\$284	\$284
I HILLAND HAVE TITO, HOLLWITH AUC		must have H16; not with X68	γ20 <del>1</del>	<b>720</b> ₹	<b>920</b> -1

170" 6C

### 2500 PASSENGER VAN - 6cyl Diesel

Options

144" 6C

144" 6C 4x4

		12 seats	12 seats	15 seats
		M2PV46	M2PV4X	M2PV76
		907.743	907.743	907.745
H16	Heated driver's seat	\$284	\$284	\$284
	must have H15; not with X68	•	•	•
HH4	Thermotronic automatic climate control	\$337	\$337	\$337
	must have JF1			
J51	Fuel gauge, optimized for aux. fuel tap	\$72	\$72	\$72
	not with HZ9/H12			
J52	Engine oil level display at cold start	\$0	\$0	\$0
JA7	Blind Spot Assist	\$450	\$450	\$450
	must have F64			
JB4	Active Lane Keeping Assist	\$288	\$288	\$288
	standard with CO2/CA2			
JB6	Parking Package with 360 degree camera	\$775	\$775	\$775
	must have CO2/CO3/E3M; not with JB7			
JB7	Parking Package	\$615	\$615	\$615
	must have CO2/CO3/E3M; not with JB6			•
JB8	360 Degree Camera	\$685	\$685	\$685
	SoP and Plausibility TBD			
JF1	Rain sensor	\$106	\$106	\$106
	standard with C02/X11			
JK5	Instrument cluster with color display	\$144	\$144	\$144
	standard with CO3	1 4	1 4	1
	Backup alarm	\$99	\$99	\$99
JW2	Deactivation lamp monitoring failure	\$34	\$34	\$34
JW8	Attention Assist	\$49	\$49	\$49
K51	Misfueling prevention for Diesel	\$49	\$49	\$49
K52	DEF fluid filler cap - lockable	\$27	\$27	\$27
L13	Fog lamp with cornering light function	\$199	\$199	\$199
LC4	Comfort overhead control panel	\$93	\$93	\$93
M20	Speed limitation 65 mph	\$60	\$60	\$60
145.0	not with MD3	1 400	1 4	400
MD3	Top speed limitation 75 mph	\$60	\$60	\$60
NICO	not with M20	6467	L 6467	<b>6467</b>
N62	Front engine bracket for additional alternator	\$467	\$467	\$467
004	not with X11	64.47	Ć4.47	
Q24	Trailer hitch, 5,000 lbs	\$147	\$147	-
0.4.0	not with W73	Ć4.04	C4.04	
QA9	Half-sided step rear (for trailer hitch)	\$101	\$101	-
DO 1	must have Q24, not with W73	¢110	Ć110	Ć110
R91	Spare tire deletion	-\$110	-\$110	-\$110
DOO	must have R92; not with R87	ćo	Ċ0.	ćo
R92	Spare tire carrier deletion  must have R91; not with R65	\$0	\$0	\$0
DOO		\$81	Ć01	\$81
R98	Rims painted jet black not with RL5/RM2	\$81	\$81	\$91
RF1	Tire brand Continental	\$0	\$0	\$0
IXI I	must have RM1 + RM9	ŞU	γU	υÇ
RF8	Tire brand Michelin	\$0	\$0	\$0
IXI O	must have RM9; not with RM1	ŞU	٥٠	Ų
RH0	Tire brand Kumho	\$0	\$0	\$0
13110	must have RM9; not with RM1	٧٠	70	γŪ
RL5	Light-alloy wheels 6.5 J x 16	\$906	\$906	\$906
11.2	not with RS3/RM2/R98	7500	<b>\$300</b>	<del>9</del> 500
RM1	M+S winter tires	\$169	\$169	\$169
I SIVI I	must have RF1/RD9; not with RF8/RH0	7103	7103	<b>9103</b>
RM2		\$81	\$81	\$81
TAVIZ		701	701	701
RM2	Rims painted arctic white  not with R98/RL5	\$81	\$81	\$81

#### 2500 PASSENGER VAN - 6cyl Diesel Options

144" 6C	144" 6C 4x4	170" 6C
12 seats	12 seats	15 seats
M2PV46	M2PV4X	M2PV76
907.743	907.743	907.745

		907.743	907.743	907.745
RM9	Specially requested tires	\$101	\$101	\$101
	must have RF1/RF8/RH0; not with RD9	•	•	
S28	Armrest, driver and passenger door	\$51	\$51	\$51
T12	Sliding door two stage opening	\$82	\$82	\$82
	not with T55/X71	•	•	
T50	Electric closing assist right sliding door	\$335	\$335	\$335
	must have D03; not with T55		•	
T55	Electric sliding door right	\$831	\$831	\$831
	must have D03 + (FY7+T16); not with T12/T50		•	
T57	Electric sliding step	\$1,071	\$1,071	\$1,071
	must have ED5			
T60	Opening limiter electrically operated sliding door	\$120	\$120	\$120
	must have T55			
T75	Door-mounted assist handles, driver & passenger	\$59	\$59	\$59
T85	Assist handle, left rear door	\$32	\$32	\$32
T86	Assist handles, right rear door	\$32	\$32	\$32
V85	Cigarette lighter & ash cup, front	\$39	\$39	\$39
V4A	Full paneling, right sliding door	\$109	\$109	\$109
	must have D03+VA5			
VA5	Full paneling, hinged rear doors	\$38	\$38	\$38
	must have D03	•	•	
W54	Rear doors, opening to side wall	\$360	\$360	\$360
W5F	90 Degree fixation point- Rear Doors	\$80	\$80	\$80
	SoP and Plausibility TBD			
W73	Bumper step, rear, grey	\$187	\$187	\$187
	not with Q24			
W78	Heated rear window(s) w/ washers/wipers	\$335	\$335	\$335
	not with W61			
X90	Deletion of Sprinter badge, left rear door	\$0	\$0	\$0
X93	Deletion of model badge, right rear door	\$0	\$0	\$0
XM4	Acoustic package	\$87	\$87	\$87
	standard with C02/C03			•
Y10	First-aid kit	\$27	\$27	\$27
Y45	Emergency flashlight	\$27	\$27	\$27
Y68	Paint preservative	\$187	\$187	\$212
Y69	Surface protection for stock vehicles	\$315	\$315	\$315
ZH4	Downhill speed regulation for 4x4	-	\$58	-

### 2500 PASSENGER VAN - 6cyl Diesel

Packages

144" 6C	144" 6C 4x4	170" 6C
12 seats	12 seats	15 seats
M2PV46	M2PV4X	M2PV76
907.743	907.743	907.745

C00	Comfort Package	\$300	\$300	\$300	
LC4	Comfort overhead control panel	X	X	Х	
SE4	Lumbar support, co-driver's seat	X	X	X	
SE5	Lumbar support, driver's seat	X	X	Х	
SK0	Comfort head restraint, driver	Х	X	Х	
SK1	Comfort head restraint, co-driver	X	X	Х	
S28	Armrest, driver and passenger door	Х	X	Х	
must	must have S28 + (COS OR X68); not with S23				

COS	Comfort Package (Seat addition)	\$381	\$381	\$381	
SB1	Comfort driver's seat	X	X	Х	
SB2	Comfort passenger seat	X	X	X	
must	must have COO				

X68	Comfort Plus Package	\$1,923	\$1,923	\$1,923
H15	Heated front passenger seat	X	X	X
H16	Heated driver's seat	Х	X	X
SF1	Driver's seat electrically adjustable	Х	X	X
SF2	Co-driver's seat electrically adjustable	X	X	X
must	must have COO and VF4 OR VF6, CA/CC only: not with S23			

C01	Driver Convenience Package	\$760	\$760	\$760
E46	12 V power outlet, driver seat base	Х	Х	Х
F64	Electrically folding exterior mirrors	Х	X	Х
FJ1	Hinged lid for storage compartment	S	S	S
FJ5	Hinged Lid for Storage Compartments left and right	X	Х	Х
FZ9	Keys, two additional masters	X	Х	Х
JA7	Blind Spot Assist	X	X	X
JW8	Attention Assist	X	X	X

C02	Premium Package	\$983	\$983	\$983
CL3	Leather steering wheel	X	X	X
E3M	MBUX Multimedia System with 7" touchscreen	X	X	X
FM3	Wet Wiper System	X	Х	X
JB4	Active Lane Keeping Assist	X	Х	Х
JK5	Instrument cluster with color display	X	Х	X
Ordo	ring quallability restricted see NotCtar for quallability and restri	istians I must bays IF	1 . VA 11. may st shoot	C FD0/ID7/ID6

Ordering availability restricted, see NetStar for availability and restrictions | must have JF1 + XM4; must choose FR8/JB7/JB6

CA2	C02 in combination with C03	\$604	\$604	\$604		
CL3	Leather steering wheel	X	X	Х		
FM3	Wet Wiper System	X	Х	X		
JB4	Active Lane Keeping Assist	Х	Х	Х		
JK5	JK5 Instrument cluster with color display X X X					
Orde	Ordering availability restricted, see NetStar for availability and restrctions must have CO3 + JF1					

#### 2500 PASSENGER VAN - 6cyl Diesel

Packages

144" 6C	144" 6C 4x4	170" 6C
12 seats	12 seats 15 seats	
M2PV46	M2PV4X	M2PV76
907.743	907.743	907.745

C03	Premium Plus Package	\$1,793	\$1,793	\$1,793
E1B	Tray for smartphones incl. wireless charging	X	Х	X
	Navigation	X	Х	X
EY2	Intelligent navigation	X	X	X
E4M	MBUX Multimedia System with 10.25" touchscreen	X	Х	X
EX9	Free map data updates for 3 years	X	Х	X
H1I	Front-to-rear outlet in instrument panel	X	Х	X
JA9	Traffic Sign Assist	X	Х	Х
XM4	Acoustic package	Х	Х	Х
must	have (CA2+(JB7/JB6/JB8)) OR (JB4+JK5+FM3+(JB7/JB6/JB8)); no	ot with FR8 and CO2		

X67	Chrome Grille Package	\$290	\$290	\$290	
CN2	Radiator grille frame in vehicle color	Х	Х	Х	
FK3	Chrome plated radiator grille (MB only)	Х	X	Х	
no re	no restrictions				

X13	Exterior Lighting Package	\$1,608	\$1,608	\$1,608	
L13	Fog lamp with cornering light function	Х	X	X	
L22	Partial LED tail lights	Х	Х	Х	
LA1	High beam assist	Х	Х	Х	
LG7	LED high performance headlamps	Х	Х	Х	
no re	no restrictions				

X70	Rear Comfort Package	\$1,521	\$1,521	\$1,521	
S31	Convenice head restraints for pass. compartment	X	Х	Х	
U3Y	3-seater comfort bench rear - 3rd row (narrow)	-	-	X	
UY1	3-seater comfort bench rear, 1st row (narrow)	X	Х	X	
UY2	3-seater comfort bench rear, 2nd row (narrow)	X	Х	X	
UY3	4-seater comfort bench rear, 3rd row	X	Х	-	
UY6	4-seater comfort bench rear, 4th row	-	-	Х	
can h	can have VF4/VF6 only				

X71	Passenger Accessibility Package	\$1,504	\$1,504	\$1,504	
T55	Electric sliding door right	X	X	X	
ED5	Parametric special module (PSM)	X	Х	X	
T57	Electric sliding step	Х	Х	X	
FY7	Optional 3-button keys	Х	Х	X	
Open	Opening limiter for electrically operated sliding door (T60) can be added in combination with the package				

X11	High-Performance Rear Air Conditioning Package	\$1,123	\$1,123	\$1,123	
HK4	Rear air conditioner, heavyduty	X	X	X	
HH4	Thermotronic automatic climate control	X	X	X	
must	must have D03; HK4 n/a on gas models				

Standard Equipment

144" 4C MXCC44 170" 4C

MXCC74

			IVIACC/4
		907.153	907.155
Engin	0		
<u> </u>	e Engine/7-Speed Trans.	S	S
	AGM battery 12V 70AH	<b>S</b>	<b>S</b>
G42	Automatic transmission, 7G-tronic	S	S
-	Alternator 14 V / 200 A	S	S
	2.0L 4-cylinder diesel engine	S	S
-	SULEV emissions	S	S
	choose while ordering	3	3
X34	Dual Rear Wheel	<i>\$</i> 0	\$0
	Tires LT 215/85 R16	S	S
RS6	5.5 J x 16 steel wheels	S	S
	Unspecified tire brand	S	S
<b>X31</b>	Super Single Tire	\$385	\$385
R9A	285/65 R 16 C super single tires	0	0
RS5	Steel wheels: 8.5Jx16 Rr; 6.5Jx16 Fr	0	0
	Unspecified tire brand	0	0
	•		
	Tire pressure monitoring sensors  fication Lights - choose while ordering	0	0
V59	Identification Lamps Package	\$0	<i>\$0</i>
	Identification Lamps Package	3 <i>0</i>	<b>30</b> O
L49 LV7		0	0
	Clearance lights pre-wiring re-wiring only (recommended for RV)	\$ <b>0</b>	
LV7		\$ <b>0</b>	<b>\$0</b>
Equip	Clearance lights pre-wiring	U	U
		ſ	· ·
-	Axle ratio 4.182	S	S
BA3	Active Brake Assist	S	S
BH1	Hold Function	S	S
CB8	Stabilization Level II	S	S
C6L	Multifunction steering wheel	S	S
CL1	Adjustable steering wheel (angle)	S	S
E07	Hill Start Assist	S	S
	Standard radio	S	S
E1U	USB-C socket, 5 V	S	S
E30	Starter battery disconnect	S	S
E3J	Pre-installation for switch panel	S	S
E40	Trailer hitch prep. wiring	S	S
ED8	Preinstallation PSM	S	S
EE5	Ultracapacitor discharge module	S	S
EK1	Body Builder Connector	S	S
ESO	Jump start terminal	S	S
EW6	Pre-installation for Mercedes me Remote Services	S	S
EY5	Emergency Call System	S	S
EY6	Breakdown management	S	S
F68	Heated & electrically adjustable exterior mirrors	S	S
FF5	Shelf above windshield	S	S
FG8	Cupholder front	S	S
FI1	Remote key (315 mhz) w/central locking	S	S
FJ4	Storage compartment underneath cockpit	S	S
FS2	Exterior mirror extended (for up to 96" box width)	S	S
H21	Windshield with filter band	S	S
HH2	Heater, auxiliary electric hot air	S	S
HH9	Air Condition, Front	S	S
IH7	Head Unit, North America	S	S
J11	Speedometer, miles and km/h	S	S
J55	Seat belt warning for co-driver seat	S	S
J58	Seat belt reminder driver	S	S

		144" 4C	170" 4C
		MXCC44	MXCC74
		907.153	907.155
J65	Outside temperature gauge	S	S
JA8	Crosswind Assist	S	S
JH3	Communication module (LTE) for dig. services	S	S
JI9	Service interval 20.000 miles	S	S
JW2	Deactivation lamp monitoring failure	S	S
K56	Red diesel filler cap	S	S
K60	Exhaust straight to rear	S	S
KB7	24.5 gallon fuel tank	S	S
KL1	Aux fuel sending unit w/ fuel tap	S	S
KL5	Fuel filter with water separator	S	S
KP6	3rd generation SCR emission control system	S	S
L94	Parking lights deletion	S	S
LA2	Headlight assistant	S	S
MS1	Cruise control	S	S
P47	Front mudflaps	S	S
Q11	Longitudinal member reinforcement	S	S
Q72	Deletion of end cross member	S	S
R60	Provisional spare wheel bracket frame mounted	S	S
R87	Spare tire	S	S
RM0	All-season tires	S	S
S02	Standard driver seat	S	S
S04	Standard front passenger seat	S	S
S22	Armrest for driver's seat	S	S
S25	Armrest for front passenger seat	S	S
SA5	Front airbag, driver	S	S
SA6	Front airbag, passenger	S	S
SH1	Thorax-pelvis sidebag, driver	S	S
SH2	Thorax-pelvis sidebag, co-driver	S	S
SH9	Airbag, driver/passenger window	S	S
SK2	Seat occupancy sensor, driver's seat	S	S
X5G	Witout load uprating/derating 5,000 kg	S	S
Y43	Jack, hydraulic	S	S

		144" 4C	170" 4C MXCC74
		MXCC44	
		907.153	907.155
	<u> </u>		
A50	Front axle reinforced	\$346	\$346
AR2	Axle ratio 3.923	\$0	\$0
	not with AR3		
B01	ESP for increased Center of Gravity above 39.4"	-	\$0
	must have CB4/CB8; not with RF8		
BE2	Handbrake lever, folding	\$55	\$55
C72	Bumpers front/rear primed	\$141	\$141
	must have CN2 (part of X67), not with CM2		
CE8	Raised rear body mounts	-	\$409
CL3	Leather steering wheel	\$187	\$187
	must have (C02/E3M)/C03 + (ET4/MS1)		
CM2	Bumpers/detachable body parts painted body colour	\$432	\$432
	must have CN2/X67 + (7755/9147/9197/9775)		
CM9	Primed side moldings	\$364	\$364
	must have C72, not with CM2		
E1B	Tray for smartphones incl. wireless charging	\$156	\$156
	must have CO2/E3M + H1I		
E1E	Navigation	\$728	\$728
	must have CO2/E3M, not with CO3		
E1S	Sirius XM, satellite radio	\$255	\$255
	must have CO2/E3M/CO3		
E1X	MBUX multimedia 6-hour runtime	-	\$0
	must have X2R + (C02+E1E/E1S)/C03/(E3M+E1E/E1S)		, -
E1R	Additional Fuses (40/80/150/100 Ampere)	\$50	\$50
	SoP and Plausibility TBD	φσσ	φσσ
E1Y	Additional Fuses (40/80/80/100 Ampere)	\$50	\$50
	SoP and Plausibility TBD	<b>\$30</b>	Ψ30
E2A	Access point for BB special signals in cockpit	\$29	\$29
E2I	Additional battery, co-driver seat base	\$248	\$248
LZI	Must have E36; not with E2M	<b>Ϋ</b> 240	<b>72</b> 40
E2M	Additional battery, engine compartment	\$248	\$248
LZIVI	must have X01+E36; not with E2I/X69	7240	72 <del>4</del> 0
E3M	MBUX Multimedia System with 7" touchscreen	\$474	\$474
LJIVI	not with CO2/CO3; must have JK5	7474	7474
E36	Cutoff relay for additional battery	\$110	\$110
L30	standard with E2I/E2M	\$110	\$110
T 4 C	12 V power outlet, driver seat base	ćoa	ćoa
E46		\$92	\$92
E5M	Extension of PSM standard contact	\$58 \$30	\$58
EA5	Pre-wiring central locking (upfitter doors rear)	\$39	\$39
ED4	AGM battery 12V 92 AH 850 A	\$101	\$101
ED5	Parametric special module (PSM)	\$317	\$317
	not with ED8	4405	4405
EE3	115 V socket	\$125	\$125
EP7	Basic electric fitting for rear loudspeakers	\$68	\$68
ET4	Active Distance Assist DISTRONIC	\$263	\$263
===	must have CO2/CO3/E3M		
ES5	Charging package, dashboard	\$82	\$82
F35	Window in cab rear wall	\$134	\$134
	must have F61/FV1; not with FW1		
F49	Electrically heated windshield	\$218	\$218
	must have ED4; not with LA3		
F61	Interior rear view mirror	\$36	\$36
	must have CO2/CO3/E3M		
FE9	Additional DIN-slot	\$81	\$81
FF8	Overhead storage slot, front center	\$105	\$105
FJ1	Hinged lid for storage compartment	\$93	\$93
	Pre-wiring rear view camera (head unit display)	\$65	\$65
FR7	Pre-wiring real view camera (nead drift display)	<del>-</del>	703

144" 4C

170" 4C

		144 4C	170 4C
		MXCC44	MXCC74
		907.153	907.155
FV1	Pre-wiring rear view camera (mirror display)	\$260	\$260
	not with F61/FR7/LA3	,	
FW1	Rear wall deletion, chassis cab	\$0	\$0
	must have P08; not with FY1		
FY1	Security alarm w. interior motion sensor	\$584	\$584
	must have LC4/C00; not with FW1/X2R		
FY7	Optional 3-button keys	\$36	\$36
FZ9	Keys, two additional masters	\$121	\$121
H04	Heat insulation, front compartment	\$187	\$187
	must have FW1/V07		
H12	Fuel-fired pre-heater/booster (17K BTU)	\$826	\$826
	must have ED4; not with HZ9		
H15	Heated front passenger seat	\$284	\$284
	must have H16; not with X68		
H16	Heated driver's seat	\$284	\$284
	must have H15; not with X68	4.00	4.00
H88	Rear heater prep	\$405	\$405
114.	must have ED4+(H12/HZ9)	A.C.	40
H1I	Front-to-rear outlet in instrument panel	\$0	\$0
	must have FJ1/C01	6227	6227
HH4	Thermotronic automatic climate control	\$337	\$337
HZ9	must have JF1 Fuel-fired heater booster (18,000 BTU)	¢676	¢676
п29	not with H12	\$676	\$676
J1V	Pre-installation Blind Spot Assist	\$450	\$450
JIV	SoP and Plausibility TBD	<b>3430</b>	<b>3430</b>
J51	Fuel gauge, optimized for aux. fuel tap	\$72	\$72
<del>131</del>	not with HZ9/H12	Ş1Z	ŞΙZ
J52	Engine oil level display at cold start	\$0	\$0
JB4	Active Lane Keeping Assist	\$288	\$288
	not with CO2/CA2	<b>7200</b>	<b>7</b> 200
JF1	Rain sensor	\$106	\$106
	standard with CO2; not with LA3	1 2 2	,
JK5	Instrument cluster with color display	\$144	\$144
	standard with CO3		·
JW0	Backup alarm	\$99	\$99
	not wit Q72	•	
JW8	Attention Assist	\$49	\$49
K51	Misfueling prevention for Diesel	\$49	\$49
K52	DEF fluid filler cap - lockable	\$27	\$27
L13	Fog lamp with cornering light function	\$199	\$199
L72	Pre-installation load compartment lighting	\$174	\$174
L76	Wire harness tail lamp w/ extended wiring	\$133	\$133
L77	Wiring for additional turn signals	\$88	\$88
L90	Tail lamp deletion, non-LED	-\$26	-\$26
	not with L22		
L91	Pre-wiring LED tail lights	\$49	\$49
	not with L22/L90		
LA3	Light sensor for vehicles with alcove	\$0	\$0
	not with F49/F61/FV1/LA2/JF1		
LB9	Illuminated front exits	\$93	\$93
LC4	Comfort overhead control panel	\$93	\$93
LV6	Third brake light pre-wiring	\$32	\$32
M20	Speed limitation 65 mph	\$60	\$60
	not with MD3		
	a		1
	Starter upgraded Top speed limitation 75 mph	\$189 \$60	\$189 \$60

144" 4C

170" 4C

		144 40	170 40
		MXCC44	MXCC74
		907.153	907.155
N62	Front engine bracket for additional alternator	\$467	\$467
	not with N63		
N63	Front engine bracket for auxiliary A/C compressor	\$467	\$467
	not with N62		
P08	Cover for transport	\$0	\$0
	must have FW1/X69		
Q18	End cross member bolted	\$65	\$65
QA2	Trailer cross member 7,500 lbs capacity	\$187	\$187
R65	Spare tire bracket below frame	\$0	\$0
	must have Q18; not with Q72/R60/R92		
R91	Spare tire deletion	-\$110	-\$110
	must have R92; not with R87/R60		
R92	Spare tire carrier deletion	\$0	\$0
	must have R91; not with R65/R60		
R98	Rims painted jet black	\$81	\$81
	not with RM2		
RF1	Tire brand Continental	\$0	\$0
	not with RD9		
RF8	Tire brand Michelin	\$0	\$0
	not with RD9/RF1/RM1		
RM1	M+S winter tires	\$169	\$169
	must have RD9/RF1; not with RF8/X31		
RM2	Rims painted arctic white	\$81	\$81
	not with X31/R98		
RM9	Specially requested tires	\$101	\$101
	must have RF1/RF8; not with RD9		
S23	Twin front passenger seat	\$400	\$400
	not with C00/X68/X01		
S28	Armrest, driver and passenger door	\$51	\$51
S62	Seat belts orange, driver and front passenger	\$32	\$32
	not with S23		
SB9	Driver's seat plus	\$238	\$238
	must have FY7		
SZ7	Storage net, driver's seat backrest	\$0	\$0
	must have FW1/X69		
SZ8	Storage net, passenger seat backrest	\$0	\$0
	must have FW1/X69; not with S23		
T75	Door-mounted assist handles, driver & passenger	\$59	\$59
V07	Cab rear wall liner	\$360	\$360
	not with FW1		
V85	Cigarette lighter & ash cup, front	\$39	\$39
VV4	Additional Ground Weld Studs	\$45	\$45
	SoP and Plausibility TBD		
X93	Deletion of model badge, right rear door	\$0	\$0
X2R	Conversion to RV requirement	-	\$0
	must have B01+E1X		
XM4	Acoustic package	\$87	\$87
	standard with CO2/CO3	·	
Y10	First-aid kit	\$27	\$27
Y26	Wheel chocks	\$38	\$38
Y45	Emergency flashlight	\$27	\$27
Y68	Paint preservative	\$88	\$88
Y69	Surface protection for stock vehicles	\$292	\$292

#### 3500XD CAB CHASSIS - 4cyl Diesel

Packages

		144" 4C	170" 4C
		MXCC44	MXCC74
		907.153	907.155
C00   Comfort Pac	kage	\$300	\$300

C00	Comfort Package	\$300	\$300
LC4	Comfort overhead control panel	X	X
SE4	Lumbar support, co-driver's seat	X	X
SE5	Lumbar support, driver's seat	X	X
SK0	Comfort head restraint, driver	X	X
SK1	Comfort head restraint, co-driver	X	X
S28	Armrest, driver and passenger door	X	X
must	have COS OR X68; not with S23		

COS	Comfort Package (Seat addition)	\$381	\$381
SB1	Comfort driver's seat	X	X
SB2	Comfort passenger seat	X	X
must have COO			

X68	Comfort Plus Package	\$1,923	\$1,923	
H15	Heated front passenger seat	X	X	
H16	Heated driver's seat	Х	X	
SF1	Driver's seat electrically adjustable	Х	X	
SF2	Co-driver's seat electrically adjustable	Х	Х	
must	must have C00 and VF4 OR VF6; not with S23			

C01	Driver Convenience Package	\$323	\$323
E46	12 V power outlet, driver seat base	X	X
FJ1	Hinged lid for storage compartment	X	X
FZ9	Keys, two additional masters	X	Х
JW8	Attention Assist	X	X

C02	Premium Package	\$983	\$983
CL3	Leather steering wheel	X	X
E3M	MBUX Multimedia System with 7" touchscreen	X	Х
FM3	Wet Wiper System	Х	X
JB4	Active Lane Keeping Assist	Х	Х
JK5	Instrument cluster with color display	Х	Х
Orde	Ordering availability restricted, see NetStar for availability and restrctions   must have (JF1/LA3) + XM4		

CA2	C02 in combination with C03	\$604	\$604
CL3	Leather steering wheel	X	X
FM3	Wet Wiper System	X	X
JB4	Active Lane Keeping Assist	X	X
JK5 Instrument cluster with color display		Х	X
Orde	ring availability restricted, see NetStar for availability and restro	tions must have C	03 + JF1

Packages

144" 4C	170" 4C
MXCC44	MXCC74
907.153	907.155

C03	Premium Plus Package	\$1,793	\$1,793
E1B	Tray for smartphones incl. wireless charging	X	X
	Navigation	X	X
EY2	Intelligent navigation	X	X
E4M	MBUX Multimedia System with 10.25" touchscreen	X	X
EX9	Free map data updates for 3 years	X	X
H1I	Front-to-rear outlet in instrument panel	X	X
JA9	Traffic Sign Assist	X	X
XM4	Acoustic package	X	X
must	have CA2 OR (JB4+JK5+FM3)	-	

X67	Chrome Grille Package	\$290	\$290	
CN2	Radiator grille frame in vehicle color	X	X	
FK3	Chrome plated radiator grille (MB only)	X	X	
no re	no restrictions			

X13	Exterior Lighting Package	\$1,608	\$1,608	
L13	Fog lamp with cornering light function	X	X	
L22	Partial LED tail lights	X	X	
LA1	High beam assist	Х	X	
LG7	LED high performance headlamps	Х	X	
no re	no restrictions			

X69	Swivel Seat Package	\$587	\$587
SR8	Swivel base for driver's seat	Х	X
SR9	Swivel base for front passenger seat	Х	X
S87	Driver's seat frame, low	Х	Х
S88	Passenger seat frame, low	Х	Х
FW1	Rear wall deletion, chassis cab	Х	X
BE2	Handbrake lever, folding	Х	X
must	have (C00+C0S) OR (C00+X68)		

X01	Suspension Seating Package	\$940	\$940	
SB3	Driver suspension seat, comfort version	X	X	
SB4	Passenger suspension seat, comfort version	X	X	
S87	Driver's seat frame, low	Х	X	
S88	Passenger seat frame, low	X	X	
not with C00/C0S/X68/S23				

Standard Equipment

144" 6C

MXCC46

170" 6C

MXCC76

		MXCC46	MXCC/6		
		907.153	907.155		
Fnair	ρ				
Engine 6-Cyl Engine/7-Speed Trans. S S					
	AGM battery 12V 70AH	S	S		
_	Automatic transmission, 7G-tronic	S	S		
	Alternator 14 V/220 A	S	S		
	3.0L V6 turbo diesel engine	S	S		
_	SULEV emissions	S	S		
	choose while ordering	-			
X34	Dual Rear Wheel	\$0	<i>\$0</i>		
RH7	Tires LT 215/85 R16	S	S		
RS6	5.5 J x 16 steel wheels	S	S		
RD9	Unspecified tire brand	S	S		
X31	Super Single Tire	\$385	\$385		
R9A	285/65 R 16 C super single tires	0	0		
RS5	Steel wheels: 8.5Jx16 Rr; 6.5Jx16 Fr	0	0		
RD9	Unspecified tire brand	0	0		
RY2	Tire pressure monitoring sensors	0	0		
Identi	fication Lights - choose while ordering				
V59	Identification Lamps Package	\$0	<i>\$</i> 0		
L49	Identification lamps	0	0		
LV7	Clearance lights pre-wiring	0	0		
For pr	e-wiring only (recommended for RV)	\$0	<i>\$</i> 0		
LV7	Clearance lights pre-wiring	0	0		
Equip		·			
AR3	Axle ratio 4.182	S	S		
BA3	Active Brake Assist	S	S		
BH1	Hold Function	S	S		
C6L	Multifunction steering wheel	S	S		
CB8	Stabilization Level II	S	S		
CL1	Adjustable steering wheel (angle)	S	S		
E07	Hill Start Assist	S	S		
	Standard radio	S	S		
E1U	USB-C socket, 5 V	S	S		
E30	Starter battery disconnect	S	S		
E3J	Pre-installation for switch panel	S	S		
E40	Trailer hitch prep. wiring	S	S		
ED8	Preinstallation PSM	S	S		
EE5	Ultracapacitor discharge module	S	S		
EK1	Body Builder Connector	S	S		
ESO	Jump start terminal	S	S		
EW6	Pre-installation for Mercedes me Remote Services	S	S		
EY5	Emergency Call System	S	S		
EY6	Breakdown management	S	S		
F68	Heated & electrically adjustable exterior mirrors  Sholf above windshield	S	S		
FF5 FG8	Shelf above windshield	S S	S		
FG8 FI1	Cupholder front  Remote key (215 mbz) w/central locking	S	S		
FJ4	Remote key (315 mhz) w/central locking Storage compartment underneath cockpit	S	S S		
FS2	Exterior mirror extended (for up to 96" box width)	S S	<u> </u>		
H21	Windshield with filter band	S S	<u> </u>		
HH2	Heater, auxiliary electric hot air	S	<u> </u>		
нн2	Air Condition, Front	S	S		
IH7	Head Unit, North America	S	S		
J11	Speedometer, miles and km/h	S	S		
J55	Seat belt warning for co-driver seat	S	S		
J58	Seat belt reminder driver	S	S		
J65	Outside temperature gauge	S	S		
,,,,			3		

### 3500XD CAB CHASSIS - 6cyl Diesel

		144" 6C	170" 6C
		MXCC46	MXCC76
		907.153	907.155
JA8	Crosswind Assist	S	S
JH3	Communication module (LTE) for dig. services	S	S
JI9	Service interval 20.000 miles	S	S
JW2	Deactivation lamp monitoring failure	S	S
K56	Red diesel filler cap	S	S
K60	Exhaust straight to rear	S	S
KB7	24.5 gallon fuel tank	S	S
KL1	Aux fuel sending unit w/ fuel tap	S	S
KL5	Fuel filter with water separator	S	S
KP6	3rd generation SCR emission control system	S	S
L94	Parking lights deletion	S	S
LA2	Headlight assistant	S	S
MS1	Cruise control	S	S
P47	Front mudflaps	S	S
Q11	Longitudinal member reinforcement	S	S
Q72	Deletion of end cross member	S	S
R60	Provisional spare wheel bracket frame mounted	S	S
R87	Spare tire	S	S
RM0	All-season tires	S	S
S02	Standard driver seat	S	S
S04	Standard front passenger seat	S	S
S22	Armrest for driver's seat	S	S
S25	Armrest for front passenger seat	S	S
SA5	Front airbag, driver	S	S
SA6	Front airbag, passenger	S	S
SH1	Thorax-pelvis sidebag, driver	S	S
SH2	Thorax-pelvis sidebag, co-driver	S	S
SH9	Airbag, driver/passenger window	S	S
SK2	Seat occupancy sensor, driver's seat	S	S
X5G	Witout load uprating/derating 5,000 kg	S	S
Y43	Jack, hydraulic	S	S

144" 6C 170" 6C MXCC46 **MXCC76** 907.155 907.153 A50 Front axle reinforced \$346 \$346 Axle ratio 3.923 \$0 not with AR3 \$0 B01 Vehicle version for high load must have CB4/CB8; not with RF8 BE2 Handbrake lever, folding \$55 \$55 \$141 \$141 C72 Bumpers front/rear primed must have CN2 (part of X67), not with CM2 \$187 \$187 CB4 Stabilization Level III must have X2R; not with CB8 \$409 CE8 Raised rear body mounts Leather steering wheel \$187 \$187 must have (C02/E3M)/C03 + (ET4/MS1) CM2 Bumpers/detachable body parts painted body colour \$432 \$432 must have CN2/X67 + (7755/9147/9197/9775) CM9 Primed side moldings \$364 \$364 must have C72, not with CM2 \$156 \$156 Tray for smartphones incl. wireless charging must have CO2/E3M + H1I \$728 \$728 E1E Navigation must have CO2/E3M, not with CO3 E1S Sirius XM, satellite radio \$255 \$255 must have CO2/E3M/CO3 MBUX multimedia 6-hour runtime \$0 must have X2R + (CO2+E1E/E1S)/CO3/(E3M+E1E/E1S) \$50 E1R Additional Fuses (40/80/150/100 Ampere) \$50 SoP and Plausibility TBD E1Y Additional Fuses (40/80/80/100 Ampere) \$50 \$50 SoP and Plausibility TBD E2A Access point for BB special signals in cockpit \$29 \$29 E2I \$248 \$248 Additional battery, co-driver seat base Must have E36; not with E2M E2M Additional battery, engine compartment \$248 \$248 must have X01+E36; not with E2I/X69 MBUX Multimedia System with 7" touchscreen \$474 \$474 not with C02/C03; must have JK5 E36 \$110 \$110 Cutoff relay for additional battery standard with E2I/E2M 12 V power outlet, driver seat base \$92 \$92 Extension of PSM standard contact \$58 \$58 EA5 Pre-wiring central locking (upfitter doors rear) \$39 \$39 AGM battery 12V 92 AH 850 A \$101 \$101 ED4 \$317 ED5 Parametric special module (PSM) \$317 not with ED8 \$125 \$125 115 V socket Basic electric fitting for rear loudspeakers \$68 ET4 Active Distance Assist DISTRONIC \$263 \$263 must have CO2/CO3/E3M ES5 Charging package, dashboard \$82 \$82 F35 Window in cab rear wall \$134 \$134 must have F61/FV1; not with FW1 \$218 F49 Electrically heated windshield \$218 must have ED4; not with LA3 \$36 \$36 F61 Interior rear view mirror must have CO2/CO3/E3M FE9 Additional DIN-slot \$81 \$81 \$105 FF8 Overhead storage slot, front center \$105 FJ1 Hinged lid for storage compartment \$93 \$93

Options

		144'' 6C	170" 6C
		MXCC46	MXCC76
		907.153	907.155
FR7	Pre-wiring rear view camera (head unit display)	\$65	\$65
FN/	must have CO2/CO3; not with FV1	\$00	\$03
FV1	Pre-wiring rear view camera (mirror display)	\$260	\$260
	not with F61/FR7/LA3	Ψ=00	Ψ=00
FW1	Rear wall deletion, chassis cab	\$0	\$0
	must have P08; not with FY1	· · · · · · · · · · · · · · · · · · ·	
FY1	Security alarm w. interior motion sensor	\$584	\$584
	must have LC4/C00; not with FW1/X2R	•	
FY7	Optional 3-button keys	\$36	\$36
FZ9	Keys, two additional masters	\$121	\$121
H04	Heat insulation, front compartment	\$187	\$187
	must have FW1/V07		
H12	Fuel-fired pre-heater/booster (17K BTU)	\$826	\$826
	must have ED4; not with HZ9		
H15	Heated front passenger seat	\$284	\$284
114.6	must have H16; not with X68	4204	<b>\$204</b>
H16	Heated driver's seat	\$284	\$284
H88	must have H15; not with X68	\$405	\$405
ПОО	Rear heater prep must have ED4+(H12/HZ9)	\$405	\$405
H1I	Front-to-rear outlet in instrument panel	\$0	\$0
1111	must have FJ1/C01	γo	γo
HH4	Thermotronic automatic climate control	\$337	\$337
	must have JF1	7-5-1	7001
HZ9	Fuel-fired heater booster (18,000 BTU)	\$676	\$676
	not with H12	, , , , , , , , , , , , , , , , , , ,	,
J1V	Pre-installation Blind Spot Assist	\$450	\$450
	SoP and Plausibility TBD		
J51	Fuel gauge, optimized for aux. fuel tap	\$72	\$72
	not with HZ9/H12		
J52	Engine oil level display at cold start	\$0	\$0
JB4	Active Lane Keeping Assist	\$288	\$288
	not with CO2/CA2		
JF1	Rain sensor	\$106	\$106
	standard with CO2; not with LA3	A	***
JK5	Instrument cluster with color display	\$144	\$144
114/0	standard with CO3	ćoo	ćoo
JW0	Backup alarm not wit Q72	\$99	\$99
JW8	Attention Assist	\$49	\$49
K51	Misfueling prevention for Diesel	\$49	\$49
K52	DEF fluid filler cap - lockable	\$27	\$27
L13	Fog lamp with cornering light function	\$199	\$199
L72	Pre-installation load compartment lighting	\$174	\$174
L76	Wire harness tail lamp w/ extended wiring	\$133	\$133
L77	Wiring for additional turn signals	\$88	\$88
L90	Tail lamp deletion, non-LED	-\$26	-\$26
	not with L22		
L91	Pre-wiring LED tail lights	\$49	\$49
	not with L22/L90		
LA3	Light sensor for vehicles with alcove	\$0	\$0
	not with F49/F61/FV1/LA2/JF1		
LB9	Illuminated front exits	\$93	\$93
LC4	Comfort overhead control panel	\$93	\$93
LV6	Third brake light pre-wiring	\$32	\$32
M20	Speed limitation 65 mph	\$60	\$60
n a c :	not with MD3	4.5-	A
M24	Starter upgraded	\$189	\$189

Options

		144" 6C	170" 6C
		MXCC46	MXCC76
		907.153	907.155
MD3	Top speed limitation 75 mph	\$60	\$60
	not with M20	4	4
N62	Front engine bracket for additional alternator	\$467	\$467
	not with N63	4467	A 167
N63	Front engine bracket for auxiliary A/C compressor	\$467	\$467
D00	not with N62	40	¢0
P08	Cover for transport	\$0	\$0
040	must have FW1/X69	ACE	Ġ.c.r.
Q18	End cross member bolted	\$65	\$65
QA2	Trailer cross member 7,500 lbs capacity	\$187	\$187
R65	Spare tire bracket below frame	\$0	\$0
D04	must have Q18; not with Q72/R60/R92	¢140	Ć110
R91	Spare tire deletion	-\$110	-\$110
D02	must have R92; not with R87/R60	ćo	ćo
R92	Spare tire carrier deletion	\$0	\$0
D00	must have R91; not with R65/R60	Ć04	Ċ04
R98	Rims painted jet black	\$81	\$81
DE4	not with RM2	ćo	¢0
RF1	Tire brand Continental	\$0	\$0
DE0	not with RD9	ćo	¢0
RF8	Tire brand Michelin	\$0	\$0
D \ 41	not with RD9/RF1/RM1	¢1.00	¢1C0
RM1	M+S winter tires	\$169	\$169
DA 42	must have RD9/RF1; not with RF8/X31	Ć04	Ċ04
RM2	Rims painted arctic white	\$81	\$81
D 1 4 0	not with X31/R98	¢101	¢101
RM9	Specially requested tires	\$101	\$101
S23	must have RF1/RF8; not with RD9	\$400	\$400
323	Twin front passenger seat	\$400	\$400
S28	not with C00/X68/X01	Ć[1	\$51
S62	Armrest, driver and passenger door	\$51	\$32
302	Seat belts orange, driver and front passenger not with S23	\$32	<b>\$</b> 32
SB9		\$238	\$238
289	Driver's seat plus must have FY7	\$238	\$238
C77		\$0	\$0
SZ7	Storage net, driver's seat backrest  must have FW1/X69	ŞU	ŞU
SZ8		\$0	\$0
328	Storage net, passenger seat backrest	ŞU	ŞU
T7E	must have FW1/X69; not with S23	¢E0	¢E0
T75 V07	Door-mounted assist handles, driver & passenger  Cab rear wall liner	\$59 \$360	\$59 \$360
VU7		\$300	\$300
\/OE	not with FW1	ćan	¢20
V85	Cigarette lighter & ash cup, front Additional Ground Weld Studs	\$39	\$39
VV4		\$45	\$45
X2R	SoP and Plausibility TBD Conversion to RV requirement		\$0
XZK	must have B01+E1X	-	\$U
X93		\$0	\$0
	Deletion of model badge, right rear door	\$87	\$0 \$87
XM4	Acoustic package	<b>٦</b> 8/	<b>\$87</b>
V10	standard with CO2/CO3  First aid kit	\$27	\$27
Y10	First-aid kit		·
Y26	Wheel chocks	\$38	\$38
Y45	Emergency flashlight	\$27	\$27
Y68	Paint preservative	\$88	\$88
Y69	Surface protection for stock vehicles	\$292	\$292

#### 3500XD CAB CHASSIS - 6cyl Diesel Packages

144" 6C	170" 6C
MXCC46	MXCC76
907.153	907.155

C00	Comfort Package	\$300	\$300	
LC4	Comfort overhead control panel	Х	X	
SE4	Lumbar support, co-driver's seat	Х	X	
SE5	Lumbar support, driver's seat	Х	X	
SK0	Comfort head restraint, driver	X	X	
SK1	Comfort head restraint, co-driver	X	X	
S28	Armrest, driver and passenger door	X	X	
must	must have COS OR X68; not with S23			

COS	Comfort Package (Seat addition)	\$381	\$381	
SB1	Comfort driver's seat	X	X	
SB2	Comfort passenger seat	Х	Х	
must	must have COO			

X68	Comfort Plus Package	\$1,923	\$1,923
H15	Heated front passenger seat	X	X
H16	Heated driver's seat	Х	X
SF1	Driver's seat electrically adjustable	Х	X
SF2	Co-driver's seat electrically adjustable	Х	Х
must	must have C00 and VF4 OR VF6; not with S23		

C01	Driver Convenience Package	\$323	\$323
E46	12 V power outlet, driver seat base	X	X
FJ1	Hinged lid for storage compartment	X	X
FZ9	Keys, two additional masters	X	X
JW8	Attention Assist	X	X

C02	Premium Package	\$983	\$983
CL3	Leather steering wheel	X	X
E3M	MBUX Multimedia System with 7" touchscreen	Х	X
FM3	Wet Wiper System	X	X
JB4	Active Lane Keeping Assist	X	X
JK5	Instrument cluster with color display	X	X

Ordering availability restricted, see NetStar for availability and restrctions | must have (JF1/LA3) + XM4

CA2	C02 in combination with C03	\$604	\$604	
CL3	Leather steering wheel	X	X	
FM3	Wet Wiper System	X	X	
JB4	Active Lane Keeping Assist	X	X	
JK5	Instrument cluster with color display	Х	X	
Orde	Ordering availability restricted, see NetStar for availability and restrctions must have CO3 + JF1			

#### 3500XD CAB CHASSIS - 6cyl Diesel Packages

144" 6C	170" 6C
MXCC46	MXCC76
907.153	907.155

C03	Premium Plus Package	\$1,793	\$1,793
E1B	Tray for smartphones incl. wireless charging	Х	X
	Navigation	X	X
EY2	Intelligent navigation	Х	X
E4M	MBUX Multimedia System with 10.25" touchscreen	X	X
EX9	Free map data updates for 3 years	Х	X
H1I	Front-to-rear outlet in instrument panel	X	X
JA9	Traffic Sign Assist	Х	X
XM4	Acoustic package	Х	X
must	have CA2 OR (JB4+JK5+FM3)	<u> </u>	

X67	Chrome Grille Package	\$290	\$290	
CN2	Radiator grille frame in vehicle color	X	X	
FK3	Chrome plated radiator grille (MB only)	X	Х	
no re	no restrictions			

X13	Exterior Lighting Package	\$1,608	\$1,608
L13	Fog lamp with cornering light function	X	X
L22	Partial LED tail lights	Х	X
LA1	High beam assist	X	X
LG7	LED high performance headlamps	X	X
no re	strictions		

X69	Swivel Seat Package	\$587	\$587
SR8	Swivel base for driver's seat	X	X
SR9	Swivel base for front passenger seat	X	X
S87	Driver's seat frame, low	Х	X
S88	Passenger seat frame, low	Х	X
FW1	Rear wall deletion, chassis cab	X	X
BE2	Handbrake lever, folding	X	X
must	have (C00+C0S) OR (C00+X68)		

X01	Suspension Seating Package	\$940	\$940
SB3	Driver suspension seat, comfort version	X	X
SB4	Passenger suspension seat, comfort version	Х	Χ
S87	Driver's seat frame, low	Х	Х
S88	Passenger seat frame, low	X	Х
not v	vith COO/COS/X68/S23		

Standard Equipment

144" 4C

M4CC44

170" 4C

M4CC74

		M4CC44	M4CC74
		907.153	907.155
Engin	0		
<u> </u>	e Engine/7-Speed Trans.	c	
		S	S
	AGM battery 12V 70AH Automatic transmission, 7G-tronic	S S	S S
	Alternator 14 V / 200 A	S	S
	2.0L 4-cylinder diesel engine	S	S
	SULEV emissions	S	S
	fication Lights - choose while ordering	ćo	ćo
V59	Identification Lamps Package	\$0	\$0
	Identification lamps	0	0
	Clearance lights pre-wiring	0	0
	re-wiring only (recommended for RV)	\$0	\$0
LV7	Clearance lights pre-wiring	0	0
Equip		1 0	
	Front axle reinforced	S	S
	Axle ratio 4.182	S	S
BA3	Active Brake Assist	S	S
BH1	Hold Function	S	S
	Stabilization Level II	S	S
C6L	Multifunction steering wheel	S	S
CL1	Adjustable steering wheel (angle)	S	S
E07	Hill Start Assist	S	S
E10	Standard radio	S	S
E1U	USB-C socket, 5 V	S	S
E30	Starter battery disconnect	S	S
E3J	Pre-installation for switch panel	S	S
E40	Trailer hitch prep. wiring	S	S
ED8	Preinstallation PSM	S	S
EE5	Ultracapacitor discharge module	S	S
EK1	Body Builder Connector	S	S
ES0	Jump start terminal	S	S
EW6	Pre-installation for Mercedes me Remote Services	S	S
EY5	Emergency Call System	S	S
EY6	Breakdown management	S	S
F68	Heated & electrically adjustable exterior mirrors	S	S
FF5	Shelf above windshield	S	S
FG8	Cupholder front	S	S
FI1	Remote key (315 mhz) w/central locking	S	S
FJ4	Storage compartment underneath cockpit	S	S
FS2	Exterior mirror extended (for up to 96" box width)	S	S
H21	Windshield with filter band	S	S
HH2	Heater, auxiliary electric hot air	S	S
HH9	Air Condition, Front	S	S
IH7	Head Unit, North America	S	S
J11	Speedometer, miles and km/h	S	S
J55	Seat belt warning for co-driver seat	S	S
J58	Seat belt reminder driver	S	S
J65	Outside temperature gauge	S	S
JA8	Crosswind Assist	S	S
JH3	Communication module (LTE) for dig. services	S	S
JI9	Service interval 20.000 miles	S	S
JW2	Deactivation lamp monitoring failure	S	S
K56	Red diesel filler cap	S	S
K60	Exhaust straight to rear	S	S
КВ7	24.5 gallon fuel tank	S	S
KL1	Aux fuel sending unit w/ fuel tap	S	S
	, , , , , , , , , , , , , , , , , , ,		

## 4500 CAB CHASSIS - 4cyl Diesel

Standard Equipment

		144" 4C	170" 4C
		M4CC44	M4CC74
		907.153	907.155
KL5	Fuel filter with water separator	S	S
KP6	3rd generation SCR emission control system	S	S
L94	Parking lights deletion	S	S
LA2	Headlight assistant	S	S
MS1	Cruise control	S	S
P47	Front mudflaps	S	S
Q11	Longitudinal member reinforcement	S	S
Q72	Deletion of end cross member	S	S
R60	Provisional spare wheel bracket frame mounted	S	S
R87	Spare tire	S	S
RD9	Unspecified tire brand	S	S
RH7	Tires LT 215/85 R16	S	S
RM0	All-season tires	S	S
RS6	5.5 J x 16 steel wheels	S	S
S02	Standard driver seat	S	S
S04	Standard front passenger seat	S	S
S22	Armrest for driver's seat	S	S
S25	Armrest for front passenger seat	S	S
SA5	Front airbag, driver	S	S
SA6	Front airbag, passenger	S	S
SH1	Thorax-pelvis sidebag, driver	S	S
SH2	Thorax-pelvis sidebag, co-driver	S	S
SH9	Airbag, driver/passenger window	S	S
SK2	Seat occupancy sensor, driver's seat	S	S
XL4	GVWR 12,125 lbs. / 5.500 Kg	S	S
Y43	Jack, hydraulic	S	S

Options

		144" 4C	170" 4C
		M4CC44	M4CC74
		907.153	907.155
AR2	Axle ratio 3.923	\$0	\$0
	not with AR3		
301	ESP for increased Center of Gravity above 39.4"	-	\$0
	must have CB4/CB8; not with RF8		
3E2	Handbrake lever, folding	\$55	\$55
C72	Bumpers front/rear primed	\$141	\$141
	must have CN2 (part of X67), not with CM2		·
CE8	Raised rear body mounts	_	\$409
CL3	Leather steering wheel	\$187	\$187
	must have (C02/E3M)/C03 + (ET4/MS1)	, -	, -
CM2	Bumpers/detachable body parts painted body colour	\$432	\$432
	must have CN2/X67 + (7755/9147/9197/9775)	7 .0=	¥ 10 =
CM9	Primed side moldings	\$364	\$364
	must have C72, not with CM2	700.	φου.
E1B	Tray for smartphones incl. wireless charging	\$156	\$156
	must have CO2/E3M + H1I	7130	Ų130
E1E	Navigation	\$728	\$728
-46	must have CO2/E3M, not with CO3	٦/ ٢٥	7120
E1S		\$255	\$255
L13	Sirius XM, satellite radio	\$255	<i>\$</i> 255
T1V	must have CO2/E3M/CO3		ćo
E1X	MBUX multimedia 6-hour runtime	-	\$0
	must have X2R + (C02+E1E/E1S)/C03/(E3M+E1E/E1S)	450	ģ.
E1R	Additional Fuses (40/80/150/100 Ampere)	\$50	\$50
	SoP and Plausibility TBD	4	4=-
E1Y	Additional Fuses (40/80/80/100 Ampere)	\$50	\$50
	SoP and Plausibility TBD		
E2A	Access point for BB special signals in cockpit	\$29	\$29
E2I	Additional battery, co-driver seat base	\$248	\$248
E2A	Access point for BB special signals in cockpit	\$29	\$29
E2I	Additional battery, co-driver seat base	\$248	\$248
	Must have E36; not with E2M		
E2M	Additional battery, engine compartment	\$248	\$248
	must have X01+E36; not with E2I/X69		
E3M	MBUX Multimedia System with 7" touchscreen	\$474	\$474
	not with CO2/CO3; must have JK5	•	
E36	Cutoff relay for additional battery	\$110	\$110
	standard with E2I/E2M		
E46	12 V power outlet, driver seat base	\$92	\$92
E5M	Extension of PSM standard contact	\$58	\$58
EA5	Pre-wiring central locking (upfitter doors rear)	\$39	\$39
ED4	AGM battery 12V 92 AH 850 A	\$101	\$101
	not with ED1		·
ED5	Parametric special module (PSM)	\$317	\$317
	not with ED8		·
EE3	115 V socket	\$125	\$125
EP7	Basic electric fitting for rear loudspeakers	\$68	\$68
ES5	Charging package, dashboard	\$82	\$82
ET4	Active Distance Assist DISTRONIC	\$263	\$263
• •	must have CO2/CO3/E3M	7-00	7-30
-35	Window in cab rear wall	\$134	\$134
<u> </u>	must have F61/FV1; not with FW1	7107	7104
49	Electrically heated windshield	\$218	\$218
7.7	must have ED4; not with LA3	Υ٢٢٥	<b>Υ</b> Ζ10
-G1		¢26	¢26
-61	Interior rear view mirror	\$36	\$36
	must have CO2/CO3/E3M	404	404
FE9	Additional DIN-slot	\$81	\$81
FF8	Overhead storage slot, front center	\$105	\$105
FJ1	Hinged lid for storage compartment	\$93	\$93

Options

		144" 4C	170" 4C
		M4CC44	M4CC74
		907.153	907.155
FR7	Pre-wiring rear view camera (head unit display)	\$65	\$65
	must have CO2/CO3; not with FV1	7.00	7.55
FV1	Pre-wiring rear view camera (mirror display)	\$260	\$260
	not with F61/FR7/LA3	,	,
FW1	Rear wall deletion, chassis cab	\$0	\$0
	must have P08; not with FY1	ΨV	7.0
FY1	Security alarm w. interior motion sensor	\$584	\$584
	must have LC4/C00; not with FW1/X2R	700.	755
FY7	Optional 3-button keys	\$36	\$36
FZ9	Keys, two additional masters	\$121	\$121
H04	Heat insulation, front compartment	\$187	\$187
110-	must have FW1/V07	7107	7107
H12	Fuel-fired pre-heater/booster (17K BTU)	\$826	\$826
1112	must have ED4; not with HZ9	Ş620	<del>3</del> 820
U15		\$284	\$284
H15	Heated front passenger seat	Ş <b>2</b> 04	<i>Ş</i> ∠04
U16	must have H16; not with X68	6204	¢204
H16	Heated driver's seat	\$284	\$284
1100	must have H15; not with X68	6405	6405
H88	Rear heater prep	\$405	\$405
	must have ED4+(H12/HZ9)	40	40
H1I	Front-to-rear outlet in instrument panel	\$0	\$0
	must have FJ1/C01	4	4
HH4	Thermotronic automatic climate control	\$337	\$337
	must have JF1		
HZ9	Fuel-fired heater booster (18,000 BTU)	\$676	\$676
	not with H12		
J1V	Pre-installation Blind Spot Assist	\$450	\$450
	SoP and Plausibility TBD		
J51	Fuel gauge, optimized for aux. fuel tap	\$72	\$72
	not with HZ9/H12		
J52	Engine oil level display at cold start	\$0	\$0
JB4	Active Lane Keeping Assist	\$288	\$288
	not with CO2/CA2		
JF1	Rain sensor	\$106	\$106
	standard with CO2; not with LA3		
JK5	Instrument cluster with color display	\$144	\$144
	standard with CO3	,	
JW0	Backup alarm	\$99	\$99
	not wit Q72		
JW8	Attention Assist	\$49	\$49
K51	Misfueling prevention for Diesel	\$49	\$49
K52	DEF fluid filler cap - lockable	\$27	\$27
L13	Fog lamp with cornering light function	\$199	\$199
L72	Pre-installation load compartment lighting	\$174	\$174
L76	Wire harness tail lamp w/ extended wiring	\$133	\$133
_70 _77	Wiring for additional turn signals	\$88	\$88
 90	Tail lamp deletion, non-LED	-\$26	-\$26
	not with L22	720	720
91	Pre-wiring LED tail lights	\$49	\$49
<u>.</u>	not with L22/L90	<b>₹</b> +7	Ş <del>+</del> J
ΔΟ	Light sensor for vehicles with alcove	ć٥	\$0
LA3	_	\$0	ŞU
D.C.	not with F49/F61/FV1/LA2/JF1	400	400
_B9	Illuminated front exits	\$93	\$93
LC4	Comfort overhead control panel	\$93	\$93
_V6	Third brake light pre-wiring	\$32	\$32
M20	Speed limitation 65 mph	\$60	\$60

		144" 4C 170" 4C	
			M4CC74
		M4CC44 907.153	907.155
_	Starter upgraded	\$189	\$189
MD3	Top speed limitation 75 mph	\$60	\$60
	not with M20	4.00	4.00
N62	Front engine bracket for additional alternator	\$467	\$467
	not with N63	A 4 6 7	<b>A</b> 4.67
N63	Front engine bracket for auxiliary A/C compressor	\$467	\$467
P08	not with N62	\$0	\$0
PU8	Cover for transport  must have FW1/X69	ŞU	\$U
Q18	End cross member bolted	\$65	\$65
QA2	Trailer cross member 7,500 lbs capacity	\$187	\$187
R65	Spare tire bracket below frame	\$0	\$0
1105	must have Q18; not with Q72/R60/R92	70	Ç
R91	Spare tire deletion	-\$110	-\$110
1131	must have R92; not with R87/R60	Ų110	<b>Ÿ</b> 110
R92	Spare tire carrier deletion	\$0	\$0
	must have R91; not with R65/R60	4.0	40
R98	Rims painted jet black	\$81	\$81
	not with RM2	, , ,	, -
RF1	Tire brand Continental	\$0	\$0
	not with RD9		·
RF8	Tire brand Michelin	\$0	\$0
	not with RD9/RF1/RM1	•	
RM1	M+S winter tires	\$169	\$169
	must have RD9/RF1; not with RF8/X31		
RM2	Rims painted arctic white	\$81	\$81
	not with X31/R98		
RM9	Specially requested tires	\$101	\$101
	must have RF1/RF8; not with RD9		
S23	Twin front passenger seat	\$400	\$400
	not with C00/X68/X01	,	
S28	Armrest, driver and passenger door	\$51	\$51
S62	Seat belts orange, driver and front passenger	\$32	\$32
	not with S23		
SB9	Driver's seat plus	\$238	\$238
	must have FY7		
SZ7	Storage net, driver's seat backrest	\$0	\$0
	must have FW1/X69		
SZ8	Storage net, passenger seat backrest	\$0	\$0
	must have FW1/X69; not with S23		
T75	Door-mounted assist handles, driver & passenger	\$59	\$59
V07	Cab rear wall liner	\$360	\$360
	not with FW1		
V85	Cigarette lighter & ash cup, front	\$39	\$39
VV4	Additional Ground Weld Studs	\$45	\$45
	SoP and Plausibility TBD	•	
X93	Deletion of model badge, right rear door	\$0	\$0
X2R	Conversion to RV requirement	-	\$0
	must have B01+E1X		
XM4	Acoustic package	\$87	\$87
	standard with CO2/CO3	, ,	7-
Y10	First-aid kit	\$27	\$27
Y26	Wheel chocks	\$38	\$38
Y45	Emergency flashlight	\$27	\$27
Y68	Paint preservative	\$88	\$88
Y69	Surface protection for stock vehicles	\$292	\$292
100	Januar protection for Stock Venicies	7636	JLJL

# **4500 CAB CHASSIS - 4cyl Diesel** Packages

170" 4C
M4CC74
907.155

C00	Comfort Package	\$300	\$300	
LC4	Comfort overhead control panel	Х	Х	
SE4	Lumbar support, co-driver's seat	Х	Х	
SE5	Lumbar support, driver's seat	Х	X	
SK0	Comfort head restraint, driver	Х	Х	
SK1	Comfort head restraint, co-driver	Х	X	
S28	Armrest, driver and passenger door	Х	Х	
must	must have COS OR X68; not with S23			

COS	Comfort Package (Seat addition)	\$381	\$381
SB1	Comfort driver's seat	Х	X
SB2	Comfort passenger seat	Х	Х
must	have COO	_	

X68	Comfort Plus Package	\$1,923	\$1,923
H15	Heated front passenger seat	X	X
H16	Heated driver's seat	X	X
SF1	Driver's seat electrically adjustable	Х	X
SF2	Co-driver's seat electrically adjustable	Х	X
must	have COO and VF4 OR VF6; not with S23		

C01	Driver Convenience Package	\$323	\$323
E46	12 V power outlet, driver seat base	X	Х
FJ1	Hinged lid for storage compartment	X	Х
FZ9	Keys, two additional masters	X	Х
JW8	Attention Assist	Х	X

C02	Premium Package	\$983	\$983
CL3	Leather steering wheel	Х	X
E3M	MBUX Multimedia System with 7" touchscreen	X	X
FM3	Wet Wiper System	Х	X
JB4	Active Lane Keeping Assist	X	X
JK5	Instrument cluster with color display	X	X

Ordering availability restricted, see NetStar for availability and restrctions|must have (JF1/LA3) + XM4

CA2	C02 in combination with C03	\$604	\$604	
CL3	Leather steering wheel	Χ	X	
FM3	Wet Wiper System	Х	X	
JB4	Active Lane Keeping Assist	Χ	X	
JK5	Instrument cluster with color display	Х	Χ	
Orde	Ordering availability restricted, see NetStar for availability and restrctions must have CO3 + JF1			

# **4500 CAB CHASSIS - 4cyl Diesel** Packages

144" 4C	170" 4C
M4CC44	M4CC74
907.153	907.155

C03	Premium Plus Package	\$1,793	\$1,793
E1B	Tray for smartphones incl. wireless charging	X	X
	Navigation	X	X
EY2	Intelligent navigation	X	X
E4M	MBUX Multimedia System with 10.25" touchscreen	X	X
EX9	Free map data updates for 3 years	X	X
H1I	Front-to-rear outlet in instrument panel	X	X
JA9	Traffic Sign Assist	X	X
XM4	Acoustic package	X	X
must	have CA2 OR (JB4+JK5+FM3)		

X67	Chrome Grille Package	\$290	\$290	
CN2	Radiator grille frame in vehicle color	X	X	
FK3	Chrome plated radiator grille (MB only)	X	X	
no re	no restrictions			

X13	Exterior Lighting Package	\$1,608	\$1,608
L13	Fog lamp with cornering light function	Х	X
L22	Partial LED tail lights	X	Х
LA1	High beam assist	X	Х
LG7	LED high performance headlamps	X	Χ
no restrictions			

X69	Swivel Seat Package	\$587	\$587	
SR8	Swivel base for driver's seat	Х	Х	
SR9	Swivel base for front passenger seat	Х	Х	
S87	Driver's seat frame, low	Х	Х	
S88	Passenger seat frame, low	Х	Х	
FW1	Rear wall deletion, chassis cab	X	Х	
BE2	Handbrake lever, folding	X	X	
must	must have (C00+C0S) OR (C00+X68)			

X01	Suspension Seating Package	\$940	\$940
SB3	Driver suspension seat, comfort version	X	X
SB4	Passenger suspension seat, comfort version	X	X
S87	Driver's seat frame, low	X	X
S88	Passenger seat frame, low	Х	X
not with COO/COS/X68/S23			

Standard Equipment

144" 6C M4CC46 170" 6C

M4CC76

Section   Sect			MI4CC46	M4CC76		
Section   Sect			907.153	907.155		
Section   Sect	Fnain	ρ				
SAME						
Automatic transmission, 7G-tronic   S   S						
MAGE   Alternator 14 V/220 A   S   S   S   S   S   S   S   S   S		·				
MGS   3.0L V6 turbo diesel engine		·				
MH8   SULEV emissions						
				S		
V59         Identification Lamps Package         \$0         \$0           L49         Identification lamps         0         0           L70         Clearance lights pre-wiring         0         0           For pre-wiring only (recommended for RV)         \$0         \$50           L70         Clearance lights pre-wiring         0         0           Decaptament         Tornt axid reinforced         \$         \$           A50         Front axid reinforced         \$         \$           A83         Active Brake Assist         \$         \$           BA3         Active Brake Assist         \$         \$           BH1         Hold Function         \$         \$           CB         Stabilization Level II         \$         \$           CL1         Adjustable steering wheel (angle)         \$         \$           CB         Statility Assist         \$         \$           E10         Usb-C socket, 5 V         \$         \$           E11         Usb-C socket, 5 V         \$         \$           E10         Usb-C socket, 5 V         \$         \$           E11         Usb-C socket, 5 V         \$         \$           E12         Verian						
Identification lamps		-	\$0	\$0		
For pre-wiring only (recommended for RV)	L49		0	0		
IV7   Clearance lights pre-wiring   O	LV7	Clearance lights pre-wiring	0	0		
Figure   Front   Sale   Front   Sale   Sal	For pr	e-wiring only (recommended for RV)	\$0	\$0		
ASO         Front akle reinforced         \$	LV7	Clearance lights pre-wiring	0	0		
AR3         Axte ratio 4.182         S         S           BA3         Active Brake Assist         S         S           BH1         Hold Function         S         S           C6L         Multifunction steering wheel         S         S           C8B         Stabilization Level II         S         S           C11         Adjustable steering wheel (angle)         S         S           C11         USB-C socket, 5 V         S         S           S20         Standard radio         S         S           S20         Standard radio         S         S           E30         Stantable steering wheel (angle)         S         S           E31         Trailer hitch prep. wirds         S <t< td=""><td>Equip</td><td>ment</td><td></td><td></td></t<>	Equip	ment				
BA3         Active Brake Assist         \$         \$           BH1         Hold Function         \$         \$           GL         Multifunction steering wheel         \$         \$           CB         Stabilization Level II         \$         \$           CL1         Adjustable steering wheel (angle)         \$         \$           E07         Hill Start Assist         \$         \$           E07         Hill Start Assist         \$         \$         \$           E10         Stacker battery disconnect         \$         \$         \$           E10         USB-C socket, 5 V         \$         \$         \$           E30         Starter battery disconnect         \$         \$         \$           E31         Pre-installation or switch panel         \$         \$         \$         \$           E40         Trailer hitch prep. wiring         \$	A50	Front axle reinforced	S	S		
BH1   Hold Function   S   S   S   S   C6L   Multifunction steering wheel   S   S   S   S   S   S   S   S   S	AR3	Axle ratio 4.182	S	S		
C6L         Multifunction steering wheel         S         S           C8B         Stabilization Level II         S         S           C1L         Adjustable steering wheel (angle)         S         S           E07         Hill Start Assist         S         S           E10         Standard radio         S         S           E31         Starter battery disconnect         S         S           E30         Starter battery disconnect         S         S           E31         Pre-installation for switch panel         S         S           E40         Trailer hitch prep. wiring         S         S           E40         Trailer hitch prep. wiring         S         S           E51         Pre-installation PSM         S         S           E52         Pre-installation PSM         S         S           EK1         Body Builder Connector         S         S         S           EK5         Ump start terminal         S         S         S           EK6         Body Builder Connector         S         S         S           EW6         Pre-installation for Mercedes me Remote Services         S         S           EV6         Bre-eins	BA3	Active Brake Assist	S	S		
CB8         Stabilization Level II         S         S           CL1         Adjustable steering wheel (angle)         S         S           D7         Hill Start Assist         S         S           E30         Stantard radio         S         S           E31         USB-C socket, S V         S         S           E30         Starter battery disconnect         S         S           E31         Pre-installation for switch panel         S         S           E40         Traller hitch prep. wiring         S         S           E84         Traller hitch prep. wiring         S         S           E85         Pre-installation PSM         S         S           E85         Ultracapacitor discharge module         S         S           E81         Body Builder Connector         S         S           E82         Litracapacitor discharge module         S         S           E84         Break Davis dischard module for module for module for module for module for module	BH1	Hold Function	S	S		
CL1         Adjustable steering wheel (angle)         S         S           EO7         Hill Start Assist         S         S           E10         Standard radio         S         S           E10         USB-C socket, S V         S         S           E30         Starter battery disconnect         S         S           E31         Pre-installation for switch panel         S         S           E32         Pre-installation for switch panel         S         S           E40         Trailer hitch prep. wiring         S         S           E87         EPreinstallation for SM         S         S           E87         Ultracapacitor discharge module         S         S           E87         Ultracapacitor discharge module         S         S           E81         Body Builder Connector         S         S           E81         Body Builder Connector         S         S           E91         Jump start terminal         S         S           E81         Body Builder Connector         S         S           E81         Body Builder Connector         S         S           E81         Body Builder Connector         S         S		Multifunction steering wheel	S	S		
E07         Hill Start Assist         S         S           E10         Standard radio         S         S           E11         USB-C socket, 5 V         S         S           E30         Starter battery disconnect         S         S           E31         Pre-installation for switch panel         S         S           E40         Trailer hitch prep. wiring         S         S           E50         Pre-installation PSM         S         S           E50         Breinstallation PSM         S         S           EK1         Body Builder Connector         S         S           EK2         Breakdown management         S         S           EV6         Breakdown management         S         S           EV6         Breakdown management         S         S           EV6         Breakd			S	S		
E10         Standard radio         S         S           E11         USB-C socket, 5 V         S         S           E30         Starter battery disconnect         S         S           E31         Pre-installation for switch panel         S         S           E40         Trailer hitch prep. wiring         S         S           E63         Preinstallation PSM         S         S           E64         Ultracapacitor discharge module         S         S           E65         Ultracapacitor discharge module         S         S           EK1         Body Builder Connector         S         S           E50         Jump start terminal         S         S           EW6         Pre-installation for Mercedes me Remote Services         S         S           EW6         Pre-installation for Mercedes me Remote Services         S         S           EW6         Pre-installation for Mercedes me Remote Services         S         S           EW6         Pre-installation for Mercedes me Remote Services         S         S           EW6         Pre-installation for Mercedes me Remote Services         S         S           EW7         Emergency Call System         S         S		Adjustable steering wheel (angle)	S	S		
E1U USB-C socket, 5 V E30 Starter battery disconnect E31 Pre-installation for switch panel E40 Trailer hitch prep. wiring E50 Preinstallation PSM E50 Pre-installation PSM E51 Ultracapacitor discharge module E51 Ultracapacitor discharge module E52 Ultracapacitor discharge module E53 S E54 Ultracapacitor discharge module E54 Ultracapacitor discharge module E55 S E56 Ultracapacitor discharge module E57 S E58 S E59 Ultracapacitor discharge module E59 S E50 Ultracapacitor discharge module E50 Ultracapacitor discharge module E50 S E50 Ultracapacitor discharge module E50 S E50 Ultracapacitor discharge module E50 S E50 S E50 Ultracapacitor discharge module E50 S E50 S E50 S E61 S E62 S E63 S E65 S E65 S E66 Breakdown management E67 S E68 Capholder front E67 S E68 Capholder front E67 S E68 Capholder front E68 S E68 S E69 S E6	E07	Hill Start Assist	S	S		
E30 Starter battery disconnect E31 Pre-installation for switch panel E32 Pre-installation for switch panel E35 S E40 Trailer hitch prep. wiring S E58 Preinstallation PSM S S S E68 Ultracapacitor discharge module S E59 Ultracapacitor discharge module S E50 Ultracapacitor discharge module S S S S EK1 Body Builder Connector S S S S EK2 Body Builder Connector S S S S S EW6 Pre-installation for Mercedes me Remote Services S S S S EV6 Breakdown management S S S S S EV76 Breakdown management S S S S S S S S S S S S S S S S S S S	E10		S	S		
E3J Pre-installation for switch panel S S S S S S S S S S S S S S S S S S S				S		
E40 Trailer hitch prep. wiring						
ED8 Preinstallation PSM S S S S S S S S S S S S S S S S S S						
EES Ultracapacitor discharge module  S S S  EK1 Body Builder Connector  S S S  EW6 Pre-installation for Mercedes me Remote Services  S S S  EW6 Pre-installation for Mercedes me Remote Services  S S S  EW7 Emergency Call System  S S S S  EW7 Breakdown management  S S S S  FF8 Heated & electrically adjustable exterior mirrors  S S S S  FF9 Shelf above windshield  S S S S  FF9 Shelf above windshield  S S S S  FF1 Remote key (315 mhz) w/central locking  S S S S  FF1 Storage compartment underneath cockpit  S S S S  FF2 Exterior mirror extended (for up to 96" box width)  S S S S  H21 Windshield with filter band  S S S S  HH2 Heater, auxiliary electric hot air  S S S S  HH7 Head Unit, North America  S S S S  S S  S S  S S  S S  S S  S						
EK1 Body Builder Connector  S S S  ESO Jump start terminal  S S S  EW6 Pre-installation for Mercedes me Remote Services  EY5 Emergency Call System  S S S  EY6 Breakdown management  S S S S  EY76 Breakdown management  S S S S S  EF76 Shelf above windshield  S S S S S  FF8 Cupholder front  S S S S S  FF9 Shelf above windshield  S S S S S S  FF1 Remote key (315 mhz) w/central locking  S S S S S S  FF2 Exterior mirror extended (for up to 96" box width)  S S S S S  HH2 Heater, auxiliary electric hot air  S S S S S S  HH9 Air Condition, Front  S S S S S S  HH9 Air Condition, Front  S S S S S S  HH9 Air Condition, Front  S S S S S S S  HH9 Air Condition, Front  S S S S S S S S S S  HH9 Air Condition for co-driver seat  S S S S S S S S S S S S S S S S S S S						
ESO Jump start terminal S S S S S S S S S S S S S S S S S S S						
EW6       Pre-installation for Mercedes me Remote Services       S       S         EY5       Emergency Call System       S       S         EY6       Breakdown management       S       S         F68       Heated & electrically adjustable exterior mirrors       S       S         FF5       Shelf above windshield       S       S         FG8       Cupholder front       S       S         F10       Remote key (315 mhz) w/central locking       S       S         F11       Remote key (315 mhz) w/central locking       S       S         F11       Remote key (315 mhz) w/central locking       S       S         F11       Storage compartment underneath cockpit       S       S         F21       Storage compartment underneath cockpit       S       S         F2       Exterior mirror extended (for up to 96" box width)       S       S         F2       Exterior mirror extended (for up to 96" box width)       S       S         F2       Exterior mirror extended (for up to 96" box width)       S       S         F42       Windshield with filter band       S       S         HH2       Heater, auxiliary electric hot air       S       S         HH3       Air Condition,						
EY5 Emergency Call System  EY6 Breakdown management  S S S  S S  F68 Heated & electrically adjustable exterior mirrors  S S S S  FF5 Shelf above windshield  S S S S  FF68 Cupholder front  S S S S  FF1 Remote key (315 mhz) w/central locking  S S S S  FF1 Storage compartment underneath cockpit  S S S S  FF2 Exterior mirror extended (for up to 96" box width)  S S S S  FF2 Exterior mirror extended (for up to 96" box width)  S S S S  HH2 Heater, auxiliary electric hot air  S S S S  HH7 Head Unit, North America  S S S S  HT7 Head Unit, North America  S S S S  JS S S  JS S S S  JS S S S  JS S S  JS S S S  JS S S S  JS S S S  JS S S S				_		
EY6 Breakdown management S S S F68 Heated & electrically adjustable exterior mirrors S S S FF5 Shelf above windshield S S S FG8 Cupholder front S S S FI1 Remote key (315 mhz) w/central locking S S S FI2 Exterior mirror extended (for up to 96" box width) S S S FS2 Exterior mirror extended (for up to 96" box width) S S S H12 Windshield with filter band S S S H14 Heater, auxiliary electric hot air S S S H17 Head Unit, North America S S S H17 Speedometer, miles and km/h S S FS5 Seat belt warning for co-driver seat S S FS6 Seat belt reminder driver S S FS S						
F68       Heated & electrically adjustable exterior mirrors       S       S         FF5       Shelf above windshield       S       S         FG8       Cupholder front       S       S         FI1       Remote key (315 mhz) w/central locking       S       S         FJ4       Storage compartment underneath cockpit       S       S         FS2       Exterior mirror extended (for up to 96" box width)       S       S         H21       Windshield with filter band       S       S         HH2       Heater, auxiliary electric hot air       S       S         HH3       Air Condition, Front       S       S         HH4       Head Unit, North America       S       S         JH7       Head Unit, North America       S       S         J55       Seat belt warning for co-driver seat       S       S         J55       Seat belt warning for co-driver seat       S       S         J58       Seat belt reminder driver       S       S         J55       Seat belt reminder driver       S       S         J65       Outside temperature gauge       S       S         J65       Outside temperature gauge       S       S         J78 <td></td> <td></td> <td></td> <td></td>						
FF5 Shelf above windshield S S S FG8 Cupholder front S S S FI1 Remote key (315 mhz) w/central locking S S FJ4 Storage compartment underneath cockpit S S FS2 Exterior mirror extended (for up to 96" box width) S S H21 Windshield with filter band S S HH2 Heater, auxiliary electric hot air S S HH9 Air Condition, Front S S S HH7 Head Unit, North America S S S JJ1 Speedometer, miles and km/h S S JS5 Seat belt warning for co-driver seat S S JS8 Seat belt reminder driver S S S JS8 Seat belt reminder driver S S S JA8 Crosswind Assist S S JH3 Communication module (LTE) for dig. services S S JM9 Service interval 20.000 miles S S KS6 Red diesel filler cap S S KS7 S KS8 S KS8 S KS8 S KS9						
FG8 Cupholder front  Remote key (315 mhz) w/central locking  FJ4 Storage compartment underneath cockpit  S S  FS2 Exterior mirror extended (for up to 96" box width)  S S  H21 Windshield with filter band  S S  HH2 Heater, auxiliary electric hot air  S S  HH9 Air Condition, Front  S S  SI  H7 Head Unit, North America  S S  J11 Speedometer, miles and km/h  S S  SS  J58 Seat belt warning for co-driver seat  S S  J58 Seat belt reminder driver  S S  J65 Outside temperature gauge  S S  JA8 Crosswind Assist  S S  JH3 Communication module (LTE) for dig. services  S S  JW2 Deactivation lamp monitoring failure  K56 Red diesel filler cap  S S  KB7 24.5 gallon fuel tank  KL1 Aux fuel sending unit w/ fuel tap						
FI1 Remote key (315 mhz) w/central locking  FJ4 Storage compartment underneath cockpit  FS2 Exterior mirror extended (for up to 96" box width)  KS SS  H21 Windshield with filter band  KH21 Heater, auxiliary electric hot air  KH3 Air Condition, Front  KS SS  KH42 Head Unit, North America  KH43 Speedometer, miles and km/h  KS SS  K						
FJ4 Storage compartment underneath cockpit S S S FS2 Exterior mirror extended (for up to 96" box width) S S S H21 Windshield with filter band S S S HH2 Heater, auxiliary electric hot air S S S HH9 Air Condition, Front S S S S HH7 Head Unit, North America S S S S H11 Speedometer, miles and km/h S S S S S J11 Speedometer, miles and km/h S S S S S S S S S S S S S S S S S S S		•				
FS2 Exterior mirror extended (for up to 96" box width)  H21 Windshield with filter band  S S S S S S S S S S S S S S S S S S S						
H21 Windshield with filter band S S S S S S S S S S S S S S S S S S S						
HH2 Heater, auxiliary electric hot air  HH9 Air Condition, Front  S S S  IH7 Head Unit, North America  S S S  IH7 Speedometer, miles and km/h  S S S  IJ11 Speedometer, miles and km/h  S S S  IJ55 Seat belt warning for co-driver seat  S S S  IJ58 Seat belt reminder driver  S S S  IJ58 Seat belt reminder driver  S S S  IJ59 Outside temperature gauge  S S S  IJ65 Outside temperature gauge  S S S  IJ65 Communication module (LTE) for dig. services  S S S  IJ78 Service interval 20.000 miles  S S S  IJ79 Service interval 20.000 miles  S S S  IJ70 Deactivation lamp monitoring failure  S S S  K56 Red diesel filler cap  S S S  K60 Exhaust straight to rear  K60 Exhaust straight to rear  K61 Aux fuel sending unit w/ fuel tap  S S S						
HH9 Air Condition, Front  IH7 Head Unit, North America  IH8 Speedometer, miles and km/h  IH8 Speedo						
IH7Head Unit, North AmericaSSJ11Speedometer, miles and km/hSSJ55Seat belt warning for co-driver seatSSJ58Seat belt reminder driverSSJ65Outside temperature gaugeSSJA8Crosswind AssistSSJH3Communication module (LTE) for dig. servicesSSJ19Service interval 20.000 milesSSJW2Deactivation lamp monitoring failureSSK56Red diesel filler capSSK60Exhaust straight to rearSSKB724.5 gallon fuel tankSSKL1Aux fuel sending unit w/ fuel tapSS						
J11Speedometer, miles and km/hSSJ55Seat belt warning for co-driver seatSSJ58Seat belt reminder driverSSJ65Outside temperature gaugeSSJA8Crosswind AssistSSJH3Communication module (LTE) for dig. servicesSSJ19Service interval 20.000 milesSSJW2Deactivation lamp monitoring failureSSK56Red diesel filler capSSK60Exhaust straight to rearSSKB724.5 gallon fuel tankSSKL1Aux fuel sending unit w/ fuel tapSS						
J55Seat belt warning for co-driver seatSSJ58Seat belt reminder driverSSJ65Outside temperature gaugeSSJA8Crosswind AssistSSJH3Communication module (LTE) for dig. servicesSSJI9Service interval 20.000 milesSSJW2Deactivation lamp monitoring failureSSK56Red diesel filler capSSK60Exhaust straight to rearSSKB724.5 gallon fuel tankSSKL1Aux fuel sending unit w/ fuel tapSS						
J58Seat belt reminder driverSSJ65Outside temperature gaugeSSJA8Crosswind AssistSSJH3Communication module (LTE) for dig. servicesSSJI9Service interval 20.000 milesSSJW2Deactivation lamp monitoring failureSSK56Red diesel filler capSSK60Exhaust straight to rearSSKB724.5 gallon fuel tankSSKL1Aux fuel sending unit w/ fuel tapSS			S	S		
JA8 Crosswind Assist  JH3 Communication module (LTE) for dig. services  S S JI9 Service interval 20.000 miles  S S JW2 Deactivation lamp monitoring failure  K56 Red diesel filler cap  K60 Exhaust straight to rear  K87 24.5 gallon fuel tank  KL1 Aux fuel sending unit w/ fuel tap  S S S S S S S S S S S S S S S S S S	J58		S	S		
JH3       Communication module (LTE) for dig. services       S       S         JI9       Service interval 20.000 miles       S       S         JW2       Deactivation lamp monitoring failure       S       S         K56       Red diesel filler cap       S       S         K60       Exhaust straight to rear       S       S         KB7       24.5 gallon fuel tank       S       S         KL1       Aux fuel sending unit w/ fuel tap       S       S	J65	Outside temperature gauge	S	S		
JI9 Service interval 20.000 miles S S  JW2 Deactivation lamp monitoring failure S S  K56 Red diesel filler cap S S  K60 Exhaust straight to rear S S  KB7 24.5 gallon fuel tank S S  KL1 Aux fuel sending unit w/ fuel tap S S	JA8	Crosswind Assist	S	S		
JW2Deactivation lamp monitoring failureSSK56Red diesel filler capSSK60Exhaust straight to rearSSKB724.5 gallon fuel tankSSKL1Aux fuel sending unit w/ fuel tapSS	JH3	Communication module (LTE) for dig. services	S	S		
K56Red diesel filler capSSK60Exhaust straight to rearSSKB724.5 gallon fuel tankSSKL1Aux fuel sending unit w/ fuel tapSS	JI9	Service interval 20.000 miles	S	S		
K60Exhaust straight to rearSSKB724.5 gallon fuel tankSSKL1Aux fuel sending unit w/ fuel tapSS	JW2	Deactivation lamp monitoring failure	S	S		
KB7 24.5 gallon fuel tank  S S  KL1 Aux fuel sending unit w/ fuel tap  S S	K56	Red diesel filler cap	S	S		
KL1 Aux fuel sending unit w/ fuel tap S S	K60	Exhaust straight to rear	S	S		
	KB7	24.5 gallon fuel tank	S	S		
KL5   Fuel filter with water separator			S	S		
	KL5	Fuel filter with water separator	S	S		

### **4500 CAB CHASSIS - 6cyl Diesel** Standard Equipment

		144" 6C	170'' 6C	
		M4CC46	M4CC76	
		907.153	907.155	
KP6 3rd	d generation SCR emission control system	S	S	
L94 Pa	rking lights deletion	S	S	
LA2 He	eadlight assistant	S	S	
MS1 Cri	ruise control	S	S	
P47 Fro	ont mudflaps	S	S	
Q11 Lo	ngitudinal member reinforcement	S	S	
Q72 De	eletion of end cross member	S	S	
R60 Pro	ovisional spare wheel bracket frame mounted	S	S	
R87 Sp	pare tire	S	S	
RD9 Un	nspecified tire brand	S	S	
RH7 Tir	res LT 215/85 R16	S	S	
RM0 All	l-season tires	S	S	
RS6 5.5	5 J x 16 steel wheels	S	S	
SO2 Sta	andard driver seat	S	S	
S04 Sta	andard front passenger seat	S	S	
S22 Ar	mrest for driver's seat	S	S	
S25 Ar	mrest for front passenger seat	S	S	
SA5 Fro	ont airbag, driver	S	S	
SA6 Fro	ont airbag, passenger	S	S	
SH1 Th	norax-pelvis sidebag, driver	S	S	
SH2 Th	norax-pelvis sidebag, co-driver	S	S	
SH9 Air	rbag, driver/passenger window	S	S	
SK2 Se	eat occupancy sensor, driver's seat	S	S	
XL4 GV	/WR 12,125 lbs. / 5.500 Kg	S	S	
Y43 Jac	ck, hydraulic	S	S	

		144" 6C	170" 6C
		M4CC46	M4CC76
		907.153	907.155
	<b>,</b>		
AR2	Axle ratio 3.923	\$0	\$0
	not with AR3		
B01	Vehicle version for high load	-	\$0
	must have CB4/CB8; not with RF8		
BE2	Handbrake lever, folding	\$55	\$55
C72	Bumpers front/rear primed	\$141	\$141
	must have CN2 (part of X67), not with CM2		
CB4	Stabilization Level III	\$187	\$187
	not with CB8		
CE8	Raised rear body mounts	-	\$409
CL3	Leather steering wheel	\$187	\$187
	must have (C02/E3M)/C03 + (ET4/MS1)		
CM2	Bumpers/detachable body parts painted body colour	\$432	\$432
	must have CN2/X67 + (7755/9147/9197/9775)		
CM9	Primed side moldings	\$364	\$364
	must have C72, not with CM2		
E1B	Tray for smartphones incl. wireless charging	\$156	\$156
	must have CO2/E3M + H1I		
E1E	Navigation	\$728	\$728
	must have CO2/E3M, not with CO3		
E1S	Sirius XM, satellite radio	\$255	\$255
	must have CO2/E3M/CO3		
E1X	MBUX multimedia 6-hour runtime	-	\$0
	must have X2R + (C02+E1E/E1S)/C03/(E3M+E1E/E1S)		
E1R	Additional Fuses (40/80/150/100 Ampere)	\$50	\$50
	SoP and Plausibility TBD		
E1Y	Additional Fuses (40/80/80/100 Ampere)	\$50	\$50
	SoP and Plausibility TBD		
E2A	Access point for BB special signals in cockpit	\$29	\$29
E2I	Additional battery, co-driver seat base	\$248	\$248
	Must have E36; not with E2M		
E2M	Additional battery, engine compartment	\$248	\$248
	must have X01+E36; not with E2I/X69		
E3M	MBUX Multimedia System with 7" touchscreen	\$474	\$474
	not with CO2/CO3; must have JK5		
E36	Cutoff relay for additional battery	\$110	\$110
	standard with E2I/E2M		
E46	12 V power outlet, driver seat base	\$92	\$92
E5M	Extension of PSM standard contact	\$58	\$58
EA5	Pre-wiring central locking (upfitter doors rear)	\$39	\$39
ED4	AGM battery 12V 92 AH 850 A	\$101	\$101
	not with ED1	1-	4
ED5	Parametric special module (PSM)	\$317	\$317
	not with ED8	1.55	445-
EE3	115 V socket	\$125	\$125
EP7	Basic electric fitting for rear loudspeakers	\$68	\$68
ES5	Charging package, dashboard	\$82	\$82
ET4	Active Distance Assist DISTRONIC	\$263	\$263
F2-	must have CO2/CO3/E3M	A40.	404
F35	Window in cab rear wall	\$134	\$134
F 4 2	must have F61/FV1; not with FW1	4016	4242
F49	Electrically heated windshield	\$218	\$218
F.5.	must have ED4; not with LA3	40.0	40.0
F61	Interior rear view mirror	\$36	\$36
	must have CO2/CO3/E3M	Ac.	404
FE9	Additional DIN-slot	\$81	\$81
FF8	Overhead storage slot, front center	\$105	\$105
FJ1	Hinged lid for storage compartment	\$93	\$93

		144" 6C	170" 6C
		M4CC46	M4CC76
		907.153	907.155
FR7	Pre-wiring rear view camera (head unit display)	\$65	\$65
	must have CO2/CO3; not with FV1		
FV1	Pre-wiring rear view camera (mirror display)	\$260	\$260
	not with F61/FR7/LA3		
FW1	Rear wall deletion, chassis cab	\$0	\$0
	must have P08; not with FY1		
FY1	Security alarm w. interior motion sensor	\$584	\$584
	must have LC4/C00; not with FW1/X2R	4	4
FY7	Optional 3-button keys	\$36	\$36
FZ9	Keys, two additional masters	\$121	\$121
H04	Heat insulation, front compartment	\$187	\$187
1112	must have FW1/V07	ćaac	ćoac
H12	Fuel-fired pre-heater/booster (17K BTU)	\$826	\$826
1115	must have ED4; not with HZ9	\$284	¢204
H15	Heated front passenger seat	\$284	\$284
H16	must have H16; not with X68 Heated driver's seat	\$284	\$284
1110	must have H15; not with X68	Ş204	<i>γ</i> 204
H88	Rear heater prep	\$405	\$405
1100	must have ED4+(H12/HZ9)	Ş <del>-</del> 05	<del>у-</del> 03
H1I	Front-to-rear outlet in instrument panel	\$0	\$0
	must have FJ1/C01	ΨU	ΨO
HH4	Thermotronic automatic climate control	\$337	\$337
	must have JF1	7001	700.
HZ9	Fuel-fired heater booster (18,000 BTU)	\$676	\$676
	not with H12	, ,	,
J1V	Pre-installation Blind Spot Assist	\$450	\$450
	SoP and Plausibility TBD	·	
J51	Fuel gauge, optimized for aux. fuel tap	\$72	\$72
	not with HZ9/H12		
J52	Engine oil level display at cold start	\$0	\$0
JB4	Active Lane Keeping Assist	\$288	\$288
	not with CO2/CA2		
JF1	Rain sensor	\$106	\$106
	standard with CO2; not with LA3	,	
JK5	Instrument cluster with color display	\$144	\$144
	standard with CO3		
JW0	Backup alarm	\$99	\$99
	not wit Q72		
JW8	Attention Assist	\$49	\$49
K51	Misfueling prevention for Diesel	\$49	\$49
K52	DEF fluid filler cap - lockable	\$27	\$27
L13	Fog lamp with cornering light function	\$199	\$199
L72	Pre-installation load compartment lighting	\$174	\$174
L76	Wire harness tail lamp w/ extended wiring	\$133	\$133
L77	Wiring for additional turn signals	\$88	\$88
L90	Tail lamp deletion, non-LED	-\$26	-\$26
101	not with L22	640	Ć40
L91	Pre-wiring LED tail lights  not with L22/L90	\$49	\$49
LA3		\$0	\$0
LAS	Light sensor for vehicles with alcove  not with F49/F61/FV1/LA2/JF1	ŞU	Ų
LB9	Illuminated front exits	\$93	\$93
LC4	Comfort overhead control panel	\$93	\$93
LV6	Third brake light pre-wiring	\$32	\$32
M20	Speed limitation 65 mph	\$60	\$60
1,1,20	not with MD3	γoo	700
<u> </u>			

		144" 6C	170" 6C
		M4CC46	M4CC76
		907.153	907.155
		307.133	907.133
	Starter upgraded	\$189	\$189
MD3	Top speed limitation 75 mph	\$60	\$60
	not with M20		
N62	Front engine bracket for additional alternator	\$467	\$467
	not with N63		
N63	Front engine bracket for auxiliary A/C compressor	\$467	\$467
	not with N62	4.0	4.5
P08	Cover for transport	\$0	\$0
040	must have FW1/X69	ACE.	d.c.r
Q18	End cross member bolted	\$65	\$65
QA2	Trailer cross member 7,500 lbs capacity	\$187	\$187
R65	Spare tire bracket below frame	\$0	\$0
R91	must have Q18; not with Q72/R60/R92 Spare tire deletion	¢110	-\$110
K91	must have R92; not with R87/R60	-\$110	-\$110
R92	Spare tire carrier deletion	\$0	\$0
NJZ	must have R91; not with R65/R60	ŞÜ	<b>3</b> 0
R98	Rims painted jet black	\$81	\$81
N30	not with RM2	701	ΨOI
RF1	Tire brand Continental	\$0	\$0
111 1	not with RD9	ΨO	ΨO
RF8	Tire brand Michelin	\$0	\$0
	not with RD9/RF1/RM1	7.5	7-5
RM1	M+S winter tires	\$169	\$169
	must have RD9/RF1; not with RF8/X31	·	,
RM2	Rims painted arctic white	\$81	\$81
	not with X31/R98		·
RM9	Specially requested tires	\$101	\$101
	must have RF1/RF8; not with RD9		
S23	Twin front passenger seat	\$400	\$400
	not with COO/X68/X01		
S28	Armrest, driver and passenger door	\$51	\$51
S62	Seat belts orange, driver and front passenger	\$32	\$32
	not with S23		
SB9	Driver's seat plus	\$238	\$238
	must have FY7		
SZ7	Storage net, driver's seat backrest	\$0	\$0
	must have FW1/X69		
SZ8	Storage net, passenger seat backrest	\$0	\$0
	must have FW1/X69; not with S23		
T75	Door-mounted assist handles, driver & passenger	\$59	\$59
V07	Cab rear wall liner	\$360	\$360
	not with FW1	•	
V85	Cigarette lighter & ash cup, front	\$39	\$39
VV4	Additional Ground Weld Studs	\$45	\$45
	SoP and Plausibility TBD		
X2R	Conversion to RV requirement	-	\$0
	must have B01+E1X		1.5
X93	Deletion of model badge, right rear door	\$0	\$0
XM4	Acoustic package	\$87	\$87
	standard with CO2/CO3	,	
Y10	First-aid kit	\$27	\$27
Y26	Wheel chocks	\$38	\$38
Y45	Emergency flashlight	\$27	\$27
Y68	Paint preservative	\$88	\$88
Y69	Surface protection for stock vehicles	\$292	\$292
103	Samuel protection for stock vehicles	∠د∠د	JLJL

# **4500 CAB CHASSIS - 6cyl Diesel** Packages

144" 6C

170" 6C

		M4CC46	M4CC76
		907.153	907.155
C00	Comfort Package	\$300	\$300
LC4	Comfort overhead control panel	X	X
SE4	Lumbar support, co-driver's seat	X	X
SE5	Lumbar support, driver's seat	X	X
SK0	Comfort head restraint, driver	X	X
SK1	Comfort head restraint, co-driver	X	X
S28	Armrest, driver and passenger door	X	X
must	have COS OR X68; not with S23		

COS	Comfort Package (Seat addition)	\$381	\$381
SB1	Comfort driver's seat	Х	Х
SB2	Comfort passenger seat	Х	Х
must	have COO	_	

X68	Comfort Plus Package	\$1,923	\$1,923
H15	Heated front passenger seat	X	X
H16	Heated driver's seat	X	Х
SF1	Driver's seat electrically adjustable	X	Х
SF2	Co-driver's seat electrically adjustable	X	Х
must	have COO and VF4 OR VF6; not with S23		

C01	Driver Convenience Package	\$323	\$323
E46	12 V power outlet, driver seat base	X	Х
FJ1	Hinged lid for storage compartment	X	Х
FZ9	Keys, two additional masters	X	Х
JW8	Attention Assist	X	X

C02	Premium Package	\$983	\$983	
CL3	Leather steering wheel	Х	X	
E3M	MBUX Multimedia System with 7" touchscreen	Х	Х	
FM3	Wet Wiper System	Х	Х	
JB4	Active Lane Keeping Assist	Х	X	
JK5	Instrument cluster with color display	X	X	
Ordering availability restricted, see NetStar for availability and restrctions   must have (JF1/LA3) +				
XM4				

CA2	C02 in combination with C03	\$604	\$604
CL3	Leather steering wheel	X	X
FM3	Wet Wiper System	X	X
JB4	Active Lane Keeping Assist	X	X
JK5	Instrument cluster with color display	X	X

Ordering availability restricted, see NetStar for availability and restrctions | must have CO3 + JF1

# **4500 CAB CHASSIS - 6cyl Diesel** Packages

144" 6C	170" 6C
M4CC46	M4CC76
907.153	907.155

C03	Premium Plus Package	\$1,793	\$1,793
E1B	Tray for smartphones incl. wireless charging	X	X
	Navigation	X	X
EY2	Intelligent navigation	X	X
E4M	MBUX Multimedia System with 10.25" touchscreen	X	X
EX9	Free map data updates for 3 years	X	X
H1I	Front-to-rear outlet in instrument panel	X	X
JA9	Traffic Sign Assist	X	X
XM4	Acoustic package	X	X
must	have CA2 OR (JB4+JK5+FM3)		

X67	Chrome Grille Package	\$290	\$290
CN2	Radiator grille frame in vehicle color	X	X
FK3	Chrome plated radiator grille (MB only)	X	X
no re	strictions		

X13	Exterior Lighting Package	\$1,608	\$1,608	
L13	Fog lamp with cornering light function	X	X	
L22	Partial LED tail lights	Х	X	
LA1	High beam assist	Х	X	
LG7	LED high performance headlamps	Х	Х	
no re	no restrictions			

X69	Swivel Seat Package	\$587	\$587
SR8	Swivel base for driver's seat	X	X
SR9	Swivel base for front passenger seat	Х	X
S87	Driver's seat frame, low	Х	X
S88	Passenger seat frame, low	Х	X
FW1	Rear wall deletion, chassis cab	X	Х
BE2	Handbrake lever, folding	X	Х
must	have (C00+C0S) OR (C00+X68)		

X01	Suspension Seating Package	\$940	\$940
SB3	Driver suspension seat, comfort version	X	Х
SB4	Passenger suspension seat, comfort version	X	X
S87	Driver's seat frame, low	Х	X
S88	Passenger seat frame, low	Х	Х
not v	vith C00/C0S/X68/S23		

## "Incomplete Vehicle" Packages - Fleet Only

If any of the below packages are ordered, vehicle will become an "incomplete vehicle"! In this case an upfitter will become the final stage manufacturer. Please note that the involvement of an upfitter is required to register the vehicle. We recommend working with one of our ExpertSolutions Partners.

For questions or further assistance please reach out to: vaninfo@mbusa.com

## Cargo Models- Only 4cyl & 6cyl Diesel engines

			2500			3500			3500XD			4500	
		144"	170"	170"EXT									
		4x2/4x4	4x2/4x4	4x2/4x4	4x2	4x2	4x2	4x2/4x4	4x2/4x4	4x2/4x4	4x2	4x2	4x2
F02	Windows All Around Package	\$2,424	\$3,062	\$3,062	\$2,424	\$3,062	\$3,062	\$2,424	\$3,062	\$3,062	\$2,424	\$3,062	\$3,062
F43	Laminated glass rear	Χ	Х	Χ	Χ	Х	Х	Χ	Х	Χ	Χ	Χ	Х
H22	Rear window defroster	Х	Х	Χ	Χ	Χ	Х	Χ	Х	Χ	Χ	Χ	Х
VA7	Storage compart. w/ net in rear doors	Х	X	Χ	Χ	Х	Х	X	Х	Χ	Χ	Χ	Х
W02	Panel van w/windows all round	Χ	Х	Χ	Χ	Χ	Х	Χ	Х	Χ	Χ	Χ	Х
W16	2nd row, fixed window, driver side	Х	Х	Χ	Χ	Χ	Х	Χ	Х	Χ	Х	Χ	Χ
W17	2nd row, fixed window, passenger side	Х	Х	Χ	Χ	Χ	Х	Χ	Х	Х	Х	Χ	Х
W22	Fixed window, center left	-	Х	Χ	-	Χ	Х	-	Х	Χ	-	Χ	Х
W23	Fixed window, center right	-	Х	Χ	-	Χ	Х	-	Х	Χ	-	Χ	Χ
W27	Fixed window, rear left	X	Х	Χ	Χ	Х	Х	Χ	Х	Х	Х	Χ	Χ
W28	Fixed window, rear right	Х	X	Х	Χ	Χ	Х	X	X	Х	Χ	Х	Х

Choose while ordering: 1. W61/W78 2. W16/W33 W22 and W23 only available for 170" and 170"170"EXT. WB If ordered with standard roof CHS production required Not with T19

			2500			2500			2F00VD			4500	
			2500			3500			3500XD			4500	
		144"	170"	170"EXT	144"	170"	170"EXT	144"	170"	170"EXT	144"	170"	170"EXT
		4x2/4x4	4x2/4x4	4x2/4x4	4x2	4x2	4x2	4x2/4x4	4x2/4x4	4x2/4x4	4x2	4x2	4x2
F03	Window Prep Package I (knockouts for window installation)	\$602	\$602	\$602	\$602	\$602	\$602	\$602	\$602	\$602	\$602	\$602	\$602
H22	Rear window defroster	Х	Х	Х	Х	Х	Х	Χ	Х	Х	Х	Х	Х
P08	Cover for transport	Х	Χ	Χ	Х	Х	Х	Χ	Х	Х	Χ	Х	X
VA7	Storage compart. w/ net in rear doors	Х	Χ	Χ	Χ	Χ	Х	Χ	Χ	Χ	Χ	Х	Х
W02	Panel van w/windows all round	X	Χ	Χ	Χ	Х	Х	Χ	Х	Χ	Χ	X	Х
W16	2nd row, fixed window, driver side	Χ	Χ	Χ	Χ	Χ	Х	Χ	Χ	Χ	Χ	Х	X
W17	2nd row, fixed window, passenger side	Х	Χ	Χ	Χ	Χ	Х	Χ	Χ	Χ	Χ	Х	Х
W22	Fixed window, center left	-	Χ	Χ	-	Х	Х	-	Х	Χ	-	X	Х
W23	Fixed window, center right	-	Χ	Χ	-	Х	Х	-	Х	Χ	-	Х	Х
W27	Fixed window, rear left	Χ	Χ	Χ	Χ	Χ	Х	Χ	Χ	Χ	Χ	Χ	X
W28	Fixed window, rear right	Х	Χ	Χ	Χ	Х	Х	Χ	Х	Χ	Χ	X	X
W61	Windows in rear doors	Х	Χ	Χ	Χ	Х	Х	Χ	Х	Χ	Χ	Х	X
W94	Window openings w/o glass - side and rear	Х	Х	Х	Х	Х	Х	X	Х	X	Х	Х	X

W22 and W23 only available for 170" and 170"170"EXT. WB.

			2500			3500			3500XD			4500	
		144"	170"	170"EXT	144"	170"	170"EXT	144"	170"	170"EXT	144"	170"	170"EXT
		4x2/4x4	4x2/4x4	4x2/4x4	4x2	4x2	4x2	4x2/4x4	4x2/4x4	4x2/4x4	4x2	4x2	4x2
F07	Window Prep Package II (knockouts for window installation with windows in rear door)	\$671	\$671	\$671	\$671	\$671	\$671	\$671	\$671	\$671	\$671	\$671	\$671
H22	Rear window defroster	X	Χ	Χ	Χ	Χ	Х	Χ	Χ	X	Χ	X	X
P08	Cover for transport	Х	Χ	Χ	Χ	Х	Х	Χ	Χ	Х	Χ	Х	Х
VA7	Storage compart. w/ net in rear doors	Χ	Χ	Χ	Χ	Χ	Х	Χ	Χ	Х	Χ	Χ	Х
W02	Panel van w/windows all round	Χ	Χ	Χ	Χ	Χ	Х	Χ	Χ	Х	Χ	Χ	Х
W16	2nd row, fixed window, driver side	Х	Χ	Χ	Χ	Χ	Х	Χ	Χ	Х	Χ	Х	Х
W17	2nd row, fixed window, passenger side	Χ	Χ	Χ	Χ	Χ	Х	Χ	Χ	Х	Χ	Χ	Х
W22	Fixed window, center left	-	Χ	Χ	-	Х	Х	-	Χ	Х	-	Х	Х
W23	Fixed window, center right	-	Χ	Χ	-	Х	Х	-	Χ	Х	-	Х	Х
W27	Fixed window, rear left	X	Χ	Χ	Χ	Χ	Χ	Χ	Χ	X	Χ	Χ	Х
W28	Fixed window, rear right	Χ	Χ	Χ	Χ	Х	Х	Χ	Χ	X	Χ	Χ	Х
W93	Window openings w/o glass - side	Х	Χ	Χ	Χ	X	Х	Χ	Χ	X	Χ	Х	Х

Choose while ordering: W61/W78

W22 and W23 only available for 170" and 170"170"EXT. WB.

## "RV Bundles" for Cargo and Cab Chassis Models

RVO and RV1 are bundling essential product features specifically for RV upfits. MBUSA Product Management suggests that these bundles are added to any vehicle that will receive an RV-type upfit in order to allow an easier upfit process, enhanced technical usability as well as an improved driving performance tailored to RV vehicle characteristics.

## **Cargo Models- Only 6cyl Diesel engines**

			2500			3500			3500XD			4500	
		144"	170"	170"EXT	144"	170"	170"EXT	144"	170"	170"EXT	144"	170"	170"EXT
		4x2/4x4	4x2/4x4	4x2/4x4	4x2	4x2	4x2	4x2/4x4	4x2/4x4	4x2/4x4	4x2	4x2	4x2
RV0	RV Technical Bundle	\$856	\$856	\$856	\$856	\$856	\$856	\$856	\$856	\$856	\$856	\$856	\$856
E1X	MBUX 6-hour runtime	Х	X	X	-	Х	Χ	-	X	X	-	Χ	Х
J51	Fuel gauge, optimized for aux. fuel tap	Χ	X	X	Х	Х	Χ	Χ	X	X	Х	Х	X
N62	Front engine bracket for additional alternator	X	X	X	Х	Х	Χ	X	X	X	X	Х	Χ
KL1	Aux fuel sending unit w/ fuel tap	X	X	X	X	X	X	X	X	X	X	Х	Х
ED5	Parametric special module (PSM)	X	Х	Х	X	Х	Х	Χ	Х	X	Х	Х	Х

Not with H12/HZ9/HK4/N63

Must have X69 + (E3M/C02/C03) + FR7/FV1; for 170/170170"EXT only + must have X2R/RV1

				2500			1	3500				3500XD			Ī	4500	<del></del>
		144"	17		170'	'EXT	144"	170"	170"EXT	144"	17		170'	'EXT	144"	170"	170"EXT
		4x2	4x2	4x4	4x2	4x4	4x2	4x2	4x2	4x2	4x2	4x4	4x2	4x4	4x2	4x2	4x2
RV1	RV Suspension Bundle	\$1,519	\$1,519	\$0	\$1,519	\$0	\$785	\$785	\$785	\$785	\$785	\$0	\$785	\$0	\$439	\$439	\$439
A50	Front axle reinforced	Х	Х	-	Х	-	Х	Х	Х	Х	Х	-	Х	-	S	S	S
B01	Vehicle version for high load	Х	Х	Х	Х	Х	-	Х	Х	-	Х	Х	Х	Х	-	Х	Х
CB4	Stabilization Level III	Х	Х	-	Х	-	Х	Х	Х	Х	Х	-	Х	-	Х	Х	Х
CE8	Raised rear body mounts	Х	Х	-	Х	-	Х	Х	Х	Х	Х	-	Х	-	Х	Х	Х
X2R	Bodybuilder requirement: conversion to motorhome	Х	Х	Х	Х	Х	-	Х	Х	-	Х	Х	Х	Х	-	Х	Х

Must have RV0 + D93; 3500XD must have X34

not with CB1/CB2/CB7/CB8/S23/RH0; 144"" WB not with K60

## Cab Chassis Models- Only 6cyl Diesel engines

				3500XD		45	00	ĺ
			144"	170"		144"	170"	
			4x2	4x2		4x2	4x2	
RV0	RV Technical Bundle		\$989	\$989		\$989	\$989	
J51	Fuel gauge, optimized for aux. fuel tap		Χ	X		Х	Х	
LV7	Clearance lights pre-wiring		Χ	X		Х	Х	
L76	Wire harness tail lamp w/ extended wiring	NI/A	Χ	X	NI/A	Х	Х	NI/A
E1X	MBUX 6-hour runtime	N/A	-	X	N/A	-	Х	N/A
N62	Front engine bracket for additional alternator		Х	X		Х	Х	
KL1	Aux fuel sending unit w/ fuel tap		Х	Х		Х	Х	
ED5	Parametric special module (PSM)		Х	Х		Х	Х	

Not with V59/H12/HZ9/N63

Must have X69 + (E3M/C02/C03) + FR7/FV1; for 170 only + must have X2R/RV1

				3500XD		45	500	
			144"	170"		144"	170"	
			4x2	4x2		4x2	4x2	
RV1	RV Suspension Bundle		\$533	\$942		\$533	\$596	
A50	Front axle reinforced		Х	X		S	S	
B01	Vehicle version for high load	N/A	-	X	NI/A	-	Х	NI/A
CB4	Stabilization Level III	N/A	Х	X	N/A	X	Х	N/A
CE8	Raised rear body mounts		-	X		-	Х	
X2R	Bodybuilder requirement: conversion to motorhome		-	X		-	Х	

Must have RV0; 3500XD must have X34 not with CB2/CB8; 144" WB not with K60

					Ехр	ertSo	lutior	ns™ Ship-Thru Pa	artners		
Price	Facility	U-Code	Descripton of U-Code		odels A	•		Shipping Contact	Shipping Email Address	Shipping phone	Shipping address
				CA	CC	CV	PV			number	
\$100	Driverge	US1	Driverge Ship-Thru	Х	-	-	-	Stephen Fink	stephen.fink@driverge.com	330 247 5246	9004 Sightline Drive, Suite 5, Ladson, SC
\$100	Driverge	US5	Driverge Fleet Ship-Thru	X	-	-	-	Stephenink	<u>stephen.iiik@driverge.com</u>	330 247 3240	29456
\$100		UK1	Knapheide Van Equipment Ship-Thru	Χ	-	Χ	-				
\$100	Knapheide	UK2	Gruau/ThermoKing by Knapheide Ship-Thru	hru X	-	Karl Braun	expertsolutions@Knapheide.com	854 529 4923	2486 US Highway 52, Moncks Corner, SC		
\$100	Kilapilelue	UK3	Knapheide Bodies Ship-Thru	-	Χ	•	-	Kali biauli	expertsolutions@knapnelde.com	034 323 4323	29461
\$100		UK5	Knapheide Fleet Ship-Thru	Х	Χ	Χ	-				
\$100	Auto Truck	UA1	Auto Truck Ship-Thru	Х	Х	Χ	-				211 Farmington RD, Summerville, SC
\$100		UA2	Auto Truck SPECIAL Ship-Thru	Х	Х	Χ	-	Tana Drake	atgmborders@autotruck.com	866 428 8267	i i
\$100	Group	UA5	Auto Truck Fleet Ship-Thru	Х	Χ	Χ	-				29483
			*US1, UK1, UK2, UK3, UA1, UA2 are to be use	ed wher	order	ing the	corres	ponding ExpertSOLU	JTIONS™ upfits as shown on upfitterpo	rtal.com or mbvans.co	m

					Othe	r Cha	rlesto	n, SC Ship-Thru	Partners		
Price	Facility	U-Code	Description of U-Code		lodels A			Shipping Contact	Shipping Email Address	Shipping phone	Shipping address
	•		·	CA	CC	CV	PV	•	•	number	•
\$100 \$100	IVS	UI1	Innovative Vehicle Solutions Ship-Thru	Х	X	Х	-	Sam Kuhn	sam.k@innovativevehicle.com	843 376 3822	3241 Benchmark Drive, Ladson, SC
\$100	173	UI5	Innovative Vehicle Solutions Ship-Thru (Fleet)	Х	Х	Х	-	Salli Kullii	<u>sam.k@iiiiovativeveiiicie.com</u>	043 370 3022	29456
\$100	Utilimaster	UU1	Utilimaster Ship-Thru	Х	Х	Х	-	Dave Stace	Dava Stace @sportanmators com	574 848 2000 Ext	6555 Fain Street, North Charleston, SC
\$100	Utilimaster	UU5	Utilimaster Ship-Thru (Fleet)	Х	Х	Χ	-	Dave Stace	<u>Dave.Stace@spartanmotors.com</u>	2122	29406
\$100	Midway	UM1	Midway Specialty Vehicles Ship-Thru	Х	Χ	Χ	-	Kathy Franklin	kfranklin@mymidway.com	574 264 2530 Ext 107	3285 Benchmark Drive, Ladson, SC
\$100	Thermo King	U52	Thermo King of Charleston	Х	X X X	Χ	Trevor Floyd	TFloyd@fleetsourcesc.com	843 744 5040	180 Strathmore RD, Summerville, SC	

## **Ordering Information**

U-Codes can be added to the Purchase Order via the VII screen in NetStar OR by emailing the request to MBUSA Van Distribution (vandistribution@mbusa.com)

\*Don't forget to place your upfit order with the upfitter after you add the U-Code\*

U-Codes can be added/changed through D40 status. No changes permitted after D41 status

U-Codes will carry over for dealer traded vehicles

Any requests to remove a U-Code must be approved by the Van Distribution & Upfitter Management Departments

For more information on U-codes, please reach out to the Upfitter Management team: upfitterinfo@mbusa.com

All information contained in this Reference Guide is based on the latest product information available at the time of publication. Mercedes-Benz USA, LLC and Daimler Vans USA, LLC reserve the right to make changes at any time, without notice, in colors, materials, equipment, specifications and models.

Prices are manufacturer suggested retail prices and are subject to change.



# MY 2022 Technical Specifications





#### **Sprinter Cargo Van**

									Cargo						
		1.5	500				2	500	Cargo					3500 DRW	
		144" SR	144" HR	144" SR	144" HR	144" SR 4x4	144" HR 4x4	170" HR	170" HR 4x4	170 Ext. HR	170 Ext. HR 4x4	144" SR	144" HR	170" HR	170 Ext. HR
	GVWR [lbs]	8,550	8,550	9,050	9,050	9,050	9,050	9,050	9,050	9,050	9,050	9,990	9,990	9,990	9,990
	GAWR.F (standard) [lbs]	4,101	4,101	4,101	4,101		•	4,101				•			
	GAWR.F (with A50) [lbs]	4,409	4,409	4,409	4,409	1		4,409	1						
	GAWR.R [lbs]	5,359	5,359	5,359	5,359			5,359							
	Base Curb Weight Front [lbs]	2,608	2,651	2,608	2,651			2,834							
	Base Curb Weight Rear [lbs]	1,967	2,000	1,967	2,000			2,138	i						
	Base Curb Weight [lbs]	4,575	4,652	4,575	4,652	1		4,971	1						
3as	Maximum Payload [lbs]	3,975	3,898	4,475	4,398		available for these	4,079			Gas engine not a	available for th	nese models		
~	UVW [lbs]	6,950	6,950	6,450	6,450	1 "	odels	6,450	1						
	Maximum Towing [lbs]	5,000	5,000	5,000	5,000			5,000							
	Maximum Tongue Weight [lbs]	500	500	500	500			500							
	GCWR [lbs]	13,550	13,550	13,930	13,930			13,930							
	Load Height - Unloaded (Ground to Cargo Floor) [in]	28	28	28	28			27							
	Load Height - Loaded (Ground to Cargo Floor) [in]	23	23	23	23			23							
	GAWR.F (standard) [lbs]			4,101	4,101	4,409	4,409	4,101	4,409	4,101	4,409	4,081	4,081	4,081	4,081
	GAWR.F (with A50) [lbs]			4,409	4,409	N/A	N/A	4,409	N/A	4,409	N/A	4,409	4,409	4,409	4,409
7	GAWR.R [lbs]			5,359	5,359	5,359	5,359	5,359	5,359	5,359	5,359	7,059	7,059	7,059	7,059
(OIMD4Z)	Base Curb Weight Front [lbs]			1,958	1,989	2,046	2,076	2,222	2,318	2,377	2,474	2,352	2,386	2,657	2,831
5	Base Curb Weight Rear [lbs]			2,937	2,983	3,201	3,248	3,069	3,336	3,025	3,280	2,994	3,037	3,119	3,067
Į,	Base Curb Weight [lbs]	Diesel or	ngines not	4,894	4,971	5,247	5,324	5,291	5,655	5,401	5,754	5,346	5,423	5,776	5,897
ii ii	Maximum Payload [lbs]		these models	4,156	4,079	3,803	3,726	3,759	3,395	3,649	3,296	4,644	4,567	4,214	4,093
Į.	UVW [lbs]	L. Janabie 101	se models	7,401	7,401	7,401	7,401	7,401	7,401	7,401	7,401	7,401	7,401	7,401	7,401
Ĕ	Maximum Towing [lbs]			5,000	5,000	5,000	5,000	5,000	5,000	5,000	5,000	7,500	7,500	7,500	5,000
ξ	Maximum Tongue Weight [lbs]			500	500	500	500	500	500	500	500	750	750	750	750
٥	GCWR [lbs]			13,930	13,930	13,930	13,930	13,930	13,930	13,930	13,930	15,250	15,250	15,250	15,250
	Load Height - Unloaded (Ground to Cargo Floor) [in]		28 28 23 23 4 101 4 101	31	31	27	31	27	31	29	29	29	29		
	Load Height - Loaded (Ground to Cargo Floor) [in]					27 27		23	27	23	27	23	23	23	23
	GAWR.F (standard) [lbs]			4,101	4,101			4,101		4,101		4,081	4,081	4,081	4,081
	GAWR.F (with A50) [lbs]		4,409 5,359	4,409	4,409			4,409		4,409		4,409	4,409	4,409	4,409
a	GAWR.R [lbs]				5,359			5,359		5,359		7,059	7,059	7,059	7,059
(OM651)	Base Curb Weight Front [lbs]			1,936	2,016			2,199 3,037		2,406		2,381	2,416	2,632	2,863
á	Base Curb Weight Rear [lbs]			2,903	2,901					2,940		2,910	2,953	3,089	2,980
diesel	Base Curb Weight [lbs]	Diesel er	ngines not	4,839	4,916			5,236	Engine not	5,346	Engine not available	5,291	5,368	5,721	5,842
ë	Maximum Payload [lbs]		these models	4,211	4,134	Engine not avai	lable for this model	3,814	available for this	3,704	for this model	4,699	4,622	4,269	4,148
der	UVW [lbs]			7,401	7,401			7,401 5,000	model	7,401	-	7,401	7,401	7,401	7,401
Ĕ	Maximum Towing [lbs]			5,000	5,000					5,000		7,500	7,500	7,500	5,000
Ş.	Maximum Tongue Weight [lbs]			500	500			500		500		750	750	750	750
7	GCWR [lbs]			13,930	13,930			13,930		13,930		15,250	15,250	15,250	15,250
	Load Height - Unloaded (Ground to Cargo Floor) [in]			28	28			27		27		29	29	29	29
	Load Height - Loaded (Ground to Cargo Floor) [in]			23	23	20.4		23	0.71	23		23	23	23	23
	Vehicle Length [in]	234	234	234	234	234	234	274	274	290	290	290	234	274	290
	Vehicle Height [in]	96	107	96	107	100	111	107	111	107	111	111	109	109	108
	Vehicle Width (w/out Mirrors) [in]	80	80	80	80	80	80	80	80	80	80	80	80	80	80
	Vehicle Width (with Mirrors) [in]	92	92	92	92	92	92	92	92	92	92	92	92	92	92
	Rear Overhang (Rear Axle to End of Frame) [in]	49 133	49 133	49 133	49 133	49 133	49 133	64 174	64 174	80 189	80 189	80 189	49 133	64 174	80 189
	Maximum Cargo Bed Length at Floor [in] Cargo Width at Wheelhouse [in]	133 53	53	133 53	53	133	133 53	53	53	189 53	189 53	189 53	133 39	39	189 39
		70	70	70	70		74	70	70	70	70	70	70	70	70
		/0			54		54	74	74	81	81	81	51	70	70
	Max. Floor Width [in]	EA	EA			70 54 68	l <sup>34</sup>								78
s	Loading Area [sq ft]	54 68	54 79	54 68			79	70	70	79	70	79			15
Sall	Loading Area [sq ft] Max. Interior Height [in]	68	79	68	79	68	79 373	79 488	79 488	79 533	79 533	79 319	79 329	79 430	160
saugues	Loading Area [sq ft] Max. Interior Height [in] Cargo Volume (Behind Last Row of Seats)	68 319	79 373	68 319	79 373	68 319	373	488	488	533	533	319	329	430	469 40
	Loading Area [sq ft] Max. Interior Height [in] Cargo Volume (Behind Last Row of Seats) Front Overhang BA [in]	68 319 40	79 373 40	68 319 40	79 373 40	68 319 40	373 40	488 40	488 40	533 40	533 40	319 40	329 40	430 40	40
	Loading Area [sq ft]  Max. Interior Height [in]  Cargo Volume (Behind Last Row of Seats)  Front Overhang BA [in]  Side Door Opening Width [in]	68 319 40 51	79 373 40 50	68 319 40 51	79 373 40 50	68 319 40 51	373 40 50	488 40 51	488 40 51	533 40 51	533 40 51	319 40 51	329 40 51	430 40 51	40 51
	Loading Area [sq ft]  Max. Interior Height [in]  Cargo Volume (Behind Last Row of Seats)  Front Overhang BA [in]  Side Door Opening Width [in]  Side Door Opening Height [in]	68 319 40 51 60	79 373 40 50 72	68 319 40 51 60	79 373 40 50 72	68 319 40 51 60	373 40 50 72	488 40 51 72	488 40 51 72	533 40 51 72	533 40 51 72	319 40 51 72	329 40 51 72	430 40 51 72	40 51 72
	Loading Area [sq ft] Max. Interior Height [in] Cargo Volume (Behind Last Row of Seats) Front Overhang BA [in] Side Door Opening Width [in] Rear Door Opening Height [in]	68 319 40 51 60	79 373 40 50 72 61	68 319 40 51 60	79 373 40 50 72 61	68 319 40 51 60 61	373 40 50 72 61	488 40 51 72 61	488 40 51 72 61	533 40 51 72 61	533 40 51 72 61	319 40 51 72 61	329 40 51 72 61	430 40 51 72 61	40 51 72 61
	Loading Area [sq ft] Max. Interior Height [in] Cargo Volume (Behind Last Row of Seats) Front Overhang BA [in] Side Door Opening Width [in] Side Door Opening Height [in] Rear Door Opening Width [in] Rear Door Opening Height [in]	68 319 40 51 60 61	79 373 40 50 72 61 73	68 319 40 51 60 61	79 373 40 50 72 61	68 319 40 51 60 61	373 40 50 72 61 73	488 40 51 72 61 73	488 40 51 72 61 73	533 40 51 72 61 73	533 40 51 72 61	319 40 51 72 61 73	329 40 51 72 61 73	430 40 51 72 61 73	40 51 72 61 73
	Loading Area [sq ft] Max. Interior Height [in] Cargo Volume (Behind Last Row of Seats) Front Overhang BA [in] Side Door Opening Width [in] Side Door Opening Height [in] Rear Door Opening Height [in] Ground Clearance (running) [in]	68 319 40 51 60 61 61	79 373 40 50 72 61 73 8	68 319 40 51 60 61 61	79 373 40 50 72 61 73 8	68 319 40 51 60 61 61 8	373 40 50 72 61 73 8	488 40 51 72 61 73 8	488 40 51 72 61 73 8	533 40 51 72 61 73 8	533 40 51 72 61 73 8	319 40 51 72 61 73 8	329 40 51 72 61 73 8	430 40 51 72 61 73 8	40 51 72 61 73 8
	Loading Area [sq ft] Max. Interior Height [in] Cargo Volume (Behind Last Row of Seats) Front Overhang BA [in] Side Door Opening Width [in] Side Door Opening Height [in] Rear Door Opening Width [in] Rear Door Opening Height [in] Ground Clearance (running) [in] Wading Depth [in]	68 319 40 51 60 61 61 8	79 373 40 50 72 61 73 8	68 319 40 51 60 61 61 8 20	79 373 40 50 72 61 73 8	68 319 40 51 60 61 61 8	373 40 50 72 61 73 8	488 40 51 72 61 73 8 20	488 40 51 72 61 73 8	533 40 51 72 61 73 8	533 40 51 72 61 73 8	319 40 51 72 61 73 8 24	329 40 51 72 61 73 8	430 40 51 72 61 73 8 20	40 51 72 61 73 8 20
all engines	Loading Area [sq ft] Max. Interior Height [in] Cargo Volume (Behind Last Row of Seats) Front Overhang BA [in] Side Door Opening Width [in] Side Door Opening Height [in] Rear Door Opening Width [in] Rear Door Opening Height [in] Ground Clearance (running) [in] Wading Depth [in] Turning Circle curb to curb [ft]	68 319 40 51 60 61 61 8 20 41	79 373 40 50 72 61 73 8 20	68 319 40 51 60 61 61 8 20 41	79 373 40 50 72 61 73 8 20	68 319 40 51 60 61 61 8 24	373 40 50 72 61 73 8 24	488 40 51 72 61 73 8 20 47	488 40 51 72 61 73 8 24	533 40 51 72 61 73 8 20 47	533 40 51 72 61 73 8 24 50	319 40 51 72 61 73 8 24 50	329 40 51 72 61 73 8 20 45	430 40 51 72 61 73 8 20 53	40 51 72 61 73 8 20 53
	Loading Area [sq ft] Max. Interior Height [in] Cargo Volume (Behind Last Row of Seats) Front Overhang BA [in] Side Door Opening Width [in] Side Door Opening Height [in] Rear Door Opening Width [in] Rear Door Opening Height [in] Ground Clearance (running) [in] Wading Depth [in]	68 319 40 51 60 61 61 8	79 373 40 50 72 61 73 8	68 319 40 51 60 61 61 8 20	79 373 40 50 72 61 73 8	68 319 40 51 60 61 61 8	373 40 50 72 61 73 8	488 40 51 72 61 73 8 20	488 40 51 72 61 73 8	533 40 51 72 61 73 8	533 40 51 72 61 73 8	319 40 51 72 61 73 8 24	329 40 51 72 61 73 8	430 40 51 72 61 73 8 20	40 51 72 61 73 8 20

#### **Sprinter Cargo Van**

			2500 66:						2F00VD DDW		Cai	rgo		2500AD C**C;			41	00	
		144" HR	170" HR	170 Ext. HR	144" SR	144" ⊔D	144" CD 4v4	144" HR 4x4	170" HR	170" UD 4v4	170 Ev+ UD	170 Ext. HR 4x4	144" HR	170" HR	170 Ext. HR	144" SR	144" HR	170" HR	170 Ext. HR
	GVWR [lbs]	9,990	9,990	9,990	11,030	11,030	11,030	11,030	11,030	11,030	11,030	11.030	11,030	11,030	11,030	12,125	12,125	12,125	12,125
	GAWR. F (standard) [lbs]	3,330	3,330	3,330	11,030	11,030	11,030	11,030	11,030	11,030	11,030	11,030	11,030	11,030	11,030	12,123	12,123	12,123	12,123
	GAWR.F (with A50) [lbs]																		
	GAWR.R [lbs]																		
	Base Curb Weight Front [lbs]																		
	Base Curb Weight Rear [lbs]																		
	Base Curb Weight [lbs]																		
ses	Maximum Payload [lbs]									Gas eng	ine not availa	ble for these mod	els						
U	UVW [lbs]									Ĭ									
	Maximum Towing [lbs]																		
	Maximum Tongue Weight [lbs]																		
	GCWR [lbs]																		
	Load Height - Unloaded (Ground to Cargo Floor) [in]																		
	Load Height - Loaded (Ground to Cargo Floor) [in]																		
	GAWR.F (standard) [lbs]	4,081	4,081	4,081	4,081	4,081	4,409	4,409	4,081	4,409	4,081	4,409	4,081	4,081	4,081		A50 is standard	with this model	ls
	GAWR.F (with A50) [lbs]	4,409	4,409	4,409	4,409	4,409	N/A	N/A	4,409	N/A	4,409	N/A	4,409	4,409	4,409			/A	
2	GAWR.R [lbs]	7,059	7,059	7,059	7,721	7,721	7,721	7,721	7,721	7,721	7,721	7,721	7,721	7,721	7,721	7,934	7,934	7,934	7,934
(OM642)	Base Curb Weight Front [lbs]	2,338	2,555	2,783	2,352	2,386	2,427	2,455	2,657	2,738	2,831	2,979	2,338	2,498	2,783	2,362	2,410	2,551	2,847
o S	Base Curb Weight Rear [lbs]	2,975	3,122	3,015	2,994	3,037	3,217	3,255	3,119	3,347	3,067	3,227	2,975	3,179	3,015	3,006	3,068	3,247	3,084
Se	Base Curb Weight [lbs]	5,313	5,677	5,798	5,346	5,423	5,644	5,710	5,776	6,085	5,897	6,206	5,313	5,677	5,798	5,368	5,478	5,798	5,930
die	Maximum Payload [lbs]	4,677	4,313	4,192	5,684	5,607	5,386	5,320	5,254	4,945	5,133	4,824	5,717	5,353	5,232	6,757	6,647	6,327	6,195
er	UVW [lbs]	7,401	7,401	7,401	10,470	10,470	10,470	10,470	10,470	10,470	10,470	10,470	10,470	10,470	10,470	9,374	9,374	9,374	9,374
Iĕ	Maximum Towing [lbs]	7,500	7,500	5,000	7,500	7,500	7,500	7,500	7,500	7,500	5,000	5,000	7,500	7,500	5,000	7,500	7,500	7,500	7,500
Ş	Maximum Tongue Weight [lbs]	750	750	750	750	750	750	750	750	750	750	750	750	750	750	750	750	750	750
~	GCWR [lbs]	15,250	15,250	15,250	15,250	15,250	15,250	15,250	15,250	15,250	15,250	15,250	15,250	15,250	15,250	15,250	15,250	15,250	15,250
	Load Height - Unloaded (Ground to Cargo Floor) [in]	29	29	29	29	29	31	31	29	31	29	31	29	29	29	29	29	29	28
	Load Height - Loaded (Ground to Cargo Floor) [in]	25	25	25	25	25	25	25	25	25	25	25	25	25	25	24	29	25	25
	GAWR.F (standard) [lbs]	4,081 4,409	4,081	4,081	4,081	4,081			4,081		4,081		4,081	4,081	4,081 4,409	4,630	4,630	4,630 /A	4,630
	GAWR.F (with A50) [lbs]	,	4,409	4,409	4,409	4,409			4,409		4,409		4,409	4,409	,	7.024	7,934	7,934	7,934
(OM651)	GAWR.R [lbs]	7,059 2,314	7,059 2,586	7,059 2,757	7,721 2,371	7,721 2,416			7,721 2,632		7,721 2,863		7,721 2,314	7,721 2.586	7,721 2,757	7,934 2,391	2,426	7,934 2.584	7,934 2.644
₩ 9	Base Curb Weight Front [lbs] Base Curb Weight Rear [lbs]	2,314	3,036	2,757	2,898	2,416			3,089		2,863		2,314	3,036	2,757	2,391	2,426	3,159	3,231
9	Base Curb Weight [lbs]	5,258	5,622	5,743	5,269	5,368		5,721	Engine not	5,842	Engine not	5,258	5,622	5,743	5,313	5,390	5,743	5,875	
diesel (	Maximum Payload [lbs]	4,732	4,368	4,247	5,761	5,662	Engine not	available for	5,309	available for	5,188	available for this	5,772	5,408	5,287	6,812	6,735	6,382	6,250
	UVW [lbs]	7,401	7,401	7,401	10,470	10,470		10,470	this model	10,470	model	10,470	10,470	10,470	9,374	9,374	9,374	9,374	
der	Maximum Towing [lbs]	7,500	7,500	5,000	7,500	7,500				till illouer	5,000		7,500	7,500	5,000	7,500	7,500	7,500	7,500
🗦	Maximum Tongue Weight [lbs]	750	750	750	750	750		7,500 750		750		750	750	750	750	750	750	750	
4	GCWR [lbs]	15,250	15,250	15,250	15,250	15,250					15,250		15,250	15,250	15,250	15,250	15,250	15,250	15,250
	Load Height - Unloaded (Ground to Cargo Floor) [in]	29	29	29	29	29			29		29		29	29	29	29	29	29	28
	Load Height - Loaded (Ground to Cargo Floor) [in]	25	25	25	25	25			25	-	25	25	25	25	25	24	29	25	25
	Vehicle Length [in]	234	274	290	234	234	234	234	274	274	290	290	234	274	290	234	234	274	290
	Vehicle Height [in]	109	109	109	98	109	100	111	109	111	108	111	109	109	109	98	109	109	108
	Vehicle Width (w/out Mirrors) [in]	80	80	80	80	80	80	80	80	80	80	80	80	80	80	80	80	80	80
	Vehicle Width (with Mirrors) [in]	92	92	92	96	96	96	96	96	96	96	96	96	96	96	96	96	96	96
	Rear Overhang (Rear Axle to End of Frame) [in]	49	64	80	49	49	49	49	64	64	80	80	49	64	80	49	49	64	80
	Maximum Cargo Bed Length at Floor [in]	133	174	189	133	133	133	133	174	174	189	189	133	174	189	133	133	174	189
	Cargo Width at Wheelhouse [in]	48	48	48	39	39	39	39	39	39	39	39	48	48	48	39	39	39	39
	Max. Floor Width [in]	70	70	70	70	70	70	70	70	70	70	70	70	70	70	70	70	70	70
	Loading Area [sq ft]	53	72	80	51	51	51	51	70	70	78	78	53	72	80	51	51	70	78
nes	Max. Interior Height [in]	79	79	79	68	79	68	79	79	79	79	79	79	79	79	68	79	79	79
engir	Cargo Volume (Behind Last Row of Seats)	358	469	512	281	329	281	329	430	430	469	469	358	469	512	281	328	430	469
e e	Front Overhang BA [in]	40	40	40	40	40	40	40	40	40	40	40	40	40	40	40	40	40	40
10	Side Door Opening Width [in]	51 72	51 72	51 72	51 60	50 72	51 60	51 72	51 72	51 72	51 72	51 72	51 72	51 72	51 72	51 60	51 72	51 72	51 72
	Side Door Opening Height [in] Rear Door Opening Width [in]	61	61	61	61	61	61	61	61	61	61	61	61	61	61	61	61	61	61
	Rear Door Opening Width [in] Rear Door Opening Height [in]	73	73	73	61	73	61	73	73	73	73	73	73	73	73	61	73	73	73
	Ground Clearance (running) [in]	8	8	8	8	8	8	8	8	8	8	8	73	8	8	8	8	8	8
	Wading Depth [in]	20	20	20	20	20	24	24	20	24	20	24	20	20	20	20	20	20	20
	Turning Circle curb to curb [ft]	45	53	53	45	45	43	43	53	50	53	50	45	53	53	45	45	53	53
	Turning Circle wall to wall [ft]	48	55	55	48	48	46	46	55	53	55	53	48	55	55	48	48	55	55
	Tires and Load Ratings	3,197	3,197	3,197	2,679	2,679	2,679	2,679	2,679	2,679	2,679	2,679	3,197	3,197	3,197	2,679	2,679	2,679	2,679
	Rim	ET54	ET54	ET54			HMA 125,5		HMA 125,5		HMA 125,5	HMA 125,5	ET54	ET54	ET54	HMA 125,5	HMA 125,5	HMA 125,5	HMA 125,5
							,0											,5	

#### **Sprinter Crew Van**

							C					
				25	.00		Crew	_	3500 DRW		350	n susi
		144" SR	144" HR	144" SR 4x4	144" HR 4x4	170" HR	170" HR 4x4	144" SR	144" HR	170" HR	144" HR	170" HR
	GVWR [lbs]	9,050	9,050	9,050	9,050	9,050	9,050	9,990	9,990	9,990	9,990	9,990
	GAWR.F (standard) [lbs]	4,101	4,101			4,101						
	GAWR.F (with A50) [lbs]	4,409	4,409			4,409	1					
	GAWR.R [lbs]	5,359	5,359			5,359						
	Base Curb Weight Front [lbs]	2,232	2,322			2,539						
	Base Curb Weight Rear [lbs]	2,728	2,726			2,863						
	Base Curb Weight [lbs]	4,960	5,049	Gas engine not	Gas engine not	5,401						
Gas	Maximum Payload [lbs]	4,090	4,001	available for	available for	3,649		Gas	engine not availa	able for these mo	dels	
	UVW [lbs]	6,450	6,450	these models	these models	6,450						
	Maximum Towing [lbs]	5,000	5,000			5,000						
	Maximum Tongue Weight [lbs]	500	500			500						
	GCWR [lbs]	13,930	13,930			13,930						
	Load Height - Unloaded (Ground to Cargo Floor) [in]	27	27			27						
	Load Height - Loaded (Ground to Cargo Floor) [in]	23	23			23						
	GAWR.F (standard) [lbs]	4,101	4,101	4,409	4,409	4,101	4,409	4,081	4,081	4,081	4,081	4,081
	GAWR.F (with A50) [lbs]	4,409	4,409	N/A	N/A	4,409	N/A	4,409	4,409	4,409	4,409	4,409
2	GAWR.R [lbs]	5,359	5,359	5,359	5,359	5,359	5,359	7,059	7,059	7,059	7,059	7,059
diesel (OM642)	Base Curb Weight Front [lbs]	2,218	2,308	2,309	2,403	2,517	2,612	2,632	2,672	2,912	2,735	2,860
Ō	Base Curb Weight Rear [lbs]	3,062	3,060	3,323	3,318	3,204	3,462	3,089	3,137	3,283	2,963	3,225
se	Base Curb Weight [lbs]	5,280	5,368	5,633	5,721	5,721	6,074	5,721	5,809	6,195	5,699	6,085
	Maximum Payload [lbs]	3,770	3,682 7,401	3,417	3,329 7,401	3,329	2,976 7,401	4,269	4,181	3,795 7,401	4,291	3,905 7,401
cylinder	UVW [lbs] Maximum Towing [lbs]	7,401 5,000	5,000	7,401 5,000	5,000	7,401 5,000	5,000	7,401 7,500	7,401 7,500	7,401	7,401 7,500	7,401
€	Maximum Towing [lbs] Maximum Tongue Weight [lbs]	500	500	500	5,000	500	500	7,500	7,500	7,500	7,500	7,500
9	GCWR [lbs]	13,930	13,930	13,930	13,930	13,930	13,930	15,250	15,250	15,250	15,250	15,250
	Load Height - Unloaded (Ground to Cargo Floor) [in]	28	28	31	31	27	31	29	29	28	29	28
	Load Height - Condeded (Ground to Cargo Floor) [in]	23	23	27	27	23	27	23	23	23	23	23
	GAWR.F (standard) [lbs]	4,101	4,101	2, 2,		4,101		4,081	4,081	4,081	4,081	4,081
	GAWR.F (with A50) [lbs]	4,409	4,409			4,409		4,409	4,409	4,409	4,409	4,409
_	GAWR.R [lbs]	5,359	5,359			5,359		7,059	7,059	7,059	7,059	7,059
551	Base Curb Weight Front [lbs]	2,247	2,285			2,493		2,606	2,704	2,947	2,596	2,894
Ž	Base Curb Weight Rear [lbs]	2,978	3,028			3,173		3,060	3,050	3,193	3,048	3,135
	Base Curb Weight [lbs]	5,225	5,313			5,666	Engine not	5,666	5,754	6,140	5,644	6,030
diesel (OM651)	Maximum Payload [lbs]	3,825	3,737	Engine not av	ailable for this	3,384	available for this model	4,324	4,236	3,850	4,346	3,960
l a	UVW [lbs]	7,401	7,401	mo	aei	7,401		7,401	7,401	7,401	7,401	7,401
4-cylinder	Maximum Towing [lbs]	5,000	5,000			5,000		7,500	7,500	7,500	7,500	7,500
- - - - - - - - - - - - - -	Maximum Tongue Weight [lbs]	500	500			500		750	750	750	750	750
4	GCWR [lbs]	13,930	13,930			13,930		15,250	15,250	15,250	15,250	15,250
	Load Height - Unloaded (Ground to Cargo Floor) [in]	28	28			27		29	29	28	29	28
	Load Height - Loaded (Ground to Cargo Floor) [in]	23	23			23		23	23	23	23	23
	Vehicle Length [in]	234	234	234	234	274	274	234	234	274	234	274
	Vehicle Height [in]	96	108	100	111	107	111	96	109	109	109	109
	Vehicle Width (w/out Mirrors) [in]	80	80	80	80	80	80	80	80	80	80	80
	Vehicle Width (with Mirrors) [in]	92	92	92	92	92	92	96	96	96	96	96
	Rear Overhang (Rear Axle to End of Frame) [in]	49 104	49 104	49 104	49 104	64 144	64 144	49 104	49 104	64 144	49 104	64 144
	Maximum Cargo Bed Length at Floor [in]	104 53	104 53	104 53	104 53	53	53	104 39	104 39	39	104 48	144 48
	Cargo Width at Wheelhouse [in] Max. Floor Width [in]	70	70	70	70	70	70	70	70	70	70	70
	Max. Interior Height [in]	65	77	65	77	77	77	65	77	77	77	77
es	Cargo Volume (Behind Last Row of Seats) [ft³]	223	262	223	262	371	371	223	261	371	261	371
engines	Front Overhang BA [in]	40	40	40	40	40	40	40	40	40	40	40
l e	Side Door Opening Width [in]	51	51	51	51	51	51	51	51	51	51	51
Ф	Side Door Opening Width [in]	60	72	60	72	72	72	60	72	72	72	72
	Rear Door Opening Width [in]	61	61	61	61	61	61	61	61	61	61	61
	Rear Door Opening Height [in]	61	73	61	73	73	73	61	73	73	73	73
	Ground Clearance (running) [in]	8	8	8	8	8	8	8	8	8	8	8
	Wading Depth [in]	20	20	24	24	20	24	20	20	20	20	20
	Turning Circle curb to curb [ft]	41	41	43	43	47	50	45	45	52	45	52
	Turning Circle wall to wall [ft]	44	44	46	46	50	53	48	48	55	48	55
	Tires and Load Ratings	3,086	3,087	3,088	3,089	3,090	3,091	2,679	2,679	2,679	3,197	3,197
	Rim	ET54	ET55	ET56	ET57	ET58	ET59	HMA 125,5	HMA 125,6	HMA 125,7	ET54	ET54

#### **Sprinter Crew Van**

							Crew							
		3500XD DRW			3500XD SuSi				4500					
		144" SR	144" HR	144" SR 4x4	144" HR 4x4	170" HR	170" HR 4x4	144" HR	170" HR	144" SR	144" HR	170" HR		
	GVWR [lbs]	11,030	11,030	11,030	11,030	11,030	11,030	11,030	11,030	12,125	12,125	12,125		
	GAWR.F (standard) [lbs]													
1	GAWR.F (with A50) [lbs]													
1	GAWR.R [lbs]													
1	Base Curb Weight Front [lbs]													
1	Base Curb Weight Rear [lbs]													
	Base Curb Weight [lbs]													
Gas	Maximum Payload [lbs]					Gas ei	ngine not availab	ole for these mod	els					
1	UVW [lbs]													
1	Maximum Towing [lbs]													
1	Maximum Tongue Weight [lbs]													
	GCWR [lbs]													
	Load Height - Unloaded (Ground to Cargo Floor) [in]													
	Load Height - Loaded (Ground to Cargo Floor) [in]	4,081	4,081	4,409	4,409	4,081	4,409	4,081	4,081	4,630	4,630	4,630		
	GAWR.F (standard) [lbs]									4,630	4,630 N/A	4,630		
	GAWR.F (with A50) [lbs] GAWR.R [lbs]	4,409 7,721	4,409 7,721	N/A 7,721	N/A 7,721	4,409 7,721	N/A 7,721	4,409 7,721	4,409 7,721	7,934	7,934	7,934		
62	Base Curb Weight Front [lbs]	2,627	2,667	2,713	2,753	2,906	2,992	2,616	2,855	2,642	2,682	2,922		
(OM642)	Base Curb Weight Rear [Ibs]	3,083	3,131	3,316	3,365	3,278	3,512	3,071	3,219	3,101	3,149	3,295		
은	Base Curb Weight [lbs]	5,710	5,798	6,030	6,118	6,184	6,504	5,688	6,074	5,743	5,831	6,217		
ese	Maximum Payload [lbs]	5,320	5,232	5,000	4,912	4,846	4,526	5,342	4,956	6,382	6,294	5,908		
Ē	UVW [lbs]	10,470	10,470	10,470	10,470	10,470	10,470	10,470	10,470	9,374	9,374	9,374		
cylinde	Maximum Towing [lbs]	7,500	7,500	7,500	7,500	7,500	7,500	7,500	7,500	7,500	7,500	7,500		
ह	Maximum Tongue Weight [lbs]	750	750	750	750	750	750	750	750	750	750	750		
ن ق	GCWR [lbs]	15,250	15,250	15,250	15,250	15,250	15,250	15,250	15,250	15,250	15,250	15,250		
	Load Height - Unloaded (Ground to Cargo Floor) [in]	29	29	31	31	29	30	29	29	29	29	29		
	Load Height - Loaded (Ground to Cargo Floor) [in]	25	25	25	25	25	25	25	25	24	24	25		
	GAWR.F (standard) [lbs]	4,081	4,081			4,081		4,081	4,081	4,630	4,630	4,630		
	GAWR.F (with A50) [lbs]	4,409	4,409			4,409		4,409	4,409		N/A			
_	GAWR.R [lbs]	7,721	7,721			7,721	Engine not available for this model	7,721	7,721	7,934	7,934	7,934		
(OM651)	Base Curb Weight Front [lbs]	2,601	2,699			2,942		2,596	2,894	2,673	2,715	2,958		
≥	Base Curb Weight Rear [lbs]	3,054	3,044			3,187		3,048	3,135	3,015	3,061	3,204		
= =	Base Curb Weight [lbs]	5,655	5,743	Engine not au	ailable for this	6,129		5,644	6,030	5,688	5,776	6,162		
diesel	Maximum Payload [lbs]	5,375	5,287		odel	4,901		5,386	5,000	6,437	6,349	5,964		
	UVW [lbs]	10,470	10,470		Juei	10,470		10,470	10,470	9,374	9,374	9,374		
cylinde	Maximum Towing [lbs]	7,500	7,500			7,500		7,500	7,500	7,500	7,500	7,500		
<b>→</b>	Maximum Tongue Weight [lbs]	750	750			750		750	750	750	750	750		
4	GCWR [lbs]	15,250	15,250			15,250		15,250	15,250	15,250	15,250	15,250		
	Load Height - Unloaded (Ground to Cargo Floor) [in]	29	29			29		29	29	29	29	29		
	Load Height - Loaded (Ground to Cargo Floor) [in]	25	25			25		25	25	24	24	25		
	Vehicle Length [in]	234	234	234	234	274	274	234	274	234	234	274		
	Vehicle Height [in]	98	109	100	111	109	111	109	109	98	109	109		
	Vehicle Width (w/out Mirrors) [in]	80	80	80	80	80	80	80	80	80	80	80		
	Vehicle Width (with Mirrors) [in]	96	96	96	96	96	96	96	96	96	96	96		
	Rear Overhang (Rear Axle to End of Frame) [in]	49	49	49	49	64	64	49	64	49	49	64		
	Maximum Cargo Bed Length at Floor [in]	104	104	104	104	144	144	104	144	104	104	144		
	Cargo Width at Wheelhouse [in]  Max. Floor Width [in]	39 70	39 70	39 70	39 70	39 70	39 70	48 70	48 70	39 70	39 70	39 70		
	Max. Floor Width [in] Max. Interior Height [in]	65	70	65	70	70	70	70	70	65	70	70		
es	Cargo Volume (Behind Last Row of Seats) [ft³]	261	370	261	261	371	371	261	371	223	261	371		
engines		40	40	40	40	40	40	40	40	40	40	40		
		40		51	51	51	51	51	51	51	51	51		
e	Front Overhang BA [in] Side Door Opening Width [in]	51			J1	JI						72		
all en	Side Door Opening Width [in]	51 60	51 72		72	72	72	72	1 77	60	72			
aller	Side Door Opening Width [in] Side Door Opening Height [in]	60	72	60	72 61	72 61	72 61	72 61	72 61	60 61	72 61			
all er	Side Door Opening Width [in] Side Door Opening Height [in] Rear Door Opening Width [in]	60 61	72 61	60 61	61	61	61	61	61	61	61	61		
aller	Side Door Opening Width [in] Side Door Opening Height [in] Rear Door Opening Width [in] Rear Door Opening Height [in]	60	72	60	61 73			61 73			61 73			
aller	Side Door Opening Width [in] Side Door Opening Height [in] Rear Door Opening Width [in] Rear Door Opening Height [in] Ground Clearance (running) [in]	60 61 61	72 61 73	60 61 61	61	61 73	61 73	61	61 73	61 61	61	61 73		
allen	Side Door Opening Width [in] Side Door Opening Height [in] Rear Door Opening Width [in] Rear Door Opening Width [in] Rear Door Opening Height [in] Ground Clearance (running) [in] Wading Depth [in]	60 61 61 8 20	72 61 73 8 20	60 61 61 8 24	61 73 8 24	61 73 8 20	61 73 8 24	61 73 8 20	61 73 8 20	61 61 8 20	61 73 8 20	61 73 8 20		
all en	Side Door Opening Width [in] Side Door Opening Height [in] Rear Door Opening Width [in] Rear Door Opening Width [in] Rear Door Opening Height [in] Ground Clearance (running) [in] Wading Depth [in] Turning Circle curb to curb [ft]	60 61 61 8	72 61 73 8	60 61 61 8	61 73 8 24 43	61 73 8	61 73 8	61 73 8	61 73 8	61 61 8 20 45	61 73 8	61 73 8		
allen	Side Door Opening Width [in] Side Door Opening Height [in] Rear Door Opening Width [in] Rear Door Opening Width [in] Rear Door Opening Height [in] Ground Clearance (running) [in] Wading Depth [in]	60 61 61 8 20 45	72 61 73 8 20 45	60 61 61 8 24 43	61 73 8 24	61 73 8 20 53	61 73 8 24 50	61 73 8 20 45	61 73 8 20 53	61 61 8 20	61 73 8 20 45	61 73 8 20 53		

## **Sprinter Passenger Van**

				Passe	nger						
		1500			2500						
		144" SR (12-seater)	144 SR (12-seater)	144" SR 4x4 (12-seater)	144" HR (12-seater)	144" HR 4x4 (12-seater)	170" HR (15-seater)				
	GVWR [lbs]	8,550	9,050	9,050	9,050	9,050	9,050				
	GAWR.F (standard) [lbs]	1,860	1,860	,	<u> </u>	<u> </u>					
	GAWR.F (with A50) [lbs]	2,000	2,000								
	GAWR.R [lbs]	2,431	2,431								
	Base Curb Weight Front [lbs]	2,679	2,679								
	Base Curb Weight Rear [lbs]	2,788	2,788								
	Base Curb Weight [lbs]	5,467	5,467								
Gas	Maximum Payload [lbs]	3,082	3,583		Gas engine not availa	able for these models					
	UVW [lbs]	3,152	2,926								
	Maximum Towing [lbs]	5,000	5,000								
	Maximum Tongue Weight [lbs]	500	500								
	GCWR [lbs]		13,550 13,930								
	Load Height - Unloaded (Ground to Cargo Floor) [in]	27	27								
	Load Height - Loaded (Ground to Cargo Floor) [in]	24	24								
	GAWR.F (standard) [lbs]		1,860	2,000	1,860	2,000	1,860				
	GAWR.F (with A50) [lbs]		2,000	N/A	2,000	N/A	2,000				
42)	GAWR.R [lbs]	-	2,431	2,431	2,431	2,431	2,431				
diesel (OM642)	Base Curb Weight Front [lbs]		2,667 3,131	2,738 3,347	2,649	2,778	2,892				
0	Base Curb Weight Rear [lbs] Base Curb Weight [lbs]		3,131 5,798	6,085	3,237 5,886	3,395 6,173	3,535 6,426				
ese	Maximum Payload [lbs]		3,252	2,965	3,164	2,877	3,053				
	UVW [lbs]		3,357	3,357	3,357	3,357	3,357				
ge	Maximum Towing [lbs]		5,000	5.000	5.000	5,000	N/A				
6-cylinder	Maximum Tongue Weight [lbs]		500	500	500	500	N/A				
	GCWR [lbs]	-	13,930	13,930	13,930	13,930	9,480				
	Load Height - Unloaded (Ground to Cargo Floor) [in]		27	31	27	31	27				
	Load Height - Loaded (Ground to Cargo Floor) [in]	Diesel engines not	24	27	24	27	24				
	GAWR.F (standard) [lbs]	available for these	1,860		1,860		1,860				
	GAWR.F (with A50) [lbs]	models	2,000		2,000		2,000				
~	GAWR.R [lbs]		2,431		2,431	1	2,431				
4-cylinder diesel (OM651)	Base Curb Weight Front [lbs]		2,699	Engine not available for this model	2,741		3,122				
Σ	Base Curb Weight Rear [lbs]		3,044		3,091		3,249				
e (	Base Curb Weight [lbs]		5,743		5,831	Engine not available for this model	6,371				
lies	Maximum Payload [lbs]		3,307		3,219		3,109				
er	UVW [lbs]		3,357	tilis illouei	3,357		3,357				
ind	Maximum Towing [lbs]		5,000		5,000		0				
ζ	Maximum Tongue Weight [lbs]		500		500		N/A				
4	GCWR [lbs]		13,930		13,930		9,480				
	Load Height - Unloaded (Ground to Cargo Floor) [in]		27		27		27				
	Load Height - Loaded (Ground to Cargo Floor) [in]		24		24		24				
	Vehicle Length [in]	234	234	234	234	234	274				
	Vehicle Height [in]	TBD	0	0	114	118	114				
	Vehicle Width (w/out Mirrors) [in]	80	80	80	80	80	80				
	Vehicle Width (with Mirrors) [in] Rear Overhang (Rear Axle to End of Frame) [in]	92 49	92 49	92	92 49	92 49	92 64				
		36	36	49 36	36	36	48				
	Maximum Cargo Bed Length at Floor [in] Cargo Width at Wheelhouse [in]	53	53	53	53	53	53				
	Max. Floor Width [in]	70	70	70	70	70	70				
	Max. Interior Height [in]	64	64	64	76	76	76				
Sec	Cargo Volume (Behind Last Row of Seats) [ft³]	79	79	79	79	79	111				
engines	Front Overhang BA [in]	40	40	40	40	40	40				
e	Side Door Opening Width [in]	51	51	51	51	51	51				
В	Side Door Opening Width [in]	59	59	60	71	71	71				
	Rear Door Opening Width [in]	61	61	61	61	61	61				
	Rear Door Opening Height [in]	60	60	60	72	72	72				
	Ground Clearance (running) [in]	20	20	20	20	20	20				
	Wading Depth [in]	50	50	61	50	61	50				
	Turning Circle curb to curb [ft]	41	41	43	41	43	47				
	Turning Circle wall to wall [ft]	44	44	46	44	46	50				
	Tires and Load Ratings Rim	3,086 ET54	3,086 ET56	3,197 ET54	3,197 ET54	3,197 ET54	3,197 ET54				

## **Sprinter Cab Chassis**

				Cab Cl	nassis		
		3500	XD DRW	3500>	(D SuSi	45	500
		144"	170"	144"	170"	144"	170"
	GVWR [lbs]	11,030	11,030	11,030	11,030	12,125	12,125
	GAWR.F (standard) [lbs]	4,081	4,081	4,081	4,081	4,630	4,630
_	GAWR.F (with A50) [lbs]	4,409	4,409	4,409	4,409	4,630	4,630
642	GAWR.R [lbs]	7,721	7,721	7,721	7,721	7,934	7,934
6-cylinder diesel (OM642)	Base Curb Weight Front [lbs]	1,628	1,659	1,597	1,628	1,636	1,667
	Base Curb Weight Rear [lbs]	3,024	3,081	2,966	3,024	3,038	3,095
ies	Base Curb Weight [lbs]	4,652	4,740	4,564	4,652	4,674	4,762
p .	Maximum Payload [lbs]	6,378	6,290	6,466	6,378	7,451	7,363
ng	UVW [lbs]	10,470	10,470	10,470	10,470	9,374	9,374
5	Maximum Towing [lbs]	7,500	7,500	7,500	7,500	7,500	7,500
٥	Maximum Tongue Weight [lbs]	750	750	750	750	750	750
	GCWR [lbs]	15,249	15,249	15,249	15,249	15,249	15,249
	GAWR.F (standard) [lbs]	4,081	4,081	4,081	4,081	4,630	4,630
_	GAWR.F (with A50) [lbs]	4,409	4,409	4,409	4,409	N.	/A
551	GAWR.R [lbs]	7,721	7,721	7,721	7,721	7,934	7,934
Ž	Base Curb Weight Front [lbs]	1,655	1,687	1,623	1,655	1,663	1,694
	Base Curb Weight Rear [lbs]	2,942	2,998	2,885	2,942	2,956	3,012
iese	Base Curb Weight [lbs]	4,597	4,685	4,508	4,597	4,619	4,707
r d	Maximum Payload [lbs]	6,433	6,345	6,522	6,433	7,506	7,418
4-cylinder diesel (OM651)	UVW [lbs]	10,470	10,470	10,470	10,470	9,374	9,374
-S	Maximum Towing [lbs]	7,500	7,500	7,500	7,500	7,500	7,500
4	Maximum Tongue Weight [lbs]	750	750	750	750	750	750
	GCWR [lbs]	15,249	15,249	15,249	15,249	15,249	15,249
	Vehicle Length [in]	246	273	246	273	246	273
	Vehicle Height [in]	94	94	94	94	94	94
	Vehicle Width (w/out Mirrors) [in]	80	80	80	80	80	80
	Vehicle Width (with Mirrors) [in]	96	96	96	96	96	96
	Rear Overhang (Rear Axle to End of Frame) [in]	61	63	61	63	61	63
	Wading Depth [in]	20	20	20	20	20	20
	Cab Length [in]	99	99	99	99	99	99
Sec	Frame Width [in]	44	44	44	44	44	44
engines	Frame Height normal [in]	32	32	33	32	32	32
P e	Frame Height loaded [in]	27	27	27	27	27	27
both	Top of Frame to Top of Cab [in]	64	64	64	64	64	64
	Tire Track Front [in]	66	66	67	67	66	66
	Tire Track Rear [in]	61	61	65	65	61	61
	Ground Clearance (running) [in]	8	8	8	8	8	8
	Turning Circle curb to curb [ft]	45	53	45	53	45	53
	Turning Circle wall to wall [ft]	48	55	48	55	48	55
	Tires and Load Ratings	2,678.6	2,678.6	3,196.7	3,196.7	2,678.6	2,678.6
	Rim	HMA 125,5	HMA 125,5	ET54	ET54	HMA 125,5	HMA 125,5





# MY22 Equipment Book

The Sprinter - US Version



©2022 Mercedes-Benz USA, LLC

## **MY22 Equipment Book - Important Considerations**

- Please note that not all codes in this equipment book are necessarily offered for sale in MY22. For details on the latest offered product portfolio and options, please see the DOG or NetStar.
- This equipment book does not contain package code designations (CO2, CO3 etc.) but rather package code components. When referencing from the MY22 Dealer Ordering Guide, please identify the individual option code in a package, which is explained in the equipment book.
- For a better understanding of the various suspension options and features offered on the Sprinter, please reference the 'Suspension Matrix' in the MY22 Dealer Ordering Guide.

A50	10	D03	18
Front Axle Reinforced	10	High Roof	
AP2	10	D13	19
Protective U-bar for driveshaft/exhaust		Mounting Rails for Roof Rack	19
extension	10	D17	
AR2	10	Interior Roof-Rack	19
Axle Ratio 3.923	10	D22	20
AR3	11	Fixed Sunroof (Rear Roof Section)	20
Axle Ratio 4.182		D50	
B01		Cargo Partition	
ESP for increased Center of Gravity above		D51	
39.4"		Cargo Partition with 1 Window	
B25		D64	
Electric Parking Brake		Bulkhead with sliding door	
BA3		D93	
Active Brake Assist		Omission Bulkhead	
BA9		E07	
Pre-Installation for Rail Vehicle / Vehicle v		Hill Start Assist	
Inter-Axle Lock		E1B	
BE2		Tray for Smartphones incl. Wireless	∠∠
			22
Handbrake Lever, Folding BH1		Charging E1E	
Hold Function			
		Navigation	
C6L		E10	
Multifunction Steering Wheel		Standard Radio	
C72		E1S	
Bumpers Front/Rear Primed		Sirius XM, Satellite Radio	
CB1	15	E1R	
Suspension for Comfort and Load	4.5	Additional Fuses (40/80/150/100 Amps)	
Protection		E1U	
CB7		USB-C Socket, 5V	
Stabilization Level I		E1X	
CB8		MBUX multimedia 6-hour runtime	
Stabilization Level II		E1Y	
CB4		Additional Fuses (40/80/80/100 Amps)	
Stabilization Level III		E2A	28
CE8		Access Point for BB Special Signals in	
Raised Rear Body Mounts		Cockpit	
CL1		E2I	29
Adjustable Steering Wheel (Angle)		Additional battery for retrofit consumers,	
CL3		driver seat base	
Leather Steering Wheel	16	E2M	29
CM0		Additional battery for retrofit consumers,	
Painted Metallic Front & Rear Bumper	17	engine Compartment	
CM2	17	E30	29
Bumpers/Detachable Body Parts Painted		Starter battery disconnect	29
Body Color	17	E36	30
CM9	17	Cutoff relay for additional battery	30
Primed Side Moldings	17	E3J	30
CN2		Pre-Installation for switch panel	30
Radiator Grille Frame in Vehicle Color	18	E3M	31
CT1	18	MBUX Multimedia System with 7"	
Rear Spring Vibration Absorbers	18	Touchscreen	31

E40	32	F28	43
Trailer Hitch Prep. Wiring	32	Roof and Rear Wall Deletion	43
E46	32	F35	44
12 V Power Outlet, Driver Seat Base	32	Window in Cab Rear Wall	44
E4A		F3W	44
Antenna Interface for Radio, Navi., Mobil	le	Omission of Storage	
Phone		F43	
E4M		Laminated Glass Rear	
MBUX Multimedia System with 10.25"		F49	
Touchscreen	33	Electrically Heated Windshield	
E5M		F50	
Extension of PSM Standard Contact		Cowl platform	
EA5		F61	
Pre-wiring central locking (upfitter doors		Interior Rear View Mirror	
rear)		F64	
ED1		Electrically Folding Exterior Mirrors	
AGM Battery 12V 70AH		F68	
ED3		Heated and Electrically Adjustable Exterio	
Antenna for Mobile Phone		Mirrors	
ED4		FA1	
		Lowered Cab Roof	
AGM Battery 12 V 92 Ah 850A			
ED5		FE9Additional DIN-Slot	
Parametric Special Module (PSM)			
ED8		FF0	
Pre-Installation PSM		Coat Hooks	
EE3		FF3	
115 V Socket		Cupholder Rear Compartment	
EE5		FF4	
Super-capacitor discharge module		Storage Compartment above Cabin	
EK1		FF5	
Body Builder Connector		Shelf above Windshield	
EL9		FF8	
Audio Systems Speakers, 5 Front, 8 Rea		Overhead Storage Slot, Front Center	
EP7	39	FG8	
Basic Electric Fitting for Rear		Cupholder Front	49
Loudspeakers	39	FJ1	
ER0	39	Hinged Lid for Storage Compartment	49
Pre-Installation for Radio	39	FJ4	50
ES0	40	Storage compartment underneath cockpit	t 50
Jump Start Terminal	40	FJ5	50
ES2		Hinged lid for storage compartments left a	and
12 V Power Outlet, Rear Compartment	40	right	
ES5		FJ6	
Charging Package, Dashboard		Central Area with 2 DIN Storage Comp. + A	Air
ET4		Vents	
Active Distance Assist DISTRONIC		FJ7	
EX9		Central Area with Storage Compartment	
Free Map Data Updates for 3 Years		FK3	
EW6		Chrome Plated Radiator Grille	
Pre-installation for Mercedes me remote		FM3	
services		Wet Wiper System	
EY2		FQ6	
			טו
Intelligent navigation F1K		Lockable Storage Compartment above	<b>5</b> 1
		Windshield	
Coat Hooks in Driver Cabin	43	FR3	52

Rear View Camera (Rear-View Mirror	H22	
Display)52	Rear Window Defroster	
FR752	H72	62
Pre-Wiring Rear View Camera (Head Unit	Roof Fan, Electric	62
Display)52	H88	63
FR852	Rear Heater Prep	63
Rear View Camera (Head Unit Display)52	H91	63
FS153	Deletion Air Conditioning System	63
Mirror Holder for Vehicle Width 2150 up to	HH2	63
2300mm53	Heater, Auxiliary Electric Hot Air	63
FS253	HH4	64
FU553	Thermotronic automatic climate control	64
Exterior Mirror without Indicator53	HH9	64
FV154	Air Condition, Front	64
Pre-Wiring Rear View Camera (Rear-View	HK4	
Mirror Display)54	Rear Air Conditioner Heavy-Duty	65
FW154	HY1	
Rear Wall Deletion - Chassis Cab54	Remote control for auxiliary heater	65
FW854	HZ9	
Deletion of passenger cab door, right54	Fuel-Fired Heater Booster (18,800 BTU)	
FW954	J11	
Deletion of driver's cab door, left54	Speedometer, miles/km	
FX454	J1V	
Omit ASR-Off Function54	Pre-installation blind spot assist	
FY155	J51	67
Security Alarm w. Interior Motion Sensor55	Fuel Gauge, Optimized for Aux. Fuel Tap	
FY755	J52	
Optional 3- Button Keys55	Engine Oil Level Display at Cold Start	
FZ955	J55	
Keys, Two Additional Masters55	Seat belt warning for passenger seat	
G4256	J58	
Automatic Transmission, 7G-TRONIC PLUS.56	Seat belt reminder, driver	
G4357	J65	
Automatic Transmission, 9G-TRONIC57	Outside temperature gauge	
H0058	JA7	
Warm/Cool Air Duct to Rear	Blind spot assist	
Compartment58	JA8	
H0159	Crosswind assist	
Heat Insulation, Rear Compartment59	JA9	
H0459	Traffic sign assist	
Heat Insulation, Front Compartment59	JB4	
H0859	Active lane keeping assist	
Air Conditioning Rear, Roof-Mounted59	JB6	
H1260	Parking package with 360 degree camera	
Fuel-Fired Pre-Heater/Booster (17K BTU)60	JB7	
H1360		
Rear Cabin Heater and Vents60	Parking package	
	JB8	
H15/ H1661	360 degree camera	
Heated Front Passenger/Driver Seat61	JF1	
H1I61	Rain sensor	
Front-to-Rear Outlet in Instrument Panel61	JH3	/ 3
H2061	Communication module (LTE) for dig.	7.0
Heat-Insulating Glass61	services	
H2161	JK5	
Windshield with Filter Band61	Instrument cluster with color display	73

JW0	74	3rd Brake Light	83
Backup alarm	74	LB9	
JW2	74	Illuminated front exits	83
Deactivation lamp monitoring failure	74	LC2	83
JW8		Led light strip in load compartment	83
Attention assist		LC4	
K51		Comfort overhead control panel	
Misfiling prevention for diesel		LG7	
K52		Led high performance headlamps	
Def fluid filler cap - lockable		LV6	
K56		Third brake light pre-wiring	
Red diesel filler cap		LV7	
K60		Clearance lights pre-wiring	
Exhaust straight to rear		M20	
KB7		Speed limitation 65 mph	
24.5 gallon fuel tank		M24	
KL1		Starter upgraded	
Aux fuel sending unit w/ fuel tap		M46	
KL5	77	Alternator 14 V / 220 A	
Fuel filter with water separator		M60	85
L13	77	Alternator 14 V / 250 A	85
Fog lamp with cornering light function	77	MD3	86
L1D		Top speed limitation 75 mph	86
Overhead control panel w/bus interior		MG3	
lighting control	78	2.0L I4 turbo diesel with 7-speed	
L22		transmission	86
LED tail lights		MG5	
L44		3.0L V6 turbo diesel with 7-Speed	07
Flashing lights, front left		Transmission	87
L49		MH8	
		SULEV Emissions	
Identification Lamps			
L65		MIO	
Interior lights, cargo compartment		ULEV Emission	
L71		MM3	
Light/motion sensor in rear compartm		2.0L 4-cylinder turbo gasoline with 9-Sp	
L72	80	Transmission	
Electrical pre-installation for load		MS1	
compartment lighting		Cruise control	-
L76		N62	90
Wire harness tail lamp w/ extended wi		Front engine bracket for additional	
L77		alternator	90
Wiring for additional turn signals	80	N63	91
L90		Front engine bracket for auxiliary A/C	
Tail lamp deletion, non-LED	80	compressor	91
L91		P08	
Tail lamp deletion, LED	81	Cover for transport	91
L94		P47	
Parking lights deletion		Front mudflaps	
LA1		P48	
High beam assist		Rear mud flaps	
LA2		P93	
Headlight assistant		Omission of D-rings	
Light capacities vehicles with alcove		Q11	
Light sensor for vehicles with alcove		Longitudinal member reinforcement	
LB5	83	Q18	93

End Cross Member Bolted Q24		Tire pressure monitoring lamp	
Trailer Hitch, 5,000 lbs		Standard front driver/passenger seat	
Q67		S20	
Tow hook rear			
Q72		Passenger seat foldable incl front airbags	
		(SA6 + SH2) S22	
Deletion of end cross member			
QA2		Armrest for driver's seat	
Trailer cross member 7,500 lbs capacity		\$23	
QA9		Twin front passenger seat	
Half-sided step rear (for trailer hitch)		S25	
R60	94	Armrest for front passenger seat	
Provisional spare wheel bracket frame		\$28	
mounted		Armrest, driver's and passenger door	
R65		\$31	. 101
Spare wheel bracket below frame		Convenience head restraints for pass.	
R87		comp	
Spare wheel		S62	. 101
R91	95	Seat belts orange, driver and front	
Spare wheel deletion	95	passenger	
R92	95	S87	. 102
Spare tire carrier deletion	95	Driver's seat frame, low	. 102
R98	95	\$88	. 102
Rims painted jet black	95	Passenger seat frame, low	. 102
R9A	96	S91	. 102
285/65 R 16 C Super-Single-Tires	96	Passenger seat discontinued	. 102
RD9		S99	
Unspecified tire brand	96	Passenger seat pedestal - deletion	. 102
RF1		SA5	
Tire brand Continental		Airbag, driver front	
RF8		SA6	
Tire brand Michelin		Front airbag, passenger	
RH0		SB1	
Tire brand Kumho		Comfort driver's seat	
RH7		SB2	
	96	Comfort passenger seat	
RH8		SB3	
Tires LT 245/75 R16		Driver Suspension Seat, Comfort Version	
RL5		SB4	
Light alloy wheels 6.5 J x 16		Passenger suspension seat, comfort	. 103
RM0		version	105
All-Season tires			
		SB9	
RM1		Driver's seat plus	
M+S Winter tires		SE4/ SE5	
RM2		Lumbar support, driver + passenger seat	
Rims painted Arctic White		SF1	
RM9		Driver's seat electrically adjustable	
Specially requested tires		SF2	
RS3		Passenger seat electrically adjustable	
6.5 J x 16 Steel Wheels		SH1	
RS5		Thorax-pelvis sidebag, driver	
Steel Wheels: 8.5Jx16 Rr; 6.5Jx16 Fr	98	SH2	. 107
RS6		Thorax-pelvis sidebag, passenger	. 107
5.5 J x 16 Steel Wheels	99	SH9	. 107
RY2	99	Airbag, driver/passenger window	. 107
		·	

SJ3 108	Three seater bench in passenger
Omission of windowbag, co-driver 108	compartment, first row (narrow) 114
SK0/ SK1108	U74114
Comfort head restraint, front	Wall-side arm rest114
driver/passenger108	U75115
SK2 108	Aisle-side arm rest 115
Seat occupancy sensor driver seat 108	UC3 115
SR8/ SR9108	Three-seater bench in passenger
Swivel base for driver's + passenger seat 108	compartment, second row (narrow) 115
SW1109	UD6115
Seat belt deletion, passenger 109	Four-seater bench in passenger
SZ7109	compartment, third row115
Storage net, driver's seat backrest 109	UD7115
SZ8109	Four-seater bench in passenger
Storage net, passenger seat backrest 109	compartment, fourth row115
T12	UY1116
Sliding door two stage opening 109	Three-seater comfort bench in passenger
T16110	compartment, first row (narrow)
Sliding door, passenger side	UY2116
T19110	Three-seater comfort bench in passenger
Sliding door, driver's side	compartment, second row (narrow) 116
T50	UY3116
Electric closing assist right sliding door (soft	
	Four-seater comfort bench in passenger
close)	compartment, third row116
T51	UY6116
Electric closing assist left sliding door (soft	Four-seater comfort bench in passenger
close)	compartment, fourth row116
T55	V07117
Electrical sliding door right	Cab rear wall liner
T57	V21117
Electric sliding step	Luxury interior trim
T60	V24118
Opening limiter, electrically operated sliding	Pallet support in sliding door step
door 112	V25118
T74	Half height load compartment trim 118
Assist handle, B-pillar 112	V31118
T75112	Window pillar trim
Door-mounted assist handles, driver &	V35119
passenger	Wheel house covering119
T77 112	V36119
Assist handle w/ partition 112	Roof trim 119
T85113	V39119
Assist handle, left rear door 113	Weight optimized plastic floor119
T86113	V40120
Assist handles, right rear door 113	Floor anchors for rear seat bench 120
T93 113	V42120
Sliding door right side deletion 113	Lashing rails, waist-level120
U1A113	V43120
14+1 seater version 113	Wood floor with 6 D-rings120
U3\$114	V4A121
U3Y 114	Full paneling, right sliding door 121
Three-seater comfort bench in passenger	V52121
compartment third row (narrow) 114	Loadable wheel arch121
U62 114	V85121
	Cigarette lighter + ash cup, front 121
	- 0

V94	122	W75	. 129
Cable duct - side wall	122	Step, wide, at rear end	. 129
V95	122	W76	
Cable duct - rear portal		Bumper step, rear, spring-loaded	. 130
VA1		W78	
Side wall paneling waist height pvc		Heated rear window(s) w/washers &	
VA3		wipers	130
Side wall paneling full hardboard		W93	
VA5		Side window openings w/o glass	
Full paneling, hinged rear doors		W94	
VA7		Window openings w/o glass	
Storage compart. W/ net in rear doors		X90	
VC4			
		Deletion of sprinter badge, left rear door.	
Cargo lashing rails, head height		X93	
VC5	124	Deletion of model badge, right rear door	
Door Sill - protective edge		XC8	
VF4		VIN visible from outside	
Fabric caluma black		XM4	
VF6		Acoustic package	
Artico man-made leather, black	124	XO5	. 132
VF7	124	Digital owner's manual	. 132
Fabric maturin black	124	XW6	. 132
VK8		Front license plate deletion	. 132
Floor covering, plastic		Y10	
VV2		First-Aid Kit	
Lashing rails, floor-level (plus 4 anchors		Y26	
VV4		Wheel chocks	
Additional ground weld studs		Y43	
W02		Jack, Hydraulic	
Panel Van w/Windows All Round		Y45	
W16		Emergency flashlight	
2 <sup>nd</sup> row, fixed window, driver side		Y68	
W17		Paint preservative	
2 <sup>nd</sup> row, fixed window, passenger side		Y69	
W22		Surface protection for stock vehicle	
Fixed window, center left		Y90	
W23		Jack deleted	. 134
Fixed window, center right	127	YK3	
W27	127	Cargo straps, D-rings	. 134
Fixed window, rear left	127	YK4	. 134
W28	127	Cargo straps, lashing rails	. 134
Fixed window, rear right	127	Z5U	
W33		Vehicle class, incomplete vehicle (49 CFF	
FMVSS 217 Emergency Exit		571.3)	
W54		ZE6	
Rear doors, opening to side wall		Shelving prep	
W5F		ZG3	
90 degree fixation point- rear doors		4x4 - high range t-case w/ low gear	
W61		ZH4	
Windows in rear doors		Downhill speed regulation for 4x4	
W70		ZZ4	. 137
Black tinting (90%) for rear windows		Brand content Mercedes-Benz, North	
W73		America	. 137
Bumper step, rear, grey	129		

A50	A50 Front Axle Reinforced	Compared to Sprinter 906		
430	Tront Axie Reinforced	Carry Over	Advanced	New

The code A50 includes an increased load capacity of the front axle, allowing for heavier bodies and equipment to be upfitted. The higher-capacity front axle caters to heavier cabs and heavy special equipment that is installed

On all 3500 vehicles with gross vehicle weight rating (GVWR) of 9,990 pounds (9,900 lbs for Canada) and 11,030 pounds, the front gross axle weight rating (GAWR) is increased from the standard 4,081 lbs. to 4,409 lbs. On the 4500 vehicles with gross vehicle weight rating (GVWR) of 12,125 pounds the front axle weight rating (GAWR) is increased to 4,630 pounds and A50 is standard

### Benefits:

Allows for heavier equipment installation that impose a greater load on the front axle. Front cab can be made heavier and optioned with special equipment.

AP2	Protective U-bar for driveshaft/exhaust	Compa	red to Sprint	er 906
APZ	extension	Carry Over	Advanced	New

The code AP2 includes one safety U-bar for each segment of the power train shaft and for an extended exhaust system to comply with the legal requirements of buses used for commercial passenger transport. This equipment is standard on Passenger vans and an option on Cargo vans.

AR2	Axle Ratio 3.923	Compa	red to Sprint	er 906
AILZ	Axie Ratio 3.723	Carry Over	Advanced	New

Each vehicle is specified with an appropriate final-drive ratio, which depends on model/engine version. The standard final-drive ratio is matched to the particular model version, taking in to account fuel economy, exhaust emissions, torque and maximum speed. However, depending on the actual operating profile, another ratio may be more appropriate.

#### Benefits:

- Matching of tractive force and top speed to the appropriate application
- Optimization of fuel consumption based on configuration of the drive train, vehicle application and operating rate as well as the topography of transport routes

A lower final-drive ratio provides more torque at the wheels and is recommended e.g., for frequent hill climbing or if the vehicle will be regularly used with a trailer. Although a higher final-drive ratio provides less torque, it offers a higher top speed and is recommended, for example, for constant-speed motorway driving in flat terrain.

AR3	Axle Ratio 4.182	Compared to Sprinter 906		
AILO	Axie Natio 4. 102	<b>Carry Over</b>	Advanced	New

Each vehicle is specified with an appropriate final-drive ratio, which depends on model/engine version. The standard final-drive ratio is matched to the particular model version, taking in to account fuel economy, exhaust emissions, torque and maximum speed. However, depending on the actual operating profile, another ratio may be more appropriateBenefits:

- Matching of tractive force and top speed to the appropriate application
- Optimization of fuel consumption based on configuration of the drive train, vehicle application and operating rate as well as the topography of transport routes

A lower final-drive ratio provides more torque at the wheels and is recommended e.g., for frequent hill climbing or if the vehicle will be regularly used with a trailer. Although a higher final-drive ratio provides less torque, it offers a higher top speed and isrecommended, for example, for constant-speed motorway driving in flat terrain.

B01	ESP for increased Center of Gravity	Compared to Sprinter 906		
БОТ	above 39.4"	Carry Over	Advanced	New

Ensuring safety and driving comfort with vehicles experiencing a high center of gravity (above 39.4" from the ground). Vehicles with a raised center of gravity due to installed bodies or larger modifications can still enjoy safety and comfort on the road in many different driving situations.

This option will ensure an optimum combination of tires, suspension, Electronic Stability Programme® (ESP9i) and assistance system settings for these vehicles. This is not available on the 3500XD/4500 144" wheelbase cargo and cab chassis.

B25	Electric Parking Brake	Compa	red to Sprint	er 906
D23	Liectife I dikilig blake	Carry Over	Advanced	New

The electric parking brake makes it possible to hold the vehicle at a standstill on gradients even without a driver present. The Electronic Stability Program (ESP) activates the left and right rear actuator motor. Activation takes place manually via the electric parking brake switch or automatically when engine is running, driver's seat occupied, gear in position "D" or "R", accelerator pedal depressed or gear lever is moved from position "P"/"D" or "R"

The electric parking brake consists of the following sub functions:

## Automatically release parking brake



The release automatic parking brake function is performed as soon as a sufficient level of driving torque is applied to the wheels on the front or rear axles to enable the vehicle to drive off. If the electric parking brake switch is operated and held when driving, the ESP unit recognizes a braking request which results inbraking via a service brake. The instrument cluster displays a message and a warning tone is sounded.

# Child safety lock

With circuit 15ROFF, operating the electric parking brake switch does not lead to actuation of the parking brake. This should prevent unintended deactivation of the electric parking brake and, as such, serves as an additional protection against the vehicle rolling away on slopes or inclines.

BA3	Active Brake Assist	Compared to Sprinter 906		
DAS	Active blake Assist	Carry Over	Advanced	New



The Active Brake Assist with cross traffic function continuously checks for a safe distance of the vehicle in front and warns the driver both optically and acoustically of potential collisions (e.g. rear-end collision) with other vehicles, significantly reducing the risk of accident.

In an imminent collision situation, the Active Brake Assist may initiate autonomous braking. To do this, the controller unit evaluates the traffic situation in front of the vehicle. Respective warnings are issued starting from vehicle speed of 4 mph (7 km/h). If the driver reacts to the acoustic warning and brakes, they will be assisted by the Brake Assist. This calculates the required brake force amplification according to the situation. Autonomous partial braking is also initiated if there is no reaction from the driver to the warnings. The system also recognizes pedestrians who are in the hazard area of the vehicle in speed range of 4 mph (7 km/h) to 37 mph (60 km/h).

The assistance system is operated via the multifunctional steering wheel and if ordered, via the multimedia system. The driver may choose from three sensitivity/warning settings: "early", "medium", and "late". The system is automatically set to "medium" with every vehicle start. The assistance system can also be deactivated, which results in the corresponding warning symbol lighting up in the multifunctional.



BA9	Pre-Installation for Rail Vehicle/	Compared to Sprinter 906		
DAT	Vehicle with Inter-Axle Lock	<b>Carry Over</b>	Advanced	New

The pre-installation includes a wiring harness with the possibility to connect e.g. the signal of active longitudinal lock. This allows a temporarily deactivation of the Electronic stability program (ESP®).

BE2	Handbrake Lever, Folding	Compared to Sprinter 906		
DLZ	Trandblake Level, Folding	Carry Over	Advanced	New



Installation of an adjustable parking brake lever. This parking brake lever can be lowered even when the parking brake is on.

#### Benefits:

Allows a driver's seat to be swiveled when the parking brake is engaged.

BH1	BH1 Hold Function	Compared to Sprinter 906		
וווט	riola i diletion	Carry Over	Advanced	New

The HOLD function assists the driver during waiting times in traffic or when starting off on a hill. The HOLD function is activated by quickly pressing down hard on the actuated brake pedal after coming to a standstill. Successful activation of the HOLD function is indicated in the instrument cluster. This is standard across all models.

The HOLD function can be activated when:

- The vehicle is stationary
- The selector lever is not in the "P" position
- The engine is running
- Active Distance Assist DISTRONIC is not activated
- The electric parking brake is not applied or it is in the process of being applied
- There is no shutoff in the standstill control
- The vehicle is not sliding

The HOLD function is deactivated automatically if:

- The accelerator pedal is operated (except in the "N" position)
- The selector lever is set to position "P"
- The brake pedal is depressed again with a certain pressure until the "HOLD" status disappears in the instrument cluster
- Active Distance Assist DISTRONIC is activated
- The brake pedal is depressed and the vehicle is sliding


C6L	Multifunction Steering Wheel	Compared to Sprinter 906			
COL	Watthanction Steering wheel	Carry Over	Advanced	New	



The multifunctional steering wheel allows for the driver to operate the onboard computer, vehicle functions, and multimedia systems without taking their hands off the steering wheel. This is done via touch-control and push buttons.

Touch-control buttons are small touch pads which – depending on equipment installed- are split amongst the left and right side of the steering wheel.

The upper left touch pad is used to control the multifunctional display of the instrument cluster, and the lower left controls the assistance systems. The top right touch pad operates the menu of the multimedia system, and the lower right controls the voice control, list of favorites, volume and telephone.



The multifunctional steering wheel is a

technical requirement for the following equipment:

- Code CL3, Leather steering wheel
- Code E3M, MBUX Multimedia system with 7-inch Touchscreen
- Code E4M, MBUX Multimedia system with 10.25-inch Touchscreen
- Code ET4, Active Distance Assist DISTRONIC
- Code JB4, Active Lane Keeping Assist
- Code JK5, Instrument Cluster with Color Display
- Code MS1, Cruise Control

C72	C72 Bumpers Front/Rear Primed	Compared to Sprinter 906			
672	bumpers from Kear Finned	Carry Over	Advanced	New	



The entire bumper is painted pure white (MB 9678). This coating makes it possible to apply a topcoat in any desired color.

#### Benefits:

Allows subsequent painting to match a desired color scheme. The bumpers can be painted in a different shade.

Note: Not available with step bumper W73. Side moldings can also be ordered primed (sales code CM9).

Note: Parking package with 360° camera (JB6) or Parking package with rear view camera (JB7) parking sensors are also installed in the color pure white (MB9678), which cannot be painted. Please refer to Mercedes-Benz Body and Equipment Guidelines available on <a href="https://www.upfitterportal.com">www.upfitterportal.com</a> for more information.

CB<sub>1</sub>

# Suspension for Comfort and Load Protection

Compared to Sprinter 906

Carry Over | Advanced

New



This includes shock absorbers tuned specifically for passenger transport as well as additional springs and rubber bearings compared to the base suspension. It additionally has an application of double-leaf parabolic springs with progressive spring characteristic which increase the driving comfort in unloaded vehicles. The spring is designed to be "soft" under low applied force, and becomes "firmer" when the vehicle is loaded, ensuring suitably firm

suspension properties.

Note: Depending on the model this code can be combined with code CB7, Stabilization Stage I.

CB7	CB7 Stabilization Level I	Compared to Sprinter 906			
CD7	Stabilization Level 1	Carry Over	Advanced	New	

The code CB7 provides enhanced roll stabilization, particularly when carrying heavier loads. Compared to the base suspension, a stiffer spring is added on to the front axle and a ride height increase of 0.5"/12.5mm is seen. A torsion bar is also added to the rear axle. In addition, shock absorbers that have adapted characteristic are mounted.

For a better understanding of the various suspension options and features offered on the Sprinter, please reference the 'Suspension Matrix' in the MY22 Dealer Ordering Guide.

CBQ	CB8 Stabilization Level II	Compared to Sprinter 906		
СВО	Stabilization Level II	Carry Over	Advanced	New

The code CB8 provides enhanced roll stabilization and body damping compared to the CB7 (stabilization stage I). Torsion bars in this package come with larger diameters that are mounted to the front and rear axle. In addition, the shock absorbers come with adapted characteristic (compression and rebound) which are mounted on front and rear axle. The leaf springs have an increased rigidity which are mounted on the rear axle.

For a better understanding of the various suspension options and features offered on the Sprinter, please reference the 'Suspension Matrix' in the MY22 Dealer Ordering Guide.

CB/I	CB4 Stabilization Level III	Compared to Sprinter 906			
ODT	Stabilization Level III	Carry Over	Advanced	New	

The code CB4 provides enhanced roll stabilization and body damping compared to the CB8 (stabilization stage II). Front axle torsion bar has a larger diameter (1.02" compared to 0.9" with CB8). The overall vehicle stiffness increase by 22% compared to CB8. In addition, the shock absorbers come with adapted characteristic (compression and rebound) which are mounted on front and rear axle. It also comes with additional bump stops in both front and rear axles.

For a better understanding of the various suspension options and features offered on the Sprinter, please reference the 'Suspension Matrix' in the MY22 Dealer Ordering Guide.

CE8	Raised Rear Body Mounts	Compared to Sprinter 906		
CLO	Raiseu Real Body Modifis	Carry Over	Advanced	New

The vehicle is raised by 1.38" (35 mm), where spacers are fitted on the driver and passenger side between the rear springs (center) and the axle spring saddle. Balances the vehicle when a particularly heavy rear upfit is installed. The length of the shock absorbers is adapted accordingly so that the vehicle has the same spring travel as the standard suspension

### Benefits:

- More space between frame and road
- Improved departure angle
- Provides more space under the frame for fitting special attachments and improve vehicle rear ramp angle

CL1	CL1 Adjustable Steering Wheel (Angle)	Compared to Sprinter 906			
OLI	Adjustable Steering Wheel (Aligie)	Carry Over	Advanced	New	



The steering wheel is manually adjustable for tilt and height. To provide a large adjustment range, the wheel can be tilted at a vertical angle between 28 and 32 degrees and adjustable axially by 2.36" (60 mm) and 1.96" (50 mm) in height. The adjustment is performed by a lever on the steering column.

## Benefits:

- An ergonomic seating position
- More comfortable seating posture

CL3	Leather Steering Wheel	Compa	red to Sprint	er 906
OLS	Leather Steering wheel	Carry Over	Advanced	New



The leather steering wheel, comes with a 3-spoke design and is lined with 'nappa' leather and a perforated grip area. The standard matt black steering wheel cover is replaced by a silver chrome version.

# **Painted Metallic Front & Rear Bumper**

**Compared to Sprinter 906** 

Carry Over | Advanced

New



Paint colors offered with the code CM0 are:

- MB 7755 Tenorit grey metallic
- MB 9197 Obsidian black metallic
- MB 9775 Iridium silver



In addition, the front and rear bumpers are equipped with one of the following:

- Code JA7, Blind Spot Assist
- Code JB6, Parking Package with 360° Camera
- Code JB7, Parking Package with Reversing Camera

CM0 is not available on Sprinter Cab Chassis (3500XD/4500).

CN2, 'Radiator Grille Frame in Vehicle Color', is automatically added when code CM0 is chosen.

Note: W73, Rear Door Step, will not be painted with the code CM0.

CM2	Bumpers/Detachable Body Parts Painted	Compared to Sprinter 906		
	Body Color	Carry Over	Advanced	New

The front bumper and the door side rub panels can be painted in one of the following vehicle colors:

- MB 7755 Tenorite grey metallic
- MB 9147 Arctic white
- MB 9197 Obsidian black metallic
- MB 9775 Iridium silver

CM9	Primed Side Moldings	Compared to Sprinter 906		
CIVI 9	i illied Side Moldings	Carry Over	Advanced	New

The side plastic molding panels are primed in a white base coat, allowing for painting with aftermarket paint.

## Benefits:

Allows subsequent painting in a desired custom color scheme e.g. fleet purposes.

## **Radiator Grille Frame in Vehicle Color**

**Compared to Sprinter 906** 

Carry Over

Advanced

New



The radiator grille frame is ordered in vehicle color. CN2 is required when ordering one of the following equipment:

- Code C72, Bumpers and corner bumpers, paintable
- Code CM0, Painted bumper
- Code FK3, Chrome-Plated radiator grille

This increases the appeal of the van allowing for a sleeker and upscale look.

CT1	T1 Rear Spring Vibration Absorbers	Compared to Sprinter 906		
OI I	iteal Spring Vibration Absorbers	<b>Carry Over</b>	Advanced	New



Installation of two vibration dampers each on the left and right rear spring. Rubber absorbers providing optimal vibration damping and reducing noise levels in the vehicle

D03	High Roof	Compared to Sprinter 906			
D03		Carry Over	Advanced	New	



High roof

The high roof includes high sidewalls and higher rear doors, giving an interior height in the load/passenger compartment of approximately 79.5" (2020 mm) (144" wheelbase approx. 79.1" (2010 mm)). Compared to the standard roof, this is approximately 11.5" (292) mm higher. This provides increased load space and room for stand up. The door apertures are higher on both rear and sliding compartment doors. The maximum load capacity is 330 lbs (150 kg) evenly distributed over the whole area of the high roof, compared to 660 lbs (300 kg) on the standard roof.

The High roof must be ordered when ordering one of the following equipment:

Code FF4, Shelf above roof trim

Standard roof

- Code HK4, High-performance roof-mounted air conditioning system
- Code VA5, Full paneling, hinged rear doors
- Code V4A, Full paneling, right- hand load comp. sliding door

## Benefits:

Increased load space

- Taller door apertures
- Room to stand upright in the load compartment

D13	Mounting Rails for Roof Rack	Compared to Sprinter 906			
וט		<b>Carry Over</b>	Advanced	New	



Two C-channel rails made of aluminium are permanently mounted in the lengthwise grooves on the vehicle roof. Maximum roof load (including basic carrier bars) 110 lbs. (50 kg) per crossbar. Maximum roof load for the standard roof is 660 lbs (300 kg) (six crossbars) and 330 lbs (150 kg) for the high roof (code D03) (three cross bars).

### Benefits:

Allows roof carriers to be fitted. The roof rails allow roof racks, roof boxes and other accessories to be fitted.

D17	7 Interior Roof-Rack	Compared to Sprinter 906			
	Interior Root-Rack	Carry Over	Advanced	New	

The roof rack is attached to the vehicle roof on the inside and serves to secure loaded goods. The system consists of the following components:

- Two rails permanently fixed to the vehicle roof, one on the left and one to the right.
- Two carrier rails are mounted perpendicular to the roof rails and can be moved back and forth along the length of the fixed rails.



- One pair of glides per carrier rail, and a belt for fastening of loaded goods.
- Two head lashings for additional load securing measures.

The inside roof rack is constructed so that the carrier rails can be moved to any position along the fixed rails which reach almost across the entire length of the load compartment. That way, the fastening system can be adapted to the individual length of the loaded goods. For repositioning, the carrier rails can be quickly released and fastened again by loosening and tightening of the clamp nuts. The two gliders can be individually repositioned along the carrier rails allowing goods with different widths and diameters to be secured.

For repositioning of the gliders, the ring must be pulled and released again once the glider is in the desired position. The length of the belts attached to the gliders can be adjusted. Fixing the gliders in the required position and strapping the loaded goods down, will safely retain them in position. The head lashings further help to secure the load in longitudinal direction, *e.g.* when braking or accelerating. They are hooked into the glider rings with two hooks each.

#### Note:

- The interior roof rack may carry a load of no more than 110 lbs (50 kg)
- High point loads on the belts and gliders may result in the belt tearing and the gliders breaking
  off the carrier rails. The load must be distributed evenly. The overall center of gravity is positioned between the fixed roof rails and the carrier rails as centrally as possible.
- When loading or unloading, the area directly below the loaded goods must be clear of persons in order to prevent injury.

D22	Fixed Sunroof (Rear Roof Section)	Compared to Sprinter 906			
DZZ		Carry Over	Advanced	New	



The 144" WB vehicles are with two <u>fixed</u> sunroofs that are installed in the front and rear sections of the load compartment. The dimensions of each sunroof are about 32.68" x 15.75" (830 x 400 mm). The 170" WB vehicles and 170" WB Ext. vehicles are fitted with the two sunroofs mentioned above, and two additional fixed sunroofs in the rear section of the roof (dimension approx. 6.69" x 20.47" ( $170 \times 520$  mm))

### Benefits:

- Load compartment experiences increased light, for easier working, etc.
- Greater amount of daylight entering the load compartment provides better working conditions, e.g., in mobile workshops and parcel delivery vehicles.

D50	Cargo Partition	Compared to Sprinter 906		
D30	Cargo i artition	Carry Over	Advanced	New



The full width sheet metal (steel) partition D50 located on the B-pillar is designed as one-piece for standard height roofs and two-pieces for high roof versions. These two options now have a 0.59" (15 mm) deeper contouring at backrest height. This allows for the front seats to be better adjusted to the driver and co-driver's comfort and provides a solid barrier for cargo, noise and dirt.

## Benefits:

- Serves to secure load, in conjunction with floor mounted lashing D-rings
- Meets the requirements of ISO 27956 standard for the simultaneous transport of passengers and cargo
- In cold temperatures, the driver's cabin can be heated quickly.

Note: Before driving, always make sure to secure your cargo using the tie down system standard in all Sprinters.

# Cargo Partition with 1 Window

**Compared to Sprinter 906** 

Advanced Carry Over

New



The full width sheet metal partition D51 with one plastic window located on the B-pillar is designed as one-piece for standard height roofs and two-pieces for high roof versions. These options now have a 0.59" (15 mm) deeper contouring at backrest height. This allows the front seats to be better adjusted to the driver and co-driver's comfort. The window dimension is 51.2" x13.4" (1300 mm x 340 mm) and is glued to the partition wall.

### Benefits:

- Serves to secure load, in conjunction with floor mounted lashing D-rings
- Meets the requirements of ISO 27956 standard for the simultaneous transport of passengers and cargo
- In cold temperatures, the driver's cabin can be heated quickly.
- Provides a visual of the cargo area
- Provides view of rear traffic if windows are fitted in the rear doors (W61, W78)

Note: Before driving, always make sure to secure your cargo using the tie down system standard in all Sprinters.

D64	Bulkhead with sliding door	Compared to Sprinter 906			
		Carry Over	Advanced	New	



The partition with sliding door is situated in the B-pillar area and fitted with a door lock and locking cylinder. From the driver's side, the sliding door can be opened by four separate keys and from the load compartment side, by a lever on the door lock. The open sliding door is held in place at the end by a retainer. When the sliding door is closed, it is not possible to see the cargo area. The aluminum sliding door is 22.72" (577 mm) x 69.88" (1775 mm) x 0.67" (17 mm) (wide x high x deep). A grab handle (code T77) is fitted on the right-hand side, in the entrance area of the

sliding load-compartment door. A passenger jump seat with a head restraint mounted to the partition (code S20) is also included with this.

## Benefits:

- Serves to secure load, in conjunction with floor mounted lashing D-rings
- Meets the requirements of ISO 27956 standard for the simultaneous transport of passengers and cargo
- In cold temperatures, the driver's cabin can be heated quickly.

D93 Omission Bulkhead Compared to Sprinter 906
Carry Over Advanced New



No partition is installed on cargo vans. B-pillar is wrapped but the retrofit of a bulkhead is still possible.

### Benefits:

- Unimpeded access to load compartment
- Allows special bodies and attachments to be fitted

Provides unimpeded access to the load compartment and allows extra-long objects such as carpet rolls to be placed right through to the passenger's seat base. Also makes it easier for body manufacturers to fit special bodies and attachments.

Note: When retrofitting, modifying or attaching any type of partition, ensure that compliance to ISO 27956 is met, specifically when transporting goods/cargo.

E07	Hill Start Assist	Compared to Sprinter 906			
E07 Hill	Tilli Start Assist	Carry Over	Advanced	New	

After the service brake has been released, the applied brake pressure continues to be provided by Start-Off Assist (AAS) for approximately 0.8 seconds. AAS automatically activates on gradients of approximately 4% or more, when a gear is selected (forward or reverse). If the direction of travel is downhill, AAS is not activated. AAS is also not activated if the parking brake is engaged.

### Benefits:

- Easier hill starts
- Temporarily prevents the vehicle from rolling away

This is standard on all Sprinter vehicles.

E1B	Tray for Smartphones incl. Wireless	Compared to Sprinter 906			
LID	Charging	Carry Over	Advanced	New	

The smartphone tray is located in the center of the cockpit and it enables wireless charging of mobile phones of up to 6.7" (170 mm) in size. Wireless charging is possible for all mobile devices that support QI Standard V1.2.

## **Near Field Communication (NFC)**

The Near Field Communication is an international transmission standard for the wireless exchange of data via radio technology over very short distances of a few centimeters. Mobile phones that are placed on the tray and that support the NFC standard can be connected easily and quickly the multimedia system via Bluetooth®.



Radio/Head Unit	Code	USB-C port	Location	Function			
Radio/ Head Offic	Code	amount	Location	Charging	Data Transfer	Intelligent*	
Standard USB-socket	E1U	1	Lower Center Console	Х			
Standard Radio	E10	1	Integrated in Standard Radio	Х	Х		
7" Screen	E3M	1	Center Dash Board	Х	Х	Х	
7" Screen with Wireless	E3M + E1B	1	Center Dash Board	Х	Х	Х	
Charging	ESIMITEID	1	Center Dash Board	Х	Х		
7" Screen with Navigation/Satellite Radio	E3M +	1	Center Dash Board	Χ	Х	Х	
	E1E/E1S	1	Center Dash Board	Х	Х		
7" Screen with	E3M + E1E/E1S +	1	Center Dash Board	Х	Х	Х	
0 /	E1B	2	Center Dash Board	Х	Х		
10.25" Course with Navigation	E4M	1	Center Dash Board	Х	Х	Х	
10.25" Screen with Navigation	E+IVI	1	Center Dash Board	Х	Х		
10.25" Screen with Navigation	E4M + E1B	1	Center Dash Board	Х	Х	Х	
and Wireless Charging	E4M + E1B 2	2	Center Dash Board	Х	Х		
Charging Package	ES5	1	Center Dash Board	Х			
- 5 5		1	also includes a 12V socket in center dash board				
Rear Ports PV	V21	4-5	Rear Paneling	Х			

<sup>\*</sup>Smartphone Integration (Apple Car Play/Android Auto)

F1F	E1E Navigation	Compared to Sprinter 906		
		Carry Over	Advanced	New



(code E4M).

With this, the MBUX multimedia system with 7" touch display (code E3M) becomes a full-fledged navigation system including free map data updates for 3 years. It can be operated either via touch screen, the buttons on the control unit below the touch screen, or via touch-control buttons to the right of the multifunctional steering wheel. Navigation can be displayed both on the display of the multimedia systems and the instrument cluster. This is not available on the 10" MBUX multimedia system

# Additional functions:

- Mercedes me connect
- LINGUATRONIC voice control
- WLAN-Hotspot
- Multimedia interface with an additional USB-C interface
- Improved hands-free function
- Center-fill loudspeaker for an improved sound quality and voice output
- Digital operator's manual
- Dual phones use

Radio/Head Unit	Code	USB-C port	Location	Function				
Radio/ Head Offic	Code	amount	Location	Charging	Data Transfer	Intelligent*		
Standard USB-socket	E1U	1	Lower Center Console	Х				
Standard Radio	E10	1	Integrated in Standard Radio	Х	Х			
7" Screen	E3M	1	Center Dash Board	Х	Х	Х		
7" Screen with Wireless	E3M + E1B	1	Center Dash Board	Х	Х	Х		
Charging	ESIMITEID	1	Center Dash Board	Х	Х			
7" Screen with Navigation/Satellite Radio	E3M +	1	Center Dash Board	Χ	Х	Х		
	E1E/E1S	1	Center Dash Board	Х	Х			
7" Screen with	E3M + E1E/E1S +	1	Center Dash Board	Х	Х	Х		
0 /	E1B	2	Center Dash Board	Х	Х			
10.25" Course with Navigation	E4M	1	Center Dash Board	Х	Х	Х		
10.25" Screen with Navigation	E+IVI	1	Center Dash Board	Х	Х			
10.25" Screen with Navigation	E4M + E1B	1	Center Dash Board	Х	Х	Х		
and Wireless Charging	E4M + E1B 2	2	Center Dash Board	Х	Х			
Charging Package	ES5	1	Center Dash Board	Х				
- 5 5		1	als	also includes a 12V socket in center dash board				
Rear Ports PV	V21	4-5	Rear Paneling	Х				

<sup>\*</sup>Smartphone Integration (Apple Car Play/Android Auto)

F10	E10 Standard Radio	Compared to Sprinter 906		
Standard Radio	Stalldald Radio	Carry Over	Advanced	New



The 1-DIN radio with FM/AM reception comes with an LCD display and an integrated USB-C port. The radio can be operated exclusively via the device itself and not via the optional multifunctional steering wheel.

Radio stations can be individually saved while the dual tuner ensures the best possible reception via the antenna on the vehicle.

The standard-Bluetooth® installation allows the customer to use the hands-free telephone system as well as accessing the list of contacts saved on the mobile phone. The quality of the telephone connection is dependent on the mobile phone's reception, as phone calls via Bluetooth® do not require the vehicle antenna.

When calling or receiving a call the radio volume is automatically reduced (mute function). The communication occurs via loud speakers and a microphone integrated in the vehicle. In addition, it is possible to stream audio files from mobile audio devices to the radio via Bluetooth®, given that the device supports the usual formats. When playing music via Bluetooth®, vehicle speakers are used allowing the user to toggle through songs via a pre-selected playlist. It is not possible to browse using the 1-DIN radio through folders on the mobile device.

Radio/Head Unit	Code	USB-C port	Location		Function	
Radio/ Head Offic	code	amount	Location	Charging	Data Transfer	Intelligent*
Standard USB-socket	E1U	1	Lower Center Console	х		
Standard Radio	E10	1	Integrated in Standard Radio	Х	Х	
7" Screen	E3M	1	Center Dash Board	Х	Х	Х
7" Screen with Wireless	F3M + F1B	1	Center Dash Board	Х	Х	Х
Charging	E3M + E1B	1	Center Dash Board	Х	Х	
7" Screen with	E3M +	1	Center Dash Board	Х	Х	Х
Navigation/Satellite Radio	E1E/E1S	1	Center Dash Board	Х	Х	
7" Screen with	E3M + E1E/E1S +	1	Center Dash Board	Х	Х	Х
Navigation/Satellite Radio and Wireless Charging	E1B	2	Center Dash Board	Х	Х	
10.25° Community Manipulation	E4M	1	Center Dash Board	Х	Х	Х
10.25" Screen with Navigation	E4IVI	1	Center Dash Board	Х	Х	
10.25" Screen with Navigation	FAM . FAD	1	Center Dash Board	Х	Х	Х
and Wireless Charging	E4M + E1B 2	2	Center Dash Board	Х	Х	
Charging Package	ES5	1	Center Dash Board	Х		
		1	a	lsoincludes a 12V so	cket in center dash bo	ard
Rear Ports PV	V21	4-5	Rear Paneling	Х		

<sup>\*</sup>Smartphone Integration (Apple Car Play/Android Auto)

E1S	Sirius XM, Satellite Radio	Compared to Sprinter 906			
LIS	Sirius Aivi, Satellite Radio	Carry Over	Advanced	New	



The head unit enables the reception of stations from provider Sirius XM® and offers more than 160 channels of music, talk, sports, news and other programs. The Satellite Digital Audio Radio Service (SDARS) information is shown on the Audio display. The Sirius satellite radio signal is broadcast 3 times to achieve a diversity of channels (using two satellites and one terrestrial transmitter). All three channels are received by the SDARS antenna placed on the roof next to the b-pillar (on cargo vans) and on the roof in front of

the B-pillar on cab chassis.


Sirius XM® radio is already activated from factory and includes a free trial period. For more information, please refer to Sirius XM®.

Radio/Head Unit	Code	USB-C port	Location		Function	
Radio/ Head Offic	Code	amount	Location	Charging	Data Transfer	Intelligent*
Standard USB-socket	E1U	1	Lower Center Console	х		
Standard Radio	E10	1	Integrated in Standard Radio	Х	Х	
7" Screen	E3M	1	Center Dash Board	Х	Х	Х
7" Screen with Wireless	E3M + E1B	1	Center Dash Board	Х	Х	Х
Charging	ESIMITEIB	1	Center Dash Board	Х	Х	
7" Screen with	E3M +	1	Center Dash Board	Х	Х	Х
Navigation/Satellite Radio	E1E/E1S	1	Center Dash Board	Х	Х	
7" Screen with	E3M + E1E/E1S +	1	Center Dash Board	Х	Х	Х
Navigation/Satellite Radio and Wireless Charging	E1B	2	Center Dash Board	Х	Х	
10.25" Carron with Manigation	E4M	1	Center Dash Board	Х	Х	Х
10.25" Screen with Navigation	E4IVI	1	Center Dash Board	Х	Х	
10.25" Screen with Navigation	E4M + E1B	1	Center Dash Board	Х	Х	Х
and Wireless Charging	E#IVI T E I B	2	Center Dash Board	Х	Х	
Charging Package	ES5	1	Center Dash Board	Х		
		1	а	lsoincludes a 12V so	cket in center dash bo	ard
Rear Ports PV	V21	4-5	Rear Paneling	Х		

<sup>\*</sup>Smartphone Integration (Apple Car Play/Android Auto)

E1R	Additional Fuses (40/80/150/100	Compared to Sprinter 906		
LIK	Amps)	Carry Over	Advanced	New





The main fuse box now contains 4 additional fuses (40/80/150/100 Amps) that are not utilized by the Sprinter and are dedicated fuses for electrical consumers on upfitted vehicles. Please look at the Sprinter operator's manual for more information on fuse locations.

Main fuse locations	Current (A)
F8	100
F9	150
F10	80
F12	40

E1U USB-C Socket, 5V Compared to Sprinter 906

Carry Over Advanced New



The 5-Volt USB-C power socket is located centrally in the lower part of the cockpit, below the center cup holder and next to the standard 12-Volt socket. Allows for these options to be within easy reach of driver and passenger.

## **USB-Port Overview**

Radio/Head Unit	Code	USB-C port	Location		Function	
Radio/ Head Offic	Code	amount	Location	Charging	Data Transfer	Intelligent*
Standard USB-socket	E1U	1	Lower Center Console	Х		
Standard Radio	E10	1	Integrated in Standard Radio	Х	Х	
7" Screen	E3M	1	Center Dash Board	Х	Х	Х
7" Screen with Wireless	E3M + E1B	1	Center Dash Board	Х	Х	Х
Charging	ESIM + ETB	1	Center Dash Board	Х	Х	
7" Screen with	E3M +	1	Center Dash Board	Х	Х	Х
Navigation/Satellite Radio	E1E/E1S	1	Center Dash Board	Х	Х	
7" Screen with Navigation/Satellite Radio and	E3M + E1E/E1S +	1	Center Dash Board	Х	Х	Х
Wireless Charging	E1B	2	Center Dash Board	Х	Х	
10.25" Screen with Navigation	E4M	1	Center Dash Board	Х	Х	Х
10.25 Octeen with Navigation	L41VI	1	Center Dash Board	Х	Х	
10.25" Screen with Navigation	E4M + E1B	1	Center Dash Board	Х	Х	Х
and Wireless Charging	2 2	2	Center Dash Board	Х	Х	
Charging Package	ES5	1	Center Dash Board	Х		
		1		lso includes a 12V so	cket in center dash bo	ard
Rear Ports PV	V21	4-5	Rear Paneling	X		

<sup>\*</sup>Smartphone Integration (Apple Car Play/Android Auto)

E1X	1X MBUX multimedia 6-hour runtime	Compared to Sprinter 906		
LIX	MDOX multimedia o-noui runtime	Carry Over	Advanced	New

The code E1X extends, depending on the battery charge level, the MBUX multimedia radio operating time up to 6 hours (without automatically shutting down). Full charging of the starter battery is recommended for an optimum radio operating time. For the use of the MBUX multimedia systems while stationary, an external power supply with a power feed to the starter battery of at least 140 W is required.


This is automatically configured in with code X2R - Requirement for conversion to RV (where applicable).



Carry Over | Advanced

New






The main fuse box now contains 4 additional fuses (40/80/80/100 Amps) that are not utilized by the Sprinter and are dedicated fuses for electrical consumers on upfitted vehicles. Please look at the Sprinter operator's manual for more information on fuse locations.

Main fuse locations	Current (A)
F8	100
F9	80
F10	80
F12	40

E2A	Access Point for BB Special Signals in	Compa	red to Sprint	er 906
CZA	Cockpit	Carry Over	Advanced	New



This pre-installation is a standardized interface located in the driver's side A-pillar to easily connect predefined electrical vehicle functions to upfitter devices. It includes 12 upfitter special signals:

- Additional terminal 15 (ignition on, 5 A)
- Terminal 30T (battery voltage behind the switch for the deep discharge protection, 7.5 A)
- Terminal 31 (ground, battery, 25 A)
- Terminal 58D (lighting instrument cluster, 1 A)
- Turn indicator left (21 W, 2 A)
- Turn indicator right (21 W, 2 A)
- Reversing lamps (2 x 21 W, 2 x 2 A)
- 5 additional freely assignable signals between the instrument panel and the seat base (7.5 A)

Note: A Parameterizable Special Module (PSM), Code ED5, is not necessarily required. If a PSM is not included, the speed and hand brake signal, terminal 30, and D+ cannot be used.

# Additional battery for retrofit consumers, driver seat base

Compared to Sprinter 906

Carry Over | Advanced

New



When ordering this, an absorbed glass mat (AGM) battery 12 V/92 Ah 850 A is installed into the passenger' seat frame. If an installation in the passenger's seat frame is not possible due to upfit restrictions, an additional 12 V / 70 Ah 720 A, AGM battery can be ordered into the engine compartment on the left hand side in driving direction, via code E2M. The battery is ideal for powering additional electrical consumers without putting a load on the starter battery.

From factory, the following equipment is connected directly to the additional battery:

- Code E46, Power socket in cab
- Code EE3, 115 V Socket
- Code ES2, 12 V Plug socket in trunk / load compartment
- Code ES5, Charging package, dashboard
- Code V85, Smoker package
- Code E1U, USB-C Socket, 5 V

A cut-off relay (E36) must be ordered with an additional battery. The relays is positioned in the charging circuit of the additional battery. It separates the load of the starter battery from the additional battery, in order to prevent the started battery from discharging. When the engine is running, the relay allows both batteries to be charged or discharged simultaneously.

E2M	Additional battery for retrofit	Compa	red to Sprint	er 906
EZIVI	consumers, engine Compartment	Carry Over	Advanced	New



If an installation in the passenger's seat frame is not possible due to upfit restrictions, an additional 12 V / 70 Ah 720 A, AGM battery can be ordered into the engine compartment on the left hand side in driving direction, via code E2M. The battery is ideal for powering additional electrical consumers without putting a load on the starter battery. A cut-off relay (E36) must be ordered with an additional battery.

E30	Starter battery disconnect	Compared to Sprinter 906		
LJU	Starter battery disconnect	Carry Over	Advanced	New

The battery quick-disconnect unplugs the battery ground connection and switches off all electrical consumers. It is located in the driver's foot well, to the right of the accelerator pedal. To disconnect, the connector has to be removed from the ground post. See owner's manual. It must be ensured that the



battery master switch is only disconnected when the vehicle key in ignition is in position 0, otherwise there is a risk of damaging other components in the electrical system. The battery quickdisconnect is standard on all Sprinters.

#### Benefits:

- Prevents uncontrolled battery discharge
- •Work on the electrical system can be carried out more quickly

The battery quick-disconnect prevents uncontrolled discharging of the battery due to standby current consumption. It is recommended that vehicles with extended

down time be disconnected (three weeks or longer). The battery quick-disconnect also allows work on the electrical system to be carried out more quickly, since it is not necessary to disconnect the battery pole.

E36	Cutoff relay for additional battery	Compared to Sprinter 906		
LJU	Cuton relay for additional battery	Carry Over	Advanced	New



The relay is installed on the charge line to the auxiliary battery. It separates the starter battery consumers from the auxiliary battery consumers. When the engine is running, the relay allows both batteries to be charged (by the alternator) or discharged simultaneously.

## Benefits:

Starter battery cannot be discharged by auxiliary consumers. The cutout relay prevents the starter battery from being drained by consumers connected to the auxiliary battery. It also prevents the auxiliary battery from being drained by the standard consumers such as the starter or fan.

E3J	Pre-Installation for switch panel	Compa	red to Sprint	er 906
ESJ	Pre-installation for switch panel	Carry Over	Advanced	New



This pre-installation includes two additional switch panels below the steering wheel with a total of eight possible switches, where two switches are located to the left and six switches are located to the right. The covers can be exchanged in the future to functioning switches for retrofitting purposes.

**E3M** 

# MBUX Multimedia System with 7" **Touchscreen**

**Compared to Sprinter 906** Carry Over Advanced New



- High-resolution 7"/17.8 cm touch screen (960 x 540 pixel)
- AM/FM Radio with dual tuner
- Bluetooth® connectivity with audio streaming
- Hands-free functionality
- Smartphone integration via Android Auto or Apple CarPlay
- Multimedia interface with USB-C port
- 2-Way loudspeakers front, 4 x 25 W power output, sound settings, separate volume settings for audio and telephone

If E3M is ordered, the standard rear view camera (FR3) is replaced with FR8, which then is displayed in the touchscreen. For cab chassis with E3M the pre-installation (FR7) for a digital rear view camera is recommended.

# **USB-Port Overview**

Radio/Head Unit	Code	USB-C port	Location	Function		
Radio/ ficad offic	Couc	amount		Charging	Data Transfer	Intelligent*
Standard USB-socket	E1U	1	Lower Center Console	Х		
Standard Radio	E10	1	Integrated in Standard Radio	Х	Х	
7" Screen	ЕзМ	1	Center Dash Board	Х	Х	Х
7" Screen with Wireless	E3M + E1B	1	Center Dash Board	Х	Х	Х
Charging	ESIM + ETB	1	Center Dash Board	Х	Х	
7" Screen with	E3M +	1	Center Dash Board	Х	Х	Х
Navigation/Satellite Radio	E1E/E1S	1	Center Dash Board	Х	Х	
7" Screen with	E3M + E1E/E1S +	1	Center Dash Board	Х	Х	Х
Navigation/Satellite Radio and Wireless Charging	E1B	2	Center Dash Board	Х	Х	
10.25" Screen with Navigation	E4M	1	Center Dash Board	Х	Х	Х
10.25 Screen with Navigation	E4M	1	Center Dash Board	Х	Х	
10.25" Screen with Navigation	E4M + E1B	1	Center Dash Board	Х	Х	Х
and Wireless Charging	E4M + E1B	2	Center Dash Board	Х	Х	
Charging Package	ES5	1	Center Dash Board	Х		
		1	а	lso includes a 12V so	cket in center dash bo	ard
Rear Ports PV	V21	4-5	Rear Paneling	Χ		

<sup>\*</sup>Smartphone Integration (Apple Car Play/Android Auto)



Wiring for trailer hitch that runs along the inside left frame. E40 includes a seven-pin connector and provides power for trailer lightning systems (tail lights, brake lights, direction indicators, rear fog lights and reversing light) and allows electrical operation. The trailer wiring is bundled up and temporarily attached to the frame during transport. This allows for installation of an authorized accessory trailer hitch by the body builder.

## Benefits:

Connects the trailer lights to the Sprinter. It is installed with the corresponding wire harness and trailer control unit, but no trailer hitch is installed.

E46	12 V Power Outlet, Driver Seat Base	Compared to Sprinter 906		
		<b>Carry Over</b>	Advanced	New



A 12 V / 15 A socket with a maximum power consumption of 180 W is installed on inner side of the driver's seat frame. The socket is supplied with power by the starter battery, except if code E2I/E2M is ordered, and then it is supplied by the auxiliary battery. In this case, power can be drawn regardless of ignition status.

### Benefits:

Can be used to power additional electrical consumers. The socket can be used to power electrical consumers such as a fan, TV or cooler

E4A	Antenna Interface for Radio, Navi., Mobile	e Compared to Sprinter 906		
	Phone	Carry Over	Advanced	New



Upfitters can install their own antenna and use the antenna interface to connect the telematics. This enables exchange of analogue and digital radio signals as well as GNSS and GSM signals and therefore the use of Mercedes-Benz radios or multimedia

systems in the vehicle. The antenna interface is located in the driver's seat box and its cable reaches to the DIN-slot in the center console.

Note: this will remove the standard antenna (ED3) from the Sprinter vehicle.

E4M

# MBUX Multimedia System with 10.25" Touchscreen


Compared to Sprinter 906

Carry Over | Advanced

New

Contains the following in addition to the 7" system (Code E3M):

- High-resolution 10.25"/26 cm touch screen (1.920 x 720 pixel)
- Hard disk navigation incl. free map data updates for 3 years
- Mercedes me connect
- LINGUATRONIC voice control
- WLAN-Hotspot
- Multimedia interface with two USB-C ports
- Air vents lined in matt silver
- Improved hands-free function
- Center fill loudspeaker for an improved sound quality and voice output
- Digital operator's manual
- High gloss optic



## Internet in the Car

The Wi-Fi Hotspot enables wireless use of the internet with mobile devices inside the vehicle. The head unit acts as a Wireless Access-Point (WAP) and exchanges Wi-Fi data with mobile devices via the antenna and routes the signals to the internet. To connect the mobile device, the user must search for networks (Wireless Local Area Network) on the mobile device and select the head unit network. Several devices can be connected simultaneously.

Conditions for using Wi-Fi:

- The Wi-Fi function on the head unit is active
- The head unit is connected to the internet
- Wi-Fi capable mobile device is available
- A contract must be made with T-Mobile in order to access data services, and this contract can be made via T-Mobile or infotainment system

# **Internet Access - General Information**

The head unit controls the internet connection. The communication module for digital services is used as a modem. In the interest of data security, SSL encryption (Secure Socket Layer) is used.

The internet can be used in the vehicle in the following ways:

- Use of Mercedes me connect services such as weather forecast, special destinations, and searching for and loading of trip routes
- Unrestricted surfing (vehicle is stationary)

# LINGUATRONIC voice control

The voice control system recognizes coherent commands that can be spoken by any person without the need for teach-in. If the spoken command is not clearly identified, a query is made by the voice control system.






Voice control allows for access to and operation of a numerous functions of the driver information system such as:

- Navigation
- Radio and other media sources
- Telephone
- Vehicle menu

When in standby mode, LINGUATRONIC can be activated via the corresponding button on the multifunctional steering wheel or by using a code word ("Hey Mercedes"). Voice input takes place via the driver hands-free system microphone.

# **Telephone**

Up to 15 mobile phones can be authorized/registered on the multimedia system. Up to two phones can be used at the same time in combination with the Navigation or the Multimedia system with a 10.25" touch screen. However, the second phone can only process incoming calls, and text messages. The user is able to receive, send and manage text messages. The system can read out text messages.



The MBUX system can be operated via:

- Touch control on the multifunctional steering wheel
- Touch control on the multimedia system display
- Buttons on the control panel below the display
- LINGUATRONIC voice control

## **USB-Port Overview**


Radio/Head Unit Code USB-C port Location Function		Function					
Radio/ Head Offic	Code	amount	Location	Charging	Data Transfer	Intelligent*	
Standard USB-socket	E1U	1	Lower Center Console	х			
Standard Radio	E10	1	Integrated in Standard Radio	Х	Х		
7" Screen	E3M	1	Center Dash Board	Х	Х	Х	
7" Screen with Wireless	E3M + E1B	1	Center Dash Board	Х	Х	Х	
Charging	E3W + E1B	1	Center Dash Board	Х	Х		
7" Screen with	E3M +	1	Center Dash Board	Х	Х	Х	
Navigation/Satellite Radio	E1E/E1S	1	Center Dash Board	Х	Х		
7" Screen with Navigation/Satellite Radio and	E3M + E1E/E1S + E1B	1	Center Dash Board	Х	Х	Х	
Wireless Charging		2	Center Dash Board	Х	Х		
10.25" Screen with Navigation	E4M	1	Center Dash Board	Х	Х	Х	
10.25 Screen with Navigation	E+IVI	1	Center Dash Board	Х	Х		
10.25" Screen with Navigation	F4M + F1B	1	Center Dash Board	Х	Х	Х	
and Wireless Charging	E4M + E1B	2	Center Dash Board	Х	Х		
Charging Package	ES5	1	Center Dash Board	Х			
		1	also includes a 12V socket in center dash board				
Rear Ports PV	V21	4-5	Rear Paneling	Χ			

<sup>\*</sup>Smartphone Integration (Apple Car Play/Android Auto)

E5M	Extension of PSM Standard Contact	Compared to Sprinter 906		
		Carry Over	Advanced	New

This code involves connection of a defined cable set to the PSM including a 21-pole socket for outlets and an 18-pole socket for inlets. This facilitates connection of retrofitted components. The corresponding plugs with part number A0285453628 (PSM-outlet) and A0265459428 (PSM-inlet) can be ordered through your nearest authorized Mercedes-Benz dealer.

Pre-wiring central locking (upfitter doors **Compared to Sprinter 906** EA5 rear) Carry Over Advanced New



Pre-installation kit includes a wiring harness that gives cab chassis customers a chance to add additional aftermarket doors that use the same Mercedes-Benz key fob signal for unlocking and locking the doors and will also indicate door lock status in the instrument cluster.

Please refer to the technical bulletin available on www.upfitterportal.com titled "Sprinter MY2019+ Preinstallation for Central Locking on Body" for more information.

ED1

# AGM Battery 12V 70AH

Carry Over Advanced New



AGM technology (Absorbent Glass Mat) and its fixed electrolytes allow better utilization of the cell volume for higher cold-starting power and extreme vibration resistance. The higher-capacity AGM battery provides a reliable power supply for numerous optional items of electrical equipment with higher power consumption and is resistant to cycling, safe against deep discharge and maintenance-free. The standard battery for all cargo vans and cab chassis comes via code ED1 as 12V 70 Ah 720 A variant and can be upgraded via code ED4 to the 12 V 92 Ah 850 A variant.

ED3	Antenna for Mobile Phone	Compared to Sprinter 906		
		<b>Carry Over</b>	Advanced	New



The antenna receives radio, telephone (up to 4G mobile phone signals), navigation signals and allows navigation and telematics systems to be fitted. If necessary, the aerial rod can be unscrewed when going through car washes. The number of available signals depends on the equipment installed in the vehicle – without telematics equipment or in conjunction with radio preparation (ERO) all 3 signals are available. In conjunction with MB audio sys-

tem (E10) the radio signal is already assigned. The aerial is grounded via the metal roof, a ground connection is not possible if the vehicle is fitted out with a plastic roof

ED4 AGM Battery 12 V 92 Ah 850A Compared to Sprinter 906
Carry Over Advanced New



A heavy-duty 12 V/92 Ah AGM (Absorbent Glass Mat) starter battery is fitted instead of the standard starter battery. The AGM battery is smaller and lighter than common batteries, because the energy density is increased.

The heavy-duty Battery 12 V 92 Ah 850 A is required when ordering one of the following equipment:

- Code F49, Windscreen, heated
- Code H12, Auxiliary hot-water heater
- Code H88, Adaption fittings for aux. heat exchanger

#### Benefits:

- Resistant to exhaustive discharge
- Deep-cycle resistant
- Maintenance-free
- Increase in power enables electrical system to cope with higher loads
- More reliable starting in winter

The AGM battery is designed for heavier-duty requirements resulting from frequent starting in short-distance operation (deep-cycle resistant) or from supplying a large number of high-consumption electrical special equipment items. It is also recommended for operation in extreme climates, e.g., when the high-performance air conditioning in the passenger compartment is used.

ED5	Parametric Special Module (PSM)	Compared to Sprinter 906		
		Carry Over	Advanced	New



The parameterizable special module (PSM) gives upfitters access to individual types of CAN bus data. The PSM is able to read messages of the various bus data and then, for example, translate them into switching signals at the outputs provided or PWM signals or forward those to a specific body manufacturer upfitter CAN. The installed electronics then have access to the necessary signals.

Vehicle information can be accessed via the 20 outputs or the ABH CAN (bodybuilder CAN) interface of the PSM. For more information, please refer to the PSM bulletin available on <a href="https://www.upfitterportal.com">www.upfitterportal.com</a>.

Note: PSM is required with the following equipment:

- Code E5M, Extension of PSM Standard Contact
- Code T57, Electr. step, load compartment sliding door, right

Parametrization of the control unit PSM is carried out using the XENTRY Diagnostic tool. The upfitter is responsible for the PSM programming that is installed on the vehicle.

### Benefits:

The Sprinter is networked with several bus systems and the PSM was developed to give upfitters access to individual types of CAN bus data. The PSM is the gateway to the CAN bus and can be used to read vehicle information and control vehicle functions (e.g., the central locking).

FDΩ	ED8 Pre-Installation PSM	Compared to Sprinter 906			
בטס		Carry Over	Advanced	New	



The pre-installation includes the electric wiring up to the driver's seat base frame.

## Benefits:

Allows easy retrofitting of the parametric special module. Access to the vehicle electronics system is now only possible/permissible via one defined interface. This improves protection of the vehicle's basic functional integrity.





The 115-V socket is located in the lower part of the center console and serves to power small electrical devices with an output of up to 150 W, such as mobile phones, cordless electric screwdrivers, laptops, or flashing lights. The system is comprised of a DC/AC-converter with surge protection and a power socket. The socket is only supplied with power if a plug is recognized. For vehicles without additional battery, the power socket is functional via the KEYLESS-START power supply when the ignition is set to position 1. Vehicles with an additional battery have a run-on function that allows for devices to be charged for up to four hours after the engine has been turned off. A light on the socket indicates when it is operating.

EE5	Super-capacitor discharge module	Compared to Sprinter 906		
		Carry Over	Advanced	New

This code is a super capacitor module that is utilized when the main battery switch is disconnected; to power the internal CAN bus system during extended periods of vehicle downtime. It avoids the complete discharge of the main or emergency battery (if equipped) which would cause lasting damage.

Standard across all Sprinter models.

EK1	Body Builder Connector	Compared to Sprinter 906			
		Carry Over	Advanced	New	



The terminal strip is installed inside the driver seat frame, allows easy integration of additional electrical consumers into the existing network, and offers three connectors:

- Terminal (engine running) D+ 12 V / 10 A (120W)
- Terminal 30 12 V / 25 A (300W)
- Terminal 15 12 V / 15 A (180W)

# Benefits:

Supplies additional consumers with power options. The blank switch panel below the steering wheel, allows the integration of additional switches for the operation of body/conversion systems installed by upfitters or vehicle operators.



2 tweeters are fitted on the outside. Depending on the configuration, an additional speaker is fitted in the centre of the instrument panel, 4 more speakers are located in the side trim of the passenger or cargo compartment. 6 bass/mid-range speakers are fitted in the driver's and co-driver's door as well as in the left and right side trim in the rear.

#### Benefits:


- Excellent sound quality due to 13 speakers
- Improved listening pleasure in passenger compartment

Offers excellent sound quality, due to separate tweeters and mid-range woofers, and improved listening pleasure for passengers, wherever they happen to be sitting.

EP7

Basic Electric Fitting for Rear
Loudspeakers

Compared to Sprinter 906
Carry Over Advanced New



The code EP7 adds a pre-wiring for a later installation of rear loudspeakers.

ERO Pre-Installation for Radio Compared to Sprinter 906
Carry Over Advanced New



The radio fittings provide an AM/FM antenna, a 12 V power source and the interface for 2-way loudspeakers in the front. A single DIN slot is provided in the center of the cockpit for retrofitting a radio. The pre-installation for radio does not support CAN technology. Without CAN e.g. the control of the radio via the multi-function steering wheel and display of radio information in the instrument cluster are not supported.



A jump-starting connection point is located on the air filter box in the engine compartment and allows easier jump starting or charging of the starter battery. The terminal can be accessed by pushing back the red protective cap for the positive terminal and a brass rod on the inner left fender for ground.

ES2	12 V Power Outlet, Rear Compartment	Compared to Sprinter 906		
		Carry Over	Advanced	New



A 12-volt socket is located in the left-hand D-pillar trim of the passenger/cargo Van. The passenger Van also has a 12-volt socket in the right-hand D-pillar trim. Both sockets have a maximum power rating of 180 watts. Power can be drawn regardless of ignition key position. The sockets are supplied with power by the starter battery, except if code E2I/E2M is specified, in which case it is supplied by the auxiliary battery.

## Benefits:

Connection point for electrical accessories. The socket can be used to power accessories such as a cool box, vacuum cleaner, electric air pump or other electrical equipment, without the need for long cables.

ES5	Charging Package, Dashboard	Compared to Sprinter 906		
Loo	Charging rackage, Dashboard	Carry Over	Advanced	New



The charging package expands the charging facilities in the cockpit to two 5 V USB-C ports and one 12 V power socket. One of the USB ports as well as the 12 V socket are located in the center storage recess of the instrument panel. Another USB port is located in the lower part of the center console. This allows for charging of electric devices such as mobile phone within the driver's and co-driver's reach.

Note: In combination with code E1B, Tray for Smartphones incl. Wireless Charging, the upper USB interface also allows for connecting of mobile devices to the multimedia system.

Radio/Head Unit	Code	USB-C port amount	Location		Function		
nadio/ fiedd Offic			Location	Charging	Data Transfer	Intelligent*	
Standard USB-socket	E1U	1	Lower Center Console	Х			
Standard Radio	E10	1	Integrated in Standard Radio	Х	Х		
7" Screen	E3M	1	Center Dash Board	Х	Х	Х	
7" Screen with Wireless Charging	E3M + E1B	1	Center Dash Board	Х	Х	Х	
		1	Center Dash Board	Х	Х		
7" Screen with	E3M + E1E/E1S	1	Center Dash Board	Х	Х	Х	
Navigation/Satellite Radio		1	Center Dash Board	Х	Х		
7" Screen with Navigation/Satellite Radio and Wireless Charging	E3M + E1E/E1S + E1B	1	Center Dash Board	Х	Х	Х	
		2	Center Dash Board	Х	Х		
10.25" Screen with Navigation	E4M	1	Center Dash Board	Х	Х	Х	
		1	Center Dash Board	Х	Х		
10.25" Screen with Navigation and Wireless Charging	E4M + E1B	1	Center Dash Board	Χ	Х	Х	
		2	Center Dash Board	Х	Х		
Charging Package	ES5	1	Center Dash Board	Х			
		1	also includes a 12V socket in center dash board				
Rear Ports PV	V21	4-5	Rear Paneling	Х		•	

<sup>\*</sup>Smartphone Integration (Apple Car Play/Android Auto)

ET4	Active Distance Assist DISTRONIC	Compared to Sprinter 906		
		Carry Over	Advanced	New



target speed.

DISTRONIC regulates the speed and the distance of the vehicle with a short and long range sensor located in the front bumper. The system regulates automatically according to the specification set by driver; it brakes when necessary and accelerates again when possible. In slow moving or stop and go traffic, the DISTRONIC brakes the vehicle automatically (if necessary to a standstill). Once the traffic situation allows moving again, the DISTRONIC accelerates the vehicle automatically up to the set

The vehicle speed can be set in a range of 15 mph (24 km/h) and the vehicle 's top speed. If the system recognizes that strong braking is necessary, the DISTRONIC warning lamp in the instrument cluster lights up and an intermittent alarm tone sounds to notify the driver to proceed with increased caution and to possibly brake themselves. If the driver reacts to the acoustic warning and brakes, they will be also assisted by the Brake Assist function. If the driver fails to respond to the acoustic warning, the Brake Assist initiates (in addition to the visual and acoustic warning) partial and then maximum full-stop braking. If the vehicle was brought to a full stop, the assistance system must be reactivated using the control device on the left side of the multifunctional steering wheel.

The vehicle speed and distance can be set on the left panel on the multifunction steering wheel.



Note: If DISTRONIC is switched off and the Brake Assist is not deactivated, the situation in front of the vehicle continues to be monitored and evaluated. In dangerous situations, either warnings are given, as described above, or autonomous braking occurs.



EX9	Free Map Data Updates for 3 Years	Compared to Sprinter 906		
EAA		Carry Over	Advanced	New

This code gives customers access to free map updates for three years after first vehicles registration. Updates are available by Mercedes-Benz service or online via Mercedes Benz PRO.

EW6	Pre-installation for Mercedes me remote	Compared to Sprinter 906			
	services	Carry Over Advanced N		New	

## Vehicle setup:

- · Remote view of vehicle status
- · Remote door locking and unlocking
- Programming auxiliary heating (H12 required)

# Vehicle monitoring:

- Vehicle GPS tracker
- Geo-fencing
- Speed regulating
- Valet parking and curfew timer
- Parked vehicle locator
- Remote vehicle finder

To use these services, please register on the Mercedes me portal and accept the Terms of Use for the Mercedes me services. In addition, the respective vehicle must be paired with the user account. After the initial term expires, the services can be renewed for a fee. Refer to the Mercedes Me Connect section at the end for more information.

EY2	Intelligent navigation	Compa	red to Sprint	er 906
LIZ	intenigent navigation	Carry Over	Advanced	New



This replaces the previous generation 'Intelligent Navigation' (E1G). The communication module forwards the real-time traffic data to the head unit and receives position data from the head unit at regular intervals in the opposite direction. The position data is sent to the service provider. The HERMES control unit therefore contributes to collecting the traffic information from

which the map navigation then benefits. This service need to be activated via Mercedes me and is free of use in the first 36 months.

This is added automatically when ordering code JH3 and one of the following equipment:

- Code E1E, Navigation
- Code E4M, MBUX Multimedia system with 10.25" touch screen

F1K	Coat Hooks in Driver Cabin	Compa	red to Sprint	er 906
1 11	Coat Hooks III Driver Cabili	Carry Over	Advanced	New



The two coat hooks in the cab are available for the cargo van and mounted above the head retrains on the partition wall inside of the driver's and co-driver's seats.

F20	F28 Roof and Rear Wall Deletion	Compared to Sprinter 906			
1 20	Roof and Real Wall Deletion	Carry Over	Advanced	New	



Chassis without rear wall and roof, but including seat bases. A cover (code P08) is supplied for transport purposes.

# Benefits:

Allows body manufacturers to produce special body designs, e.g., camper bodies, which also include the roof over the cab.

# F35 Window in Cab Rear Wall Compared to Sprinter 906 Carry Over Advanced New



The Cab Chassis rear wall is fitted with a window of single-layer safety glass, size 52.4"x14.2" (1330 x 360 mm)

#### Benefits:

- Improved rearward visibility
- Allows visual checking of cargo

The window allows more light into the cab. It provides rearward visibility, for easier reversing. In the case of vehicles with box bodies, it allows the driver to keep an eye on the cargo.

E3/W	F3W Omission of Storage	Compared to Sprinter 906		
1 3 44	offission of Storage	Carry Over	Advanced	New



The open storage compartment (FJ4) can be optionally deleted via code F3W.

F43 Laminated Glass Rear	Compared to Sprinter 906			
143	Laillillated Glass Real	Carry Over	Advanced	New



Laminated glass is installed for the side windows behind the driver/passenger and -if applicable- behind the last seat row. It is a legal requirement (FMVSS 226) for vehicles with a gross vehicle weight rating (GVWR) of up to 10,000 lbs. without a partition wall and this is met.

# Benefits:

- Reduce the risk of complete ejections of occupants through the side windows during rollovers or side impact collisions.
- Reduce the risk of partial ejections of occupants through the side windows during rollovers or side impact collisions.

The safety effect of laminated glass is based on the high tear strength of the intermediate layer and its great adhesion to the glass. In the case of mechanical overloading, the glass breaks, but the fragments remain attached to the uninjured intermediate layer.

Note: The laminated glass is only available as a black-tinted variant, code W70.

# **Electrically Heated Windshield**

Carry Over Advanced New



A heated laminated windshield is mounted onto the vehicle. The heating consists of thin, wavy, vertically aligned heating filaments embedded within the laminated glass and is controlled by a rocker switch with an indicator light on the center console. Heating the windshield is only possible while the engine is running. In the event of high outside temperatures, the windscreen heater may not turn on.

It automatically switches itself off after approximately five minutes — or can be switched off manually by pressing the rocker switch again.

#### Benefits:

Prevents fogging. The heated windshield helps, e.g., to keep the windshield free from fogging, snow or ice in winter.

F50	Cowl platform	Compared to Sprinter 906		
1 30	Cowi piationii	Carry Over	Advanced	New



The cowl platform, is based on the cab chassis but without a wind-screen, roof frame, rear wall and doors. This type of vehicle provides upfitters a basis for fitting fully integrated superstructures e.g. campers or special-purpose solutions. The cowl version comes always without a driver and co-driver's airbag. Comfort seats with swivel base for driver and passenger are part of the vehicle configuration.

F61	Interior Rear View Mirror	Compared to Sprinter 906		
101	interior Rear View Willion	<b>Carry Over</b>	Advanced	New



An interior mirror is attached to the front windshield to provide rearward visibility.

#### Benefits:

- Manually adjustable for day and night
- Enhances safety

The interior mirror is particularly useful when reversing and when maneuvering at loading ramps. Allows the driver to keep an eye on the cargo compartment/passenger compartment.

Carry Over | Advanced

New

The electrically foldable mirrors, are only available in conjunction with the adjustable and heated exterior mirrors (F68) for vehicles up to 10,000 lbs. They can be operated using the button located in the control panel on the driver's door. The side mirrors can be conveniently folded when parking, and driving through a narrow road or car wash facility preventing any potential damage.

The code F64 is required for:

- Code JB6, Parking package with 360° camera
- Code JB7, Parking package with reversing camera



F68 Heated an

Heated and Electrically Adjustable Exterior Mirrors Carry Over Advanced New




The exterior rear view mirrors and the wide-angle mirrors are heated and electrically adjustable. The mirrors can be adjusted to the optimal position for the driver's visibility. Each mirror can be adjusted with switches located on the driver's door control panel. These switches allow for right-hand or left-hand exterior mirror adjustments. The heating for the mirror is regulated dependent on the exterior temperature, for temperatures below 59°F the heating is activated, and at 66°F it is deactivated again. This can be activated by another switch located on

the control panel.

#### Benefits:

- Rapid mirror adjustment following a change of driver
- Helps to prevent mirrors misting up or frosting over
- Allows quick and easy adjustment of the exterior mirrors following a change of driver. Also reduces misting or frosting over of the rear view mirror, and wide-angle mirror in cold or damp weather.

EA1	FA1 Lowered Cab Roof	Compared to Sprinter 906			
IAI	Lowered Cab Roof	Carry Over	Advanced	New	



In the case of a cab chassis without a rear wall and roof (code F28), the door portals and remaining roof structure are trimmed. A square tube construction is bolted in, providing both provisional rigidity and an attachment surface. This provisional structural rigidity must be accounted for in dimensional terms when planning and designing alcove based bodies. The auxiliary roof frame allows for mounting of additional

roof structures such as alcoves. The maximum dynamic support load is 220 lbs. / 100 kg. The top of the auxiliary roof frame is about 2.36" (60 mm) lower than that of the standard cowl and doors, code F28.

The lowered version is also painted in the body shop following modification. The standard-specification sun visors and grab handles are mounted. The roof paneling can be attached to the established securing points, but must be trimmed individually by the body manufacturer and adapted to the interior equipment. Alternatively, an upfitter can install their own construction if this has a rigidity equivalent to that of the original design.

#### Benefits:

- Caters to special body designs
- Allows a lower overall vehicle height
- Roof variant specially aligned with the requirements of camper van body manufacturers

This makes it possible to produce an alcove variant more closely aligned with the requirements of camper van manufacturers compared with the standard chassis. Thanks to pre-installation in the body shop, the overall vehicle height can be reduced — particularly for camper vans. A clearly defined attachment level is available to the body manufacturer — complex body shop modifications are not necessary.

FE9	FE9 Additional DIN-Slot	Compared to Sprinter 906		
I L7	Additional Div-Slot	Carry Over	Advanced	New



When ordering code FE9 a 1-DIN slot is included underneath the dashboard on the co-driver's side. This slot can be used for additional electronic devices. It comes with a cover for delivery and includes a cable set which reaches into the slot and offers the following connections:

- Terminal 15, Ignition
- Terminal 30, Battery plus
- Terminal 58d, Instrument lighting
- Terminal 31, Battery ground

FF0	Coat Hooks	Compared to Sprinter 906		
110	Coat Hooks	Carry Over	Advanced	New

The clothes hook in passenger compartment are within reach of the passengers on the restraint of the benches. Depending on the vehicle configuration:

- 1 coat hook at the back of the driver's seat
- 1 coat hook at the back of the passenger's seat, 2 hooks in conjunction with twin passenger seat (S23)
- 2 hooks at the back of the twin passenger benches in the passenger compartment
- 3 hooks at the back of the 3-seat benches in the passenger compartment

# Benefits:

Safe storage of clothing items.



# FF3

# **Cupholder Rear Compartment**

Compared to Sprinter 906

Carry Over Advanced

New



Cup holders are mounted between the rear seats on each bench. One cup holder can carry two cups or bottles with a diameter of up to 3.3" (84 mm). The cup holders can be ejected individually by pushing on its flap.

#### Benefits:

Allows drink containers to be put down safely in the passenger compartment.

FF4	Storage Compartment above Cabin	Compa	red to Sprint	er 906
114	Storage Compartment above Cabin	Carry Over	Advanced	New



The storage compartment above the roof paneling uses the space between the headliner of the cab and the vehicle's high roof (D03) as an additional storage facility. The compartment is accessible from the loading area and can support a load up to 77 lbs. (35 kg).

Aperture of the storage compartment: approx.  $51.97 \times 7.09$ " (1320 x 180 mm) with a depth of approx. 21.65 in (550 mm).

FF5	FF5 Shelf above Windshield	Compared to Sprinter 906		
113	Shell above Willushleiu	<b>Carry Over</b>	Advanced	New



The vehicles are fitted with storage plastic shelves for the driver and co-driver above the windshield. Openings in the storage shelves allow the occupants to easily see any stowed items from their seats. Each shelf has a dimension of 22.83 X 10.63" (580 mm X 270 mm) and has a carry capacity per shelf of approximately 5.50 lbs. (2.5 kg). A raised lip around the edge prevents stowed items from falling out. The side grab handles for the driver and co-driver are an integral part of the storage facility.

#### Benefits:

- Additional storage facility
- Additional grab handles for a safe hold

The storage compartment provides additional space for tidy storage of papers, documents or objects. The two grab handles also provide another option for holding on.

FF8	Overhead Storage Slot, Front Center	Compared to Sprinter 906		
110	Overnead Storage Slot, Front Genter	Carry Over	Advanced	New



An opening (1 DIN slot) is centrally located in the headliner above the windshield. This slot can be used for additional electronic devices. It comes with a cover for delivery and includes a cable set which reaches into the slot and offer the following connections:

- Terminal 15, Ignition
- Terminal 30, Battery plus
- Terminal 58d, Instrument lighting
- Terminal 31, Battery ground

#### Benefits:

Can accommodate 1-DIN-sized equipment. The slot can be used for installing 1-DIN-sized equipment (e.g., CB radio).

FG8	FG8 Cupholder Front	Compared to Sprinter 906		
1 00	oupholder Front	Carry Over	Advanced	New



With code FG8, a total of four-cup holders are included in the center console. The cup holders are suited for holding cans, cups or bottles up to 16 oz./500 ml. For cleaning, the cup holders can be removed.

FJ1	Hinged Lid for Storage Compartment	Compa	red to Sprint	er 906
'''	Tilliged Lid for Storage Compartment	Carry Over	Advanced	New



This equipment allows the customer to store items out of sight allowing for a tidy atmosphere. The center storage compartment on the instrument panel may be fitted with a hinged lid via code FJ1. Complementary to this code, FJ5 offers two hinged lids for storage compartments on the left and right side. The cup holders on the left and right outside are then omitted.

The hinged lids can be opened using the corresponding buttons and remain in position when opened. All compartments with lids are fitted with rubber inlays.

The Hinged lid for storage compartment, code FJ1, is required for the following option codes:

- Code E1B, Tray for smartphones incl. wireless charging
- Code FJ5, Hinged lid for storage compartments left and right
- Code HH4, Thermotronic automatic climate control

#### Benefits:

The storage compartment with hinged lid allows items such as a clipboard, personal items, documents (e.g., freight papers), maps, etc., to be stored safely out of sight and within easy reach.

FJ4	Storage compartment underneath	Compared to Sprinter 906		
	cockpit	Carry Over	Advanced	New



An open storage compartment is included on the co-driver's side. The dimensions of the storage compartment are 18.9 x 3.94 x 6.3" (480 x 100 x 160 mm) (Width x Height x Depth). FJ4 replaces the former lockable glove compartment.

FJ5	Hinged lid for storage compartments left	Compa	red to Sprint	er 906
гјо	and right	Carry Over	Advanced	New



This equipment allows the customer to store items out of sight and secure. The center storage compartment on the instrument panel may be fitted with a hinged lid via code FJ1. Complementary to this code, FJ5 includes two hinged lids for storage compartments on the left and right side. The cup holders on the left and right outside are then omitted. The hinged lids can be opened using the corresponding buttons and remain in position when opened. All compartments with lids are fitted with rubber inlays.

FI6	Central Area with 2 DIN Storage Comp. +	Compa	red to Sprint	er 906
ין ו	Air Vents	Carry Over	Advanced	New



The code FJ6 includes two DIN storage compartments and two additional air vents in the upper central area of the instrument panel. Each air vent can be individually adjusted. This layout of the central area is standard for vehicles without pre-installation for radio or multimedia system. The dimensions of the storage

compartments are 3.94 x 1.77 x 3.94" (100 x 45 x 100 mm) (Width x Height x Depth).



The code FJ7 includes a large storage compartment in the upper central area of the instrument panel and is only available when the air conditioning system code HH4/HH9 is omitted. The dimensions of this storage compartment are 18.11 x 3.94 x 4.72" (460 x 100 x 120 mm) (Width x Height x Depth).

FK3	3 Chrome Plated Radiator Grille	Compared to Sprinter 906		
110	omome riated Radiator Grine	Carry Over	Advanced	New



The code FK3 includes five chrome trim strips applied to the radiator grille and the grille frame comes always in the ordered vehicle color. The chromed radiator grille enhances the appearance of the vehicle.

FM3	Met Wiper System	Compared to Sprinter 906		
1 IVIS Wet	wet wiper system	Carry Over	Advanced	New



The adaptive wind-screen wiper system provides the driver with an ideal view - even during the cleaning process. The cleaning fluid is sprayed directly in front of the wiper blades through its small nozzles and is wiped away immediately. In result of the directed distribution, the amount of cleaning fluid needed can be reduced by up to 50 % while still obtaining ideal cleaning results.

FQ6	Lockable Storage Compartment above	Compared to Sprinter 906			
ruo	Windshield	Carry Over	Advanced	New	



The lockable compartment, code FQ6, is placed on the driver 's side above the windscreen and complements a shelf. The hatch (approx. 13" x 3" (330 x 77 mm) opens upwards and remains in position. It can be locked using the emergency key attached to the key fob. The maximum dimensions of the lockable unit correspond to the size of the shelf is approx. 22.83" x 10.63" (580 x 270 mm).

FR3

# Rear View Camera (Rear-View Mirror Display)

Compared to Sprinter 906

Carry Over | Advanced

New



For passenger, cargo and crew vans with the standard radio E10, the rear view camera FR3 is standard. This camera will display the area behind the vehicle, with the image appearing in the rear view mirror. This allows the vehicle to display areas that are not commonly visible to the driver. The image appears in the rear view mirror when shifting to reverse gear. The reversing camera switches off automatically

when the vehicle is driven in forward direction.

	FR7	Pre-Wiring Rear View Camera	Compared to Sprinter 906			
FR/	(Head Unit Display)	Carry Over	Advanced	New		

This code is only available for the cab chassis ordered with the MBUX multimedia system and includes the wiring harness located in the driver's seat frame. This allows the retrofitting of a Mercedes-Benz digital reversing camera. The wiring harness is already connected to the MBUX multimedia system and the reversing area is shown in the multimedia display.

Note: The MBUX multimedia system is only compatible with the original digital Mercedes Benz camera.

FR8	Rear View Camera (Head Unit Display)	Compared to Sprinter 906		
110	Real view Gainera (riead Gint Display)	Carry Over	Advanced	New



The reversing camera makes the rear area with an angle of 195° visible. When selecting the reverse gear the camera is activated and its picture displayed on the media system. The reversing camera switches off once the vehicle is driven forward at speeds > 10 mph (16 km/h). Yellow guide lines are displayed when reverse gear is engaged. They indicate the path which the vehicle would follow with the current steering wheel angle. The yellow guide lines are automatically adapted as the steering wheel angle changes. The outer guide lines symbolize the vehicle width including the outside mir-

rors. Via a switch on the media system, the reversing camera can also manually be activated when driving in forward direction at speeds of up to 18 mph (29 km/h). The camera can remain active even when the rear doors are open. In the media system the driver can choose different perspectives for viewing the rear area:

- Rear view
- Wide-angle mode:

The wide-angle mode provides assistance when reversing into traffic areas that are not clearly visible. The reversing area is shown as a three-part view. This provides a clear view into a traversing road in good time, e.g. when reversing out of a narrow lane.



Trailer mode supports the driver when reversing to a trailer by zooming to the trailer hitch. To do so, special guide lines are shown in the display in addition to the pictures recorded by the reversing camera.

For additional safety, the rear view camera is activated when the rear doors are opened even if the van is not in reverse gear.

The reversing camera will be added with the multimedia system code E3M/E4M and replaces the standard camera FR3.

> Mirror Holder for Vehicle Width 2150 up to 2300mm

**Compared to Sprinter 906 Carry Over** Advanced New

New



FS<sub>1</sub>

The exterior mirror is mounted on an extended mirror arm which improves rearward visibility, in case an extra-wide body is fitted. Code FS1 is for a vehicle width of 86 - 90" (2184 - 2286 mm)

**Exterior mirror extended Compared to Sprinter 906** FS<sub>2</sub> (for up to 96" box width) **Carry Over** Advanced



The standard exterior mirror is mounted on longer mirror arm and improves rearward visibility if an extra-wide body is fitted. Code FS2 is for a vehicle width of 90 - 92.9" (2190 - 2300 mm)

**Compared to Sprinter 906** FU<sub>5</sub> **Exterior Mirror without Indicator Carry Over** Advanced New



With code FU5, the exterior mirrors are fitted without turn signal indicators. Due to the omission of the indicators the mirror housing is not as wide, thereby overall width of the vehicle is reduced by approx. 0.78" (20 mm) each side. Other dimensions and the geometry of the mirror glass, also in combination with code FS2, extra-long mirror bracket, remain identical with those of the serial exterior mirrors. The mirror heating, code F68 as well as F64, is not available.

# FV1 Pre-Wiring Rear View Camera Compared to Sprinter 906 (Rear-View Mirror Display) Carry Over Advanced New

For passenger, cargo and crew vans, a reversing camera with rearview mirror display is standard. This analog camera can display the area behind the vehicle, which would otherwise not be immediately visible for the driver. The camera picture is displayed in the rearview mirror when shifting to reverse gear. The reversing camera switches off automatically when the vehicle is driven forward.

For cab chassis the pre-installation, code FV1, includes the required wiring harness and the display in the rear-view mirror. This allows later installation of an analogue reversing camera (NTSC 60 Hz). The disconnecting points of the included wiring harness are located inside the driver's seat box for the cab chassis. The upfitter must supply their own analog camera.

FW1	Rear Wall Deletion - Chassis Cab	Compared to Sprinter 906		
1 44 1	Real Wall Deletion - Chassis Cab	Carry Over	Advanced	New

The deletion of the cab rear wall allows upfitters to fit special bodies, which are accessible from the cab. The aperture is closed with a tarpaulin, which is necessary for transportation purposes.

The code FW1 is required when ordering one of the following equipment:

- Code F28, Cowl and doors
- Code F50, Cowl version
- Code SR8/SR9, Swivel base
- Code ZW4, Customer Winnebago C-Line



FW8	-W8 Deletion of passenger cab door, right	Compa	red to Sprint	er 906
PWO Deletion of passenger cab door, right	Carry Over	Advanced	New	

This option code, FW8, deletes the passenger door on a cab chassis. The opening is covered with a tarpaulin for transportation purposes.

FW9	FW9 Deletion of driver's cab door, left	Compared to Sprinter 906		
1 44 7	Deletion of univer's cab door, left	<b>Carry Over</b>	Advanced	New

This option code, FW9, deletes the driver door on a cab chassis. The opening is covered with a tarpaulin for transportation purposes.

FX4	Omit ASR-Off Function	Compa	red to Sprint	er 906
1 74	Offit ASK-Off Function	Carry Over	Advanced	New

With this code the ESP function can no longer be turned off via the instrument cluster or if ordered, via the multimedia system. Not choosing this deactivation function can prevent possible damage to the rear axle (or other parts), which may be caused by improper driving.

# Security Alarm w. Interior Motion Sensor

Carry Over Advanced New



The Anti-Theft Protection Package provides comprehensive protection for the vehicle and cargo. The battery-powered horn is not accessible from outside the vehicle and is independent of the on-board power supply. An inclination sensor integrated in the control unit offers tow-away protection. The anti-theft alarm system is armed automatically when the radio remote control is operated.

# Alarm is triggered if:


- A door is opened
- A door is opened from the inside
- The hood is opened
- The vehicle is raised at the front or rear
- If movement is detected inside the vehicle
- If the central locking system is unlocked using the key at a door other than the driver's door

#### Benefits:

- Additional anti-theft protection
- Comprehensive anti-theft protection for vehicle and load
- Audible alarm: intermittent sounding of the self-powered horn for approximately 25 seconds
- Visual alarm: the turn signal indicators flash for approximately four minutes at twice the normal rate

FY7 C	Optional 3- Button Keys	Compared to Sprinter 906		
' ' '	Optional 5- Button Reys	Carry Over	Advanced	New

The multi-button radio remote control allows for selective locking and unlocking of the load compartment (sliding and rear doors). For cab chassis, this function is available for programming of vehicle conversions/additions. When ordering the electric sliding door the multi-button radio remote control is required. The sliding doors



can then be lock and unlocked as well as opened and closed using the remote control key.

FZ9	Keys, Two Additional Masters	Compared to Sprinter 906	er 906	
1 2 7	Reys, Two Additional Masters	Carry Over	Advanced	New

Two extra master keys are provided in addition to the two keys supplied as standard.

#### Benefits:

Customer is provided with four keys (e.g., for taxi companies or large fleets).



# **Automatic Transmission**, **7G-TRONIC PLUS**

**Compared to Sprinter 906** 

Advanced Carry Over New



The Automatic Transmission 7G-TRONIC PLUS is electronically controlled with seven forward gears and one reverse gear. The gear ratios for the gear ranges are planetary gear sets. All the transmission functions and components for this transmission are combined in one assembly module. The integration of the electric controller unit in the transmission means that the interfaces to the wiring harness have been minimized. The service life can be increased. the fuel consumption reduced, the gearshift comfort improved and

maintenance intervals revised by using optimized transmission components, a new automatic transmission fluid and by reducing working pressure and implementing software modifications. The engine performance is transmitted via a torque converter with an integrated torque converter lock up clutch. The torque converter lock up clutch minimizes the performance, reducing slip of the torque converter. Depending on the rotational speed and engine load the torque converter lock up clutch is switched into all gears slip-controlled. With this system an almost deceleration-free and comfortable shifting is achieved. The 5th forward gear is designed as a direct gear. The 6th and 7th gear is conceived with longer ratio enabling potential reduction of fuel consumption through lower rotational speed.

# Benefits:

- Very smooth shifting
- Long service life and high reliability
- Low maintenance costs
- Low fuel consumption

# **Both Automatic Transmissions come with following functions:**

# Kick-down

The kick-down sets in when the accelerator is pushed past the pressure point. During this mode the acceleration is at its maximum. Depending on the engine rpm, the automatic transmission shifts to a lower gear and at maximum engine rpm to the next higher gear. The engine cannot be over-revved during this process. During kick-down the gear cannot be shifted using the switch paddles.

#### **Gear Shift**

To shift, the driver can use the gear shift located on the right side behind the steering wheel or the two flat rocker switches on the back of the steering wheel. The current driving mode is shown in the display of the instrument cluster.

Tech	Technical data				
Automatic trans-	G42				
mission	722.908 / T7C700				
Shift	7-speed, automatic				
Number of ratios	7 + R				
Gear ratio spread	6.016				
Weight complete	approx. 92.4 kg				
Transmission ratio					
1 <sup>st</sup> gear	4.377				
2 <sup>nd</sup> gear	2.859				
3 <sup>rd</sup> gear	1.921				
4 <sup>th</sup> gear	1.368				
5 <sup>th</sup> gear	1				
6 <sup>th</sup> gear	0.82				
7 <sup>th</sup> gear	0.728				
8 <sup>th</sup> gear	n/a				
9 <sup>th</sup> gear	n/a				
Reverse gear	-3.416				

To put the transmission into drive (D) or reverse gear (R), the brake has to be engaged and the gear shift pushed past the first resistance - up for reverse gear, and down for drive. To put the transmission into neutral gear (N) from Drive (D) the lever is pushed up, while from reverse gear (R) the gear shift is pushed down to the first resistance setting. In order to switch from park (P) to neutral (N), the break must be engaged and the gear shift pushed either up or down to the first resistance. When in drive (D), the driver can shift manually using the paddle switches on the steering wheel. To return to automatic, mode position (D) must be re-selected. To put the transmission into park (P), the button on the gear switch must be pushed.



R = Reverse gear

- N = Neutral
- P = Park with parking lock
- D = Drive

G43	Automatic Transmission,	Compared to Sprinter 906		er 906
	9G-TRONIC	Carry Over	Advanced	New



The Automatic Transmission 9G-TRONIC is fully electronically controlled with nine forward gears and one reverse gear. The gear ratios for the gear ranges are realized with planetary gear sets. All transmission functions and components are combined in one assembly module. The fully integrated transmission controller unit is located in the automatic transmission. This minimizes the number of interfaces to the vehicle wiring harness.

The fully integrated transmission control has the following advantages:

- High electromagnetic compatibility (prevention of interaction between multiple electronic components)
- Fast current control as well as the compensation of on-board electrical system fluctuations, which leads to increased shift quality.
- Accurate determination of measurements relevant to shift operations and faster evaluation of the measured values

This automatic transmission excels due to the following features that increase its service life, reduce fuel consumption and increase smoothness of gear changes:

- Transmission set-up with nine gears and gear ratio spread of 9.156
- Optimized transmission components
- Low working pressure
- Transmission housing with mechanical transmission components

# **Both Automatic Transmissions come with following functions:**

Technical data				
Automatic trans-	G43			
mission	725.018 / W9B500			
Shift	9-speed, automatic			
Number of ratios	9 + R			
Gear ratio spread	9.156			
Weight complete	approx. 95 kg			
Transmission ratio				
1st gear	5.503			

#### Kick-down

The kick-down sets in when the accelerator is pushed past the pressure point. During this mode the acceleration is at its maximum. Depending on the engine rpm, the automatic transmission shifts to a lower gear and at maximum engine rpm to the next higher gear. The engine cannot be over-revved during this process. During kick-down the gear cannot be shifted using the switch paddles.

2 <sup>nd</sup> gear	3.333
3 <sup>rd</sup> gear	2.315
4 <sup>th</sup> gear	1.661
5 <sup>th</sup> gear	1.211
6 <sup>th</sup> gear	1
7 <sup>th</sup> gear	0.865
8 <sup>th</sup> gear	0.717
9 <sup>th</sup> gear	0.601
Reverse gear	-4.932

#### **Gear Shift**

To shift the vehicle into different gears, the driver can use the gear stalk located on the right side behind the steering wheel or the two paddle shifters on the back of the steering wheel. The current driving mode is shown in the display of the instrument cluster.

To put the transmission into drive (D) or reverse gear (R), the brake has to be engaged and the gear shift pushed past the first resistance - up for reverse gear, and down for drive. To put the transmission into neutral gear (N) from Drive (D) the lever is pushed up, while from reverse gear (R) the gear shift is pushed down to the first resistance setting. In order to switch from park (P) to neutral (N), the break must be engaged and the gear shift pushed either up or down to the first resistance. When in drive (D), the driver can shift manually using the paddle switches on the steering wheel. To return to automatic, mode position (D) must be re-selected. To put the transmission into park (P), the button on the gear switch must be pushed.



R = Reverse gear

N = Neutral

P = Park with parking lock

D = Drive

H00	Warm/Cool Air Duct to Rear	Compared to Sprinter 906		er 906
	Compartment	<b>Carry Over</b>	Advanced	New



The hot-air duct to the rear passenger compartment is installed between driver and co-driver's seats. The hot air duct supplies the rear passengers with warm air when the air distribution control is set to ventilate the foot well.

#### Benefits:

- Enhanced comfort for passengers in the rear compartment
- Improves the warm/cool air supply to the passenger
- Improves passenger comfort and well-being by providing enhanced heating/cooling

H01

# **Heat Insulation, Rear Compartment**

**Compared to Sprinter 906** 



Advanced

New



Insulation material is fitted up to the belt rail in the sidewalls of the load/passenger compartment and in the rear doors.

#### Benefits:

Reduces heat loss at low ambient temperatures. The insulation reduces heat losses at low outside temperatures.

H04	Heat Insulation, Front Compartment	Compared to Sprinter 906			
1104	rieat insulation, i font compartment	Carry Over	Advanced	New	



Code H04 includes the insulation mats in the front doors and in the rear- / partition wall. The insulation reduces heat losses at low outside temperatures.

#### Benefits:

Reduces heat loss at low ambient temperatures. The insulation reduces heat losses at low outside temperatures.

H08 Air Conditioning Rear, Roof	Air Conditioning Rear, Roof-Mounted	Compa	red to Sprint	er 906
1100	All Collattioning Real, Root-Woulted	Carry Over	Advanced	New



The rear air conditioning system is mounted onto the rear part of the roof and partially on the inside roof of the vehicle that comfortably cools the rear compartment. Compared to MY18 the roof unit is located more towards the rear of the vehicle.

The code H08, is powered by the same compressor as the front air conditioning system, and together has a maximum cooling output of 47,800 BTU (14 kW). This system comes with two evaporator/fans and works in fresh-air and recirculated-air mode. The quality of the interior air is ensured by pollen and particle filters.

The AC unit is operated via the rocker switches to manage venting levels (seven venting levels) and the desired temperature. The temperature is controlled automatically through air blending vents. Depending on the vehicle length, the cool air can be distributed over up to 16 individually adjustable air vents in the ceiling. If required, these may be closed completely. Because of the roof canal, the interior height is reduced by 3.94" (100 mm). The evaporator is mounted underneath a hood on the top of the vehicle roof. This increases the vehicle height by about 7.48" (190 mm). The roof hood is only available in color anthracite MB 9B51 but can be painted.

#### Benefits:

- Optimizes interior climate in rear section
- Must-have for comfort and well-being for passengers in the rear for hot climates
- Improves interior air quality

# Fuel-Fired Pre-Heater/Booster (17K BTU)

Compared to Sprinter 906

Carry Over Advanced

New



In addition to the heater booster, with the auxiliary hot-water heater, the departure time can be programmed in the instrument cluster using the stationary heater button in the climate control panel on the multi steering wheel.

The colors of the indicator lamps above the stationary heater button have the following meanings:

- blue: auxiliary ventilation is switched on
- red: auxiliary heating is switched on
- yellow: departure time is preselected

In ventilation mode, the climate-control unit actuates the blower motor and the indicator lamp in the stationary heater button continues to light up in blue. The maximum ventilation/heating time is 50 minutes. The auxiliary heater has a maximum heating capacity of 5.5 kW and is supplied with fuel from the fuel tank until the fuel supply drops to 15 I/1.3 gallons. The air is supplied to the interior through the existing air outlets in the instrument panel or optionally H00 and H13.

#### Benefits:

- Comfortably warm interior
- Aids defrosting of the windows
- Protects the engine by preheating the coolant prior to starting

This system is particularly recommended for vehicles with engines which will be used in very cold climate regions. Since these engines are extremely efficient, their thermal energy may not always be sufficient in extremely low ambient temperatures. With this option it allows for a comfortable level of warmth in the cab. The stationary heating function allows the interior to be warmed even before the engine is started, so when the driver steps into the cabin it is pleasantly warm right from the start.

H13 Rear Cabin Heater and Vents	Rear Cabin Heater and Vents	Compared to Sprinter 906		
1113	Real Cabili fleater and Vents	Carry Over	Advanced	New



The additional heat exchanger is mounted underneath the vehicle floor on the left side behind the B-pillar. With this comes an air duct in the rear passenger/load compartment on the left side on top of the wood or plastic flooring. The heat exchanger can be activated/deactivated using the climate control panel and set to three different levels. It is connected to the water circuit of the front heating system, and is only operational when the engine is running. The code HH4, THERMOTRONIC, is only available in combination with

code H08 or code HK4, Roof-mounted air conditioning system.

#### Benefits:

Provides warm air flow for rear passenger compartment. Improved heating effectiveness throughout the load/passenger compartment with the engine switched on.

Н	1	5/
H	1 1	6

# Heated Front Passenger/Driver Seat

Compared to Sprinter 906

Carry Over Advanced

New



The heated seats are equipped with heating filaments in the seat cushion and backrest which are controlled by three-stage switches in the front door panels. When stage three is turned on for rapid heating, the system will run for approx. 7 minutes then automatically switches to stage two. After approx. 10 minutes, the seat heating automatically switches to stage one. The seat heating is automatically switched off after a further 20 minutes. It can be switched off manually at any time.

#### Benefits:

Cold seats can be warmed up immediately, even before the vehicle heating system has had a chance to warm the interior. In cold weather, comfort is ensured right from the start of the journey.

H11	Front-to-Rear Outlet in Instrument Panel	Compared to Sprinter 906			
1111	110111-to-Real Outlet III IIIsti uillelit I allei	Carry Over	Advanced	New	



Two additional air vents are installed in the center storage compartment on the instrument panel. This vents are adjustable and distribute exclusively cooled air. Heating up is not possible in this case.

The air vents must be ordered with:

- Code E1B, Tray for smartphones incl. wireless charging
- Code F50, Cowl version

H20	Heat-Insulating Glass	Compared to Sprinter 906		
1120	ricat-insulating Glass	Carry Over	Advanced	New

The code H20 includes green-tinted laminated safety glass for the windscreen and single-layer safety glass for all other windows. This ensures less heating up in the cockpit as well as in the load or passenger compartment even when the vehicle is exposed to very intensive sunlight.

H21	Windshield with Filter Band	Compa	red to Sprint	er 906
	Windshield with Filter Band	Carry Over	Advanced	New



Green-tinted laminated safety glass with a darker tinting along the upper edge of the windscreen and a mounting plate for the interior mirror. The band filter reduces dazzle when the sun is low in the sky, but without impairing the driver´s view of the traffic. The mounting plate allows an easy retrofitting of the interior mirror.

#### Benefits:

- Reduces heating of the interior
- Prevents dazzle when the sun is low
- Enhances the look of the vehicle

The tinting reduces heating of the interior when the vehicle is exposed to direct sunlight, and thus also reduces heating of the steering wheel and dashboard. The filter band reduces dazzle when the sun is low in the sky, but without impairing the driver's view of traffic lights.

H22	Rear Window Defroster	Compared to Sprinter 906		
	Real Willdow Dellostel	Carry Over	Advanced	New



Windows with heating filaments are fitted in the rear doors. The rear window heating function is switched on by a switch with integral indicator light. The rear window heating function can only be switched on when the engine is running. It switches off automatically after approximately 5 minutes, or can also be switched off manually

#### Benefits:

- Ice on the rear windows is quickly thawed
- No fogging of rear windows
- Improved rear view of traffic

Prevents fogging of the rear windows in damp weather and at low outside temperatures. Ice on the rear windows is quickly thawed. Unimpeded rearward visibility ensures safe driving and maneuvering.

H72 Roof Fan, Electric	Compared to Sprinter 906			
11/2	Roof Fall, Liectric	Carry Over	Advanced	New

The electric roof fan is installed centrally on the roof towards the sliding door and increases the rate of air intake in the load compartment and also provides ventilation. It is operated using the button located right of the steering wheel. Pressing the upper section of the




roof ventilator button actuates the roof fan motor and the air is drawn out of the vehicle's load compartment and the lower section start the ventilation.

- Air delivery: 350 m<sup>3</sup>/h
- Max. power input: 32 W
- Roof assembly: overall height 4.92" (125 mm) increased

#### Benefits:

Improves air intake and ventilation in the load compartment.





Two water lines (supply line/return line) are routed under the floor panel on the left-hand side of the vehicle, extending after the B-pillar. The ends of the two lines are connected by a hose. This allows an easier fitting of aux. heater exchanger from the accessories range. The opening in the floor (cargo/passenger van) /wooden floor for the warm air ducting and electrical parts e.g. climate control panel, wiring harness are not included.

#### Benefits:

Simplifies installation of the aftermarket heat exchanger in the rear passenger compartment

The pre-installation package is recommended upfitters who offer their own and not ex-factory hot-water heating systems.

H91	Deletion Air Conditioning System	Compared to Sprinter 906		
1171	Defetion All Conditioning System	Carry Over	Advanced	New

The code H91 is a heating and ventilation system without integrated air conditioning, air recirculation mode and any dust filter. The system is operated via the heating control panel placed in the upper center console.

HH2	Heater, Auxiliary Electric Hot Air	Compared to Sprinter 906		
11112	Heater, Adxillary Liectric Hot All	Carry Over	Advanced	New



The heater booster consists of radiator elements (fins) that are fitted with PTC (positive temperature coefficient) resistors and are held together in a mounting frame by spring clips. When an electric voltage is applied to the heater elements, an electric current flows through the PTC resistors, which heat up. The fins absorb the heat and radiate it to the passing air. As soon as the engine is running, the electric

heater booster steadily increases its power from 0 to 100% in the space of 28 seconds. The heater booster is situated in close proximity to the air outlets, to keep heat losses to a minimum. The warmed air is circulated into the interior via the vehicle heater/blower system.

#### Switch-on conditions:

Coolant temp. < 80 °C (176°F) and ambient temp. < 10 °C (50°F).

### Switch-off conditions:

Coolant temp. > 80 °C (176°F) and ambient temp. > 13 °C (55°F).

#### Benefits:

- Aids quick defrosting of the windows
- Quick defogging

- Quicker warming of the interior
- Environmentally friendly, robust, long service life

The electric PTC heater booster is environmentally friendly, since no emissions are generated. Despite its lightweight and compact design it is robust, has a long service life and is highly efficient. The PTC resistor has self-regulating properties that prevent overheating. The heater booster accelerates defrosting of windows and counteracts window fogging. It provides faster heating of the interior and improves comfort on cold days.

HH4	Thermotronic automatic climate control	Compared to Sprinter 906			
11114	Thermotrome automatic climate control	Carry Over	Advanced	New	



In addition to the TEMPMATIC standard A/C, the HH4 air conditioning system THERMOTRONIC is also available. HH4 is a single-zone automatic air-conditioning, which provides a constant climate by taking into account external factors such as solar irradiation, exterior and interior temperature.

The installed sensors monitor interior temperature, air volume and air distribution when the AUTO function is activated and will regulated the conditions automatically. A filter with a special layer of activated carbon protects from unpleasant odors, dust, pollen and harmful substances. The integrated dehumidifier reliably prevents the windows from steaming up.

Note: The front-to-rear outlets on the instrument panel, Code H1I, exclusively distributes cool air.

HH9 Air Co	Air Condition, Front	Compared to Sprinter 906		
11117	All Collation, Front	Carry Over	Advanced	New



The code HH9, air conditioning system TEMPMATIC, is standard equipment for all vehicles. The Tempmatic enables a pleasant interior climate for the passengers in different weather conditions. The Tempmatic is a semi-automatically regulated air conditioning system with a maximum cooling output of approx. 24K BTU (7 kW) and is controlled by buttons and switches integrated in the climate control. Ventilation ensures air circulation in the vehicle interior. The fresh air is cleaned by a particle filter. The user can switch select between fresh

air and air recirculation mode. The airflow can be set in seven steps and a temperature selector switch is used to set the desired temperature. Apart from the display of the control unit the air-conditioner settings can also be viewed on the optionally available multimedia system, code E3M/E4M.

# Benefits:

- An pleasant interior temperature is maintained even in hot weather
- Integrated filter protects against dust and pollen
- Dehumidification prevents fogging in cold, damp weather
- The filter protects against allergic reactions by preventing pollen, dust and odors from entering the vehicle.

HK4

# **Rear Air Conditioner Heavy-Duty**

**Compared to Sprinter 906** 

Carry Over

Advanced

New



The rear air conditioning system is mounted onto the rear part of the roof and partially on the inside roof of the vehicle that comfortably cool the rear compartment.

The high-performance air-conditioning system, code HK4, has its own refrigerant compressor condenser with a maximum cooling output of 37,500 BTU (11 kW). In combination with one of the

front AC units, code HH9/HH4, the total output is 62,400 BTU (18 kW). Temperature and venting levels can be activated and set for cab and the rear passenger compartment separately.

The AC unit is operated via the rocker switches to manage venting levels (seven venting levels) and the desired temperature. The temperature is generated automatically through air blending vents. Depending on the vehicle length the cooled air can be distributed over up to 16 individually adjustable air vents in the ceiling. If required, these may be closed completely. Because of the roof canal the interior height

is reduced by 3.94" (100 mm). The evaporator is mounted underneath a hood on the top of the vehicle roof. This increases the vehicle height by about 7.48" (190 mm). The roof hood is only available in color anthracite MB 9B51 but can be painted.



HY1

Remote control for auxiliary heater

**Compared to Sprinter 906** 

Advanced Carry Over

New

The radio remote control allows turning the stationary heater on and off from a distance and thereby ensures pleasant temperatures in the vehicle interior already when getting in. In addition, the heated interior can ensure fog-free windows already before the start of the trip. The driver can set the departure time with the radio remote control (within 300 m of the vehicle) or in the instrument cluster. The vehicle then automatically calculates the activation time of the auxiliary heating to reach the preset interior temperature by the time of departure in dependence of the outside temperature and the weather conditions. The maximum heater operating time is 50 minutes.

HZ9

Fuel-Fired Heater Booster (18,800 BTU)

**Compared to Sprinter 906** 

Carry Over Advanced

New



The 18,800 BTU (5.5 kW) heater booster (for diesel engines only) can only be activated when the engine is running. The heater booster is a compact water heater that is connected to the engine coolant circuit. The heater booster can be activated manually with the stationary heater button in the climate control panel or automatically as required at an outside temperature of less than 32 F (0 °C). The indicator lamp in the stationary heater button continues to light up in red when the heating is switched on.

The air is supplied to the interior through the existing air outlets in the instrument panel or if optionally fitted with H00 and H13. After the heater booster has been switched off, the coolant pump and the burner blower continue running for approximately 3 minutes, then switch off automatically.

#### Benefits:

- Engine reaches optimal operating temperature quickly
- Faster heater response

This system is particularly recommended for vehicles with engines that will be used in very cold climate regions. Since these engines are extremely efficient, their thermal energy may not always be sufficient in extremely low ambient temperatures. This helps to guarantee a comfortable level of warmth in the cab.

l11	Speedometer, miles/km	Compared to Sprinter 906		
,,,	Specuometer, innes/ kin	Carry Over	Advanced	New



All vehicles with country code USA display mph and Fahrenheit in the instrument cluster via code J11.

#### Benefits:

The speed indication in the digital display can be given in km/h and mph.

J1V	Pre-installation blind spot assist	Compared to Sprinter 906		
) I V	Fre-installation billio spot assist	Carry Over	Advanced	New

Blind Spot Assist and Exit Warning is offered on cab-chassis to increase the safety and comfort of the customers.

# Blind Spot Assist provides:


- Visual and acoustic warning to alert the drivers when changing lane or reversing
- If a vehicle is detected in the blind spot, red triangle appears in the corresponding side mirror
- If the respective turn signal is activated despite this warning, the triangle starts to flash quickly and acoustic warning is sounded

### Exit Warning provides:

- Visual and acoustic warning to alert of an approaching vehicle when exiting the driver and/or passenger doors
- Available only when the Blind Spot Assist is active and up to three minutes after turning off the ignition.

Pre-installation of Blind Spot Sensor (J1V) package includes:

2 Blind spot sensors



- 2 Plastic brackets
- 2 Covers
- Wiring harness interface placed in the driver seat box

Blind spot sensor must be placed in the specified area provided by Mercedes-Benz, in the rear of the vehicle. For more information, please refer to the technical bulletin 'Installation of Blind Spot Sensor (J1V) available on <a href="https://www.upfitterportal.com">www.upfitterportal.com</a>.

<b>I51</b>	Fuel Gauge, Optimized for Aux. Fuel Tap	Compared to Sprinter 906		
J	Tuel Gauge, Optimized for Aux. I del Tap	Carry Over	Advanced	New

In the standard specification, the fuel level display in the instrument cluster is controlled solely by the fuel consumption as calculated by the on-board computer. The level is only reconciled with the fuel level sensor in the tank and corrected when refueling is detected. With this code, the fuel level display in the instrument cluster is reprogrammed so that it is solely controlled by the fuel level sensor in the tank, and shows the approximate amount of fuel remaining in the tank.

# Benefits:

- The approximate amount of fuel remaining in the tank is shown in the instrument cluster
- Protection against unexpectedly running out of fuel due to an incorrect fuel level shown in the instrument cluster
- This code is recommended for vehicles that operate auxiliary consumers via the KL1 auxiliary fuel tap

<b>J</b> 52	Engine Oil Level Display at Cold Start	Compa	Carry Over Advanced New			
J32	Lingine On Level Display at Cold Start	Carry Over	Advanced	New		



When parking the vehicle for a longer period of time, the last saved oil level is displayed at the start of the engine. The notification must be acknowledged by the driver. In addition, the oil fill level can be accessed via the service menu on the instrument cluster. It also scans a too low/high oil level in order to prevent engine damage.

# Seat belt warning for passenger seat

**Compared to Sprinter 906** 

Carry Over Advanced New



The seat belt warning for driver's seat, code J58, is now complemented by the seat belt reminder for passenger seat, code J55. The seat belt reminder for driver and co-driver increases the passive safety level. An optical signal in the instrument cluster reminds the driver or co-driver to buckle up when starting the vehicle. If this is ignored and the vehicle is in motion 15 mph (25 km/h) an acoustic signal sounds.

158	Seat belt reminder, driver	Compared to Sprinter 906		
100	Seat beit reillilider, driver	Carry Over	Advanced	New



An optical signal in the instrument cluster reminds the driver to buckle up when starting the vehicle. If this is ignored and the vehicle is in motion 15 mph (25 km/h) an acoustic signal sounds.

#### Benefits:

Reminds the driver to fasten the safety belt, thereby indirectly increasing passive safety.

165	Outside temperature gauge	Compared to Sprinter 906			
100	Outside temperature gauge	<b>Carry Over</b>	Advanced	New	



The temperature sensor is mounted in the front bumper and displays the current outside temperature in the instrument cluster.

Displays the current outside temperature. The temperature display gives the driver advance warning of icy conditions.

IA7	JA7 Blind spot assist	Compared to Sprinter 906		
JAZ	billia spot assist	Carry Over	Advanced	New



The Blind Spot Assist monitors the rear and side areas of the vehicle using two short-range radar sensors located in the rear bumper. The detection range covers an area of 137" (3.5 m) of both sides of the vehicle and 118" (3 m) to the rear starting at the B-pillar. If a vehicle is detected in the blind spot, a red triangle appears in the corresponding side mirror. Should the driver activate the indicator to change lanes despite this optical warning, the red triangle will start to blink and an acoustic signal will sound. In addition, this assistance system can be activated or deactivated manually via the menu on the on-board computer or the multimedia system.

# The Blind Spot Assist includes following functions:

#### Rear Cross Traffic Alert

Automatic braking to avoid collision with traffic crossing the vehicle's path (e.g. vehicles, pedestrians) when reversing. If an object is registered, the warning symbol on the corresponding side mirror lights up in red and additionally,



an acoustic warning signal sounds. In combination with the parking package, code JB6/JB7, a warning signal appears in the multimedia system in case of critical situations

# **Exit Warning**

If an approaching vehicle is registered, the exit warner can alert the passengers when exiting the vehicle. The system is only available when the Blind Spot Assist is activated and up to three minutes after turning off the ignition. If an object with little safety distance is registered while the cabin doors are opened, an optical and acoustic warning follows. The exit warning is not issued for sliding doors and rear doors.

#### Benefits:

Aids in lane changes can help to prevent blind spot-related collisions.

**Notice:** Blind Spot Assist is not available when driving with a trailer.

JA8	Crosswind assist	Compared to Sprinter 906		
JAO	Crosswilla assist	Carry Over	Advanced	New



The Crosswind Assist detects sudden strong wind blasts impacting laterally the vehicle and helps to avoid that the vehicle unintentionally drifts away via targeted, one-sided intervention on the brake. The Crosswind Assist works at a speed from 50 mph / 80 km/h up to maximum vehicle speed. When a wind blast is registered the wheels facing the wind side will brake according to the situation. The braking pressure depends in this case on the wind strength. The system is principally activated and can only be deactivated in very certain use cases involving very large upfits on the vehicle. Please contact your nearest authorized Mercedes-Benz dealer for more information. In case of a considerably noticeable system intervention, the driver is informed via the in-

strument cluster. Slight or not noticeable system intervention will not be notified. When the system recognizes a safety critical situation (for example ESP-intervention, aquaplaning) the Crosswind Assist will not intervene. The steering behavior gives information whether the driver is active and compensates itself wind blasts through steering correction. In this case the intervention of the system will diminish.

#### Benefits:

- Helps to keep the vehicle on course in strong crosswinds
- Corrects the course by means of automatic braking intervention
- Helps to avoid inappropriate reactions by the driver

Carry Over | Advanced

New



This assistance system can detect road signs, such as speed limit, no entry and no passing zones using a multifunction camera mounted to the inside of the windshield. It can recognize signs on the side of the road, on overhead gantries and in construction sites. Their data is compared with the information of the navigation system and is displayed in the instrument cluster and in the navigation map view. The connection to the navigation system ensures that the driver receives information on the current speed limit and other important restrictions even when no road signs are present. In the case of restricted access with corresponding signage, a visual and acoustic warning is additionally output in the instrument cluster.

A visual and acoustic warning can also be issued when a speed limit is exceeded. This can be selected and configured using the head unit. The driver can select the operating modes visual warning, visual, and acoustic warning off. A maximum of two speed limits and additional signage are shown at the same time. If several speed limits are detected, the lowest speed limit is displayed.

JB4 Active lane keeping assist


Compared to Sprinter 906

Carry Over | Advanced | New



The lane assist detects when the vehicle crosses lane markings and is activated at speeds between 37 mph (60 km/h) and the maximum speed. The camera registers clear road markings by comparing the difference in contrasts of road surface and clear road markings. An electronic control unit processes the camera data, the driver's activity, and calculates if a lane change is intentional or not. If an un-intentional lane change is registered the assistance system sends out an acoustic, visual and, haptic warning to the driver through vibrations

on the steering wheel. If the vehicle un-intentionally crosses a solid lane marking and the driver does not respond to the warning, the Active Lane Keeping Assist will correct the vehicle's course through targeted brake interventions on one side. If the driver indicates activity before or during the intervention by the brake system, the intervention is cancelled. The Assist can be activated/deactivated in the onboard computer and, if optioned with on the multimedia system. If a lane-correction brake application occurs, a display appears in the multifunction display.







In addition to twelve distance sensors the 360° camera system has four digital cameras. One camera behind the radiator trim, one in each side mirror housings and one on the rear roof. The parking system uses picture data to generate various views of the vehicle's surroundings which are shown in real time in the multimedia display. The views can be generated either from one camera or from four cameras. Depending on the view, dynamic guide lines are displayed to assist the driver. They indicate the path which the vehicle would follow with the current steering wheel angle. The yellow guide lines are

automatically adapted as the steering wheel angle changes. The outer guide lines symbolize the vehicle width including the outside mirrors.

Via a switch on the media system the reversing camera can also manually be activated when driving in forward direction at speeds of up to 18 mph (29 km/h). The camera also works with opened rear doors. The cameras cover an area of about 118 inch (3 m) in front and behind, and about 98 inch (2.5 m) to the left and right side of the vehicle.

JB6 requires F64 and is only available for vehicles below 10,000lbs.

#### Additional features:

#### **Parktronic**

The Parktronic is an electronic parking aid with ultrasound and uses six distance sensors in the front bumper and six distance sensors in the rear bumper to monitor the vehicle 's surroundings. The Parktronic provides a visual and acoustic indication of the distance between the vehicle and an obstacle. The volume of acoustic warnings can be adapted in the multimedia system.

# Rear Cross Traffic Alert (with code JA7, Blind Spot Assist)

Automatic braking to avoid collision with traffic crossing the vehicle'spath (e.g. vehicles, pedestrians) when reversing. If an object is registered the warning symbol on the corresponding side mirror lights up in red and additionally, an acoustic warning signal occurs. A warning signal appears in the multimedia system in case of critical situations.

# **Drive Away Assist**

If an obstacle is registered in the driving path, it temporarily limits the driving speed to 1.8 mph (3 km/h). In critical situations a warning symbol is displayed via the multimedia system.

JB7 Parking package	Compared to Sprinter 906			
יטנ	I alkilig package	Carry Over	Advanced	New



The parking system is using twelve distance sensors and the reversing camera. It supports the driver during the parking procedure, when maneuvering in confined spaces and when driving out of exits.

The parking system ensures greater safety when parking and maneuvering due to:

- Visual and acoustic warnings of objects in front of and behind the vehicle as well as at the side of the vehicle
- Speed limitation when driving off if obstacles are detected in the direction of travel (Drive Away Assist)

JB7 uses one digital camera on the rear roof end (FR8). Dynamic guide lines are displayed when the reverse gear is engaged and irrespective of the current wheel angle. If the rear door is open, this is indicated in the view.

#### **Additional features:**

#### **Parktronic**

The Parktronic is an electronic parking aid with ultrasound and uses six distance sensors in the front bumper and six distance sensors in the rear bumper to monitor the vehicle's surroundings. The Parktronic provides a visual and acoustic indication of the distance between the vehicle and an obstacle. The volume of acoustic warnings can be adapted in the multimedia system.

# Rear Cross Traffic Alert (with code JA7, Blind Spot Assist)

Automatic braking to avoid collision with traffic crossing the vehicle'spath (e.g. vehicles, pedestrians) when reversing. If an object is registered the warning symbol on the corresponding side mirror lights up in red and additionally, an acoustic warning signal occurs. A warning signal appears in the multimedia system in case of critical situations.

# **Drive Away Assist**

If an obstacle is registered in the driving path, it temporarily limits the driving speed to 1.8 mph (3 km/h). In critical situations a warning symbol is displayed via the multimedia system.

IB8	360 degree camera	Compared to Sprinter 906		
JDO	300 degree camera	Carry Over	Advanced	New



In addition to twelve distance sensors the 360° camera system has four digital cameras. One camera behind the radiator trim, one in each side mirror housings and one on the rear roof. The parking system uses picture data to generate various views of the vehicle's surroundings which are shown in real time in the multimedia display. The views can be generated either from one camera or from four cameras. Depending on the view, dynamic guide lines are displayed to assist the driver. They indicate the path which the vehicle would follow with the current steer-

ing wheel angle. The yellow guide lines are automatically adapted as the steering wheel angle changes. The outer guide lines symbolize the vehicle width including the outside mirrors.

Via a switch on the media system the reversing camera can also manually be activated when driving in forward direction at speeds of up to 18 mph (29 km/h). The camera also works with opened rear doors. The cameras cover an area of about 118 inch (3 m) in front and behind, and about 98 inch (2.5 m) to the left and right side of the vehicle.

JF1 Rain sensor Compared to Sprinter 906

Carry Over Advanced New



The code JF1, Rain sensor, automatically regulates the activity of the wind-screen wiper when set to interval. It is located centrally at the top behind the wind screen and registers wetness levels on the sensor surface. The rain sensor can be set to two different wiping speeds and the sensitivity of both settings can be further differentiated.

The code JF1 is required for the following equipment:

- Code FM3, Wet wiper system
- Code HH4, Thermotronic automatic climate control

JH3	Communication module (LTE) for	Compared to Sprinter 906		
JIIO	dig. services	Carry Over	Advanced	New

The Communication Module (LTE) for Digital Services is standardly integrated in every U.S. vehicle. The built-in SIM card is required for connectivity services and provides a fast and reliable LTE internet connection used for the Emergency Call System, Live Traffic Information, and other Mercedes me connect services. Use of Mercedes me connect services requires the customer to register through the Mercedes me connect Portal and accept the Terms of Use in addition to an authorized dealer linking the vehicle to the customer's account, all of which can be done on the Mercedes me connect Portal.

IK5	Instrument cluster with color display	Compa	red to Sprint	er 906
JICO	mistrument cluster with color display	Carry Over	Advanced	New



JK5 has two large chrome-lined analogue displays for vehicle speed in km/h or mph, engine rpm, fuel fill level, and temperature. A centrally placed high-resolution 5.5" color display allows the driver to easily view and browse the menu using the upper left touch-control panel on the multifunctional steering wheel.

Depending on the vehicle equipment, all vehicle information can be accessed:

#### Navigation

- Radio
- Media
- Telephone
- Service
- Vehicle Settings
- Assistance
- Trip computer with ECO-Score and average fuel consumption

JK5 is required for the following options:

- Code E4M, MBUX Multimedia system with 10.25-inch Touchscreen
- Code ET4, Active Distance Assist DISTRONIC
- Code JA9, Traffic Sign Assist

JWO	Backup alarm	Compared to Sprinter 906		
7000	Dackup alaitii	Carry Over	Advanced	New

When reverse gear is selected with the ignition switched on, an audible signal (~90dB) is activated. If reverse gear is engaged twice within five seconds, the volume of the reversing warning signal switches to the quieter setting. This procedure must be repeated every time a reversing operation is to be performed with reduced signal volume. The reversing warning system cannot be switched off. Switching off the ignition reactivates the default setting. The horn for the reversing warning system is normally fitted on the inside of the end cross member. A sticker stating "Engage reverse gear twice in quick succession to set the reversing beeper to the quieter nighttime setting" is enclosed with the vehicle document wallet.

#### Benefits:

An audible warning signal alerts passerby's that a vehicle is reversing.

JW2	Deactivation lamp monitoring failure	Compared to Sprinter 906		
J V V Z	Deactivation famp monitoring familie	Carry Over	Advanced	New

This code allows upfitters to connect their own or additional lights to the vehicle but must take into account the maximum lamp load. The maximum lamp loads can be found in the latest Mercedes-Benz Body and Equipment guideline for Sprinters. When the bulb failure indicator is active, the signal acquisition and control module (SAM) for torn wires and short circuit monitors the exterior lighting. If a light bulb with output other than the vehicle's standard is connected, an error message is entered in the control unit log, and the driver is informed via a message displayed in the instrument cluster.

License plate light: 1.0 ABackup light: 2.4 A

• Turn signal: 1.75 A -1.96 A (maximum 2.1 A)

Fog light: N/A (tape back)

Tail light: 1.0 A

When using LEDs, a resistor must be used to compensate for the lower amp draw. Turn signal LEDs amp draw is recommended to be between 1.75 A - 1.96 A (maximum 2.1 A) otherwise rapid flashing will occur.

Standard on cab chassis.

**Compared to Sprinter 906** JW8 Attention assist Carry Over Advanced New



The Attention Assist supports the driver during long trips by monitoring the driver's attention level. When the system recognizes signs of fatigue or decreasing attention levels, it will suggest taking a break. The assistance system generates an individual driver profile in the first 15 - 30 minutes, which is then continuously compared to their current driving style. Up to 70 parameters are taken into account, such as time of day, length of trip, speed, steering motion, use of buttons on the multifunctional display or steering wheel, etc.

Attention Assist is active at speeds between 40 mph (65 km/h) and the maximum speed. The driver can set the assistance system to 'standard', 'sensitive 'or "off". When the system begins to recognize signs of fatigue, decreasing attention levels or variations from the individual driver profile, it will display a warning message 'Pause!' along with a coffee-cup symbol and an acoustic signal. In addition, if the vehicle has a navigation system, it suggests nearby rest areas.


If the driver does not take a break and ATTENTION ASSIST continues to register decreasing attention levels, the system displays another warning after 15 minutes.

The high-end instrument cluster displays the assistance graphic with 5 segment bar and a picture of a coffee cup in its center. The circle shrinks with decreasing attention levels. In addition, the travel time since the last break is displayed.

Attention Assist may only partially function among other things when:

- The trip takes less than 30 minutes
- The road conditions are bad, e.g. rough roads, potholes
- There is strong crosswind
- The vehicle is driven in a racy manner, e.g. with high curve speed and rapid acceleration
- The speed is less than 40 mph (65 km/h) for most of the trip
- The clock is set incorrect

K51	Misfiling prevention for diesel	Compa	red to Sprint	er 906
	wildring prevention for dieser	Carry Over	Advanced	New



The protection system is designed for diesel models and includes a locking device with two levers that is made in such a way that it can only be unlocked by a standardized diesel pump nozzle. This prevents the tank from inadvertently being filled with gas. The diameter of the standardized gas pump nozzle (0.83" (21 mm)) is smaller than the diesel analogue (0.94" (24 mm)) and therefore too small to unlock the mechanism.

Note: It is the responsibility of the customer to ensure they are filling with the appropriate fuel as there may be instances where a nozzle capable of unlocking the mechanism is utilized on a gas pump.

# Def fluid filler cap - lockable

Carry Over Advanced New



This code includes a blue filler cap for the DEF tank and a plastic key element for diesel engines. To lock or unlock the filler cap the dust protection must be turned to the side and the key element needs to be inserted. This makes it possible to turn and remove the DEF filler cap. After the DEF tank has been filled and closed, the key element can be removed. The key element is with the tool kit enclosed in the storage compartment on the passenger 's foot well.

K56	Red diesel filler cap	Compa	red to Sprint	er 906
KJU	ned diesei filler cap	Carry Over	Advanced	New



Instead of the standard black filler cap a red filler cap clearly labelled 'DIE-SEL' is mounted. The red color serves as an optical warning for the customer when refueling. This should prevent the customer from using the wrong type of fuel and having to pay for repairs.

K60	Exhaust straight to rear	Compared to Sprinter 906		
	Exhaust straight to real		New	



The vehicles come with a straight exhaust up to the rear as standard via code K60. The exhaust ends shortly before the rear of the vehicle and prevent unpleasant odors in areas of boarding and alighting.

#### Benefits:

- Rear-exiting exhaust
- Recommended for vehicles used in applications such as passenger transport and distribution work

KB7 24.5 gallon fuel tank Compared to Sprinter 906
Carry Over Advanced New



Diesel engines get a 24.5 gallon (93 litres) fuel tank fitted underneath the left vehicles side. The fuel filler is integrated in the left b-pillar nearly the driver's door.

KL1	Aux fuel sending unit w/ fuel tap	Compared to Sprinter 906		
IXL I	Aux ruer sending unit w/ ruer tap	Carry Over	Advanced	New



The fuel gauge sensor is fitted with an additional fuel connection to facilitate retrofitting of a fuel-powered auxiliary heater and similar smaller consumers. The fuel tank can be consumed down to approximately five gallons. A "pig tail" (see picture) is located next to the fuel filler pipe and can be easily accessed from the driver side.

Benefits: Simplified retrofitting of smaller auxiliary consumers.

KL5	Fuel filter with water separator	Compa	red to Sprint	er 906
KLS	i dei inter with water separator	Carry Over	Advanced	New

On vehicles with diesel engines, a water separator and a sensor are fitted to the fuel filter. The water separator absorbs the water contained in diesel fuel with higher water content. A control lamp indicates that the water separator is full. For servicing and cleaning, see the latest Sprinter operator's manual.

#### Benefits:

Enhanced reliability when using poor-quality fuel. Enhanced engine reliability when using diesel fuel with a high water content

L13	Fog lamp with cornering light function	Compared to Sprinter 906		
	Tog famp with cornering light function	Carry Over	Advanced	New



left of the steering wheel.

The halogen front fog lamps are integrated into the front bumper and support a cornering light function whereby one of the two front fog lamps switches on automatically when the driver activates a direction indicator or turns the steering wheel. The cornering light dims on at speeds up to 25 mph (40 km/h). A curve light function dims on at speeds up to 43 mph (70 km/h). The fog lamps can be switched on/off with a button at the light switch positioned on the

L<sub>1</sub>D

# Overhead control panel w/bus interior lighting control

Compared to Sprinter 906

Carry Over | Advanced

New



The Overhead Control Panel with interior lighting control, Code L1D, is comparable to the Comfort overhead control panel but includes an additional button to operate a retrofitted interior lighting for busses. The interior lighting in the rear is dimmed when activated.

If one of the lights is switched on manually via a button in the overhead control panel, it switches off automatically after approx. 20 minutes.

L22	LED tail lights	Compared to Sprinter 906		
LZZ	LLD tall lights	Carry Over	Advanced	New



Apart from giving the vehicle front a high-quality look, the LED high-performance headlamps illuminate the lane evenly both with standard driving light and full beam. The LED technology produces a pleasantly soft light. Due to the quantity of light sources, the light distribution is more homogenous compared to the halogen headlamps. An additional advantage is the low direct glare for oncoming traffic and other road users. The LED lights also have a long lifespan and consume a reduced amount of electricity.

The code L22, includes the following functions in LED technology for the cargo/passenger van:

- Rear lights
- Brake lights

The remaining functions employ conventional light bulbs:

- Rear fog lamp (always on left side)
- Reverse lights
- Indicators

Note: For cab chassis, the code L22 includes all tail light functions in LED technology

L44	Flashing lights, front left	Compared to Sprinter 906		er 906
L44	riasiling lights, front left	Carry Over	Advanced	New



The direction indicators are mounted on the left and right front fender instead of on the outside mirrors.



Vehicle marker and clearance lamps are required by law on all vehicles with a total width of 80" (203 cm) and above according to FMVSS standards. The five identification lamps are mounted in the area of the windshield at the vehicle roof. The two outer ones are used as clearance lamps and the three inner ones are identification lamps. The preparation

clearance lights includes the wiring harness (tied in the roof) and allows an easier installation of the lights on the roof.

Note: It is the upfitter's responsibility to order these lamps to meet FMVSS guidelines.

L65	Interior lights, cargo compartment	Compared to Sprinter 906			
LUJ	interior lights, cargo compartment	Carry Over	Advanced	New	



Two additional ceiling lights are fitted at the roof frame on the side wall. A door contact switch turns the lights on/off when the load compartment doors are opened/closed. The lights can also be switched on/off by the switch in the overhead control panel. In combination with code LC2, all standard ceiling lights in the load compartment come are LED.

#### Benefits:

Better visibility when loading/unloading the vehicle during darkness.

L71	Light/motion sensor in rear Compa		red to Sprinter 906		
L/ I	compartment	Carry Over	Advanced	New	



A motion sensor is installed at the center of the roof cross bow towards the sliding doors. The sensor activates the load compartment lighting if motion is detected when the vehicle is stationary and the vehicle has not been locked. The lighting will switch on for approximately two minutes. If no change to the vehicle is detected over several minutes, the motion sensor will automatically switch off. This prevents the battery from discharging. In combination with code LC2 all ceiling lights in the load compartment come as LED variants.

#### Benefits:

Automatic load compartment illumination. As soon as the driver/co-driver moves from the cab into the rear section, the lighting is automatically activated to provide improved illumination. Prevention of battery discharging.

L72 Electrical pre-installation for load compartment lighting

Compared to Sprinter 906

Carry Over

Advanced

New



The electrics for body interior lighting include the wiring harness with a 3-pin connecting point in the driver's seat frame and allows upfitters to fit load compartment lighting quickly and easily. The operation of the light can be done with a switch in the overhead control panel.

#### Benefits:

Simplifies retrofitting of load compartment lighting. Allows upfitters to install cargo compartment lights quickly and easily. Available for cab chassis

L76	Wire harness tail lamp w/	Compared to Sprinter 906		
L/U	extended wiring	Carry Over	Advanced	New



The wiring harness of both tail lights are approx. 78.7" (200 cm) longer than the standard one. They are rolled up and provisionally fastened at the rear frame end and allows upfitters to fit taillights easier in a different position.

#### Benefits:

Makes it easy to fit the taillights in a different position. The extended tail light line serves as a pre-installation, e.g., for body manufacturers

who wish to fit the taillights in a different position.

177	L77 Wiring for additional turn signals	Compared to Sprinter 906		
L//		<b>Carry Over</b>	Advanced	New

The wiring harness can be find at the rear frame end and allows upfitters to fit easier additional turn signal indicators e.g. at the mounted body.

#### Benefits:

Easier fitting of additional turn signal indicators.

L90	L90 Tail lamp deletion, non-LED	Compared to Sprinter 906			
Lyu	Tall famp defection, non-LLD	Carry Over	Advanced	New	

The vehicle is supplied without taillights at the rear of the vehicle but with relevant connections and wiring. This allows upfitters to fit alternative <u>non-LED</u> lights. The wiring harness is tied in the rear area.

Upfitters can fit aftermarket lamps:

• License plate light: 1.0 A

Backup light: 2.4 A

• Turn signal: 1.75 A -1.96 A (maximum 2.1 A)

Fog light: N/A (tape back)

• Tail light: 1.0 A

Please consult the Mercedes Body and Equipment guidelines for further information available via <a href="https://www.upfitterportal.com">www.upfitterportal.com</a>.

#### Benefits:

Pre-installation for alternative rear lights. Allows upfitters to fit alternative lights and turn signals at the rear of the vehicle.

L91	L91 Tail lamp deletion, LED	Compared to Sprinter 906		
L7 I	rail famp defetion, LLD	<b>Carry Over</b>	Advanced	New

The vehicle is supplied without taillights at the rear of the vehicle but with relevant connections and wiring. This allows upfitters to fit alternative <u>LED</u> lights. The wiring harness is tied in the rear area.

Upfitters can fit aftermarket lamps:

• License plate light: 1.0 A

Backup light: 2.4 A

• Turn signal: 1.75 A -1.96 A (maximum 2.1 A)

• Fog light: N/A (tape back)

• Tail light: 1.0 A

When using LEDs, a resistor must be used to compensate for the lower amp draw. Turn signal LEDs amp draw is recommended to be between 1.75 A – 1.96 A (maximum 2.1 A) otherwise rapid flashing will occur. Please consult the Mercedes Body and Equipment guidelines for further information available via <a href="https://www.upfitterportal.com">www.upfitterportal.com</a>.

#### Benefits:

Pre-installation for alternative rear lights. Allows upfitters to fit alternative lights and turn signals at the rear of the vehicle.

L94	4 Parking lights deletion	Compared to Sprinter 906		
L94 Farking lights deletion	Carry Over	Advanced	New	

The parking lights function is deactivated. These vehicles must be parked with the sidelights on instead.





The code LA1, High beam Assist is based on a camera on the inside of the front windscreen which monitors the traffic situation in front of the vehicle. The camera identifies other vehicles and calculates their distances. When the system calculates that the road ahead is clear, high beam is activated automatically. The High Beam Assist is available at speeds of > 18 mph (30 km/h) and over. Once it has been switched on, it operates fully automatically. The High beam

Assist is only active (so long not deactivated permanently) when the light switch is in the position "AUTO" and the high beam lever is in the position "ON". The activation of the system will be shown in the instrument cluster. This Assist can be deactivated permanently in the instrument cluster.

## Components of High beam Assist:


- · Camera on the inside of the windshield
- Electronic control unit
- Image-processing software

#### Benefits:

- Ideal illumination of the road at all times without blinding oncoming traffic
- Automatic adjustment (on/off) for enhanced comfort
- This assist can be deactivated permanently in the instrument cluster or with the optional multifunction steering wheel, code C6L

LA2	LA2 Headlight assistant	Compared to Sprinter 906		
LAZ	rieaulight assistant	Carry Over	Advanced	New

The code LA2, Headlight assistant, monitors the brightness of weather and lighting conditions during driving operation and switches the lights on or off as required. The light switch must be in the "AUTO" position for automatic on/off driving lights. In conditions of changing brightness, e.g. when driving through tunnels, the assistance system can improve driving safety by switching on the lights. The light sensor is located centrally on the windscreen. When the brightness is dropped below a defined value, the system automatically switches on the driving lights. If the measured value increases to the defined level, the driving lights switch off again.




LA3	LA3 Light sensor for vehicles with alcove	Compared to Sprinter 906			
LAS	Light sensor for vehicles with alcove	Carry Over	Advanced	New	

LA3 is a relocated light sensor at the lower end of the windshield for vehicles with an alcove. The standard light sensor LA2 is located at the top of the windshield and could be covered by the shade

of the alcove. Please refer to the Mercedes-Benz Body and Equipment Guidelines on <a href="www.upfitterportal.com">www.upfitterportal.com</a> for more information and criteria.





LB5	5 3rd Brake Light	Compared to Sprinter 906		
LD3 Stu blake Light	<b>Carry Over</b>	Advanced	New	



An additional LED brake light is fitted at the rear edge of the cargo van or passenger roof. The third brake light does not affect the height of the vehicle at the rear.

#### Benefits:

Enhanced active safety. The LED-based brake light responds more quickly and is visible from afar. Particularly in bad weather, the better visibility provides enhanced safety without affecting vehicle functionality. Standard on Cargo, Crew and Passenger Vans.

LB9	LB9 Illuminated front exits	Compared to Sprinter 906		
LD7	illullillateu Holit exits	Carry Over	Advanced	New



The exit lights are integrated in the driver's and passenger's door and in each step trim of the sliding door. The exit lights of the step trim come as LED variants and the lights of the doors come as conventional bulbs. As the doors swing open, the exit lights illuminate the ground for safe boarding and alighting.

#### Benefits:

Improves safety when getting in and out of the vehicle. As the doors opens, the exit lights turn on automatically.

LC2	Led light strip in load compartment	Carry Over Advanced New				
	Led light strip in load compartment	Carry Over Adv	Advanced	New		



In addition to the standard interior lighting, two LED lights approximately 30" (762 mm) long (3000 K, warm white, approx. 20 Lux; luminous flux: approx. 400 Lumen) are included. These are located in the center of the entry area and on the back roof bow of the load compartment. The lights can be switched on and off either using the interior-light switch by the rear door via the door contact switch or via an overhead control panel with switch for interior lighting in the rear.

The comfort overhead control panel comes with an LED strip replacing the conventional halogen light. The panel allows for the driver and co-driver to manage all settings for interior lighting such as:



- Manually switching them on/off (if required).
- Switches for reading lights for driver and co-driver.
- A switch for deactivating the 'door contact' function.
  - A control switch for the interior lighting in the front.
- A button for switching the interior lights in the load/passenger compartment on and off.
- A storage compartment for glasses.

It also holds the buttons for code EY6, Accident and breakdown Management and code EY5, emergency call system. When also choosing the optionally available Code FY1, the required buttons are also included in the comfort overhead control panel.

LG7 Led high perfo	Led high performance headlamps	Compa	red to Sprint	er 906
LO	Led high performance headiamps	Carry Over	Advanced	New



LED High performance headlamps give the vehicle front a high-quality look, the headlamps illuminate the lane evenly both with standard driving light and full beam. The LED technology produces a pleasant soft light from the quantity of light sources, additionally the light distribution is more homogenous compared to the halogen headlamps. Another benefit is the low direct glare for oncoming traffic and other road users. The LED lights also have a long lifespan and consume little power.

LV6	Third brake light pre-wiring	Compared to Sprinter 906			
LVO	Tillia brake light pre-wiring	Carry Over	Advanced	New	

This pre installation includes the wiring to allow the quick and easy fitting of a 3rd brake light. The wiring is tied in the driver's seat base.

## Benefits:

Easy connection of the third brake light by an upfitter.

LV7	Clearance lights pre-wiring	Compared to Sprinter 906		
LV/	Clearance lights pre-wiring	Carry Over	Advanced	New

The preparation clearance lights includes the wiring harness (tied in the roof) and allows an easier installation of the lights on the roof.

## Benefits:

Allows identification and clearance lights to be retrofitted easily.

M20	Speed limitation 65 mph	Compa	mpared to Sprinter 906		
IVIZO	Speed minitation of mpn	Carry Over	Advanced	New	

The top speed is limited to 65 mph (105 km/h) via the engine control unit.

#### Benefits:

For vehicles where speed limitation is desired or is necessary for technical reasons.

M24	Starter upgraded	Compared to Sprinter 906		
IVIZ	Starter upgraded	Carry Over	Advanced	New



The reinforced starter is designed for significantly more starts of the engine, and is particularly suitable for customers driving mainly short distances, with a frequent stop, and go driving profile.

M46 Alternator	Alternator 14 V / 220 A	Compared to Sprinter 906		
	Alternator 14 V / 220 A	Carry Over	Advanced	New

Standard high-capacity 14 V/220 A alternator. This alternator is automatically specified in conjunction with the six-cylinder engine (OM642).

### Benefits:

- Improves battery charging in short-distance operation
- Enhances electrical system performance

The higher-capacity alternator enhances the performance of the electrical system in vehicles such as ambulances or fire-fighting vehicles. It meets the power requirements of high-consumption electrical auxiliaries such as tailgate lifts. It also ensures rapid battery charging in the case of frequent short distance operation and operation in cold temperatures.

M60	Alternator 14 V / 250 A	Compared to Sprinter 906		
IVIOO	Alternator 14 V / 230 A	Carry Over	Advanced	New

A high-output alternator rated at 14 V/250 A is fitted instead of the standard alternator, and only in conjunction with code M47, alternator for fuel economy.

#### Benefits:

- Improves efficiency
- Increases output

#### Reduces noise

The more powerful alternator increases the performance of the electrical system. It ensures that the increased power requirements of additional electrical equipment are met. It also ensures fast battery charging in vehicles frequently used on short-distance trips and at low temperatures.

MD3	Top speed limitation 75 mph	Compared to Sprinter 906		
IVIDS	Top speed minitation 73 mpn	<b>Carry Over</b>	Advanced	New

The top speed is limited to 75 mph (120 km/h) via the engine control unit.

#### Benefits:

For vehicles for which speed limitation is desired or is mandatory for technical reasons (e.g., haulage vehicles, special-purpose vehicles).

MG3	2.0L I4 turbo diesel with 7-speed trans- Compared to Sprinte		er 906	
IVIGS	mission	Carry Over	Advanced	New

Four-cylinder OM 651 diesel engine with fourth-generation common rail technology generates a rail pressure of 1800 bar (26,100 psi) in the high-pressure reservoir. The maximum ignition pressure in the cylinders is 200 bar (2,900 psi). The two-stage turbocharger comprises a high-pressure and a low-pressure exhaust gas turbocharger. The fuel is injected directly into the combustion chamber with the aid of solenoid valves. The engine comes with a rear-mounted camshaft drive and two-mass flywheel to isolate the crankshaft's vibration stimuli from the drive system. Two balancer shafts with counterweights ensure that the centers of gravity of the pistons and counterweights move in parallel to the cylinders' axes, thereby maintaining the common center of gravity in approximately the same place (Lanchester balancer). In addition, the oil injection nozzles and the water pump are activated on demand.

## TECHNICAL DATA

Configuration: DOHC

No. of cylinders/arrangement: I4

Valves: 4 (2 in/2 out)

• Bore/stroke: 83.0 mm/99.0 mm

Cubic capacity: 2143 cc

• Output: 161 hp (120 kW) at 3800 rpm

Max. torque: 266 lb.-ft. (360 Nm) at 1400-2400 rpm

Compression ratio 16.2:1

• Injection system: Common-rail direct injection (CDI)

Benefits compared to previous generation engines:

- High flexibility
- High torque
- Powerful acceleration
- Optimized fuel consumption

Low noise

# **Emission standard for diesel engines**

The diesel engine follows the emissions values of the ULEV (< 10.000 lbs.) or SULEV (> 10.000 lbs.) exhaust emissions standard with active nitrogen oxide reduction which means that a SCR – system (Selective Catalytic Reduction) is used. Accordingly DEF (Diesel Exhaust Fluid) is needed.

The task of the exhaust treatment is to reduce the exhaust emissions:

• Nitrous oxide (NOX) • Hydrocarbons (HC) • Carbon monoxide (CO) • Soot particle

The exhaust gases expelled from the engine are cleaned in an oxidation catalytic converter, a diesel particulate filter (DPF) and a reduction catalytic converter (**S**elective **C**atalytic **R**eduction (SCR).

The DEF (**D**iesel **E**xhaust **F**luid) reducing agent is injected upstream of the SCR catalytic converter, and is converted to ammonia (NH3) by thermal decomposition (heat-induced chemical reaction) and hydrolysis (water-induced chemical reaction). In the SCR catalytic converter, the NOX contained in the exhaust gas is converted with the NH3 to nitrogen (N2) and H2O molecules.

All vehicles with diesel engine get the DEF-Tank incl. filler with blue cap mounted on the right side in the engine compartment. The maximum filling capacity of DEF (**D**iesel **E**xhaust **F**luid) is 22 l. The current filling level is shown in the instrument cluster.

Noise, exhaust emissions and fuel consumption are optimized by multi-stage injection and a turbo-charger. Optimization of the engine control unit and the use of a diesel particulate filter with DEF (Diesel Emission Fluid) enable this engine to meet the stringent exhaust emission limits of EPA 2013 standard and is 50 states certified. High torque output already at very low rpm (1400 to 2400 rpm).

Note: Biodiesel B5 only.

MG5	3.0L V6 turbo diesel with	Compa	red to Sprint	er 906
IVIGS	7-Speed Transmission	<b>Carry Over</b>	Advanced	New

OM 642 six-cylinder diesel engine with common-rail direct injection (CDI) and fuel preheating.

An intake-metered high-pressure pump sends fuel to the high-pressure accumulator (fuel rail), where pressures of up to 1600 bar (23,200 psi) is developed. The electrically controlled injectors inject the fuel directly into the combustion chamber. Thanks to the very high injection pressures, this system ensures excellent mixture formation. The electronic management allows good adaptation of injection timing and quantity to operating and driving conditions.

## TECHNICAL DATA

Configuration: DOHC

No. of cylinders/arrangement: V6 72°

• Valves: 4 (2 in/2 out)

• Bore/stroke: 83.0 mm/92.0 mm

• Cubic capacity: 2987 cc

• Output: 188 hp (140 kW) at 3800 rpm

• Max. torque: 325 lb.-ft. (440 Nm) at 1400-2400 rpm

Compression ratio 18.0:1

• Injection system: Common-rail direct injection (CDI)

#### Benefits:

- High flexibility
- High torque
- Powerful acceleration
- Optimized fuel consumption
- Meets EPA 2013 emission standard
- Low noise

## **Emission standard for diesel engines**

The diesel engine follows the emissions values of the ULEV (< 10.000 lbs.) or SULEV (> 10.000 lbs.) exhaust emissions standard with active nitrogen oxide reduction which means that a SCR – system (Selective Catalytic Reduction) is used. Accordingly DEF (Diesel Exhaust Fluid) is needed.

The task of the exhaust treatment is to reduce the exhaust emissions:

• Nitrous oxide (NOX) • Hydrocarbons (HC) • Carbon monoxide (CO) • Soot particle

The exhaust gases expelled from the engine are cleaned in an oxidation catalytic converter, a diesel particulate filter (DPF) and a reduction catalytic converter (**S**elective **C**atalytic **R**eduction (SCR).

The DEF (**D**iesel **E**xhaust **F**luid) reducing agent is injected upstream of the SCR catalytic converter, and is converted to ammonia (NH3) by thermal decomposition (heat-induced chemical reaction) and hydrolysis (water-induced chemical reaction). In the SCR catalytic converter, the NOX contained in the exhaust gas is converted with the NH3 to nitrogen (N2) and H2O molecules.

All vehicles with diesel engine get the DEF-Tank incl. filler with blue cap mounted on the right side in the engine compartment. The maximum filling capacity of DEF (**D**iesel **E**xhaust **F**luid) is 22 l. The current filling level is shown in the instrument cluster.

Noise, exhaust emissions and fuel consumption are optimized by multi-stage injection and a turbo-charger. Optimization of the engine control unit and the use of a diesel particulate filter with DEF (Diesel Emission Fluid) enable this engine to meet the stringent exhaust emission limits of EPA 2013 standard and is 50 states certified. High torque output already at very low rpm (1400 to 2400 rpm).

Note: Biodiesel B5 only.

мнв	H8 SULEV Emissions	Compared to Sprinter 906		
IVITIO	SOLLY LIIISSIONS	Carry Over	Advanced	New

According to the CARB emission legislation, the Sprinter is categorized as a Medium Duty Vehicle (MDV). The future CARB LEVIII SULEV emission standards of MDVs are to be phased in from 2018 to 2022. From 2023 onward the SULEV limits will be mandatory for all newly introduced MDV vehicles.

With this code, the Sprinter is programmed with an improved combustion, emission and OBD calibration to meet the higher requirements of LEVIII SULEV.

Standard on all Gas models and 3500XD and 4500 Diesel models.

MIO	ULEV Emission	Compared to Sprinter 906			
IVIIO	OLLV LIIISSIOII	Carry Over	Advanced	New	

According to the CARB emission legislation, the Sprinter is categorized as a Medium Duty Vehicle (MDV). ULEV is standard for all Diesel models below 10,000 lbs. (4535kg) (2500 and 3500 models).

ммз	2.0L 4-cylinder turbo gasoline with	Compared to Sprinter 906			
IVIIVIS	9-Speed Transmission	Carry Over Advanced Ne		New	

The engine M274 is a 4-cylinder gas engine with an aluminum alloy crank case, direct injection and fast-acting piezo-injectors for multiple injection, needs-orientated multi spark ignition, controlled oil pump, switchable water pump and high compression one-stage turbocharging. Common features are the use of state-of-the art technologies for maximum efficiency, very smooth running, high tractive power right from low revs, sustainability in terms of impending emissions standards and low weight.

#### TECHNICAL DATA

Configuration: DOHC

• No. of cylinders/arrangement: 4/in-line

Valves: 4 (2 in/2 out)

• Bore/stroke: 83.0 mm/92.0 mm

• Cubic capacity: 1991 cc

• Output: 188 hp (140 kW) at 5000 rpm

• Max. torque: 258 lb.-ft. (350 Nm) at 2500-3500 rpm

Compression ratio 9.8:1

• Injection system: Bosch injection (200bar)

## Benefits:

- High flexibility
- High torque
- Low emissions
- Optimized fuel consumption
- Powerful acceleration
- Low noise and vibration levels

## **Direct inject**

A high-pressure pump with integrated flow control valve is used to generate the required high pressure. The fuel is conducted via a high-pressure rail to the centrally located fuel injectors to inject up to five very precise injections per cycle into the combustion chamber. The injectors operate extremely fast and can inject even the smallest amounts of fuel. Due to the high fuel pressure the outwards opening nozzle develops a stable hollow-cone beam under all operating conditions.

## **Emission standard for gas engines**

The M274 fulfills the emissions values of the SULEV exhaust emissions standard with a direct injection homogeneous mode. In homogeneous mode a combustible fuel/air mixture is generated within the whole combustion chamber. There are no further measures required for exhaust after treatment since normal three-way catalytic converter adequately converts the pollutants.

The task of the exhaust treatment is to reduce the exhaust emissions:

• Nitrous oxide (NOX) • Hydrocarbons (HC) • Carbon monoxide (CO)

MC1	MS1 Cruise control	Compared to Sprinter 906			
IVIST		Carry Over	Advanced	New	



The cruise control accelerates and brakes the vehicle automatically in order to maintain a previously stored speed above 15 mph (24 km/h). The cruise control is operated using the left steering wheel buttons. A limiter function is not available. If the cruise control is activated and the optimal available Traffic Sign Assist has detected a speed restriction sign, the maximum permissible speed displayed in the instrument display can be stored

and the vehicles maintains or does not exceed this speed.

#### Benefits:

- Constant speeds result in fuel-efficient driving
- Easier compliance with speed limits

N62	Front engine bracket for	Compared to Sprinter 906			
NOZ	additional alternator	Carry Over	Advanced	New	



It is possible to attach an additional auxiliary alternator on the right side of the engine next to the oil pan, but this must be done using the factory option N62 as the bracket.

Maximum weight of device on bracket: 16 lbs. (7.25 kg) Maximum power output of alternator: max. 8.5 kW

It is the upfitters responsibility to choose the correct belt length and to ensure the correct belt layout and belt durability. Alternator is customer supplied.

Brackets will differ depending on which engine is ordered with the vehicle. For more information, please refer to the Mercedes-Benz Body and Equipment guidelines available on <a href="https://www.upfitterportal.com">www.upfitterportal.com</a>.

**N63** 

# Front engine bracket for auxiliary A/C compressor

**Compared to Sprinter 906 Carry Over** Advanced New



It is possible to attach an additional auxiliary alternator on the right side of the engine next to the oil pan, but this must be done using the factory option N63 as the bracket.

Maximum weight of device on bracket: 16 lbs. (7.25 kg) Maximum power output of alternator: max. 8.5 kW

It is the upfitters responsibility to choose the correct belt length and to ensure the correct belt layout and belt durability. Alternator is customer supplied.

Brackets will differ depending on which engine is ordered with the vehicle. For more information, please refer to the Mercedes-Benz Body

and Equipment guidelines available on www.upfitterportal.com.

DΩ	P08 Cover for transport	Compared to Sprinter 906		
F 00		Carry Over	Advanced	New

Cab chassis base versions (F28, F50) are supplied with a cover for transport. In case of vehicles specified with deletion of windows for bus version (code W94), code P08 includes polypropylene (PP) conpearl plastic panels to close the resulting cutouts.

## Benefits:

Weatherproof transport protection.

P47	P47 Front mudflaps	Compared to Sprinter 906			
F47	Tront madnaps	Carry Over Advanced Nev	New		



Plastic mud flaps are fitted to the wings behind the front wheels.

## Benefits:

Reduces dirt accumulation on the vehicle. The mud flaps reduce spray in the wet and help to keep the body and sides clean. Standard on all Sprinters.

P48	Rear mud flaps	Compared to Sprinter 906	er 906	
1 40	iteal illuu liaps	Carry Over	Advanced	New



Plastic mud flaps are fitted behind the rear wheels.

#### Benefits:

- Reduces dirt accumulation on the vehicle
- Improves visibility for traffic behind

The mud flaps reduce spray in the wet, thereby reducing dirt accumulation on the body and improving visibility for traffic behind. Standard on all Sprinter models.

P93 Omission of I	Omission of Drings	Carry Over Advanced New		
	Offication of D-filigs	Carry Over	Advanced	New




Depending on the vehicles wheelbase the lashing eyelets are installed as follows:

144" wheelbase: 10 lashing eyelets
170" wheelbase: 12 lashing eyelets
170"EXT wheelbase: 14 lashing eyelets

Two lashing eyelets are always at the partition wall and the rest in the load compartments floor. The lashing eyelets keep the

wooden/plastic floor (if ordered) in position. Omission means that the lashing eyelets in the load compartments floor are not installed and the openings are with plastic covers closed.

Q11	Q11 Longitudinal member reinforcement	Compared to Sprinter 906		
απ	Longitudinal member remiorcement	Carry Over	Advanced	New



Reinforcements are welded to both rear left and right longitudinal members where these inserts serve an additional base for different options, such as trailer couplings, steps and cross members.

Q18

## **End Cross Member Bolted**

Carry Over Advanced New




The end cross member is bolted to the side members.

#### Benefits:

Allows easy retrofitting of bodies and attachments. Allows the end cross member to be easily removed if necessary to make room for fitting box bodies, aerial platforms, etc.

Q24	Trailer Hitch, 5,000 lbs.	Compared to Sprinter 906		
UZ4	Trailer Tittell, 3,000 lbs.	Carry Over	Advanced	New



The trailer cross-member code Q24 has a towing capacity of 5,000 lbs. (2,268 kg) and a maximum trailer load of 500 lbs. (227 kg). A trailer plug socket with 7-poles and a trailer connection unit, which also supports LED lights on a trailer, is included with the code E40. A permanent power supply is on the trailer socket pin 4 and allows a connection to accessories up to a maximum of 240 W. Do not use the power supply to charge the trailer battery. Charging the trailer battery using the power supply of the vehicle can damage the battery.

#### Benefits:

This trailer hitch enables a conventional trailer coupling to be fitted, and also allows the connection of a power supply for the trailer.

Note: Customers need to make sure that they do not exceed the GCWR (see operators manual or identification plate on seat base).

067	Q67 Tow hook rear	Compared to Sprinter 906		
407		Carry Over	Advanced	New

The towing eye is permanently attached to the vehicle on the right of the rear longitudinal member and can be used to tow away vehicles. Please note: when a towing eye is used to recover a vehicle, the vehicle may be damaged in the process.


Q72 Deletion of end cross member	Compared to Sprinter 906		
	Deletion of end cross member	Carry Over	Advanced



The rear end cross member is not fitted. Four weld nuts are fitted at the mounting plate corners.

#### Benefits:

Easier mounting of upfits on the end of the chassis.



The option code QA2 offers a towing capacity of 7,500 lbs. (3402 kg) and a maximum trailer load of 750 lbs. (340 kg). Customers need to make sure that they do not exceed the GCWR (see operators manual or identification plate on seat base).

QA9	Half-sided step rear (for trailer hitch)	Compa	red to Sprint	er 906
UAT	Train-sided step rear (for trainer fitteri)	Carry Over	Advanced	New



In conjunction with a trailer hitch Q24/QA2, it is possible to order a black painted step (7.48 x 20.47" (190 x 520 mm)) consisting of a tubular steel frame with a welded anti-slip tread surface. The step is bolted onto the right side of the trailer coupling and allows an easier entry and exit at the rear.

R60	Provisional spare wheel bracket	Compared to Sprinter 906		
	frame mounted	Carry Over	Advanced	New



All vehicles come with the spare wheel bracket mounted under the end of the frame which allows to carry a full-sized spare wheel (except the super single). For cab chassis where the area of the rear frame end is used for custom upfits, the spare wheel can be provisionally mounted on the frame via code R60. In this case the spare tire must subsequently be relocated to another position in or on the vehicle.

Benefits:

For transport purposes. This provisional arrangement is used exclusively for transporting vehicles to Mercedes-Benz sales outlets, dealers or body

manufacturers. The spare wheel must subsequently be relocated to another position in or on the vehicle.

R65	Spare wheel bracket below frame	Compared to Sprinter 906		er 906
NOS	Spare wheel bracket below frame	Carry Over	Advanced	New



The spare wheel bracket is mounted under the end of the frame behind the rear axle.

## Benefits:

Allows a spare wheel to be carried without restricting the load compartment.

R87	R87 Spare wheel	Compared to Sprinter 906		
NO7	Spare writer	Carry Over	Advanced	New



All vehicles, except the super-single, come with an equipped full size spare wheel. Vehicles equipped with alloy wheels also have the spare tire equipped with an alloy wheel. For vehicles with super single tires: the spare wheel needs to be mounted at the rear axle and it is mandatory to fix the adapter before the use of the spare wheel. On the front axle, the spare wheel has to be mounted without the adapter. The super-single spare wheel comes in the dimension 225/75 R16

with a one-time use at the rear axle and reduced maximum allowed velocity of 34 mph (55 km/h).

## Benefits:

Allows a wheel to be changed in the event of a tire puncture.

R91	Spare wheel deletion	Compared to Sprinter 906		
131	Spare wheel deletion	Carry Over	Advanced	New

All vehicles, except the super-single, are equipped with an appropriately sized spare wheel. Optionally it's possible to delete the spare wheel via code R91.

R92	R92 Spare tire carrier deletion	Compared to Sprinter 906		
11.72	Spare the carrier defetion	Carry Over	Advanced	New

All vehicles comes with the spare tire bracket mounted under the end of the frame which allows a full-sized spare tire (except the super single). Optionally it's possible to delete the spare tire bracket via code R92. For cab chassis, where the area of the rear frame end is used for custom upfits, the spare tire must subsequently be relocated to another position in or on the vehicle.

R98	Rims painted jet black	Compared to Sprinter 906		er 906
K70	Killis pallited jet black	Carry Over	Advanced	New



The vehicle is fitted with jet black (MB 9040) painted wheels.

R9A	285/65 R 16 C Super-Single-Tires	Compared to Sprinter 906		er 906
INTA	203/03 K 10 C Super-Single-Tires	Carry Over	Advanced	New

The super-single variant is available for the cargo van or cab chassis and includes steel wheel rims  $(8,5] \times 16$ ) at the rear axle with 285/65 R16 C tires. Steel wheel rims  $(6,5] \times 16$ ) and 225/75 R16 C tires come for the front axle and the spare tire. All wheels are mounted with spherical seat bolts. As a standard, these are all-season tires and optionally winter tires are available. The super-single variant for the cargo van offers an increased load width between the wheel housing of up to approx. 48,35" (122.8 cm) (dual tires approx. 38,19" (97 cm)). The vehicle height raises approx. 1" (2.54 cm). The cab chassis comes with more available space between the wheel housing for custom bodies.

RD9	Unspecified tire brand	Compared to Sprinter 906		
ND9	onspecified the braild	Carry Over	Advanced	New

With RD9, any available tire brand will be added to the order. If a specific brand is required, please add RM9 and the wished brand. For possible combinations and availability, please see the tire section of the DOG.

RF1	Tire brand Continental	Compared to Sprinter 906		er 906
Ki i	The brand Continental	Carry Over	Advanced	New

Please see the tire section in the DOG for an overview of the tire options.

RF8	RF8 Tire brand Michelin	Compared to Sprinter 906		
IXI O	The brand wichem	Carry Over	Advanced	New

Please see the tire section in the DOG for an overview of the tire options.

RHO	Tire brand Kumho	Compared to Sprinter 906		
KHO	The braild Ruillio	Carry Over	Advanced	New

Please see the tire section in the DOG for an overview of the tire options.

RH7	Tires LT 215/85 R16	Compared to Sprinter 906		er 906
KIIZ	Thes Li 213/03 Kio	Carry Over	Advanced	New

Vehicles are equipped with tire size 215/85 R16, which can be selected with different tire options as below:

- Continental Tire (Code RF1)
- Michelin Tire (Code RF8)
- All Season Tire (Code RM0)

- Mud+Snow (Code RM1)
- Unspecified brand (Code RD9) which is standard on all models.

Please see the tire section of the DOG for the available combinations.

RH8	Tires LT 245/75 R16	Compared to Sprinter 906		
KIIO	Tiles El 243/73 KTO	<b>Carry Over</b>	Advanced	New

Vehicles are equipped with tire size 245/75 R16 which can be selected with different tire options as below:

- Continental Tire (Code RF1)
- Michelin Tire (Code RF8)
- Kumho Tire (Code RH0)
- Mud+Sonw Tire (Code RM1)
- Unspecified brand (Code RD9) which is standard on all models

Please see the tire section in the DOG for available combinations.

RL5 Light alloy wheels 6.5 J x 16	Compared to Sprinter 906			
ILLS	Light alloy wheels 0.5 J x 10	Carry Over	Advanced	New



Installation of four 6.5 J  $\times$  16 light-alloy wheels with longer wheel bolts (73 mm) for 235/65 R 16 C tires.

## Benefits:

Enhances the look of the vehicle. The light-alloy wheels enhance the appearance of the vehicle.

RMO	All-Season tires	Compared to Sprinter 906		
KIVIO	All-Season thes	Carry Over	Advanced	New

The compound used in the all-season tires ensures that they do not harden too much in low temperatures and at the same time retain their stiffness in summer temperatures.

#### Benefits:

No change in tires needed due to seasonal weather. All-season tires are standard equipment. For Winter Tire see RM1.

RM1	M+S Winter tires	Compared to Sprinter 906			
KIVI I	WITS WILLEI LITES	Carry Over	Advanced	New	

The Mud and Snow tires feature a compound and tread design, which ensures good traction and lateral stability in the cold, snow and slush, as well as in similar adverse road conditions.

## Benefits:

- Safer driving and better traction on wintry roads
- Improves climbing ability since more grip

RM2	Rims painted Arctic White	Compared to Sprinter 906		
	Kinis painted Arctic Writte	Carry Over		



The vehicle is equipped with steel wheels painted arctic white (MB 9147).

Benefits:

Requirement from various fleet customers.

RM9	RM9 Specially requested tires	Compared to Sprinter 906		
IVIVI 7	Specially requested tiles	Carry Over	Advanced	New

RM9 must be added when choosing any specific tire brand.

RS3	RS3 6.5 J x 16 Steel Wheels	Compared to Sprinter 906			
N33	0.5 J X 10 Steel Wileels	Carry Over	Advanced	New	



Please see the tire section in the DOG for an overview of the tire options.

RS5	Steel Wheels: 8.5Jx16 Rr;	Compared to Sprinter 906		er 906
NOO	6.5Jx16 Fr	Carry Over	Advanced	New



Please see the tire section in the DOG for an overview of the tire options.

## 5.5 J x 16 Steel Wheels

Compared to Sprinter 906

Carry Over Advanced

New



Please see the tire section in the DOG for an overview of the tire options.

RY2	RY2 Tire pressure monitoring lamp	Compared to Sprinter 906		
IX I Z	The pressure monitoring lamp	Carry Over	Advanced	New

With the help of sensors on the inside of the tires it can monitor pressure and report if the pressure is low on one or more tires. The tire pressure will be displayed after few minutes of driving in the multifunction display. If there is a substantial loss of tire pressure, a warning is issued via a display message and a warning lamp in the instrument cluster. New tire pressure sensors, e.g. in winter tires, are automatically taught-in first time they are driven. For vehicles with RY2 the spare wheel is also equipped with a pressure sensor. The spare wheel sensing is activated after replacing with the damaged wheel.



#### Benefits:

- Enhances safety
- Lower fuel consumption
- Reduces tire wear

If the pressure is too low in one or more tires, a visual warning appears in the instrument cluster if the discrepancy is more than 14%. Early detection of pressure losses extends tire life and reduces running costs. Correct inflation pressures also optimize steering and braking performance.

S02/		Compa	red to Sprint	er 906
<b>S04</b>	Standard front driver/passenger seat	Carry Over	Advanced	New



The standard seats come with the method to be adjust manually:

- Seat fore-and-aft adjustment of 10.24" (260 mm)
- Seat backrest inclination of 69°
- Seat height adjustment of 2.36" (60 mm)
- 2-way head restraint

#### Benefits:

Extended adjustment possibilities allow seat position to be adapted to suit individual requirements.

<b>S20</b>	Passenger seat foldable	Compared to Sprinter 906		
320	incl front airbags (SA6 + SH2)	Carry Over	Advanced	New



The foldable co-driver seat and its head restraint are directly attached to the partition with sliding door. This seat makes it easier for the driver to enter or exit the vehicle on the passenger's side and provides easier access from the passenger door into the load department. The upholstery is always fabric maturin black without any sales code. For folding the seat cushion up or down the red button needs to be pushed first.

Benefits:

Eases the driver's workload, particularly in the distribution sector. This seat offers advantages when the driver is only occasionally accompanied, for example in the distribution sector (e.g., when training a new driver).

<b>S22</b>	S22 Armrest for driver's seat	Compared to Sprinter 906		
SZZ	Armiest for univer 5 seat	Carry Over	Advanced	New



A tilt-adjustable armrest is fitted to the inboard side of the driver's backrest. Retrofitting this armrest entails swapping the entire backrest.

## Benefits:

More relaxed driving, particularly on long journeys. Allows the arm to be supported during continuous driving.

S23 Twin front pa	Twin front passenger seat	Compared to Sprinter 906				
323	Twill from passenger seat	Carry Over	Advanced	New		



With code S23, a twin seat is installed on the passenger's side instead of a single seat, allowing an additional seat for a third person. Both seats are equipped with three-point seat belts and head restraints. The seat cushion can be completely folded forward and therefore it's possible to use the seat frame as a storage compartment.

## Benefits:

- A third person can be seated in the cab
- Seat base frame can be used as a storage compartment
- Three-point belts on both co-driver 's seats

## Armrest for front passenger seat

Carry Over Advanced New



A tilt-adjustable armrest is fitted to the inboard side of the co-driver's backrest. Retrofitting this armrest entails swapping the entire backrest.

#### Benefits:

More relaxed driving, particularly on long journeys. Allows the arm to be supported during continuous driving.

<b>S28</b>	Armrest, driver's and passenger door	Compa	Compared to Sprinter 906 rry Over Advanced New			
320	Anniest, univer s and passenger door	Carry Over	Advanced	New		



The cushioned armrests on the driver's and co-driver's door, code S28, are optionally available. The faux-leather armrests offer an increased level of comfort and are mounted behind the door switch and handle.

<b>S</b> 31	Convenience head restraints for	Compared to Sprinter 906		
	pass. comp.	Carry Over	Advanced	New



The height and angle of the luxury head restraints for the passengers can be adapted to the individual requirements. They thereby facilitate a comfortable and relaxed seating position particularly on longer routes.

<b>S62</b>	Seat belts orange,	Compared to Sprinter 906		er 906
	driver and front passenger	<b>Carry Over</b>	Advanced	New



Orange safety belts replace the standard black safety belts for the driver and passenger (not with S23, twin passenger seat).

#### Benefits:

Makes it easier to see whether occupants are wearing their safety belts. The demand for orange safety belts comes from various fleet customers. Since these belts contrast significantly better with clothing than the standard black safety belts, it is much easier to tell from the outside whether the person(s) is/are buckled up.

S87	Driver's seat frame, low	Compa	red to Sprint	er 906
	Driver's seat frame, low	Carry Over Advanced New	New	

The reinforced seat base includes additional reinforcing sheets on and inside the seat box. The standard driver's seat base frame (height approximately 12 inch (305 mm)) is replaced by a version 3.34inch (85 cm) lower (height approximately 8.7 inch (221 mm)

#### Benefits:

Allows a custom driver's seat to be fitted. Basis for installation of a suspension seat or a swiveling seat ex-factory (e.g., SR8 + SB1) or by an upfitter (with or without SR8).

<b>S88</b>	Passenger seat frame, low	Compared to Sprinter 906		
300	l assenger seat frame, low	<b>Carry Over</b>	Advanced	New

The reinforced seat base includes additional reinforcing sheets on and inside the seat box. The standard driver's seat base frame (height approximately 12 inch (305 mm)) is replaced by a version 3.34inch (85 cm) lower (height approximately 8.7 inch (221 mm)

#### Benefits:

Allows a custom driver's seat to be fitted. Basis for installation of a suspension seat or a swiveling seat ex-factory (e.g., SR9 + SB2) or by an upfitter (with or without SR9).

S91	S91 Passenger seat discontinued	Compared to Sprinter 906		
371	rassenger seat discontinued	Carry Over	Advanced	New

With code S91 the complete passenger's seat can be deleted. If requested, the seat frame can also be deleted via code S99. This equipment is only available for all vehicles >10.000 lbs. and provides unimpeded access from the passenger's door to the load compartment.

\$99 Passenger seat pedestal - deletion	Compared to Sprinter 906			
377	i assenger seat pedestar-deretion	Carry Over	Advanced	New

The vehicle is supplied without a passenger seat base frame.

## Benefits:

Provides unimpeded access from the passenger door to the load compartment. For custom vehicles such as buses or parcel delivery vehicles, where unimpeded access through the passenger door to the passenger/load compartment is required.





The driver airbag unit is integrated in the impact absorber of the steering wheel. In an accident it is inflated within milliseconds by a gas generator, reducing the risk of the driver's head or chest impacting the steering wheel during a frontal collision. The airbag acts in concert with the belt tensioner, which minimizes the slack in the safety belt. To ensure that the restraining force of the safety belt does not cause injury to the driver during a collision, a belt force limiter is integrated into the restraint system.

Benefits:

Reduces the risk and severity of head/chest injuries in a frontal collision. The risk and severity of a head and chest impact on the steering wheel are reduced in conjunction with a safety belt.

SA6	Front airbag, passenger	Compared to Sprinter 906 Carry Over Advanced New		
	i Tont an bag, passenger	Carry Over	Advanced	New



The passenger airbag unit is located in the right side of the instrument. The passenger airbag is available for an individual seat, for a bench seat (S23) and only as a twin passenger airbag version. In an accident it is inflated within milliseconds by a gas generator, reducing the risk of the seat occupant's head or chest impacting the steering wheel during a frontal collision. The airbag acts in concert with the belt tensioner, which minimizes the

slack in the safety belt. To ensure that the restraining force of the safety belt does not cause injury to the occupant(s) during a collision, a belt force limiter is integrated into the restraint system.

#### Benefits:

Reduces the risk and severity of head/chest injuries in a frontal collision. The risk and severity of a head and chest impact on the dashboard are reduced in conjunction with a safety belt.

SB1 Comfort driver's se	Comfort driver's seat	Compa	red to Sprint	er 906
	Comfort univer's seat	Carry Over	Advanced	New



The comfort seats are characterized by their wide range of manually adjustment options:

- Seat fore-and-aft adjustment of 10.24" (260 mm)
- Seat backrest inclination of 69°
- Seat height adjustment of 2.36" (60 mm)
- Seat cushion inclination of 5.5°
- Seat cushion length of 2.36" (60 mm)
- 2-Way head restraint

The multitude of individual seat adjustments allows for a higher level of comfort e.g. by relieving strain on the back muscles and thus makes for comfortable driving.

## Benefits:

- More precise adjustment of the seat to suit individual requirements
- Relaxed driving, particularly on long journeys

## Comfort passenger seat

Carry Over Advanced New



The comfort seats are characterized by their wide range of manually adjustment options:

- Seat fore-and-aft adjustment of 10,24" (260 mm)
- Seat backrest inclination of 69°
- Seat height adjustment of 2,36" (60 mm)
- Seat cushion inclination of 5,5°
- Seat cushion length of 2,36" (60 mm)
- 2-Way head restraint

The multitude of individual seat adjustments allows for a higher level of comfort e.g. by relieving strain on the back muscles and thus makes for comfortable driving.

#### Benefits:

- More precise adjustment of the seat to suit individual requirements
- Relaxed driving, particularly on long journeys

SB3	Driver Suspension Seat, Comfort Version	Compa	red to Sprint	er 906
303	Driver Suspension Seat, Connort version	Carry Over	Advanced	New



These suspension seats are based on the comfort seats code SB1/SB2 and have the same manually adjustable options. Additionally it 's possible to set the seat suspension and a vibration limiting. The body weight of 88 lbs. (40 kg) to 264 lbs. (120 kg) can be set with a hand wheel so that the seat suspension works optimally. With a higher weight, the seat suspension will become firmer and the seat will then not vibrates as much. If the seat vibrates often and significantly, it 's possible to engage vibration limiting in the lower area.

## Benefits:

Enhances seat comfort, particularly on poor roads. Road shocks are absorbed by a combination of mechanical and hydraulic suspension, thereby reducing strain on the driver's back. This seat is recommended particularly for vehicles, which are regularly used in areas with poor roads condition.

SB4

# Passenger suspension seat, comfort version

Compared to Sprinter 906

Carry Over Advanced

New



These suspension seats are based on the comfort seats code SB1/SB2 and have the same manually adjustable options. Additionally it's possible to set the seat suspension and a vibration limiting. The body weight of 88 lbs. (40 kg) to 264 lbs. (120 kg) can be set with a hand wheel so that the seat suspension works optimally. With a higher weight, the seat suspension will become firmer and the seat will then not vibrates as much. If the seat vibrates often and significantly, it's possible to engage vibration limiting in the lower area.

#### Benefits:

Enhanced seat comfort, particularly on poor roads. Road shocks are absorbed by a combination of mechanical and hydraulic suspension, thereby reducing

strain on the driver's back. This seat is recommended particularly for vehicles that are regularly used in areas with poor roads condition.

SB9	Driver's seat plus	Compa	red to Sprint	er 906
307	briver a seat plus	Carry Over	Advanced	New

The driver's seat plus has a foam-filled cushion in the center section of the seat cover. The flatter seat cushion makes standing up easier for the driver and also getting in and out of the vehicle. The driver's seat features fore/aft, backrest and height adjustment. The fabric cover is the same as on the standard driver's seat.

- Seat fore-and-aft adjustment of 10.24" (260 mm)
- Seat backrest inclination of 69°
- Seat height adjustment of 2.36" (60 mm)
- 2-Way head restraint

## Benefits:

- Makes standing up easier
- Easier to get in and out of the vehicle
- Recommended for delivery drivers with frequent stops

SE4/	Lumbar support, driver +	Compared to Sprinter 906		
SE5	passenger seat	Carry Over	Advanced	New



The lumbar support in the backrest of the driver's seat enables the seat to be adjusted to suit the driver's ergonomic comfort requirements. Both air bladders are adjusted pneumatically. The height of the bladders and the extent of the curvature can be controlled with a 4-way switch at the outside of the driver's seat. This optional feature is available for 3 seat variants. Seats fitted with lumbar support meet the criteria of the German AGR campaign for healthy spines.

## Driver's seat electrically adjustable

Compared to Sprinter 906

Carry Over | Advanced

New



This electrical driver seat is based on the driver's comfort seat code SB1 and has the same adjustment options. The main difference is the head restraint height and seat cushion length. All adjustments can be made electrically using the switches on the control unit located on the driver's door.

The integrated memory function on the driver's side can save up to three different seat adjustment settings. When switching drivers, the

required seat adjustments can quickly be made with the push of a button making it convenient for frequent driver changes. The electrically adjustable seats come standard with lumbar support, code SE5, and seat heating, code H16. The electrical seat heater with three settings allows for an individual adjustment of the seat temperature and can be operated using the button on the driver's door. The memory function does not save the individual mirror settings. The seat position is not saved on any vehicle key.

The optional 4-way lumbar support system supports the vertebral of the lower back and relieves the back muscles. The backrest contains two air cushions that can be inflated or deflated via two control valves, supporting an ergonomic posture. In addition, their position within the backrest is vertically adjustable. This setting is performed via the lumbar support adjustment switch on the door side of the seat cushion.

SF2	Passenger seat electrically adjustable	Compa	red to Sprint	er 906
	assenger seat electrically adjustable	Carry Over	Advanced	New



This electrical passenger seat is based on the driver's comfort seat code SB2 and has the same adjustment options. The main difference is the head restraint height and seat cushion length. All adjustments can be made electrically using the switches on the control unit located on the co-driver's door.

The integrated memory function on the co-driver's side can save up to three different seat adjustment settings. When switching drivers, the re-

quired seat adjustments can quickly be made with the push of a button making it convenient for frequent driver changes. The electrically adjustable seats come standard with lumbar support, code SE4, and seat heating, code H15. The electrical seat heater with three settings allows for an individual adjustment of the seat temperature and can be operated using the button on the driver's door. The memory function does not save the individual mirror settings. The seat position is not saved on any vehicle key.

The optional 4-way lumbar support system supports the vertebral of the lower back and relieves the back muscles. The back rest contains two air cushions that can be inflated or deflated via two control valves, supporting an ergonomic posture. In addition, their position within the back rest is vertically adjustable.



The thorax-pelvis sidebags are complete integrated in the back rest of the driver's and co-driver's seat. A tag located at the back rest's outside shows the installation of the sidebags. In a side impact, the side airbags can help to protect the torso and pelvis of the driver and co-driver. In addition they can stabilize the whole body to reduce the risk of serious injury in case of an accident.

SH2	SH2 Thorax-pelvis sidebag, passenger	Compared to Sprinter 906		
3112	Thorax-pervis sidebag, passeriger	Carry Over	Advanced	New



The thorax-pelvis sidebags are complete integrated in the back rest of the driver's and co-driver's seat. A tag located at the back rest's outside shows the installation of the sidebags. In a side impact, the side airbags can help to protect the torso and pelvis of the driver and co-driver. In addition they can stabilize the whole body to reduce the risk of serious injury in case of an accident.

SH9 Air	Airbag, driver/passenger window	Compared to Sprinter 906			
	Alibag, univer/passenger willdow		New		



The window bags, fitted in the roof trim over the driver's and passenger doors, deploy in an accident with severe lateral acceleration/deceleration (e.g., a side impact). Within fractions of a second, the window bag fills with gas and positions itself like a curtain between the side window and the driver's/passenger's head.

## Benefits:

Reduces the risk and severity of head and facial injuries in the event of a severe side impact. Window airbags reduce the risk of the driver/passenger on the collision side sustaining head and facial injuries in the event of a severe side impact. In conjunction with correctly fastened safety belts, they provide increased protection in the event of a severe side impact.

## Omission of windowbag, co-driver

**Compared to Sprinter 906** 

Carry Over Advanced New



The window airbag units are installed along with the associated filling pipe at the inside of the respective roof frame behind the A-pillar paneling. The window airbags can protect the head area of the front passengers on the affected side in the event of a side impact. The code SJ3 deletes the codriver's window airbag. In this case only the driver's window airbag is installed. This allows special-purpose vehicles with modified passenger section.

SKO/	0 ( ) 1 ( ) 1 ( ) (	Compai	red to Sprin	ter 906
SK1	Comfort head restraint, front driver/passenger	Carry Over	Advanced	New



The standard 2-way head restraints of the front seats can be replaced with the comfort variant. The comfort variants are characterized by manually adjustment options:

- Raise upwards
- Lower downwards
- Move forwards
- Move backwards

SK2	Seat occupancy sensor driver seat	Compared to Sprinter 906			
SILZ	Seat occupancy sensor universeat	Carry Over	Advanced	New	

The driver's seat occupied recognition detects whether the driver's seat is occupied. Only the status "seat occupied" or "seat not occupied" can be detected. This feature is needed for the HOLD-function, Electrical parking brake, and DISTRONIC.

SR8/	Swivel base for driver's +	Compared to Sprinter 906		
SR9	passenger seat	Carry Over	Advanced	New

A swiveling base is fitted on the driver/ passenger seat base.

#### Benefits:

Allows a custom driver/passenger seat to be fitted. Can be turned around by about 180 degrees to face the rear. Basis for installation of a swiveling seat ex-factory works (e.g., SB1) or installation of a custom seat by an upfitter. Recommended for vehicles, which are to be equipped as an RV.

SW1 Seat belt deletion	Seat belt deletion, passenger	Compared to Sprinter 906		
344 1	Seat beit deletion, passenger	Carry Over	Advanced	New

The code SW1 is available for all vehicles >10.000 lbs. and includes the deletion of the passenger's height-adjustable three-point seat belt.

#### Benefits:

For custom vehicles (e.g., buses) that are not fitted with a passenger seat and seat base since the passenger's door is used as an entrance

SZ7 Storage net, driver's seat backrest	Compared to Sprinter 906			
3L1	Storage net, driver a seat backrest	Carry Over	Advanced	New



Storage net installation on the back of the driver's seat backrest.

#### Benefits:

The installation of this equipment provides a further storage possibility, for instance, for newspapers.

SZ8	Storage net, passenger seat backrest	Compared to Sprinter 906		
320	Storage net, passenger seat backrest	<b>Carry Over</b>	Advanced	New



Storage net installation on the back of the passenger seat backrest.

#### Benefits:

The installation of this equipment provides a further storage possibility, for instance, for newspapers.

T12	Sliding door two stage opening	Compared to Sprinter 906		
112	Silding door two stage opening	Carry Over	Advanced	New

An intermediate stop that allows the sliding load-compartment door to stop at approximately 30.7" (780mm). The intermediate detent, lock the sliding door(s) in place around halfway when opening and closing. This occurs due to different sliding rail(s) and travel limiter(s) and allows that the door does not have to be opened fully when getting into or out of the vehicle. The door can still be opened all the way.

## Benefits:

Additional stop point for sliding load-compartment door(s). Allows rear passengers to board and alight quickly, since the sliding load-compartment door does not need to be opened as far as the end position.

## Sliding door, passenger side

**Compared to Sprinter 906** 

**Carry Over** Advanced

New

Sliding load-compartment door on the right-hand side of the vehicle. The size of the door depends on wheelbase and roof height.

Width and height of door opening (W x H):

- Low Roof: 51.2" x 59.8" (1300 x 1520 mm) with 144 WB
- High Roof (D03): 51.2" x 71.2" (1300 x 1810 mm) with 170 WB



#### Benefits:

Access to passenger/load compartment

T19	Sliding door, driver's side	Compared to Sprinter 906		
3 Siluling door, driver's side	Carry Over	Advanced	New	

Sliding load-compartment door on the left-hand side of the vehicle. The size of the door depends on the wheelbase and roof height.

Width and height of door opening (W x H):

- Low Roof: 51.2" x 59.8" (1300 x 1520 mm) with 144 WB
- High Roof (D03): 51.2" x 71.2" (1300 x 1810 mm) with 170 WB



## Benefits:

Access to passenger/load compartment

T50	Electric closing assist right sliding door	Compared to Sprinter 906		
	(soft close)	Carry Over	Advanced	New

To overcome the closing forces at the end of closing procedure, an electrically driven closing assist is used in the corresponding sliding door. A sliding door closing assist motor is located in the center of the C-pillar and move the striker in the corresponding door a defined distance to ensure that the sliding door can be closed without noise, free of vibration and without increased force. On vehicles with high roof, code D03, an electrically driven auxiliary lock is additionally installed in the corresponding sliding door.

T51	Electric closing assist left sliding door	Compared to Sprinter 906		
	(soft close)	<b>Carry Over</b>	Advanced	New

To overcome the closing forces at the end of closing procedure, an electrically driven closing assist is used in the corresponding sliding door. A sliding door closing assist motor is located in the center of the C-pillar and move the striker in the corresponding door a defined distance to ensure that the sliding door can be closed without noise, free of vibration and without increased force. On vehicles with High

roof, code D03, an electrically driven auxiliary lock is additionally installed in the corresponding sliding door.

T55	Electrical sliding door right	Compared to Sprinter 906		
		Carry Over	Advanced	New



The Electrical operation of the right sliding door, enables the sliding door to be opened and closed electrically via a button on the center console, on the B-pillar or via the key. The sliding door can also be stopped and held in any position. The electric sliding door is provided with an obstacle detection function for improved protection of persons using the door. If the obstacle detection function detects any resistance during closing the sliding door, the closing process is interrupted and the door opens again.

The electrical operation function is deactivated during driving. An audible warning occurs when the sliding door is opened or closed. The closing assist is included without any sales code. If there has been a malfunction or if the battery has been disconnected, the sliding door can be disconnect from the electric motor using the release catch. Then the sliding door can be opened manually.

T57	Electric sliding step	Compared to Sprinter 906		
		Carry Over	Advanced	New



The electric step automatically extends when the sliding door opens, and retracts after the sliding door closes. This operation is possible without a use of the ignition key. The electric step is 47.24" (1200 mm) width and 11.42" (290 mm) depth. The maximum permissible capacity is 330 lbs. (150 kg). The aluminum step with a hot- dip galvanized cassette has a self-weight of 92 lbs. (42 kg).

The electric step includes an obstacle detection sensor at the front, so in the case of a collision, e.g. with the curb, it stops immediately. In this situation, a warning signal occurs and a visual warning signal will be shown on the display. To reactivate the electric step into the normal model, it is necessary to close the load compartment sliding door again. With this action, the electric step moves in and switch over into normal mode.

The access height for the step is 8.66" (220 mm).

Note: The ground clearance is reduced by approx. 3,94" (100 mm).


T60

# Opening limiter, electrically operated sliding door

Compared to Sprinter 906

Carry Over | Advanced

New



The opening limiter is a fixed stop of the sliding door at an opening of 30.7" (780 mm). This allows passengers a faster step in and out of the vehicle.

Notice: Other than the manual operated sliding door with a two-stage opening T60 has a limited door opening. Hence the door can never be opened further than 30.7" (780 mm).

٦	<b>7</b> 4	
	/4	

# Assist handle, B-pillar

**Compared to Sprinter 906** 

Carry Over

Advanced

New



This grab handle(s) is installed vertically on each B-pillar if the vehicle is equipped with sliding door(s) and allows an easier entry to the load/passenger compartment through the sliding door(s).

#### Benefits:

Easy entry to passenger compartment. Easier entry for passengers.

**T75** 

# Door-mounted assist handles, driver & passenger

Compared to Sprinter 906

Carry Over A

Advanced

New



The grab handle is installed vertically on the driver and passenger door of the vehicle, and facilitates getting into the vehicle providing another option to hold on the way.

The grab handles are automatically added with the following equipment:

Code ZG3, All-wheel-drive, engage able, with low range

**T77** 

## Assist handle w/ partition

Compared to Sprinter 906

**Carry Over** 

Advanced

New



Installation of a vertical grab handle on the partition.

#### Benefits:

Easy entry to load compartment.

T85 Assist handle, left rear door Compared to Sprinter 906

Carry Over Advanced New



This grab handle(s) is installed vertically on the left D-pillar and allows an easier entry to the load compartment through the rear door.

T86	Assist handles, right rear door	Compared to Sprinter 906		
		Carry Over	Advanced	New



This grab handle(s) is installed vertically on the right D-pillar and allows an easier entry to the load compartment through the rear door.

T93	Sliding door right side deletion	Compared to Sprinter 906		
173	Silding door right side deletion	<b>Carry Over</b>	Advanced	New

Via code T93, it is possible to delete the right-hand side sliding door and its entrance step.

## Benefits:

Special interior fittings can be installed. Allows interior fittings to be mounted on both sidewalls.

U1A	14+1 seater version	Compared to Sprinter 906		
		Carry Over	Advanced	New



The 14+1 seater version, with four rows of seat benches, is for the passenger van (BM907.745) with weight variant of 9,480lbs (4,300kg). All benches include three-point seat belts and can be upgraded with available comfort packages and options.

**U3S** 

Three-seater bench in passenger compartment, third row (narrow)

Compared to Sprinter 906



Advanced

New



A three-seater bench (narrow) is fitted in the **third** row of the passenger compartment on 14+1 passenger vans. All three seats are fitted with a three-point seat belt, and can be upgraded with available comfort packages and options.

U3Y

Three-seater comfort bench in passenger compartment third row (narrow)

Compared to Sprinter 906

Carry Over | Advanced

New



A three-seater <u>comfort</u> bench is fitted in the **third** row of the 14+1 passenger compartment and can be optionally selected. All three seats are fitted with a three-point seat belt and have additional seat bolter padding, allowing for enhanced seating comfort. Each row is individually reclinable as well as an individual recliner setting on each seat.

U62

Three seater bench in passenger compartment, first row (narrow)

**Compared to Sprinter 906** 

Carry Over

Advanced

New



Three-seater bench in passenger compartment, **first** row, on left-hand side (in the direction of travel). All three seats are fitted with a three-point inertia-reel safety belts. ISOFIX child seat attachment points are on the two outer seats.

**U74** 

Wall-side arm rest

Compared to Sprinter 906

Carry Over

Advanced

New



An angle-adjustable armrest is fitted to the outboard side (wall side) of the backrest of the passenger compartment bench seat.

#### Benefits:

Enhanced seating comfort. Armrest allows a more relaxed seating posture to be adopted.

U75 Aisle-side arm rest Compared to Sprinter 906

Carry Over Advanced New



An arm rest is fitted to the aisle side of the backrest of the passenger bench seat, allowing for enhanced seating comfort.

UC3

Three-seater bench in passenger compartment, second row (narrow)

Carry Over Advanced New



A three-seater bench is fitted in the **second** row of the passenger compartment. All three seats are fitted with three-point inertia-reel seat belts. ISOFIX child seat attachment points are on the two outer seats.

UD6
Four-seater bench in passenger compared to Sprinter 906
Carry Over Advanced New



A four-seater bench is installed in the passenger compartment, **third** row. All four seats are fitted with three-point inertia-reel seat belts.

UD7 Four-seater bench in passenger compartment, fourth row Compared to Sprinter 906

Carry Over Advanced New



A four-seater bench is fitted in the **fourth** row of the 14+1 passenger compartment. All four seats are fitted with a three-point seat belt and can be upgraded with available packages and options ordered as a comfort variant. (UY6)

UY1

# Three-seater comfort bench in passenger compartment, first row (narrow)

Compared to Sprinter 906

Carry Over | Advanced

New



A three-seater <u>comfort</u> bench is fitted in the **first** row of the 14+1 passenger compartment. All three seats are fitted with a three-point seat belt and have additional seat bolster padding, allowing for enhanced seating comfort. This comfort variant can be equipped on Crew and Passenger Sprinters. Each row is individually reclinable as well as an individual recliner setting on each seat.

UY2

Three-seater comfort bench in passenger compartment, second row (narrow)

Compared to Sprinter 906

Carry Over | Advanced

New



A three-seater <u>comfort</u> bench is fitted in the **second** row of the passenger compartment. All three seats are fitted with a three-point seat belt and have additional seat bolster padding, allowing for enhanced seating comfort. Each row is individually reclinable as well as an individual recliner setting on each seat.

UY3

Four-seater comfort bench in passenger compartment, third row

Compared to Sprinter 906

Carry Over | Advanced

New



A four-seater <u>comfort</u> bench is fitted in the **third** row of the passenger compartment. All four seats are fitted with a three-point seat belt and have additional seat bolster padding, allowing for enhanced seating comfort.

UY6

Four-seater comfort bench in passenger compartment, fourth row

Compared to Sprinter 906

Carry Over | Advanced

New



A four-seater <u>comfort</u> bench is fitted in the **fourth** row of the 14+1 passenger compartment. All three seats are fitted with a three-point seat belt and have additional seat bolster padding, allowing for enhanced seating comfort.

V07	V07 Cab rear wall liner	Compared to Sprinter 906		
<b>V</b> 0 7	Cab leal wall lillel	<b>Carry Over</b>	Advanced	New

Functional and visually appealing addition: The rear wall of the cab on the Sprinter cab chassis and with the Sprinter cargo, the inside of the partition wall to the load compartment, is fitted with additional paneling made of pressed fiber fleece. It provides sound insulation of the cargo compartment from the driver's cockpit. The rear wall paneling is required when ordering the following equipment:

• Code H04, Heat insulation

V21	Luxury interior trim	Compared to Sprinter 906		
VZI	Luxury interior triiii	Carry Over	Advanced	New



The luxury interior paneling, code V21, in dark grey fabric gives the passenger compartment a representative look, and also improves the noise and heat insulation. The paneling is made of wood-dust filled polypropylene boards and a 0.12" (3.05 mm) thick layer of polyurethane foam, all lined with fabric. This paneling includes 5V USB-C charging ports with a smart phone holder for each row installed on the left side of the vehicle.

#### Benefits:

- Luxurious interior appearance
- Good sound and heat insulation
- Charging capabilities



#### **USB-Port Overview**

Radio/Head Unit	Code	USB-C port	Location		Function		
Parallel Come	Total Control	amount	Location	Charging	Data Transfer	Intelligent*	
Standard USB-socket	E1U	110	Lower Center Console	×			
Standard Radio	E10	157	Integrated in Standard Radio	×	x		
7" Screen	ESM	1	Center Dash Board	×	х.	X	
7° Screen with Wirelesa	E3M + E1B	T.	Center Dash Board	×	×	x	
Charging	ESW + E1B	1	Center Dash Board	x	X		
7° Screen with	ESM +	1	Center Dash Board	×	×	×	
Navigation/Satellite Radio	E1E/E1S	10	Center Dash Board	×	X		
7* Screen with	E3M + E1E/E1S + E1B	1	Center Dash Board	×	X	х	
Navigation/Setallite Redio and Wireless Charging		2	Center Dash Board	Х	х		
	E4M	t	Center Deah Board	x	×	х	
10.25" Screen with Navigation	E4M	1.	Center Dash Board	×	x		
10.25" Screen with Navigation	E4M + E1B	10	Center Dash Soard	X	х	Х	
and Wireless Charging	E4M + E1B 2	Center Dash Board	×	×			
Charging Package	ES5	10	Center Dash Board	×			
CONTRACTOR AND		13	also includes a 12V socket in center dash board				
Rear Ports PV	V21	4-5	Rear Paneling	X			

<sup>\*</sup>Smartphone Integration (Apple Car Play/Android Auto)

# Pallet support in sliding door step

Compared to Sprinter 906
Carry Over Advanced New



A pallet support is available for the standard step in the load compartment (sliding door). The two plastic inserts are latched onto the step and close the gap between the closed sliding door and the floor of the load compartment.

Allows for the entire space between the sliding door and opposite wall to be used e.g. for heavy pallets. The pallet support is only available in

combination with wood flooring (V43) and a partition (D50/D51). The pallet support has a cavity which can be used to store the optionally available straps (YK3 / YK4).

V25	Half height load compartment trim	Compared to Sprinter 906		
VZJ	Trail height load compartment trill	Carry Over	Advanced	New



The side walls and doors of the passenger/load compartment are covered with 0.08" (2.03 mm) thick black wood-dust filled polypropylene boards from floor up to the height of the window sill girder, code V25. The wood-dust filled polypropylene boards are hydrophobic, washable, robust and 100 % recyclable.

#### Benefits:

Protects metal surfaces from damage. The interior paneling provides enhanced protection for the metal surfaces of the load compartment against damage from the inside.

V31	1 Window pillar trim	Compared to Sprinter 906		
V31	willdow pillar trilli	<b>Carry Over</b>	Advanced	New



The standard painted window pillars can be lined, between the roof trim and the side trim, with matt black washable plastic paneling.

#### Benefits:

Enhances the look of the interior. Standard on passenger vans and optional on cargo vans.

# V35 Wheel house covering Compared to Sprinter 906 Carry Over Advanced New



The code V35 includes black rubber covers for the wheel housings, protects them from damage, and provides additional noise insulation.

#### Benefits:

- Protects the wheel arches against damage
- Additional noise insulation

V36	Roof trim	Compared to Sprinter 906		
VSU	ROOI UIIII	Carry Over	Advanced	New

The roof can be covered with anthracite non-woven fabric, which improves the heat and sound insulation in the load/passenger compartment. Additionally the D-pillars are lined with matt black washable plastic paneling. There can be up to four interior lights



installed and can be turned on/off via the front overhead panel or the first row interior light.

#### Benefits:

- Enhances the look of the interior
- Good sound and heat insulation

V39	Weight optimized plastic floor	Compared to Sprinter 906		
V 3 7	Weight optimized plastic hoof	Carry Over	Advanced	New



The load compartment floor consists of a three-dimensional center layer with bubble structure on which a TPO film (thermoplastic polyolefin) is laminated. The TPO film is durable, stain-resistant, slipresistant and has low wear. The bubble structure of the center layer ensures a low weight while offering strong rigidity and good damping properties. Below that is an insulating foam layer. Support bars connect it to the vehicle floor. The plastic floor has a thickness of

0.31" (8 mm) and builds as tall as the wood floor (code V43).

- Durable, stain-resistant, slip-resistant and has low wear
- Protection against damage to the bare load compartment floor
- · Additional heat and noise insulation
- Pleasant stepping surface for passengers
- Added payload over wood floor of about 66 lbs.

# V40 Floor anchors for rear seat bench Compared to Sprinter 906 Carry Over Advanced New

The V40 floor allows installing bench seats up to the fourth seat row of the passenger compartment (depending on the vehicle). To this end, the passenger compartment is already fitted with the appropriate mounting points and reinforcements in the body shop. For cargo vans ordered with this floor and without any seating in the rear compartment, there is no direct access to the mounting points. V40 is standard for passenger vans.

#### Benefits:

Bench seats can be retrofitted.

V42	Lashing rails, waist-level	Compared to Sprinter 906				
V4Z	Lasillig rails, waist-level	Carry Over	Advanced	New		



The sidewall tie-down rails on the hip rail/roof frame and the load securing rail system allow cargo to be safely secured to the sidewalls. The holes in the lashing rails are spaced at about 1" (25 mm) intervals where the four supplied anchoring lugs (studs) can be attached. The maximum tensile loading of the lashing points on the tie-down rail on the hip rail is 450 lb.ft/200 daN. Tie-down rails are not installed on the load compartment sliding door, but are available as part of the accessories range.

Load Rating is 2,500 N (562 ft-lbs.).

#### Benefits:

Provides a load restraint for bulky cargo. The lashing rails are used in conjunction with load-securing straps to prevent cargo such as windows from sliding around or falling over.

V43	V43 Wood floor with 6 D-rings	Compared to Sprinter 906		
V43	Wood floor with o D-filigs	Carry Over	Advanced	New



The code V43, wood flooring, includes a plywood floor installed in the load compartment. The top of the wooden floor is coated with a grey, hardwearing and non-slip melamine resin film. The bolted lashing points fix the wooden floor down. The number of

anchoring lugs utilized varies according to the length of vehicle.

# For vehicle length

144" WB: 8 lugs170" WB: 10 lugs170" WB EXT: 12 lugs

• D-Ring load rating is 5,000 N (1,124 ft-lbs.)

#### Benefits:

- Easier loading/unloading and easier cleaning of the load compartment
- Additional heat and noise insulation
- Protects the underlying floor of the load compartment from damage. Facilitates cleaning and loading – particularly of heavy objects such as pallets – since the wood floor is level-surfaced.
   Provides additional heat and noise insulation.

V4A Full paneling, right sliding d	Full papeling right sliding door	Compa	red to Sprint	er 906
	run panenng, right shung door	Carry Over	Advanced	New



The matte black washable plastic paneling is available for the right-hand sliding door and for the hinged rear doors. This paneling completely covers all metal parts; therefore, improving a visual upgrade of the passenger compartment. In addition, it improves the sound and heat insulation.

V52	Loadable wheel arch	Compared to Sprinter 906		
VJZ	Loadable wheel alch	Carry Over	Advanced	New



The square shaped wheel arch covering provides protection for the wheel arches and increased storage space in the load compartment due to their flat top. Similar to the wood floor (V43), the wheel arch covers are made of 0.31" (8 mm) thick wood, and can carry a load of up to 440 lbs. (200 kg). The edges and corners are protected by aluminum strips and steel caps. The width of the load compartment is slightly reduced.

The wheel arch covers are fastened to both floor and side wall. They are only available in combination with the wood floor (V43). V52 reduces the payload by approximately 22lbs (10kg).

Note: V52 is only available for single tire models (1500/2500).

V85	Cigarette lighter + ash cup, front	Compared to Sprinter 906			
<b>V</b> 05	organiette righter + asir cup, mont	Carry Over	Advanced	New	



small waste receptacle.

The smoker package, includes a cigarette lighter in the center console and an ashtray located in the upper part of the dashboard. The cigarette lighter is supplied with voltage via the terminal 15.

#### Benefits:

Helps keep the driver's section clean and tidy. Also serves as a

V94	V94 Cable duct - side wall	Compared to Sprinter 906		
V 7+	Cable duct - Side Wall	<b>Carry Over</b>	Advanced	New

The ducts are standard for the cargo van and include the installation of cable ducts on the side wall

V95	Cable duct - rear portal	Compared to Sprinter 906			
V 75	Cable duct - Teal portal	Carry Over	Advanced	New	

The ducts are standard for the cargo van and includes the installation of cable ducts on the rear portal

VA1	VA1 Side wall paneling waist height pvc	Compared to Sprinter 906			
VAI	Side wall patiening waist neight pvc	Carry Over Advanced	New		



When ordering code VA1, the sidewalls and doors of the load compartment are covered with 0.08" (2.4 mm) thick black wood-dust filled polypropylene boards as well as a 0.12" (3.0 mm) thick layer of polyure-thane foam from floor up to the height of the window sill girder.

#### Benefits:

Enhances the appearance of the load compartment. Protects the metal surfaces of the load compartment against damage from the inside and creates a high-class appearance.

VA3	VA3 Side wall paneling full hardboard	Compared to Sprinter 906		
VAS	Side wan panening full hardboard	Carry Over	Advanced	New

The cargo compartment sidewalls, the sliding door(s) and the rear doors are lined with 0.189" (4.8 mm) thick gray polypropylene (PP) Con-Pearl plastic panels. The trim extends as far as the roof frame. The plastic panels are food-safe, moisture-resistant, washable, abrasion-resistant and recyclable.

Vans with a high roof (D03) without a window have a three-piece paneling on the side walls, sliding door(s) and rear-end doors, from the floor up to the belt rail as well as two pieces from the belt rail to the roof. Vans with a high roof (D03) with a window: two-piece paneling of the side walls, sliding door(s) and rear-end doors, from the floor up to the belt rail as well from above the window to below the roof



- Washable
- Food-safe
- Abrasion-resistant
- Recyclable
- Protects the interior sidewalls
- The floor-to-roof trim protects the metal surfaces inside the cargo compartment from shifting cargo.

# Full paneling, hinged rear doors

**Compared to Sprinter 906** 

Carry Over | Advanced

New



The matte black washable plastic paneling is available for the right-hand sliding door and for the hinged rear doors. This paneling completely covers all metal parts; therefore, improving a visual upgrade of the passenger compartment. In addition, it improves the sound and heat insulation.

VA7

Storage compart. W/ net in rear doors

Carry Over Advanced New



An additional storage compartment with nets is integrated into the door panels of the rear doors. This creates storage facilities for various items, such as Straps or work gloves, directly on the inside of both rear doors.

Benefits: Additional storage

VC4

Cargo lashing rails, head height

Carry Over Advanced New



height at approximately 28.5" (724 mm) and also the roof frame at approximately 64.4" (1636mm) with a distance between the two of approximately 38.9" (988 mm) below the roof frame. The holes in the lashing rails are spaced at approximately 1" (25 mm) intervals. Straps are not included in the specification, but are available as accessories. Load

Bonded lashing rails are fitted along the side walls of the vehicle at hip

rating is 1,500 N (335 ft-lbs.).

### Benefits:

Provides load restraint for tall bulky objects. The lashing rails are used in conjunction with load-securing straps to prevent tall bulky objects such as doors from sliding around or falling over.

# VC5 Door Sill - protective edge Compared to Sprinter 906 Carry Over Advanced New



When ordering this code an aluminum strip is mounted to the wooden floor in the entrance area of the right load compartment sliding door. In order to make the strip fit perfectly that part of the wooden floor is milled out and the aluminum strip inserted into the recess. The strip

serves to protect the edge of the floor from damage when entering and exiting, or loading and unloading.

#### Benefits:

Protects the edge of the wood floor. The aluminum strip protects the edge of the wood floor from damage during loading.

Note: The lashing eyes in the sliding door entrance area are not level with the floor.

VEA	VF4 Fabric caluma black	Compared to Sprinter 906			
V14	l abiic calulla black	Carry Over	Advanced	New	



Seat cushion and back rest are decorated with a white striped pattern, while seat bolsters, head rest and back of the seat remain solid black

VF6	VF6 Artico man-made leather, black	Compared to Sprinter 906		
VIO	Aitico man-made leather, black	Carry Over	Advanced	New



Seat cushion, back rest, seat bolsters, head rest and the back of the seat are covered in artificial leather. However, the seat bolsters (seat cushion only) of the driver's seat are covered in real leather. The low-wear artificial leather is easy to clean using water and a suitable soap-based detergent.

Note: For vehicles without partition wall, the back of the seat is covered in artificial leather, while for vehicles with partition wall the back of the seat will be covered in black fabric.

VF7	VF7 Fabric maturin black	Compared to Sprinter 906		
V1 /	l ablic maturin black	Carry Over	Advanced	New

This Fabric Maturin Black, code VF7, is the standard upholstery material offered, and can optionally be replaced by either Fabric Caluma black, code VF4, or Artico Man-Made Leather Black, code VF6.

The following areas are covered in the Fabric Maturin black:



- Seat cushion
- Back rest
- Seat bolsters
- Head rest
- Back of the seat

VK8	Floor covering, plastic	Carry Over Advanced New			Compared to Sprinter 906		
VICO	riodi covering, piastic	Carry Over	Advanced	New			



The weight-optimized plastic floor consists of a cap profile middle layer with plastic sheets laminated onto each side. The cap profile in the middle provides very good stability and sound insulation while at the same time being light-weight. A layer of foam

backing underneath the plastic floor creates additional sound insulation. Supporting strips complete the vehicle floor. Depending on vehicle length, six to twelve lashing eyelets are mounted. These plastic sheets are slightly thicker while the middle layer is lower in height. That way, the covering is more robust while retaining the same overall height. In addition to the improved structure a TPO-layer (TPO = thermoplastic polyolefin) is applied to the top surface to make it water-proof, low-wear and slip resistant.

VV2	Lashing rails, floor-level	Compared to Sprinter 906		
V V Z	(plus 4 anchors)	Carry Over	Advanced	New



The load securing rail system includes two rails that are attached to the floor in the load compartment. Each load securing rail is configured for a maximum tensile loading of 1124 lb.ft/500 daN. Straps are not included in the specification, but are available as accessory.

Benefits:

Allows loads to be firmly secured. The lashing rails are used in conjunction with load-restraining straps to provide quick, individually adaptable restraint for objects of varying sizes.

VV4	Additional ground weld studs	Compared to Sprinter 906		
V V <del>'</del>	Additional ground weld studs	<b>Carry Over</b>	Advanced	New

An additional set of 4x ground studs will be added on to the vehicle to allow for appropriate grounding locations across the whole vehicle. These studs are in the following locations:

- Passenger seat box 5/16" (M8)
- Driver seat box ¼" (M6)
- Center cross member on the underbody 1/4" (M6)
- Rear right frame member 1/4" (M6)

For more information, please refer to <a href="www.upfitterportal.com">www.upfitterportal.com</a> for 3D CAD data outlining the positions of these ground studs on the vehicle.

Note: these locations will vary slightly depending on the model and wheelbase of the vehicle

W02	Panel Van w/Windows All Round	Compared to Sprinter 906		
VVOZ	i aliei vali w/ willdows Ali Roulid	Carry Over	Advanced	New



The panel van is fitted with windows all-around.

#### Benefits:

- Better visibility when driving and maneuvering
- Lets daylight into the cargo compartment

W16	2 <sup>nd</sup> row, fixed window, driver side	Compared to Sprinter 906		
VVIO	2 Tow, fixed willdow, driver side	Carry Over	Advanced	New

The single-pane safety glass window installed in the front of the left sidewall or in the sliding door lets more daylight into the vehicle interior and improves the situational awareness when driving and maneuvering.

#### Benefits:

- Allows more light into the load compartment
- Provides better visibility when driving

W17	717 2 <sup>nd</sup> row, fixed window, passenger side	Compared to Sprinter 906		
W 17   2	2 Tow, fixed willdow, passeliger side	Carry Over Advanced N	New	

The single-pane safety glass window installed in the front of the right side wall or in the sliding door lets more daylight into the vehicle interior and also improves the situational awareness when driving and maneuvering.

#### Benefits:

- Allows more light into the load compartment
- Provides better visibility when driving

W22	22 Fixed window, center left	Compared to Sprinter 906		
VV Z Z	lixed willdow, center left	Carry Over	Advanced	New

The fixed window at the center of the left side lets more daylight into the load or passenger compartment. It is made of heat-insulating single-pane safety glass.

#### Benefits:

Allows more light into the load compartment

Provides better visibility when driving

W23	Fixed window, center right	Compared to Sprinter 906		
VVZS	Tixed willdow, center right	Carry Over	Advanced	New

The fixed window at the center of the right side lets more daylight into the load or passenger compartment. It is made of heat-insulating single-pane safety glass.

#### Benefits:

- Allows more light into the load compartment
- Provides better visibility when driving

W27	Fixed window, rear left	Compared to Sprinter 906			
VV Z /	l ixed willdow, real left	Carry Over	Advanced	New	

The fixed window at the rear of the left side lets more daylight into the load or passenger compartment. The interior heats up less thanks to heat-insulating single-pane glass.

#### Benefits:

- Allows more light into the load compartment
- Provides better visibility when driving

W28	Fixed window, rear right	Compared to Sprinter 906		
VVZO	Tixed willdow, real right	Carry Over	Advanced	New

The fixed window at the rear of the right side lets more daylight into the load or passenger compartment. The interior heats up less thanks to heat-insulating single-pane glass.

#### Benefits:

- Allows more light into the load compartment
- Provides better visibility when driving

W33	FMVSS 217 Emergency Exit	Compared to Sprinter 906		
VVJJ	Tiwiv 33 2 17 Linei genicy Exit	Carry Over	Advanced	New

In passenger vans, an emergency exit with two lift handles is installed. That allows for a quick exit during an emergency. The emergency window complies with FMVSS 217 regulatory requirements.

### Benefits:

Offers an escape route in the event of a roll-over crash event



# Rear doors, opening to side wall

**Compared to Sprinter 906** 

Carry Over Advanced

New



With W54, hinges are installed that allow the rear doors to be opened to the side wall of the vehicle. The new hinges hold the doors in place on its own without the need of rubber, magnetic bumpers on the door/side wall. This makes loading much easier in confined spaces, for example on ramps. The newly developed door hinges engage automatically at 90° and in the maximum opening position.

#### Benefits:

Easier loading and unloading, particularly in confined spaces. Allows easy reversing with opened rear doors (e.g., at loading ramps), with a view to the rear in the exterior mirrors.

Note: For 170EXT models W54 is standard.

W5F	90 degree fixation point- rear doors	Compa	red to Sprint	er 906
VVJI	70 degree fixation point-real doors	Carry Over	Advanced	New



When loading and unloading on an incline or, for example, in strong winds: with the optionally available additional blocks, the open rear doors of your Sprinter are mechanically fixed at an angle of 90°. This facilitates access to the load compartment and ensures that the rear doors do not close unintended.

Only available in conjunction with rear doors, opening to sidewall (W54)

\M/6.1	W61 Windows in rear doors	Compared to Sprinter 906		
VVOI	Willdows III real doors	Carry Over	Advanced	New



The rear doors are fitted with windows.

- Better rearward visibility
- Allows more light into the cargo compartment

# Black tinting (90%) for rear windows

Carry Over Advanced New



The rear windows, and all side windows in the rear section, are dark gray-tinted (approximately 90% tinting). The windshield and the windows in the driver's and co-driver's doors are green-tinted.

Heating due to solar irradiation of the interior through the rear windows is reduced by approximately 90% compared with non-tinted windows

and by approximately 85% compared with green-tinted windows. Ninety-nine percent of ultraviolet radiation is blocked. If a rear air conditioning system is fitted, its effectiveness is increased. The tinted glass also conceals the passenger/load compartment from view. At the same time the tinting also enhances the look of the vehicle.

#### Benefits:

- Reduces heating of the interior
- Provides visual privacy in the rear section
- Enhances the look of the vehicle

W73	Bumper step, rear, grey	Compa	red to Sprint	er 906
VV / J	bumper step, real, grey	Carry Over	Advanced	New



A slip-resistant step is fitted at the rear of the vehicle, extending across the full width of the doors

W75	Step, wide, at rear end	Compa	red to Sprint	er 906
VV/J	Step, wide, at real elid	Carry Over	Advanced	New



The code W75 includes a hot-dip-galvanized steel step fitted at the rear of the vehicle. The step measures  $63 \times 11,81$ " (1,600 x 300 mm) (width x depth). Solid rubber mouldings on the outer corners provide protection when manoeuvring.

#### Benefits:

Facilitates loading and unloading at the rear of the vehicle.

### Bumper step, rear, spring-loaded

Carry Over Advanced New



A hot-dip-galvanized steel step is fitted at the rear of the vehicle, with fore/aft springing provided by four leaf springs. The leaf springs allow free fore/aft movement of the rear step in a forward direction (in the direction of travel). The step measures approximately 68.89" x 8.66"(1750 X 220 mm) (L x W). The spring-mounted rear step allows for an easy entry and exit. It can prevent or mitigate damage to the vehicle in the event of a collision with an obstacle such as a loading ramp if the vehicle is reversed without due care (the protective effect depends on the speed and angle of the impact).

#### Benefits:

- Impact protection
- Safe and easy access to load compartment

W78	Heated rear window(s) w/washers & wip-	Compared to Sprinter 906		
	ers	Carry Over	Advanced	New



Water is supplied from the central washer fluid reservoir through flexible hoses to spray nozzles mounted in the wiper blades. The windows in the rear-end door provide a clear rear view, thanks to the wiper and washer system. If the front windscreen wipers are turned on, the rear window wipers are automatically switched on in addition when reverse gear is engaged or selected. The position of the wipers has changed from horizontal to vertical.

#### Benefits:

- Cleaning rear door windows
- Better rearward visibility
- Allows more light into the load compartment

W93	Side window openings w/o glass	Compared to Sprinter 906		
W 7 3	Side willdow openings w/ o glass	Carry Over	Advanced	New

On request, the vehicle can be delivered without the side windows in the passenger compartment. When this deletion is requested, the hinged rear doors are equipped with two dark gray (approximately 90% coloration) tinted (code W70) and heated (code H22) windows. For vehicle transfer, the side openings are sealed with a white, protective shipping film.

- Retrofitting of other windows is made possible
- Sidewall only windows are missing for easy retrofit

W94	W94 Window openings w/o glass	Compared to Sprinter 906		
VV 7+	willdow openings w/ o glass	Carry Over	Advanced	New

No passenger compartment windows are fitted, including windows in the rear doors. For transport purposes, con-pearl plastic panels (code P08) close the apertures.

#### Benefits:

Allows easy fitting of different windows.

X90	Deletion of sprinter badge,	Compa	red to Sprint	er 906
λ 7 0	left rear door	Carry Over	Advanced	New

The "Sprinter" badge on the left-hand rear door of cargo and passenger van is deleted.

#### Benefits:

- More room for promotional/company stickers or decals
- Easy wrapping



X93	Deletion of model badge,	Compa	red to Sprint	er 906
Λ73	right rear door	Carry Over	Advanced	New

Deletion of the model identification on the right side hinged rear door.

## Benefits:

More room for promotional/company stickers or decals.



XC8	XC8 VIN visible from outside	Compared to Sprinter 906		
ACO	VIII VISIBLE HOIH outside	Carry Over	Advanced	New




The code XC8 includes a VIN-plate (Vehicle Identification Number) affixed on the left side of the dashboard underneath the windscreen what is visible from the outside.


XM4	Acoustic package	Compared to Sprinter 906		
VIAI	Acoustic package	Carry Over	Advanced	New

XM4 gets added in combination with the head units E3M or E4M. Since you can also control them via voice some additional noise isolation (in the areas marked blue) is installed in the vehicle to reduce road noise.

Cargo, Crew and Cab Chassis



Passenger Van



XO5 Digital owner's manual	Compared to Sprinter 906			
703	Digital Owner's manual	Carry Over	Advanced	New

The digital owner's manual provides the customer with vehicle information via the multimedia system with 7" touch screen with navigation or satellite radio or the multimedia system with 10.25" touch screen that exceeds the standard paper format. The search function makes finding information easier and faster. Navigation through the document is self-explanatory, the digital owner's manual is furnished with high-resolution animations, and interactive pictures, which help, make the complex vehicle functions easier to understand. A multitude of animations can be streamed online. The customer can also bookmark content for easier access, e.g. the instructions for hooking up smartphones. The Owner's Manual is also available in the Mercedes-Benz Guides App, which can be obtained from common phone app-stores.

XW6	6 Front license plate deletion	Compared to Sprinter 906			
AVVO	Tront needse plate deletion	Carry Over	Advanced	New	

This option code XW6 deletes the front license plate.

Y10	First-Aid Kit	Compa	red to Sprint	er 906
110	i iist-Aid Kit	Carry Over	Advanced	New



The First aid kit will be stored in a plastic case in the co-driver's door panel and can be used to provide initial care for injured persons.

- Allows initial care to be provided for injured persons
- Conveniently located for quick access
- Takes up little space





Cargo and passenger van models have a chock holder mounted on the D-pillar at the rear right of the cab. Cab chassis models have a chock holder mounted on the left at the frame end.

#### Benefits:

- Secures the vehicle against rolling on gradients
- Safe storage of the chock
- Additional security when parking the vehicle on an incline

Y43	Jack, Hydraulic	Compa	red to Sprint	er 906
143	Jack, Hydraulic	Carry Over	Advanced	New



The hydraulic jack facilitates jacking up the vehicle to change a tire. It is located in a bracket in the entrance area on the passenger's side and is easy to remove.

Benefits: Easy tire changing.

Y45	Emergency flashlight	Compa	red to Sprint	er 906
143	Linergency nashinging	Carry Over	Advanced	New



The warning lamp increases the road safety in case of an accident or breakdown, because the flashing light provides timely warning for drivers of following vehicles. The lamp can be set to steady white light or on orange flashing light. The white light can be helpful when making minor repairs in the dark.

Y68	Paint preservative	Compa	red to Sprint	er 906
100	Failit preservative	Carry Over	Advanced	New

A white protective film is applied on the roof and bonnet of the finished vehicle that protects the paint from the environment.

Y69	Surface protection for stock vehicle	Compared to Sprinter 906		
109	Surface protection for Stock vehicle	<b>Carry Over</b>	Advanced	New

Vehicles which exceed a storage period of 21 days after completion are covered with white protective foil. This adhesive foil is applied to the front, sides, rear and roof. The protective foil must be removed and the vehicle washed before delivery.

Y90	Jack deleted	Compared to Sprinter 906		
170	Jack deleted	Carry Over	Advanced	New

Deletion of hydraulic jack.

YK3	Cargo straps, D-rings	Compared to Sprinter 906		
113	Caigo straps, D-rings	<b>Carry Over</b>	Advanced	New

Two tensioning straps with lever brace and lashing hook with an overall length of 137.79" / 3.5 m is be provided via code YK3. The maximum rated loads are for the draw out is 1461 lb.ft/650 daN and for the strapping 2922 lb.ft/1.300 daN.

#### Benefits:

- Load-restraining function
- Improves safety since the load cannot shift out of place easily

YK4	Cargo straps, lashing rails	Compared to Sprinter 906		
11174	Cargo straps, lastillig rails	Carry Over	Advanced	New





The package code YK4 includes four lashing eyes/double-studs (without straps) with maximum rated load of 800 daN, and two lashing straps with two double-studs (length 118.0" (3 m)) and maximum rated load with draw out of 1124 lb.ft/500 daN.

#### Benefits:

Enables the load to be restrained and prevents shifting.

Z5U	Vehicle class, incomplete vehicle	Compared to Sprinter 906		er 906
230	(49 CFR, 571.3)	Carry Over	Advanced	New

Vehicles with code Z5U are classified as incomplete vehicle, which need to be completed by a body-builder. An Incomplete Vehicle Document (IVD) will be delivered with the vehicle. If any of the packages (F02/F03/F07) are ordered, the vehicle will become an "incomplete vehicle"! In this case, an upfitter will become the final stage manufacturer.

Please note that the involvement of an upfitter is required to register the vehicle. We recommend working with one of our ExpertSolutions Partners

For questions or further assistance, please reach out to vaninfo@mbusa.com

ZE6	Shelving prep	Compared to Sprinter 906		
ZLO	Sileiving prep	Carry Over	Advanced	New



Brackets welded to the roof bows and to the floor and allow shelves to be retrofitted easily. Avoids the need for drilling and welding to the frame.

#### Benefits:

Shelves can be retrofitted more easily. The pre-installed mounting points allow shelves to be retrofitted more quickly. No further drilling or welding of the frame and roof spars is required.



ZG3	4x4 - high range t-case w/ low gear	Compared to Sprinter 906		
203	+x4 - Iligii ralige t-case w/ low geal	<b>Carry Over</b>	Advanced	New

Vehicles specified with all-wheel drive have flange-mounted the transfer case directly onto the main gearbox for the power transmission to the front axle, while the front-axle-drive has been kept very compact. The all-wheel drive can be engaged when the engine is running either when the vehicle is stationary and shifting lever is in position N.

By using a switch on the instrument panel, an electric motor engages a pair of spur gears in the transfer case. An indicator lamp in the switch informs the driver that the all-wheel drive is engaged and the instrument cluster shows the message "Four-wheel drive active".

When all-wheel drive is engaged, the drive power of the Sprinter 4x4 is split 35:65 between the front and rear axles. The planetary gear unit acts as an inter-axle differential and balances the differences in rotational speed between the front and rear axle. The drive power will be shared over the front differential to the front wheels.. All the components of the standard-fit adaptive ESP remain operational even when all-wheel drive is selected and the acceleration skid control (ASR) is activated. Selecting the all-wheel drive improves the Sprinter's traction, lateral stability and pulling power whereby the vehicle handling improves mainly on difficult surfaces (e.g. snow, ice, gravel).

The Sprinter 4x4 model 's all-wheel-drive system works with the electronic traction system 4ETS instead of mechanical differential locks. If one or more of the wheels lose traction on a slippery ground, 4ETS brakes the spinning wheels automatically with short pulses and increases the drive torque at the wheels that is offering a good traction. To do this, 4ETS uses the ABS wheel sensors. Automatic brake application 4ETS has the same effect as up to three differential locks: the inter-axle lock, the rear axle lock and the front axle lock.

Additionally a "Low Range" reduction gear is available for off-road use whereby the ratio is shorted by a factor about of 40 percent. The maximum vehicle speeds obtainable in the individual gears are reduced while traction is increased. The reduction gear is recommended where there is a high percentage of driving in mountainous regions, and also in cases where the vehicle is often used with a full payload, or for towing a trailer in off-road situations.

The "Low Range" can be engaged at the push of a switch on the instrument panel with the vehicle stationary, engine running, and the all-wheel drive is activated. An indicator lamp in the instrument cluster informs the driver that the "Low Range" is engaged. The reduction gear is straight-cut, making it extremely robust to maximize mechanical load ability.

With the 4x4, the body of the 2500 (BM907.x4x) is raised approx. 3.94" (100 mm) at the front and approx. 2.95" (75 mm) at the rear. For the 3500XD (BM907.x5x) it is raised approx. 3.94" (100 mm) at the front and approx. 1.77" (45 mm) at the rear. This allows for a proper approach-and break over angle and the wading depth increased. 4x4 vehicles with a permissible maximum weight up to < 10.000 lbs. get a front under ride protection and a front bumper with an integrated front spoiler.

#### Benefits:

- Expands operations in difficult terrain
- · Allows particularly slow and sensitive driving

ZH4	Downhill speed regulation for 4x4	Compared to Sprinter 906		
Z11 <del>4</del>	Downlin speed regulation for 4x4	Carry Over	Advanced	New

The code ZH4, Off-road operation, includes a Downhill Speed Regulation (DSR). DSR supports the driver with the Low Range transmission ratio when the vehicle is driving downhill, off-road and on construction sites. DSR maintains a preset speed on downhill gradients by applying the brakes as required. The speed can be set between about 2.5 mph (4 km/h) and 11 mph (18 km/h) using the brake and accelerator pedals or the cruise control lever. When the vehicle is faster than 11 mph (18 km/h) off-road, DSR switches to standby mode. DSR remains activated but does not brake automatically. If the vehicle is slower than 11 mph (18 km/h), DSR sets the speed to the previously set speed. DSR switches off automatically when the speed is exceeding 28 mph (45 km/h). The Low Range transmission ratio is engaged, the indicator lamp in the instrument cluster lights up and the vehicle is stationary or not faster than 18 km/h.



- 1. Activates DSR and stores the current higher speed
- 2. Activates DSR and stores the current speed
- 3. Activates DSR and stores the current lower speed
- 4. Deactivates DSR

ZZ4

# Brand content Mercedes-Benz, North America

Carry Over Advanced New

The Mercedes-Benz Sprinter is available in both US and Canada.

The main differences between the two brands:



# **Mercedes Me Connect Breakdown**

Service	Hermes (JH3)	Other mandatory op- tional equipment	Further information
Accident & Breakdown Management <sup>7</sup>	✓	EY6	
Emergency Call System <sup>9</sup>	<b>√</b>	EY5	No activation of Mercedes me connect necessary.
Software Updates	<b>~</b>	-	Service works after accepting Mercedes me connect's Terms of Use.
Internet in the Car <sup>22</sup>	✓	E3M + E1E or E3M + E1S or E4M	Additional data volume contract with T-Mo- bile
Live Traffic Information <sup>17</sup> incl. Car 2X Communication	✓	E3M + E1E + E1G or E4M + E1G or E3M + E1E + E2Y or E4M + E2Y	
Multimedia Functions <sup>21</sup>	✓	E3M + E1E or E3M + E1S or E4M	
Navigation Functions <sup>20</sup>	<b>√</b>	E3M + E1E <b>or</b> E4M	
Online Map Update <sup>19</sup>	✓	E3M + E1E <b>or</b> E4M	
Maintenance & Repair Management <sup>7</sup>	✓	-	
Remote Vehicle Diag- nostics	<b>√</b>	-	
Telediagnostics	<b>✓</b>	-	
Remote Retrieval of Vehicle Status	✓	-	
Vehicle Tracker	<b>✓</b>	-	
Parked Vehicle Locator	✓	-	
Internet Radio	✓	E3M or E4M	
Remote door lock/un-lock <sup>23</sup>	✓	-	

1	Mercedes me connect	Mercedes me connect is available for the Contiguous US, Hawaii, and
'	Weredeed me connect	Alaska with the new Sprinter (as of MY 19) and the Metris (as of September 2019 production, MY 20) with a connectivity module. Contact an authorized Mercedes-Benz dealership for more information.
3	Mercedes me connect	In order to prevent distracted driving, the use of the Mercedes me con-
3	App	nect App is not permitted while operating a motor vehicle in order to prevent distracted driving. If used while operating a motor vehicle, there is an increased risk of endangering oneself and others. Please follow your local laws and restrictions.
4	Communication Mod- ule for Digital Services	The availability of services in addition to the integrated Communication Module for Digital Services (LTE) depends on the network coverage of the mobile network provider. The Communication Module for Digital Services (LTE) is not available in the US Virgin Islands or Puerto Rico.
5	Communication Mod- ule for Digital Services	The Communication Module for Digital Services (LTE) is standardly equipped in the Sprinter (as of MY 19) and optionally equipped in the Metris (as of September 2019 production, MY 20).
7	Maintenance & Repair Management	In order for us to offer customer this service, data is transferred from the vehicle to the preferred Dealership. This data includes the vehicle identification number, mileage, service code (A or B), as well as remaining time and mileage until the next service is due and information on the brake system and coolant.
8	Accident and Break- down Management	When customer requests the service, the vehicle data and location are automatically transferred to the CAC. Accident and Breakdown Management is only available in conjunction with the Emergency Call System. The Communication Module for Digital Services (LTE) and the emergency call button are required to use the Accident and Breakdown Management service.
9	Emergency Call System	When the Emergency Call System is triggered, the following data are automatically transmitted: vehicle identification number, GPS position, travel direction, time of the emergency call, language setting, and number of occupants in the vehicle. The Emergency Call System is activated from the moment the vehicle is delivered to the customer following a sale. No separate terms of use have to be accepted. The Communication Module for Digital Services (LTE) and the emergency call button are necessary for use of the Emergency Call System service.
10	Software Updates	Update times, content, and installation times can vary. These are activated when the vehicle is delivered. Updates to the Communication Module for Digital Services (LTE) are automatic, as otherwise certain applications might no longer work. You can access the current status of the software versions in your vehicle via the Mercedes me connect.
16	Internet in the Car	The wireless Internet in the Car is provided by T-Mobile and created via built-in SIM card. A contract must be made with T-mobile in order to access data services, and this contract can be made via the provider's system or infotainment system. In addition to a data contract with T-Mobile, either an MBUX multimedia system with 17.8 cm (7-inch) touchscreen and navigation or satellite radio or the MBUX multimedia system with 26 cm (10.25-inch) touchscreen is required for the Internet in the Car service. Additional costs may apply depending on the amount of data used.
17	Live Traffic Infor- mation	The information from this service is shown on the touchscreen of the multimedia system. Live Traffic Information can only be used in conjunction with the multimedia systems MBUX multimedia system with 17.8 cm (7-inch) touchscreen and navigation or the MBUX multimedia system with 26 cm (10.25-inch) touchscreen.

10	Carta V Camanauniaa	A valid aubaccintian to Live Traffic Information is necessary to use Con-
18	Car-to-X Communica- tion	A valid subscription to Live Traffic Information is necessary to use Carto-X Communication. Car-to-X Communication can only be used in conjunction with the MBUX multimedia system with 17.8 cm (7-inch) touchscreen and navigation or MBUX multimedia system with 26 cm (10.25-inch) touchscreen. Only the data of vehicles directly affected by the event and equipped with Car-to-X Communication are processed, therefore you may not always receive a timely warning of hazards through this system.
19	Online Map Update	The Online Map Update service is only available in conjunction with the MBUX multimedia system with 17.8 cm (7-inch) touchscreen and navigation or MBUX multimedia system with 26 cm (10.25-inch) touchscreen. The service must first be activated and the region for the map update selected in the Mercedes me connect Portal.
20	Navigation Functions	You can only use the Navigation Functions service in conjunction with the MBUX multimedia system with 17.8 cm (7-inch) touchscreen and navigation or the MBUX multimedia system with 26 cm (10.25-inch) touchscreen. Before use, some of the applications must first be activated via the Mercedes me connect.
21	Multimedia Functions	You can only use the Multimedia Functions service in conjunction with the MBUX multimedia system with 17.8 cm (7-inch) touchscreen and navigation or the satellite radio or with the MBUX multimedia system with 26 cm (10.25-inch) touchscreen. Before use, some of the applications must first be activated via the Mercedes me connect. For various functions (Internet Radio and Browser), additional data volume is necessary which can be purchased via the Internet in the Car service.
22	Internet Radio	For Internet Radio to work a contract must be made with T-Mobile in order to access data services, and this contract can be made via the infotainment system in conjunction with the service Internet in the Car.
23	Remote Door Lock/Unlock	The Remote Control function via the Mercedes me connect App makes it possible for you to view the status of the doors and windows. The driver is also able to unlock the vehicle via the Mercedes me connect App.