COLORAND

OPTION PRICING

FOR All 2500 CREW VANS,

M2CV4G - M2CV7X

Exterior Paint Overview

3432	Calcite yellow Sunset red	\$675		7701			
3432	Cumpat red		0-2	7701	Pebble grey	\$0	0=0
	Sunset red	\$675		7224	Graphite grey	\$675	
3583	Velvet red	\$0		7708	Silver grey	\$675	0-0
3589	Jupiter red	\$0	(- ô -)	7709	Blue grey	\$0	0=0
5362	Brilliant blue	\$675		7755	Tenorite grey metallic	\$1,070	0=0
5389	Steel blue	\$0	0 - 0 -	7992	Selenite grey metallic	\$1,070	
5524	Black blue	\$1,070		9040	Jet black	\$1,070	0_0_
5890	Cavansite blue metallic	\$1,070		9136	Grey white	\$675	0=0
5957	Vanda blue	\$675		9147	Arctic white	\$0	
6830	Aqua green	\$0		9197	Obsidian black metallic	\$1,070	0_0_
7160	Stone grey	\$675		9775	Iridiumsilver	\$1,070	

Please see NetStar for latest paint availability information.


Upholstery

Standard

VF7

Fabric

Maturin Black Upholstery



Optional

VF4

Fabric

Caluma Black Upholstery

Upcharge					
Cargo	\$	60			
Cab Chassis	\$	60			
Crew Van	\$	205			
Passenger Van	\$	430			



Optional

VF6

Leatherette

Black


Upcharge					
Cargo	\$	60			
Cab Chassis	\$	60			
Crew Van	\$	205			
Passenger Van	\$	430			




Seat restrictions

		No. of the last of	Fabrics	
Code	Seat VF7		VF4	VF6
	Standard Seats Front	S	0	0
	Standard Seats Rear	S	n/a	0
SF1/SF2	Power Seats	n/a	0	0
SB1/SB2	Comfort Seats Front	S	0	0
	Comfort Seats Rear	n/a	0	0

Front and rear fabric always have to match.





Suspension Matrix

	(argo Van	/ Crew Va	n		
Standard	1500	2500	3500	3500 3500XD		
	Base Sus	pension		CB8	CB8 + A50	
120000		-	A50		-	
	CB1 (add to standard)		-			
Outland	CB7 (moved to option)			-		
Options	CB8 (replacing standard)			S		
	- CB4 (R		Recommended for RV) - only 6cyl Diesel			
	CT1 -					
Coorinlined	CE8 (not with 4x4 models)					
Specialized	B01 (not with 3500/3500XD/4500 144"WB)					
Options	X2R (not with 3500/3500XD/4500 144"W8)					

		Passenger	
	1500	250	0
Standard	144" WB	144" WB	170" WB
	Base Suspension + CB1 + CT1		Base Suspension + CB1 + CT1 + A50

	Cab Chassis		
e	3500XD	4500	
Standard	CB8	CB8 + A50	
0.41		CB4	
Options	A50	-	
	CE8 (not on .	144"WB models)	
Specialized Options	BO1 (not with 3500XD/4500 144"WB)		
	X2R (not with 3500XD/4.	500 144"WB)	

Suspension Details

378371	Standard Suspensions and Options					
Code	Title		Details Details			
A50			creased load capacity of the front axle, where heavier bodies and equipment can be fitted. The higher capacity front heavier cabs and heavier special equipment (e.g. for fire-fighting vehicles and ambulances).			
		Description	Ride comfort due to reduced roll stabilization.			
No Factory Code			The Base Standard Factory suspension, has an adapted front suspension for a lower and more comfortable entry. With the removal of the rear stabilization bar it allows for an overall comfortable ride with reduced roll.			
		Description	Roll Stabilization with height body damping			
СВ7	CB7 Stabilization Level I		CB7 compensates for rolling behavior due to higher center of gravity of loads or bodies. Torsion bars with an increased diameter are added to the front and rear axels. Furthermore, shock absorbers with an adapted characteristic are installed.			
		Description	Enhanced roll stabilization with higher body damping compared to CB7			
CB8	68 Stabilization Level II Benefit		Additional roll stabilization and body damping compared to CB7. Increases torsion bar diameters at the front and rear axles and provides an adapted shock absorber characteristic. Furthermore, rear axle springs with increased rigidity are installed.			
		Description	Designed for vans with a intense rolling behavior due to a much heavier load and higher center of gravity. (i.e. recreational vehicles)			
CB4 Stabilization Level III	Benefit	CB4 comes with larger diameter stabilizers, shock absorbers and with charateristics that are adapted for an increased rebound and compression curve. Furthermore, the leaf springs are increased in rigidity.				
CB1	Suspension for comfort and load protection	Enhanced com	ofort due to adapted damper characteristics and the use of progressive spring characteristics.			
CT1	Rear spring vibration absorbers	:	tion absorbers fitted on the left and right rear spring and lowers the resonant vibrations of the rear springs, thus e development.			

Specialized Suspension Options						
Code	ode Title Explanation					
CE8	Raised rear body mounts	Raised body on rear axle (35mm/1.4")				
		Description	Adjusted braking and handling characteristics for vehicles with increased center of gravity.			
B01	B01 ESP for increased Center of Gravity		With code 801, the ESP® is optimized to reduce the vehicles tilt tendency with a total center of gravity of more than 1000 mm (39,4 inches). It is essential to ensure that the vehicle is equipped with the right suspension and tires. With 801 it is required to also add CB8 or CB4.			
X2R	Canversion to RV requirement	MBUX Timed	Switch-off extended to 6 hours and B01 is automatically added to this code.			

Rear view camera/head unit plausibility

CA/PV/CV					
	Standard	Option A	Option A + JB7	Option A + JB6	Option A + JB8
Radio/HU	E10	E3M/E4M	E3M/E4M	E3M/E4M	E3M/E4M
Camera	FR3	FR8	integrated camera	integrated 360 degree camera	integrated 360 degree camera
Pre-wiring Camera	n/a	n/a	n/a	n/a	n/a
Camera Display	Interior rear view, mirror	7/10.25" Screen	7/10.25" Screen	7/10.25" Screen	7/10.25" Screen

Options shown above lead to an upcharge.

€C					
	Standard	Option A	Option B		
Radio/HU	E10	E10	E3M/E4M		
After-Sales Camera	-	Any analog* Camera	Mercedes-Benz Camera** (digital)		
Pre-wiring	-	FV1	FR7		
Rear-View Display		Interior rear view			
	<u> </u>	mirror	7/10.25" Screen		

Options shown above lead to an upcharge.

Cargo Van Floor Variations

Standard	. V93	Without factory installed flooring
Options	V43	Wood floor with 6 D-rings
	VK8	Floor covering, plastic

Note: see restrictions in combination with metallic paint

Special Rule for cargo vans with metallic paint

	5890/7755/7992/9197/9775
V43	Wood floor with 6 D-rings
VK8	Floor covering, plastic
	No floor covering; requires customer
	floor installation
779	Package contains:
223	V93 - No factory installed flooring
	VL4 - Metallic painted floor
	V43

Note: Fleet only

Additional comments ZZ9 Package

While applying the required clear coat layer to the metallic painted cargo floor, imperfections could occur. Therefore, we strongly recommend to install flooring in the cargo area for vehicles with a metallic paint.

Please be aware that potential paint appearance, contamination or imperfections of the uncovered cargo floor are not considered a defect and are therefore not reimbursable for repairs.

^{*}only cameras with analog signal works

^{**}only the Mercedes-Benz rear view camera works (digital signal)

Tire & Wheel Overview

		1500/25	80 Models
		Standard Tire	RH8
		Standard Wheel	RS3
		Optional Wheel	RL5
		Brand	Options
		RMO All-season tires	RM1 M+S tires
RD9	Tire brand, unspecified	S	0
RF8	Michelin	0	n/a
RF1	Continental	n/a	0
RHO	Kumho	0	n/a

To order any of the tire brands above code RM9 has to be added to order.

			3580/3508XD Mc	odels	
		Standard: Dua	Standard: Dual Rear Wheel		er Single
		Standard Tire	RH7	Standard Tire	R9A
		Standard Wheel	RS6	Standard Wheel	RS5
		Brand O	ptions	Brand Opt	tions
		RM0 All-season tires	RM1 M+S tires	RM0 All-season tires	RM1 M+S tires
RD9	Tire brand, unspecified	0	0	S	n/a
RF8	Michelin	0	n/a	n/a	n/a
RF1	Continental	0	0	0	n/a
RHO	Kumho	n/a	n/a	n/a	n/a

Single tire

Dual Rear Wheel

Steel

Alloy

To order any of the tire brands above code RM9 has to be added to order.

Standard is DRW, Option is Super Single

		4500 M	lodels
		Standard Tire	RH7
		Standard Wheel	RS6
		Brand O	ptions
		RM0 All-season tires	RM1 M+S tires
RD9	Tire brand, unspecified	S	0
RF8	Michelin	0	n/a
RF1	Continental	0	0
RHO	Kumho	n/a	n/a

To order any of the tire brands above code RM9 has to be added to order.

2500 CREW VAN - GAS Standard Equipment

		144" G	170" G M2CV7G
		M2CV4G	
		907.643	907.645
Engine			
Gas En	gine/9-Speed Trans.	S	5
	AGM battery 12V 92 AH 850 A	\$	S
G43	Automatic transmission, 9G-tronic	S	S
	SULEV emissions	S	5
ммз :	2.0L 4-cylinder turbo gasoline engine	S	S
M60 /	Alternator 14 V / 250 A	S	5
	g and Trim Packages		
X75 :	Standard Rear Seats	S	S
_	3-seater bench rear, 1st row (narrow)	5	S
U74	Wall-side armrest	S	S
	Aisle-side armrest	S	S
	ave VF7/VF6 only; with X68 must have VF6		
X2V	Standard Trim Crew Van Package	S	S
V25	Half height load compartment trim	S	5
V35	Wheel house covering	S	S
V43	Wood floor with 6 D-rings	S	S
Equip	ment		
	Axle ratio 4.182	S	S
_	Active Brake Assist	S	S
вн1	Hold Function	S	S
271921L	Multifunction steering wheel	S	S
	Adjustable steering wheel (angle)	S	S
_	High roof	0	S
_	Omission bulkhead	S	S
-	Hill Start Assist	S	S
	Standard radio	5	5
_	USB-C socket, 5 V	S	S
_	Starter battery disconnect	S	S
_	Pre-installation for switch panel	S	S
_		S	S
	Trailer hitch prep. wiring Preinstallation PSM	S	5
_		S	S
-	Ultracapacitor discharge module	S	S
	Body Builder Connector	S	S
_	Jump start terminal	S	S
	Pre-installation for Mercedes me Remote Services	S	S
EY5	Emergency Call System	S	S
EY6	Breakdown management		
F68	Heated & electrically adjustable exterior mirrors	S	S
F43	Laminated glass rear	S	\$
FF3	Cupholder rear compartment	S	S
FF5	Shelf above windshield	S	S
FG8	Cupholder front	S	S
FI1	Remote key (315 mhz) w/central locking	S	\$
FJ4	Storage compartment underneath cockpit	S	\$
FR3	Rear view camera (rear-view mirror display)	S	\$
H00	Warm/cool air duct to rear compartment	S	S
H21	Windshield with filter band	S	S
H22	Rear window defroster	S	S
HH2	Heater, auxiliary electric hot air	S	S
нн9	Air Condition, Front	S	S
IH7	Head Unit, North America	S	5
J11	Speedometer, miles and km/h	S	S
J1W	Service Interval 1 year	S	S
J55	Seat belt warning for co-driver seat	5	S
J58	Seat belt reminder driver	S	S
165	Outside temperature gauge	S	S

2500 CREW VAN - GAS Standard Equipment

		144" G	170" G
		M2CV4G	M2CV7G 907.645
		907.643	
JA8	Crosswind Assist	S	S
	Communication module (LTE) for dig. services	S	S
	Service interval 15.000 miles	S	S
	22 gallon fuel tank	S	S
	Exhaust straight to rear	S	5
	Parking lights deletion	S	S
	Headlight assistant	S	S
_	3rd brake light	S	S
	Cruise control	S	S
	Front mudflaps	S	S
	Rear mudflaps	S	S
_	Longitudinal member reinforcement	S	S
	Spare tire bracket below frame	S	S
	Spare tire	S	5
_	Unspecified tire brand	S	S
	Tires LT 245/75 R16	S	S
	All-season tires	S	S
_	6.5 J x 16 steel wheels	S	S
	Tire pressure monitoring sensors	S	S
	Standard driver seat	S	S
	Standard front passenger seat	S	S
522	Armrest for driver's seat	S	S
525	Armrest for front passenger seat	S	S
SA5	Front airbag, driver	S	S
SA6	Front airbag, passenger	S	S
****	Thorax-pelvis sidebag, driver	S	5
SH2	Thorax-pelvis sidebag, co-driver	S	S
SH9	Airbag, driver/passenger window	S	S
SK2	Seat occupancy sensor, driver's seat	S	S
T16	Sliding door, passenger side	\$	S
T74	Assist handle, B-pillar	S	S
U22	Pre-inst. for seating configuration Crew Van	S	S
V35	Wheel house covering	S	S
V36	Roof trim	S	S
V40	Floor anchors for rear seat bench	S	S
VA7	Storage compart. w/ net in rear doors	S	S
	2nd row, fixed window, driver side	S	S
	2nd row, fixed window, passenger side	S	S
	Windows in rear doors	S	S
	Black tinting (90%) for rear windows	S	S
XL2	GVWR 9,050 lbs. / 4.100 Kg	S	S
Y43	Jack, hydraulic	S	S

2500 CREW VAN - GAS Options

		144" G 1	
		M2CV4G	M2CV7G
		907.643	907.645
450	Front axle reinforced	\$346	\$346
AP2	Addtl, bar for driveshaft & exhaust extension	\$69	\$69
325	Electric parking brake	\$279	\$279
323	no restrictions		
C72	Bumpers front/rear primed	\$268	\$268
-12	must have CN2/X67, not with CM0	V 200	
B01	ESP for increased Center of Gravity above 39.4"	\$0	\$0
DUI	must have CB4/CB8/X30; not with RH0/CB7	Ų.	
CB1	Suspension for comfort and load protection	\$241	\$241
CB1 CB7	Stabilization Level I	\$307	\$307
ÇB/	not with CB4/CB8/X30	7507	
CB8	Stabilization Level II	\$723	\$723
CDO.		9,723	V. 25
CI 2	not with CB4/CB8/ZG3	\$187	\$187
CL3	Leather steering wheel	3187	9101
21.10	must have (CO2/E3M)/CO3 + (ET4/MS1)	\$587	\$587
CIVIU	Painted metallic front & rear bumper	2307	7507
01.10	must have (CN2/X67) + (JA7/C01) + (JB6/JB7) + (7755/9197/9775)	\$364	\$364
	Primed side moldings	\$138	\$138
CT1	Rear spring vibration absorbers		\$136
D03	High roof	\$2,900	3
Li team	D03 must be added for Duesseldorf production	¢200	\$300
D13	Mounting rails for roof rack	\$300	\$156
E18	Tray for smartphones incl. wireless charging	\$156	\$120
	must have CO2/E3M + H1I	4770	\$728
E1E	Navigation	\$728	\$728
	must have CO2/E3M, not with CO3	door	Ć OFF
E1S	Sirius XM, satellite radio	\$255	\$255
	must have CO2/E3M/CO3	1	1 4=0
E1R	Additional Fuses (40/80/150/100 Ampere)	\$50	\$50
	SoP and Plausibility TBD	T	1 4=0
E1Y	Additional Fuses (40/80/80/100 Ampere)	\$50	\$50
	SoP and Plausibility TBD		
E2A	Access point for BB special signals in cockpit	\$29	\$29
E21	Additional battery, co-driver seat base	\$248	\$248
	Must have E36; not with E2M; CHS production only		
E36	Cutoff relay for additional battery	\$110	\$110
	standard with E2I/E2M		
É3M	MBUX Multimedia System with 7" touchscreen	\$474	\$474
	not with CO2/CO3; must have JK5+(JB7/JB6/JB8/FR8)		
E5M	Extension of PSM standard contact	\$58	\$58
ED5	Parametric special module (PSM)	\$317	\$317
	not with ED8		
EE3	115 V socket	\$125	\$125
ES2	12 V power outlet, rear compartment	\$92	\$92
ES5	Charging package, dashboard	\$82	\$82
ET4	Active Distance Assist DISTRONIC	\$263	\$263
	must have CO2/CO3/E3M; not with ZH4		
F49	Electrically heated windshield	\$218	\$218
	no restrictions		
F61	Interior rear view mirror	\$36	\$36
	must have E3M/C02/C03		
FE9	Additional DIN-slot	\$81	\$81
FF8	Overhead storage slot, front center	\$105	\$105
FJ1	Hinged lid for storage compartment	\$93	\$93
FR8	Rear view camera (head unit display)	\$336	\$336
	must have CO2/E3M; not with FR3/JB7/JB6/JB8		
FY1	Security alarm w. interior motion sensor	\$584	\$584

2500 CREW VAN - GAS Options

		144" G	170" G
		M2CV4G	M2CV7G
		907.643	907.645
Y7	Optional 3-button keys	\$36	\$36
$\overline{}$	Keys, two additional masters	\$121	\$121
_	Heat insulation, rear compartment	\$156	\$156
	must have V25/VA3/VA1/C07/X66		
	Heat insulation, front compartment	\$187	\$187
_	if + D50/D51 must have V07		
_	Rear cabin heater and vents	\$786	\$786
	must have V43 + (H12/HZ9); not with VK8		
	Heated front passenger seat	\$284	\$284
113	must have H16; not with X68		
116	Heated driver's seat	\$284	\$284
110	must have H15; not with X68		
188	Rear heater prep	\$405	\$405
	must have H12/HZ9; not with H13/T19		
111	Front-to-rear outlet in instrument panel	\$0	\$0
111		7.	
1114	must have FJ1/C01 Thermotronic automatic climate control	\$337	\$337
1H4	must have JF1; if +H13 must have H08/HK4	755,	755.
47		\$450	\$450
A7	Blind Spot Assist	J-130	V 130
	must have F64; not with C01	\$288	\$288
B4	Active Lane Keeping Assist	J200	7200
	standard with CO2/CA2	\$775	\$775
186	Parking Package with 360 degree camera	\$173	\$775
	must have E3M/C02/C03; not with W75/W76/JB7	\$615	\$615
IB7	Parking Package	2012	\$013
	must have E3M/C02/C03; not with W75/W76/JB6	ccor.	\$685
IB8	360 Degree Camera	\$685	2005
	SoP and Plausibility TBD	\$106	\$106
JF1	Rain sensor		\$100
JK5	Instrument cluster with color display	\$144	\$144
	not with CO3	Ć00	200
1M0	Backup alarm	\$99	\$99 \$27
JW2	Deactivation lamp monitoring failure	\$27	
IW8	Attention Assist	\$49	\$49
L13	Fog lamp with cornering light function	\$199	\$199
LB9	Illuminated front exits	\$151	\$151
LC4	Comfort overhead control panel	\$93	\$93
M20	Speed limitation 65 mph	\$60	\$60
	not with MD3		T
MD3	Top speed limitation 75 mph	\$60	\$60
	not with M20		T
Q24	Trailer hitch, 5,000 lbs	\$147	\$147
	not with W73/W75/W76		,
QA9	Half-sided step rear (for trailer hitch)	\$101	\$101
	must have Q24/QA2; not with W73/W75/W76		
R91	Spare tire deletion	-\$110	-\$110
	must have R92; not with R87		
R92	Spare tire carrier deletion	\$0	\$0
	must have R91; not with R65		
R98	Rims painted jet black	\$81	\$81
	not with RL5/RM2		
RF1	Tire brand Continental	\$0	\$0
	must have RM1 + RM9		
RF8	Tire brand Michelin	\$0	\$0
	must have RM9; not with RM1		
	The state of the s	\$0	\$0

2500 CREW VAN - GAS Options

		144" G	170" G		
		M2CV4G	M2CV7G 907.645		
		907.643			
RL5	Light allow who als C.E. Ly. 16	\$906	\$906		
KL5	Light-alloy wheels 6.5 J x 16	\$300	7500		
20.44	not with RS3/RM2/R98	\$169	\$169		
KIVI I	M+S winter tires must have RF1/RD9; not with RF8/RH0/X31	7103	7100		
DA 40		\$81	\$81		
RIVIZ	Rims painted arctic white	701	701		
0110	not with R98/RL5 Specially requested tires	\$101	\$101		
TIVIS	must have RF1/RF8/RH0; not with RD9	7101	Ų101		
528	Armrest, driver and passenger door	\$51	\$51		
T12	Sliding door two stage opening	\$82	\$82		
112	not with T55				
T50	Electric closing assist right sliding door	\$335	\$335		
130	must have D03; not with T55/T93	4000	4000		
T55	Electric sliding door right	\$831	\$831		
, ,,,	must have D03 + (FY7+T16); not with T12/T50	700-	7 "		
T57	Electric sliding step	\$1,071	\$1,071		
137	must have D03 + ED5; not with T93	V2)0.2	44/4/4		
TEO	Opening limiter electrically operated sliding door	\$120	\$120		
T60		7120	7120		
	must have 755	\$59	\$59		
T75	Door-mounted assist handles, driver & passenger				
T85	Assist handle, left rear door	\$32	\$32		
T86	Assist handles, right rear door	\$32	\$32		
V43	Wood floor with 6 D-rings	\$422	\$422		
	not with P93/V93/VL4/VK8/C07; standard with D93/H13/V24/		1 4		
V85	Cigarette lighter & ash cup, front	\$39	\$39		
VC5	Door sill - protective edge	\$71	\$71		
	must have V43/X66; not with T19/T93/VK8/VV2/V93/C07				
VK8	Floor covering, plastic	\$370	\$370		
	not with V43/P93/T19/T93/V52/VC5/X66				
W54	Rear doors, opening to side wall	\$360	\$360		
W5F	90 Degree fixation point- Rear Doors	\$80	\$80		
	SoP and Plausibility TBD				
W73	Bumper step, rear, grey	\$187	\$187		
	not with Q24/W75/W76				
W75	Step, wide, at rear end	\$308	\$308		
	not with JB6/JB7/Q24/QA9; must have R91+R92				
W76	Bumper step, rear, spring-loaded	\$601	\$601		
	must have R91+R92; not with JB6/JB7/X30/Q24				
W78		\$335	\$335		
	Must have H22+VA7 / if D51 must have F61; not with W61				
X90	Deletion of Sprinter badge, left rear door	\$0	\$0		
X93	Deletion of model badge, right rear door	\$0	\$0		
XM4		\$87	\$87		
*FIALM	standard with CO2/CO3	70.	1 ,		
Y10	First-aid kit	\$27	\$27		
	Wheel chocks	\$38	\$38		
Y26		\$27	\$27		
Y45	Emergency flashlight	\$187	\$212		
Y68	Paint preservative				
Y69	Surface protection for stock vehicles	\$315	\$315		
YK3	Cargo straps, D-rings	\$81	\$81		

2500 CREW VAN - GAS

Packages

		144" G	170" G M2CV7G
		M2CV4G	
		907.643	907.645
C00	Comfort Package	\$300	\$300
LC4	Comfort overhead control panel	Х	X
SE4	Lumbar support, co-driver's seat	X	Х
SE5	Lumbar support, driver's seat	X	Х
SK0	Comfort head restraint, driver	X	X
SK1	Comfort head restraint, co-driver	X	Х
S28	Armrest, driver and passenger door	X	X
must	have COS OR X68; CA/CC only: not with S23		

COS	Comfort Package (Seat addition)	\$381	\$381
SB1	Comfort driver's seat	X	X
SB2	Comfort passenger seat	X	Х

X68	Comfort Plus Package	\$1,923	\$1,923
H15	Heated front passenger seat	X	Х
H16	Heated driver's seat	X	Х
SF1	Driver's seat electrically adjustable	X	X
SF2	Co-driver's seat electrically adjustable	X	Х

C01	Driver Convenience Package	\$760	\$760
E46	12 V power outlet, driver seat base	X	Х
F64	Electrically folding exterior mirrors	X	X
FJ1	Hinged lid for storage compartment	X	Х
FJ5	Hinged Lid for Storage Compartments left and right	X	X
FZ9	Keys, two additional masters	X	Х
JA7	Blind Spot Assist	X	X
JW8	Attention Assist	X	X

C02	Premium Package	\$983	\$983
CL3	Leather steering wheel	X	Х
E3M	MBUX Multimedia System with 7" touchscreen	X	Х
FM3	Wet Wiper System	X	Х
JB4	Active Lane Keeping Assist	X	X
JK5	Instrument cluster with color display	X	Х
Order	ing availability restricted, see NetStar for availability and restrict	tions must have JF1 + X	M4; must
choos	e FR8/JB7/JB6		

CA2	C02 in combination with C03	\$604	\$604
CL3	Leather steering wheel	X	X
FM3	Wet Wiper System	X	X
JB4	Active Lane Keeping Assist	X	Х
JK5	Instrument cluster with color display	Х	X
	ring availability restricted, see NetStar for availability and	restrctions must have (03 + J

2500 CREW VAN - GAS Packages

144" G	170" G
M2CV4G	M2CV7G
907.643	907.645

Premium Plus Package	\$1,793	\$1,793
	X	Х
	X	Х
Intelligent navigation	X	X
MBUX Multimedia System with 10.25" touchscreen	X	X
Free map data updates for 3 years	X	X
Front-to-rear outlet in instrument panel	X	Х
Traffic Sign Assist	X	X
Acoustic package	X	X
	Tray for smartphones incl. wireless charging Navigation Intelligent navigation MBUX Multimedia System with 10.25" touchscreen Free map data updates for 3 years Front-to-rear outlet in instrument panel Traffic Sign Assist	Tray for smartphones incl. wireless charging X Navigation X Intelligent navigation X MBUX Multimedia System with 10.25" touchscreen X Free map data updates for 3 years X Front-to-rear outlet in instrument panel X Traffic Sign Assist X

\$290	\$290
X	Х
X	X
	X X

X13	Exterior Lighting Package	\$1,608	\$1,608
	Fog lamp with cornering light function	X	X
	Partial LED tail lights	X	X
\rightarrow	High beam assist	X	X
LG7	LED high performance headlamps	X	Х

X72 Crew Van Comfort Package	\$220	\$220
S31 Convenice head restraints for pass, compartment	Х	X
UY1 3-seater comfort bench rear, 1st row (narrow)	Х	Х

X4Z Interior Trim Upgrade Package	\$610	\$610
VA1 Side wall paneling waist height PVC	X	X
VA3 Side wall paneling full hardboard	X	X
ZK4 Crew Van, produced in Germany	X	Х

2500 CREW VAN - 4cyl Diesel Standard Equipment

		144" 4C	170" 4C
		M2CV44	M2CV74
		907.643	907.645
ngine		S	S
	Ingine/7-Speed Trans.	S	S
	AGM battery 12V 92 AH 850 A	S	S
	Automatic transmission, 7G-tronic	S	S
	Alternator 14 V / 200 A	S	S
-	2.0L 4-cylinder diesel engine	S	S
	SULEV emissions		
	g and Trim Packages Standard Rear Seats	S	S
_	3-seater bench rear, 1st row (narrow)	S	S
_	Wall-side armrest	S	S
	Aisle-side armrest	S	S
	ave VF7/VF6 only; with X68 must have VF6		
	Standard Trim Crew Van Package	S	5
	Half height load compartment trim	S	S
-	Wheel house covering	5	S
	Wood floor with 6 D-rings	S	S
	roduction only		
Eguipi Eguipi			
		S	S
	Axle ratio 3.923	S	S
	Active Brake Assist Hold Function	S	S
		S	S
	Multifunction steering wheel	S	S
	Adjustable steering wheel (angle)	0	S
	High roof	S	S
	Omission bulkhead	S	S
	Hill Start Assist	S	S
-	Standard radio	S	5
	USB-C socket, 5 V	S	S
_	Starter battery disconnect	S	S
_	Pre-installation for switch panel	S	S
E40	Trailer hitch prep. wiring	S	S
ED8	Preinstallation PSM	S	5
EE5	Ultracapacitor discharge module	S	S
EK1	Body Builder Connector	S S	5
	Jump start terminal	S	S
	Pre-installation for Mercedes me Remote Services		5
EY5	Emergency Call System	S	S
EY6	Breakdown management	S	S
F43	Laminated glass rear	\$	S
F68	Heated & electrically adjustable exterior mirrors	S	S
FF3	Cupholder rear compartment	S	5
FF5	Shelf above windshield	S	5
FG8	Cupholder front Remote key (315 mhz) w/central locking	S	S
FI1	Storage compartment underneath cockpit	S	S
FJ4	Rear view camera (rear-view mirror display)	S	S
FR3	Warm/cool air duct to rear compartment	S	S
H00	Windshield with filter band	S	S
H21	Rear window defroster	S	5
H22		S	S
HH2	Heater, auxiliary electric hot air	S	5
HH9	Air Condition, Front	S	5
1H7	Head Unit, North America	S	S
J11	Speedometer, miles and km/h	S	5
J55	Seat belt warning for co-driver seat	S	S
J58 J65	Seat belt reminder driver Outside temperature gauge	S	S

2500 CREW VAN - 4cyl Diesel Standard Equipment

		144" 4C M2CV44	170" 4C M2CV74
		907.643	907.645
JA8	Crosswind Assist	S	S
ЈН3	Communication module (LTE) for dig. services	S	5
119	Service interval 20.000 miles	S	S
K56	Red diesel filler cap	S	S
K60	Exhaust straight to rear	S	S
KB7	24.5 gallon fuel tank	S	S
KL1	Aux fuel sending unit w/ fuel tap	S	S
KL5	Fuel filter with water separator	S	S
KP6	3rd generation SCR emission control system	S	S
194	Parking lights deletion	S	S
LA2	Headlight assistant	S	S
LB5	3rd brake light	S	S
	Cruise control	S	S
P47	Front mudflaps	S	S
P48	Rear mudflaps	S	S
Q11	Longitudinal member reinforcement	S	S
R65	Spare tire bracket below frame	S	S
R87	Spare tire	5	S
RD9	Unspecified tire brand	S	S
RH8	Tires LT 245/75 R16	S	S
RMO	All-season tires	S	S
RS3	6.5 J x 16 steel wheels	S	S
RY2	Tire pressure monitoring sensors	S	S
502	Standard driver seat	S	S
504	Standard front passenger seat	S	S
S22	Armrest for driver's seat	S	S
525	Armrest for front passenger seat	5	S
SA5	Front airbag, driver	S	S
SA6	Front airbag, passenger	S	S
SH1	Thorax-pelvis sidebag, driver	S	S
SH2	Thorax-pelvis sidebag, co-driver	S	S
\$H9	Airbag, driver/passenger window	S	S
SK2	Seat occupancy sensor, driver's seat	S	S
T16	Sliding door, passenger side	S	S
T74	Assist handle, B-pillar	S	S
U22	Pre-inst. for seating configuration Crew Van	S	S
V36	Roof trim	5	S
V40	Floor anchors for rear seat bench	S	S
VA7	Storage compart. w/ net in rear doors	S	S
W16	2nd row, fixed window, driver side	S	S
W17	·	S	S
W61	Windows in rear doors	S	S
	Black tinting (90%) for rear windows	S	S
XL2	GVWR 9,050 lbs. / 4.100 Kg	S	S
Y43	Jack, hydraulic	S	S

		144" 4C	170" 4C
		M2CV44	M2CV74
		907.643	907.645
A50	Front axle reinforced	\$346	\$346
NP2	Addtl. bar for driveshaft & exhaust extension	\$69	\$69
AR3	Axle ratio 4.182	\$0	\$0
_	ESP for increased Center of Gravity above 39.4"	\$0	\$0
301		γο	70
	must have CB4/CB8/X30; not with RH0/CB7	\$279	\$279
325	Electric parking brake	9275	72,0
	no restrictions	\$268	\$268
72	Bumpers front/rear primed	\$200	7200
	must have CN2/X67, not with CM0	\$241	\$241
CB1	Suspension for comfort and load protection	\$307	\$307
CB7	Stabilization Level !	\$507	\$307
	not with CB1/CB7/CB8/ZG3	6722	\$723
B8	Stabilization Level II	\$723	\$725
	not with CB4/CB8/ZG3	4407	C407
CL3	Leather steering wheel	\$187	\$187
CM0	Painted metallic front & rear bumper	\$587	\$587
	must have (CN2/X67) + (JA7/C01) + (JB6/JB7) + (7755/9197/9775)		de a c
CM9	Primed side moldings	\$364	\$364
CT1	Rear spring vibration absorbers	\$138	\$138
D03	High roof	\$2,900	S
	DO3 must be added for Duesseldorf production		
D13	Mounting rails for roof rack	\$300	\$300
E1B	Tray for smartphones incl. wireless charging	\$156	\$156
	must have CO2/E3M + H1I		
E1E	Navigation	\$728	\$728
	must have CO2/E3M, not with CO3		
E1S	Sirius XM, satellite radio	\$255	\$255
	must have CO2/E3M/CO3	-	
EİR	Additional Fuses (40/80/150/100 Ampere)	\$50	\$50
	SoP and Plausibility TBD		
E1Y	Additional Fuses (40/80/80/100 Ampere)	\$50	\$50
Cal	SoP and Plausibility TBD		
E2A	Access point for BB special signals in cockpit	\$29	\$29
E2I	Additional battery, co-driver seat base	\$248	\$248
EZI	Must have E36; not with E2M; CHS production only	72.0	
F26	Cutoff relay for additional battery	\$110	\$110
E36	standard with E2I/E2M	V	
F21.4		\$474	\$474
ESIVI	MBUX Multimedia System with 7" touchscreen	7474	7111
mes r	not with CO2/CO3; must have JK5+(JB7/JB6/JB8/FR8)	\$58	\$58
E5M	Extension of PSM standard contact	\$317	\$317
ED5	Parametric special module (PSM)	3211	3211
	not with ED8	6135	\$125
EE3	115 V socket	\$125	
ES2	12 V power outlet, rear compartment	\$92	\$92
ES5	Charging package, dashboard	\$82	\$82
ET4	Active Distance Assist DISTRONIC	\$263	\$263
	must have CO2/CO3/E3M; not with ZH4	144	1 44.4
F49	Electrically heated windshield	\$218	\$218
	no restrictions		
F61	Interior rear view mirror	\$36	\$36
	must have E3M/C02/C03		-
ECA	Electrically folding exterior mirrors	\$49	\$49
F64	Additional DIN-slot	\$81	\$81
FE9		1	6405
	Overhead storage slot, front center	\$105	\$105
FE9		\$105 \$93	\$105

		144" 4C	170" 4C
		M2CV44	M2CV74 907.645
		907.643	
Y1	Security alarm w. interior motion sensor	\$584	\$584
	must have LC4/C00		
Y7	Optional 3-button keys	\$36	\$36
Z 9	Keys, two additional masters	\$121	\$121
101	Heat insulation, rear compartment	\$156	\$156
10.1	must have V25/VA3/VA1/C07/X66		
104	Heat insulation, front compartment	\$187	\$187
	if + D50/D51 must have V07		
H12	Fuel-fired pre-heater/booster (17K BTU)	\$1,116	\$1,116
144	not with HZ9		
113	Rear cabin heater and vents	\$786	\$786
113	must have V43 + (H12/HZ9); not with VK8		
H15	Heated front passenger seat	\$284	\$284
113	must have H16; not with X68	7-01	7-07
116	Heated driver's seat	\$284	\$284
H16		7204	ĢEU-T
100	must have H15; not with X68	\$405	\$405
H88	Rear heater prep	3403	3403
	must have H12/HZ9; not with H13/T19	\$0	\$0
H1I	Front-to-rear outlet in instrument panel	\$0	50
180,000	must have FJ1/C01	6227	6227
НН4	Thermotronic automatic climate control	\$337	\$337
	must have JF1; if +H13 must have H08/HK4	1000	6576
HZ9	Fuel-fired heater booster (18,000 BTU)	\$676	\$676
	not with H12	1	1 4
151	Fuel gauge, optimized for aux. fuel tap	\$72	\$72
	not with HZ9/H12		
J52	Engine oil level display at cold start	\$0	\$0
JA7	Blind Spot Assist	\$450	\$450
	must have F64; not with C01		
JB4	Active Lane Keeping Assist	\$288	\$288
	standard with CO2/CA2		
JB6	Parking Package with 360 degree camera	\$775	\$775
	must have E3M/C02/C03; not with W75/W76/JB7		
JB7	Parking Package	\$615	\$615
	must have E3M/C02/C03; not with W75/W76/JB6		
JB8	360 Degree Camera	\$685	\$685
	SoP and Plausibility TBD		
JF1	Rain sensor	\$106	\$106
_	standard with C02/X11		
JK5	Instrument cluster with color display	\$144	\$144
3110	not with CO3		
JW0	Backup alarm	\$99	\$99
JW2	Deactivation lamp monitoring failure	\$27	\$27
JW8	Attention Assist	\$49	\$49
K51	Misfueling prevention for Diesel	\$49	\$49
K52	DEF fluid filler cap - lockable	\$27	\$27
	Fog lamp with cornering light function	\$199	\$199
L13		\$151	\$151
LB9	Illuminated front exits	\$93	\$93
LC4	Comfort overhead control panel	\$60	\$60
M20		700	200
	not with MD3	400	100
MD3	Top speed limitation 75 mph	\$60	\$60
	not with M20		1 4.5-
N62	Front engine bracket for additional alternator	\$467	\$467
	not with HK4/N63	\$467	\$467
N63	Front engine bracket for auxiliary A/C compressor		

	144" 4C	170" 4C
	M2CV44	M2CV74
	907.643	907.645
724 Trailer hitch, 5,000 lbs	\$147	\$147
not with W73/W75/W76		
QA9 Half-sided step rear (for trailer hitch)	\$101	\$101
must have Q24/QA2; not with W73/W75/W76		
R91 Spare tire deletion	-\$110	-\$110
must have R92; not with R87		
R92 Spare tire carrier deletion	\$0	\$0
must have R91; not with R65		
R98 Rims painted jet black	\$81	\$81
not with RL5/RM2		
RF1 Tire brand Continental	\$0	\$0
must have RM1 + RM9		
RF8 Tire brand Michelin	\$0	\$0
must have RM9; not with RM1		
RHO Tire brand Kumho	\$0	\$0
must have RM9; not with RM1		
RL5 Light-alloy wheels 6.5 J x 16	\$906	\$906
not with RS3/RM2/R98		
RM1 M+S winter tires	\$169	\$169
must have RF1/RD9; not with RF8/RH0/X31		
RM2 Rims painted arctic white	\$81	\$81
not with R98/RL5		
RM9 Specially requested tires	\$101	\$101
must have RF1/RF8/RH0; not with RD9		
Armrest, driver and passenger door	\$51	\$51
T12 Sliding door two stage opening	\$82	\$82
not with T55		
T50 Electric closing assist right sliding door	\$335	\$335
must have D03; not with T55/T93		-
T55 Electric sliding door right	\$831	\$831
must have D03 + (FY7+T16); not with T12/T50		
T57 Electric sliding step	\$1,071	\$1,071
must have D03 + ED5; not with T93		
T60 Opening limiter electrically operated sliding door	\$120	\$120
must have T55		
T75 Door-mounted assist handles, driver & passenger	\$59	\$59
T85 Assist handle, left rear door	\$32	\$32
T86 Assist handles, right rear door	\$32	\$32
V43 Wood floor with 6 D-rings	\$422	\$422
not with P93/V93/VL4/VK8/C07; standard with D93/H13/V	/24/V52/VC5/VV2/ZE6	
V85 Cigarette lighter & ash cup, front	\$39	\$39
VC5 Door sill - protective edge	\$71	\$71
must have V43/X66; not with T19/T93/VK8/VV2/V93/C07		
VK8 Floor covering, plastic	\$370	\$370
not with V43/P93/T19/T93/V52/VC5/X66		
W54 Rear doors, opening to side wall	\$360	\$360
W5F 90 Degree fixation point-Rear Doors	\$80	\$80
SoP and Plausibility TBD	, , , ,	400
	\$187	\$187
W73 Bumper step, rear, grey	3101	310)
not with Q24/W75/W76	ćano	ones
W75 Step, wide, at rear end	\$308	\$308
not with JB6/JB7/Q24/QA9; must have R91+R92	1404	4-0-
W76 Bumper step, rear, spring-loaded	\$601	\$601
must have R91+R92; not with JB6/JB7/X30/Q24		
		C225
W78 Heated rear window(s) w/ washers/wipers	\$335	\$335
		\$555

		144" 4C	170" 4C M2CV74 907.645
		M2CV44 907.643	
X93	Deletion of model badge, right rear door	\$0	\$0
XM4	Acoustic package	\$87	\$87
	standard with C02/C03		
Y10	First-aid kit	\$27	\$27
Y26	Wheel chocks	\$38	\$38
Y45	Emergency flashlight	\$27	\$27
Y68	Paint preservative	\$187	\$212
Y69	Surface protection for stock vehicles	\$315	\$315
YK3	Cargo straps, D-rings	\$81	\$81

2500 CREW VAN - 4cyl Diesel Packages

		144" 4C	170" 4C
		M2CV44	M2CV74
		907.643	907.645
C00	Comfort Package	\$300	\$300
LC4	Comfort overhead control panel	X	Х
SE4	Lumbar support, co-driver's seat	X	Х
SE5	Lumbar support, driver's seat	X	Х
SK0	Comfort head restraint, driver	X	Х
SK1	Comfort head restraint, co-driver	X	Х
S28	Armrest, driver and passenger door	X	Х
must	have COS OR X68; CA/CC only: not with S23		

\$381	\$381
X	X
X	Х
	\$381 X X

X68	Comfort Plus Package	\$1,923	\$1,923
H15	Heated front passenger seat	X	Х
H16	Heated driver's seat	X	Х
SF1	Driver's seat electrically adjustable	X	X
SF2	Co-driver's seat electrically adjustable	X	Х

C01	Driver Convenience Package	\$760	\$760
E46	12 V power outlet, driver seat base	X	X
F64	Electrically folding exterior mirrors	X	X
FJ1	Hinged lid for storage compartment	Х	Х
	Hinged Lid for Storage Compartments left and right	X	X
FZ9	Keys, two additional masters	X	X
JA7	Blind Spot Assist	X	Х
JW8	Attention Assist	X	Х

C02	Premium Package	\$983	\$983
CL3	Leather steering wheel	X	X
E3M	MBUX Multimedia System with 7" touchscreen	X	X
FM3	Wet Wiper System	Х	Х
JB4	Active Lane Keeping Assist	X	X
JK5	Instrument cluster with color display	Х	X

CA2	CO2 in combination with CO3	\$604	\$604
CL3	Leather steering wheel	X	Х
FM3	Wet Wiper System	X	Х
JB4	Active Lane Keeping Assist	X	Х
JK5	Instrument cluster with color display	X	Х

2500 CREW VAN - 4cyl Diesel Packages

144" 4C	170" 4C
M2CV44	M2CV74
907.643	907.645

C03	Premium Plus Package	\$1,793	\$1,793
E18	Tray for smartphones incl. wireless charging	Х	X
	Navigation	X	Х
EY2	Intelligent navigation	Х	Х
E4M	MBUX Multimedia System with 10.25" touchscreen	Х	X
EX9	Free map data updates for 3 years	Х	Х
H1I	Front-to-rear outlet in instrument panel	X	Х
JA9	Traffic Sign Assist	X	X
XM4	Acoustic package	X	X
	Acoustic package have (CA2+(JB7/JB6/JB8)) OR (JB4+JK5+FM3+(JB7/JB6/JB8)); not w.	ith FR8 and	

X67	Chrome Grille Package	\$290	\$290
CN2	Radiator grille frame in vehicle color	X	Х
FK3	Chrome plated radiator grille (MB only)	X	Х

X13	Exterior Lighting Package	\$1,608	\$1,608
L13	Fog lamp with cornering light function	X	Х
	Partial LED tail lights	X	X
LA1	High beam assist	X	X
LG7	LED high performance headlamps	×	Х

X.	Х
Х	X
	X X

X4Z Interior Trim Upgrade Package	\$610	\$610
VA1 Side wall paneling waist height PVC	X	Х
VA3 Side wall paneling full hardboard	X	Х
ZK4 Crew Van, produced in Germany	X	Х

2500 CREW VAN - 6cyl Diesel Standard Equipment

			144" 6C 4x4	170" 6C	170" 6C 4x4
		M2CV46	M2CV4X	M2CV76 907.645	M2CV7X 907.645
		907.643	907.643		
ngin	a				-111
_	Engine/7-Speed Trans.	5	S	S	S
_	AGM battery 12V 92 AH 850 A	S	S	S	S
_	Automatic transmission, 7G-tronic	S	S	S	S
_	ULEV emission	S	S	5	S
	3.0L V6 turbo diesel engine	S	S	S	S
_	Alternator 14 V/220 A	S	S	S	S
_	4x4 Package		\$8,200		\$8,200
_	Door-mounted assist handles, driver & passenger		S	4	S
_	4x4 - High range transfer case w/ low gear		S		S
	ng and Trim Packages				
_	Standard Rear Seats	S	S	S	S
	3-seater bench rear, 1st row (narrow)	S	S	S	S
_		S	S	S	S
_	Wall-side armrest	S S	S	S	S
-	Aisle-side armrest ave VF7/VF6 only; with X68 must have VF6		3		
		S	S	S	5
	Standard Trim Crew Van Package	S S	S	S	S
	Half height load compartment trim	S	S	S	S
	Wheel house covering	S S	S	S	S
_	Wood floor with 6 D-rings	3	3	3	3
	production only				
_	ment				
R2	Axle ratio 3.923	S	S	S	S
A3	Active Brake Assist	S	S	S	S
_	Hold Function	S	S	S	S
6L	Multifunction steering wheel	S	S	S	S
L1	Adjustable steering wheel (angle)	S	S	5	S
03	High roof	0	0	5	\$
93	Omission bulkhead	5	S	S	S
07	Hill Start Assist	S	S	S	S
10	Standard radio	S	S	S	S
1U	USB-C socket, 5 V	S	S	S	S
30	Starter battery disconnect	S	S	S	S
3J	Pre-installation for switch panel	S		S	-
40	Trailer hitch prep, wiring	S	S	S	S
D8	Preinstallation PSM	S	S	S	\$
E5	Ultracapacitor discharge module	S	S	S	S
K1	Body Builder Connector	S	S	S	S
SO	Jump start terminal	S	S	S	S
	Pre-installation for Mercedes me Remote Services	S	S	S	S
Y5	Emergency Call System	S	S	S	S
Y6	Breakdown management	5	S	S	S
43	Laminated glass rear	S	S	S	S
68	Heated & electrically adjustable exterior mirrors	S	S	5	S
F3	Cupholder rear compartment	S	S	5	5
F5	Shelf above windshield	S	S	S	S
G8	Cupholder front	S	S	S	S
11	Remote key (315 mhz) w/central locking	S	S	S	S
J4	Storage compartment underneath cockpit	S	S	S	S
_	Rear view camera (rear-view mirror display)	S	S	S	S
R3	Warm/cool air duct to rear compartment	S	S	5	S
100		S	5	5	5
121	Windshield with filter band	S	S	S	S
122	Rear window defroster	\$	S	S	S
IH2		S S	S	S	5
1H9		S	S S	S	S
H7	Head Unit, North America	S	S	S	S

2500 CREW VAN - 6cyl Diesel Standard Equipment

		144" 6C	144" 6C 4x4 M2CV4X 907.643	170" 6C M2CV76 907.645	170" 6C 4×4 M2CV7X 907.645
		M2CV46			
		907.643			
ee I	Seek halk warning for on driver cost	S	S	S	S
_	Seat belt warning for co-driver seat	S	S	S	S
	Seat belt reminder driver	S	S	S	S
	Outside temperature gauge	S	S	S	S
8A	Crosswind Assist	S	S	S	S
_	Communication module (LTE) for dig. services	S	S	S	S
_	Service interval 20.000 miles	S	S	S	S
	Red diesel filler cap	S	S	S	S
	Exhaust straight to rear	S	S	S	S
	24.5 gallon fuel tank		S	S	S
	Aux fuel sending unit w/ fuel tap	5		S	S
	Fuel filter with water separator	S	S	5	S
	3rd generation SCR emission control system	S	S	S	S
	Parking lights deletion	S	S		S
_	Headlight assistant	S	S	S	S S
_	3rd brake light	S	S	S	
	Cruise control	S	S	S	S
	Front mudflaps	S	S	\$	5
	Rear mudflaps	S	S	S	5
	Longitudinal member reinforcement	S	S	S	S
65	Spare tire bracket below frame	S	S	S	S
87	Spare tire	S	S	S	S
D9	Unspecified tire brand	S	S	S	S
H8	Tires LT 245/75 R16	S	S	S	S
MO	All-season tires	S	S	S	S
53	6.5 J x 16 steel wheels	S	S	S	S
Y2	Tire pressure monitoring sensors	S	S	S	S
02	Standard driver seat	S	S	S	5
04	Standard front passenger seat	S	S	S	5
22	Armrest for driver's seat	S	5	5	S
25	Armrest for front passenger seat	S	S	\$	S
A5	Front airbag, driver	\$	\$	S	S
A6	Front airbag, passenger	S	S	S	S
H1	Thorax-pelvis sidebag, driver	S	S	S	S
H2	Thorax-pelvis sidebag, co-driver	S	S	S	S
H9	Airbag, driver/passenger window	S	S	S	5
	Seat occupancy sensor, driver's seat	S	S	S	S
16	Sliding door, passenger side	S	S	S	5
r74	Assist handle, B-pillar	S	S	S	S
J22	Pre-inst. for seating configuration Crew Van	S	S	S	S
/36	Roof trim	S	S	S	S
/40	Floor anchors for rear seat bench	S	S	S	S
/A7	Storage compart. w/ net in rear doors	S	S	S	S
N16		S	S	S	S
	2nd row, fixed window, driver side	S	S	S	S
W61		S	S	S	S
	Black tinting (90%) for rear windows	S	S	S	S
XL2	GVWR 9,050 lbs. / 4.100 Kg	S	S	\$	S
VFG.	Jack, hydraulic	S	S	S	S

A50 Front axle reinforced AP2 Addtl. bar for driveshaft & exhaust extension AR3 Axle ratio 4.182 B01 ESP for increased Center of Gravity above 39.4" must have CB4/CB8/X30; not with RH0/CB7 B25 Electric parking brake no restrictions C72 Bumpers front/rear primed must have CN2/X67, not with CM0 CB1 Suspension for comfort and load protection CB7 Stabilization Level II not with CB1/CB7/CB8/ZG3 CB3 Stabilization Level II not with CB4/CB8/ZG3 CL3 Leather steering wheel must have (C02/E3M)/C03 + (ET4/MS1) CM0 Painted metallic front & rear bumper must have (C02/E3M)/C01 + (IB6/IB7) + (7755/9197/97) CM9 Primed side moldings C71 Rear spring vibration absorbers D03 Must be added for Duesseldorf production D13 Mounting ralls for roof rack E1B Tray for smartphones incl. wireless charging must have C02/E3M, not with C03 E1S Sirius XM, satellite radio must have C02/E3M, not with C03 E1S Sirius XM, satellite radio must have C02/E3M/C03 E1R Additional Fuses (40/80/150/100 Ampere) SoP and Plausibility TBD E1A Additional Fuses (40/80/150/100 Ampere) SoP and Plausibility TBD E2A Access point for BB special signals in cockpit E2I Additional battery, co-driver seat base Must have E36; not with E2M; CH5 production only E36 Cutoff relay for additional battery standard with E2I/E2M E3M MBUX Multimedia System with 7" touchscreen not with C02/C03; must have JK5+(JB7/IB6/JB8/FR8) E5M Extension of P5M standard contact ED5 Parametric special module (PSM) not with E0B E51 12 V power outlet, rear compartment E55 Charging package, dashboard E74 Active Distance Assist DISTRONIC must have C02/C03/E3M, not with ZH4 E1ECTICALLY E1ECTIONS E1CTIONS	144" 6C	4" 6C 144" 6C 4x4 170" 6C		170" 6C 4x4
Addtl. bar for driveshaft & exhaust extension AR3 Axle ratio 4.182 ESP for increased Center of Gravity above 39.4" must have CB4/CB8/X30; not with RH0/CB7 BIST Electric parking brake no restrictions C72 Bumpers front/rear primed must have CN2/K67, not with CM0 CB1 Suspension for comfort and load protection CB7 Stabilization Level II not with CB1/CB7/CB8/ZG3 CB8 Stabilization Level II not with CB4/CB8/ZG3 CB8 Stabilization Level II not with CB4/CB8/ZG3 CB8 Stabilization Level II not with CB1/CB7/CB8/ZG3 CB8 Stabilization Level II not with CB1/CB7/CB8/ZG3 CB9 Primed side moldings CM0 Painted metallic front & rear bumper must have (CO2/E3M)/CO3 + (ET4/MS1) CM0 Painted metallic front & rear bumper must have (CN2/X67) + (IA7/CO1) + (IB6/IB7) + (7755/9197/97) CM9 Primed side moldings CM1 Rear spring vibration absorbers D03 High roof D03 must be added for Duesseldorf production D13 Mounting rails for roof rack E1B Tray for smartphones incl. wireless charging must have CO2/E3M + H11 E1E Navigation must have CO2/E3M, not with CO3 E1S Sirius XM, satellite radio must have CO2/E3M/CO3 E1R Additional Fuses (40/80/150/100 Ampere) SOP and Plausibility TBD E1Y Additional Fuses (40/80/150/100 Ampere) SOP and Plausibility TBD E2A Access point for BB special signals in cockpit E2I Additional battery, co-driver seat base Must have E36, not with E2M; CH5 production only E36 Cutoff relay for additional battery standard with E0/E2M E36 MBUX Multimedia System with 7" touchscreen not with CO2/CO3; must have JK5+(JB7/JB6/JB8/FR8) E55 Charging package, dashboard E74 Active Distance Assist DISTRONIC must have CO2/CO3/E3M; not with ZH4 E16 Interior rear view mirror must have E3M/CO2/CO3 E16 Interior rear view mirror must have E3M/CO2/CO3	M2CV46	M2CV4X	M2CV76	M2CV7X
Addtl. bar for driveshaft & exhaust extension ARS Axle ratio 4.182 ESP for increased Center of Gravity above 39.4" must have CB4/CB8/X30; not with RHO/CB7 BEST Electric parking brake no restrictions C72 Bumpers front/rear primed must have CN2/X67, not with CMO BBI Suspension for comfort and load protection CB7 Stabilization Level II not with CB1/CB8/ZG3 CB8 Stabilization Level II not with CB4/CB8/ZG3 CB8 Stabilization Level II not with CO2/CB3M/CO3 + (ET4/MS1) CB9 Primed side moldings CB1 CB9 Primed side moldings CB1 CB1 Strips Stability TBD CB2 Strips Strip	907.643	907.643	907.645	907.645
Axle ratio 4.182 ESP for increased Center of Gravity above 39.4" must have CB4/CB8/X30; not with RHO/CB7 Electric parking brake no restrictions Suspension for comfort and load protection Satistication Level I not with CB1/CB8/ZG3 East Stabilization Level II not with CB4/CB8/ZG3 East Stabilization Level II not viet Level East Stability TBD East Additional Fuses (40/80/150/100 Ampere) East Additional Fuses (40/80/80/100 Ampere) East Additional Fuses (40/80/80/100 Ampere) East Additi	\$346		\$346	
Axie ratio 4.182 101 ESP for increased Center of Gravity above 39.4" must have CB4/CB8/X30; not with RHO/CB7 252 Electric parking brake no restrictions 263 Bumpers front/rear primed must have CN2/X67, not with CMO 264 Stabilization Level I not with CB1/CB7/CB8/ZG3 265 Italization Level II not with CB4/CB8/ZG3 266 Italization Level II not with CB4/CB8/ZG3 267 Italization Level II not with CB4/CB8/ZG3 268 Stabilization Level II not with CB4/CB8/ZG3 269 Italization Level II not with CB4/CB8/ZG3 270 Italization Level II not with CB4/CB8/ZG3 271 Italization Level II not with CB4/CB8/ZG3 272 Italization Level II not with CB4/CB8/ZG3 273 Italization Level II not with CB4/CB8/ZG3 274 Italization Level II not with CB4/CB8/ZG3 275 Italization Level II not with CB4/CB8/ZG3 276 Italization Level II not with CB4/CB8/ZG3 277 Italization Level II not with CB4/CB8/ZG3 278 Italization Level II not with CB4/CB8/ZG3 279 Italization Level II not with CB4/CB8/ZG3 270 Italization Level II not with ave CO2/E3M/CO3 Italization Italization Level Italization Italizati	\$69	\$69	\$69	\$69
ESP for increased Center of Gravity above 39.4" must have CB4/CB8/X30; not with RHO/CB7 Electric parking brake no restrictions Bumpers front/rear primed must have CN2/K67, not with CMO El Suspension for comfort and load protection Br Stabilization Level I not with CB1/CB7/CB8/ZG3 Elsa Stabilization Level III not with CB4/CB8/ZG3 Leather steering wheel must have (CO2/E3M)/CO3 + (ET4/MS1) Emperormant of the model of the	\$0		\$0	
must have CB4/CB8/X30; not with RHO/CB7 Electric parking brake no restrictions Bumpers front/rear primed must have CN2/X67, not with CMO B1 Suspension for comfort and load protection B3 Stabilization Level I not with CB1/CB7/CB8/ZG3 B3 Stabilization Level II not with CB4/CB8/ZG3 B3 Leather steering wheel must have (CO2/E3M)/CO3 + (ET4/MS1) B40 Painted metallic front & rear bumper must have (CN2/X67) + (JA7/CO1) + (JB6/JB7) + (7755/9197/97) B40 Primed side moldings B41 Rear spring vibration absorbers B43 High roof D43 must be added for Duesseldorf production B44 Mounting ralls for roof rack B55 Tray for smartphones incl. wireless charging must have CO2/E3M, not with CO3 B51 Sirius XM, satellite radio must have CO2/E3M/CO3 B46 Additional Fuses (40/80/150/100 Ampere) B50 And Plausibility TBD B44 Access point for BB special signals in cockpit B45 Access point for BB special signals in cockpit B46 Access point for BB special signals in cockpit B47 Additional battery, co-driver seat base Must have E36; not with E2M; CH5 production only B48 Surface Access point for BB special signals in cockpit B49 Access point for BB special signals in cockpit B40 Access point for BB special signals in cockpit B41 Additional battery, co-driver seat base Must have E36; not with E2M; CH5 production only B42 Access point for BB special signals in cockpit B43 Access point for BB special signals in cockpit B44 Active Distance Assist DISTRONIC mot with ED8 B45 Lis V socket B46 Lis V power outlet, rear compartment B47 Active Distance Assist DISTRONIC must have E3M/CO2/CO3 B48 Cather CO2/CO3/E3M; not with ZH4 B49 Electrically heated windshield no restrictions B40 Interior rear view mirror must have E3M/CO2/CO3	\$0	\$0	\$0	\$0
Electric parking brake no restrictions Bumpers front/rear primed must have CN2/X67, not with CM0 B1 Suspension for comfort and load protection B3 Stabilization Level I not with CB1/CB7/CB8/ZG3 B3 Stabilization Level II not with CB4/CB8/ZG3 B3 Stabilization Level II not with CB4/CB8/ZG3 B4 Leather steering wheel must have (CO2/E3M)/CO3 + (ET4/MS1) B50 Painted metallic front & rear bumper must have (CN2/X67) + (JA7/CO1) + (JB6/JB7) + (7755/9197/97) B60 Primed side moldings B71 Rear spring vibration absorbers B71 High roof B72 DO3 must be added for Duesseldarf production B73 Mounting rails for roof rack B74 Tray for smartphones incl. wireless charging must have CO2/E3M, not with CO3 B75 Sirius XM, satellite radio must have CO2/E3M, not with CO3 B77 Additional Fuses (40/80/150/100 Ampere) B79 And Plausibility TBD B79 And Plausibility TBD B79 And Plausibility TBD B79 And Plausibility TBD B79 Additional battery, co-driver seat base Must have E36; not with E2M; CHS production only B79 Cutoff relay for additional battery standard with E2I/E2M B79 MBUX Multimedia System with 7" touchscreen not with CO2/CO3; must have JK5+(JB7/JB6/JB8/FR8) B79 Extension of PSM standard contact B79 Parametric special module (PSM) not with ED8 B79 Carging package, dashboard Active Distance Assist DISTRONIC must have E36/CO2/CO3 B70 Interior rear view mirror must have E3M/CO2/CO3 B71 Interior rear view mirror must have E3M/CO2/CO3 B72 Interior rear view mirror must have E3M/CO2/CO3				
no restrictions 272 Bumpers front/rear primed must have CN2/X67, not with CM0 183 Suspension for comfort and load protection 1867 Stabilization Level I not with CB1/CB7/CB8/ZG3 188 Stabilization Level II not with CB4/CB8/ZG3 188 Stabilization Level II not with CB4/CB8/ZG3 189 Leather steering wheel must have (C02/E3M)/C03 + (ET4/MS1) 199 Primed side moldings 190 Primed side moldings 190 Primed side moldings 190 Primed side moldings 191 Rear spring vibration absorbers 193 High roof 190 D03 must be added for Duesseldorf production 191 Mounting rails for roof rack 198 Tray for smartphones incl. wireless charging 199 must have C02/E3M, not with C03 191 Sirius XM, satellite radio 191 must have C02/E3M/C03 191 Additional Fuses (40/80/150/100 Ampere) 192 SoP and Plausibility TBD 203 Access point for BB special signals in cockpit 204 Access point for BB special signals in cockpit 205 Additional battery, co-driver seat base 192 Must have E36; not with E2M; CHS production only 205 SoP and Plausibility TBD 206 Cutoff relay for additional battery 207 standard with E2I/E2M 208 MBUX Multimedia System with 7" touchscreen 209 not with C02/C03; must have JK5+(JB7/JB6/JB8/FR8) 200 Sop Parametric special module (PSM) 201 not with ED8 202 Charging package, dashboard 203 Active Distance Assist DISTRONIC 204 must have C02/C03/E3M; not with ZH4 205 Electrically heated windshield 206 no restrictions 207 Interior rear view mirror 208 must have E3M/C02/C03	\$279	\$279	\$279	\$279
must have CN2/X67, not with CM0 B1 Suspension for comfort and load protection B3 Suspension for comfort and load protection B3 Stabilization Level II not with CB1/CB7/CB8/ZG3 B3 Stabilization Level II not with CB4/CB8/ZG3 B3 Leather steering wheel must have (C02/E3M)/C03 + (ET4/MS1) B4 Primed side moldings B5 Primed side moldings B6 Primed side moldings B7 Primed side moldings B8 Tray for smartphones incl. wireless charging must have C02/E3M, not with C03 B8 Tray for smartphones incl. wireless charging must have C02/E3M, not with C03 B9 Srius XM, satellite radio must have C02/E3M/C03 Additional Fuses (40/80/150/100 Ampere) S0P and Plausibility TBD Additional Fuses (40/80/80/100 Ampere) S0P and Plausibility TBD Additional Plausibility TBD Access point for B8 special signals in cockpit C14 Additional battery, co-driver seat base Must have E36; not with E2M; CHS production only S18 Cutoff relay for additional battery standard with E2I/E2M MBUX Multimedia System with 7" touchscreen not with C02/C03; must have JK5+(IB7/IB6/JB8/FR8) E50 Parametric special module (PSM) not with ED8 E11 V power outlet, rear compartment C12 Charging package, dashboard Active Distance Assist DISTRONIC must have C02/C03/E3M; not with ZH4 E12 Electrically heated windshield no restrictions E13 Interior rear view mirror must have E3M/C02/C03				
must have CN2/X67, not with CM0 Suspension for comfort and load protection Stabilization Level I not with CB1/CB7/CB8/ZG3 Stabilization Level II not with CB4/CB8/ZG3 Stabilization Level II not with CB4/CB8/CB3/CO1) + (IB6/IB7) + (7755/9197/97 SM9 Primed side metallic front & rear bumper must have (CN2/K67) + (IA7/CO1) + (IB6/IB7) + (7755/9197/97 SM9 Primed side moldings Tall Rear spring vibration absorbers High roof DO3 must be added for Duesseldorf production DO3 must be added for Duesseldorf production DO3 must have CO2/E3M + H11 Nounting rails for roof rack Tray for smartphones incl. wireless charging must have CO2/E3M, not with CO3 Sirius XM, satellite radio must have CO2/E3M, not with CO3 Sirius XM, satellite radio must have CO2/E3M/CO3 Additional Fuses (40/80/150/100 Ampere) SOP and Plausibility TBD SOP and Plausibility TBD Additional Fuses (40/80/80/100 Ampere) SOP and Plausibility TBD Access point for BB special signals in cockpit Additional battery, co-driver seat base Must have E36; not with E2M; CHS production only Standard with E2I/E2M SMM MBUX Multimedia System with 7" touchscreen not with CO2/CO3; must have JK5+(JB7/JB6/JB8/FR8) EXTENSION OF PSM standard contact DS Parametric special module (PSM) not with ED8 E13 115 V socket 12 V power outlet, rear compartment Charging package, dashboard Active Distance Assist DISTRONIC must have CO2/CO3/CS3/S3M; not with ZH4 E14 E14 ctrically heated windshield no restrictions E14 Active Distance Assist DISTRONIC must have E3M/CO2/CO3 must have E3M/CO2/CO3	\$268	\$268	\$268	\$268
Suspension for comfort and load protection Stabilization Level I not with CB1/CB7/CB8/ZG3 Stabilization Level II not with CB4/CB8/ZG3 Stabilization Level II not with CB4/CB8/CB3 Stabilization Level II not with CB4/CB8/CB3/CB1/CB1/CB1/CB1/CB1/CB1/CB1/CB1/CB1/CB1				
Stabilization Level I not with CB1/CB7/CB8/ZG3 Stabilization Level II not with CB4/CB8/ZG3 Leather steering wheel must have (CO2/E3M)/CO3 + (ET4/MS1) MO Painted metallic front & rear bumper must have (CN2/K67) + (IA7/CO1) + (IB6/IB7) + (7755/9197/97 MO Printed side moldings The Rear spring vibration absorbers Mounting rails for roof rack Tray for smartphones incl. wireless charging must have CO2/E3M + H11 Moving Mounting Fails for roof rack Sirius XM, satellite radio must have CO2/E3M, not with CO3 Sirius XM, satellite radio must have CO2/E3M/CO3 Additional Fuses (40/80/150/100 Ampere) SoP and Plausibility TBD Additional Fuses (40/80/80/100 Ampere) SoP and Plausibility TBD Additional battery, co-driver seat base Must have E36; not with E2M; CHS production only Must have E36; not with E2M; CHS production only Standard with E2I/E2M MMS Multimedia System with 7" touchscreen not with CO2/CO3; must have JK5+(IB7/IB6/JB8/FR8) Extension of PSM standard contact DS Parametric special module (PSM) not with ED8 LEVEL STANDARD STANDAR	\$241		\$241	-
not with CB1/CB7/CB8/ZG3 SB8 Stabilization Level II not with CB4/CB8/ZG3 Leather steering wheel must have (CO2/E3M)/CO3 + (ET4/MS1) MO Painted metallic front & rear bumper must have (CN2/X67) + (JA7/CO1) + (JB6/JB7) + (7755/9197/97 MO Primed side moldings TI Rear spring vibration absorbers Mounting rails for roof rack High roof DO3 must be odded for Duesseldorf production Mounting rails for roof rack High Tray for smartphones incl. wireless charging must have CO2/E3M + H11 Navigation must have CO2/E3M, not with CO3 Sirius XM, satellite radio must have CO2/E3M/CO3 Additional Fuses (40/80/150/100 Ampere) SoP and Plausibility TBD Additional Fuses (40/80/80/100 Ampere) SoP and Plausibility TBD Access point for BB special signals in cockpit Additional battery, co-driver seat base Must have E36; not with E2M; CHS production only Ctoff relay for additional battery standard with E2I/E2M MMUX Multimedia System with 7" touchscreen not with CO2/CO3; must have JK5+(JB7/JB6/JB8/FR8) EXENDED SIN Sextension of PSM standard contact DS Parametric special module (PSM) not with ED8 115 V socket 12 V power outlet, rear compartment Charging package, dashboard Active Distance Assist DISTRONIC must have CO2/CO3/E3M; not with ZH4 Electrically heated windshield no restrictions Interior rear view mirror must have E3M/CO2/CO3	\$307	-	\$307	
Stabilization Level II not with CB4/CB8/ZG3 Leather steering wheel must have (CO2/E3M)/CO3 + (ET4/MS1) MO Painted metallic front & rear bumper must have (CN2/X67) + (JA7/CO1) + (JB6/JB7) + (7755/9197/97 MP Primed side moldings The Rear spring vibration absorbers Mounting rails for roof rack Tray for smartphones incl. wireless charging must have CO2/E3M + H11 The Navigation must have CO2/E3M, not with CO3 Sirius XM, satellite radio must have CO2/E3M/CO3 Additional Fuses (40/80/150/100 Ampere) SoP and Plausibility TBD Additional Fuses (40/80/80/100 Ampere) SoP and Plausibility TBD Additional Fuses (40/80/80/100 Ampere) SoP and Plausibility TBD CAA Access point for BB special signals in cockpit Additional battery, co-driver seat base Must have E36; not with E2M; CHS production only Sob MBUX Multimedia System with 7" touchscreen not with CO2/CO3; must have JK5+(JB7/JB6/JB8/FR8) EXAM BUX Multimedia System with 7" touchscreen not with ED8 115 V socket 12 V power outlet, rear compartment Charging package, dashboard Active Distance Assist DISTRONIC must have CO2/CO3/E3M; not with ZH4 Electrically heated windshield no restrictions Interior rear view mirror must have E3M/CO2/CO3 Interior rear view mirror must have E3M/CO2/CO3		-		
not with CB4/CB8/ZG3 Leather steering wheel must have (CO2/E3M)/CO3 + (ET4/MS1) MO Painted metallic front & rear bumper must have (CN2/X67) + (JA7/CO1) + (JB6/JB7) + (7755/9197/97) MO Primed side moldings T1 Rear spring vibration absorbers Mounting rails for roof rack Tray for smartphones incl. wireless charging must have CO2/E3M + H11 Navigation must have CO2/E3M, not with CO3 Sirius XM, satellite radio must have CO2/E3M/CO3 Additional Fuses (40/80/150/100 Ampere) SoP and Plausibility TBD Additional Fuses (40/80/80/100 Ampere) SoP and Plausibility TBD Additional battery, co-driver seat base Must have E36; not with E2M; CHS production only Standard with E2I/E2M MBUX Multimedia System with 7" touchscreen not with CO2/CO3; must have JK5+(JB7/JB6/JB8/FR8) E5M Extension of PSM standard contact EDS Parametric special module (PSM) not with ED8 115 V socket 126 Charging package, dashboard E44 Active Distance Assist DISTRONIC must have CO2/CO3/E3M; not with ZH4 E49 Electrically heated windshield no restrictions E61 Interior rear view mirror must have E3M/CO2/CO3	\$723		\$723	
Leather steering wheel must have (CO2/E3M)/CO3 + (ET4/MS1) MO Painted metallic front & rear bumper must have (CN2/X67) + (JA7/CO1) + (JB6/JB7) + (7755/9197/97 MO Primed side moldings T1 Rear spring vibration absorbers Mounting rails for roof rack Mounting rails for roof rack Tray for smartphones incl. wireless charging must have CO2/E3M + H11 Navigation must have CO2/E3M, not with CO3 Sirus XM, satellite radio must have CO2/E3M/CO3 Additional Fuses (40/80/150/100 Ampere) SoP and Plausibility TBD Additional Fuses (40/80/80/100 Ampere) SoP and Plausibility TBD Access point for BB special signals in cockpit Additional battery, co-driver seat base Must have E36; not with E2M; CHS production only standard with E2I/E2M MBUX Multimedia System with 7" touchscreen not with CO2/CO3; must have JK5+(JB7/JB6/JB8/FR8) Extension of PSM standard contact Parametric special module (PSM) not with ED8 115 V socket 12 V power outlet, rear compartment Charging package, dashboard Active Distance Assist DISTRONIC must have CO2/CO3/E3M; not with ZH4 Electrically heated windshield no restrictions 111 Interior rear view mirror must have E3M/CO2/CO3	7,75			
must have (CO2/E3M)/CO3 + (ET4/MS1) MO Painted metallic front & rear bumper must have (CN2/X67) + (JA7/CO1) + (JB6/JB7) + (7755/9197/97 MO Primed side moldings The Rear spring vibration absorbers Mounting rails for roof rack Mounting rails for roof rack Tray for smartphones incl. wireless charging must have CO2/E3M + H11 ELE Navigation must have CO2/E3M, not with CO3 Sirius XM, satellite radio must have CO2/E3M/CO3 Additional Fuses (40/80/150/100 Ampere) SoP and Plausibility TBD Additional Fuses (40/80/80/100 Ampere) SoP and Plausibility TBD Additional Fuses (40/80/80/100 Ampere) Additional battery, co-driver seat base Must have E36; not with E2M; CHS production only Cutoff relay for additional battery standard with E2/E2M MBUX Multimedia System with 7" touchscreen not with CO2/CO3; must have JK5+(JB7/JB6/JB8/FR8) EXENDED SO COMPANY (COS) EXENDED SO COMPANY (COS) MBUX Multimedia System with 7" touchscreen not with CO2/CO3; must have JK5+(JB7/JB6/JB8/FR8) EXENDED SO COMPANY (COS) EXENDED SO COS COS COS COS COS COS COS COS COS	\$187	\$187	\$187	\$187
must have (CN2/X67) + (JA7/C01) + (JB6/JB7) + (7755/9197/97 M9 Primed side moldings Rear spring vibration absorbers High roof D03 must be added for Duesseldorf production Mounting rails for roof rack B Tray for smartphones incl. wireless charging must have CO2/E3M + H11 B Navigation must have CO2/E3M, not with CO3 B Sirius XM, satellite radio must have CO2/E3M/CO3 Additional Fuses (40/80/150/100 Ampere) SoP and Plausibility TBD Additional Fuses (40/80/80/100 Ampere) SoP and Plausibility TBD Additional Battery, co-driver seat base Must have E36; not with E2M; CHS production only Cutoff relay for additional battery standard with E2I/E2M MBUX Multimedia System with 7" touchscreen not with CO2/CO3; must have JK5+(JB7/JB6/JB8/FR8) EXES 115 V socket D Parametric special module (PSM) not with ED8 B 115 V socket CHA Active Distance Assist DISTRONIC must have CO2/CO3/E3M; not with ZH4 Electrically heated windshield no restrictions Interior rear view mirror must have E3M/CO2/CO3	7			
must have (CN2/X67) + (JA7/CO1) + (JB6/JB7) + (7755/9197/97 CM9 Primed side moldings CM1 Rear spring vibration absorbers CM3 High roof CM3 Mounting rails for roof rack CM4 Mounting rails for roof rack CM4 Mounting rails for roof rack CM5 Mounting rails for roof rack CM5 Mounting rails for roof rack CM6 Mounting rails for roof rack CM7 Additional Fuses (40/80/80/100 Ampere) CM8 Additional Fuses (40/80/80/100 Ampere) CM7 Additional Fuses (40/80/80/100 Ampere) CM8 Additional Fuses (40/80/80/100 Ampere) CM8 Additional Battery, co-driver seat base CM8 Must have E36; not with E2M; CHS production only CM7 Additional Battery, co-driver seat base CM8 Mounting rails for roof rack CM8 Mounting rails CM8 Mounting	\$587	\$587	\$587	\$587
2M9 Primed side moldings 2T1 Rear spring vibration absorbers 2D3 High roof 2D3 must be added for Duesseldorf production 2D3 Mounting rails for roof rack 2D5 Mounting rails for roof rack 2D6 Tray for smartphones incl. wireless charging 2D7 must have CO2/E3M + H11 2D8 Mavigation 2D9 must have CO2/E3M, not with CO3 2D9 Sirius XM, satellite radio 2D9 must have CO2/E3M/CO3 2D9 Moditional Fuses (40/80/150/100 Ampere) 2D9 Additional Fuses (40/80/80/100 Ampere) 2D9 Additional Fuses (40/80/80/100 Ampere) 2D9 Additional Fuses (40/80/80/100 Ampere) 2D9 Access point for BB special signals in cockpit 2D1 Additional battery, co-driver seat base 2D9 Must have E36; not with E2M; CHS production only 2D9 Cutoff relay for additional battery 2D9 standard with E21/E2M 2D9 MBUX Multimedia System with 7" touchscreen 2D9 Parametric special module (PSM) 2D9 not with ED8 2D9 Parametric special module (PSM) 2D9 not with ED8 2D1 V power outlet, rear compartment 2D9 Charging package, dashboard 2D1 Active Distance Assist DISTRONIC 2D9 must have CO2/CO3/E3M; not with ZH4 2D9 Electrically heated windshield 2D9 no restrictions 2D1 Interior rear view mirror 2D1 must have E3M/CO2/CO3			1	
High roof DO3 must be added for Duesseldorf production Mounting rails for roof rack Tray for smartphones incl. wireless charging must have CO2/E3M + H11 E1E Navigation must have CO2/E3M, not with CO3 E1S Sirius XM, satellite radio must have CO2/E3M/CO3 E1R Additional Fuses (40/80/150/100 Ampere) SoP and Plausibility TBD E1Y Additional Fuses (40/80/80/100 Ampere) SoP and Plausibility TBD E2A Access point for BB special signals in cockpit Additional battery, co-driver seat base Must have E36; not with E2M; CHS production only Cutoff relay for additional battery standard with E2I/E2M MBUX Multimedia System with 7" touchscreen not with CO2/CO3; must have JK5+(JB7/JB6/JB8/FR8) EXENSION OF PSM standard contact D5 Parametric special module (PSM) not with ED8 E1S V socket E12 V power outlet, rear compartment Charging package, dashboard Active Distance Assist DISTRONIC must have CO2/CO3/E3M; not with ZH4 E1G Interior rear view mirror must have E3M/CO2/CO3 must have E3M/CO2/CO3 E1G Interior rear view mirror must have E3M/CO2/CO3	\$364	\$364	\$364	\$364
High roof D03 must be added for Duesseldorf production Mounting rails for roof rack Tray for smartphones incl. wireless charging must have C02/E3M + H11 Navigation must have C02/E3M, not with C03 Sirius XM, satellite radio must have C02/E3M/C03 Additional Fuses (40/80/150/100 Ampere) SoP and Plausibility TBD Additional Fuses (40/80/80/100 Ampere) SoP and Plausibility TBD Access point for BB special signals in cockpit Additional battery, co-driver seat base Must have E36; not with E2M; CHS production only Cutoff relay for additional battery standard with E21/E2M MBUX Multimedia System with 7" touchscreen not with C02/C03; must have JK5+(JB7/JB6/JB8/FR8) Extension of PSM standard contact D5 Parametric special module (PSM) not with ED8 115 V socket 12 V power outlet, rear compartment Charging package, dashboard Active Distance Assist DISTRONIC must have C02/C03/E3M; not with ZH4 Electrically heated windshield no restrictions Interior rear view mirror must have E3M/C02/C03	\$138	\$138	\$138	\$138
D03 must be added for Duesseldorf production Mounting rails for roof rack Tray for smartphones incl. wireless charging must have C02/E3M + H11 Navigation must have C02/E3M, not with C03 Sirius XM, satellite radio must have C02/E3M/C03 Additional Fuses (40/80/150/100 Ampere) SoP and Plausibility TBD SoP and Plausibility TBD Additional Fuses (40/80/80/100 Ampere) SoP and Plausibility TBD Access point for BB special signals in cockpit Additional battery, co-driver seat base Must have E36; not with E2M; CHS production only Cutoff relay for additional battery standard with E2I/E2M MBUX Multimedia System with 7" touchscreen not with C02/C03; must have JK5+(JB7/JB6/JB8/FR8) EXTENSION OF PSM standard contact D5 Parametric special module (PSM) not with ED8 ESS 115 V socket 12 V power outlet, rear compartment Charging package, dashboard Active Distance Assist DISTRONIC must have C02/C03/E3M; not with ZH4 Electrically heated windshield no restrictions Interior rear view mirror must have E3M/C02/C03	\$2,900	\$2,900	S	S
Mounting rails for roof rack Tray for smartphones incl. wireless charging must have CO2/E3M + H11 The Navigation must have CO2/E3M, not with CO3 The Sirius XM, satellite radio must have CO2/E3M/CO3 The Additional Fuses (40/80/150/100 Ampere) SoP and Plausibility TBD Additional Fuses (40/80/80/100 Ampere) SoP and Plausibility TBD Access point for BB special signals in cockpit Additional battery, co-driver seat base Must have E36; not with E2M; CHS production only Cutoff relay for additional battery standard with E2I/E2M MBUX Multimedia System with 7" touchscreen not with CO2/CO3; must have JK5+(JB7/JB6/JB8/FR8) EXTENSION OF PSM standard contact DS Parametric special module (PSM) not with ED8 115 V socket 12 V power outlet, rear compartment Charging package, dashboard Active Distance Assist DISTRONIC must have CO2/CO3/E3M; not with ZH4 Electrically heated windshield no restrictions Interior rear view mirror must have E3M/CO2/CO3 Bust have E3M/CO2/CO3 Interior rear view mirror must have E3M/CO2/CO3	<i>\$2,000</i>	V =,000		
must have CO2/E3M + H11 Navigation must have CO2/E3M, not with CO3 Sirius XM, satellite radio must have CO2/E3M/CO3 Additional Fuses (40/80/150/100 Ampere) SoP and Plausibility TBD Additional Fuses (40/80/80/100 Ampere) SoP and Plausibility TBD Additional Fuses (40/80/80/100 Ampere) SoP and Plausibility TBD Access point for BB special signals in cockpit Additional battery, co-driver seat base Must have E36; not with E2M; CHS production only Cutoff relay for additional battery standard with E2I/E2M MBUX Multimedia System with 7" touchscreen not with CO2/CO3; must have JK5+(JB7/JB6/JB8/FR8) Extension of PSM standard contact Parametric special module (PSM) not with ED8 E3 115 V socket 12 V power outlet, rear compartment Charging package, dashboard Active Distance Assist DISTRONIC must have CO2/CO3/E3M; not with ZH4 Electrically heated windshield no restrictions Interior rear view mirror must have E3M/CO2/CO3	\$300	\$300	\$300	\$300
must have CO2/E3M + H11 1E Navigation must have CO2/E3M, not with CO3 1S Sirius XM, satellite radio must have CO2/E3M/CO3 1R Additional Fuses (40/80/150/100 Ampere) SoP and Plausibility TBD 1Y Additional Fuses (40/80/80/100 Ampere) SoP and Plausibility TBD 2A Access point for BB special signals in cockpit Additional battery, co-driver seat base Must have E36; not with E2M; CHS production only Cutoff relay for additional battery standard with E2I/E2M MBUX Multimedia System with 7" touchscreen not with CO2/CO3; must have JK5+(JB7/JB6/JB8/FR8) EXTENSION of PSM standard contact DS Parametric special module (PSM) not with ED8 115 V socket 12 V power outlet, rear compartment Charging package, dashboard Active Distance Assist DISTRONIC must have CO2/CO3/E3M; not with ZH4 Electrically heated windshield no restrictions Interior rear view mirror must have E3M/CO2/CO3	\$156	\$156	\$156	\$156
must have CO2/E3M, not with CO3 Sirius XM, satellite radio must have CO2/E3M/CO3 Additional Fuses (40/80/150/100 Ampere) SoP and Plausibility TBD Additional Fuses (40/80/80/100 Ampere) SoP and Plausibility TBD Access point for BB special signals in cockpit Additional battery, co-driver seat base Must have E36; not with E2M; CHS production only Cutoff relay for additional battery standard with E2I/E2M MBUX Multimedia System with 7" touchscreen not with CO2/CO3; must have JK5+(JB7/JB6/JB8/FR8) EXTENSION of PSM standard contact Parametric special module (PSM) not with ED8 115 V socket 12 V power outlet, rear compartment Charging package, dashboard Active Distance Assist DISTRONIC must have CO2/CO3/E3M; not with ZH4 Electrically heated windshield no restrictions Interior rear view mirror must have E3M/CO2/CO3	7200	7200	7555	, , , , ,
must have CO2/E3M, not with CO3 Sirius XM, satellite radio must have CO2/E3M/CO3 Additional Fuses (40/80/150/100 Ampere) SoP and Plausibility TBD Additional Fuses (40/80/80/100 Ampere) SoP and Plausibility TBD Access point for BB special signals in cockpit Additional battery, co-driver seat base Must have E36; not with E2M; CHS production only Cutoff relay for additional battery standard with E2I/E2M MBUX Multimedia System with 7" touchscreen not with CO2/CO3; must have JK5+(JB7/JB6/JB8/FR8) Extension of PSM standard contact Parametric special module (PSM) not with ED8 115 V socket 12 V power outlet, rear compartment Charging package, dashboard Active Distance Assist DISTRONIC must have CO2/CO3/E3M; not with ZH4 Electrically heated windshield no restrictions Interior rear view mirror must have E3M/CO2/CO3	\$728	\$728	\$728	\$728
Sirius XM, satellite radio must have CO2/E3M/CO3 Additional Fuses (40/80/150/100 Ampere) SoP and Plausibility TBD Additional Fuses (40/80/80/100 Ampere) SoP and Plausibility TBD Access point for BB special signals in cockpit Additional battery, co-driver seat base Must have E36; not with E2M; CHS production only Cutoff relay for additional battery standard with E2I/E2M MBUX Multimedia System with 7" touchscreen not with CO2/CO3; must have JK5+(JB7/JB6/JB8/FR8) Extension of PSM standard contact Parametric special module (PSM) not with ED8 115 V socket 12 V power outlet, rear compartment Charging package, dashboard Active Distance Assist DISTRONIC must have CO2/CO3/E3M; not with ZH4 Electrically heated windshield no restrictions Interior rear view mirror must have E3M/CO2/CO3	7720	7/20	V, 20	V. 20
must have CO2/E3M/CO3 Additional Fuses (40/80/150/100 Ampere) SoP and Plausibility TBD Additional Fuses (40/80/80/100 Ampere) SoP and Plausibility TBD Access point for BB special signals in cockpit Additional battery, co-driver seat base Must have E36; not with E2M; CHS production only Cutoff relay for additional battery standard with E2I/E2M MBUX Multimedia System with 7" touchscreen not with CO2/CO3; must have JK5+(JB7/JB6/JB8/FR8) EXTENSION of PSM standard contact Parametric special module (PSM) not with ED8 115 V socket 12 V power outlet, rear compartment Charging package, dashboard Active Distance Assist DISTRONIC must have CO2/CO3/E3M; not with ZH4 Electrically heated windshield no restrictions Interior rear view mirror must have E3M/CO2/CO3	\$255	\$255	\$255	\$255
Additional Fuses (40/80/150/100 Ampere) SoP and Plausibility TBD Additional Fuses (40/80/80/100 Ampere) SoP and Plausibility TBD Access point for BB special signals in cockpit Additional battery, co-driver seat base Must have E36; not with E2M; CHS production only Cutoff relay for additional battery standard with E2I/E2M MBUX Multimedia System with 7" touchscreen not with C02/C03; must have JK5+(JB7/JB6/JB8/FR8) Extension of PSM standard contact Parametric special module (PSM) not with ED8 115 V socket 12 V power outlet, rear compartment Charging package, dashboard Active Distance Assist DISTRONIC must have C02/C03/E3M; not with ZH4 Electrically heated windshield no restrictions Interior rear view mirror must have E3M/C02/C03	7233	7255	7230	7.23
SoP and Plausibility TBD 1Y Additional Fuses (40/80/80/100 Ampere) SoP and Plausibility TBD 2A Access point for BB special signals in cockpit Additional battery, co-driver seat base Must have E36; not with E2M; CHS production only Cutoff relay for additional battery standard with E2I/E2M MBUX Multimedia System with 7" touchscreen not with C02/C03; must have JK5+(JB7/JB6/JB8/FR8) EXTENSION of PSM standard contact Parametric special module (PSM) not with ED8 115 V socket 12 V power outlet, rear compartment Charging package, dashboard Active Distance Assist DISTRONIC must have C02/C03/E3M; not with ZH4 Electrically heated windshield no restrictions Interior rear view mirror must have E3M/C02/C03	\$50	\$50	\$50	\$50
SoP and Plausibility TBD 2A Access point for BB special signals in cockpit Additional battery, co-driver seat base Must have E36; not with E2M; CHS production only Cutoff relay for additional battery standard with E2I/E2M MBUX Multimedia System with 7" touchscreen not with C02/C03; must have JK5+(JB7/JB6/JB8/FR8) EXTENSION of PSM standard contact Parametric special module (PSM) not with ED8 115 V socket 12 V power outlet, rear compartment Charging package, dashboard Active Distance Assist DISTRONIC must have C02/C03/E3M; not with ZH4 Electrically heated windshield no restrictions Interior rear view mirror must have E3M/C02/C03	730	450	400	
SoP and Plausibility TBD E2A Access point for BB special signals in cockpit Additional battery, co-driver seat base Must have E36; not with E2M; CHS production only E36 Cutoff relay for additional battery standard with E2I/E2M E3M MBUX Multimedia System with 7" touchscreen not with C02/C03; must have JK5+(JB7/JB6/JB8/FR8) E5M Extension of PSM standard contact ED5 Parametric special module (PSM) not with ED8 E15 V socket E12 V power outlet, rear compartment Charging package, dashboard Active Distance Assist DISTRONIC must have C02/C03/E3M; not with ZH4 Electrically heated windshield no restrictions E61 Interior rear view mirror must have E3M/C02/C03	\$50	\$50	\$50	\$50
Access point for BB special signals in cockpit Additional battery, co-driver seat base Must have E36; not with E2M; CHS production only Cutoff relay for additional battery standard with E2I/E2M BM MBUX Multimedia System with 7" touchscreen not with C02/C03; must have JK5+(JB7/JB6/JB8/FR8) Extension of PSM standard contact Parametric special module (PSM) not with ED8 115 V socket 12 V power outlet, rear compartment Charging package, dashboard Active Distance Assist DISTRONIC must have C02/C03/E3M; not with ZH4 Electrically heated windshield no restrictions Interior rear view mirror must have E3M/C02/C03	750	250	950	934
Additional battery, co-driver seat base Must have E36; not with E2M; CHS production only Cutoff relay for additional battery standard with E2I/E2M MBUX Multimedia System with 7" touchscreen not with C02/C03; must have JK5+(JB7/JB6/JB8/FR8) Extension of PSM standard contact Parametric special module (PSM) not with ED8 115 V socket 12 V power outlet, rear compartment Charging package, dashboard Active Distance Assist DISTRONIC must have C02/C03/E3M; not with ZH4 Electrically heated windshield no restrictions Interior rear view mirror must have E3M/C02/C03	\$29	\$29	\$29	\$29
Must have E36; not with E2M; CHS production only Cutoff relay for additional battery standard with E2I/E2M MBUX Multimedia System with 7" touchscreen not with C02/C03; must have JK5+(JB7/JB6/JB8/FR8) Extension of PSM standard contact Parametric special module (PSM) not with ED8 115 V socket 12 V power outlet, rear compartment Charging package, dashboard Active Distance Assist DISTRONIC must have C02/C03/E3M; not with ZH4 Electrically heated windshield no restrictions Interior rear view mirror must have E3M/C02/C03	\$248	\$248	\$248	\$248
Cutoff relay for additional battery standard with E2I/E2M MBUX Multimedia System with 7" touchscreen not with C02/C03; must have JK5+(JB7/JB6/JB8/FR8) EXEMSION OF PSM standard contact EDS Parametric special module (PSM) not with ED8 115 V socket 12 V power outlet, rear compartment Charging package, dashboard Active Distance Assist DISTRONIC must have C02/C03/E3M; not with ZH4 Electrically heated windshield no restrictions Interior rear view mirror must have E3M/C02/C03	Ş240	7240	\$2.10	72.0
standard with E2I/E2M 3M MBUX Multimedia System with 7" touchscreen not with C02/C03; must have JK5+(JB7/JB6/JB8/FR8) EXEMSION OF PSM standard contact EDS Parametric special module (PSM) not with ED8 115 V socket 12 V power outlet, rear compartment Charging package, dashboard Active Distance Assist DISTRONIC must have C02/C03/E3M; not with ZH4 Electrically heated windshield no restrictions F61 Interior rear view mirror must have E3M/C02/C03	\$110	\$110	\$110	\$110
MBUX Multimedia System with 7" touchscreen not with CO2/CO3; must have JK5+(JB7/JB6/JB8/FR8) Extension of PSM standard contact EDS Parametric special module (PSM) not with ED8 115 V socket 12 V power outlet, rear compartment Charging package, dashboard Active Distance Assist DISTRONIC must have CO2/CO3/E3M; not with ZH4 Electrically heated windshield no restrictions F61 Interior rear view mirror must have E3M/CO2/CO3	3110	\$110	7110	7110
not with CO2/CO3; must have JK5+(JB7/JB6/JB8/FR8) ESM Extension of PSM standard contact EDS Parametric special module (PSM) not with ED8 E13 115 V socket E52 12 V power outlet, rear compartment Charging package, dashboard ET4 Active Distance Assist DISTRONIC must have CO2/CO3/E3M; not with ZH4 Electrically heated windshield no restrictions E61 Interior rear view mirror must have E3M/CO2/CO3	\$474	\$474	\$474	\$474
EXTENSION OF PSM standard contact EDS Parametric special module (PSM) not with ED8 115 V socket ES2 12 V power outlet, rear compartment Charging package, dashboard ET4 Active Distance Assist DISTRONIC must have CO2/CO3/E3M; not with ZH4 Electrically heated windshield no restrictions F61 Interior rear view mirror must have E3M/CO2/CO3	Ş474	\$414	V	¥
Parametric special module (PSM) not with ED8 115 V socket 12 V power outlet, rear compartment Charging package, dashboard Active Distance Assist DISTRONIC must have CO2/CO3/E3M; not with ZH4 Electrically heated windshield no restrictions Interior rear view mirror must have E3M/CO2/CO3	\$58	\$58	\$58	\$58
not with ED8 ES3 115 V socket ES2 12 V power outlet, rear compartment Charging package, dashboard ET4 Active Distance Assist DISTRONIC must have CO2/CO3/E3M; not with ZH4 Electrically heated windshield no restrictions F61 Interior rear view mirror must have E3M/CO2/CO3	\$317	\$317	\$317	\$317
115 V socket 12 V power outlet, rear compartment Charging package, dashboard Active Distance Assist DISTRONIC must have CO2/CO3/E3M; not with ZH4 Electrically heated windshield no restrictions Interior rear view mirror must have E3M/CO2/CO3	2317	7517	4517	401.
12 V power outlet, rear compartment Charging package, dashboard Active Distance Assist DISTRONIC must have CO2/CO3/E3M; not with ZH4 Electrically heated windshield no restrictions Interior rear view mirror must have E3M/CO2/CO3	\$125	\$125	\$125	\$125
Charging package, dashboard Active Distance Assist DISTRONIC must have CO2/CO3/E3M; not with ZH4 Electrically heated windshield no restrictions Interior rear view mirror must have E3M/CO2/CO3	\$92	\$92	\$92	\$92
Active Distance Assist DISTRONIC must have C02/C03/E3M; not with ZH4 Electrically heated windshield no restrictions Interior rear view mirror must have E3M/C02/C03	\$82	\$82	\$82	\$82
must have CO2/CO3/E3M; not with ZH4 Electrically heated windshield no restrictions Interior rear view mirror must have E3M/CO2/CO3	\$263	\$263	\$263	\$263
749 Electrically heated windshield 750 no restrictions 751 Interior rear view mirror 752 must have E3M/C02/C03	7203	7203	7203	1 4205
no restrictions F61 Interior rear view mirror must have E3M/C02/C03	\$218	\$218	\$218	\$218
Interior rear view mirror must have E3M/C02/C03	2210	2210	ASTO	7210
must have E3M/C02/C03	¢26	\$25	\$36	\$36
	\$36	\$36	230	0.00
	Ć40	\$40	¢40	\$49
-64 Electrically folding exterior mirrors	\$49	\$49	\$49	543
no restrictions	And	604	Ċ01	Č01
FE9 Additional DIN-slot	\$81	\$81	\$81	\$81
FFB Overhead storage slot, front center FJ1 Hinged lid for storage compartment	\$105 \$93	\$105 \$93	\$105 \$93	\$105

		144" 6C		170" 6C M2CV76 907.645	170" 6C 4x4 M2CV7X 907.645
		M2CV46			
		907.643	907.643		
R8	Rear view camera (head unit display)	\$336	\$336	\$336	\$336
10	must have CO2/E3M; not with FR3/JB7; 3500XD not with JB8			· · · · · · · · · · · · · · · · · · ·	
Y1	Security alarm w. Interior motion sensor	\$584	\$584	\$584	\$584
	must have LC4/C00				
Y7	Optional 3-button keys	\$36	\$36	\$36	\$36
	Keys, two additional masters	\$121	\$121	\$121	\$121
101	Heat insulation, rear compartment	\$156	\$156	\$156	\$156
	must have V25/VA3/VA1/C07/X66				
104	Heat insulation, front compartment	\$187	\$187	\$187	\$187
	if + D50/D51 must have V07				
112	Fuel-fired pre-heater/booster (17K BTU)	\$1,116	\$1,116	\$1,116	\$1,116
	not with HZ9				
113	Rear cabin heater and vents	\$786	\$786	\$786	\$786
	must have V43 + (H12/HZ9); not with VK8				
115	Heated front passenger seat	\$284	\$284	\$284	\$284
	must have H16; not with X68				
116	Heated driver's seat	\$284	\$284	\$284	\$284
	must have H15; not with X68			F.	
188	Rear heater prep	\$405	\$405	\$405	\$405
	must have H12/HZ9; not with H13/T19				
111	Front-to-rear outlet in instrument panel	\$0	\$0	\$0	\$0
	must have FJ1/C01				
Hi4	Thermotronic automatic climate control	\$337	\$337	\$337	\$337
	must have JF1; if +H13 must have H08/HK4		-		
179	Fuel-fired heater booster (18,000 BTU)	\$676	\$676	\$676	\$676
142	not with H12				
51	Fuel gauge, optimized for aux. fuel tap	\$72	\$72	\$72	\$72
-	not with HZ9/H12				
52	Engine oil level display at cold start	\$0	\$0	\$0	\$0
A7	Blind Spot Assist	\$450	\$450	\$450	\$450
-	must have F64; not with C01				
IB4	Active Lane Keeping Assist	\$288	\$288	\$288	\$288
	standard with CO2/CA2				
B6	Parking Package with 360 degree camera	\$775	\$775	\$775	\$775
	must have E3M/C02/C03; not with W75/W76/JB7				•
JB7	Parking Package	\$615	\$615	\$615	\$615
	must have E3M/C02/C03; not with W75/W76/JB6		-		
JB8	360 Degree Camera	\$685	\$685	\$685	\$685
	SoP and Plausibility TBD				
JF1	Rain sensor	\$106	\$106	\$106	\$106
	standard with CO2/X11		*		
JK5	Instrument cluster with color display	\$144	\$144	\$144	\$144
,,,,	not with CO3		-		
JWO	Backup alarm	\$99	\$99	\$99	\$99
IW2	Deactivation lamp monitoring failure	\$27	\$27	\$27	\$27
JW8	Attention Assist	\$49	\$49	\$49	\$49
K51	Misfueling prevention for Diesel	\$49	\$49	\$49	\$49
K52	DEF fluid filler cap - lockable	\$27	\$27	\$27	\$27
L13	Fog lamp with cornering light function	\$199	\$199	\$199	\$199
LB9	Illuminated front exits	\$151	\$151	\$151	\$151
LC4	Comfort overhead control panel	\$93	\$93	\$93	\$93
	Speed limitation 65 mph	\$60	\$60	\$60	\$60
20	not with MD3	· · · · - · - ·	-4		
MD3	Top speed limitation 75 mph	\$60	\$60	\$60	\$60
دس,۰,۰	not with M20			h-	
N62	Front engine bracket for additional alternator	\$467	\$467	\$467	\$467
, , , , ,	not with HK4/N63	7.22			

		144" 6C	144" 6C 144" 6C 4x4		170" 6C 4x
		M2CV46	M2CV4X	M2CV76	M2CV7X
		907.643	907.643	907.645	907.645
N63	Front engine bracket for auxiliary A/C compressor	\$467	\$467	\$467	\$467
	not with HK4/N62				
Q24	Trailer hitch, 5,000 lbs	\$147	\$147	\$147	\$147
	not with W73/W75/W76		-		-
QA9	Half-sided step rear (for trailer hitch)	\$101	\$101	\$101	\$101
	must have Q24/QA2; not with W73/W75/W76				
391	Spare tire deletion	-\$110	-\$110	-\$110	-\$110
	must have R92; not with R87				
392	Spare tire carrier deletion	\$0	\$0	\$0	\$0
	must have R91; not with R65				
398	Rims painted jet black	\$81	\$81	\$81	\$81
	not with RL5/RM2				
₹F1	Tire brand Continental	\$0	\$0	\$0	\$0
	must have RM1 + RM9				
RF8	Tire brand Michelin	\$0	\$0	\$0	\$0
	must have RM9; not with RM1				
RHO	Tire brand Kumho	\$0	\$0	\$0	\$0
	must have RM9; not with RM1				
RL5	Light-alloy wheels 6.5 J x 16	\$906	\$906	\$906	\$906
	not with RS3/RM2/R98				
RM1	M+S winter tires	\$169	\$169	\$169	\$169
	must have RF1/RD9; not with RF8/RH0/X31				
M2	Rims painted arctic white	\$81	\$81	\$81	\$81
	not with R98/RL5		-		
RM9	Specially requested tires	\$101	\$101	\$101	\$101
	must have RF1/RF8/RH0; not with RD9				
28	Armrest, driver and passenger door	\$51	\$51	\$51	\$51
Γ12	Sliding door two stage opening	\$82	\$82	\$82	\$82
	not with T55	***************************************			
r50	Electric closing assist right sliding door	\$335	\$335	\$335	\$335
	must have D03; not with T55/T93				
75 5	Electric sliding door right	\$831	\$831	\$831	\$831
	must have D03 + (FY7+T16); not with T12/T50		,		
۲ 5 7	Electric sliding step	\$1,071	\$1,071	\$1,071	\$1,071
	must have D03 + ED5; not with T93				
r60	Opening limiter electrically operated sliding door	\$120	\$120	\$120	\$120
	must have T55				
Γ75	Door-mounted assist handles, driver & passenger	\$59	S	\$59	S
85	Assist handle, left rear door	\$32	\$32	\$32	\$32
86	Assist handles, right rear door	\$32	\$32	\$32	\$32
/43	Wood floor with 6 D-rings	\$422	\$422	\$422	\$422
	not with P93/V93/VL4/VK8/C07; standard with D93/H13/V24		7.22	¥ /	7.25
/85	Cigarette lighter & ash cup, front	\$39	\$39	\$39	\$39
/C5	Door sill - protective edge	\$71	\$71	\$71	\$71
163	must have V43/X66; not with T19/T93/VK8/VV2/V93/C07	3/1	2/1	1/ب	2/1
1110		£270	6270	cara.	£270
/K8	Floor covering, plastic	\$370	\$370	\$370	\$370
	not with V43/P93/T19/T93/V52/VC5/X66	T			1
	Rear doors, opening to side wall	\$360	\$360	\$360	\$360
N5F	90 Degree fixation point- Rear Doors	\$80	\$80	\$80	\$80
	SoP and Plausibility TBD				
N73	Bumper step, rear, grey	\$187	\$187	\$187	\$187
	not with Q24/W75/W76				7
N75	Step, wide, at rear end	\$308	\$308	\$308	\$308
	not with JB6/JB7/Q24/QA9; must have R91+R92				
N76	Bumper step, rear, spring-loaded	\$601	- 1	\$601	SINKIE.
_	must have R91+R92; not with JB6/JB7/X30/Q24				

		144" 6C	144" 6C 4x4	170" 6C M2CV76	170" 6C 4x4
		M2CV46	M2CV4X		M2CV7X
		907.643	907.643	907.645	907.645
W78	Heated rear window(s) w/ washers/wipers	\$335	\$335	\$335	\$335
	Must have H22+VA7 / if D51 must have F61; not with W6	1			12
X90	Deletion of Sprinter badge, left rear door	\$0	\$0	\$0	\$0
X93	Deletion of model badge, right rear door	\$0	\$0	\$0	\$0
XM4	Acoustic package	\$87	\$87	\$87	\$87
	standard with CO2/CO3				
Ý10	First-aid kit	\$27	\$27	\$27	\$27
Y26	Wheel chocks	\$38	\$38	\$38	\$38
Y45	Emergency flashlight	\$27	\$27	\$27	\$27
Y68	Paint preservative	\$187	\$187	\$212	\$212
Y69	Surface protection for stock vehicles	\$315	\$315	\$315	\$315
YK3	Cargo straps, D-rings	\$81	\$81	\$81	\$81
ZH4	Downhill speed regulation for 4x4	-	\$58		\$58
	must have ED5; not with ET4				

2500 CREW VAN - 6cyl Diesel Packages

	144" 6C	144" 6C 4x4	170" 6C M2CV76 907.645	170" 6C 4x4
	M2CV46	M2CV4X		M2CV7X
	907.643	907.643		907.645
C00 Comfort Package	\$300	\$300	\$300	\$300
LC4 Comfort overhead control panel	X	Х	Х	Х
E4 Lumbar support, co-driver's seat	X	Х	X	Х
E5 Lumbar support, driver's seat	X	Х	X	Х
SKO Comfort head restraint, driver	X	Х	X	X
SK1 Comfort head restraint, co-driver	X	Х	X	Х
Armrest, driver and passenger door	X	Х	X	X
nust have COS OR X68; CA/CC only: not with S23				

OS Comfort Package (Seat addition)	\$381	\$381	\$381	\$381
B1 Comfort driver's seat	X	X	X	X
B2 Comfort passenger seat	X	X	X	Х

X68	Comfort Plus Package	\$1,923	\$1,923	\$1,923	\$1,923
H 1 5	Heated front passenger seat	X	Х	Х	X
H16	leated driver's seat	Х	Х	X	X
SF1	Driver's seat electrically adjustable	X	Х	X	X
SF2	Co-driver's seat electrically adjustable	X	Х	X	X

C01	Driver Convenience Package	\$760	\$760	\$760	\$760
E46	12 V power outlet, driver seat base	X	Х	X	Х
F64	Electrically folding exterior mirrors	X	Х	X	X
FJ1	Hinged lid for storage compartment	X	Х	Х	Х
-J5	Hinged Lid for Storage Compartments left and right	X	X	X	X
-Z9	Keys, two additional masters	X	Х	X	Х
IA7	Blind Spot Assist	X	Х	X	Х
W8	Attention Assist	X	Х	X	Х

C02 Prem	ium Package	\$983	\$983	\$983	\$983
CL3 Leath	er steering wheel	X	X	X	X
E3M MBUX	(Multimedia System with 7" touchscreen	X	Х	X	X
FM3 Wet V	Viper System	Х	Х	X	X
JB4 Active	Lane Keeping Assist	X	Х	X	X
JK5 Instru	ment cluster with color display	X	X	X	Х

CA2	C02 in combination with C03	\$604	\$604	\$604	\$604
CL3	Leather steering wheel	X	Х	X	X
FM3	Wet Wiper System	X	Х	X	Х
JB4	Active Lane Keeping Assist	X	Х	X	X
JK5	Instrument cluster with color display	X	Х	X	Х

2500 CREW VAN - 6cyl Diesel Packages

144" 6C	144" 6C 4x4	170" 6C	170" 6C 4x4
M2CV46	M2CV4X	M2CV76	M2CV7X
907.643	907.643	907.645	907.645

C03	Premium Plus Package	\$1,793	\$1,793	\$1,793	\$1,793
E1B	Tray for smartphones incl. wireless charging	X	X	X	Х
	Navigation	X	Х	X	X
Y2	Intelligent navigation	X	Х	X	X
4M	MBUX Multimedia System with 10.25" touchscreen	X	Х	X	X
X9	Free map data updates for 3 years	Х	X	X	X
∃1 I	Front-to-rear outlet in instrument panel	X	X	X	X
A9	Traffic Sign Assist	X	Х	X	X
XM4	Acoustic package	Х	Х	X	X
111	Front-To-Rear Outlet In Instrument Panel	X	Х	X	X
_	have (CA2+(JB7/JB6/JB8)) OR (JB4+JK5+FM3+(JB7/JB6/JB8)); no	t with FR8 and CO2			

67 Chrome Grille Package	\$290	\$290	\$290	\$290
N2 Radiator grille frame in vehicle color	X	X	X	X
K3 Chrome plated radiator grille (MB only)	X	X	X	X

X13	Exterior Lighting Package	\$1,608	\$1,608	\$1,608	\$1,608
L13	Fog lamp with cornering light function	X	X	X	X
L22	Partial LED tail lights	X	Х	X	X
LA1	High Beam Assist	X	X	X	X
LG7	LED High Performance headlamps	X	X	X	Х
no res	trictions				

X72 Crew Van Comfort Package	\$220	\$220	\$220	\$220
Convenience Head Restraints For Pass. Comp.	X	X	X	X
T12 Sliding door two stage opening	Х	Х	X	X
T50 Electric closing assist right sliding door (soft close)	X	Х	X	Х
UY1 Three-seater comfort bench in passenger compartment, first row (na	Х	X	X	Х

(4Z Interior Trim Upgrade Package	\$610	\$610	\$610	\$610
/A1 Side wall paneling waist height PVC	X	Х	X	Х
/A3 Side wall paneling full hardboard	Х	Х	X	X
K4 Mixto	X	Х	X	X