

| 144" 4C | 170" 4C |
|---------|---------|
| M4CC44 | M4CC74 |
| 907.153 | 907.155 |

| | | |
|--|--|------------|
| Engine | | |
| 4-Cyl Engine/7-Speed Trans. | | |
| ED1 | AGM battery 12V 70AH | S |
| G42 | Automatic transmission, 7G-tronic | S |
| M40 | Alternator 14 V / 200 A | S |
| MG3 | 2.0L 4-cylinder diesel engine | S |
| MH8 | SULEV emissions | S |
| Identification Lights - choose while ordering | | |
| V59 | Identification Lamps Package | \$0 |
| L49 | Identification lamps | O |
| LV7 | Clearance lights pre-wiring | O |
| For pre-wiring only (recommended for RV) | | \$0 |
| LV7 | Clearance lights pre-wiring | O |
| Equipment | | |
| A50 | Front axle reinforced | S |
| AR3 | Axle ratio 4.182 | S |
| BA3 | Active Brake Assist | S |
| BH1 | Hold Function | S |
| CB8 | Stabilization Level II | S |
| C6L | Multifunction steering wheel | S |
| CL1 | Adjustable steering wheel (angle) | S |
| E07 | Hill Start Assist | S |
| E10 | Standard radio | S |
| E1U | USB-C socket, 5 V | S |
| E30 | Starter battery disconnect | S |
| E3J | Pre-installation for switch panel | S |
| E40 | Trailer hitch prep. wiring | S |
| ED8 | Preinstallation PSM | S |
| EE5 | Ultracapacitor discharge module | S |
| EK1 | Body Builder Connector | S |
| ES0 | Jump start terminal | S |
| EW6 | Pre-installation for Mercedes me Remote Services | S |
| EY5 | Emergency Call System | S |
| EY6 | Breakdown management | S |
| F68 | Heated & electrically adjustable exterior mirrors | S |
| FF5 | Shelf above windshield | S |
| FG8 | Cupholder front | S |
| FI1 | Remote key (315 mhz) w/central locking | S |
| FJ4 | Storage compartment underneath cockpit | S |
| FS2 | Exterior mirror extended (for up to 96" box width) | S |
| H21 | Windshield with filter band | S |
| HH2 | Heater, auxiliary electric hot air | S |
| HH9 | Air Condition, Front | S |
| IH7 | Head Unit, North America | S |
| J11 | Speedometer, miles and km/h | S |
| J55 | Seat belt warning for co-driver seat | S |
| J58 | Seat belt reminder driver | S |
| J65 | Outside temperature gauge | S |
| JA8 | Crosswind Assist | S |
| JH3 | Communication module (LTE) for dig. services | S |
| JI9 | Service interval 20,000 miles | S |
| JW2 | Deactivation lamp monitoring failure | S |
| K56 | Red diesel filler cap | S |
| K60 | Exhaust straight to rear | S |
| KB7 | 24.5 gallon fuel tank | S |
| KL1 | Aux fuel sending unit w/ fuel tap | S |

| | | 144" 4C | 170" 4C |
|-----|---|---------|---------|
| | | M4CC44 | M4CC74 |
| | | 907.153 | 907.155 |
| KL5 | Fuel filter with water separator | S | S |
| KP6 | 3rd generation SCR emission control system | S | S |
| L94 | Parking lights deletion | S | S |
| LA2 | Headlight assistant | S | S |
| MS1 | Cruise control | S | S |
| P47 | Front mudflaps | S | S |
| Q11 | Longitudinal member reinforcement | S | S |
| Q72 | Deletion of end cross member | S | S |
| R60 | Provisional spare wheel bracket frame mounted | S | S |
| R87 | Spare tire | S | S |
| RD9 | Unspecified tire brand | S | S |
| RH7 | Tires LT 215/85 R16 | S | S |
| RM0 | All-season tires | S | S |
| RS6 | 5.5 J x 16 steel wheels | S | S |
| S02 | Standard driver seat | S | S |
| S04 | Standard front passenger seat | S | S |
| S22 | Armrest for driver's seat | S | S |
| S25 | Armrest for front passenger seat | S | S |
| SA5 | Front airbag, driver | S | S |
| SA6 | Front airbag, passenger | S | S |
| SH1 | Thorax-pelvis sidebag, driver | S | S |
| SH2 | Thorax-pelvis sidebag, co-driver | S | S |
| SH9 | Airbag, driver/passenger window | S | S |
| SK2 | Seat occupancy sensor, driver's seat | S | S |
| XL4 | GVWR 12,125 lbs. / 5.500 Kg | S | S |
| Y43 | Jack, hydraulic | S | S |

Options

| | | 144" 4C | 170" 4C |
|-----|--|---------|---------|
| | | M4CC44 | M4CC74 |
| | | 907.153 | 907.155 |
| AR2 | Axle ratio 3.923 | \$0 | \$0 |
| | <i>not with AR3</i> | | |
| B01 | ESP for increased Center of Gravity above 39.4" | - | \$0 |
| | <i>must have CB4/CB8; not with RF8</i> | | |
| BE2 | Handbrake lever, folding | \$55 | \$55 |
| C72 | Bumpers front/rear primed | \$141 | \$141 |
| | <i>must have CN2 (part of X67), not with CM2</i> | | |
| CE8 | Raised rear body mounts | - | \$409 |
| CL3 | Leather steering wheel | \$187 | \$187 |
| | <i>must have (C02/E3M)/C03 + (ET4/MS1)</i> | | |
| CM2 | Bumpers/detachable body parts painted body colour | \$432 | \$432 |
| | <i>must have CN2/X67 + (7755/9147/9197/9775)</i> | | |
| CM9 | Primed side moldings | \$364 | \$364 |
| | <i>must have C72, not with CM2</i> | | |
| E1B | Tray for smartphones incl. wireless charging | \$156 | \$156 |
| | <i>must have C02/E3M + H1I</i> | | |
| E1E | Navigation | \$728 | \$728 |
| | <i>must have C02/E3M, not with C03</i> | | |
| E1S | Sirius XM, satellite radio | \$255 | \$255 |
| | <i>must have C02/E3M/C03</i> | | |
| E1X | MBUX multimedia 6-hour runtime | - | \$0 |
| | <i>must have X2R + (C02+E1E/E1S)/C03/(E3M+E1E/E1S)</i> | | |
| E1R | Additional Fuses (40/80/150/100 Ampere) | \$50 | \$50 |
| | <i>SoP and Plausibility TBD</i> | | |
| E1Y | Additional Fuses (40/80/80/100 Ampere) | \$50 | \$50 |
| | <i>SoP and Plausibility TBD</i> | | |
| E2A | Access point for BB special signals in cockpit | \$29 | \$29 |
| E2I | Additional battery, co-driver seat base | \$248 | \$248 |
| E2A | Access point for BB special signals in cockpit | \$29 | \$29 |
| E2I | Additional battery, co-driver seat base | \$248 | \$248 |
| | <i>Must have E36; not with E2M</i> | | |
| E2M | Additional battery, engine compartment | \$248 | \$248 |
| | <i>must have X01+E36; not with E2I/X69</i> | | |
| E3M | MBUX Multimedia System with 7" touchscreen | \$474 | \$474 |
| | <i>not with C02/C03; must have JK5</i> | | |
| E36 | Cutoff relay for additional battery | \$110 | \$110 |
| | <i>standard with E2I/E2M</i> | | |
| E46 | 12 V power outlet, driver seat base | \$92 | \$92 |
| E5M | Extension of PSM standard contact | \$58 | \$58 |
| EA5 | Pre-wiring central locking (upfitter doors rear) | \$39 | \$39 |
| ED4 | AGM battery 12V 92 AH 850 A | \$101 | \$101 |
| | <i>not with ED1</i> | | |
| ED5 | Parametric special module (PSM) | \$317 | \$317 |
| | <i>not with ED8</i> | | |
| EE3 | 115 V socket | \$125 | \$125 |
| EP7 | Basic electric fitting for rear loudspeakers | \$68 | \$68 |
| ES5 | Charging package, dashboard | \$82 | \$82 |
| ET4 | Active Distance Assist DISTRONIC | \$263 | \$263 |
| | <i>must have C02/C03/E3M</i> | | |
| F35 | Window in cab rear wall | \$134 | \$134 |
| | <i>must have F61/FV1; not with FW1</i> | | |
| F49 | Electrically heated windshield | \$218 | \$218 |
| | <i>must have ED4; not with LA3</i> | | |
| F61 | Interior rear view mirror | \$36 | \$36 |
| | <i>must have C02/C03/E3M</i> | | |
| FE9 | Additional DIN-slot | \$81 | \$81 |
| FF8 | Overhead storage slot, front center | \$105 | \$105 |
| FJ1 | Hinged lid for storage compartment | \$93 | \$93 |

Options

| | | 144" 4C | 170" 4C |
|-----|---|---------|---------|
| | | M4CC44 | M4CC74 |
| | | 907.153 | 907.155 |
| FR7 | Pre-wiring rear view camera (head unit display) | \$65 | \$65 |
| | <i>must have C02/C03; not with FV1</i> | | |
| FV1 | Pre-wiring rear view camera (mirror display) | \$260 | \$260 |
| | <i>not with F61/FR7/LA3</i> | | |
| FW1 | Rear wall deletion, chassis cab | \$0 | \$0 |
| | <i>must have P08; not with FY1</i> | | |
| FY1 | Security alarm w. interior motion sensor | \$584 | \$584 |
| | <i>must have LC4/C00; not with FW1/X2R</i> | | |
| FY7 | Optional 3-button keys | \$36 | \$36 |
| FZ9 | Keys, two additional masters | \$121 | \$121 |
| H04 | Heat insulation, front compartment | \$187 | \$187 |
| | <i>must have FW1/V07</i> | | |
| H12 | Fuel-fired pre-heater/booster (17K BTU) | \$826 | \$826 |
| | <i>must have ED4; not with HZ9</i> | | |
| H15 | Heated front passenger seat | \$284 | \$284 |
| | <i>must have H16; not with X68</i> | | |
| H16 | Heated driver's seat | \$284 | \$284 |
| | <i>must have H15; not with X68</i> | | |
| H88 | Rear heater prep | \$405 | \$405 |
| | <i>must have ED4+(H12/HZ9)</i> | | |
| H11 | Front-to-rear outlet in instrument panel | \$0 | \$0 |
| | <i>must have FJ1/C01</i> | | |
| HH4 | Thermotronic automatic climate control | \$337 | \$337 |
| | <i>must have JF1</i> | | |
| HZ9 | Fuel-fired heater booster (18,000 BTU) | \$676 | \$676 |
| | <i>not with H12</i> | | |
| J1V | Pre-installation Blind Spot Assist | \$450 | \$450 |
| | <i>SoP and Plausibility TBD</i> | | |
| J51 | Fuel gauge, optimized for aux. fuel tap | \$72 | \$72 |
| | <i>not with HZ9/H12</i> | | |
| J52 | Engine oil level display at cold start | \$0 | \$0 |
| JB4 | Active Lane Keeping Assist | \$288 | \$288 |
| | <i>not with C02/CA2</i> | | |
| JF1 | Rain sensor | \$106 | \$106 |
| | <i>standard with C02; not with LA3</i> | | |
| JK5 | Instrument cluster with color display | \$144 | \$144 |
| | <i>standard with C03</i> | | |
| JW0 | Backup alarm | \$99 | \$99 |
| | <i>not with Q72</i> | | |
| JW8 | Attention Assist | \$49 | \$49 |
| K51 | Misfueling prevention for Diesel | \$49 | \$49 |
| K52 | DEF fluid filler cap - lockable | \$27 | \$27 |
| L13 | Fog lamp with cornering light function | \$199 | \$199 |
| L72 | Pre-installation load compartment lighting | \$174 | \$174 |
| L76 | Wire harness tail lamp w/ extended wiring | \$133 | \$133 |
| L77 | Wiring for additional turn signals | \$88 | \$88 |
| L90 | Tail lamp deletion, non-LED | -\$26 | -\$26 |
| | <i>not with L22</i> | | |
| L91 | Pre-wiring LED tail lights | \$49 | \$49 |
| | <i>not with L22/L90</i> | | |
| LA3 | Light sensor for vehicles with alcove | \$0 | \$0 |
| | <i>not with F49/F61/FV1/LA2/JF1</i> | | |
| LB9 | Illuminated front exits | \$93 | \$93 |
| LC4 | Comfort overhead control panel | \$93 | \$93 |
| LV6 | Third brake light pre-wiring | \$32 | \$32 |
| M20 | Speed limitation 65 mph | \$60 | \$60 |
| | <i>not with MD3</i> | | |

| | | 144" 4C | 170" 4C |
|-----|---|---------|---------|
| | | M4CC44 | M4CC74 |
| | | 907.153 | 907.155 |
| M24 | Starter upgraded | \$189 | \$189 |
| MD3 | Top speed limitation 75 mph | \$60 | \$60 |
| | <i>not with M20</i> | | |
| N62 | Front engine bracket for additional alternator | \$467 | \$467 |
| | <i>not with N63</i> | | |
| N63 | Front engine bracket for auxiliary A/C compressor | \$467 | \$467 |
| | <i>not with N62</i> | | |
| P08 | Cover for transport | \$0 | \$0 |
| | <i>must have FW1/X69</i> | | |
| Q18 | End cross member bolted | \$65 | \$65 |
| QA2 | Trailer cross member 7,500 lbs capacity | \$187 | \$187 |
| R65 | Spare tire bracket below frame | \$0 | \$0 |
| | <i>must have Q18; not with Q72/R60/R92</i> | | |
| R91 | Spare tire deletion | -\$110 | -\$110 |
| | <i>must have R92; not with R87/R60</i> | | |
| R92 | Spare tire carrier deletion | \$0 | \$0 |
| | <i>must have R91; not with R65/R60</i> | | |
| R98 | Rims painted jet black | \$81 | \$81 |
| | <i>not with RM2</i> | | |
| RF1 | Tire brand Continental | \$0 | \$0 |
| | <i>not with RD9</i> | | |
| RF8 | Tire brand Michelin | \$0 | \$0 |
| | <i>not with RD9/RF1/RM1</i> | | |
| RM1 | M+S winter tires | \$169 | \$169 |
| | <i>must have RD9/RF1; not with RF8/X31</i> | | |
| RM2 | Rims painted arctic white | \$81 | \$81 |
| | <i>not with X31/R98</i> | | |
| RM9 | Specially requested tires | \$101 | \$101 |
| | <i>must have RF1/RF8; not with RD9</i> | | |
| S23 | Twin front passenger seat | \$400 | \$400 |
| | <i>not with C00/X68/X01</i> | | |
| S28 | Armrest, driver and passenger door | \$51 | \$51 |
| S62 | Seat belts orange, driver and front passenger | \$32 | \$32 |
| | <i>not with S23</i> | | |
| SB9 | Driver's seat plus | \$238 | \$238 |
| | <i>must have FY7</i> | | |
| SZ7 | Storage net, driver's seat backrest | \$0 | \$0 |
| | <i>must have FW1/X69</i> | | |
| SZ8 | Storage net, passenger seat backrest | \$0 | \$0 |
| | <i>must have FW1/X69; not with S23</i> | | |
| T75 | Door-mounted assist handles, driver & passenger | \$59 | \$59 |
| V07 | Cab rear wall liner | \$360 | \$360 |
| | <i>not with FW1</i> | | |
| V85 | Cigarette lighter & ash cup, front | \$39 | \$39 |
| VV4 | Additional Ground Weld Studs | \$45 | \$45 |
| | <i>SoP and Plausibility TBD</i> | | |
| X93 | Deletion of model badge, right rear door | \$0 | \$0 |
| X2R | Conversion to RV requirement | - | \$0 |
| | <i>must have B01+E1X</i> | | |
| XM4 | Acoustic package | \$87 | \$87 |
| | <i>standard with C02/C03</i> | | |
| Y10 | First-aid kit | \$27 | \$27 |
| Y26 | Wheel chocks | \$38 | \$38 |
| Y45 | Emergency flashlight | \$27 | \$27 |
| Y68 | Paint preservative | \$88 | \$88 |
| Y69 | Surface protection for stock vehicles | \$292 | \$292 |

| 144" 4C | 170" 4C |
|---------|---------|
| M4CC44 | M4CC74 |
| 907.153 | 907.155 |

| | | | |
|---|------------------------------------|--------------|--------------|
| C00 | Comfort Package | \$300 | \$300 |
| LC4 | Comfort overhead control panel | X | X |
| SE4 | Lumbar support, co-driver's seat | X | X |
| SE5 | Lumbar support, driver's seat | X | X |
| SK0 | Comfort head restraint, driver | X | X |
| SK1 | Comfort head restraint, co-driver | X | X |
| S28 | Armrest, driver and passenger door | X | X |
| <i>must have C05 OR X68; not with S23</i> | | | |

| | | | |
|----------------------|--|--------------|--------------|
| C05 | Comfort Package (Seat addition) | \$381 | \$381 |
| SB1 | Comfort driver's seat | X | X |
| SB2 | Comfort passenger seat | X | X |
| <i>must have C00</i> | | | |

| | | | |
|---|--|----------------|----------------|
| X68 | Comfort Plus Package | \$1,923 | \$1,923 |
| H15 | Heated front passenger seat | X | X |
| H16 | Heated driver's seat | X | X |
| SF1 | Driver's seat electrically adjustable | X | X |
| SF2 | Co-driver's seat electrically adjustable | X | X |
| <i>must have C00 and VF4 OR VF6; not with S23</i> | | | |

| | | | |
|------------|-------------------------------------|--------------|--------------|
| C01 | Driver Convenience Package | \$323 | \$323 |
| E46 | 12 V power outlet, driver seat base | X | X |
| FJ1 | Hinged lid for storage compartment | X | X |
| FZ9 | Keys, two additional masters | X | X |
| JW8 | Attention Assist | X | X |

| | | | |
|--|--|--------------|--------------|
| C02 | Premium Package | \$983 | \$983 |
| CL3 | Leather steering wheel | X | X |
| E3M | MBUX Multimedia System with 7" touchscreen | X | X |
| FM3 | Wet Wiper System | X | X |
| JB4 | Active Lane Keeping Assist | X | X |
| JK5 | Instrument cluster with color display | X | X |
| <i>Ordering availability restricted, see NetStar for availability and restrictions must have (JF1/LA3) + XM4</i> | | | |

| | | | |
|--|---------------------------------------|--------------|--------------|
| CA2 | C02 in combination with C03 | \$604 | \$604 |
| CL3 | Leather steering wheel | X | X |
| FM3 | Wet Wiper System | X | X |
| JB4 | Active Lane Keeping Assist | X | X |
| JK5 | Instrument cluster with color display | X | X |
| <i>Ordering availability restricted, see NetStar for availability and restrictions must have C03 + JF1</i> | | | |

| | |
|---------|---------|
| 144" 4C | 170" 4C |
| M4CC44 | M4CC74 |
| 907.153 | 907.155 |

| | | | |
|---------------------------------------|--|----------------|----------------|
| C03 | Premium Plus Package | \$1,793 | \$1,793 |
| E1B | Tray for smartphones incl. wireless charging | X | X |
| | Navigation | X | X |
| EY2 | Intelligent navigation | X | X |
| E4M | MBUX Multimedia System with 10.25" touchscreen | X | X |
| EX9 | Free map data updates for 3 years | X | X |
| H1I | Front-to-rear outlet in instrument panel | X | X |
| JA9 | Traffic Sign Assist | X | X |
| XM4 | Acoustic package | X | X |
| <i>must have CA2 OR (JB4+JK5+FM3)</i> | | | |

| | | | |
|------------------------|---|--------------|--------------|
| X67 | Chrome Grille Package | \$290 | \$290 |
| CN2 | Radiator grille frame in vehicle color | X | X |
| FK3 | Chrome plated radiator grille (MB only) | X | X |
| <i>no restrictions</i> | | | |

| | | | |
|------------------------|--|----------------|----------------|
| X13 | Exterior Lighting Package | \$1,608 | \$1,608 |
| L13 | Fog lamp with cornering light function | X | X |
| L22 | Partial LED tail lights | X | X |
| LA1 | High beam assist | X | X |
| LG7 | LED high performance headlamps | X | X |
| <i>no restrictions</i> | | | |

| | | | |
|---|--------------------------------------|--------------|--------------|
| X69 | Swivel Seat Package | \$587 | \$587 |
| SR8 | Swivel base for driver's seat | X | X |
| SR9 | Swivel base for front passenger seat | X | X |
| S87 | Driver's seat frame, low | X | X |
| S88 | Passenger seat frame, low | X | X |
| FW1 | Rear wall deletion, chassis cab | X | X |
| BE2 | Handbrake lever, folding | X | X |
| <i>must have (C00+C05) OR (C00+X68)</i> | | | |

| | | | |
|---------------------------------|--|--------------|--------------|
| X01 | Suspension Seating Package | \$940 | \$940 |
| SB3 | Driver suspension seat, comfort version | X | X |
| SB4 | Passenger suspension seat, comfort version | X | X |
| S87 | Driver's seat frame, low | X | X |
| S88 | Passenger seat frame, low | X | X |
| <i>not with C00/C05/X68/S23</i> | | | |

| 144" 6C | 170" 6C |
|---------|---------|
| M4CC46 | M4CC76 |
| 907.153 | 907.155 |

| Engine | | |
|--|--|-----|
| 6-Cyl Engine/7-Speed Trans. | | |
| ED1 | AGM battery 12V 70AH | \$ |
| G42 | Automatic transmission, 7G-tronic | \$ |
| M46 | Alternator 14 V/220 A | \$ |
| MG5 | 3.0L V6 turbo diesel engine | \$ |
| MH8 | SULEV emissions | \$ |
| Identification Lights - choose while ordering | | |
| V59 | Identification Lamps Package | \$0 |
| L49 | Identification lamps | O |
| LV7 | Clearance lights pre-wiring | O |
| For pre-wiring only (recommended for RV) | | \$0 |
| LV7 | Clearance lights pre-wiring | O |
| Equipment | | |
| A50 | Front axle reinforced | \$ |
| AR3 | Axle ratio 4.182 | \$ |
| BA3 | Active Brake Assist | \$ |
| BH1 | Hold Function | \$ |
| C6L | Multifunction steering wheel | \$ |
| CB8 | Stabilization Level II | \$ |
| CL1 | Adjustable steering wheel (angle) | \$ |
| E07 | Hill Start Assist | \$ |
| E10 | Standard radio | \$ |
| E1U | USB-C socket, 5 V | \$ |
| E30 | Starter battery disconnect | \$ |
| E3J | Pre-installation for switch panel | \$ |
| E40 | Trailer hitch prep. wiring | \$ |
| ED8 | Preinstallation PSM | \$ |
| EE5 | Ultracapacitor discharge module | \$ |
| EK1 | Body Builder Connector | \$ |
| ES0 | Jump start terminal | \$ |
| EW6 | Pre-installation for Mercedes me Remote Services | \$ |
| EY5 | Emergency Call System | \$ |
| EY6 | Breakdown management | \$ |
| F68 | Heated & electrically adjustable exterior mirrors | \$ |
| FF5 | Shelf above windshield | \$ |
| FG8 | Cupholder front | \$ |
| FI1 | Remote key (315 mhz) w/central locking | \$ |
| FJ4 | Storage compartment underneath cockpit | \$ |
| FS2 | Exterior mirror extended (for up to 96" box width) | \$ |
| H21 | Windshield with filter band | \$ |
| HH2 | Heater, auxiliary electric hot air | \$ |
| HH9 | Air Condition, Front | \$ |
| IH7 | Head Unit, North America | \$ |
| J11 | Speedometer, miles and km/h | \$ |
| J55 | Seat belt warning for co-driver seat | \$ |
| J58 | Seat belt reminder driver | \$ |
| J65 | Outside temperature gauge | \$ |
| JA8 | Crosswind Assist | \$ |
| JH3 | Communication module (LTE) for dig. services | \$ |
| JI9 | Service interval 20,000 miles | \$ |
| JW2 | Deactivation lamp monitoring failure | \$ |
| K56 | Red diesel filler cap | \$ |
| K60 | Exhaust straight to rear | \$ |
| KB7 | 24.5 gallon fuel tank | \$ |
| KL1 | Aux fuel sending unit w/ fuel tap | \$ |
| KL5 | Fuel filter with water separator | \$ |

| | | 144" 6C | 170" 6C |
|-----|---|---------|---------|
| | | M4CC46 | M4CC76 |
| | | 907.153 | 907.155 |
| KP6 | 3rd generation SCR emission control system | S | S |
| L94 | Parking lights deletion | S | S |
| LA2 | Headlight assistant | S | S |
| MS1 | Cruise control | S | S |
| P47 | Front mudflaps | S | S |
| Q11 | Longitudinal member reinforcement | S | S |
| Q72 | Deletion of end cross member | S | S |
| R60 | Provisional spare wheel bracket frame mounted | S | S |
| R87 | Spare tire | S | S |
| RD9 | Unspecified tire brand | S | S |
| RH7 | Tires LT 215/85 R16 | S | S |
| RM0 | All-season tires | S | S |
| RS6 | 5.5 J x 16 steel wheels | S | S |
| S02 | Standard driver seat | S | S |
| S04 | Standard front passenger seat | S | S |
| S22 | Armrest for driver's seat | S | S |
| S25 | Armrest for front passenger seat | S | S |
| SA5 | Front airbag, driver | S | S |
| SA6 | Front airbag, passenger | S | S |
| SH1 | Thorax-pelvis sidebag, driver | S | S |
| SH2 | Thorax-pelvis sidebag, co-driver | S | S |
| SH9 | Airbag, driver/passenger window | S | S |
| SK2 | Seat occupancy sensor, driver's seat | S | S |
| XL4 | GVWR 12,125 lbs. / 5,500 Kg | S | S |
| Y43 | Jack, hydraulic | S | S |

Options

| | | 144" 6C | 170" 6C |
|-----|--|---------|---------|
| | | M4CC46 | M4CC76 |
| | | 907.153 | 907.155 |
| AR2 | Axle ratio 3.923 | \$0 | \$0 |
| | <i>not with AR3</i> | | |
| B01 | Vehicle version for high load | - | \$0 |
| | <i>must have CB4/CB8; not with RF8</i> | | |
| BE2 | Handbrake lever, folding | \$55 | \$55 |
| C72 | Bumpers front/rear primed | \$141 | \$141 |
| | <i>must have CN2 (part of X67), not with CM2</i> | | |
| CB4 | Stabilization Level III | \$187 | \$187 |
| | <i>not with CB8</i> | | |
| CE8 | Raised rear body mounts | - | \$409 |
| CL3 | Leather steering wheel | \$187 | \$187 |
| | <i>must have (C02/E3M)/C03 + (ET4/MS1)</i> | | |
| CM2 | Bumpers/detachable body parts painted body colour | \$432 | \$432 |
| | <i>must have CN2/X67 + (7755/9147/9197/9775)</i> | | |
| CM9 | Primed side moldings | \$364 | \$364 |
| | <i>must have C72, not with CM2</i> | | |
| E1B | Tray for smartphones incl. wireless charging | \$156 | \$156 |
| | <i>must have C02/E3M + H1I</i> | | |
| E1E | Navigation | \$728 | \$728 |
| | <i>must have C02/E3M, not with C03</i> | | |
| E1S | Sirius XM, satellite radio | \$255 | \$255 |
| | <i>must have C02/E3M/C03</i> | | |
| E1X | MBUX multimedia 6-hour runtime | - | \$0 |
| | <i>must have X2R + (C02+E1E/E1S)/C03/(E3M+E1E/E1S)</i> | | |
| E1R | Additional Fuses (40/80/150/100 Ampere) | \$50 | \$50 |
| | <i>SoP and Plausibility TBD</i> | | |
| E1Y | Additional Fuses (40/80/80/100 Ampere) | \$50 | \$50 |
| | <i>SoP and Plausibility TBD</i> | | |
| E2A | Access point for BB special signals in cockpit | \$29 | \$29 |
| E2I | Additional battery, co-driver seat base | \$248 | \$248 |
| | <i>Must have E36; not with E2M</i> | | |
| E2M | Additional battery, engine compartment | \$248 | \$248 |
| | <i>must have X01+E36; not with E2I/X69</i> | | |
| E3M | MBUX Multimedia System with 7" touchscreen | \$474 | \$474 |
| | <i>not with C02/C03; must have JK5</i> | | |
| E36 | Cutoff relay for additional battery | \$110 | \$110 |
| | <i>standard with E2I/E2M</i> | | |
| E46 | 12 V power outlet, driver seat base | \$92 | \$92 |
| E5M | Extension of PSM standard contact | \$58 | \$58 |
| EA5 | Pre-wiring central locking (upfitter doors rear) | \$39 | \$39 |
| ED4 | AGM battery 12V 92 AH 850 A | \$101 | \$101 |
| | <i>not with ED1</i> | | |
| ED5 | Parametric special module (PSM) | \$317 | \$317 |
| | <i>not with ED8</i> | | |
| EE3 | 115 V socket | \$125 | \$125 |
| EP7 | Basic electric fitting for rear loudspeakers | \$68 | \$68 |
| ES5 | Charging package, dashboard | \$82 | \$82 |
| ET4 | Active Distance Assist DISTRONIC | \$263 | \$263 |
| | <i>must have C02/C03/E3M</i> | | |
| F35 | Window in cab rear wall | \$134 | \$134 |
| | <i>must have F61/FV1; not with FW1</i> | | |
| F49 | Electrically heated windshield | \$218 | \$218 |
| | <i>must have ED4; not with LA3</i> | | |
| F61 | Interior rear view mirror | \$36 | \$36 |
| | <i>must have C02/C03/E3M</i> | | |
| FE9 | Additional DIN-slot | \$81 | \$81 |
| FF8 | Overhead storage slot, front center | \$105 | \$105 |
| FJ1 | Hinged lid for storage compartment | \$93 | \$93 |

| | | 144" 6C | 170" 6C |
|-----|---|---------|---------|
| | | M4CC46 | M4CC76 |
| | | 907.153 | 907.155 |
| FR7 | Pre-wiring rear view camera (head unit display) <i>must have C02/C03; not with FV1</i> | \$65 | \$65 |
| FV1 | Pre-wiring rear view camera (mirror display) <i>not with F61/FR7/LA3</i> | \$260 | \$260 |
| FW1 | Rear wall deletion, chassis cab <i>must have P08; not with FY1</i> | \$0 | \$0 |
| FY1 | Security alarm w. interior motion sensor <i>must have LC4/C00; not with FW1/X2R</i> | \$584 | \$584 |
| FY7 | Optional 3-button keys | \$36 | \$36 |
| FZ9 | Keys, two additional masters | \$121 | \$121 |
| H04 | Heat insulation, front compartment <i>must have FW1/V07</i> | \$187 | \$187 |
| H12 | Fuel-fired pre-heater/booster (17K BTU) <i>must have ED4; not with HZ9</i> | \$826 | \$826 |
| H15 | Heated front passenger seat <i>must have H16; not with X68</i> | \$284 | \$284 |
| H16 | Heated driver's seat <i>must have H15; not with X68</i> | \$284 | \$284 |
| H88 | Rear heater prep <i>must have ED4+(H12/HZ9)</i> | \$405 | \$405 |
| H1I | Front-to-rear outlet in instrument panel <i>must have FJ1/C01</i> | \$0 | \$0 |
| HH4 | Thermotronic automatic climate control <i>must have JF1</i> | \$337 | \$337 |
| HZ9 | Fuel-fired heater booster (18,000 BTU) <i>not with H12</i> | \$676 | \$676 |
| J1V | Pre-installation Blind Spot Assist <i>SoP and Plausibility TBD</i> | \$450 | \$450 |
| J51 | Fuel gauge, optimized for aux. fuel tap <i>not with HZ9/H12</i> | \$72 | \$72 |
| J52 | Engine oil level display at cold start | \$0 | \$0 |
| JB4 | Active Lane Keeping Assist <i>not with C02/CA2</i> | \$288 | \$288 |
| JF1 | Rain sensor <i>standard with C02; not with LA3</i> | \$106 | \$106 |
| JK5 | Instrument cluster with color display <i>standard with C03</i> | \$144 | \$144 |
| JW0 | Backup alarm <i>not with Q72</i> | \$99 | \$99 |
| JW8 | Attention Assist | \$49 | \$49 |
| K51 | Misfueling prevention for Diesel | \$49 | \$49 |
| K52 | DEF fluid filler cap - lockable | \$27 | \$27 |
| L13 | Fog lamp with cornering light function | \$199 | \$199 |
| L72 | Pre-installation load compartment lighting | \$174 | \$174 |
| L76 | Wire harness tail lamp w/ extended wiring | \$133 | \$133 |
| L77 | Wiring for additional turn signals | \$88 | \$88 |
| L90 | Tail lamp deletion, non-LED <i>not with L22</i> | -\$26 | -\$26 |
| L91 | Pre-wiring LED tail lights <i>not with L22/L90</i> | \$49 | \$49 |
| LA3 | Light sensor for vehicles with alcove <i>not with F49/F61/FV1/LA2/JF1</i> | \$0 | \$0 |
| LB9 | Illuminated front exits | \$93 | \$93 |
| LC4 | Comfort overhead control panel | \$93 | \$93 |
| LV6 | Third brake light pre-wiring | \$32 | \$32 |
| M20 | Speed limitation 65 mph <i>not with MD3</i> | \$60 | \$60 |

| | | 144" 6C | 170" 6C |
|-----|---|---------|---------|
| | | M4CC46 | M4CC76 |
| | | 907.153 | 907.155 |
| M24 | Starter upgraded | \$189 | \$189 |
| MD3 | Top speed limitation 75 mph | \$60 | \$60 |
| | <i>not with M20</i> | | |
| N62 | Front engine bracket for additional alternator | \$467 | \$467 |
| | <i>not with N63</i> | | |
| N63 | Front engine bracket for auxiliary A/C compressor | \$467 | \$467 |
| | <i>not with N62</i> | | |
| P08 | Cover for transport | \$0 | \$0 |
| | <i>must have FW1/X69</i> | | |
| Q18 | End cross member bolted | \$65 | \$65 |
| QA2 | Trailer cross member 7,500 lbs capacity | \$187 | \$187 |
| R65 | Spare tire bracket below frame | \$0 | \$0 |
| | <i>must have Q18; not with Q72/R60/R92</i> | | |
| R91 | Spare tire deletion | -\$110 | -\$110 |
| | <i>must have R92; not with R87/R60</i> | | |
| R92 | Spare tire carrier deletion | \$0 | \$0 |
| | <i>must have R91; not with R65/R60</i> | | |
| R98 | Rims painted jet black | \$81 | \$81 |
| | <i>not with RM2</i> | | |
| RF1 | Tire brand Continental | \$0 | \$0 |
| | <i>not with RD9</i> | | |
| RF8 | Tire brand Michelin | \$0 | \$0 |
| | <i>not with RD9/RF1/RM1</i> | | |
| RM1 | M+S winter tires | \$169 | \$169 |
| | <i>must have RD9/RF1; not with RF8/X31</i> | | |
| RM2 | Rims painted arctic white | \$81 | \$81 |
| | <i>not with X31/R98</i> | | |
| RM9 | Specially requested tires | \$101 | \$101 |
| | <i>must have RF1/RF8; not with RD9</i> | | |
| S23 | Twin front passenger seat | \$400 | \$400 |
| | <i>not with C00/X68/X01</i> | | |
| S28 | Armrest, driver and passenger door | \$51 | \$51 |
| S62 | Seat belts orange, driver and front passenger | \$32 | \$32 |
| | <i>not with S23</i> | | |
| SB9 | Driver's seat plus | \$238 | \$238 |
| | <i>must have FY7</i> | | |
| S27 | Storage net, driver's seat backrest | \$0 | \$0 |
| | <i>must have FW1/X69</i> | | |
| S28 | Storage net, passenger seat backrest | \$0 | \$0 |
| | <i>must have FW1/X69; not with S23</i> | | |
| T75 | Door-mounted assist handles, driver & passenger | \$59 | \$59 |
| V07 | Cab rear wall liner | \$360 | \$360 |
| | <i>not with FW1</i> | | |
| V85 | Cigarette lighter & ash cup, front | \$39 | \$39 |
| VV4 | Additional Ground Weld Studs | \$45 | \$45 |
| | <i>SoP and Plausibility TBD</i> | | |
| X2R | Conversion to RV requirement | - | \$0 |
| | <i>must have B01+E1X</i> | | |
| X93 | Deletion of model badge, right rear door | \$0 | \$0 |
| XM4 | Acoustic package | \$87 | \$87 |
| | <i>standard with C02/C03</i> | | |
| Y10 | First-aid kit | \$27 | \$27 |
| Y26 | Wheel chocks | \$38 | \$38 |
| Y45 | Emergency flashlight | \$27 | \$27 |
| Y68 | Paint preservative | \$88 | \$88 |
| Y69 | Surface protection for stock vehicles | \$292 | \$292 |

| | | 144" 6C | 170" 6C |
|---|------------------------------------|--------------|--------------|
| | | M4CC46 | M4CC76 |
| | | 907.153 | 907.155 |
| C00 | Comfort Package | \$300 | \$300 |
| LC4 | Comfort overhead control panel | X | X |
| SE4 | Lumbar support, co-driver's seat | X | X |
| SE5 | Lumbar support, driver's seat | X | X |
| SK0 | Comfort head restraint, driver | X | X |
| SK1 | Comfort head restraint, co-driver | X | X |
| S28 | Armrest, driver and passenger door | X | X |
| <i>must have C05 OR X68; not with S23</i> | | | |

| | | | |
|----------------------|--|--------------|--------------|
| C05 | Comfort Package (Seat addition) | \$381 | \$381 |
| SB1 | Comfort driver's seat | X | X |
| SB2 | Comfort passenger seat | X | X |
| <i>must have C00</i> | | | |

| | | | |
|---|--|----------------|----------------|
| X68 | Comfort Plus Package | \$1,923 | \$1,923 |
| H15 | Heated front passenger seat | X | X |
| H16 | Heated driver's seat | X | X |
| SF1 | Driver's seat electrically adjustable | X | X |
| SF2 | Co-driver's seat electrically adjustable | X | X |
| <i>must have C00 and VF4 OR VF6; not with S23</i> | | | |

| | | | |
|------------|-------------------------------------|--------------|--------------|
| C01 | Driver Convenience Package | \$323 | \$323 |
| E46 | 12 V power outlet, driver seat base | X | X |
| FJ1 | Hinged lid for storage compartment | X | X |
| FZ9 | Keys, two additional masters | X | X |
| JW8 | Attention Assist | X | X |

| | | | |
|--|--|--------------|--------------|
| C02 | Premium Package | \$983 | \$983 |
| CL3 | Leather steering wheel | X | X |
| E3M | MBUX Multimedia System with 7" touchscreen | X | X |
| FM3 | Wet Wiper System | X | X |
| JB4 | Active Lane Keeping Assist | X | X |
| JK5 | Instrument cluster with color display | X | X |
| <i>Ordering availability restricted, see NetStar for availability and restrictions/must have (JF1/LA3) + XM4</i> | | | |

| | | | |
|--|---------------------------------------|--------------|--------------|
| CA2 | C02 in combination with C03 | \$604 | \$604 |
| CL3 | Leather steering wheel | X | X |
| FM3 | Wet Wiper System | X | X |
| JB4 | Active Lane Keeping Assist | X | X |
| JK5 | Instrument cluster with color display | X | X |
| <i>Ordering availability restricted, see NetStar for availability and restrictions/must have C03 + JF1</i> | | | |

| 144" 6C | 170" 6C |
|---------|---------|
| M4CC46 | M4CC76 |
| 907.153 | 907.155 |

| | | | |
|---------------------------------------|--|----------------|----------------|
| C03 | Premium Plus Package | \$1,793 | \$1,793 |
| E1B | Tray for smartphones incl. wireless charging | X | X |
| | Navigation | X | X |
| EY2 | Intelligent navigation | X | X |
| E4M | MBUX Multimedia System with 10.25" touchscreen | X | X |
| EX9 | Free map data updates for 3 years | X | X |
| H1I | Front-to-rear outlet in instrument panel | X | X |
| JA9 | Traffic Sign Assist | X | X |
| XM4 | Acoustic package | X | X |
| <i>must have CA2 OR (JB4+JK5+FM3)</i> | | | |












| | | | |
|------------------------|---|--------------|--------------|
| X67 | Chrome Grille Package | \$290 | \$290 |
| CN2 | Radiator grille frame in vehicle color | X | X |
| FK3 | Chrome plated radiator grille (MB only) | X | X |
| <i>no restrictions</i> | | | |












| | | | |
|------------------------|--|----------------|----------------|
| X13 | Exterior Lighting Package | \$1,608 | \$1,608 |
| L13 | Fog lamp with cornering light function | X | X |
| L22 | Partial LED tail lights | X | X |
| LA1 | High beam assist | X | X |
| LG7 | LED high performance headlamps | X | X |
| <i>no restrictions</i> | | | |

| | | | |
|---|--------------------------------------|--------------|--------------|
| X69 | Swivel Seat Package | \$587 | \$587 |
| SR8 | Swivel base for driver's seat | X | X |
| SR9 | Swivel base for front passenger seat | X | X |
| S87 | Driver's seat frame, low | X | X |
| S88 | Passenger seat frame, low | X | X |
| FW1 | Rear wall deletion, chassis cab | X | X |
| BE2 | Handbrake lever, folding | X | X |
| <i>must have (C00+C05) OR (C00+X68)</i> | | | |

| | | | |
|---------------------------------|--|--------------|--------------|
| X01 | Suspension Seating Package | \$940 | \$940 |
| SB3 | Driver suspension seat, comfort version | X | X |
| SB4 | Passenger suspension seat, comfort version | X | X |
| S87 | Driver's seat frame, low | X | X |
| S88 | Passenger seat frame, low | X | X |
| <i>not with C00/C05/X68/S23</i> | | | |

Exterior Paint Overview

| Code | Description | Price | Paint |
|------|-------------------------|---------|---|
| 1243 | Calcite yellow | \$675 |  |
| 3432 | Sunset red | \$675 |  |
| 3583 | Velvet red | \$0 |  |
| 3589 | Jupiter red | \$0 |  |
| 5362 | Brilliant blue | \$675 |  |
| 5389 | Steel blue | \$0 |  |
| 5524 | Black 'blue | \$1,070 |  |
| 5890 | Cavansite blue metallic | \$1,070 |  |
| 5957 | Vanda blue | \$675 |  |
| 6830 | Aqua green | \$0 |  |
| 7160 | Stone grey | \$675 |  |


| Code | Description | Price | Paint |
|------|-------------------------|---------|---|
| 7701 | Pebble grey | \$0 |  |
| 7224 | Graphite grey | \$675 |  |
| 7708 | Silver grey | \$675 |  |
| 7709 | Blue grey | \$0 |  |
| 7755 | Tenorite grey metallic | \$1,070 |  |
| 7992 | Selenite grey metallic | \$1,070 |  |
| 9040 | Jet black | \$1,070 |  |
| 9136 | Grey white | \$675 |  |
| 9147 | Arctic white | \$0 |  |
| 9197 | Obsidian black metallic | \$1,070 |  |
| 9775 | Iridiumsilver | \$1,070 |  |

Please see NetStar for latest paint availability information.

Upholstery

Standard

VF7
Fabric
Maturin Black Upholstery



Optional

VF4
Fabric
Caluma Black Upholstery


| Upcharge | |
|---------------|--------|
| Cargo | \$ 60 |
| Cab Chassis | \$ 60 |
| Crew Van | \$ 205 |
| Passenger Van | \$ 430 |



Optional

VF6
Leatherette
Black


| Upcharge | |
|---------------|--------|
| Cargo | \$ 60 |
| Cab Chassis | \$ 60 |
| Crew Van | \$ 205 |
| Passenger Van | \$ 430 |



Seat restrictions

| Code | Seat | Fabrics | | |
|---------|----------------------|---------|-----|-----|
| | | VF7 | VF4 | VF6 |
| | Standard Seats Front | S | O | O |
| | Standard Seats Rear | S | n/a | O |
| SF1/SF2 | Power Seats | n/a | O | O |
| SB1/SB2 | Comfort Seats Front | S | O | O |
| | Comfort Seats Rear | n/a | O | O |

Front and rear fabric always have to match.



Suspension Matrix

| Cargo Van / Crew Van | | | | | |
|----------------------|--|---|------|--------|-----------|
| Standard | 1500 | 2500 | 3500 | 3500XD | 4500 |
| | Base Suspension | | CB8 | | CB8 + A50 |
| Options | A50 | | | | - |
| | CB1 (add to standard) | | - | | |
| | CB7 (moved to option) | | - | | |
| | CB8 (replacing standard) | | S | | |
| | - | CB4 (Recommended for RV) - only 6cyl Diesel | | | |
| | CT1 | | - | | |
| Specialized Options | CE8 (not with 4x4 models) | | | | |
| | B01 (not with 3500/3500XD/4500 144"WB) | | | | |
| | X2R (not with 3500/3500XD/4500 144"WB) | | | | |

| Passenger | | | |
|-----------|-----------------------------|---------|-----------------------------------|
| Standard | 1500 | 2500 | |
| | 144" WB | 144" WB | 170" WB |
| | Base Suspension + CB1 + CT1 | | Base Suspension + CB1 + CT1 + A50 |

| Cab Chassis | | |
|---------------------|-----------------------------------|-----------|
| Standard | 3500XD | 4500 |
| | CB8 | CB8 + A50 |
| Options | CB4 | |
| | A50 | - |
| Specialized Options | CE8 (not on 144"WB models) | |
| | B01 (not with 3500XD/4500 144"WB) | |
| | X2R (not with 3500XD/4500 144"WB) | |

Suspension Details

| Standard Suspensions and Options | | | |
|----------------------------------|--|--|--|
| Code | Title | Details | |
| A50 | Front axle reinforced | Includes an increased load capacity of the front axle, where heavier bodies and equipment can be fitted. The higher capacity front axle caters to heavier cabs and heavier special equipment (e.g. for fire-fighting vehicles and ambulances). | |
| No Factory Code | Base Standard Factory Suspension | Description | Ride comfort due to reduced roll stabilization. |
| | | Benefit | The Base Standard Factory suspension, has an adapted front suspension for a lower and more comfortable entry. With the removal of the rear stabilization bar it allows for an overall comfortable ride with reduced roll. |
| CB7 | Stabilization Level I | Description | Roll Stabilization with height body damping |
| | | Benefit | CB7 compensates for rolling behavior due to higher center of gravity of loads or bodies. Torsion bars with an increased diameter are added to the front and rear axels. Furthermore, shock absorbers with an adapted characteristic are installed. |
| CB8 | Stabilization Level II | Description | Enhanced roll stabilization with higher body damping compared to CB7 |
| | | Benefit | Additional roll stabilization and body damping compared to CB7. Increases torsion bar diameters at the front and rear axles and provides an adapted shock absorber characteristic. Furthermore, rear axle springs with increased rigidity are installed. |
| CB4 | Stabilization Level III | Description | Designed for vans with a intense rolling behavior due to a much heavier load and higher center of gravity. (i.e. recreational vehicles) |
| | | Benefit | CB4 comes with larger diameter stabilizers, shock absorbers and with characteristics that are adapted for an increased rebound and compression curve. Furthermore, the leaf springs are increased in rigidity. |
| CB1 | Suspension for comfort and load protection | Enhanced comfort due to adapted damper characteristics and the use of progressive spring characteristics. | |
| CT1 | Rear spring vibration absorbers | Includes vibration absorbers fitted on the left and right rear spring and lowers the resonant vibrations of the rear springs, thus hindering noise development. | |

| Specialized Suspension Options | | | |
|--------------------------------|-------------------------------------|--|--|
| Code | Title | Explanation | |
| CE8 | Raised rear body mounts | Raised body on rear axle (35mm/1.4") | |
| B01 | ESP for increased Center of Gravity | Description | Adjusted braking and handling characteristics for vehicles with increased center of gravity. |
| | | Benefit | With code B01, the ESP® is optimized to reduce the vehicles tilt tendency with a total center of gravity of <u>more than 1000 mm (39.4 inches)</u> . It is essential to ensure that the vehicle is equipped with the right suspension and tires. With B01 it is required to also add CB8 or CB4. |
| X2R | Conversion to RV requirement | MBUX Timed Switch-off extended to 6 hours and B01 is automatically added to this code. | |

Rear view camera/head unit plausibility

| CA/PV/CV | | | | | |
|-------------------|---------------------------|-----------------|-------------------|------------------------------|------------------------------|
| | Standard | Option A | Option A + JB7 | Option A + JB6 | Option A + JB8 |
| Radio/HU | E10 | E3M/E4M | E3M/E4M | E3M/E4M | E3M/E4M |
| Camera | FR3 | FR8 | integrated camera | integrated 360 degree camera | integrated 360 degree camera |
| Pre-wiring Camera | n/a | n/a | n/a | n/a | n/a |
| Camera Display | Interior rear view mirror | 7/10.25" Screen | 7/10.25" Screen | 7/10.25" Screen | 7/10.25" Screen |

Options shown above lead to an upcharge.

| CC | | | |
|--------------------|----------|---------------------------|----------------------------------|
| | Standard | Option A | Option B |
| Radio/HU | E10 | E10 | E3M/E4M |
| After-Sales Camera | - | Any analog* Camera | Mercedes-Benz Camera** (digital) |
| Pre-wiring | - | FV1 | FR7 |
| Rear-View Display | - | Interior rear view mirror | 7/10.25" Screen |

Options shown above lead to an upcharge.

*only cameras with analog signal works

**only the Mercedes-Benz rear view camera works (digital signal)

Cargo Van Floor Variations

| | | |
|----------|-----|------------------------------------|
| Standard | V93 | Without factory installed flooring |
| Options | V43 | Wood floor with 6 D-rings |
| | VK8 | Floor covering, plastic |

Note: see restrictions in combination with metallic paint

Special Rule for cargo vans with metallic paint

| | | |
|------------------|--------------------------|--|
| Paint Code | 5890/7755/7992/9197/9775 | |
| Must have one of | V43 | Wood floor with 6 D-rings |
| | VK8 | Floor covering, plastic |
| | ZZ9 | No floor covering; requires customer floor installation |
| | | Package contains: V93 - No factory installed flooring VL4 - Metallic painted floor |

Note: Fleet only

Additional comments ZZ9 Package

While applying the required clear coat layer to the metallic painted cargo floor, imperfections could occur. Therefore, we strongly recommend to install flooring in the cargo area for vehicles with a metallic paint.

Please be aware that potential paint appearance, contamination or imperfections of the uncovered cargo floor are not considered a defect and are therefore not reimbursable for repairs.

Tire & Wheel Overview

| | | 1500/2500 Models | | |
|-----|-------------------------|----------------------|---------------|-------------|
| | | Standard Tire | RH8 | Single tire |
| | | Standard Wheel | RS3 | Steel |
| | | Optional Wheel | RL5 | Alloy |
| | | Brand Options | | |
| | | RM0 All-season tires | RM1 M+S tires | |
| RD9 | Tire brand, unspecified | S | O | |
| RF8 | Michelin | O | n/a | |
| RF1 | Continental | n/a | O | |
| RH0 | Kumho | O | n/a | |

To order any of the tire brands above code RM9 has to be added to order.

| 3500/3500XD Models | | | | | |
|---------------------------|-------------------------|---------------|-----|------------------------|---------------|
| Standard: Dual Rear Wheel | | | | Optional: Super Single | |
| Standard Tire | | RH7 | | Standard Tire | R9A |
| Standard Wheel | | RS6 | | Standard Wheel | RS5 |
| Brand Options | | | | Brand Options | |
| RM0 All-season tires | | RM1 M+S tires | | RM0 All-season tires | RM1 M+S tires |
| RD9 | Tire brand, unspecified | O | O | S | n/a |
| RF8 | Michelin | O | n/a | n/a | n/a |
| RF1 | Continental | O | O | O | n/a |
| RH0 | Kumho | n/a | n/a | n/a | n/a |

To order any of the tire brands above code RM9 has to be added to order.

Standard is DRW, Option is Super Single

| | | 4500 Models | | Dual Rear Wheel Steel |
|-----|-------------------------|----------------------|---------------|--------------------------|
| | | Standard Tire | RH7 | |
| | | Standard Wheel | RS6 | |
| | | Brand Options | | |
| | | RM0 All-season tires | RM1 M+S tires | |
| RD9 | Tire brand, unspecified | S | O | |
| RF8 | Michelin | O | n/a | |
| RF1 | Continental | O | O | |
| RH0 | Kumho | n/a | n/a | |

To order any of the tire brands above code RM9 has to be added to order.