Color AND OPTION PRICING FOR All Model. M2CA46 - M2CA7X

Exterior Paint Overview

Code	Description	Price	Paint	Code	Description	Price	Paint
1243	Calcite yellow	\$675		7701	Pebble grey	\$0	
3432	Sunset red	\$675	0_0	7224	Graphite grey	\$675	000
3583	Velvet red	\$0	0 - 0	7708	Silver grey	\$675	0 0
3589	Jupiter red	\$0	0_0_	7709	Blue grey	\$0	0=0
5362	Brilliant blue	\$675	0-0	7755	Tenorite grey metallic	\$1,070	0-0-
5389	Steel blue	\$0	0 -0	7992	Selenite grey metallic	\$1,070	
5524	Black blue	\$1,070	0_0	9040	Jet black	\$1,070	0_0_
5890	Cavansite blue metallic	\$1,070	0-0-	9136	Grey white	\$675	0=0
5957	Vanda blue	\$675	0=0-	9147	Arctic white	\$0	
6830	Aqua green	\$0		9197	Obsidian black metallic	\$1,070	0_0_
7160	Stone grey	\$675		9775	Iridiumsilver	\$1,070	
	letStar for latest paint availability						

Please see NetStar for latest paint availability information.

Upholstery

Standard

VF7

Fabric

Maturin Black Upholstery



Optional

VF4

Fabric

Caluma Black Upholstery

Upcharge				
Cargo	\$	60		
Cab Chassis	\$	60		
Crew Van	\$	205		
Passenger Van	\$	430		



Optional

VF6

Leatherette

Black


Upcharge				
Cargo	\$	60		
Cab Chassis	\$	60		
Crew Van	\$	205		
Passenger Van	\$	430		




Seat restrictions

			Fabrics		
Code	Seat VF7		VF4	VF6	
	Standard Seats Front	S	0	0	
	Standard Seats Rear	S	n/a	0	
SF1/SF2	Power Seats	n/a	0	0	
SB1/SB2	Comfort Seats Front	S	0	0	
	Comfort Seats Rear	n/a	0	0	

Front and rear fabric always have to match.





Suspension Matrix

	(Cargo Van	/ Crew Va	ın			
Standard	1500	2500	3500	3500XD	4500		
Stanuard	Base Suspension			C88	CB8 + A50		
SAMPLE		-	A50		-		
Options	CB1 (add to st	andard)	<u> </u>				
	CB7 (moved to	option)					
Options	CB8 (replacing standard)		S				
	- CB4 (Recommended for RV) - only 6cyl Diesel			/ Diese			
C. Party Co.	CT1 -						
Specialized	CE8 (not with 4x4 models)						
THE PERSON AS	BO1 (not with 3500/3500XD/4500 144"WB)						
Options		X2R (not with 3500/3500XD/4500 144"WB)					

		Passenger	
	1500	250	0
Standard	144" WB	144" WB	170" WB
	Base Suspen	sion + CB1 + CT1	Base Suspension + CB1 + CT1 + A50

	Cab Chassis	HE DELEGATION OF THE PARTY OF T		
Standard	3500XD	4500		
Standard	CB8	CB8 + A50		
Ontions	CB4			
Options	A50	-		
	CE8 (not on :	44"WB models)		
Specialized Options	BO1 (not with 3500XD/4500 144"WB)			
	X2R (not with 3500XD/45	500 144"WB)		

Suspension Details

			Standard Suspensions and Options	
Code	Title		Détails	
A50	Front axle reinforced	Includes an in- axle caters to	creased load capacity of the front axle, where heavier bodies and equipment can be fitted. The higher capacity front heavier cabs and heavier special equipment (e.g. for fire-fighting vehicles and ambulances).	
		Description	Ride comfort due to reduced roll stabilization.	
No Factory Code	Base Standard Factory Suspension	Benefit	The Base Standard Factory suspension, has an adapted front suspension for a lower and more comfortable entry. With the removal of the rear stabilization bar it allows for an overall comfortable ride with reduced roll.	
		Description	Roll Stabilization with height body damping	
CB7 Stabilization Level I	Benefit	CB7 compensates for rolling behavior due to higher center of gravity of loads or bodies. Torsion bars with an increased diameter are added to the front and rear axels. Furthermore, shock absorbers with an adapted characteristic are installed.		
		Description	Enhanced roll stabilization with higher body damping compared to CB7	
CB8 Stabilization Level II		Benefit	Additional roll stabilization and body damping compared to CB7. Increases torsion bar diameters at the front and rear axles and provides an adapted shock absorber characteristic. Furthermore, rear axle springs with increased rigidity are installed.	
CB4	Stabilization Level III	Description	Designed for vans with a intense rolling behavior due to a much heavier load and higher center of gravity. (i.e. recreational vehicles)	
C84	Stabilization Level (II		CB4 comes with larger diameter stabilizers, shock absorbers and with charateristics that are adapted for an increased rebound and compression curve. Furthermore, the leaf springs are increased in rigidity.	
CB1	Suspension for comfort and load protection	Enhanced comfort due to adapted damper characteristics and the use of progressive spring characteristics.		
CT1	Rear spring vibration absorbers	Includes vibration absorbers fitted on the left and right rear spring and lowers the resonant vibrations of the rear springs, thus hindering noise development.		

Specialized Suspension Options						
Code	Title		Explanation			
CE8	Raised rear body mounts	Raised body o	Raised body on rear axle (35mm/1.4")			
		Description	Adjusted braking and handling characteristics for vehicles with increased center of gravity.			
B01	ESP for increased Center of Gravity	Benefit	With code B01, the ESP® is optimized to reduce the vehicles tilt tendency with a total center of gravity of more than 1000 mm (39.4 inches). It is essential to ensure that the vehicle is equipped with the right suspension and tires. With B01 it is required to also add CB8 or CB4.			
X2R	Conversion to RV requirement	MBUX Timed S	Switch-off extended to 6 hours and B01 is automatically added to this code.			

Rear view camera/head unit plausibility

		CA/	PV/CV		
	Standard	Option A	Option A + JB7	Option A + JB6	Option A + JB8
Radio/HU	E10	E3M/E4M	E3M/E4M	E3M/E4M	E3M/E4M
Camera	FR3	FR8	integrated camera	integrated 360 degree camera	integrated 360 degree camera
Pre-wiring Camera	n/a	n/a	n/a	n/a	n/a
Camera Display	Interior rear view, mirror	7/10.25" Screen	7/10.25" Screen	7/10.25" Screen	7/10.25" Screen

Options shown above lead to an upcharge.

	CC					
	Standard	Option A	Option B			
Radio/HU	E10	E10	E3M/E4M			
After-Sales Camera	-	Any analog* Camera	Mercedes-Benz Camera** (digital)			
Pre-wiring	-	FV1	FR7			
Rear-View Display		Interior rear view				
		mirror	7/10.25" Screen			

Options shown above lead to an upcharge.

Cargo Van Floor Variations

Standard	. V93	Without factory installed flooring
Options	V43	Wood floor with 6 D-rings
	VK8	Floor covering, plastic

Note: see restrictions in combination with metallic paint

Special Rule for cargo vans with metallic paint

Paint Code		5890/7755/7992/9197/9775
	V43	Wood floor with 6 D-rings
	VK8	Floor covering, plastic
		No floor covering; requires customer
Must have one of		floor installation
	779	Package contains:
		V93 - No factory installed flooring
		VL4 - Metallic painted floor

Note: Fleet only

Additional comments ZZ9 Package

While applying the required clear coat layer to the metallic painted cargo floor, imperfections could occur. Therefore, we strongly recommend to install flooring in the cargo area for vehicles with a metallic paint.

Please be aware that potential paint appearance, contamination or imperfections of the uncovered cargo floor are not considered a defect and are therefore not reimbursable for repairs.

^{*}only cameras with analog signal works

^{**}only the Mercedes-Benz rear view camera works (digital signal)

Tire & Wheel Overview

		1500/250	0 Models
		Standard Tire	RH8
		Standard Wheel	RS3
		Optional Wheel	RL5
		Brand O	ptions
		RM0 All-season tires	RM1 M+S tires
RD9	Tire brand, unspecified	S	0
RF8	Michelin	. 0	n/a
RF1	Continental	n/a	0
RHO	Kumho	0	n/a

Single tire Steel Alloy

To order any of the tire brands above code RM9 has to be added to order.

			3500/3500XD Mode
		Standard: Du	ial Rear Wheel
		Standard Tire	RH7
	•	Standard Wheel	RS6
		Brand	Options
		RM0 All-season tires	RM1 M+S tires
RD9	Tire brand, unspecified	0	0
RF8	Michelin	0	n/a
RF1	Continental	0	0
RHO	Kumho	n/a	n/a

е	I-To Receive and Company	4 4 4
	Optional: Sup	er Single
	Standard Tire	R9A
	Standard Wheel	RS5
	Brand Opt	ions
	RM0 All-season tires	RM1 M+S tires
	S	n/a
	n/a	n/a
	0	n/a
	n/a	n/a

To order any of the tire brands above code RM9 has to be added to order.

Standard is DRW, Option is Super Single

	4500 M	lodels
	Standard Tire	RH7
	Standard Wheel	RS6
	Brand O	ptions
	RMO All-season tires	RM1 M+S tires
Tire brand, unspecified	S	0
Michelin	0	n/a
Continental	0	0
Kumho	n/a	n/a
	Michelin Continental	Standard Tire Standard Wheel Brand O RMO All-season tires Tire brand, unspecified S Michelin O Continental O

Dual Rear Wheel Steel

To order any of the tire brands above code RM9 has to be added to order.

2500 CARGO VAN - GAS Standard Equipment

144" G	170" G
M2CA4G	M2CA7G
907.643	907.645

		907.643	907.645
Engine			
Gas Er	ngine/ 9-Speed Trans.	S	S
ED4	AGM battery 12V 92 AH 850 A	S	S
G43	Automatic transmission, 9G-tronic	S	S
V160	Alternator 14 V / 250 A	S	\$
MM3	2.0L 4-cylinder turbo gasoline engine	S	S
MH8	SULEV emissions	S	S
Equipr	nent		
AR3	Axle ratio 4.182	S	S
ВАЗ	Active Brake Assist	S	S
вн1	Hold Function	S	5
C6L	Multifunction steering wheel	S	S
CL1	Adjustable steering wheel (angle)	S	S
D03	High roof		S
D93	Omission bulkhead	S	\$
E07	Hill Start Assist	S	S
E10	Standard radio	S	5
E1U	USB-C socket, 5 V	S	S
E30	Starter battery disconnect	S	S
E3J	Pre-installation for switch panel	S	S
E40	Trailer hitch prep. wiring	S	S
ED8	Preinstallation PSM	S	S
EE5	Ultracapacitor discharge module	S	S
EK1	Body Builder Connector	S	S
ESO	Jump start terminal	S	5
EW6	Pre-installation for Mercedes me Remote Services	S	S
EY5	Emergency Call System	S	S
EY6	Breakdown management	S	S
F68	Heated & electrically adjustable exterior mirrors	S	S
FF5	Shelf above windshield	S	S
FG8	Cupholder front	S	S
FI1	Remote key (315 mhz) w/central locking	S	S
FJ4	Storage compartment underneath cockpit	S	S
FR3	Rear view camera (rear-view mirror display)	S	S
H21	Windshield with filter band	S	\$
HH2	Heater, auxiliary electric hot air	S	S
нн9	Air Condition, Front	S	S
H7	Head Unit, North America	S	S
11	Speedometer, miles and km/h	S	S
1W	Service Interval 1 year	S	S
155	Seat belt warning for co-driver seat	S	S
158	Seat belt reminder driver	S	5
165	Outside temperature gauge	S	S
JA8	Crosswind Assist	S	S
H3	Communication module (LTE) for dig. services	S	S
18	Service interval 15.000 miles	S	S
<14	22 gallon fuel tank	S	S
K60	Exhaust straight to rear	S	S
.65	Interior lights, cargo compartment	S	S
.94	Parking lights deletion	S	S
.A2	Headlight assistant	S	S
.B5	3rd brake light	S	\$
MS1	Cruise control	S	S
P47	Front mudflaps	S	S

Standard Equipment

		144" G	170" G M2CA7G
		M2CA4G	
		907.643	907.645
P48	Rear mudflaps	S	S
Q11	Longitudinal member reinforcement	S	S
R65	Spare tire bracket below frame	S	S
R87	Spare tire	S	S
RH8	Tires LT 245/75 R16	S	S
RM0	All-season tires	S	S
RD9	Unspecified tire brand	S	S
R\$3	6.5 J x 16 steel wheels	S	S
RY2	Tire pressure monitoring sensors	S	S
S02	Standard driver seat	S	S
S04	Standard front passenger seat	S	S
S22	Armrest for driver's seat	S	S
S25	Armrest for front passenger seat	S	S
SA5	Front airbag, driver	S	S
SA6	Front airbag, passenger	S	S
SH1	Thorax-pelvis sidebag, driver	S	S
SH2	Thorax-pelvis sidebag, co-driver	S	5
SH9	Airbag, driver/passenger window	S	S
SK2	Seat occupancy sensor, driver's seat	S	S
T16	Sliding door, passenger side	S	S
V93	Without factory installed flooring	S	S
V94	Cable duct - side wall	S	S
V95	Cable duct - rear portal	S	S
XL2	GVWR 9,050 lbs. / 4.100 Kg	S	S
Y43	Jack, hydraulic	S	S

		144" G M2CA4G	170" G M2CA7G
		907.643	907.645
A50	Front axle reinforced	\$346	\$346
AP2	Addtl. bar for driveshaft & exhaust extension	\$69	\$69
B01	ESP for increased Center of Gravity above 39.4"	\$0	\$0
	must have CB4/CB8/X30; not with RH0/CB7		, ,
B25	Electric parking brake	\$279	\$279
-	not with BE2; X69 choose B25/BE2	V 2.73	,
BE2	Handbrake lever, folding	\$55	\$55
	not with B25; X69 choose B25/BE2	433	403
C72	Bumpers front/rear primed	\$268	\$268
., .	must have CN2 (part of X67), not with CM0	7200	9200
CB1	Suspension for comfort and load protection	\$241	\$241
CB7	Stabilization Level I	\$307	\$307
00/		\$507	\$307
CDO	not with CB4/CB8/X30	(777	¢722
CB8	Stabilization Level !!	\$723	\$723
CER	not with CB1/CB4/CB7/X30	ćara.	cara
CE8	Raised rear body mounts	\$252	\$252
CL3	Leather steering wheel	\$187	\$187
	must have (CO2/E3M)/CO3 + (ET4/MS1)	1 4505	4500
CM0		\$587	\$587
	must have (CN2/X67) + (JA7/C01) + (JB6/JB7) + (7755/9197/9775)	,	
	Primed side moldings	\$364	\$364
CT1	Rear spring vibration absorbers	\$138	\$138
D03	High roof	\$2,900	S
D13	Mounting rails for roof rack	\$300	\$300
D22	Fixed sunroof (rear roof section)	\$336	\$336
	not with H08/HK4/H72/V36/ZK4		
D50	Cargo partition	\$288	\$288
	not with D51/D93/H08/HK4/T74/V36; must have one of T93/T77		
051	Cargo partition with 1 window	\$335	\$335
	not with D50/D93/H08/HK4/T74/V37/D17; must have one of T93/T7	77	
E1B	Tray for smartphones incl. wireless charging	\$156	\$156
	must have CO2/E3M + H1I		
1E	Navigation	\$728	\$728
	must have CO2/E3M, not with CO3		
E1S	Sirius XM, satellite radio	\$255	\$255
	must have CO2/E3M/CO3		
E1R	Additional Fuses (40/80/150/100 Ampere)	\$50	\$50
	SoP and Plausibility TBD		
E1Y	Additional Fuses (40/80/80/100 Ampere)	\$50	\$50
	SoP and Plausibility TBD	- Aria-	
2A -	Access point for BB special signals in cockpit	\$29	\$29
E21	Additional battery, co-driver seat base	\$248	\$248
	must have E36/C06; not with E2M/F09; CHS production only	1	, , , ,
E2M	Additional battery, engine compartment	\$248	\$248
	must have X01+ (E36/C06); not with E2I/X69/F09	72.10	72.0
E3M	MBUX Multimedia System with 7" touchscreen	\$474	\$474
20101	not with CO2/CO3; must have JK5+(JB7/JB6/JB8/FR8)	1 7	7171
E36	Cutoff relay for additional battery	\$110	\$110
.00	standard with E2I/E2M	ŞIIO	3110
-40		602	ćna
E46	12 V power outlet, driver seat base	\$92	\$92
E5M	Extension of PSM standard contact	\$58	\$58
ED5	Parametric special module (PSM)	\$317	\$317
	not with ED8	4:	4.0-
EE3	115 V socket	\$125	\$125

		144" G	170" G M2CA7G
		M2CA4G	
		907.643	907.645
EP7	Basic electric fitting for rear loudspeakers	\$68	\$68
S2	12 V power outlet, rear compartment	\$92	\$92
S 5	Charging package, dashboard	\$82	\$82
ET4	Active Distance Assist DISTRONIC	\$263	\$263
	must have CO2/CO3/E3M; not with ZH4		
1K	Coat hooks in driver cabin	\$14	\$14
	must have D50/D51		
49	Electrically heated windshield	\$218	\$218
	no restriction		
61	Interior rear view mirror	\$36	\$36
	not with D50; must have C02/E3M/C03		
64	Electrically folding exterior mirrors	\$49	\$49
E9	Additional DIN-slot	\$81	\$81
F8	Overhead storage slot, front center	\$105	\$105
-J1	Hinged lid for storage compartment	\$93	\$93
R8	Rear view camera (head unit display)	\$336	\$336
	must have CO2/E3M; not with FR3/JB7/JB6/JB8	4330	7550
Y1	Security alarm w. interior motion sensor	\$584	\$584
	must have LC4/C00	7504	7504
-Y7	Optional 3-button keys	\$36	\$36
-Z9	Keys, two additional masters.	\$121	\$121
H00	Warm/cool air duct to rear compartment	\$59	\$59
100	not with D50/D51/Y2A	200	223
H01	Heat insulation, rear compartment	\$156	\$156
101	must have V21/V25/VA3/VA1/C07/X66	\$120	2130
H04	Heat insulation, front compartment	\$187	\$187
104	if + D50/D51 must have V07	2101	2101
100		¢2.072	ć1 071
408	Air conditioning rear, roof-mounted	\$2,872	\$2,872
112	must have D93 +V36; not with HK4/C06/X66/C07	6700	ė=oc
113	Rear cabin heater and vents	\$786	\$786
11 5	must have H12/HZ9	¢204	ć204
115	Heated front passenger seat	\$284	\$284
10.0	must have H16; not with X68	(204	6204
116	Heated driver's seat	\$284	\$284
inn	must have H15; not with X68	1 4000 1	4000
122	Rear window defroster	\$253	\$253
	must have W61/W78; standard for W61+W70	1 4	4.00
172	Roof fan, electric	\$400	\$400
	not with D22/V36		
188	Rear heater prep	\$405	\$405
	must have H12/HZ9; not with H13/T19		
111	Front-to-rear outlet in instrument panel	\$0	\$0
OFFICE OF	must have FJ1/C01	T	
1H4	Thermotronic automatic climate control	\$337	\$337
	must have JF1; if +H13 must have H08/HK4		
A7	Blind Spot Assist	\$450	\$450
	must have F64; not with C01		
B4	Active Lane Keeping Assist	\$288	\$288
	standard with CO2/CA2		
В6	Parking Package with 360 degree camera	\$775	\$775
	must have CO2/CO3/E3M; not with W75/W76/JB7		
D 7	Parking Package	\$615	\$615
IB7	must have CO2/CO2/E2AA, not with M7E/M7C/IDC		
В/	must have CO2/CO3/E3M; not with W75/W76/JB6		
B8	360 Degree Camera	\$685	\$685
		\$685	\$685

		144" G	17,0" G
		M2CA4G	M2CA7G
		907.643	907.645
JK5	Instrument cluster with color display	\$144	\$144
	standard with CO2/CA2		
JW0	Backup alarm	\$99	\$99
JW2	Deactivation lamp monitoring failure	\$27	\$27
JW8	Attention Assist	\$49	\$49
L13	Fog lamp with cornering light function	\$199	\$199
L71	Light/motion sensor in rear compartment	\$54	\$54
	not with V36		
LB9	Illuminated front exits	\$151	\$151
LC2	LED light strip in load compartment	\$263	\$263
	not with H08/HK4/V36/C06		
LC4	Comfort overhead control panel	\$93	\$93
M20	Speed limitation 65 mph	\$60	\$60
	not with MD3		
MD3	Top speed limitation 75 mph	\$60	\$60
	not with M20		
P93	Omission of D-rings	-\$15	-\$15
	not with D93/V43/VK8		
Q24	Trailer hitch, 5,000 lbs	\$147	\$147
	not with W73/W75/W76		
QA9	Half-sided step rear (for trailer hitch)	\$101	\$101
	must have Q24/QA2; not with W73/W75/W76		
R91	Spare tire deletion	-\$110	-\$110
	must have R92; not with R87		
R92	Spare tire carrier deletion	\$0	\$0
	must have R91; not with R65		
R98	Rims painted jet black	\$81	\$81
	not with RL5/RM2		
RF1	Tire brand Continental	\$0	\$0
	must have RM1 + RM9		
RF8	Tire brand Michelin	\$0	\$0
	must have RM9; not with RM1		
RHO	Tire brand Kumho	\$0	\$0
	must have RM9; not with RM1		
RL5	Light-alloy wheels 6.5 J x 16	\$906	\$906
	not with RS3/RM2/R98	7000	1000
RM1	M+S winter tires	\$169	\$169
	must have RF1/RD9; not with RF8/RH0/X31		
RM2	Rims painted arctic white	\$81	\$81
	not with R98/RL5		
RM9	Specially requested tires	\$101	\$101
	must have RF1/RF8/RH0; not with RD9	7.55	7
523	Twin front passenger seat	\$400	\$400
0113	not with C00/X68/X01	V100	V 100
S28	Armrest, driver and passenger door	\$51	\$51
562	Seat belts orange, driver and front passenger	\$32	\$32
	not with 523	702	452
589	Driver's seat plus	\$238	\$238
	must have VF7; not with COO/X68/X69	7250	₩ 230
SZ7	Storage net, driver's seat backrest	\$64	\$64
SZ8	Storage net, passenger seat backrest	\$64	\$64
T12	Sliding door two stage opening	\$82	\$82
112	not with T55	\$02	204
T19	Sliding door, driver's side	\$935	\$935
172	not with H13/H88/VC5/ZE6/F43/W16/F02; if +V36 must hav		2233

		144" G	170" G M2CA7G
		M2CA4G	
		907.643	907.645
r50	Electric closing assist right sliding door	\$335	\$335
	must have D03; not with T55/T93		
51	Electric closing assist left sliding door	\$335	\$335
	must have T19 + D03		
r 5 5	Electric sliding door right	\$831	\$831
	must have D03 + (FY7+T16); not with T12/T50		
۲ 5 7	Electric sliding step	\$1,071	\$1,071
	must have ED5; not with T93		
T60	Opening limiter electrically operated sliding door	\$120	\$120
	must have T55		
74	Assist handle, B-pillar	\$32	\$32
	must have D93; not with T77		
75	Door-mounted assist handles, driver & passenger	\$59	\$59
77	Assist handle w/ partition	\$32	\$32
	must have D50/D51/D64	VOII.	, , , , , , , , , , , , , , , , , , ,
185	Assist handle, left rear door	\$32	\$32
186	Assist handles, right rear door	\$32	\$32
793	Sliding door right side deletion	\$0	\$0
	not with T16/T50/T57/VK8/VC5	70	ŲΨ
/07	Cab rear wall liner	\$360	\$360
	must have (D50/D51)+F1K; standard with H04	\$300	\$300
v21	Luxury interior Trim	¢cc3	¢661
V Z I		\$661	\$661
ini	must have VA5/VA7; not with V52/VA1/VA3	¢oc l	¢oc.
V24	Pallet support in sliding door step	\$96	\$96
105	must have (V43/X66)+(D50/D51); not with VK8/V93/C07	4004	4004
V25	Half height load compartment trim	\$201	\$201
	not with VA1/VA3/VA5/V52/X66	Terr 1212	20163625
V31	Window pillar trim	\$513	\$513
1	must have V36 + (V21/VA1) + (F02/F03/F07); not with V42		
V35	Wheel house covering	\$105	\$105
	if +V43 must have V25/VA1/VA3; not with V52		
/36	Roof trim	\$876	\$876
	must have D93; not with D17/D22/H72/L65/L71/LC2/VA3/V42/ZE6/(T93		
/42	Lashing rails, waist level	\$277	\$277
	not with V36/ZE6		
/43	Wood floor with 6 D-rings	\$422	\$422
	not with P93/V93/VL4/VK8/C07; standard with D93/H13/V24/V52	2/VC5/VV2/ZE6	
V48	Floor cover behind seat box	\$27	\$27
	must have D93; not with D50/D51/D56/D62/D64/V43/VK5		
V4A	Full paneling, right sliding door	\$109	\$109
	must have D03+T16+V21+VA5+W17; not with T19		
/52	Loadable wheel arch	\$375	\$375
	must have V43/X66; not with EL9/V21/V25/V35/VA1/C07		
V85	Cigarette lighter & ash cup, front	\$39	\$39
/A1	Side wall paneling waist height PVC	\$319	\$319
	must have VA5/VA7; not with V52		
/A3	Side wall paneling full hardboard	\$444	\$444
	not with V36/F02; if T93 must have (D50/D51)		
/A5	Full paneling, hinged rear doors	\$38	\$38
	must have D03+VA7+(W61/W78); not with V25		
/A7	Storage compart. w/ net in rear doors	\$127	\$127
,	must have W61/W78; not with V52	7-41	7221
VC4	Cargo lashing rails, head height	\$415	\$415
v U4	must have V42/C07/X66; not with ZE6) july	5413
VC5	Door sill - protective edge	\$71	\$71

		144" G	170" G	
		M2CA4G	M2CA7G 907.645	
		907.643		
VK8	Floor covering, plastic	\$370	\$370	
	not with V43/P93/T19/T93/V52/VC5/X66			
VV2	Lashing rails, floor level (plus 4 anchors)	\$270	\$345	
	must have V43; not with V93/VC5/ZE6			
W16	2nd row, fixed window, driver side	\$145	\$145	
	if D93 must have F43+W70; if D93 & standard roof CHS pro	duction required		
W17	2nd row, fixed window, passenger side	\$145	\$145	
	if D93 must have F43+W70; if D93 & standard roof CHS pro	duction required		
W33	FMVSS 217 emergency exit	\$379	\$379	
	must have V31; not with D50/T19/W16			
W54	Rear doors, opening to side wall	\$360	\$360	
W5F	90 Degree fixation point- Rear Doors	\$80	\$80	
	SoP and Plausibility TBD			
W61	Windows in rear doors	\$93	\$93	
	must have VA7/ if D51 must have F61; not with W78/(W70-	+-(H22/F02))		
W70	Black tinting (90%) for rear windows	\$138	\$138	
	not with W94; must have W16/W17/F02/((W61/W78)+H22); standard with F43/W33/F07			
W73	Bumper step, rear, grey	\$187	\$187	
	not with Q24/W75/W76			
W75	Step, wide, at rear end	\$308	\$308	
	not with JB6/JB7/Q24/QA9; must have R91+R92			
W76	Bumper step, rear, spring-loaded	\$601	\$601	
	must have R91+R92; not with JB6/JB7/X30/Q24			
W78	Heated rear window(s) w/ washers/wipers	\$335	\$335	
	Must have H22+VA7 / if D51 must have F61; not with W61			
X90	Deletion of Sprinter badge, left rear door	\$0	\$0	
X93	Deletion of model badge, right rear door	\$0	\$0	
XM4	Acoustic package	\$87	\$87	
	standard with C02/C03			
Y10	First-aid kit	\$27	\$27	
Y26	Wheel chocks	\$38	\$38	
Y45	Emergency flashlight	\$27	\$27	
Y68	Paint preservative	\$187	\$212	
Y69	Surface protection for stock vehicles	\$315	\$315	
ҮКЗ	Cargo straps, D-rings	\$81	\$81	
YK4	Cargo straps, lashing rails	\$104	\$104	
	must have V42/VV2; not with ZE6	100		
ZE6	Shelving prep	\$640	\$640	

Packages	Packag	es
----------	--------	----

		144" G	170" G M2CA7G 907.645
		M2CA4G	
		907.643	
C00	Comfort Package	\$300	\$300
LC4	Comfort overhead control panel	X	Х
SE4	Lumbar support, co-driver's seat	X	Х
SE5	Lumbar support, driver's seat	Х	Х
SK0	Comfort head restraint, driver	X	Х
SK1	Comfort head restraint, co-driver	X	Х
\$28	Armrest, driver and passenger door	Х	Х
must l	ave COS OR X68; CA/CC only: not with \$23	*	

X	X
X	Х
	X

X68	Comfort Plus Package	\$1,923	\$1,923
H15	Heated front passenger seat	X	Х
H16	Heated driver's seat	X	Х
SF1	Driver's seat electrically adjustable	X	X
SF2	Co-driver's seat electrically adjustable	X	X

C01	Driver Convenience Package	\$760	\$760
E46	12 V power outlet, driver seat base	X	Х
F64	Electrically folding exterior mirrors	X	Х
FJ1	Hinged lid for storage compartment	Х	Х
FJ5	Hinged Lid for Storage Compartments left and right	Х	Х
FZ9	Keys, two additional masters	X	Х
JA7	Blind Spot Assist	X	Х
JW8	Attention Assist	Х	Х

C02	Premium Package	\$983	\$983
CL3	Leather steering wheel	X	Х
E3M	MBUX Multimedia System with 7" touchscreen	X	Х
FM3	Wet Wiper System	X	Х
JB4	Active Lane Keeping Assist	X	Х
JK5	Instrument cluster with color display	Х	Х

Ordering availability restricted, see NetStar for availability and restrictions|must have JF1 + XM4; must choose FR8/JB7/JB6

CA2	C02 in combination with C03	\$604	\$604
CL3	Leather steering wheel	X	Х
FM3	Wet Wiper System	X	Х
JB4	Active Lane Keeping Assist	X	Х
JK5	Instrument cluster with color display	X	Х
Orderi	ing availability restricted, see NetStar for availability and re	strctions must have CO3 + JF1	

2500 CARGO VAN - GAS

144" G	170" G
M2CA4G	M2CA7G
907.643	907.645

C03	Premium Plus Package	\$1,793	\$1,793
E1B	Tray for smartphones incl. wireless charging	X	Х
	Navigation	X	Х
EY2	Intelligent navigation	X	Х
E4M	MBUX Multimedia System with 10.25" touchscreen	X	X
EX9	Free map data updates for 3 years	X	X
H1I	Front-to-rear outlet in instrument panel	X	X
JA9	Traffic Sign Assist	X	Х
XM4	Acoustic package	X	Х
must l	have (CA2+(JB7/JB6/JB8)) OR (JB4+JK5+FM3+(JB7/JB6/JB8)); not w	ith FR8 and CO2	

X67 Chrome Grille Package	\$290	\$290
CN2 Radiator grille frame in vehicle color	X	Х
FK3 Chrome plated radiator grille (MB only)	X	Х

X	X
X	Х
X	Х
Х	Х
-	X X X

C06	Cargo Convenience Package	\$658	\$658
E36	Cutoff relay for additional battery	X	Х
ES2.	12 V power outlet, rear compartment	X	Х
LC2	LED light strip in load compartment	X	Х
T12	Sliding door two stage opening	X	Х
T85	Assist handle, left rear door	X	Х
T86	Assist handles, right rear door	X	X
W54	Rear doors, opening to side wall	X	Х
must	nave T74 OR (T77+D50) OR (T77+D51)		

C07	Cargo Protection Package	\$1,117	\$1,117
V25	Half height load compartment trim	X	Х
V42	Lashing rails, waist level	X	Х
VC4	Cargo lashing rails, head height	X	Х
VK8	Floor covering, plastic	X	Х
YK3	Cargo straps, D-rings	X	Х
not w	ith X66		

2500 CARGO VAN - GAS Packages

144" G	170" G
M2CA4G	M2CA7G
907.643	907.645

X66	Heavy-Duty-Cargo Protection Package	\$2,043	\$2,043
V43	Wood floor with 6 D-rings	X	Х
V42	Lashing rails, waist level	X	Х
V52	Loadable wheel arch	X	Х
VA3	Side wall paneling full hardboard	X	Х
VC4	Cargo lashing rails, head height	X	Х
VV2	Lashing rails, floor level (plus 4 anchors)	X	Х
YK3	Cargo straps, D-rings	X	Х
YK4	Cargo straps, lashing rails	X	X
not w	ith CO7	*	

X69	Swivel Seat Package	\$532	\$532
SR8	Swivel base for driver's seat	X	Х
SR9	Swivel base for front passenger seat	Х	Х
\$87	Driver's seat frame, low	X	Х
S88	Passenger seat frame, low	X	Х

X01	Suspension Seating Package	\$940	\$940
SB3	Driver suspension seat, comfort version	X	Х
SB4	Passenger suspension seat, comfort version	X	Х
S87	Driver's seat frame, low	X	Х
\$88	Passenger seat frame, low	X	Х

2500 CARGO VAN - 4cyl Diesel Standard Equipment

144" 4C

170" 4C

170" E 4C

		144 40	170 40	170 140
		M2CA44	M2CA74	M2CAE4
		907.643	907.645	907.647
Engir	10	-	-	
_	Engine/7-Speed Trans.	5	S	S
ED4	AGM battery 12V 92 AH 850 A	S	S	S
	Automatic transmission, 7G-tronic	S	S	S
	Alternator 14 V / 200 A	S	S	S
	2.0L 4-cylinder diesel engine	S	S	S
MH8	SULEV emissions	S	S	S
Equip	ment			
AR2	Axle ratio 3.923	S	S	S
ваз	Active Brake Assist	S	S	5
вн1	Hold Function	S	S	Ş
C6L	Multifunction steering wheel	S	S	S
CL1	Adjustable steering wheel (angle)	S	S	S
D03	High roof		S	S
D93	Omission bulkhead	S	S	S
E07	Hill Start Assist	S	S	S
E10	Standard radio	S	S	S
	USB-C socket, 5 V	S	S	S
	Starter battery disconnect	S	S	S
E3J	Pre-installation for switch panel	S	S	
E40	Trailer hitch prep. wiring			S
ED8	Preinstallation PSM	S	5	S
-		S	S	S
EE5	Ultracapacitor discharge module	S	S	S
EK1	Body Builder Connector	S	S	\$
ESO.	Jump start terminal	S	S	5
	Pre-installation for Mercedes me Remote Services	S	S	S
EY5	Emergency Call System	S	S	S
EY6	Breakdown management	S	S	S
F68	Heated & electrically adjustable exterior mirrors	S	S	S
FF5	Shelf above windshield	S	S	S
FG8	Cupholder front	S	S	S
FI1	Remote key (315 mhz) w/central locking	S	5	S
FJ4	Storage compartment underneath cockpit	S	S	\$
FR3	Rear view camera (rear-view mirror display)	S	S	5
H21	Windshield with filter band	S	S	S
HH2	Heater, auxiliary electric hot air	S	S	S
нн9	Air Condition, Front	S	S	S
IH7	Head Unit, North America	S	S	S
	Speedometer, miles and km/h	S	S	5
J 5 5	Seat belt warning for co-driver seat	S	S	S
	Seat belt reminder driver	S	S	S
	Outside temperature gauge	S	S	S
	Crosswind Assist	S	S	S
	Communication module (LTE) for dig. services	S	S	S
	Service Interval 20.000 miles	S	S	S
	Red diesel filler cap	S	S	S
	Exhaust straight to rear			
	24.5 gallon fuel tank	S	S	S
	Aux fuel sending unit w/ fuel tap	S	S	S
		S	S	S
	Fuel filter with water separator	S	S	S
	3rd generation SCR emission control system	S	S	S
	Interior lights, cargo compartment	5	S	5
	Parking lights deletion	S	S	S
	Headlight assistant	S	S	S
	3rd brake light	\$	S	S
MS1	Cruise control	S	5	S

2500 CARGO VAN - 4cyl Diesel Standard Equipment

		144" 4C	170" 4C	170" E 4C
		M2CA44	M2CA44 M2CA74 907.643 907.645	M2CAE4 907.647
		907.643		
P47	Front mudflaps	\$	S	S
P48	Rear mudflaps	S	S	S
Q11	Longitudinal member reinforcement	S	S	S
R65	Spare tire bracket below frame	S	5	S
R87	Spare tire	S	S	\$
RH8	Tires LT 245/75 R16	S	S	S
RM0	All-season tires	S	S	S
RD9	Unspecified tire brand	S	S	S
RS3	6.5 J x 16 steel wheels	S	S	S
RY2	Tire pressure monitoring sensors	S	S	S
502	Standard driver seat	S	S	S
504	Standard front passenger seat	S	S	S
S22	Armrest for driver's seat	S	S	S
\$25	Armrest for front passenger seat	S	S	\$
SA5	Front airbag, driver	S	S	S
SA6	Front airbag, passenger	S	S	S
SH1	Thorax-pelvis sidebag, driver	S	5	\$
SH2	Thorax-pelvis sidebag, co-driver	S	S	S
SH9	Airbag, driver/passenger window	S	5	S
SK2	Seat occupancy sensor, driver's seat	S	S	\$
T16	Sliding door, passenger side	S	S	\$
V93	Without factory installed flooring	S	S	S
V94	Cable duct - side wall	S	S	S
V95	Cable duct - rear portal	S	S	S
W54	Rear doors, opening to side wall	0	0	S
XL2	GVWR 9,050 lbs. / 4.100 Kg	S	S	S
/43	Jack, hydraulic	S	5	S

		144" 4C	IC 170" 4C	170" E 4C M2CAE4 907.647
		M2CA44	M2CA74	
		907.643	907.645	
50	Front axle reinforced	\$346	\$346	\$346
P2	Addtl. bar for driveshaft & exhaust extension	\$69	\$69	
R3	Axle ratio 4.182	\$0	\$0	\$0
01	ESP for increased Center of Gravity above 39.4"	\$0	\$0	\$0
	must have CB4/CB8/X30; not with RH0/CB7			
25	Electric parking brake	\$279	\$279	\$279
	not with BE2; X69 choose B25/BE2			
E2	Handbrake lever, folding	\$55	\$55	\$55
	not with B25; X69 choose B25/BE2			
72	Bumpers front/rear primed	\$268	\$268	\$268
	must have CN2 (part of X67), not with CM0			
B1	Suspension for comfort and load protection	\$241	\$241	\$241
B7	Stabilization Level I	\$307	\$307	\$307
	not with CB4/CB8/X30			
B8	Stabilization Level II	\$723	\$723	\$723
	not with CB1/CB4/CB7/X30			
E8	Raised rear body mounts	\$252	\$252	\$252
L 3	Leather steering wheel	\$187	\$187	\$187
	must have (C02/E3M)/C03 + (ET4/MS1)			
MO	Painted metallic front & rear bumper	\$587	\$587	\$587
	must have (CN2/X67) + (JA7/C01) + (JB6/JB7) + (7755/9197/9775)		
M9	Primed side moldings	\$364	\$364	\$364
T1	Rear spring vibration absorbers	\$138	\$138	\$138
03	High roof	\$2,900	S	S
13	Mounting rails for roof rack	\$300	\$300	\$300
22	Fixed sunroof (rear roof section)	\$336	\$336	\$336
	not with H08/HK4/H72/V36/ZK4			
50	Cargo partition	\$288	\$288	\$288
	not with D51/D93/H08/HK4/T74/V36; must have one of T93/T77			
51	Cargo partition with 1 window	\$335	\$335	\$335
	not with D50/D93/H08/HK4/T74/V37/D17; must have one of T93	/177		
1B	Tray for smartphones incl. wireless charging	\$156	\$156	\$156
	must have CO2/E3M + H1I			
1E	Navigation	\$728	\$728	\$728
	must have CO2/E3M, not with CO3			
15	Sirius XM, satellite radio	\$255	\$255	\$255
	must have CO2/E3M/CO3		-	
1R	Additional Fuses (40/80/150/100 Ampere)	\$50	\$50	\$50
	SoP and Plausibility TBD			
1Y ·	Additional Fuses (40/80/80/100 Ampere)	\$50	\$50	\$50
	SoP and Plausibility TBD			
1X	MBUX multimedia 6-hour runtime	\$0	\$0	\$0
	must have X2R + (C02+E1E/E1S)/C03/(E3M+E1E/E1S)		***************************************	
2A	Access point for BB special signals in cockpit	\$29	\$29	\$29
21	Additional battery, co-driver seat base	\$248	\$248	\$248
	must have E36/C06; not with E2M/F09; CHS production only		to the same of the	
2M	Additional battery, engine compartment	\$248	\$248	\$248
	must have X01+ (E36/C06); not with E2I/X69/F09			
3M	MBUX Multimedia System with 7" touchscreen	\$474	\$474	\$474
J. 71	not with CO2/CO3; must have JK5+(JB7/JB6/JB8/FR8)	1 7		
36	Cutoff relay for additional battery	\$110	\$110	\$110
	standard with E2I/E2M	7110	7.000	1 ,,,,,
46	12 V power outlet, driver seat base	\$92	\$92	\$92
5M	Extension of PSM standard contact	\$58	\$58	\$58
D5	Parametric special module (PSM)	\$317	\$317	\$317
	it at a most to appear a module (1 arri)	4211	V	

		144" 4C	170" 4C	170" E 40
		M2CA44	M2CA74	M2CAE4 907.647
		907.643	907.645	
E3	115 V socket	\$125	\$125	\$125
P7	Basic electric fitting for rear loudspeakers	\$68	\$68	\$68
52	12 V power outlet, rear compartment	\$92	\$92	\$92
S5	Charging package, dashboard	\$82	\$82	\$82
T4	Active Distance Assist DISTRONIC	\$263	\$263	\$263
-1-	must have CO2/CO3/E3M; not with ZH4	7203	7203	7203
1K	Coat hooks in driver cabin	\$14	\$14	\$14
11	must have D50/D51	711	(金色)	721
49	Electrically heated windshield	\$218	\$218	\$218
7.7	no restriction	7210	9210	9210
61	Interior rear view mirror	\$36	\$36	\$36
01	not with D50; must have C02/E3M/C03	, J.30	230	930
64	Electrically folding exterior mirrors	\$49	\$49	\$49
E9				\$81
	Additional DIN-slot	\$81	\$81	
F8	Overhead storage slot, front center	\$105	\$105	\$105
J1	Hinged lid for storage compartment	\$93	\$93	\$93
R8	Rear view camera (head unit display)	\$336	\$336	\$336
1/4	must have CO2/E3M; not with FR3/JB7/JB6/JB8	4504	A=0.5	éro.
Y1	Security alarm w. interior motion sensor	\$584	\$584	\$584
	must have LC4/C00	405	1 400	400
Y7	Optional 3-button keys	\$36	\$36	\$36
Z9	Keys, two additional masters	\$121	\$121	\$121
100	Warm/cool air duct to rear compartment	\$59	\$59	\$59
	not with D50/D51/Y2A			
101	Heat insulation, rear compartment	\$156	\$156	\$156
	must have V21/V25/VA3/VA1/C07/X66			
104	Heat insulation, front compartment	\$187	\$187	\$187
	if + D50/D51 must have V07			
108	Air conditioning rear, roof-mounted	\$2,872	\$2,872	\$2,872
	must have D93 +V36; not with HK4/C06/X66/C07			
112	Fuel-fired pre-heater/booster (17K BTU)	\$1,116	\$1,116	\$1,116
	not with HZ9			
113	Rear cabin heater and vents	\$786	\$786	\$786
	must have H12/HZ9			
15	Heated front passenger seat	\$284	\$284	\$284
	must have H16; not with X68			
116	Heated driver's seat	\$284	\$284	\$284
	must have H15; not with X68			
122	Rear window defroster	\$253	\$253	\$253
	must have W61/W78; standard for W61+W70	-		
172	Roof fan, electric	\$400	\$400	\$400
	not with D22/V36			
188	Rear heater prep	\$405	\$405	\$405
	must have H12/HZ9; not with H13/T19			
111	Front-to-rear outlet in instrument panel	\$0	\$0	\$0
	must have FJ1/C01		1000	,-
H4	Thermotronic automatic climate control	\$337	\$337	\$337
	must have JF1; if +H13 must have H08/HK4	400.	7.25	700,
IK4	Rear air conditioner, heavyduty	\$3,940	\$3,940	\$3,940
.,,,,,	must have D03+V36+D93; not with H08/ZB6/ZE6/N62/N63	45,540	95,570	Q-0,040
IZ9	Fuel-fired heater booster (18,000 BTU)	\$676	\$676	\$676
147	not with H12	2070	2070	7070
51		ללים	\$72	\$72
31	Fuel gauge, optimized for aux. fuel tap	\$72	3/2	3/2
	not with HZ9/H12	60	ĊO.	do.
52	Engine oil level display at cold start	\$0	\$0	\$0

		144" 4C	170" 4C	170" E 40 M2CAE4 907.647
		M2CA44	M2CA74	
		907.643	907.645	
JA7	Blind Spot Assist	\$450	\$450	\$450
	must have F64; not with C01	7.00		
B4	Active Lane Keeping Assist	\$288	\$288	5288
	standard with CO2/CA2	1 1111	AMMERAN	
B6	Parking Package with 360 degree camera	\$775	\$775	\$775
	must have CO2/CO3/E3M; not with W75/W76/JB7	7		7.75
IB7	Parking Package	\$615	\$615	\$615
	must have CO2/CO3/E3M; not with W75/W76/JB6			
B8	360 Degree Camera	\$685	\$685	\$685
	SoP and Plausibility TBD	,	,	
F1	Rain sensor	\$106	\$106	\$106
-	not with CO2/X11	1	,	, , , , , ,
K5	Instrument cluster with color display	\$144	\$144	\$144
11.5	standard with CO2/CA2	9111	9211	7-11
WO	Backup alarm	\$99	\$99	\$99
W2	Deactivation lamp monitoring failure	\$27	\$27	\$27
W8	Attention Assist	\$49	\$49	\$49
(51	Misfueling prevention for Diesel	\$49	\$49	\$49
(52	DEF fluid filler cap - lockable	\$27	\$27	\$27
_		\$199	\$199	\$199
.13	Fog lamp with cornering light function	\$199		\$199
.71	Light/motion sensor in rear compartment	\$54	\$54	Ş34
òo	not with V36	C454	6151	6151
.B9	uminated front exits	\$151	\$151	\$151
C4	Comfort overhead control panel	\$93	\$93	\$93
.C2	LED light strip in load compartment	\$263	\$263	\$263
	not with H08/HK4/V36/C06	1 460	650	450
M20	Speed limitation 65 mph	\$60	\$60	\$60
	not with MD3	r		4
M60	Alternator 14 V / 250 A	\$704	\$704	\$704
MD3	Top speed limitation 75 mph	\$60	\$60	\$60
	not with M20			4
N62	Front engine bracket for additional alternator	\$467	\$467	\$467
	not with HK4/N63			
V63	Front engine bracket for auxiliary A/C compressor	\$467	\$467	\$467
	not with HK4/N62			
93	Omission of D-rings	-\$15	-\$15	-\$15
	not with D93/V43/VK8			
224	Trailer hitch, 5,000 lbs	\$147	\$147	\$147
	not with W73/W75/W76			-
QA9	Half-sided step rear (for trailer hitch)	\$101	\$101	\$101
	must have Q24/QA2; not with W73/W75/W76			
R91	Spare tire deletion	-\$110	-\$110	-\$110
	must have R92; not with R87			
392	Spare tire carrier deletion	\$0	\$0	\$0
	must have R91; not with R65			
398	Rims painted jet black	\$81	\$81	\$81
	not with RL5/RM2			
RF1	Tire brand Continental	\$0	50	\$0
	must have RM1 + RM9			
RF8	Tire brand Michelin	\$0	\$0	\$0
	must have RM9; not with RM1			
RHO	Tire brand Kumho	\$0	\$0	\$0
_	must have RM9; not with RM1		2-3790	1
RL5	Light-alloy wheels 6.5 J x 16	\$906	\$906	\$906
	1			

		144" 4C	170" 4C	170" E 40
		M2CA44	2CA44 M2CA74	M2CAE4 907.647
		907.643	907.645	
M1	M+S winter tires	\$169	\$169	\$169
	must have RF1/RD9; not with RF8/RH0/X31			
M2	Rims painted arctic white	\$81	\$81	\$81
	not with R98/RL5			
M9	Specially requested tires	\$101	\$101	\$101
	must have RF1/RF8/RH0; not with RD9			
23	Twin front passenger seat	\$400	\$400	\$400
	not with C00/X68/X01			
28	Armrest, driver and passenger door	\$51	\$51	\$51
62	Seat belts orange, driver and front passenger	\$32	\$32	\$32
	not with S23			
В9	Driver's seat plus	\$238	\$238	\$238
	must have VF7; not with C00/X68/X69			Tale Salar
Z7	Storage net, driver's seat backrest	\$64	\$64	\$64
Z8	Storage net, passenger seat backrest	\$64	\$64	\$64
12	Sliding door two stage opening	\$82	\$82	\$82
	not with T55		7.5	
19	Sliding door, driver's side	\$935	\$935	\$935
13	not with H13/H88/VC5/ZE6/F43/W16/F02; if +V36 must have		7000	
50	Electric closing assist right sliding door	\$335	\$335	\$335
20	must have DO3; not with T55/T93	7000	7000	V
51	Electric closing assist left sliding door	\$335	\$335	\$335
21	must have T19 + D03	7000	4555	7555
55	Electric sliding door right	\$831	\$831	\$831
33	must have D03 + (FY7+T16); not with T12/T50	7031	7001	2004
57	Electric sliding step	\$1,071	\$1,071	\$1,071
3/	must have ED5; not with T93	\$1,071	\$1,071	71,071
	Opening limiter electrically operated sliding door	\$120	\$120	\$120
60		\$120	\$120	3120
74	Must have T55	\$32	\$32	\$32
74	Assist handle, B-pillar	\$32	\$32	202
	must have D93; not with T77	ĆEO.	èro.	\$59
75	Door-mounted assist handles, driver & passenger	\$59	\$59	
77	Assist handle w/ partition	\$32	\$32	\$32
_	must have D50/D51/D64	1 400	420	400
85	Assist handle, left rear door	\$32	\$32	\$32
86	Assist handles, right rear door	\$32	\$32	\$32
93	Sliding door right side deletion	\$0	\$0	\$0
	not with T16/T50/T57/VK8/VC5	1 4000	1000	Anca
/07	Cab rear wall liner	\$360	\$360	\$360
	must have (D50/D51)+F1K; standard with H04	1 444	4.00	4004
/21	Luxury interior Trim	\$661	\$661	\$661
	must have VA5/VA7; not with V52/VA1/VA3		Til Paners	1,000
/24	Pallet support in sliding door step	\$96	\$96	\$96
	must have (V43/X66)+(D50/D51); not with VK8/V93/C07	γ	r	
/25	Half height load compartment trim	\$201	\$201	\$201
	not with VA1/VA3/VA5/V52/X66			
/31	Window pillar trim	\$513	\$513	\$513
	must have V36 + (V21/VA1) + (F02/F03/F07); not with V42			
/35	Wheel house covering	\$105	\$105	\$105
	if +V43 must have V25/VA1/VA3; not with V52			
/36	Roof trim	\$876	\$876	\$876
	must have D93; not with D17/D22/H72/L65/L71/LC2/VA3/V4	12/ZE6/(T93+-D03)/X6	5/C06/C07	
/42	Lashing rails, waist level	\$277	\$277	\$277
	not with V36/ZE6			
/43	Wood floor with 6 D-rings	\$422	\$422	\$422
	not with P93/V93/VL4/VK8/C07; standard with D93/H13/V24	1/V52/VC5/VV2/ZE6		
/48	Floor cover behind seat box	\$27	\$27	\$27

		144" 4C	170" 4C	170" E 40
		M2CA44	M2CA74	M2CAE4
		907.643	907.645	907.647
/4A	Full paneling, right sliding door	\$109	\$109	\$109
4A	must have D03+T16+V21+VA5+W17; not with T19	\$103	3103	\$103
52	Loadable wheel arch	\$375	\$375	\$375
12	must have V43/X66; not with EL9/V21/V25/V35/VA1/C07	7373	2373	\$373
/85	Cigarette lighter & ash cup, front	\$39	\$39	\$39
/A1	Side wall paneling waist height PVC	\$319	\$319	\$319
MI	must have VA5/VA7; not with V52	7313	2213	3313
/A3	Side wall paneling full hardboard	\$444	\$444	\$444
AJ	not with V36/F02; if T93 must have (D50/D51)	7444	2444	2444
/A5	Full paneling, hinged rear doors	\$38	\$38	\$38
IAS	must have D03+VA7+(W61/W78); not with V25	230	230	220
/A7	Storage compart. w/ net in rear doors	\$127	\$127	\$127
Α/	must have W61/W78; not with V52	3127	7121	712/
/C4	Cargo lashing rails, head height	\$415	\$415	\$415
C4	must have V42/C07/X66; not with ZE6	3413	3413	3413
ICE.	Door sill - protective edge	\$71	\$71	\$71
/C5		\$/1	5/1	\$/1
nvo.	must have V43/X66; not with T19/T93/VK8/VV2/V93/C07	\$370	\$370	\$370
/K8	Floor covering, plastic not with V43/P93/T19/T93/V52/VC5/X66	\$370	\$570	\$570
///2	Lashing rails, floor level (plus 4 anchors)	\$270	¢24E	6277
/V2		\$270	\$345	\$377
. 10 5	must have V43; not with V93/VC5/ZE6	CA AF	£4.45	61.45
N16	2nd row, fixed window, driver side	\$145	\$145	\$145
ia ¬	If D93 must have F43+W70; if D93 & standard roof CHS production		£4.45	£1.45
V17	2nd row, fixed window, passenger side	\$145	\$145	\$145
	if D93 must have F43+W70; if D93 & standard roof CHS production		10-0	4000
N33	FMVSS 217 emergency exit	\$379	\$379	\$379
	must have V31; not with D50/T19/W16	1 4000	****	_
	Rear doors, opening to side wall	\$360	\$360	S
V5F	90 Degree fixation point- Rear Doors	\$80	\$80	\$80
	SoP and Plausibility TBD		A-a-a	Vasa -
V61	Windows in rear doors	\$93	\$93	\$93
	must have VA7/ if D51 must have F61; not with W78/(W70+-(H2		4	4.00
V70	Black tinting (90%) for rear windows	\$138	\$138	\$138
	not with W94; must have W16/W17/F02/((W61/W78)+H22); sta			
V73	Bumper step, rear, grey	\$187	\$187	\$187
	not with Q24/W75/W76			
V75	Step, wide, at rear end	\$308	\$308	\$308
	not with JB6/JB7/Q24/QA9; must have R91+R92			
N76	Bumper step, rear, spring-loaded	\$601	\$601	\$601
	must have R91+R92; not with JB6/JB7/X30/Q24			
V78	Heated rear window(s) w/ washers/wipers	\$335	\$335	\$335
	Must have H22+VA7 / if D51 must have F61; not with W61			
(90	Deletion of Sprinter badge, left rear door	\$0	\$0	\$0
(93	Deletion of model badge, right rear door	\$0	\$0	\$0
(2R	Conversion to RV requirement	\$0	\$0	\$0
	must have B01+D93+E1X			
M4	Acoustic package	\$87	\$87	\$87
	standard with CO2/CO3			
10	First-aid kit	\$27	\$27	\$27
26	Wheel chocks	\$38	\$38	\$38
45	Emergency flashlight	\$27	\$27	\$27
68	Paint preservative	\$187	\$212	\$225
69	Surface protection for stock vehicles	\$315	\$315	\$315
′K3	Cargo straps, D-rings	\$81	\$81	\$81
′K4	Cargo straps, lashing rails	\$104	\$104	\$104
	must have V42/VV2; not with ZE6			
:E6	Shelving prep	\$640	\$640	\$640

2500 CARGO VAN - 4cyl Diesel Packages

144" 4C	M2CA44 M2CA74	170" E 4C M2CAE4
M2CA44		
907.643		907.647
\$300	\$300	\$300
X	X	X
X	X	Х
X	X	X
X	X	X
Х	X	X
X	X	X
	M2CA44 907.643 \$300 X X X X	M2CA44 M2CA74 907.643 907.645 \$300 \$300 X X X X X X X X X X X X X X

X	X	Х
X	X	Х
	X	X X X

X68	Comfort Plus Package	\$1,923	\$1,923	\$1,923
H15	Heated front passenger seat	X	X	Х
H16	Heated driver's seat	X	X	Χ
SF1	Driver's seat electrically adjustable	X	X	X
SF2	Co-driver's seat electrically adjustable	Х	X	Х

C01	Driver Convenience Package	\$760	\$760	\$760
E46	12 V power outlet, driver seat base	X	X	X
F64	Electrically folding exterior mirrors	X	X	Х
FJ1	Hinged lid for storage compartment	Х	X	Х
FJ5	Hinged Lid for Storage Compartments left and right	X	X	X
FZ9	Keys, two additional masters	Х	X	X
JA7	Blind Spot Assist	X	X	Х
JW8	Attention Assist	Х	X	X

C02	Premium Package	\$983	\$983	\$983
CL3	Leather steering wheel	X	X	X
E3M	MBUX Multimedia System with 7" touchscreen	X	X	X
FM3	Wet Wiper System	X	Х	X
JB4	Active Lane Keeping Assist	X	X	X
JK5	Instrument cluster with color display	X	X	X

Ordering availability restricted, see NetStar for availability and restrictions|must have JF1 + XM4; must choose FR8/JB7/JB6

CA2	CO2 in combination with CO3	\$604	\$604	\$604
CL3	Leather steering wheel	X	X	X
FM3	Wet Wiper System	X	X	Х
JB4	Active Lane Keeping Assist	X	X	X
JK5	Instrument cluster with color display	X	X	X

2500 CARGO VAN - 4cyl Diesel Packages

144" 4C	170" 4C	170" E 4C
M2CA44	M2CA74	M2CAE4
907.643	907.645	907.647

C03	Premium Plus Package	\$1,793	\$1,793	\$1,793
E1B	Tray for smartphones incl. wireless charging	Х	X	X
	Navigation	X	X	Х
EY2	Intelligent navigation	X	X	X
E4M	MBUX Multimedia System with 10.25" touchscreen	X	X	Х
EX9	Free map data updates for 3 years	X	Х	Х
H1I	Front-to-rear outlet in instrument panel	X	X	X
JA9	Traffic Sign Assist	X	Х	X
XM4	Acoustic package	X	X	Х
must	have (CA2+(JB7/JB6/JB8)) OR (JB4+JK5+FM3+(JB7/JB6/JB	8)); not with FR8 and	C02	

X67 Chrome Grille Package	\$290	\$290	\$290
CN2 Radiator grille frame in vehicle color	X	Х	Х
FK3 Chrome plated radiator grille (MB only)	X	Х	Х

X	.,	
	X	X
X	X	X
X	X	X
Х	Х	X
	X X X	X X X X X X X X X X X X X X X X X X X

C06	Cargo Convenience Package	\$658	\$658	\$658
E36	Cutoff relay for additional battery	X	X	X
E\$2	12 V power outlet, rear compartment	Х	X	Х
LC2	LED light strip in load compartment	X	X	X
T12	Sliding door two stage opening	Х	X	Х
T85	Assist handle, left rear door	X	X	X
T86	Assist handles, right rear door	X	X	X
W54	Rear doors, opening to side wall	X	X	5
must	have T74 OR (T77+D50) OR (T77+D51)	***		

C07	Cargo Protection Package	\$1,117	\$1,117	\$1,117
V25	Half height load compartment trim	X	X	Х
V42	Lashing rails, waist level	X	X	X
VC4	Cargo lashing rails, head height	X	X X	
VK8	Floor covering, plastic	X	X	X
YK3	Cargo straps, D-rings	X	X	X

X66	Heavy-Duty-Cargo Protection Package	\$2,043	\$2,043	\$2,043
V43	Wood floor with 6 D-rings	X	Х	Χ
V42	Lashing rails, waist level	X	X	Х
V52	Loadable wheel arch	X	X	X
VA3	Side wall paneling full hardboard	X	X	Х
VC4	Cargo lashing rails, head height	X	X	Х
VV2	Lashing rails, floor level (plus 4 anchors)	X	X	X
ҮКЗ	Cargo straps, D-rings	X	Х	Х
YK4	Cargo straps, lashing rails	X	X	Х
not v	vith CO7		*	

2500 CARGO VAN - 4cyl Diesel Packages

144" 4C	170" 4C	170" E 4C
M2CA44	M2CA74	M2CAE4
907.643	907.645	907.647

X69	Swivel Seat Package	\$532	\$532	\$532
SR8	Swivel base for driver's seat	X	X	X
SR9	Swivel base for front passenger seat	X	Х	Х
S87	Driver's seat frame, low	×	X	Х
S88	Passenger seat frame, low	X	X	X

X	X	Х
X	X	Х
X	X	X
X	X	Х
	X X X	V V

2500 CARGO VAN - 6cyl Diesel Standard Equipment

144" 6C	144" 4x4	170" 6C	170" 4x4	170" E 6C	170" E 4x4
M2CA46	M2CA4X	M2CA76	M2CA7X	M2CAE6	M2CAEX
907.643	907.643	907.645	907.645	907.647	907.647

		907.643	907.643	907.645	907.645	907.647	907.647
Engin	е						
6-Cyl	Engine/7-Speed Trans.	S	S	S	S	5	S
ED4	AGM battery 12V 92 AH 850 A	S	S	S	S	S	S
G42	Automatic transmission, 7G-tronic	S	S	S	S	S	S
MIO	ULEV emission	S	5	S	S	S	S
MG5	3.0L V6 turbo diesel engine	S	S	S	S	S	S
M46	Alternator 14 V/220 A	S	5	S	S	S	S
X30	4x4 Package		\$8,200		\$8,200		\$8,200
T75	Door-mounted assist handles, driver & passenger		S	AT SECUL	S		S
ZG3	4x4 - High range transfer case w/ low gear	- 1	S	The part of	5		\$
Equip	ment						
AR2	Axle ratio 3.923	S	S	\$	S	S	S
ВАЗ	Active Brake Assist	S	5	S	S	S	S
BH1	Hold Function	S	S	S	S	S	S
C6L	Multifunction steering wheel	S	5	S	S	S	\$
CL1	Adjustable steering wheel (angle)	S	S	\$	S	S	S
D03	High roof		-	S	S	5	5
D93	Omission bulkhead	S	S	S	\$	S	S
E07	Hill Start Assist	S	S	S	S	S	S
E10	Standard radio	S	S	S	S	S	\$
E1U	USB-C socket, 5 V	S	S	S	S	S	S
E30	Starter battery disconnect	S	S	S	S	S	S
E3J	Pre-installation for switch panel	S	-	S		S	
E40	Trailer hitch prep, wiring	S	S	S	S	S	S
ED8	Preinstallation PSM	S	S	S	S	S	S
EES	Ultracapacitor discharge module	S	S	S	S	S	S
EK1	Body Builder Connector	S	S	5	S	S	S
ESO	Jump start terminal	S	S	S	S	S	S
EW6	Pre-installation for Mercedes me Remote Services	S	S	S	S	S	S
EY5	Emergency Call System	S	S	S	S	S	S
EY6	Breakdown management	S	S	S	S	S	S
FF5	Shelf above windshield	Ş	5	S	S	S	S
FG8	Cupholder front	S	5	S	S	S	S
F68	Heated & electrically adjustable exterior mirrors	S	S	S	S	S	S
FI1	Remote key (315 mhz) w/central locking	S	S	S	S	S	S
FJ4	Storage compartment underneath cockpit	S	S	S	S	S	S
FR3	Rear view camera (rear-view mirror display)	S	5	S	S	S	S
H21	Windshield with filter band	S	S	S	S	S	Ş
нн2	Heater, auxiliary electric hot air	S	S	S	S	S	S
	Air Condition, Front	S	S	S	S	S	S
	Head Unit, North America	S	S	S	S	S	S
J11	Speedometer, miles and km/h	S	S	5	S	S	S
155	Seat belt warning for co-driver seat	S	S	5	5	S	S
158	Seat belt reminder driver	S	S	S	S	S	S
165	Outside temperature gauge	5	\$	S	S	S	S
JA8	Crosswind Assist	S	S	S	S	S	S
JH3	Communication module (LTE) for dig. services	S	S	S	5	S	S
119	Service interval 20.000 miles	5	S	S	S	S	S
K56	Red diesel filler cap	S	S	S	S	S	S
K60	Exhaust straight to rear	S	S	S	S	S	S
KB7	24.5 gallon fuel tank	S	S	S	S	S	S
KL1	Aux fuel sending unit w/ fuel tap	S	S	S	S	S	S
KL5	Fuel filter with water separator	S	S	S	\$	S	S
KP6	3rd generation SCR emission control system	S	S	S	S	S	S

2500 CARGO VAN - 6cyl Diesel

Stano	lard	Equi	pment

		144" 6C	144" 4x4	170" 6C	170" 4x4	170" E 6C	170" E 4x4
		M2CA46	M2CA4X	M2CA76		M2CAE6 907.647	M2CAEX
		907.643	907.643	907.645			907.647
L65	Interior lights, cargo compartment	S	S	S	S	S	S
L94	Parking lights deletion	S	S	S	S	S	S
LA2	Headlight assistant	\$	S	S	S	S	S
LB5	3rd brake light	S	S	S	S	S	S
MS1	Cruise control	S	5	S	S	S	S
P47	Front mudflaps	S	S	S	S	S	S
P48	Rear mudflaps	S	S	S	S	S	S
Q11	Longitudinal member reinforcement	S	S	S	S	S	S
R65	Spare tire bracket below frame	S	S	S	S	S	S
R87	Spare tire	S	S	S	S	S	S
RH8	Tires LT 245/75 R16	S	S	S	S	S	S
RMO	All-season tires	S	S	S	S	S	S
RD9	Unspecified tire brand	S	S	S	S	S	S
RS3	6.5 J x 16 steel wheels	S	S	S	S	S	S
RY2	Tire pressure monitoring sensors	S	S	5	S	S	5
S02	Standard driver seat	5	S	S	S	S	S
504	Standard front passenger seat	S	S	S	S	S	S
522	Armrest for driver's seat	S	S	\$	S	S	S
S25	Armrest for front passenger seat	S	S	S	S	S	S
SAS	Front airbag, driver	S	5	S	S	S	S
SA6	Front airbag, passenger	S	S	S	S	S	S
SH1	Thorax-pelvis sidebag, driver	S	S	S	S	S	S
SH2	Thorax-pelvis sidebag, co-driver	S	S	S	S	S	S
SH9	Airbag, driver/passenger window	S	S	S	S	S	S
SK2	Seat occupancy sensor, driver's seat	S	S	S	S	S	S
T15	Sliding door, passenger side	S	S	S	S	S	S
V93	Without factory installed flooring	S	S	5	S	S	S
V94	Cable duct - side wall	S	S	S	S	S	S
V95	Cable duct - rear portal	S	S	S	S	S	S
W54	Rear doors, opening to side wall	0	0	0	0	S	S
XL2	GVWR 9,050 lbs. / 4.100 Kg	S	S	S	S	S	S
Y43	Jack, hydraulic	S	S	S	5	S	S

Options

		144" 6C	144" 4x4	170" 6C	170" 4x4	170" E 6C	170" E 4x4
		M2CA46	M2CA4X	M2CA76	M2CA7X	M2CAE6	M2CAEX
		907.643	907.643	907.645	907.645	907.647	907.647
A50	Front axle reinforced	\$346		\$346		\$346	
AP2	Addtl. bar for driveshaft & exhaust extension	\$69	\$69	\$69	\$69		1
AR3	Axle ratio 4.182	\$0	-	\$0	400	\$0	
B01	ESP for increased Center of Gravity above 39.4"	\$0	\$0	\$0	\$0	\$0	\$0
-	must have CB4/CB8/X30; not with RHO/CB7	70	70	30	50	20	30
B25	Electric parking brake	\$279	\$279	\$279	\$279	\$279	\$279
525	not with BE2; X69 choose B25/BE2	3213	\$275	32/3	3213	32/3	\$213
BE2	Handbrake lever, folding	\$55	\$55	ĊCC.	ČEE	err.	cer.
DLZ	not with B25; X69 choose B25/BE2	300	\$55	\$55	\$55	\$55	\$55
C72	Bumpers front/rear primed	i caco	¢ace.	¢aco.	(torn)	1000	ènca
C/2		\$268	\$268	\$268	\$268	\$268	\$268
CD4	must have CN2 (part of X67), not with CM0	1 4244		date		40.4	
CB1	Suspension for comfort and load protection	\$241	-	\$241		\$241	7
CB4	Stabilization Level III	\$921		\$921		\$921	HOVER DIK
-	not with CB1/CB7/CB8/X30						
CB7	Stabilization Level I	\$307	-	\$307	II II - STATE	\$307	
	not with CB4/CB8/X30	,					
CB8	Stabilization Level II	\$723		\$723		\$723	
	not with CB1/CB4/CB7/X30						
CE8	Raised rear body mounts	\$252	-	\$252		\$252	- F
CL3	Leather steering wheel	\$187	\$187	\$187	\$187	\$187	\$187
CMO	Painted metallic front & rear bumper	\$587	\$587	\$587	\$587	\$587	\$587
	must have (CN2/X67) + (JA7/C01) + (JB6/JB7) + (7755/9197/9775)			,			,
CM9	Primed side moldings	\$364	\$364	\$364	\$364	\$364	\$364
CT1	Rear spring vibration absorbers	\$138	\$138	\$138	\$138	\$138	\$138
D03	High roof	\$2,900		\$136	\$130	\$136 S	\$136 S
D13	Mounting rails for roof rack		\$2,900				
D22	Fixed sunroof (rear roof section)	\$300	\$300	\$300	\$300	\$300	\$300
022		\$336	\$336	\$336	\$336	\$336	\$336
DEO	not with H08/HK4/H72/V36/ZK4	4000	4000	4000	4000	4000	Anna
D50	Cargo partition	\$288	\$288	\$288	\$288	\$288	\$288
254	not with D51/D93/H08/HK4/T74/V36; must have one of T93/T77				7.422		
D51	Cargo partition with 1 window	\$335	\$335	\$335	\$335	\$335	\$335
-	not with D50/D93/H08/HK4/T74/V37/D17; must have one of T93/T7						
E1B	Tray for smartphones incl. wireless charging	\$156	\$156	\$156	\$156	\$156	\$156
	must have CO2/E3M + H1I						
E1E	Navigation	\$728	\$728	\$728	\$728	\$728	\$728
	must have CO2/E3M, not with CO3						
E1S	Sirius XM, satellite radio	\$255	\$255	\$255	\$255	\$255	\$255
	must have CO2/E3M/CO3						
E1R	Additional Fuses (40/80/150/100 Ampere)	\$50	\$50	\$50	\$50	\$50	\$50
	SoP and Plausibility TBD						
E1Y	Additional Fuses (40/80/80/100 Ampere)	\$50	\$50	\$50	\$50	\$50	\$50
	SoP and Plausibility TBD			3433-353		W. S.	
E1X	MBUX multimedia 6-hour runtime	\$0	\$0	\$0	\$0	\$0	\$0
	must have X2R + (CO2+E1E/E1S)/CO3/(E3M+E1E/E1S)	70	70	90	90	90	Q O
EZA	Access point for BB special signals in cockpit	\$29	\$29	\$29	\$29	\$29	\$29
E21	Additional battery, co-driver seat base						
E.21		\$248	\$248	\$248	\$248	\$248	\$248
	must have E36/C06; not with E2M/F09; CHS production only				4		44.14
E2M	Additional battery, engine compartment	\$248	\$248	\$248	\$248	\$248	\$248
	must have X01+ (E36/C06); not with E2I/X69/F09						
ЕЗМ	MBUX Multimedia System with 7" touchscreen	\$474	\$474	\$474	\$474	\$474	\$474
	not with CO2/CO3; must have JK5+(JB7/JB6/JB8/FR8)						
E36	Cutoff relay for additional battery	\$110	\$110	\$110	\$110	\$110	\$110
	standard with E2I/E2M						
E46	12 V power outlet, driver seat base	\$92	\$92	\$92	\$92	\$92	\$92
ESNA	Extension of PSM standard contact	\$58	\$58	\$58	\$58	\$58	\$58

		144" 6C	144" 4x4	170" 6C	170" 4x4	70" 4x4 170" E 6C	170" E 4x4
		M2CA46	M2CA4X	M2CA76	M2CA7X	M2CAE6	M2CAEX
		907.643	907.643	907.645	907.645	907.647	907.647
ED5	Parametric special module (PSM)	\$317	\$317	\$317	\$317	\$317	\$317
	not with ED8						
EE3	115 V socket	\$125	\$125	\$125	\$125	\$125	\$125
EP7	Basic electric fitting for rear loudspeakers	\$68	\$68	\$68	\$68	\$68	\$68
ES2	12 V power outlet, rear compartment	\$92	\$92	\$92	\$92	\$92	\$92
ES5	Charging package, dashboard	\$82	\$82	\$82	\$82	\$82	\$82
ET4	Active Distance Assist DISTRONIC	\$263	\$263	\$263	\$263	\$263	\$263
	must have CO2/CO3/E3M; not with ZH4	7-00	7-00	7203	7205	7203	7203
F1K	Coat hooks in driver cabin	\$14	\$14	\$14	\$14	\$14	\$14
	must have D50/D51	¥	V		***	W-11	421
F49	Electrically heated windshield	\$218	\$218	\$218	\$218	\$218	\$218
113	no restriction	7210	3210	7216	7210	7210	7210
F61	Interior rear view mirror	\$36	\$36	\$36	\$36	\$36	\$36
101	not with D50; must have C02/E3M/C03	1 200	1 230	250	220	230	250
F64	Electrically folding exterior mirrors	\$49	¢40	C40	¢40	640	640
1.04	no restriction	242	\$49	\$49	\$49	\$49	\$49
FE9	Additional DIN-slot	¢01	¢01	Ć01	Ċ04	¢01	Ċ01
		\$81	\$81	\$81	\$81	\$81	\$81
FF8	Overhead storage slot, front center	\$105	\$105	\$105	\$105	\$105	\$105
FJ1	Hinged lid for storage compartment	\$93	\$93	\$93	\$93	\$93	\$93
FR8	Rear view camera (head unit display)	\$336	\$336	\$336	\$336	\$336	\$336
PR 44	must have CO2/E3M; not with FR3/JB7/JB6/JB8	100		4-21	T	Y	1000
FY1	Security alarm w. interior motion sensor	\$584	\$584	\$584	\$584	\$584	\$584
	must have LC4/C00	- i		7	P 2000		
FY7	Optional 3-button keys	\$36	\$36	\$36	\$36	\$36	\$36
FZ9	Keys, two additional masters	\$121	\$121	\$121	\$121	\$121	\$121
H00	Warm/cool air duct to rear compartment	\$59	\$59	\$59	\$59	\$59	\$59
	not with D50/D51/Y2A						
H01	Heat insulation, rear compartment	\$156	\$156	\$156	\$156	\$156	\$156
	must have V21/V25/VA3/VA1/C07/X66						
H04	Heat insulation, front compartment	\$187	\$187	\$187	\$187	\$187	\$187
	if + D50/D51 must have V07						
H08	Air conditioning rear, roof-mounted	\$2,872	\$2,872	\$2,872	\$2,872	\$2,872	\$2,872
	must have D93 +V36; not with HK4/C06/X66/C07						
H12	Fuel-fired pre-heater/booster (17K BTU)	\$1,116	\$1,116	\$1,116	\$1,116	\$1,116	\$1,116
	not with HZ9						
H13	Rear cabin heater and vents	\$786	\$786	\$786	\$786	\$786	\$786
	must have H12/HZ9		11		1		
H15	Heated front passenger seat	\$284	\$284	\$284	\$284	\$284	\$284
	must have H16; not with X68						
H16	Heated driver's seat	\$284	\$284	\$284	\$284	\$284	\$284
	must have H15; not with X68	-					
H22	Rear window defroster	\$253	\$253	\$253	\$253	\$253	\$253
	must have W61/W78; standard for W61+W70					2000000	
H72	Roof fan, electric	\$400	\$400	\$400	\$400	\$400	\$400
	not with D22/V36	7.00	V.00	V 100	V 100	V.00	4 100
H88	Rear heater prep	\$405	\$405	\$405	\$405	\$405	\$405
1100	must have H12/HZ9; not with H13/T19	7403	Ş-103	Ş-103	7403	4-03	Ş-103
H11	Front-to-rear outlet in instrument panel	\$0	\$0	\$0	\$0	\$0	\$0
1 1 14-1	must have FJ1/C01	70	70	50	50/	70	30
HH4	Thermotronic automatic climate control	\$337	\$227	\$337	\$337	\$337	\$337
1114	must have JF1; if +H13 must have H08/HK4	\$337	\$337	333/	3337	J33/	2231
LIVA		62.040	\$2.040	£2.040	\$2.040	¢2.040	\$2.040
HK4	Rear air conditioner, heavyduty	\$3,940	\$3,940	\$3,940	\$3,940	\$3,940	\$3,940
1170	must have D03+V36+D93; not with H08/ZB6/ZE6/N62/N63	1 4	00-0	Ac==	6536	4575	-
HZ9	Fuel-fired heater booster (18,000 BTU)	\$676	\$676	\$676	\$676	\$676	\$676
	not with H12	T	4	Arra	400	Al-e	4
J51·	Fuel gauge, optimized for aux. fuel tap	\$72	\$72	\$72	\$72	572	\$72
	not with HZ9/H12						
J52	Engine oil level display at cold start	\$0	\$0	\$0	50	\$0	\$0

		144" 6C	144" 4x4	170" 6C	170" 4x4	170" E 6C	170" E 4x4
		M2CA46	M2CA4X	M2CA76	M2CA7X	M2CAE6	M2CAEX
		907.643	907.643	907.645	907.645	907.647	907.647
A7	Blind Spot Assist	\$450	\$450	\$450	\$450	\$450	\$450
	must have F64; not with C01						
В4	Active Lane Keeping Assist	\$288	\$288	\$288	\$288	\$288	\$288
	standard with CO2/CA2						
186	Parking Package with 360 degree camera	\$775	\$775	\$775	\$775	\$775	\$775
	must have CO2/CO3/E3M; not with W75/W76/JB7						
В7	Parking Package	\$615	\$615	\$615	\$615	\$615	\$615
	must have CO2/CO3/E3M; not with W75/W76/JB6						
В8	360 Degree Camera	\$685	\$685	\$685	\$685	\$685	\$685
	SoP and Plausibility TBD						
F1	Rain sensor	\$106	\$106	\$106	\$106	\$106	\$106
	not with CO2/X11						
K5	Instrument cluster with color display	\$144	\$144	\$144	\$144	\$144	\$144
	standard with CO2/CA2						
W0	Backup alarm	\$99	\$99	\$99	\$99	\$99	\$99
W2	Deactivation lamp monitoring failure	\$27	\$27	\$27	\$27	\$27	\$27
W8	Attention Assist	\$49	\$49	\$49	\$49	\$49	\$49
(51	Misfueling prevention for Diesel	\$49	\$49	\$49	\$49	\$49	\$49
(52	DEF fluid filler cap - lockable	\$27	\$27	\$27	\$27	\$27	\$27
.13	Fog lamp with cornering light function	\$199	\$199	\$199	\$199	\$199	\$199
71	Light/motion sensor in rear compartment	\$54	\$54	\$54	\$54	\$54	\$54
	not with V36	***************************************			•		
B9	Illuminated front exits	\$151	\$151	\$151	\$151	\$151	\$151
C4	Comfort overhead control panel	\$93	\$93	\$93	\$93	\$93	\$93
C2	LED light strip in load compartment	\$263	\$263	\$263	\$263	\$263	\$263
	not with H08/HK4/V36/C06						
/120	Speed limitation 65 mph	\$60	\$60	\$60	\$60	\$60	\$60
	not with MD3						
AD3	Top speed limitation 75 mph	\$60	\$60	\$60	\$60	\$60	\$60
	not with M20						
162	Front engine bracket for additional alternator	\$467	\$467	\$467	\$467	\$467	\$467
	not with HK4/N63						
163	Front engine bracket for auxiliary A/C compressor	\$467	\$467	\$467	\$467	\$467	\$467
	not with HK4/N62						
93	Omission of D-rings	-\$15	-\$15	-\$15	-\$15	-\$15	-\$15
	not with D93/V43/VK8			33312			
224	Trailer hitch, 5,000 lbs	\$147	\$147	\$147	\$147	\$147	\$147
	not with W73/W75/W76						
QA9	Half-sided step rear (for trailer hitch)	\$101	\$101	\$101	\$101	\$101	\$101
	must have Q24/QA2; not with W73/W75/W76					La Contraction	
91	Spare tire deletion	-\$110	-\$110	-\$110	-\$110	-\$110	-\$110
	must have R92; not with R87				,	Ţ	
192.	Spare tire carrier deletion	\$0	\$0	\$0	\$0	\$0	\$0
	must have R91; not with R65			3.2	337		- P (4)
198	Rims painted jet black	\$81	\$81	\$81	\$81	\$81	\$81
	not with RL5/RM2	701	402	201	7	202	701
F1	Tire brand Continental	\$0	\$0	\$0	\$0	\$0	\$0
	must have RM1 + RM9			7.7	***		1000
F8	Tire brand Michelin	\$0	\$0	\$0	\$0	\$0	\$0
	must have RM9; not with RM1	γυ	70	- 40	90		90
H0	Tire brand Kumho	\$0	\$0	\$0	\$0	\$0	\$0
	must have RM9; not with RM1	70	70	1,0	90	70	1 99
L5	Light-alloy wheels 6.5 J x 16	\$906	\$906	\$906	\$906	\$906	\$906
رے	not with RS3/RM2/R98	2200	9000	9000	2300	۵۷۵۶	2300
M1	M+S winter tires	\$169	¢160	\$160	¢160	6160	¢160
(1X) T	must have RF1/RD9; not with RF8/RH0/X31	1 5103	\$169	\$169	\$169	\$169	\$169
RM2		\$81	\$81	\$81	\$81	\$81	\$81

		144" 6C	144" 4x4	170" 6C	170" 4x4	170" E 6C	170" E 4x4
		M2CA46	M2CA4X	M2CA76	M2CA7X	M2CAE6	M2CAEX
		907.643	907.643	907.645	907.645	907.647	907.647
RM9	Specially requested tires	\$101	\$101	\$101	\$101	\$101	\$101
	must have RF1/RF8/RH0; not with RD9						
23	Twin front passenger seat	\$400	\$400	\$400	\$400	\$400	\$400
	not with C00/X68/X01			,			
528	Armrest, driver and passenger door	\$51	\$51	\$51	\$51	\$51	\$51
62	Seat belts orange, driver and front passenger	\$32	\$32	\$32	\$32	\$32	\$32
	not with \$23						
В9	Driver's seat plus	\$238	\$238	\$238	\$238	\$238	\$238
	must have VF7; not with C00/X68/X69						
Z7	Storage net, driver's seat backrest	\$64	\$64	\$64	\$64	\$64	\$64
Z8	Storage net, passenger seat backrest	\$64	\$64	\$64	\$64	\$64	\$64
12	Sliding door two stage opening	\$82	\$82	\$82	\$82	\$82	\$82
	not with T55					**	
19	Sliding door, driver's side	\$935	\$935	\$935	\$935	\$935	\$935
	not with H13/H88/VC5/ZE6/F43/W16/F02; if +V36 must have Di	03					
50	Electric closing assist right sliding door	\$335	\$335	\$335	\$335	\$335	\$335
	must have DO3; not with T55/T93		h		***************************************	"	
51	Electric closing assist left sliding door	\$335	\$335	\$335	\$335	\$335	\$335
	must have T19 + D03						
55	Electric sliding door right	\$831	\$831	\$831	\$831	\$831	\$831
	must have D03 + (FY7+T16); not with T12/T50	111111111111111111111111111111111111111			***************************************		
57	Electric sliding step	\$1,071	\$1,071	\$1,071	\$1,071	\$1,071	\$1,071
	must have ED5; not with T93						
60	Opening limiter electrically operated sliding door	\$120	\$120	\$120	\$120	\$120	\$120
	must have T55						
74	Assist handle, B-pillar	\$32	\$32	\$32	\$32	\$32	\$32
	must have D93; not with T77						
75	Door-mounted assist handles, driver & passenger	\$59	S	\$59	S	\$59	S
77	Assist handle w/ partition	\$32	\$32	\$32	\$32	\$32	\$32
	must have D50/D51/D64						
85	Assist handle, left rear door	\$32	\$32	\$32	\$32	\$32	\$32
86	Assist handles, right rear door	\$32	\$32	\$32	\$32	\$32	\$32
93	Sliding door right side deletion	\$0	\$0	\$0	\$0	\$0	\$0
	not with T16/T50/T57/VK8/VC5						
/07	Cab rear wall liner	\$360	\$360	\$360	\$360	\$360	\$360
	must have (D50/D51)+F1K; standard with H04						
/21	Luxury interior Trim	\$661	\$661	\$661	\$661	\$661	\$661
	must have VA5/VA7; not with V52/VA1/VA3						
/24	Pallet support in sliding door step	\$96	\$96	\$96	\$96	\$96	\$96
	must have (V43/X66)+(D50/D51); not with VK8/V93/C07						
/25	Half height load compartment trim	\$201	\$201	\$201	\$201	\$201	\$201
	not with VA1/VA3/VA5/V52/X66						
/31	Window pillar trim	\$513	\$513	\$513	\$513	\$513	\$513
	must have V36 + (V21/VA1) + (F02/F03/F07); not with V42				//		
/35	Wheel house covering	\$105	\$105	\$105	\$105	\$105	\$105
	if +V43 must have V25/VA1/VA3; not with V52						
/36	Roof trim	\$876	\$876	\$876	\$876	\$876	\$876
	must have D93; not with D17/D22/H72/L65/L71/LC2/VA3/V42/	ZE6/(T93+-D03)/X66,	/C06/C07				
42	Lashing rails, waist level	\$277	\$277	\$277	\$277	\$277	\$277
	not with V36/ZE6				r		
43	Wood floor with 6 D-rings	\$422	\$422	\$422	\$422	\$422	\$422
	not with P93/V93/VL4/VK8/C07; standard with D93/H13/V24/V	/52/VC5/VV2/ZE6	,				
/48	Floor cover behind seat box	\$27	\$27	\$27	\$27	\$27	\$27
	must have D93; not with D50/D51/D56/D62/D64/V43/VK5			,		1	
/4A	Full paneling, right sliding door	\$109	\$109	\$109	\$109	\$109	\$109
	must have D03+T16+V21+VA5+W17; not with T19		,			1	T
_		\$375	\$375	\$375	\$375	\$375	\$375

		144" 6C	144" 4x4	170" 6C	170" 4x4	170" 4x4 170" E 6C	
		M2CA46	M2CA4X	M2CA76	M2CA7X	M2CAE6	M2CAEX
		907.643	907.643	907.645	907.645	907.647	907.647
V85	Cigarette lighter & ash cup, front	\$39	\$39	\$39	\$39	\$39	\$39
VA1	Side wall paneling waist height PVC	\$319	\$319	\$319	\$319	\$319	\$319
	must have VA5/VA7; not with V52	4013	4313	7313	2213	3313	2010
VA3	Side wall paneling full hardboard	\$444	\$444	\$444	\$444	\$444	\$444
	not with V36/F02; if T93 must have (D50/D51)	7 (1)	7111	9171) 	9777	- VTTT
VA5	Full paneling, hinged rear doors	\$38	\$38	\$38	\$38	\$38	\$38
	must have D03+VA7+(W61/W78); not with V25	750	400	230	450	430	200
VA7	Storage compart. w/ net in rear doors	\$127	\$127	\$127	\$127	\$127	\$127
	must have W61/W78; not with V52	1 7227	7127	9+21	7427	7441	7241
VC4	Cargo lashing rails, head height	\$415	\$415	\$415	\$415	\$415	\$415
	must have V42/C07/X66; not with ZE6	7.55	7.55	Ţ 120	4.00	Ų 130	V.125
/C5	Door sill - protective edge	\$71	\$71	\$71	\$71	\$71	\$71
	must have V43/X66; not with T19/T93/VK8/VV2/V93/C07	7.0	7.2	Y/-	412	4	71.1
/K8	Floor covering, plastic	\$370	\$370	\$370	\$370	\$370	\$370
	not with V43/P93/T19/T93/V52/VC5/X66	1 1 1 1 1 1	75.5	70.0	\$510	40.0	φ5.0
/V2	Lashing rails, floor level (plus 4 anchors)	\$270	\$270	\$345	\$345	\$377	\$377
	must have V43; not with V93/VC5/ZE6	V-10	V =.0	43.0	93 13	9517	9377
N16	2nd row, fixed window, driver side	\$145	\$145	\$145	\$145	\$145	\$145
	if D93 must have F43+W70; if D93 & standard roof CHS produ			72.0	41.0	70010	72.10
N17	2nd row, fixed window, passenger side	\$145	\$145	\$145	\$145	\$145	\$145
	if D93 must have F43+W70; if D93 & standard roof CHS produ		42.0	4.10	74,0	74.15	71.0
N33	FMVSS 217 emergency exit	\$379	\$379	\$379	\$379	\$379	\$379
	must have V31; not with D50/T19/W16		40.0	40.0	4013	9310	9373
N54	Rear doors, opening to side wall	\$360	\$360	\$360	\$360	S	S
-	90 Degree fixation point- Rear Doors	\$80	\$80	\$80	\$80	\$80	\$80
	SoP and Plausibility TBD		7.00	400	ÇCO	700	700
V61	Windows in rear doors	\$93	\$93	\$93	\$93	\$93	\$93
	must have VA7/ if D51 must have F61; not with W78/(W70+-		400	933	425	455	455
V70	Black tinting (90%) for rear windows	\$138	\$138	\$138	\$138	\$138	\$138
	not with W94; must have W16/W17/F02/((W61/W78)+H22);			7200	Ų130	9.50	7230
V73	Bumper step, rear, grey	\$187	\$187	\$187	\$187	\$187	\$187
	not with Q24/W75/W76	,,,,,,	7-07	720	y 20,	410 ,	7107
V75	Step, wide, at rear end	\$308	\$308	\$308	\$308	\$308	\$308
	not with JB6/JB7/Q24/QA9; must have R91+R92	, \$500	V300	\$500	4300	\$300	\$300
V76	Bumper step, rear, spring-loaded	\$601	-	\$601		\$601	
	must have R91+R92; not with JB6/JB7/X30/Q24	9002		\$001		9001	
V78	Heated rear window(s) w/ washers/wipers	\$335	\$335	\$335	\$335	\$335	\$335
	Must have H22+VA7 / if D51 must have F61; not with W61		V 000	4555	7555	4955	4000
2R	Conversion to RV requirement	\$0	\$0	\$0	\$0	\$0	\$0
	must have B01+D93+E1X		70	70 1	70	40	70
90	Deletion of Sprinter badge, left rear door	\$0	\$0	\$0	\$0	\$0	\$0
93	Deletion of model badge, right rear door	\$0	\$0	\$0	\$0	\$0	\$0
M4	Acoustic package	\$87	\$87	\$87	\$87	\$87	\$87
	standard with CO2/CO3	45.	407	501	70.71	50,	707
10	First-aid kit	\$27	\$27	\$27	\$27	\$27	\$27
26	Wheel chocks	\$38	\$38	\$38	\$38	\$38	\$38
	Emergency flashlight	\$27	\$27	\$27	\$27	\$27	\$27
_	Paint preservative	\$187	\$187	\$212	\$212	\$225	\$225
-	Surface protection for stock vehicles	\$315	\$315	\$315	\$315	\$315	\$315
	Cargo straps, D-rings	\$81	\$81	\$81	\$81	\$81	\$81
K4	Cargo straps, lashing rails	\$104	\$104	\$104	\$104	\$104	\$104
	must have V42/VV2; not with ZE6	7104	2104	7104	7104	7104	31 04
E6	Shelving prep	\$640	\$640	\$640	\$640	\$640	\$EAO
	not with T93/H13/T19/V36/V42/VC4/VK8/VV2/YK4	7040	2 040	304U	204 U	204U	\$640
H4	Downhill speed regulation for 4x4		\$58		\$58		enn.
1 1-1	oomman speed regardation for 4x4		220		220		\$58

144" 6C	144" 4x4	170" 6C	170" 4x4	170" E 6C	170" E 4x4
M2CA46	M2CA4X	M2CA76	M2CA7X	M2CAE6	M2CAEX
907.643	907.643	907.645	907.645	907.647	907.647
\$300	\$300	\$300	\$300	\$300	\$300
X	X	X	X	X	X
X	Х	X	X	X	Х
X	Х	X	Х	X	Х
Х	Х	X	X	X	Х
Х	Х	X	X	X	Х
Х	Х	X	X	X	Х
	M2CA46 907.643 \$300 X X X X X X X X X	M2CA46 M2CA4X 907.643 907.643 907.643	M2CA46 M2CA4X M2CA76 907.643 907.643 907.645 \$300 \$300 \$300 X X X X X X X X X X X X X X X X X X X X X X X X	M2CA46 M2CA4X M2CA76 M2CA7X 907.643 907.643 907.645 907.645 \$300 \$300 \$300 \$300 X X X X X X X X X X X X X X X X X X X X X X X X X X X X	M2CA46 M2CA4X M2CA76 M2CA7X M2CAE6 907.643 907.645 907.645 907.647 \$300 \$300 \$300 \$300 X X X X X X X X X X X X X X X X X X X X X X X X X X X X X X X X X X X X

COS C	Comfort Package (Seat addition)	\$381	\$381	\$381	\$381	\$381	\$381
SB1 C	Comfort driver's seat	X	Х	X	Х	X	X
SB2 C	Comfort passenger seat	X	Х	X	Х	X	X
must h	have COO						

X68	Comfort Plus Package	\$1,923	\$1,923	\$1,923	\$1,923	\$1,923	\$1,923
H15	Heated front passenger seat	X	Х	Х	X	X	X
H16	Heated driver's seat	X	Х	X	X	X	X
SF1	Driver's seat electrically adjustable	Х	Х	×	X	X	X
SF2	Co-driver's seat electrically adjustable	X	X	X	X	X	X

C01	Driver Convenience Package	\$760	\$760	\$760	\$760	\$760	\$760
E46	12 V power outlet, driver seat base	X	X	X	Х	X	X
F64	Electrically folding exterior mirrors	X	X	X	X	X	X
FJ1	Hinged lid for storage compartment	Х	X	X	X	X	X
FJ5	Hinged Lid for Storage Compartments left and right	Х	X	X	X	X	X
FZ9	Keys, two additional masters	X	X	X	X	X	X
	Blind Spot Assist	X	X	X	X	X	Х
W8	Attention Assist	Х	X	Х	X	X	Х

CO2 Premium Package	\$983	\$983	\$983	\$983	\$983	\$983
CL3 Leather steering wheel	X	Х	Х	X	X	Х
E3M MBUX Multimedia System with 7" touchscreen	X	X	X	Х	Х	X
FM3 Wet Wiper System .	X	X	X	X	X	Х
B4 Active Lane Keeping Assist	X	X	X	X	X	Х
IK5 Instrument cluster with color display	X	X	X	X	X	X

CAZ	C02 in combination with C03	\$604	\$604	\$604	\$604	\$604	\$604
CL3	Leather steering wheel	X	X	Х	Х	X	X
FM3	Wet Wiper System	X	X	Х	Х	X	X
B4	Active Lane Keeping Assist	X	X	X	X	Х	X
IK5	Instrument cluster with color display	X	X	X	X	X	X

2500 CARGO VAN - 6cyl Diesel

144" 6C	144" 4x4	170" 6C	170" 4x4	170" E 6C	170" E 4x4
M2CA46	M2CA4X	M2CA76	M2CA7X	M2CAE6	M2CAEX
907.643	907.643	907.645	907.645	907.647	907.647

C03	Premium Plus Package	\$1,793	\$1,793	\$1,793	\$1,793	\$1,793	\$1,793
E1B	Tray for smartphones incl. wireless charging	X	Х	Х	Х	Х	X
	Navigation	Х	Х	Х	X	X	X
EY2	Intelligent navigation	X	X	Х	X	X	X
E4M	MBUX Multimedia System with 10.25" touchscreen	X	X	X	X	X	X
EX9	Free map data updates for 3 years	Х	Х	Х	X	X	Х
H1I	Front-to-rear outlet in instrument panel	Х	Х	X	X	X	Х
JA9	Traffic Sign Assist	Х	X	X	X	X	X
XM4	Acoustic package	Х	Х	Х	X	Х	X
	have (CA2+(JB7/JB6/JB8)) OR (JB4+JK5+FM3+(JB7/JB6/JB	38)); not with FR8 ar	nd C02				

7 Chrome Grille Package	\$290	\$290	\$290	\$290	\$290	\$290
N2 Radiator grille frame in vehicle color	X	X	X	X	X	X
G Chrome plated radiator grille (MB only)	X	X	X	X	X	X

X13 Exterior Lighting Package		\$1,608	\$1,608	\$1,608	\$1,608	\$1,608	\$1,608
L13 Fog lamp with cornering light functi	on	X	Х	X	Х	Х	Х
L22 Partial LED tail lights		Х	Х	Х	Х	X	X
LA1 High beam assist		X	X	X	Х	X	X
LG7 LED high performance headlamps		X	Х	Х	Х	Х	Х

C06	Cargo Convenience Package	\$658	\$658	\$658	\$658	\$658	\$658
E36	Cutoff relay for additional battery	X	X	X	X	X	X
ES2	12 V power outlet, rear compartment	X	Х	X	X	X	X
LC2	LED light strip in load compartment	X	Х	X	Х	Х	X
T12	Sliding door two stage opening	X	Х	Х	Х	Х	X
T85	Assist handle, left rear door	X	Х	Х	X	X	X
T86	Assist handles, right rear door	X	Х	X	X	Х	Х
W54	Rear doors, opening to side wall	X	X	X	X	S	S

C 07	Cargo Protection Package	\$1,117	\$1,117	\$1,117	\$1,117	\$1,117	\$1,117
V25	Half height load compartment trim	X	Х	Х	X	X	Х
	Lashing rails, waist level	X	X	X	X	Х	X
VC4	Cargo lashing rails, head height	X	Х	X	X	Х	Х
VK8	Floor covering, plastic	X	X	X	X	Х	Х
УКЗ	Cargo straps, D-rings	X	X	X	X	Х	X
	vith X66				-		

X66	Heavy-Duty-Cargo Protection Package	\$2,043	\$2,043	\$2,043	\$2,043	\$2,043	\$2,043
V43	Wood floor with 6 D-rings	Х	Х	X	Х	X	Х
V42	Lashing rails, waist level	X	Х	X	X	X	X
V52	Loadable wheel arch	X	X	X	X	X	X
VA3	Side wall paneling full hardboard	X	Х	Х	Х	X	X
	Cargo lashing rails, head height	X	Х	X	Х	X	Х
VV2	Lashing rails, floor level (plus 4 anchors)	X	Х	X	X	X	X
YK3	Cargo straps, D-rings	X	Х	X	Х	X	X
YK4	Cargo straps, lashing rails	X	X	Х	X	X	Х
not v	vith CO7						

144" 6C	144" 4x4	170" 6C	170" 4x4	170" E 6C	170" E 4x4
M2CA46	M2CA4X	M2CA76	M2CA7X	M2CAE6	MZCAEX
907.643	907.643	907.645	907.645	907.647	907.647

X69	Swivel Seat Package	\$532	\$532	\$532	\$532	\$532	\$532
SR8	Swivel base for driver's seat	X	х	Х	X	X	X
SR9	Swivel base for front passenger seat	X	Х	X	X	X	Х
S87	Driver's seat frame, low	X	х	X	X	X	Х
588	Passenger seat frame, low	X	Х	X	X	Х	Х

X01	Suspension Seating Package	\$940	\$940	\$940	\$940	\$940	\$940
SB3	Driver suspension seat, comfort version	X	X	X	X	X	X
SB4	Passenger suspension seat, comfort version	Х	X	X	X	X	X
S87	Driver's seat frame, low	X	X	X	Х	X	Х
S88	Passenger seat frame, low	X	X	X	Х	Х	Х
not v	vith C00/C0S/E2I/X68/S23						