























COLOR AND  
OPTION PRICING  
FOR ALL 3500XD Models  
MXCA44 — MXCAEX

## Exterior Paint Overview

Code	Description	Price	Paint
1243	Calcite yellow	\$675	
3432	Sunset red	\$675	
3583	Velvet red	\$0	
3589	Jupiter red	\$0	
5362	Brilliant blue	\$675	
5389	Steel blue	\$0	
5524	Black blue	\$1,070	
5890	Cavansite blue metallic	\$1,070	
5957	Vanda blue	\$675	
6830	Aqua green	\$0	
7160	Stone grey	\$675	


Code	Description	Price	Paint
7701	Pebble grey	\$0	
7224	Graphite grey	\$675	
7708	Silver grey	\$675	
7709	Blue grey	\$0	
7755	Tenorite grey metallic	\$1,070	
7992	Selenite grey metallic	\$1,070	
9040	Jet black	\$1,070	
9136	Grey white	\$675	
9147	Arctic white	\$0	
9197	Obsidian black metallic	\$1,070	
9775	Iridiumsilver	\$1,070	

Please see NetStar for latest paint availability information.

Upholstery

Standard

VF7  
Fabric  
Maturin Black Upholstery



Optional

VF4  
Fabric  
Caluma Black Upholstery

Upcharge	
Cargo	\$ 60
Cab Chassis	\$ 60
Crew Van	\$ 205
Passenger Van	\$ 430



Optional

VF6  
Leatherette  
Black


Upcharge	
Cargo	\$ 60
Cab Chassis	\$ 60
Crew Van	\$ 205
Passenger Van	\$ 430



Seat restrictions

Code	Seat	Fabrics		
		VF7	VF4	VF6
	Standard Seats Front	S	O	O
	Standard Seats Rear	S	n/a	O
SF1/SF2	Power Seats	n/a	O	O
SB1/SB2	Comfort Seats Front	S	O	O
	Comfort Seats Rear	n/a	O	O

Front and rear fabric always have to match.



## Suspension Matrix

Cargo Van / Crew Van					
Standard	1500	2500	3500	3500XD	4500
	Base Suspension			CB8	CB8 + A50
Options	A50				-
	CB1 <i>(add to standard)</i>			-	
	CB7 <i>(moved to option)</i>			-	
	CB8 <i>(replacing standard)</i>			S	
	-	CB4 (Recommended for RV) - only 6cyl Diesel			
	CT1			-	
Specialized Options	CE8 <i>(not with 4x4 models)</i>				
	B01 <i>(not with 3500/3500XD/4500 144"WB)</i>				
	X2R <i>(not with 3500/3500XD/4500 144"WB)</i>				

Passenger			
Standard	1500	2500	
	144" WB	144" WB	170" WB
	Base Suspension + CB1 + CT1		Base Suspension + CB1 + CT1 + A50

Cab Chassis		
Standard	3500XD	4500
	CB8	CB8 + A50
Options	CB4	
	A50	-
Specialized Options	CE8 (not on 144"WB models)	
	B01 (not with 3500XD/4500 144"WB)	
	X2R (not with 3500XD/4500 144"WB)	

## Suspension Details

Standard Suspensions and Options			
Code	Title	Details	
A50	Front axle reinforced	Includes an increased load capacity of the front axle, where heavier bodies and equipment can be fitted. The higher capacity front axle caters to heavier cabs and heavier special equipment (e.g. for fire-fighting vehicles and ambulances).	
No Factory Code	Base Standard Factory Suspension	Description	Ride comfort due to reduced roll stabilization.
		Benefit	The Base Standard Factory suspension, has an adapted front suspension for a lower and more comfortable entry. With the removal of the rear stabilization bar it allows for an overall comfortable ride with reduced roll.
CB7	Stabilization Level I	Description	Roll Stabilization with height body damping
		Benefit	CB7 compensates for rolling behavior due to higher center of gravity of loads or bodies. Torsion bars with an increased diameter are added to the front and rear axels. Furthermore, shock absorbers with an adapted characteristic are installed.
CB8	Stabilization Level II	Description	Enhanced roll stabilization with higher body damping compared to CB7
		Benefit	Additional roll stabilization and body damping compared to CB7. Increases torsion bar diameters at the front and rear axles and provides an adapted shock absorber characteristic. Furthermore, rear axle springs with increased rigidity are installed.
CB4	Stabilization Level III	Description	Designed for vans with a intense rolling behavior due to a much heavier load and higher center of gravity. (i.e. recreational vehicles)
		Benefit	CB4 comes with larger diameter stabilizers, shock absorbers and with characteristics that are adapted for an increased rebound and compression curve. Furthermore, the leaf springs are increased in rigidity.
CB1	Suspension for comfort and load protection	Enhanced comfort due to adapted damper characteristics and the use of progressive spring characteristics.	
CT1	Rear spring vibration absorbers	Includes vibration absorbers fitted on the left and right rear spring and lowers the resonant vibrations of the rear springs, thus hindering noise development.	

Specialized Suspension Options			
Code	Title	Explanation	
CE8	Raised rear body mounts	Raised body on rear axle (35mm/1.4")	
B01	ESP for increased Center of Gravity	Description	Adjusted braking and handling characteristics for vehicles with increased center of gravity.
		Benefit	With code B01, the ESP® is optimized to reduce the vehicles tilt tendency with a total center of gravity of <u>more than 1000 mm (39.4 inches)</u> . It is essential to ensure that the vehicle is equipped with the right suspension and tires. With B01 it is required to also add CB8 or CB4.
X2R	Conversion to RV requirement	MBUX Timed Switch-off extended to 6 hours and B01 is automatically added to this code.	

## Rear view camera/head unit plausibility

CA/PV/CV					
	Standard	Option A	Option A + JB7	Option A + JB6	Option A + JB8
Radio/HU	E1O	E3M/E4M	E3M/E4M	E3M/E4M	E3M/E4M
Camera	FR3	FR8	integrated camera	integrated 360 degree camera	integrated 360 degree camera
Pre-wiring Camera	n/a	n/a	n/a	n/a	n/a
Camera Display	Interior rear view mirror	7/10.25" Screen	7/10.25" Screen	7/10.25" Screen	7/10.25" Screen

Options shown above lead to an upcharge.

CC			
	Standard	Option A	Option B
Radio/HU	E1O	E1O	E3M/E4M
After-Sales Camera	-	Any analog* Camera	Mercedes-Benz Camera** (digital)
Pre-wiring	-	FV1	FR7
Rear-View Display	-	Interior rear view mirror	7/10.25" Screen

Options shown above lead to an upcharge.

\*only cameras with analog signal works

\*\*only the Mercedes-Benz rear view camera works (digital signal)

## Cargo Van Floor Variations

Standard	V93	Without factory installed flooring
Options	V43	Wood floor with 6 D-rings
	VK8	Floor covering, plastic

Note: see restrictions in combination with metallic paint

### Special Rule for cargo vans with metallic paint

Paint Code	5890/7755/7992/9197/9775	
Must have one of	V43	Wood floor with 6 D-rings
	VK8	Floor covering, plastic
	ZZ9	No floor covering; requires customer floor installation
		Package contains: V93 - No factory installed flooring VL4 - Metallic painted floor

Note: Fleet only

### Additional comments ZZ9 Package

While applying the required clear coat layer to the metallic painted cargo floor, imperfections could occur. Therefore, we strongly recommend to install flooring in the cargo area for vehicles with a metallic paint.

Please be aware that potential paint appearance, contamination or imperfections of the uncovered cargo floor are not considered a defect and are therefore not reimbursable for repairs.

## Tire & Wheel Overview

		1500/2500 Models		
		Standard Tire	RH8	Single tire
		Standard Wheel	RS3	Steel
		Optional Wheel	RL5	Alloy
		Brand Options		
		RM0 All-season tires	RM1 M+S tires	
RD9	Tire brand, unspecified	S	O	
RF8	Michelin	O	n/a	
RF1	Continental	n/a	O	
RH0	Kumho	O	n/a	

To order any of the tire brands above code RM9 has to be added to order.

		3500/3500XD Models			
		Standard: Dual Rear Wheel		Optional: Super Single	
		Standard Tire	RH7	Standard Tire	R9A
		Standard Wheel	RS6	Standard Wheel	RS5
		Brand Options		Brand Options	
		RM0 All-season tires	RM1 M+S tires	RM0 All-season tires	RM1 M+S tires
RD9	Tire brand, unspecified	O	O	S	n/a
RF8	Michelin	O	n/a	n/a	n/a
RF1	Continental	O	O	O	n/a
RH0	Kumho	n/a	n/a	n/a	n/a

To order any of the tire brands above code RM9 has to be added to order.

Standard is DRW, Option is Super Single

		4500 Models		Dual Rear Wheel Steel
		Standard Tire	RH7	
		Standard Wheel	RS6	
		Brand Options		
		RM0 All-season tires	RM1 M+S tires	
RD9	Tire brand, unspecified	S	O	
RF8	Michelin	O	n/a	
RF1	Continental	O	O	
RH0	Kumho	n/a	n/a	

To order any of the tire brands above code RM9 has to be added to order.

		144" 4C	170" 4C	170" E 4C
		MXCA44	MXCA74	MXCAE4
		907.653	907.655	907.657
<b>Engine</b>				
<b>4-Cyl Engine/7-Speed Trans.</b>		<b>S</b>	<b>S</b>	<b>S</b>
ED4	AGM battery 12V 92 AH 850 A	S	S	S
G42	Automatic transmission, 7G-tronic	S	S	S
M40	Alternator 14 V / 200 A	S	S	S
MG3	2.0L 4-cylinder diesel engine	S	S	S
MH8	SULEV emissions	S	S	S
<b>Tires - choose while ordering</b>				
<b>X34 Dual Rear Wheel</b>		<b>\$0</b>	<b>\$0</b>	<b>\$0</b>
RH7	Tires LT 215/85 R16	S	S	S
RS6	5.5 J x 16 steel wheels	S	S	S
RD9	Unspecified tire brand	S	S	S
<b>X31 Super Single Tire</b>		<b>\$385</b>	<b>\$385</b>	<b>\$385</b>
R9A	285/65 R 16 C super single tires	O	O	O
RS5	Steel wheels: 8.5Jx16 Rr; 6.5Jx16 Lr	O	O	O
RD9	Unspecified tire brand	O	O	O
RY2	Tire pressure monitoring sensors	O	O	O
<b>Equipment</b>				
AR3	Axle ratio 4.182	S	S	S
BA3	Active Brake Assist	S	S	S
BH1	Hold Function	S	S	S
C6L	Multifunction steering wheel	S	S	S
CB8	Stabilization Level II	S	S	S
CL1	Adjustable steering wheel (angle)	S	S	S
D03	High roof	O	S	S
D93	Omission bulkhead	S	S	S
E07	Hill Start Assist	S	S	S
E10	Standard radio	S	S	S
E1U	USB-C socket, 5 V	S	S	S
E30	Starter battery disconnect	S	S	S
E3J	Pre-installation for switch panel	S	S	S
E40	Trailer hitch prep. wiring	S	S	S
ED8	Preinstallation PSM	S	S	S
EE5	Ultracapacitor discharge module	S	S	S
EK1	Body Builder Connector	S	S	S
ES0	Jump start terminal	S	S	S
EW6	Pre-installation for Mercedes me Remote Services	S	S	S
EY5	Emergency Call System	S	S	S
EY6	Breakdown management	S	S	S
F68	Heated & electrically adjustable exterior mirrors	S	S	S
FF5	Shelf above windshield	S	S	S
FG8	Cupholder front	S	S	S
FI1	Remote key (315 mhz) w/central locking	S	S	S
FJ4	Storage compartment underneath cockpit	S	S	S
FR3	Rear view camera (rear-view mirror display)	S	S	S
H21	Windshield with filter band	S	S	S
HH2	Heater, auxiliary electric hot air	S	S	S
HH9	Air Condition, Front	S	S	S
IH7	Head Unit, North America	S	S	S
J11	Speedometer, miles and km/h	S	S	S
J55	Seat belt warning for co-driver seat	S	S	S
J58	Seat belt reminder driver	S	S	S
J65	Outside temperature gauge	S	S	S
JA8	Crosswind Assist	S	S	S
JH3	Communication module (LTE) for dig. services	S	S	S
JI9	Service interval 20.000 miles	S	S	S
K56	Red diesel filler cap	S	S	S
K60	Exhaust straight to rear	S	S	S

		144" 4C	170" 4C	170" E 4C
		MXCA44	MXCA74	MXCAE4
		907.653	907.655	907.657
KB7	24.5 gallon fuel tank	S	S	S
KL1	Aux fuel sending unit w/ fuel tap	S	S	S
KL5	Fuel filter with water separator	S	S	S
KP6	3rd generation SCR emission control system	S	S	S
L65	Interior lights, cargo compartment	S	S	S
L94	Parking lights deletion	S	S	S
LA2	Headlight assistant	S	S	S
LB5	3rd brake light	S	S	S
MS1	Cruise control	S	S	S
P47	Front mudflaps	S	S	S
P48	Rear mudflaps	S	S	S
Q11	Longitudinal member reinforcement	S	S	S
R65	Spare tire bracket below frame	S	S	S
R87	Spare tire	S	S	S
RM0	All-season tires	S	S	S
S02	Standard driver seat	S	S	S
S04	Standard front passenger seat	S	S	S
S22	Armrest for driver's seat	S	S	S
S25	Armrest for front passenger seat	S	S	S
SA5	Front airbag, driver	S	S	S
SA6	Front airbag, passenger	S	S	S
SH1	Thorax-pelvis sidebag, driver	S	S	S
SH2	Thorax-pelvis sidebag, co-driver	S	S	S
SH9	Airbag, driver/passenger window	S	S	S
SK2	Seat occupancy sensor, driver's seat	S	S	S
T16	Sliding door, passenger side	S	S	S
V93	Without factory installed flooring	S	S	S
V94	Cable duct - side wall	S	S	S
V95	Cable duct - rear portal	S	S	S
W54	Rear doors, opening to side wall	O	O	S
X5G	Without load uprating/derating 5,000 kg	S	S	S
Y43	Jack, hydraulic	S	S	S



## Options

		144" 4C	170" 4C	170" E 4C
		MXCA44	MXCA74	MXCAE4
		907.653	907.655	907.657
A50	Front axle reinforced	\$346	\$346	\$346
AP2	Addtl. bar for driveshaft & exhaust extension	\$69	\$69	-
AR2	Axle ratio 3.923	\$0	\$0	\$0
	<i>not with AR3</i>			
B01	ESP for increased Center of Gravity above 39.4"	-	\$0	\$0
	<i>must have CB4/CB8/X30; not with RH0/CB7</i>			
BE2	Handbrake lever, folding	\$55	\$55	\$55
	<i>X69 must have BE2</i>			
C72	Bumpers front/rear primed	\$268	\$268	\$268
	<i>must have CN2 (part of X67), not with CM0</i>			
CE8	Raised rear body mounts	\$252	\$252	\$252
CL3	Leather steering wheel	\$187	\$187	\$187
	<i>must have (C02/E3M)/C03 + (ET4/MS1)</i>			
CM0	Painted metallic front & rear bumper	\$587	\$587	\$587
	<i>must have (CN2/X67) + (JA7/C01) + JB7 + (7755/9197/9775)</i>			
CM9	Primed side moldings	\$364	\$364	\$364
D03	High roof	\$2,900	\$	\$
D13	Mounting rails for roof rack	\$300	\$300	\$300
D22	Fixed sunroof (rear roof section)	\$336	\$336	\$336
	<i>not with H08/HK4/H72/V36/ZK4</i>			
D50	Cargo partition	\$288	\$288	\$288
	<i>not with D51/D93/H08/HK4/T74/V36; must have one of T93/T77</i>			
D51	Cargo partition with 1 window	\$335	\$335	\$335
	<i>not with D50/D93/H08/HK4/T74/V37/D17; must have one of T93/T77</i>			
E1B	Tray for smartphones incl. wireless charging	\$156	\$156	\$156
	<i>must have C02/E3M + H1I</i>			
E1E	Navigation	\$728	\$728	\$728
	<i>must have C02/E3M, not with C03</i>			
E1S	Sirius XM, satellite radio	\$255	\$255	\$255
	<i>must have C02/E3M/C03</i>			
E1X	MBUX multimedia 6-hour runtime	-	\$0	\$0
	<i>must have X2R + (C02+E1E/E1S)/C03/(E3M+E1E/E1S)</i>			
E1R	Additional Fuses (40/80/150/100 Ampere)	\$50	\$50	\$50
	<i>SoP and Plausibility TBD</i>			
E1Y	Additional Fuses (40/80/80/100 Ampere)	\$50	\$50	\$50
	<i>SoP and Plausibility TBD</i>			
E2A	Access point for BB special signals in cockpit	\$29	\$29	\$29
E2I	Additional battery, co-driver seat base	\$248	\$248	\$248
	<i>must have E36/C06; not with E2M/F09; CHS production only</i>			
E2M	Additional battery, engine compartment	\$248	\$248	\$248
	<i>must have X01+ (E36/C06); not with E2I/X69/F09</i>			
E3M	MBUX Multimedia System with 7" touchscreen	\$474	\$474	\$474
	<i>not with C02/C03; must have JK5+(JB7/FR8)</i>			
E36	Cutoff relay for additional battery	\$110	\$110	\$110
	<i>standard with E2I/E2M</i>			
E46	12 V power outlet, driver seat base	\$92	\$92	\$92
E5M	Extension of PSM standard contact	\$58	\$58	\$58
ED5	Parametric special module (PSM)	\$317	\$317	\$317
	<i>not with ED8</i>			
EE3	115 V socket	\$125	\$125	\$125
EP7	Basic electric fitting for rear loudspeakers	\$68	\$68	\$68
ES2	12 V power outlet, rear compartment	\$92	\$92	\$92
ES5	Charging package, dashboard	\$82	\$82	\$82
ET4	Active Distance Assist DISTRONIC	\$263	\$263	\$263
	<i>must have C02/C03/E3M; not with ZH4</i>			
F1K	Coat hooks in driver cabin	\$14	\$14	\$14
	<i>must have D50/D51</i>			

## Options

		144" 4C	170" 4C	170" E 4C
		MXCA44	MXCA74	MXCAE4
		907.653	907.655	907.657
F49	Electrically heated windshield	\$218	\$218	\$218
	<i>no restriction</i>			
F61	Interior rear view mirror	\$36	\$36	\$36
	<i>not with D50; must have C02/E3M/C03</i>			
FE9	Additional DIN-slot	\$81	\$81	\$81
FF4	Storage compartment above cabin	\$186	\$186	\$186
	<i>must have D03, not with D17/D64/H08/HK4</i>			
FF8	Overhead storage slot, front center	\$105	\$105	\$105
FJ1	Hinged lid for storage compartment	\$93	\$93	\$93
FR8	Rear view camera (head unit display)	\$336	\$336	\$336
	<i>must have C02/E3M; not with FR3/JB7; 3500XD not with JB8</i>			
FY1	Security alarm w. interior motion sensor	\$584	\$584	\$584
	<i>must have LC4/C00</i>			
FY7	Optional 3-button keys	\$36	\$36	\$36
FZ9	Keys, two additional masters	\$121	\$121	\$121
H00	Warm/cool air duct to rear compartment	\$59	\$59	\$59
	<i>not with D50/D51/Y2A</i>			
H01	Heat insulation, rear compartment	\$156	\$156	\$156
	<i>must have V21/V25/VA3/VA1/C07/X66</i>			
H04	Heat insulation, front compartment	\$187	\$187	\$187
	<i>if + D50/D51 must have V07</i>			
H08	Air conditioning rear, roof-mounted	\$2,872	\$2,872	\$2,872
	<i>must have D93 +V36; not with HK4/C06/X66/C07</i>			
H12	Fuel-fired pre-heater/booster (17K BTU)	\$1,116	\$1,116	\$1,116
	<i>not with HZ9</i>			
H13	Rear cabin heater and vents	\$786	\$786	\$786
	<i>must have H12/HZ9</i>			
H15	Heated front passenger seat	\$284	\$284	\$284
	<i>must have H16; not with X68</i>			
H16	Heated driver's seat	\$284	\$284	\$284
	<i>must have H15; not with X68</i>			
H22	Rear window defroster	\$253	\$253	\$253
	<i>must have W61/W78; standard for W61+W70</i>			
H72	Roof fan, electric	\$400	\$400	\$400
	<i>not with D22/V36</i>			
H88	Rear heater prep	\$405	\$405	\$405
	<i>must have H12/HZ9; not with H13/T19</i>			
H11	Front-to-rear outlet in instrument panel	\$0	\$0	\$0
	<i>must have FJ1/C01</i>			
HH4	Thermotronic automatic climate control	\$337	\$337	\$337
	<i>must have JF1; if +H13 must have H08/HK4</i>			
HK4	Rear air conditioner, heavyduty	\$3,940	\$3,940	\$3,940
	<i>must have D03+V36+D93; not with H08/ZB6/ZE6/N62/N63</i>			
HZ9	Fuel-fired heater booster (18,000 BTU)	\$676	\$676	\$676
	<i>not with H12</i>			
J51	Fuel gauge, optimized for aux. fuel tap	\$72	\$72	\$72
	<i>not with HZ9/H12</i>			
J52	Engine oil level display at cold start	\$0	\$0	\$0
JA7	Blind Spot Assist	\$450	\$450	\$450
	<i>not with C01</i>			
JB4	Active Lane Keeping Assist	\$288	\$288	\$288
	<i>standard with C02/CA2</i>			
JB7	Parking Package	\$615	\$615	\$615
	<i>must have C02/C03/E3M; not with W75/W76/JB6</i>			
JF1	Rain sensor	\$106	\$106	\$106
JK5	Instrument cluster with color display	\$144	\$144	\$144
	<i>standard with C02/CA2</i>			
JW0	Backup alarm	\$99	\$99	\$99

## Options

		144" 4C	170" 4C	170" E 4C
		MXCA44	MXCA74	MXCAE4
		907.653	907.655	907.657
JW2	Deactivation lamp monitoring failure	\$27	\$27	\$27
JW8	Attention Assist	\$49	\$49	\$49
K51	Misfueling prevention for Diesel	\$49	\$49	\$49
K52	DEF fluid filler cap - lockable	\$27	\$27	\$27
L13	Fog lamp with cornering light function	\$199	\$199	\$199
L71	Light/motion sensor in rear compartment	\$54	\$54	\$54
	<i>not with V36</i>			
LB9	Illuminated front exits	\$151	\$151	\$151
LC2	LED light strip in load compartment	\$263	\$263	\$263
	<i>not with H08/HK4/V36/C06</i>			
LC4	Comfort overhead control panel	\$93	\$93	\$93
M20	Speed limitation 65 mph	\$60	\$60	\$60
	<i>not with MD3</i>			
MD3	Top speed limitation 75 mph	\$60	\$60	\$60
	<i>not with M20</i>			
N62	Front engine bracket for additional alternator	\$467	\$467	\$467
	<i>not with HK4/N63</i>			
N63	Front engine bracket for auxiliary A/C compressor	\$467	\$467	\$467
	<i>not with HK4/N62</i>			
P93	Omission of D-rings	-\$15	-\$15	-\$15
	<i>not with D93/V43/VK8</i>			
QA2	Trailer cross member 7,500 lbs capacity	\$186	\$186	-
	<i>not with W73/W75/W76/Q24/Q67</i>			
QA9	Half-sided step rear (for trailer hitch)	\$101	\$101	\$101
	<i>must have QA2; not with W73/W75/W76</i>			
Q24	Trailer hitch, 5,000 lbs	-	-	\$147
	<i>not with W73/W75/W76</i>			
R91	Spare tire deletion	-\$110	-\$110	-\$110
	<i>must have R92; not with R87</i>			
R92	Spare tire carrier deletion	\$0	\$0	\$0
	<i>must have R91; not with R65</i>			
R98	Rims painted jet black	\$81	\$81	\$81
	<i>not with RL5/RM2</i>			
RF1	Tire brand Continental	\$0	\$0	\$0
	<i>must have RM1 + RM9</i>			
RF8	Tire brand Michelin	\$0	\$0	\$0
	<i>must have RM9; not with RM1</i>			
RH0	Tire brand Kumho	\$0	\$0	\$0
	<i>must have RM9; not with RM1</i>			
RM1	M+S winter tires	\$169	\$169	\$169
	<i>must have RF1/RD9; not with RF8/RH0/X31</i>			
RM2	Rims painted arctic white	\$81	\$81	\$81
	<i>not with R98/RL5</i>			
RM9	Specially requested tires	\$101	\$101	\$101
	<i>must have RF1/RF8/RH0; not with RD9</i>			
S23	Twin front passenger seat	\$400	\$400	\$400
	<i>not with C00/X68/X01</i>			
S28	Armrest, driver and passenger door	\$51	\$51	\$51
S62	Seat belts orange, driver and front passenger	\$32	\$32	\$32
	<i>not with S23</i>			
SB9	Driver's seat plus	\$238	\$238	\$238
	<i>must have VF7; not with C00/X68/X69</i>			
S27	Storage net, driver's seat backrest	\$64	\$64	\$64
S28	Storage net, passenger seat backrest	\$64	\$64	\$64
T12	Sliding door two stage opening	\$82	\$82	\$82
	<i>not with T55</i>			
T19	Sliding door, driver's side	\$935	\$935	\$935
	<i>not with H13/H88/VCS/ZE6/F43/W16/F02; if +V36 must have D03</i>			

## Options

		144" 4C	170" 4C	170" E 4C
		MXCA44	MXCA74	MXCAE4
		907.653	907.655	907.657
T50	Electric closing assist right sliding door <i>must have D03; not with T55/T93</i>	\$335	\$335	\$335
T51	Electric closing assist left sliding door <i>must have T19 + D03</i>	\$335	\$335	\$335
T55	Electric sliding door right <i>must have D03 + (FY7+T16); not with T12/T50</i>	\$831	\$831	\$831
T57	Electric sliding step <i>must have ED5; not with T93</i>	\$1,071	\$1,071	\$1,071
T60	Opening limiter electrically operated sliding door <i>must have T55</i>	\$120	\$120	\$120
T74	Assist handle, B-pillar <i>must have D93; not with T77</i>	\$32	\$32	\$32
T75	Door-mounted assist handles, driver & passenger	\$59	\$59	\$59
T77	Assist handle w/ partition <i>must have D50/D51/D64</i>	\$32	\$32	\$32
T85	Assist handle, left rear door	\$32	\$32	\$32
T86	Assist handles, right rear door	\$32	\$32	\$32
T93	Sliding door right side deletion <i>not with T16/T50/T57/VK8/VC5</i>	\$0	\$0	\$0
V07	Cab rear wall liner <i>must have (D50/D51)+F1K; standard with H04</i>	\$360	\$360	\$360
V21	Luxury interior Trim <i>must have VA5/VA7; not with V52/VA1/VA3</i>	\$661	\$661	\$661
V24	Pallet support in sliding door step <i>must have (V43/X66)+(D50/D51); not with VK8/V93/C07</i>	\$96	\$96	\$96
V25	Half height load compartment trim <i>not with VA1/VA3/VA5/V52/X66</i>	\$201	\$201	\$201
V31	Window pillar trim <i>must have V36 + (V21/VA1) + (F02/F03/F07); not with V42</i>	\$513	\$513	\$513
V35	Wheel house covering <i>if +V43 must have V25/VA1/VA3; not with V52</i>	\$105	\$105	\$105
V36	Roof trim <i>must have D93; not with D17/D22/H72/L65/L71/LC2/VA3/V42/ZE6/(T93+-D03)/X66/C06/C07</i>	\$876	\$876	\$876
V42	Lashing rails, waist level <i>not with V36/ZE6</i>	\$277	\$277	\$277
V43	Wood floor with 6 D-rings <i>not with P93/V93/VL4/VK8/C07; standard with D93/H13/V24/V52/VC5/VV2/ZE6</i>	\$422	\$422	\$422
V48	Floor cover behind seat box <i>must have D93; not with D50/D51/D56/D62/D64/V43/VK5</i>	\$27	\$27	\$27
V4A	Full paneling, right sliding door <i>must have D03+T16+V21+VA5+W17; not with T19</i>	\$109	\$109	\$109
V85	Cigarette lighter & ash cup, front	\$39	\$39	\$39
VA1	Side wall paneling waist height PVC <i>must have VA5/VA7; not with V52</i>	\$319	\$319	\$319
VA3	Side wall paneling full hardboard <i>not with V36/F02; if T93 must have (D50/D51)</i>	\$444	\$444	\$444
VA5	Full paneling, hinged rear doors <i>must have D03+VA7+(W61/W78); not with V25</i>	\$38	\$38	\$38
VA7	Storage compart. w/ net in rear doors <i>must have W61/W78; not with V52</i>	\$127	\$127	\$127
VC4	Cargo lashing rails, head height <i>must have V42/C07/X66; not with ZE6</i>	\$415	\$415	\$415
VC5	Door sill - protective edge <i>must have V43/X66; not with T19/T93/VK8/VV2/V93/C07</i>	\$71	\$71	\$71
VK8	Floor covering, plastic <i>not with V43/P93/T19/T93/V52/VC5/X66</i>	\$370	\$370	\$370
VV2	Lashing rails, floor level (plus 4 anchors) <i>must have V43; not with V93/VC5/ZE6</i>	\$270	\$345	\$377

		144" 4C	170" 4C	170" E 4C
		MXCA44	MXCA74	MXCAE4
		907.653	907.655	907.657
W16	2nd row, fixed window, driver side	\$145	\$145	\$145
	<i>if D93 must have F43+W70; if D93 &amp; standard roof CHS production required</i>			
W17	2nd row, fixed window, passenger side	\$145	\$145	\$145
	<i>if D93 must have F43+W70; if D93 &amp; standard roof CHS production required</i>			
W33	FMVSS 217 emergency exit	\$379	\$379	\$379
	<i>must have V31; not with D50/T19/W16</i>			
W54	Rear doors, opening to side wall	\$360	\$360	\$
W5F	90 Degree fixation point- Rear Doors	\$80	\$80	\$80
	<i>SoP and Plausibility TBD</i>			
W61	Windows in rear doors	\$93	\$93	\$93
	<i>must have VA7/ if D51 must have F61; not with W78/(W70+-(H22/F02))</i>			
W70	Black tinting (90%) for rear windows	\$138	\$138	\$138
	<i>not with W94; must have W16/W17/F02/((W61/W78)+H22); standard with F43/W33/F07</i>			
W73	Bumper step, rear, grey	\$187	\$187	\$187
	<i>not with QA2/W75/W76</i>			
W75	Step, wide, at rear end	\$308	\$308	\$308
	<i>not with JB6/JB7/Q24/QA9; must have R91+R92</i>			
W76	Bumper step, rear, spring-loaded	-	\$601	\$601
	<i>must have R91+R92; not with JB6/JB7/X30/Q24</i>			
W78	Heated rear window(s) w/ washers/wipers	\$335	\$335	\$335
	<i>Must have H22+VA7 / if D51 must have F61; not with W61</i>			
X90	Deletion of Sprinter badge, left rear door	\$0	\$0	\$0
X93	Deletion of model badge, right rear door	\$0	\$0	\$0
X2R	Conversion to RV requirement	-	\$0	\$0
	<i>must have B01+D93+E1X</i>			
XM4	Acoustic package	\$87	\$87	\$87
	<i>standard with C02/C03</i>			
Y10	First-aid kit	\$27	\$27	\$27
Y26	Wheel chocks	\$38	\$38	\$38
Y45	Emergency flashlight	\$27	\$27	\$27
Y68	Paint preservative	\$187	\$212	\$225
Y69	Surface protection for stock vehicles	\$315	\$315	\$315
YK3	Cargo straps, D-rings	\$81	\$81	\$81
YK4	Cargo straps, lashing rails	\$104	\$104	\$104
	<i>must have V42/VV2; not with ZE6</i>			
ZE6	Shelving prep	\$640	\$640	\$640
	<i>not with T93/H13/T19/V36/V42/VC4/VK8/VV2/YK4</i>			

		144" 4C	170" 4C	170" E 4C
		MXCA44	MXCA74	MXCAE4
		907.653	907.655	907.657
<b>C00</b>	<b>Comfort Package</b>	<b>\$300</b>	<b>\$300</b>	<b>\$300</b>
LC4	Comfort overhead control panel	X	X	X
SE4	Lumbar support, co-driver's seat	X	X	X
SE5	Lumbar support, driver's seat	X	X	X
SK0	Comfort head restraint, driver	X	X	X
SK1	Comfort head restraint, co-driver	X	X	X
S28	Armrest, driver and passenger door	X	X	X
<i>must have C05 OR X68; CA/CC only: not with S23</i>				

<b>C05</b>	<b>Comfort Package (Seat addition)</b>	<b>\$381</b>	<b>\$381</b>	<b>\$381</b>
SB1	Comfort driver's seat	X	X	X
SB2	Comfort passenger seat	X	X	X
<i>must have C00</i>				

<b>X68</b>	<b>Comfort Plus Package</b>	<b>\$1,923</b>	<b>\$1,923</b>	<b>\$1,923</b>
H15	Heated front passenger seat	X	X	X
H16	Heated driver's seat	X	X	X
SF1	Driver's seat electrically adjustable	X	X	X
SF2	Co-driver's seat electrically adjustable	X	X	X
<i>must have C00 and VF4 OR VF6, CA/CC only: not with S23</i>				

<b>C01</b>	<b>Driver Convenience Package</b>	<b>\$760</b>	<b>\$760</b>	<b>\$760</b>
E46	12 V power outlet, driver seat base	X	X	X
F64	Electrically folding exterior mirrors	X	X	X
FJ1	Hinged lid for storage compartment	X	X	X
FJ5	Hinged Lid for Storage Compartments left and right	X	X	X
FZ9	Keys, two additional masters	X	X	X
JA7	Blind Spot Assist	X	X	X
JW8	Attention Assist	X	X	X

<b>C02</b>	<b>Premium Package</b>	<b>\$983</b>	<b>\$983</b>	<b>\$983</b>
CL3	Leather steering wheel	X	X	X
E3M	MBUX Multimedia System with 7" touchscreen	X	X	X
FM3	Wet Wiper System	X	X	X
JB4	Active Lane Keeping Assist	X	X	X
JK5	Instrument cluster with color display	X	X	X
<i>Ordering availability restricted, see NetStar for availability and restrictions   must have JF1 + XM4; must choose FR8/JB7</i>				

<b>CA2</b>	<b>C02 in combination with C03</b>	<b>\$604</b>	<b>\$604</b>	<b>\$604</b>
CL3	Leather steering wheel	X	X	X
FM3	Wet Wiper System	X	X	X
JB4	Active Lane Keeping Assist	X	X	X
JK5	Instrument cluster with color display	X	X	X
<i>Ordering availability restricted, see NetStar for availability and restrictions   must have C03 + JF1</i>				

144" 4C	170" 4C	170" E 4C
MXCA44	MXCA74	MXCAE4
907.653	907.655	907.657

C03	Premium Plus Package	\$1,793	\$1,793	\$1,793
E1B	Tray for smartphones incl. wireless charging	X	X	X
	Navigation	X	X	X
EY2	Intelligent navigation	X	X	X
E4M	MBUX Multimedia System with 10.25" touchscreen	X	X	X
EX9	Free map data updates for 3 years	X	X	X
H1I	Front-to-rear outlet in instrument panel	X	X	X
JA9	Traffic Sign Assist	X	X	X
XM4	Acoustic package	X	X	X
<i>must have (CA2+JB7) OR (JB4+JK5+FM3+JB7); not with FR8 and C02</i>				

X67	Chrome Grille Package	\$290	\$290	\$290
CN2	Radiator grille frame in vehicle color	X	X	X
FK3	Chrome plated radiator grille (MB only)	X	X	X
<i>no restrictions</i>				

X13	Exterior Lighting Package	\$1,608	\$1,608	\$1,608
L13	Fog lamp with cornering light function	X	X	X
L22	Partial LED tail lights	X	X	X
LA1	High beam assist	X	X	X
LG7	LED high performance headlamps	X	X	X
<i>no restrictions</i>				

C06	Cargo Convenience Package	\$658	\$658	\$658
E36	Cutoff relay for additional battery	X	X	X
ES2	12 V power outlet, rear compartment	X	X	X
LC2	LED light strip in load compartment	X	X	X
T12	Sliding door two stage opening	X	X	X
T85	Assist handle, left rear door	X	X	X
T86	Assist handles, right rear door	X	X	X
W54	Rear doors, opening to side wall	X	X	S
<i>must have T74 OR (T77+D50) OR (T77+D51)</i>				

C07	Cargo Protection Package	\$1,117	\$1,117	\$1,117
V25	Half height load compartment trim	X	X	X
V42	Lashing rails, waist level	X	X	X
VC4	Cargo lashing rails, head height	X	X	X
VK8	Floor covering, plastic	X	X	X
YK3	Cargo straps, D-rings	X	X	X
<i>not with X66</i>				

144" 4C	170" 4C	170" E 4C
MXCA44	MXCA74	MXCAE4
907.653	907.655	907.657

X66	Heavy-Duty-Cargo Protection Package	\$2,043	\$2,043	\$2,043
V43	Wood floor with 6 D-rings	X	X	X
V42	Lashing rails, waist level	X	X	X
VA3	Side wall paneling full hardboard	X	X	X
VC4	Cargo lashing rails, head height	X	X	X
VV2	Lashing rails, floor level (plus 4 anchors)	X	X	X
YK3	Cargo straps, D-rings	X	X	X
YK4	Cargo straps, lashing rails	X	X	X
<i>not with C07</i>				

X69	Swivel Seat Package	\$532	\$532	\$532
SR8	Swivel base for driver's seat	X	X	X
SR9	Swivel base for front passenger seat	X	X	X
S87	Driver's seat frame, low	X	X	X
S88	Passenger seat frame, low	X	X	X
<i>must have (C00+C05) OR (C00+X68)</i>				

F09	SHUTTLE DOOR PREP PACKAGE	\$0	\$0	\$0
SW1	Seat belt deletion, passenger	X	X	X
S91	Passenger seat, deleted	X	X	X
S99	Passenger seat pedestal - deletion	X	X	X
<i>Package deletes standard options: SH2 Thorax-Pelvis sidebag, co-driver; To add/delete from order must call distribution team</i>				

X01	Suspension Seating Package	\$940	\$940	\$940
S83	Driver suspension seat, comfort version	X	X	X
S84	Passenger suspension seat, comfort version	X	X	X
S87	Driver's seat frame, low	X	X	X
S88	Passenger seat frame, low	X	X	X
<i>not with C00/C05/E21/X68/S23</i>				



144" 6C	144" 4x4	170" 6C	170" 4x4	170" E 6C	170" E 4x4
MXCA46	MXCA4X	MXCA76	MXCA7X	MXCAE6	MXCAEX
907.653	907.653	907.655	907.655	907.657	907.657

<b>Engine</b>						
<b>6-Cyl Engine/7-Speed Trans.</b>		S	S	S	S	S
ED4 AGM battery 12V 92 AH 850 A		S	S	S	S	S
G42 Automatic transmission, 7G-tronic		S	S	S	S	S
M46 Alternator 14 V/220 A		S	S	S	S	S
MG5 3.0L V6 turbo diesel engine		S	S	S	S	S
MH8 SULEV emissions		S	S	S	S	S
<b>X30 4x4 Package</b>		-	\$8,200	-	\$8,200	-
T75 Door-mounted assist handles, driver & passenger		-	S	-	S	-
ZG3 4x4 - High range transfer case w/ low gear		-	S	-	S	-
<b>Tires - choose while ordering</b>						
<b>X34 Dual Rear Wheel</b>		\$0	\$0	\$0	\$0	\$0
RH7 Tires LT 215/85 R16		S	S	S	S	S
RS6 5.5 J x 16 steel wheels		S	S	S	S	S
RD9 Unspecified tire brand		S	S	S	S	S
<b>X31 Super Single Tire</b>		\$385	-	\$385	-	\$385
R9A 285/65 R 16 C super single tires		O	-	O	-	O
RS5 Steel wheels: 8.5Jx16 Rr; 6.5Jx16 Lr		O	-	O	-	O
RD9 Unspecified tire brand		O	-	O	-	O
RY2 Tire pressure monitoring sensors		O	-	O	-	O
<b>Equipment</b>						
AR2 Axle ratio 3.923		O	S	O	S	O
AR3 Axle ratio 4.182		S	-	S	-	S
BA3 Active Brake Assist		S	S	S	S	S
BH1 Hold Function		S	S	S	S	S
C6L Multifunction steering wheel		S	S	S	S	S
CB8 Stabilization Level II		S	-	S	-	S
CL1 Adjustable steering wheel (angle)		S	S	S	S	S
D03 High roof		O	O	S	S	S
D93 Omission bulkhead		S	S	S	S	S
E07 Hill Start Assist		S	S	S	S	S
E10 Standard radio		S	S	S	S	S
E1U USB-C socket, 5 V		S	S	S	S	S
E30 Starter battery disconnect		S	S	S	S	S
E3J Pre-installation for switch panel		S	-	S	-	S
E40 Trailer hitch prep. wiring		S	S	S	S	S
ED8 Preinstallation PSM		S	S	S	S	S
EE5 Ultracapacitor discharge module		S	S	S	S	S
EK1 Body Builder Connector		S	S	S	S	S
ES0 Jump start terminal		S	S	S	S	S
EW6 Pre-installation for Mercedes me Remote Services		S	S	S	S	S
EY5 Emergency Call System		S	S	S	S	S
EY6 Breakdown management		S	S	S	S	S
F68 Heated & electrically adjustable exterior mirrors		S	S	S	S	S
FF5 Shelf above windshield		S	S	S	S	S
FG8 Cupholder front		S	S	S	S	S
FI1 Remote key (315 mhz) w/central locking		S	S	S	S	S
FJ4 Storage compartment underneath cockpit		S	S	S	S	S
FR3 Rear view camera (rear-view mirror display)		S	S	S	S	S
H21 Windshield with filter band		S	S	S	S	S
HH2 Heater, auxiliary electric hot air		S	S	S	S	S
HH9 Air Condition, Front		S	S	S	S	S
IH7 Head Unit, North America		S	S	S	S	S
J11 Speedometer, miles and km/h		S	S	S	S	S
J55 Seat belt warning for co-driver seat		S	S	S	S	S
J58 Seat belt reminder driver		S	S	S	S	S
J65 Outside temperature gauge		S	S	S	S	S
JA8 Crosswind Assist		S	S	S	S	S

		144" 6C	144" 4x4	170" 6C	170" 4x4	170" E 6C	170" E 4x4
		MXCA46	MXCA4X	MXCA76	MXCA7X	MXCAE6	MXCAEX
		907.653	907.653	907.655	907.655	907.657	907.657
JH3	Communication module (LTE) for dig. services	S	S	S	S	S	S
J19	Service interval 20,000 miles	S	S	S	S	S	S
K56	Red diesel filler cap	S	S	S	S	S	S
K60	Exhaust straight to rear	S	S	S	S	S	S
KB7	24.5 gallon fuel tank	S	S	S	S	S	S
KL1	Aux fuel sending unit w/ fuel tap	S	S	S	S	S	S
KL5	Fuel filter with water separator	S	S	S	S	S	S
KP6	3rd generation SCR emission control system	S	S	S	S	S	S
L65	Interior lights, cargo compartment	S	S	S	S	S	S
L94	Parking lights deletion	S	S	S	S	S	S
LA2	Headlight assistant	S	S	S	S	S	S
LB5	3rd brake light	S	S	S	S	S	S
MS1	Cruise control	S	S	S	S	S	S
P47	Front mudflaps	S	S	S	S	S	S
P48	Rear mudflaps	S	S	S	S	S	S
Q11	Longitudinal member reinforcement	S	S	S	S	S	S
R65	Spare tire bracket below frame	S	S	S	S	S	S
R87	Spare tire	S	S	S	S	S	S
RM0	All-season tires	S	S	S	S	S	S
S02	Standard driver seat	S	S	S	S	S	S
S04	Standard front passenger seat	S	S	S	S	S	S
S22	Armrest for driver's seat	S	S	S	S	S	S
S25	Armrest for front passenger seat	S	S	S	S	S	S
SA5	Front airbag, driver	S	S	S	S	S	S
SA6	Front airbag, passenger	S	S	S	S	S	S
SH1	Thorax-pelvis sidebag, driver	S	S	S	S	S	S
SH2	Thorax-pelvis sidebag, co-driver	S	S	S	S	S	S
SH9	Airbag, driver/passenger window	S	S	S	S	S	S
SK2	Seat occupancy sensor, driver's seat	S	S	S	S	S	S
T16	Sliding door, passenger side	S	S	S	S	S	S
V93	Without factory installed flooring	S	S	S	S	S	S
V94	Cable duct - side wall	S	S	S	S	S	S
V95	Cable duct - rear portal	S	S	S	S	S	S
W54	Rear doors, opening to side wall	O	O	O	O	S	S
X5G	Without load uprating/derating 5,000 kg	S	S	S	S	S	S
Y43	Jack, hydraulic	S	S	S	S	S	S

## Options

		144" 6C	144" 4x4	170" 6C	170" 4x4	170" E 6C	170" E 4x4
		MXCA46	MXCA4X	MXCA76	MXCA7X	MXCAE6	MXCAEX
		907.653	907.653	907.655	907.655	907.657	907.657
A50	Front axle reinforced	\$346	-	\$346	-	\$346	-
AP2	Addtl. bar for driveshaft & exhaust extension	\$69	\$69	\$69	\$69	-	-
AR2	Axle ratio 3.923	\$0	S	\$0	S	\$0	S
	<i>not with AR3</i>						
B01	ESP for increased Center of Gravity above 39.4"	-	-	\$0	\$0	\$0	\$0
	<i>must have CB4/CB8/X30; not with RH0/CB7</i>						
BE2	Handbrake lever, folding	\$55	\$55	\$55	\$55	\$55	\$55
	<i>X69 must have BE2</i>						
CB4	Stabilization Level III	\$187	-	\$187	-	\$187	-
	<i>not with CB7/CB8/X30</i>						
C72	Bumpers front/rear primed	\$268	\$268	\$268	\$268	\$268	\$268
	<i>must have CN2 (part of X67), not with CM0</i>						
CE8	Raised rear body mounts	\$252	-	\$252	-	\$252	-
CL3	Leather steering wheel	\$187	\$187	\$187	\$187	\$187	\$187
	<i>must have (C02/E3M)/C03 + (ET4/MS1)</i>						
CM0	Painted metallic front & rear bumper	\$587	\$587	\$587	\$587	\$587	\$587
	<i>must have (CN2/X67) + (JA7/C01) + JB7 + (7755/9197/9775)</i>						
CM9	Primed side moldings	\$364	\$364	\$364	\$364	\$364	\$364
D03	High roof	\$2,900	\$2,900	S	S	S	S
D13	Mounting rails for roof rack	\$300	\$300	\$300	\$300	\$300	\$300
D22	Fixed sunroof (rear roof section)	\$336	\$336	\$336	\$336	\$336	\$336
	<i>not with H08/HK4/H72/V36/ZK4</i>						
D50	Cargo partition	\$288	\$288	\$288	\$288	\$288	\$288
	<i>not with D51/D93/H08/HK4/T74/V36; must have one of T93/T77</i>						
D51	Cargo partition with 1 window	\$335	\$335	\$335	\$335	\$335	\$335
	<i>not with D50/D93/H08/HK4/T74/V37/D17; must have one of T93/T77</i>						
E1B	Tray for smartphones incl. wireless charging	\$156	\$156	\$156	\$156	\$156	\$156
	<i>must have C02/E3M + H1I</i>						
E1E	Navigation	\$728	\$728	\$728	\$728	\$728	\$728
	<i>must have C02/E3M, not with C03</i>						
E1S	Sirius XM, satellite radio	\$255	\$255	\$255	\$255	\$255	\$255
	<i>must have C02/E3M/C03</i>						
E1X	MBUX multimedia 6-hour runtime	-	-	\$0	\$0	\$0	\$0
	<i>must have X2R + (C02+E1E/E1S)/C03/(E3M+E1E/E1S)</i>						
E1R	Additional Fuses (40/80/150/100 Ampere)	\$50	\$50	\$50	\$50	\$50	\$50
	<i>SoP and Plausibility TBD</i>						
E1Y	Additional Fuses (40/80/80/100 Ampere)	\$50	\$50	\$50	\$50	\$50	\$50
	<i>SoP and Plausibility TBD</i>						
E2A	Access point for BB special signals in cockpit	\$29	\$29	\$29	\$29	\$29	\$29
E2I	Additional battery, co-driver seat base	\$248	\$248	\$248	\$248	\$248	\$248
	<i>must have E36/C06; not with E2M/F09; CHS production only</i>						
E2M	Additional battery, engine compartment	\$248	\$248	\$248	\$248	\$248	\$248
	<i>must have X01+ (E36/C06); not with E2I/X69/F09</i>						
E3M	MBUX Multimedia System with 7" touchscreen	\$474	\$474	\$474	\$474	\$474	\$474
	<i>not with C02/C03; must have JK5+(JB7/FR8)</i>						
E36	Cutoff relay for additional battery	\$110	\$110	\$110	\$110	\$110	\$110
	<i>standard with E2I/E2M</i>						
E46	12 V power outlet, driver seat base	\$92	\$92	\$92	\$92	\$92	\$92
E5M	Extension of PSM standard contact	\$58	\$58	\$58	\$58	\$58	\$58
ED5	Parametric special module (PSM)	\$317	\$317	\$317	\$317	\$317	\$317
	<i>not with ED8</i>						
EE3	115 V socket	\$125	\$125	\$125	\$125	\$125	\$125
EP7	Basic electric fitting for rear loudspeakers	\$68	\$68	\$68	\$68	\$68	\$68
ES2	12 V power outlet, rear compartment	\$92	\$92	\$92	\$92	\$92	\$92
ES5	Charging package, dashboard	\$82	\$82	\$82	\$82	\$82	\$82
ET4	Active Distance Assist DISTRONIC	\$263	\$263	\$263	\$263	\$263	\$263
	<i>must have C02/C03/E3M; not with ZH4</i>						

		144" 6C	144" 4x4	170" 6C	170" 4x4	170" E 6C	170" E 4x4
		MXCA46	MXCA4X	MXCA76	MXCA7X	MXCAE6	MXCAEX
		907.653	907.653	907.655	907.655	907.657	907.657
F1K	Coat hooks in driver cabin <i>must have D50/D51</i>	\$14	\$14	\$14	\$14	\$14	\$14
F49	Electrically heated windshield <i>no restriction</i>	\$218	\$218	\$218	\$218	\$218	\$218
F61	Interior rear view mirror <i>not with D50; must have C02/E3M/C03</i>	\$36	\$36	\$36	\$36	\$36	\$36
FE9	Additional DIN-slot	\$81	\$81	\$81	\$81	\$81	\$81
FF4	Storage compartment above cabin <i>must have D03, not with D17/D64/H08/HK4</i>	\$186	\$186	\$186	\$186	\$186	\$186
FF8	Overhead storage slot, front center	\$105	\$105	\$105	\$105	\$105	\$105
FJ1	Hinged lid for storage compartment	\$93	\$93	\$93	\$93	\$93	\$93
FR8	Rear view camera (head unit display) <i>must have C02/E3M; not with FR3/JB7; 3500XD not with JB8</i>	\$336	\$336	\$336	\$336	\$336	\$336
FY1	Security alarm w. interior motion sensor <i>must have LC4/C00</i>	\$584	\$584	\$584	\$584	\$584	\$584
FY7	Optional 3-button keys	\$36	\$36	\$36	\$36	\$36	\$36
FZ9	Keys, two additional masters	\$121	\$121	\$121	\$121	\$121	\$121
H00	Warm/cool air duct to rear compartment <i>not with D50/D51/Y2A</i>	\$59	\$59	\$59	\$59	\$59	\$59
H01	Heat insulation, rear compartment <i>must have V21/V25/VA3/VA1/C07/X66</i>	\$156	\$156	\$156	\$156	\$156	\$156
H04	Heat insulation, front compartment <i>if + D50/D51 must have V07</i>	\$187	\$187	\$187	\$187	\$187	\$187
H08	Air conditioning rear, roof-mounted <i>must have D93 +V36; not with HK4/C06/X66/C07</i>	\$2,872	\$2,872	\$2,872	\$2,872	\$2,872	\$2,872
H12	Fuel-fired pre-heater/booster (17K BTU) <i>not with HZ9</i>	\$1,116	\$1,116	\$1,116	\$1,116	\$1,116	\$1,116
H13	Rear cabin heater and vents <i>must have H12/HZ9</i>	\$786	\$786	\$786	\$786	\$786	\$786
H15	Heated front passenger seat <i>must have H16; not with X68</i>	\$284	\$284	\$284	\$284	\$284	\$284
H16	Heated driver's seat <i>must have H15; not with X68</i>	\$284	\$284	\$284	\$284	\$284	\$284
H22	Rear window defroster <i>must have W61/W78; standard for W61+W70</i>	\$253	\$253	\$253	\$253	\$253	\$253
H72	Roof fan, electric <i>not with D22/V36</i>	\$400	\$400	\$400	\$400	\$400	\$400
H88	Rear heater prep <i>must have H12/HZ9; not with H13/T19</i>	\$405	\$405	\$405	\$405	\$405	\$405
H11	Front-to-rear outlet in instrument panel <i>must have F11/C01</i>	\$0	\$0	\$0	\$0	\$0	\$0
HH4	Thermotronic automatic climate control <i>must have JF1; if +H13 must have H08/HK4</i>	\$337	\$337	\$337	\$337	\$337	\$337
HK4	Rear air conditioner, heavyduty <i>must have D03+V36+D93; not with H08/ZB6/ZE6/N62/N63</i>	\$3,940	\$3,940	\$3,940	\$3,940	\$3,940	\$3,940
H29	Fuel-fired heater booster (18,000 BTU) <i>not with H12</i>	\$676	\$676	\$676	\$676	\$676	\$676
J51	Fuel gauge, optimized for aux. fuel tap <i>not with HZ9/H12</i>	\$72	\$72	\$72	\$72	\$72	\$72
J52	Engine oil level display at cold start	\$0	\$0	\$0	\$0	\$0	\$0
JA7	Blind Spot Assist <i>not with C01</i>	\$450	\$450	\$450	\$450	\$450	\$450
JB4	Active Lane Keeping Assist <i>standard with C02/CA2</i>	\$288	\$288	\$288	\$288	\$288	\$288
JB7	Parking Package <i>must have C02/C03/E3M; not with W75/W76/JB6</i>	\$615	\$615	\$615	\$615	\$615	\$615
JF1	Rain sensor	\$106	\$106	\$106	\$106	\$106	\$106

## Options

		144" 6C	144" 4x4	170" 6C	170" 4x4	170" E 6C	170" E 4x4
		MXCA46	MXCA4X	MXCA76	MXCA7X	MXCAE6	MXCAEX
		907.653	907.653	907.655	907.655	907.657	907.657
JK5	Instrument cluster with color display <i>standard with C02/CA2</i>	\$144	\$144	\$144	\$144	\$144	\$144
JW0	Backup alarm	\$99	\$99	\$99	\$99	\$99	\$99
JW2	Deactivation lamp monitoring failure	\$27	\$27	\$27	\$27	\$27	\$27
JW8	Attention Assist	\$49	\$49	\$49	\$49	\$49	\$49
K51	Misfueling prevention for Diesel	\$49	\$49	\$49	\$49	\$49	\$49
K52	DEF fluid filler cap - lockable	\$27	\$27	\$27	\$27	\$27	\$27
L13	Fog lamp with cornering light function	\$199	\$199	\$199	\$199	\$199	\$199
L71	Light/motion sensor in rear compartment <i>not with V36</i>	\$54	\$54	\$54	\$54	\$54	\$54
LB9	Illuminated front exits	\$151	\$151	\$151	\$151	\$151	\$151
LC2	LED light strip in load compartment <i>not with H08/HK4/V36/C06</i>	\$263	\$263	\$263	\$263	\$263	\$263
LC4	Comfort overhead control panel	\$93	\$93	\$93	\$93	\$93	\$93
M20	Speed limitation 65 mph <i>not with MD3</i>	\$60	\$60	\$60	\$60	\$60	\$60
MD3	Top speed limitation 75 mph <i>not with M20</i>	\$60	\$60	\$60	\$60	\$60	\$60
N62	Front engine bracket for additional alternator <i>not with HK4/N63</i>	\$467	\$467	\$467	\$467	\$467	\$467
N63	Front engine bracket for auxiliary A/C compressor <i>not with HK4/N62</i>	\$467	\$467	\$467	\$467	\$467	\$467
P93	Omission of D-rings <i>not with D93/V43/VK8</i>	-\$15	-\$15	-\$15	-\$15	-\$15	-\$15
QA2	Trailer cross member 7,500 lbs capacity <i>not with W73/W75/W76/Q24/Q67</i>	\$186	\$186	\$186	\$186	-	-
QA9	Half-sided step rear (for trailer hitch) <i>must have QA2; not with W73/W75/W76</i>	\$101	\$101	\$101	\$101	\$101	\$101
Q24	Trailer hitch, 5,000 lbs <i>not with W73/W75/W76</i>	-	-	-	-	\$147	\$147
R91	Spare tire deletion <i>must have R92; not with R87</i>	-\$110	-\$110	-\$110	-\$110	-\$110	-\$110
R92	Spare tire carrier deletion <i>must have R91; not with R65</i>	\$0	\$0	\$0	\$0	\$0	\$0
R98	Rims painted jet black <i>not with RL5/RM2</i>	\$81	\$81	\$81	\$81	\$81	\$81
RF1	Tire brand Continental <i>must have RM1 + RM9</i>	\$0	\$0	\$0	\$0	\$0	\$0
RF8	Tire brand Michelin <i>must have RM9; not with RM1</i>	\$0	\$0	\$0	\$0	\$0	\$0
RH0	Tire brand Kumho <i>must have RM9; not with RM1</i>	\$0	\$0	\$0	\$0	\$0	\$0
RM1	M+S winter tires <i>must have RF1/RD9; not with RF8/RH0/X31</i>	\$169	\$169	\$169	\$169	\$169	\$169
RM2	Rims painted arctic white <i>not with R98/RL5</i>	\$81	\$81	\$81	\$81	\$81	\$81
RM9	Specially requested tires <i>must have RF1/RF8/RH0; not with RD9</i>	\$101	\$101	\$101	\$101	\$101	\$101
S23	Twin front passenger seat <i>not with C00/X68/X01</i>	\$400	\$400	\$400	\$400	\$400	\$400
S28	Armrest, driver and passenger door	\$51	\$51	\$51	\$51	\$51	\$51
S62	Seat belts orange, driver and front passenger <i>not with S23</i>	\$32	\$32	\$32	\$32	\$32	\$32
SB9	Driver's seat plus <i>must have VF7; not with C00/X68/X69</i>	\$238	\$238	\$238	\$238	\$238	\$238
SZ7	Storage net, driver's seat backrest	\$64	\$64	\$64	\$64	\$64	\$64
SZ8	Storage net, passenger seat backrest	\$64	\$64	\$64	\$64	\$64	\$64



## Options

		144" 6C	144" 4x4	170" 6C	170" 4x4	170" E 6C	170" E 4x4
		MXCA46	MXCA4X	MXCA76	MXCA7X	MXCAE6	MXCAEX
		907.653	907.653	907.655	907.655	907.657	907.657
T12	Sliding door two stage opening <i>not with T55</i>	\$82	\$82	\$82	\$82	\$82	\$82
T19	Sliding door, driver's side <i>not with H13/H88/VCS/ZE6/F43/W16/F02; if +V36 must have D03</i>	\$935	\$935	\$935	\$935	\$935	\$935
T50	Electric closing assist right sliding door <i>must have D03; not with T55/T93</i>	\$335	\$335	\$335	\$335	\$335	\$335
T51	Electric closing assist left sliding door <i>must have T19 + D03</i>	\$335	\$335	\$335	\$335	\$335	\$335
T55	Electric sliding door right <i>must have D03 + (FY7+T16); not with T12/T50</i>	\$831	\$831	\$831	\$831	\$831	\$831
T57	Electric sliding step <i>must have ED5; not with T93</i>	\$1,071	\$1,071	\$1,071	\$1,071	\$1,071	\$1,071
T60	Opening limiter electrically operated sliding door <i>must have T55</i>	\$120	\$120	\$120	\$120	\$120	\$120
T74	Assist handle, B-pillar <i>must have D93; not with T77</i>	\$32	\$32	\$32	\$32	\$32	\$32
T75	Door-mounted assist handles, driver & passenger	\$59	\$59	\$59	\$59	\$59	\$59
T77	Assist handle w/ partition <i>must have D50/D51/D64</i>	\$32	\$32	\$32	\$32	\$32	\$32
T85	Assist handle, left rear door	\$32	\$32	\$32	\$32	\$32	\$32
T86	Assist handles, right rear door	\$32	\$32	\$32	\$32	\$32	\$32
T93	Sliding door right side deletion <i>not with T16/T50/T57/VK8/VCS</i>	\$0	\$0	\$0	\$0	\$0	\$0
V07	Cab rear wall liner <i>must have (D50/D51)+F1K; standard with H04</i>	\$360	\$360	\$360	\$360	\$360	\$360
V21	Luxury interior Trim <i>must have VA5/VA7; not with V52/VA1/VA3</i>	\$661	\$661	\$661	\$661	\$661	\$661
V24	Pallet support in sliding door step <i>must have (V43/X66)+(D50/D51); not with VK8/V93/C07</i>	\$96	\$96	\$96	\$96	\$96	\$96
V25	Half height load compartment trim <i>not with VA1/VA3/VA5/V52/X66</i>	\$201	\$201	\$201	\$201	\$201	\$201
V31	Window pillar trim <i>must have V36 + (V21/VA1) + (F02/F03/F07); not with V42</i>	\$513	\$513	\$513	\$513	\$513	\$513
V35	Wheel house covering <i>if +V43 must have V25/VA1/VA3; not with V52</i>	\$105	\$105	\$105	\$105	\$105	\$105
V36	Roof trim <i>must have D93; not with D17/D22/H72/L65/L71/LC2/VA3/V42/ZE6/(T93+-D03)/X66/C06/C07</i>	\$876	\$876	\$876	\$876	\$876	\$876
V42	Lashing rails, waist level <i>not with V36/ZE6</i>	\$277	\$277	\$277	\$277	\$277	\$277
V43	Wood floor with 6 D-rings <i>not with P93/V93/VL4/VK8/C07; standard with D93/H13/V24/V52/VCS/VV2/ZE6</i>	\$422	\$422	\$422	\$422	\$422	\$422
V48	Floor cover behind seat box <i>must have D93; not with D50/D51/D56/D62/D64/V43/VK5</i>	\$27	\$27	\$27	\$27	\$27	\$27
V4A	Full paneling, right sliding door <i>must have D03+T16+V21+VA5+W17; not with T19</i>	\$109	\$109	\$109	\$109	\$109	\$109
V85	Cigarette lighter & ash cup, front	\$39	\$39	\$39	\$39	\$39	\$39
VA1	Side wall paneling waist height PVC <i>must have VA5/VA7; not with V52</i>	\$319	\$319	\$319	\$319	\$319	\$319
VA3	Side wall paneling full hardboard <i>not with V36/F02; if T93 must have (D50/D51)</i>	\$444	\$444	\$444	\$444	\$444	\$444
VA5	Full paneling, hinged rear doors <i>must have D03+VA7+(W61/W78); not with V25</i>	\$38	\$38	\$38	\$38	\$38	\$38
VA7	Storage compart. w/ net in rear doors <i>must have W61/W78; not with V52</i>	\$127	\$127	\$127	\$127	\$127	\$127
VC4	Cargo lashing rails, head height <i>must have V42/C07/X66; not with ZE6</i>	\$415	\$415	\$415	\$415	\$415	\$415
VC5	Door sill - protective edge <i>must have V43/X66; not with T19/T93/VK8/VV2/V93/C07</i>	\$71	\$71	\$71	\$71	\$71	\$71

## Options

		144" 6C	144" 4x4	170" 6C	170" 4x4	170" E 6C	170" E 4x4
		MXCA46	MXCA4X	MXCA76	MXCA7X	MXCAE6	MXCAEX
		907.653	907.653	907.655	907.655	907.657	907.657
VK8	Floor covering, plastic <i>not with V43/P93/T19/T93/V52/VC5/X66</i>	\$370	\$370	\$370	\$370	\$370	\$370
VV2	Lashing rails, floor level (plus 4 anchors) <i>must have V43; not with V93/VC5/ZE6</i>	\$270	\$270	\$345	\$345	\$377	\$377
W16	2nd row, fixed window, driver side <i>if D93 must have F43+W70; if D93 &amp; standard roof CHS production required</i>	\$145	\$145	\$145	\$145	\$145	\$145
W17	2nd row, fixed window, passenger side <i>if D93 must have F43+W70; if D93 &amp; standard roof CHS production required</i>	\$145	\$145	\$145	\$145	\$145	\$145
W33	FMVSS 217 emergency exit <i>must have V31; not with D50/T19/W16</i>	\$379	\$379	\$379	\$379	\$379	\$379
W54	Rear doors, opening to side wall	\$360	\$360	\$360	\$360	\$	\$
W5F	90 Degree fixation point- Rear Doors <i>SoP and Plausibility TBD</i>	\$80	\$80	\$80	\$80	\$80	\$80
W61	Windows in rear doors <i>must have VA7/ if D51 must have F61; not with W78/(W70+-(H22/F02))</i>	\$93	\$93	\$93	\$93	\$93	\$93
W70	Black tinting (90%) for rear windows <i>not with W94; must have W16/W17/F02/((W61/W78)+H22); standard with F43/W33/F07</i>	\$138	\$138	\$138	\$138	\$138	\$138
W73	Bumper step, rear, grey <i>not with QA2/W75/W76</i>	\$187	\$187	\$187	\$187	\$187	\$187
W75	Step, wide, at rear end <i>not with JB6/JB7/Q24/QA9; must have R91+R92</i>	\$308	-	\$308	-	\$308	-
W76	Bumper step, rear, spring-loaded <i>must have R91+R92; not with JB6/JB7/X30/Q24</i>	-	-	\$601	-	\$601	-
W78	Heated rear window(s) w/ washers/wipers <i>Must have H22+VA7 / if D51 must have F61; not with W61</i>	\$335	\$335	\$335	\$335	\$335	\$335
X2R	Conversion to RV requirement <i>must have B01+D93+E1X</i>	-	-	\$0	\$0	\$0	\$0
X90	Deletion of Sprinter badge, left rear door	\$0	\$0	\$0	\$0	\$0	\$0
X93	Deletion of model badge, right rear door	\$0	\$0	\$0	\$0	\$0	\$0
XM4	Acoustic package <i>standard with C02/C03</i>	\$87	\$87	\$87	\$87	\$87	\$87
Y10	First-aid kit	\$27	\$27	\$27	\$27	\$27	\$27
Y26	Wheel chocks	\$38	\$38	\$38	\$38	\$38	\$38
Y45	Emergency flashlight	\$27	\$27	\$27	\$27	\$27	\$27
Y68	Paint preservative	\$187	\$187	\$212	\$212	\$225	\$225
Y69	Surface protection for stock vehicles	\$315	\$315	\$315	\$315	\$315	\$315
YK3	Cargo straps, D-rings	\$81	\$81	\$81	\$81	\$81	\$81
YK4	Cargo straps, lashing rails <i>must have V42/VV2; not with ZE6</i>	\$104	\$104	\$104	\$104	\$104	\$104
ZE6	Shelving prep <i>not with T93/H13/T19/V36/V42/VC4/VK8/VV2/YK4</i>	\$640	\$640	\$640	\$640	\$640	\$640
ZH4	Downhill speed regulation for 4x4 <i>must have ED5; not with ET4</i>	-	\$58	-	\$58	-	\$58

		144" 6C	144" 4x4	170" 6C	170" 4x4	170" E 6C	170" E 4x4
		MXCA46	MXCA4X	MXCA76	MXCA7X	MXCAE6	MXCAEX
		907.653	907.653	907.655	907.655	907.657	907.657
<b>C00</b>	<b>Comfort Package</b>	<b>\$300</b>	<b>\$300</b>	<b>\$300</b>	<b>\$300</b>	<b>\$300</b>	<b>\$300</b>
LC4	Comfort overhead control panel	X	X	X	X	X	X
SE4	Lumbar support, co-driver's seat	X	X	X	X	X	X
SE5	Lumbar support, driver's seat	X	X	X	X	X	X
SK0	Comfort head restraint, driver	X	X	X	X	X	X
SK1	Comfort head restraint, co-driver	X	X	X	X	X	X
S28	Armrest, driver and passenger door	X	X	X	X	X	X
<i>must have C05 OR X68; CA/CC only: not with S23</i>							

<b>C05</b>	<b>Comfort Package (Seat addition)</b>	<b>\$381</b>	<b>\$381</b>	<b>\$381</b>	<b>\$381</b>	<b>\$381</b>	<b>\$381</b>
SB1	Comfort driver's seat	X	X	X	X	X	X
SB2	Comfort passenger seat	X	X	X	X	X	X
<i>must have C00</i>							

<b>X68</b>	<b>Comfort Plus Package</b>	<b>\$1,923</b>	<b>\$1,923</b>	<b>\$1,923</b>	<b>\$1,923</b>	<b>\$1,923</b>	<b>\$1,923</b>
H15	Heated front passenger seat	X	X	X	X	X	X
H16	Heated driver's seat	X	X	X	X	X	X
SF1	Driver's seat electrically adjustable	X	X	X	X	X	X
SF2	Co-driver's seat electrically adjustable	X	X	X	X	X	X
<i>must have C00 and VF4 OR VF6, CA/CC only: not with S23</i>							

<b>C01</b>	<b>Driver Convenience Package</b>	<b>\$760</b>	<b>\$760</b>	<b>\$760</b>	<b>\$760</b>	<b>\$760</b>	<b>\$760</b>
E46	12 V power outlet, driver seat base	X	X	X	X	X	X
f64	Electrically folding exterior mirrors	X	X	X	X	X	X
FJ1	Hinged lid for storage compartment	X	X	X	X	X	X
FJ5	Hinged Lid for Storage Compartments left and right	X	X	X	X	X	X
FZ9	Keys, two additional masters	X	X	X	X	X	X
JA7	Blind Spot Assist	X	X	X	X	X	X
JW8	Attention Assist	X	X	X	X	X	X

<b>C02</b>	<b>Premium Package</b>	<b>\$983</b>	<b>\$983</b>	<b>\$983</b>	<b>\$983</b>	<b>\$983</b>	<b>\$983</b>
CL3	Leather steering wheel	X	X	X	X	X	X
E3M	MBUX Multimedia System with 7" touchscreen	X	X	X	X	X	X
FM3	Wet Wiper System	X	X	X	X	X	X
JB4	Active Lane Keeping Assist	X	X	X	X	X	X
JK5	Instrument cluster with color display	X	X	X	X	X	X
<i>Ordering availability restricted, see NetStar for availability and restrictions   must have JF1 + XM4; must choose FR8/JB7</i>							

<b>CA2</b>	<b>C02 in combination with C03</b>	<b>\$604</b>	<b>\$604</b>	<b>\$604</b>	<b>\$604</b>	<b>\$604</b>	<b>\$604</b>
CL3	Leather steering wheel	X	X	X	X	X	X
FM3	Wet Wiper System	X	X	X	X	X	X
JB4	Active Lane Keeping Assist	X	X	X	X	X	X
JK5	Instrument cluster with color display	X	X	X	X	X	X
<i>Ordering availability restricted, see NetStar for availability and restrictions   must have C03 + JF1</i>							



144" 6C	144" 4x4	170" 6C	170" 4x4	170" E 6C	170" E 4x4
MXCA46	MXCA4X	MXCA76	MXCA7X	MXCAE6	MXCAEX
907.653	907.653	907.655	907.655	907.657	907.657

C03	Premium Plus Package	\$1,793	\$1,793	\$1,793	\$1,793	\$1,793	\$1,793
E1B	Tray for smartphones incl. wireless charging	X	X	X	X	X	X
	Navigation	X	X	X	X	X	X
EY2	Intelligent navigation	X	X	X	X	X	X
E4M	MBUX Multimedia System with 10.25" touchscreen	X	X	X	X	X	X
EX9	Free map data updates for 3 years	X	X	X	X	X	X
H1I	Front-to-rear outlet in instrument panel	X	X	X	X	X	X
JA9	Traffic Sign Assist	X	X	X	X	X	X
XM4	Acoustic package	X	X	X	X	X	X
<i>must have (CA2+JB7) OR (JB4+JK5+FM3+JB7); not with FR8 and C02</i>							

X67	Chrome Grille Package	\$290	\$290	\$290	\$290	\$290	\$290
CN2	Radiator grille frame in vehicle color	X	X	X	X	X	X
FK3	Chrome plated radiator grille (MB only)	X	X	X	X	X	X
<i>no restrictions</i>							

X13	Exterior Lighting Package	\$1,608	\$1,608	\$1,608	\$1,608	\$1,608	\$1,608
L13	Fog lamp with cornering light function	X	X	X	X	X	X
L22	Partial LED tail lights	X	X	X	X	X	X
LA1	High beam assist	X	X	X	X	X	X
LG7	LED high performance headlamps	X	X	X	X	X	X
<i>no restrictions</i>							

C06	Cargo Convenience Package	\$658	\$658	\$658	\$658	\$658	\$658
E36	Cutoff relay for additional battery	X	X	X	X	X	X
ES2	12 V power outlet, rear compartment	X	X	X	X	X	X
LC2	LED light strip in load compartment	X	X	X	X	X	X
T12	Sliding door two stage opening	X	X	X	X	X	X
T85	Assist handle, left rear door	X	X	X	X	X	X
T86	Assist handles, right rear door	X	X	X	X	X	X
W54	Rear doors, opening to side wall	X	X	X	X	S	S
<i>must have T74 OR (T77+D50) OR (T77+D51)</i>							

C07	Cargo Protection Package	\$1,117	\$1,117	\$1,117	\$1,117	\$1,117	\$1,117
V25	Half height load compartment trim	X	X	X	X	X	X
V42	Lashing rails, waist level	X	X	X	X	X	X
VC4	Cargo lashing rails, head height	X	X	X	X	X	X
VK8	Floor covering, plastic	X	X	X	X	X	X
YK3	Cargo straps, D-rings	X	X	X	X	X	X
<i>not with X66</i>							

X66	Heavy-Duty-Cargo Protection Package	\$2,043	\$2,043	\$2,043	\$2,043	\$2,043	\$2,043
V43	Wood floor with 6 D-rings	X	X	X	X	X	X
V42	Lashing rails, waist level	X	X	X	X	X	X
V52	Loadable wheel arch	X	X	X	X	X	X
VA3	Side wall paneling full hardboard	X	X	X	X	X	X
VC4	Cargo lashing rails, head height	X	X	X	X	X	X
VV2	Lashing rails, floor level (plus 4 anchors)	X	X	X	X	X	X
YK3	Cargo straps, D-rings	X	X	X	X	X	X
YK4	Cargo straps, lashing rails	X	X	X	X	X	X
<i>not with C07</i>							

## Packages

144" 6C	144" 4x4	170" 6C	170" 4x4	170" E 6C	170" E 4x4
MXCA46	MXCA4X	MXCA76	MXCA7X	MXCAE6	MXCAEX
907.653	907.653	907.655	907.655	907.657	907.657

<b>X69</b>	<b>Swivel Seat Package</b>	<b>\$532</b>	<b>\$532</b>	<b>\$532</b>	<b>\$532</b>	<b>\$532</b>	<b>\$532</b>
SR8	Swivel base for driver's seat	X	X	X	X	X	X
SR9	Swivel base for front passenger seat	X	X	X	X	X	X
S87	Driver's seat frame, low	X	X	X	X	X	X
S88	Passenger seat frame, low	X	X	X	X	X	X
<i>must have (C00+C05) OR (C00+X68)</i>							

<b>X01</b>	<b>Suspension Seating Package</b>	<b>\$940</b>	<b>\$940</b>	<b>\$940</b>	<b>\$940</b>	<b>\$940</b>	<b>\$940</b>
SB3	Driver suspension seat, comfort version	X	X	X	X	X	X
S84	Passenger suspension seat, comfort version	X	X	X	X	X	X
S87	Driver's seat frame, low	X	X	X	X	X	X
S88	Passenger seat frame, low	X	X	X	X	X	X
<i>not with C00/C05/E21/X68/S23</i>							