

Hyundai 4.75 to 6.5 CY Wheel Loaders Options Page:

	<u>HL965</u>	<u>HL970A/XT</u>	<u>HL975/XT</u>	<u>HL980A/XT</u>
4.7 CY Bucket	\$15,310	\$0	\$0	\$0
5.0 CY Bucket	\$19,280	\$0	\$0	\$0
5.5 CY Bucket	\$0	\$16,420	\$0	\$0
5.5 CY Spade Nose Bucket	\$0	\$43,280	\$0	\$0
6.3 CY Bucket	\$0	\$0	\$18,790	\$49,750 Spade
7.3 CY Bucket	\$0	\$0	\$0	\$22,890
8.2 Cy Bucket	\$0	\$0	\$0	\$27,990 Light
Hyun Quick Coupler:	\$12,610	\$15,580	\$13,850	N/A
Belly Pan Guard:	\$1,230	\$1,230	\$1,230	\$0
Rear View Camera:	Standard	Standard	Standard	Standard
AAVM 360 Degree Camera:	\$4,090	\$4,800	\$4,800	\$5,020
2nd Monitor and Rear Detect:	\$2,380	\$2,380	\$2,380	\$2,380
Full LED Light Package:	\$7,350	\$7,580	\$7,580	\$7,580
Auto Lube System:	\$12,370	\$13,590	\$13,710	\$15,050
XT Package:	\$0	\$11,088	\$6,667	\$10,404.29

ADD OPTIONS ABOVE and many other attachments through various vendors